

20.10/2002

ASSY REC BY:

REF: CS/FCI17017883/Alrbn2 Special Instruction:

Survivor
CWS

Resu

ASSIGNMENT (Office)

Date/Time: 15/9/17 4:32pm

From (Person): Aung Yin Ming

of FCI

Bill to:

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

Insured: SHC0666T

To Inspect Vehicle No:

SLQ 9577L

Tel: 81261237

at Workshop m/s

Weermes Automotive

Policy No:

Claim No:

D17008723 MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 10/9/17

CA / REV / REP. / REV 24 HRS

13.10.2017 @ after 4pm

H.O.D. Endorsement

Date/Time: 15/9/17 4:53pm

Person Contacted:

Paul Ong

Vehicle IN/OUT

Date/Time Action/Instruction (✓) Estimate

SLQ 9577L-X

SHC 0666T-X

Confirm P/P \$7308.39 6 days

Red: \$3,063.51, 29%.

(06/11/13)

A.S. REC. BY: Pam

REF: FCI

0115B

ASSIGNMENT

From:

Date: 13/10/17

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLQ 9577 L

at Workshop m/s

Wearnes Automotive

of

28 Leng Kee Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

After 4pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLQ 9577 L

Yr Regn:

2017 / July

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Megane 1.5 c.c. 1461

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

5654

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF1RF B009 570 30922

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

205/50R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

10/07/17

D.O.I.

13/10/17

Survey held at

Wearnes

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)



Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:



Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) 7308.39

RECEIVED 03 JAN 2018

170
50
50
31
301



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17017883/R1rb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 15-09-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 0666T	Veh. Inspected	SLQ 9577L
Policy No.		Coverage (\$)	0.00
Claim No.	D17008723MFSH	Excess (\$)	0.00
Assign From	CWS (AUNG YIN MIN)	Assign Date	15/09/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	10/09/2017	Inspection Date
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date	12-09-2017	Our Ref No. D17008723MFSH
Accident Date	10-09-2017	Claim Type. Third Party
Insured Vehicle	SHC0666T	Third Party Vehicle. SLQ9577L
Survey Location	BODY AND PAINT DEPT 249 ALEXANDRA ROAD	
Contact Person.	PAUL ONG	
Contact No.	64304899/ 81261237	Fax No. 0
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WEARNES AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/227931)



PRI Documents



Close



PRI Header Details

Claim No	D17008723MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & WEARNES
Workshop Name	WEARNES AUTOMOTIVE PTE LTD (Contact Person : PAUL ONG)	Survey Location & Contact Details	BODY AND PAINT DEPT 249 ALEXANDRA ROAD Mobile: 81261237 , Phone: 64304899 , Fax: 0 EmailId: PAUL.ONG@WEARNES.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0666T	TP Vehicle No	SLQ9577L
PRI Recieved Date	15-09-2017 12:59:58 PM	Surveyor Appointed Date	15-09-2017 04:32:32 PM	Surveyor Accept Date	15-09-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	15-09-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Wheel alignment test report

Client name: SLQ 9577 L

Vehicle plate No.: SLQ 9577 L

Mileage:

Contact:

Address:

Manufacturer name: RENAULT(EUR)

Model: Megane II,Hatchback/Van,(XMOX),HD

Start year:2002 End year:2012

Parameter	Before adj.	MIN spec	MAX spec	After adj.
Front Total Toe	-0.40°	-0.34°	0.00°	-0.18°
FL Toe	-0.83°	-0.17°	0.00°	-0.09°
FR Toe	0.43°	-0.17°	0.00°	-0.09°
FL Camber	-0.51°	-0.70°	0.30°	-0.56°
FR Camber	-0.49°	-0.70°	0.30°	-0.45°
Left Caster	4.25°	5.17°	6.17°	4.05°
Right Caster	4.42°	5.17°	6.17°	4.49°
Left SAI	12.82°	10.90°	11.90°	12.82°
Right SAI	11.34°	10.90°	11.90°	11.20°
Rear Total Toe	0.65°	-0.02°	0.82°	0.65°
RL Toe	1.00°	-0.01°	0.41°	1.00°
RR Toe	-0.35°	-0.01°	0.41°	-0.35°
RL Camber	-1.46°	-1.75°	-1.09°	-1.46°
RR Camber	-0.77°	-1.75°	-1.09°	-0.77°
Thrust Angle	-0.67°			-0.68°
Wheelbase Dif.	0.67°(30.9mm)			0.60°(27.4mm)
Tread width Dif.	-0.44°(-0.0mm)			-0.44°(-0.0mm)
Included angle FL	12.31°			12.27°
Included angle FR	10.86°			10.75°
Toe-out on turn L	12.45°			12.45°
Toe-out on turn R	12.20°			12.20°
MAX left turn angle				
MAX right turn angle				

Test date:2017-11-03 16:23

Operator:

Fault cause:

Remark:

Name : VOLVO WEARNES Pte Ltd

Address : 249 ALEXANDRA RD.

Tel : 63789358

Fax : Setting of Garage fax

Post Code : Setting of Garage post code

Janice Lee (LKKAUTO)

From: Paul Ong Qing Yong <paul.ong@wearnes.com>
Sent: Tuesday, December 19, 2017 10:16 AM
To: Rasul (LKKAUTO); SUR; Janice Lee (LKKAUTO)
Subject: RE: SLQ 9577L
Attachments: WhatsApp Image 2017-11-03 at 11.17.41.jpeg

Hi Janice,

Attached photo scratch marks on spoiler, default factory colour is silver.

Best Regards,

Paul Ong
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 8126 1237 D (65) 6378 9336
www.wearnesauto.com paul.ong@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Paul Ong Qing Yong
Sent: Monday, 18 December, 2017 12:09 PM
To: 'Rasul (LKKAUTO)'; 'SUR'; 'Janice Lee (LKKAUTO)'
Subject: FW: SLQ 9577L

Hi,

Attached for finalisation, thanks.

Best Regards,

Paul Ong
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 8126 1237 D (65) 6378 9336
www.wearnesauto.com paul.ong@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Janice Lee (LKKAUTO) [<mailto:JaniceLee@lkkauto.com>]
Sent: Monday, 18 December, 2017 11:18 AM

To: Paul Ong Qing Yong
Subject: SLQ 9577L

Hi Paul,

Kindly sent us the finalize as the insurance has received the LOD.
*Please give me a call.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 0115B

Vehicle Details

Vehicle No.: SLQ9577L
Vehicle to be Exported: No
Intended De-registration Date: 03 Jan 2018
Vehicle Make: RENAULT
Vehicle Model: MEGANE GT LINE 1.5DCI AT EU6
Primary Colour: Silver
Manufacturing Year: 2017
Engine No.: K9KG657D050031
Chassis No.: VF1RFB00957030922
Maximum Power Output: 81.0 kW (108 bhp)
Open Market Value: \$22,815.00
Original Registration Date: 27 Jul 2017
First Registration Date: 27 Jul 2017
Transfer Count: 0
Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 26 Jul 2027
PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 26 Jul 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$44,002.00
COE Rebate Amount: \$42,073.00
Total Rebate Amount: \$45,823.00

The information contained herein is correct as at 03 Jan 2018

OK

SERVICE ESTIMATE

92912 - C00001 SL: SERVICE SALES - PC

Mr Lee Jian Liang, Alex

Blk 715 Clementi West Street 2
#10-87

Singapore 120715

Closed by : Richmond Ho

Svc Consultant :

Remarks : Mr Lee Jian Liang, A

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 13/10/2017

WIP No. . : 18965

Veh.In/Out:

*Tel.No. . : Mobile: 90901317

Reg.No. . : SLQ9577L

Reg.date . : 27/07/2017

Mileage .. : 0

Chassis No: VF1RFB00957030922

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE REAR LH FENDER, REAR BUMPER, REAR TAILLAMP, REPAIR REAR LH DOORX	0	2250.00	0	2,250.00	S	1800
-----	---	---	---------	---	----------	---	------

800	TO PUTTY SPRAY PAINT ON REAR LH DOOR, REAR LH FENDER, REAR BUMPER	0	1600.00	0	1,600.00	S	800
-----	--	---	---------	---	----------	---	-----

280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	330.00	0	330.00	S	/
-----	---	---	--------	---	--------	---	---

419	COMPUTERISED WHEEL ALIGNMENT	0	280.00	0	280.00	S	/
	REAR BUMPER	1.0 EA	554.20		554.20	S	DE -
	BRACKET	1.0 EA	180.40		180.40	S	Ref -
	BUMPER SPOILER	1.0 EA	554.20		554.20	S	X - Tan
	BRACKET RH	1.0 EA	83.70	75.33	83.70	S	Ref -
	BRACKET LH	1.0 EA	83.70	75.33	83.70	S	Ref -
	REAR FENDER LH	1.0 EA	1576.30	1418.67	1,576.30	S	Ref -
	FENDER BRACKET LH	1.0 EA	28.50	25.65	28.50	S	Ref -
	BODY PANEL SEALANT X	1.0 EA	820.20		820.20	S	X - Tan

SERVICE ESTIMATE

92912 - C00001 SL: SERVICE SALES - PC

Mr Lee Jian Liang, Alex
Blk 715 Clementi West Street 2
#10-87

Singapore 120715

Closed by : Richmond Ho
Svc Consultant :
Remarks : Mr Lee Jian Liang, A

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 2
Inv.date. : 13/10/2017
WIP No. . : 18965
Veh.In/Out:
*Tel.No. . : Mobile: 90901317
Reg.No. . : SLQ9577L
Reg.date. : 27/07/2017
Mileage . : 0
Chassis No: VF1RFB00957030922

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

TAILLAMP LH

1.0 EA 260.70

CRN

234.63
260.70 S

CRN
7/-
photo

Repair
4p 90010068

6 days

13/10/17 @ 16:00

Resurvey by paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour Total	4,460.00	
Parts Total	4,141.90	
Package Total	0.00	

Gross Total. 8,601.90 *10371.90*

Net..... 8,601.90

GST @ 7.0% 602.13

Total..... 9,204.05

Paid..... 0.00

Please Pay.. 9,204.05

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - F00003 SL: FIRST CAPITAL INSURANCE LTD GST Reg.No:M28920628X
 FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD Inv.No. . : B&P 0 Page 1
 #16-01, CITY HOUSE Inv.date. : 03/01/2018
 SINGAPORE WIP No. . : 18965
 Singapore 068877 Veh.In/Out: 13/10/2017 10/11/2017

Closed by : Paul Ong Qing Yong
 Svc Consultant : ACC
 Remarks : Mr Lee Jian Liang, A

*Tel.No. . :
 Reg.No. . : SLQ9577L
 Reg.date . : 27/07/2017
 Mileage .. : 2,722
 Chassis No: VF1RFB00957030922

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR LH FENDER,	0	1800.00	0		1,800.00	S
	REAR BUMPER						
800	TO PUTTY SPRAY PAINT ON	0	800.00	0		800.00	S
	REAR LH FENDER, REAR BUMPER						
280	TO CHECK WIRING INCLUDE	0	330.00	0		330.00	S
	RESETTING OF ALL ELECTRICAL						
	MODULES						
419	COMPUTERISED WHEEL ALIGNMENT	0	280.00	0		280.00	S
802	TO REMOVE & INSTALL INTERIOR	0	450.00	0		450.00	S
	PARTS						
287	TO REMOVE, READJUST REAR LH	0	1320.00	0		1,320.00	S
	UNDERCARRIAGE						
	REAR BUMPER	1.0 EA	554.20	10		498.78	S
	BRACKET RH	1.0 EA	83.70	10		75.33	S
	BRACKET LH	1.0 EA	83.70	10		75.33	S
	REAR FENDER LH	1.0 EA	1576.30	10		1,418.67	S
	FENDER BRACKET LH	1.0 EA	28.50	10		25.65	S

(A)
(A)

SERVICE ESTIMATE

0 - F00003 SL: FIRST CAPITAL INSURANCE LTD
 FIRST CAPITAL INSURANCE LTD GST Reg.No:M28920628X
 36 ROBINSON ROAD Inv.No. . : B&P 0 Page 2
 #16-01, CITY HOUSE Inv.date. : 03/01/2018
 SINGAPORE WIP No. . : 18965
 Singapore 068877 Veh.In/Out: 13/10/2017 10/11/2017

Closed by : Paul Ong Qing Yong
 Svc Consultant : ACC
 Remarks : Mr Lee Jian Liang, A

*Tel.No. . :
 Reg.No. . : SLQ9577L
 Reg.date. : 27/07/2017
 Mileage . : 2,722
 Chassis No: VF1RFB00957030922

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	TAILLAMP LH	1.0 EA	260.70	10		234.63	S

		Gross Total.	7,308.39
Labour Total	4,980.00	Net.....	7,308.39
Parts Total	2,328.39	GST @ 7.0%	511.59
Package Total	0.00	Total.....	7,819.98
		Paid.....	0.00
		Please Pay..	7,819.98

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - F00003 SL: FIRST CAPITAL INSURANCE LTD
 FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01, CITY HOUSE
 SINGAPORE
 Singapore 068877

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 1
 Inv.date. : 18/12/2017
 WIP No. . : 18965
 Veh.In/Out: 13/10/2017 10/11/2017
 *Tel.No. . :
 Reg.No. . : SLQ9577L
 Reg.date . : 27/07/2017
 Mileage . : 2,722
 Chassis No: VF1RFB00957030922

Closed by : Paul Ong Qing Yong
 Svc Consultant : ACC
 Remarks : Mr Lee Jian Liang, A

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR LH FENDER, REAR BUMPER	0	1800.00	0		1,800.00	S
800	TO PUTTY SPRAY PAINT ON REAR LH FENDER, REAR BUMPER	0	800.00	0		800.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	330.00	0		330.00	S
419	COMPUTERISED WHEEL ALIGNMENT	0	280.00	0		280.00	S
802	TO REMOVE & INSTALL INTERIOR PARTS	0	450.00	0		450.00	S
287	TO REMOVE, READJUST REAR LH UNDERCARRIAGE	0	1320.00	0		1,320.00	S
	REAR BUMPER①	1.0 EA	554.20	10		498.78	S
	BUMPER SPOILER	1.0 EA	554.20	10		498.78	S
	BRACKET RH	1.0 EA	83.70	10		75.33	S
	BRACKET LH	1.0 EA	83.70	10		75.33	S
	REAR FENDER LH	1.0 EA	1576.30	10		1,418.67	S

Alignment
Before & After
1 hour - 1/10
12 hour

Supp undercarriage rest.

SERVICE ESTIMATE

0 - F00003 SL: FIRST CAPITAL INSURANCE LTD FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01, CITY HOUSE SINGAPORE Singapore 068877	GST Reg.No:M28920628X Inv.No. . : B&P 0 Page 2 Inv.date. : 18/12/2017 WIP No. . : 18965 Veh.In/Out: 13/10/2017 10/11/2017 *Tel.No. . : Reg.No. . : SLQ9577L Reg.date. : 27/07/2017 Mileage . : 2,722 Chassis No: VF1RFB00957030922
---	--

Closed by : Paul Ong Qing Yong
 Svc Consultant : ACC
 Remarks : Mr Lee Jian Liang, A

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	FENDER BRACKET LH	1.0 EA	28.50	10		25.65	S
	TAILLAMP LH	1.0 EA	260.70	10		234.63	S

	Gross Total.	7,807.17
Labour Total	4,980.00	Net.....
Parts Total	2,827.17	7,807.17
Package Total	0.00	GST @ 7.0%
		546.50
		Total.....
		8,353.67
		Paid.....
		0.00
		Please Pay..
		8,353.67

GST: S=StdRated; O=OutOfScope; Z=ZeroRated



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17017883/R1rbn2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 03-01-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 666T	Veh. Inspected	SLQ 9577L
Policy No.	D-15072702MFSH	Coverage (\$)	0.00
Claim No.	D17008723MFSH	Excess (\$)	0.00
Assign From	AUNGYM	Assign Date	15/09/2017

2. Vehicle Particulars & Condition

Make & Model	RENAULT MEGANE 1.5	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	VF1RFB00957030922	Colour	GREY
Odometer	5654	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50 R17	MICHELIN	6 mm
L/H Front Tyre	205/50 R17	MICHELIN	6 mm
R/H Rear Tyre	205/50 R17	MICHELIN	6 mm
L/H Rear Tyre	205/50 R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	10/09/2017	Inspection Date	13/10/2017
Survey held at	28 LENG KEE ROAD		
Repairer	WEARNES AUTOMOTIVE PTE LTD		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 9577L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (SN)	DEFORMED	554.20	498.78
1	BRACKET (SN)	SERVICEABLE	180.40	-
1	BUMPER SPOILER (SN)	NOT NECESSARY	554.20	-
1	BRACKET RH (SN)	NECESSARY	83.70	75.33
1	BRACKET LH (SN)	NECESSARY	83.70	75.33
1	REAR FENDER LH (SN)	BUCKLED	1,576.30	1,418.67
1	FENDER BRACKET LH (SN)	NECESSARY	28.50	25.65
1	BODY PANEL SEALANT X (SN)	NOT NECESSARY	820.20	-
1	TAILLAMP LH (SN)	CRACKED	260.70	234.63
			4,141.90	2,328.39
LABOUR				
	TO REPLACE REAR LH FENDER, REAR BUMPER, REAR TAILLAMP, REPAIR REAR LH DOOR.		2,250.00	1,800.00
	TO PUTTY SPRAY PAINT ON REAR LH DOOR, REAR LH FENDER, REAR BUMPER.		1,600.00	800.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		330.00	330.00
	COMPUTERISED WHEEL ALIGNMENT.		280.00	280.00
	TO REMOVE & INSTALL INTERIOR PARTS (ADDITIONAL).		450.00	450.00
	TO REMOVE, READJUST REAR LH UNDERCARRIAGE (ADDITIONAL).		1,320.00	1,320.00
			6,230.00	4,980.00
GRAND TOTAL			10,371.90	7,308.39
RECOMMENDED COST OF REPAIRS				7,308.39

Report Ref No. CS/FC117017883/R1rbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
 No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.