

SERVICE ESTIMATE

0 - F00003 SL: FIRST CAPITAL INSURANCE LTD FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01, CITY HOUSE SINGAPORE Singapore 068877 Closed by : Paul Ong Qing Yong Svc Consultant : ACC Remarks : Mr Lee Jian Liang, A	GST Reg.No:M28920628X Inv.No. . : B&P 0 Page 1 Inv.date. : 03/01/2018 WIP No. . : 18965 Veh.In/Out: 13/10/2017 10/11/2017 *Tel.No. . : Reg.No. . : SLQ9577L Reg.date . : 27/07/2017 Mileage .. : 2,722 Chassis No: VF1RFB00957030922
--	--

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR LH FENDER, REAR BUMPER	0	1800.00	0		1,800.00	S
800	TO PUTTY SPRAY PAINT ON REAR LH FENDER, REAR BUMPER	0	800.00	0		800.00	S
280	TO CHECK WIRING INCLUDE RESETTNG OF ALL ELECTRICAL MODULES	0	330.00	0		330.00	S
419	COMPUTERISED WHEEL ALIGMENT	0	280.00	0		280.00	S
802	TO REMOVE & INSTALL INTERIOR PARTS	0	450.00	0		450.00	S (A)
287	TO REMOVE, READJUST REAR LH UNDERCARRIAGE	0	1320.00	0		1,320.00	S (A)
	REAR BUMPER	1.0 EA	554.20	10		498.78	S
	BRACKET RH	1.0 EA	83.70	10		75.33	S
	BRACKET LH	1.0 EA	83.70	10		75.33	S
	REAR FENDER LH	1.0 EA	1576.30	10		1,418.67	S
	FENDER BRACKET LH	1.0 EA	28.50	10		25.65	S