

ASS. REC. BY:

REF: CS/TP17017991/Gabnz

Special Instruction:

Surveyor: GB

ASSIGNMENT (Office)

From (Person): Lee Lim Siang Teck of Areda Adjusters Date/Time: 18/09/2017 11:23am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 1506R Insured: Public Liability

at Workshop m/s Comfort Delgro Tel: 8191 6644

of 600 Sin Ming Avenue Citycab Building

Policy No: 1793033 / LST Claim No: AC170367

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 11.09.2017  
(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 18/09/2017 Person Contacted: Kelvin Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 1506R - NA / ZNC 00018784/r DUA: 230809
	Public liability - x.
<u>20/9/17</u>	Had checked with Mr Lee, Areda Adjusted, they have not GVA report.
<u>28/11/17</u>	Submit Preli-report. (US \$ 2300)
	Send soft copy to Areda Adjusted, hard copy to III, Jason Yeoh.

prev.





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AREDA ADJUSTERS PL		Ref : CS/LAW17017991/Gqb	
195 PEARL'S HILL TERRACE #02-63SINGAPORE 168976		Date : 19-09-2017	
		Code : L125	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SHC 1506R
Policy No.	1793533/LST	Coverage (\$)	0.00
Claim No.	AC170367	Excess (\$)	0.00
Assign From	LIM SIANG TECK	Assign Date	18/09/2017
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	11/09/2017	Inspection Date	18/09/2017
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 600 SIN MING AVENUE CITYCAB BUILDING SINGAPORE 575733		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## Survey Department Check List (Case Handler)

Reference No. : 09/144W/17017991/G9b  
 Policy Type: OD / TP / TP RES / TL / EVA

SHC 1506R  
Typist

Case Handler

**Admin** ( Cothra ): Case handler to make sure all information created by the assignment team are **ACCURATE**.

**(1) Office Assign Form**

	Y-Date	N-Date	Y-Date	N-Date
C Reference No.	✓			
C Customer Code	✓			
N Assign From	✓			
C Assign Date	✓			
C Veh No (Inspected)	✓			
C Veh No (Insured)	✓			
C D.O.A	✓			
C Policy No	✓			
C Claim No	✓			
C Insurance Authorisation (CA/REV/REP)				
C Report Type	✓			
C Weekend Charges				
N Survey held at/Repairer	✓			
C Excess				

**Surveyor** ( Guo Bing ): Case handler to make sure the surveyor completed all required information.

**(1) Assignment Form**

C Vehicle No	✓			
C Regn Month/Year	✓			
N Vehicle Type	✓			
N Make & Model	✓			
C Engine Capacity. (C.C)	✓			
N Colour	✓			
C Odometer. (Sp.Reading)				
C Chassis No	✓			
N General Condition	✓			
N Steering	✓			
N Brake	✓			
N Modification (Modi)	✓			
C Tyre Size	✓			
N Tyre Make	✓			
C Tyre Balance	✓			
C Date of Inspection	✓			
N Survey held	✓			
N Des.of Damages	✓			

**(2) System - (Views/Merimen)**

C Damaged Vehicle Photographs Uploaded	✓		
--	---	--	--

**(3) Workshop Estimate/Assignment Form**

N ALL Parts condition	✓		
C Market Value for OD cases			
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)			
C Days of repair	✓		
C Finalised Amount			
C Re-inspection Cases to Finalize within 5 Days			

**(4) System - (Views/Merimen)**

C Resurvey photo Uploaded			
---------------------------	--	--	--

Check By: [Signature] 28/11/17  
 Case Handler Date

## Catherine Chong (LKK Auto)

---

**From:** Lee Siang Teck <leesiangteck@areda.com.sg>  
**Sent:** Monday, 18 September, 2017 11:23 AM  
**To:** assignments@lkkauto.com  
**Cc:** Jackson Yeo  
**Subject:** Motor assessment on 3 dmaaged taxis  
**Attachments:** 1793533 Repair estimates.pdf

Our Ref : 1793533/LST

Dear Catherine

We refer to our telephone conversation this morning, 18 September 2017.

As discussed, please conduct motor survey on 3 damaged taxis (i.e. SHA 2574Y, SHD 3853U & SHC 1506R) for our Principal, India International Insurance Pte Ltd. The repair estimates is enclosed for your perusal.

Please contact Mr Kelvin Tan of Comfort Transportation Pte Ltd for the survey. His contact nos. :

Hand phone      8491 6644

DID                6550 8571

If you need any clarification, please contact the undersigned.

Thank you.

Best Regards

*Lee Siang Teck*

**Areda Adjusters Pte Ltd**  
195 Pearl's Hill Terrace, #02-63  
Singapore 168976

Tel: 6557 0258 Fax: 6557 0256

The logo for AREDA, featuring the word "AREDA" in a bold, stylized, sans-serif font. The letters are thick and have a slightly distressed or metallic appearance. The "A" is particularly large and prominent.

Text size + -

**Enquire Transfer Fee****Vehicle Details**

Vehicle No. : SHC1506R  
 Vehicle Type : H10 - Public Transport Taxi (Motor Car)  
 Vehicle Attachment 1 : Air-Con (Taxi)  
 Vehicle Scheme : Taxi (Company)  
 Vehicle Make : HYUNDAI  
 Vehicle Model : SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO  
 Chassis No. : KMHET41VMAA784397  
 Propellant : Diesel  
 Engine No. : D4EA7335063  
 Engine Capacity : 1991 cc  
 Maximum Power Output : 110.0 kW (147 bhp)  
 Maximum Laden Weight : 2150 kg  
 Unladen Weight : 1685 kg  
 Year Of Manufacture : 2010  
 Original Registration Date : 27 May 2010  
 Lifespan Expiry Date : 26 May 2018  
 COE Category : A - Car (1600cc & below)  
 PQP Paid : \$20,470.00  
 COE Expiry Date : 26 May 2018  
 Road Tax Expiry Date : 26 Nov 2017  
 PARF Eligibility Expiry Date : 26 May 2018  
 Inspection Due Date : 26 Nov 2017  
 Intended Transfer Date : 19 Sep 2017  
 CO2 Emission: -

The current road tax expiry is 26 Nov 2017. You may renew the road tax from 27 Aug 2017 with all pre-requisite(s) fulfilled. If the road tax is renewed after 26 Nov 2017, late renewal fee(s) will be imposed. Please use [Enquire Road Tax Payable](#) to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

**Amount Payable (From 27 Nov 2017 to 26 May 2018)**

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	11.00	-	11.00
<b>Sub Total :</b>			<b>11.00</b>
Nett Road Tax Amount (After Offsetting Over Payment) :	1,982.00	-	1,982.00
<b>Total Amount Payable :</b>			<b>1,993.00</b>

**Message**

This vehicle has a road tax Over Payment of \$653.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE

CityCab PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO : SHC 1506R

DATE 9/15/2017 15:55

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet / BNC			\$ 1,151.80
	Front Fender (LH) X repair			\$ 593.00
	Front Windscreen Glass - CRA			\$ 1,015.00
	Front Windscreen Moulding - MC			\$ 60.00
	Wiper Panel Top Garnish X NN			\$ 87.40
	Roof Moulding (LH) / MC			\$ 132.30
	SUB TOTAL			\$ 3,039.50
	LESS 20%			\$ 607.90
	DISCOUNTED TOTAL			\$ 2,431.60
	Front Windscreen Sealant / MC			\$ 46.00
	Front ERP Sticker /			\$ 30.00
				\$ 76.00
	Labour Charge			\$ 1,000.00
	Panel Beating			\$ 600.00
	Spray Painting Charge			\$ 50.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 120.00
	Remove/Refix Front Windscreen Glass:			\$ 90.00
	Remove/Refix Cushion & Upholstery Front			
	TOTAL LABOUR			\$ 1,910.00
	ESTIMATE TOTAL			\$ 4,417.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:

Nett  
Nett

300  
450  
30  
40  
100  
X NN

4 Days  
lump sum repair  
After repair photos.  
Gao Qiang - 8288 0282  
18/9/17

*[Signature]*  
20/9/17

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CS/TP17017991/Gqbn2	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711 ATTN: JACKSON YEO		Date : 30-11-2017 Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SHC 1506R
Policy No.	1793533/LST	Coverage (\$)	0.00
Claim No.	AC170367	Excess (\$)	0.00
Assign From	LEE SIANG TECK	Assign Date	18/09/2017
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI SONATA	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	KMHET41VMAA784397	Colour	BLUE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	MAXXIS	6 mm
L/H Front Tyre	215/60 R16	MAXXIS	6 mm
R/H Rear Tyre	215/60 R16	MAXXIS	6 mm
L/H Rear Tyre	215/60 R16	MAXXIS	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/09/2017	Inspection Date	18/09/2017
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 600 SIN MING AVENUE CITYCAB BUILDING SINGAPORE 575733		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1506R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BONNET	BUCKLED	1,151.80	1,151.80
1	FRONT FENDER (LH)	TO REPAIR SEE LABOUR	593.00	-
1	FRONT WINDSCREEN GLASS	CRACKED	1,015.00	1,015.00
1	FRONT WINDSCREEN MOULDING	NECESSARY	60.00	60.00
1	WIPER PANEL TOP GARNISH	NOT NECESSARY	87.40	-
1	ROOF MOULDING (LH)	NECESSARY	132.30	132.30
	LESS 20% DISCOUNT		-607.90	-471.82
			<b>2,431.60</b>	<b>1,887.28</b>
<b>SPECIAL NETT ITEMS</b>				
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	FRONT ERP STICKER (SN)	NECESSARY	30.00	30.00
			<b>76.00</b>	<b>76.00</b>
<b>LABOUR</b>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT FENDER (LH).		1,000.00	300.00
	SPRAY PAINTING CHARGE.		600.00	450.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		50.00	40.00
	REMOVE/REFIX FRONT WINDSCREEN GLASS.		120.00	100.00
	REMOVE/REFIX CUSHION & UPHOLSTERY FRONT.	NOT NECESSARY	90.00	-
			<b>1,910.00</b>	<b>920.00</b>
<b>GRAND TOTAL</b>			<b>4,417.60</b>	<b>2,883.28</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE)</b>				<b>2,300.00</b>

Report Ref No. CS/TP17017991/Gqbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.