

ASS. REC. BY:

REF: CS / TP17017991 / Grb 02 Special Instruction:

Surveyor: GA**ASSIGNMENT (Office)**From (Person): Lee Siang Teck of Areca Adjusters. Date/Time: 18092017 11:23am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SHA 2574Y Insured: Public Liabilityat Workshop m/s Comfort Delgro Tel: 8491 6644of 600 Sin Ming Avenue Citycab BuildingPolicy No: 1793533 / LST Claim No: AC170364

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 11-09-2017
(Client's Record)

CA / REV / REP. / REV 24 HRS WP H.O.D. Endorsement: _____

Date/Time: 18092017 Person Contacted: Kelvin Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SHA 2574Y - NO / LCR 17010012 / H109542</u> <u>DLA: 180517</u>
<u>4/10/17</u>	<u>According to Mr Lee, No GA because of no reporting</u>
	<u>submit preli report</u>

(08/11/13)

A.S. REC. BY: Xnl

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Comfort

of _____

Insured: _____

Policy No: _____


Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHA 2574Y Yr Regn: 31 May 2011
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Sonata c.c. 1991Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMAHET41V-MBA811296Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60 R16R: 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or MAXXIS

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 18-09-17Survey held at comfort sin ming 5:10pmDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

According to Mr Lee, Bill to India sent soft copy to Areda Adjuster

RECEIVED 29 NOV 2017

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2) _____

☒ : Preli. Report☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ S + RS ____ SI

Photos

Others

TOTAL

350

Report Format : _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AREDA ADJUSTERS PL

Ref : CS/LAW17018000/Grb

195 PEARL'S HILL TERRACE
#02-63 SINGAPORE 168976

Date : 19-09-2017



Code : L125

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SHA 2574Y
Policy No.	1793533/LST	Coverage (\$)	0.00
Claim No.	AC170367	Excess (\$)	0.00
Assign From	LIM SIANG TECK	Assign Date	18/09/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Engine No.	HIDDEN	Accident Date	11/09/2017	Inspection Date	18/09/2017
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 600 SIN MING AVENUE CITYCAB BUILDING SINGAPORE 575733				

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Catherine Chong (LKK Auto)

From: Lee Siang Teck <leesiangteck@areda.com.sg>
Sent: Monday, 18 September, 2017 11:23 AM
To: assignments@lkkauto.com
Cc: Jackson Yeo
Subject: Motor assessment on 3 dmaaged taxis
Attachments: 1793533 Repair estimates.pdf

Our Ref : 1793533/LST

Dear Catherine

We refer to our telephone conversation this morning, 18 September 2017.

As discussed, please conduct motor survey on 3 damaged taxis (i.e. SHA 2574Y, SHD 3853U & SHC 1506R) for our Principal, India International Insurance Pte Ltd. The repair estimates is enclosed for your perusal.

Please contact Mr Kelvin Tan of Comfort Transportation Pte Ltd for the survey. His contact nos. :

Hand phone 8491 6644

DID 6550 8571

If you need any clarification, please contact the undersigned.

Thank you.

Best Regards

Lee Siang Teck

Areda Adjusters Pte Ltd
195 Pearl's Hill Terrace, #02-63
Singapore 168976

Tel: 6557 0258 Fax: 6557 0256

The logo for AREDA, featuring the word "AREDA" in a bold, stylized, sans-serif font. The letters are thick and blocky, with a slight shadow or 3D effect. The "A" and "E" have unique shapes with horizontal bars.

Text size + -

Enquire Transfer Fee**Vehicle Details**

Vehicle No. : SHA2574Y
 Vehicle Type : H10 - Public Transport Taxi (Motor Car)
 Vehicle Attachment 1 : Air-Con (Taxi)
 Vehicle Scheme : Taxi (Company)
 Vehicle Make : HYUNDAI
 Vehicle Model : SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO
 Chassis No. : KMHET41VMBA811296
 Propellant: Diesel
 Engine No. : D4EAB965435
 Engine Capacity : 1991 cc
 Maximum Power Output: 110.0 kW (147 bhp)
 Maximum Laden Weight: 2150 kg
 Unladen Weight: 1685 kg
 Year Of Manufacture: 2011
 Original Registration Date: 31 May 2011
 Lifespan Expiry Date : 30 May 2019
 COE Category : A - Car (1600cc & below)
 PQP Paid : \$33,834.00
 COE Expiry Date : 30 May 2019
 Road Tax Expiry Date : 30 Nov 2017
 PARF Eligibility Expiry Date : 30 May 2019
 Inspection Due Date : 30 Nov 2017
 Intended Transfer Date : 19 Sep 2017
 CO2 Emission: -

The current road tax expiry is 30 Nov 2017. You may renew the road tax from 01 Sep 2017 with all pre-requisite(s) fulfilled. If the road tax is renewed after 30 Nov 2017, late renewal fee(s) will be imposed. Please use [Enquire Road Tax Payable](#) to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 01 Dec 2017 to 31 May 2018)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	11.00	-	11.00
Sub Total :			11.00
Nett Road Tax Amount (After Offsetting Over Payment) :	1,971.00	-	1,971.00
Total Amount Payable :			1,982.00

Message

This vehicle has a road tax Over Payment of \$664.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 2574Y

MAKE :

MODEL : HYUNDAI SONATA

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

DATE 9/15/2017 15:50

Acknowledged by Repairer

Signature:

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet / BUC			\$ 1,151.80
	Radiator Grille X NN			\$ 282.10
	Radiator Grille U Moulding X NN NN			\$ 108.90
	Headlamp (LH/RH) S ?	\$	797.90	\$ 1,595.80
	Front Fender (LH/RH) / BUC	\$	593.00	\$ 1,186.00
	Front Door Mirror (LH/RH) / CRA	\$	545.50	\$ 1,091.00
	Rear Door (LH) / BUC			\$ 1,294.70
	Front Windscreen Glass / CRA			\$ 1,015.00
	Front Windscreen Moulding / MC			\$ 60.00
	Wiper Panel Top Garnish X NN			\$ 87.40
	Roof Panel Assy X Repair.			\$ 1,194.90
	Roof Moulding (LH/RH) / MC	\$	132.30	\$ 264.60
	SUB TOTAL			\$ 9,332.20
	LESS 20%			\$ 1,866.44
	DISCOUNTED TOTAL			\$ 7,465.76
	Front Windscreen Sealant / MC			\$ 46.00
	Front ERP Sticker / MC			\$ 30.00
				\$ 76.00
	Labour Charge			
	Panel Beating			\$ 1,500.00
	Spray Painting Charge			\$ 1,200.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 100.00
	Transfer of Door			\$ 120.00
	Remove/Refix Front Windscreen Glass			\$ 120.00
	Remove/Refix Cushion & Upholstery Front			\$ 90.00
	Remove/Refix Roof Top Taxi Digital Sign			\$ 150.00
	TOTAL LABOUR			\$ 3,330.00
	ESTIMATE TOTAL			\$ 10,871.76

10 Days
Wing Sun Repair
After repair photos.
Gino Qiang - 82880282
18/9/17

20/9/17

800 1200
900
30
80
60
100
80
?

Nett
Nett

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS/TP17018000/Grbn2

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711
ATTN: JACKSON YEO

Date : 30-11-2017

Code : III2



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SHA 2574Y
Policy No.	1793533/LST	Coverage (\$)	0.00
Claim No.	AC170367	Excess (\$)	0.00
Assign From	LEE SIANG TECK	Assign Date	18/09/2017

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI SONATA	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	KMHET41VMBAB11296	Colour	BLUE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	MAXXIS	6 mm
L/H Front Tyre	215/60 R16	MAXXIS	6 mm
R/H Rear Tyre	215/60 R16	MAXXIS	6 mm
L/H Rear Tyre	215/60 R16	MAXXIS	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S, N/S BODY AND ROOFTOP. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	11/09/2017	Inspection Date	18/09/2017
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 600 SIN MING AVENUE CITYCAB BUILDING SINGAPORE 575733		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 2574Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	BUCKLED	1,151.80	1,151.80
1	RADIATOR GRILLE	NOT NECESSARY	282.10	-
1	RADIATOR GRILLE U MOULDING	NOT NECESSARY	108.90	-
2	HEADLAMP (LH/RH) @\$797.90	* CHECK	1,595.80	-
2	FRONT FENDER (LH/RH) @\$593.00	BUCKLED	1,186.00	1,186.00
2	FRONT DOOR MIRROR (LH/RH) @\$545.50	CRACKED	1,091.00	1,091.00
1	REAR DOOR (LH)	BUCKLED	1,294.70	1,294.70
1	FRONT WINDSCREEN GLASS	CRACKED	1,015.00	1,015.00
1	FRONT WINDSCREEN MOULDING	NECESSARY	60.00	60.00
1	WIPER PANEL TOP GARNISH	NOT NECESSARY	87.40	-
1	ROOF PANEL ASSY	TO REPAIR SEE LABOUR	1,194.90	-
2	ROOF MOULDING (LH/RH) @\$132.30	NECESSARY	264.60	264.60
	LESS 20% DISCOUNT		-1,866.44	-1,212.62
			7,465.76	4,850.48
SPECIAL NETT ITEMS				
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	FRONT ERP STICKER (SN)	NECESSARY	30.00	30.00
			76.00	76.00
LABOUR				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF ROOF PANEL ASSY.		1,500.00	1,200.00
	SPRAY PAINTING CHARGE.		1,200.00	900.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		100.00	80.00
	TRANSFER OF DOOR.		120.00	60.00
	REMOVE/REFIX FRONT WINDSCREEN GLASS.		120.00	100.00
	REMOVE/REFIX CUSHION & UPHOLSTERY FRONT.		90.00	80.00
	REMOVE/REFIX ROOF TOP TAXI DIGITAL SIGN.	* CHECK	150.00	-
			3,330.00	2,450.00
GRAND TOTAL			10,871.76	7,376.48

Report Ref No. CS/TP17018000/Grbn2



RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1,426.64 NETT)			7,376.48
---	--	--	----------

Report Ref No. CS/TP17018000/Grbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.