

ASS. REC. BY:

REP: cs/sm017018007/Dtbn2

Special Instruction:

Surveyor

Bryan

ASSIGNMENT (Office)

From (Person):

Sherry Wong

of

SMO

Date/Time

19/9/17 10:12am

Estimated Cost

Bill to:

O) (H) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJK781C

Insured:

SJF8007D

at Workshop m/s

Teamwork Garage

Tel:

6844 2475

of Blk 53 Ubi Avenue 1 # 01-24

Policy No:

Claim No:

CMTD1703212 / AGC

Sum Insured

Excess:

Make of Veh:

D.O.A 15/9/17

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement

Date/Time:

19/9/17 10:30am

Person Contacted:

Darren

\*Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SJK781C - NA / CTI 17017833 / 24 - D.O.A: 15/9/17

SJF8007D - NA / CTI 17017833 / 24 - D.O.A: 15/9/17

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s:

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S

O/S

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

4 days Res.: Yes or No

20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Yr Regn:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond:

Steering:

Brake:

Modi:

Tyre Size:

Honda Accord cc 2354

Grey A/C: Insured / Std / NI / NA

145959 T/Radio: Insured / Std / NI / NA

K24Z21955602

MRHLP26308P020371

Good / Fair / Poor / Burnt

Inorder / Jammed / Leaked / Burnt or

Inorder / Jammed / Leaked / Burnt or

Nil / S/Rim / STD A/Rim or

F: 215/55 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 15/09/2017

D.O.I. 19/09/2017

Survey held at Technovic Page ubi

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
09/07/18	Sampo 35F8007D
	Insured 215 3850/- with 4 days J 12
	(Red: 6049.26 : 61%)

Date/Time, File Pass to?

1) 9/7 Typist

Date/Time, File Return to?

2)

Preli. Report

Final Report

Report Format :

Lump Sum / I.B.I. (\$ 3850)

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee:

Transportation:

S + R5, \$

Photos

Others

TOTAL

350

## Nivitha (LKK Auto)

---

**From:** Henry, Irene James <irene.henry@sompo.com.sg>  
**Sent:** Tuesday, 19 September, 2017 10:12 AM  
**To:** assignments  
**Cc:** Admin-D (LKKAuto)  
**Subject:** FW: PRE-REPAIR INSPECTION NOTIFICATION FOR SJK781C

**Importance:** High

Our Reference: CMTD1703212/AGC

Hi,

Kindly assign your motor surveyor, to conduct motor survey of the mentioned (SJK 781C).

Please refer to the email correspondence below.

Best Regards

**Irene Henry**

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

---

**From:** TEAMWORK GARAGE CLAIMS [mailto:claims@teamworkgarage.com]

**Sent:** Tuesday, 19 September, 2017 9:27 AM

**To:** Wong, Shi Yi Shery <Shery.Wong@sompo.com.sg>

**Cc:** Henry, Irene James <irene.henry@sompo.com.sg>; Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Han, Bernard <Bernard.han@sompo.com.sg>; claims@teamworkgarage.com

**Subject:** RE: PRE-REPAIR INSPECTION NOTIFICATION FOR SJK781C

**Importance:** High

Dear Sir,

We have agreed and selected the surveyor / surveyor company proposed by you to conduct the pre-repair inspection as a single joint expert whereby the cost of the pre-repair survey carried out by single joint expert will be bear by you.

We have selected :

LKK AUTO CONSULTANTS

as the motor surveyor / surveyor company named in your attached list.

Kindly forward your assignment to them asap so that we can arrange for the survey with them.

*\*Do get the surveyor / surveyor office to check with us on the availability of the car at the workshop before sending their surveyor down for PRI survey. We'll not be held responsible for wasted trips made to the workshop.*

Darren Ng  
Teamwork Garage Pte Ltd  
53 Ubi Avenue 1  
#01-24 Paya Ubi Industrial Park  
Singapore 408934  
Tel: 68442475  
Fax: 68442474

---

**From:** Wong, Shi Yi Shery [<mailto:Shery.Wong@sompo.com.sg>]  
**Sent:** Friday, September 15, 2017 3:15 PM  
**To:** [claims@teamworkgarage.com](mailto:claims@teamworkgarage.com)  
**Cc:** Henry, Irene James; Chan, Shu Hui Agnes; Han, Bernard  
**Subject:** FW: PRE-REPAIR INSPECTION NOTIFICATION FOR SJK781C  
**Importance:** High

Our Reference: CMTD1703212/AGC  
Your Reference: SJK781C

Date: 15<sup>TH</sup> September 2017

Without Prejudice

BY EMAIL ONLY

Attention:

M/S TEAMWORK GARAGE PTE LTD

ACCIDENT INVOLVING SJK781C, SJF8007D & SLP5464K ON 15.09.17

Dear Sir

We refer to your Notice of Accident via email dated 15/09/2017.

Please be informed that Agnes is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

**Pre-Repair Survey**

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Ma Chin Fook (North area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

**Shery Wong**

Claims Division

T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

**From:** Teamwork Garage Pte Ltd [<mailto:claims@teamworkgarage.com>]

**Sent:** Friday, September 15, 2017 2:56 PM

**To:** Motor Survey; claimsreport; Henry, Irene James

**Cc:** [claims@teamworkgarage.com](mailto:claims@teamworkgarage.com)

**Subject:** PRE-REPAIR INSPECTION NOTIFICATION FOR SJK781C

**Importance:** High

**WITHOUT PREJUDICE**

**OUR REF: 1709-13**

YOUR REF: SJF8007D

Dear Sir/Madam,

**PRE-REPAIR INSPECTION FOR SJK781C  
ACCIDENT INVOLVING SJK781C, SJF8007D & SLP5464K ON 15.09.17**

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

Please let us have your list of surveyors for us to select as stated in the Practice Direction – Amendment No. 1 of 2016; Pre-action Protocol within 2 working days as of the date of our notice to you.

**Please take note: We will not entertain any of your surveyor calling us for the above inspection, without you giving us your list of surveyors for us to select by the Practice Direction of Pre-repair Inspection.**

Thank you.

Regards,

**Alison**  
Teamwork Garage Pte Ltd  
Blk 53 Ubi Avenue 1  
#01-24  
Paya Ubi Industrial Park  
Singapore 408934  
Tel: 6844 2475  
Fax: 6844 2474

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	15/09/2017 11:45
Date Of Accident	15/09/2017 10:15
Exact Location Of Accident	KPE TUNNEL TWDS CITY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJK781C
Insured/Policyholder	
Name Of Registered Owner	M/S MY CAR CONSULTANT PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97915102
Vehicle Particulars	
Manufacturer	HONDA
Model	ACCORD.
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMHCSN1724191700
Cover Note Number	
Driver	
Name of Driver	WANG BIN
NRIC No	S8577447F
Date Of Birth	13/01/1985
Occupation	OUTDOOR
Date Of Driving Pass	21/04/2015
Driving Experience	2 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97915102
Fax Number	
Contact Number	OFFICE-97915102
Email Address	NOEMAIL

Address BLK 257A COMPASSVALE ROAD #02-515  
 Postcode 541257  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - HIRER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident CHAIN COLLISION  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

REFER TO STATEMENT.

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJF8007D  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Name of Driver MOHAMED SUMAIMI BIN MOHAMED SULAIMAN  
 NRIC/Passport Number S1365061F  
 Contact Number 84846405  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

#### Details of Witness

Name  
 Phone Number  
 Email Address

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLP5464K  
 Vehicle Make/Model/Colour





### SKETCH PLAN

3. You must report correctly if you are involved in an accident involving a motor vehicle.

4. The report must be completed by the Police officer and/or the Authorized signee.

5. The report must state that the report is **truthful and accurate as possible**. Any officer responsible for a false report is liable for disciplinary action and is liable to **rescind police liability**.

6. There is a **statutory maximum penalty** (expensive compensation) will be imposed on anyone who is negligent in reporting an accident.

7. **Any false reporting may be referred to the Police for investigation**.

8. The report will be forwarded to the relevant of the Road Transport Department and used in the investigation of the accident and for issuing and final report of the report giving a new vehicle licence or other application for a renewed licence.

9. Before completion of the report by the signee, the signee should be fully conversant with the report and the signee should sign the report and make it available to the signee.

10. **Consent under the Personal Data Protection Act (PDPA)**

(a) I consent to the collection, usage and disclosure of

(i) my name, my workplace and the General Insurance Association of Singapore ("GIAS") may be permitted to collect, use, disclose and/or process my **PERSONAL DATA** (personal information or contact information) and any other personal information provided by me or possessed by my insurer (collectively, the **"Personal Information"**) and disclose and/or process such personal information to all entities who have insured with us) involved in the accident (all members of the household who have insured with us) in connection with the accident (all the information collected by the **"Insurers"**), the insurers, Insurance Corporation of Singapore, a company of Singapore and any relevant government agency and/or entity in the process for the purposes of

(ii) conducting an investigation and dealing with my claim involving the vehicle of the motor vehicle involved in the accident relating to the claim

(iii) in conducting the claims and/or my claims

(iv) conducting an investigation and dealing with my claim and/or processing my claim and/or my claim

(v) conducting my claims involving the making of the Insurance Statement (including reports, documents, records, and other material) and/or disclosure of my personal data about the vehicle of the motor vehicle involved in the accident (including my personal data about the vehicle of the motor vehicle involved in the accident) and/or

(vi) complying with applicable law or Administrative, regulatory or judicial order dealing with my claim, including the **Purposes**;

(ii) an insurance policy, which is issued and/or involved in this accident and the insurer's Insurance Policy may be permitted to collect, use, disclose and/or process my **PERSONAL INFORMATION** for the purposes of the above purposes; and

(iii) my **PERSONAL INFORMATION** may be disclosed by any of the Insurers and/or to the third party who is involved in the accident (including the Insurers, law firms, which may be located outside of Singapore, for one or more of the above purposes).

(c) My **PERSONAL INFORMATION** is also being collected and used to complete claims history for the purpose of rating between insurance companies and management of claims and adjustment (MIS).

(d) The information collected under (b) above may be shared with

(i) the Insurers and/or any other third parties that assist in marketing, managing, controlling or managing brand reputation, law enforcement and government agencies as reasonably required for the purposes stated; or

(ii) for complying with requirements under any regulatory laws or legal orders.

Reporting Center No. 00000153250001  
Name  
ADDRESS

# Accident Sketch Plan

SKETCH PLAN



A - 03/08/2010

B - 03/08/2010

C - 03/08/2010

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

--

My car was travelling along the first lane of KPE tunnel towards City. The vehicle in front of me stopped and my car also stopped without any contact and with a safe distance from the front vehicle. All of a sudden, I felt an impact from the rear portion of my car. I came out of my car and found out that in total, there were 3 vehicles involved in the accident.


## DECLARATION

(We declare the foregoing particulars are true in every respect)

Policyholder's Signature  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Reporting Centre/Insurer's Signature  
Name  
Date & Time



Teamwork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475 Fax : 6844 2474

E-mail : claims@teamworkgarage.com

Register number : 201015366H

ROC number : 201015366H

3RD PARTY CLAIM ESTIMATION

Sompo Insurance Pte Ltd

50 Raffles Place , #05-01/06

Singapore Land Tower

Singapore 048623

Vehicle number : SJK781C  
Make / Model : HONDA/ACCORD  
Chassis number : MRHCP26308P020371  
Accident date : 15 September 2017  
Reference : 1709-13

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		769.10
1	REAR BUMPER <i>distorted</i>	941.29 ✓
2	REAR BUMPER SIDE RETAINER <i>SVL N/S o/s broken</i>	39.20 250.30 ✓
1	REAR BUMPER REINFORCEMENT <i>bt</i>	452.02 ✓
2	REAR BUMPER REFLECTOR <i>NH</i>	182.60 X
1	REAR END PANEL <i>req</i>	643.38 X
1	END PANEL GARNISH <i>SVL</i>	282.91 X
1	BOOTLID <i>bt</i>	791.80 ✓
1	BOOTLID EMBLEM LOGO -H <i>NH</i>	49.80 ✓
1	BOOTLID EMBLEM - ACCORD <i>NH</i>	53.00 ✓
1	BOOTLID EMBLEM -I-VTEC <i>NH</i>	42.93 ✓
2	BOOTLID LAMP <i>N/S NH o/s mounting broken</i>	267.90 515.80 ✓
1	BOOTLID LOCK <i>NH</i>	315.83 X
1	BOOTLID LOCK STRIKER <i>NH</i>	65.00 X
1	BOOTLID INNER TRIM <i>NH</i>	281.34 X
2	REAR FENDER INNER TRIM <i>NH</i>	482.48 X
2	REAR TAILLAMP <i>N/S NH o/s mounting crack</i>	341.95 683.90 ✓
2	REAR TAILLAMP SEALER <i>SVL</i>	80.00 X
1	REAR EXHAUST ASSY <i>bt</i>	1082.80 1351.30 ✓
2	REAR EXHAUST MOUNTING <i>NH</i>	80.00 X
		7545.68
Less 20 %		1886.42
Subtotal		5659.26
Balance C/F		5659.26
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		6036.54
Balance B/F		5659.26
1 SET	REAR BUMPER CLIP <i>NH</i>	60.00 301-
1 SET	REAR FENDER INNER TRIM CLIP <i>NH</i>	50.00 X
1 SET	REAR REVERSE SENSOR <i>Dam</i>	400.00 2201-
1	JOINT SEALANT <i>NH</i>	150.00 X
1	REAR NUMBER PLATE <i>NH</i>	70.00 X
Subtotal		730.00
Balance C/F		6389.26

Vehicle number : SJK781C

Make Model : HONDA/ACCORD

Reference : 1709-13

Qty Particulars

Unit Price - SGD \$

<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	6389.26
1	CHECK REAR WIRING AND LIGHTING SYSTEM	60.00 30/-
2	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	200.00 80/-
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 40/-
4	REMOVE AND RENEW REAR EXHAUST ASSY	150.00 60/-
5	TRANSFER PARTS, ATTACHEMENT FROM OLD BOOTLID TO NEW	200.00 60/-
6	PANEL BEATING ON AFFECTED AREAS	1400.00 600/-
7	SPRAY PAINTING ON AFFECTED AREAS 1510/-	1200.00 600/-
8	APPLY ANTI RUST ON AFFECTED AREAS	150.00 40/-
	Subtotal	3510.00
	Grand total	10276.54
		9899.26
		4864.40
		1/5 3850/-

19/09/2017 @ 1100hrs

Not Authn

L/Sing

4 days

ryan

LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17018007/Dtbn2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 11-07-2018



Code : SMO

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJF 8007D	Veh. Inspected	SJK 781C
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1703212/AGC	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	19/09/2017

## 2. Vehicle Particulars & Condition

Make & Model	HONDA ACCORD	c.c	2354
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MRHCP26308P020371	Colour	GREY
Odometer	145959	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	CONTINENTAL	5 mm
L/H Front Tyre	215/55 R17	CONTINENTAL	5 mm
R/H Rear Tyre	215/55 R17	CONTINENTAL	5 mm
L/H Rear Tyre	215/55 R17	CONTINENTAL	5 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

## 5. General Information

Accident Date	15/09/2017	Inspection Date	19/09/2017
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 781C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DISTORTED	941.29	769.10
2	REAR BUMPER SIDE RETAINER	O/S BROKEN / N/S SERVICEABLE	250.30	39.20
1	REAR BUMPER REINFORCEMENT	BENT	452.02	452.02
2	REAR BUMPER REFLECTOR	NOT FITTED	182.60	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	643.38	-
1	END PANEL GARNISH	SERVICEABLE	282.91	-
1	BOOTLID	BENT	791.80	791.80
1	BOOTLID EMBLEM LOGO-H	NECESSARY	49.80	49.80
1	BOOTLID EMBLEM-ACCORD	NECESSARY	53.00	53.00
1	BOOTLID EMBLEM-I-VTEC	NECESSARY	42.93	42.93
2	BOOTLID LAMP	O/S MOUNTING BROKEN / N/S NOT NECESSARY	515.80	257.90
1	BOOTLID LOCK	NOT NECESSARY	315.83	-
1	BOOTLID LOCK STRIKER	NOT NECESSARY	65.00	-
1	BOOTLID INNER TRIM	NOT NECESSARY	281.34	-
2	REAR FENDER INNER TRIM	NOT NECESSARY	482.48	-
2	REAR TAILLAMP	O/S MOUNTING CRACKED / N/S NOT NECESSARY	683.90	341.95
2	REAR TAILLAMP SEALER	SERVICEABLE	80.00	-
1	REAR EXHAUST ASSY	BENT	1,351.30	1,082.80
2	REAR EXHAUST MOUNTING	NOT NECESSARY	80.00	-
	LESS 20% DISCOUNT		-1,509.14	-776.10
			6,036.54	3,104.40
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	60.00	30.00
1	SET REAR FENDER INNER TRIM CLIP (SN)	NOT NECESSARY	50.00	-
1	SET REAR REVERSE SENSOR (SN)	DAMAGED	400.00	220.00
1	JOINT SEALANT (SN)	NOT NECESSARY	150.00	-
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	70.00	-
			730.00	250.00

Report Ref No. CS/SMO17018007/Dtbn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	CHECK REAR WIRING AND LIGHTING SYSTEM.		60.00	30.00
	REMOVE AND REFIT REAR LINING,TRIM AND GASNISH.		200.00	80.00
	REMOVE AND RENEW REAR REVERSE SENSOR.		150.00	40.00
	REMOVE AND RENEW REAR EXHAUST ASSY.		150.00	60.00
	TRANSFER PARTS,ATTACHMENT FROM OLD BOOTLID TO NEW.		200.00	60.00
	PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,400.00	600.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,200.00	600.00
	APPLY ANTI RUST ON AFFECTED AREAS.		150.00	40.00
			3,510.00	1,510.00
	<b>GRAND TOTAL</b>		<b>10,276.54</b>	<b>4,864.40</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,850.00</b>

Report Ref No. CS/SMO17018007/Dtbn2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.