Add Fee:

Paport Format:

Lump Sum / I.B.I: (\$ 7980 . 20

Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

10

210

S+RS, SI

Photos

Others



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

WANTED STATE OF	A PARTIE OF THE PARTY OF THE PA	nationale Des Experts En Automo	ACIANA
AIG ASIA PACIFIC I	NSURANCE PTE LTD	Ref : CC3/AIG170180)42/Atb
8 SHENTON WAY: CHARTIS BUILDING SINGAPORE 079120	,	Date: 19-09-2017	
		Code: AIG	***************************************
	Policy Par	ticulars :- OWN DAMAGE	
Insured Veh.		Veh. Inspected	SJG 5111A
Policy No.	1700016560	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	19/09/2017
2.	Vehicle	Particulars & Condition	MINISTER OF THE STREET
Make & Mode	ol .	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	•	Steering	
Brakes		Modification	
General			
3.	C	onditions of Tyres	
	Size	Make	Balance
R/H Front Ty	re		mm
L/H Front Ty	re		mm
R/H Rear Tyr	re e		mm
L/H Rear Tyr			mm
4.	Des	cription of Damages	
5. English No.	A STATE OF THE STA	eneral Information	19/09/2017
Accident Da	Control of the Contro	Inspection Date	19/09/2017
Survey held		ES PTE LTD	
	55 UBI ROAD 1 . SINGAPORE 408699		
5a.		Remarks	
TANTUE MADE	ET VALUE IS S\$(ES'DANCE TO YOUR INSTRUCTION	T. AVERAGE) ONS, WE HAVE AUTHORISED	REPAIRS.

Denise Tay (LKKAuto)

From:

Denise Tay (LKKAuto)

Sent:

Thursday, 21 September, 2017 3:32 PM

To:

Claims SUR

Cc: Subject:

SJG 5111A AIG OD

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle SJG 5111A (Excess \$300/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with:

*SJG5111A (6028807856SG)

OD Sep 14 2017 8:30AM [TANG WEIXIANG, THOMAS] Premium Automobiles Pte Ltd

Reply | Reply All | Mark as Unread | Print Message | Delete Message | Forward

AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 21/09/2017 13:38 PM.

From AIG Asia
To LKK_HQ

Subject

Alert - Adj Mandate Approved (S\$8856.00) - SJG5111A - Claim Handler: Chan, Kian Meng

Approved:8856.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Text size +

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

0351E

Vehicle Details

Vehicle No.:

SJG5111A

Vehicle to be Exported: No

Intended De-registration 20 Sep 2017

Date:

Vehicle Make:

AUDI

Vehicle Model:

A4 1.4 TFSI S TRONIC (NAV)

Primary Colour:

Red

Manufacturing Year:

2017

Engine No.:

CVN038980

Chassis No.:

WAUZZZF46HA163038

Maximum Power

Output:

110.0 kW (147 bhp)

Open Market Value:

\$32,490.00

Original Registration

13 Jun 2017

Date:

Transfer Count:

0

Actual ARF Paid:

\$27,486.00

Intended PARF Rebate Details

First Registration Date: 13 Jun 2017

PARF Eligibility:

PARF Eligibility Expiry

12 Jun 2027

PARF Rebate Amount: \$20,614.00

Intended COE Rebate Details

COE Expiry Date:

12 Jun 2027

COE Category:

B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$50,110.00

COE Rebate Amount:

\$48,754.00

Total Rebate Amount: \$69,368.00

The information contained herein is correct as at 20 Sep 2017

OK


Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer. Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | Privacy Statement | Terms of Use | Disclaimer | Rate the Website | Rate this e-Service Last updated on 27 Aug 2017 at 01:09 AM



REPUBLIC OF SINGAPORE

51E





Name

TANG WEIXIANG, THOMAS

唐伟祥

CHINESE Date of birth

22-04-1983 M Country of birth \$8310351E

Country of birth SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cers=< 3000kg with =<7 passengers, exclusive 16 Jan 2004 of the driver; and other motor vehicles =< 2500kg

Licence No. S8310351E

NP 428A :

SINGAPORE 210663 NRIC No: S8310351E

Date: 09/08/2016

4317213



Date of Issue 17-11-2008

APT BLK 663 BUFFALO ROAD #08-11 SINGAPORE 210663



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder

: TANG WEIXIANG, THOMAS

Period of Insurance Engine No.

: 13 Jun 2017 To 12 Jun 2018

Chassis No.

: CVN038980 : WAUZZZF46HA163038 Vehicle No. Policy No.

: SJG5111A : 1700016560

Endorsement No.

Issued Date

: 16 Jun 2017

ABOUT THE COVER

Make/Model

: AUDI/A4 1.4 TFSI S tronic

Engine Capacity/Tonnage : 1,395.00 CC

Sum Insured : Market Value

First Year of Registration : 2017

Driver Restriction

: NA

Off Peak Car : No

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if halshe ments the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or thexperienced Driver Excess" ("YIDR") if You are or Your Authorisad Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience

Age Condition

: All Age Condition

imitation as to use*

be only for social, domestic and pleasure purposes and for the Policyholder's tusiness.

This Policy does not cover use for hire or reward, driving fulfion, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with Motor Triade.

This Policy does not cover use for hire or reward, driving fulfion, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with Motor Triade.

Loss of Use (15 days)

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be

EXCESS

Fire -\$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

TANG WEIXIANG, THOMAS - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Audi Custoiner Service Center, Add: 55 Ubi Road 1 Singapore 408699 63682323

For other Approvett Reporting ContrastAtG Authorised Repairers, please contact our 24-hour accident emergency hottine at +85 6338 6200. Atternatively, you may refer to AtG website www.aig.com.sg or AtG SG Mobile App. Samply search and download: "AtG SG" from iT unles or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189). Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125200

PREMIUM LEASING - AP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE Stuffany Loh

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediale assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related).
- Advice on Mofor Claims procedures
- Medical Referral Assistance

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(les).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons Correspondences from third partyles) to AIG immediately.

If no one is injured in the accident:

- You are not required to make any piolice report.
- Record vehicle number, name and address, insurance company and policy number of the other griver(s) and vehicle(s). Collect details (name, address and contact number) of witnesses and/or by to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the accumstances of the accident.
- Record validate number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable,
- Collect details (name, wildress and contact number) of witnesses and/or try to take photographs of the scene of the accident
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

15 DAYS LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your policy. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company eserves the right to verify the identity of the holder of the CI.

The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to you.

Steps to activate Loss of Use Car Replacement Benefit and Important Information relating to the Benefit:

- To activate your Loss of Use Car Replacement Benefit, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
- Your rental car will be made available within 3 working hours after you contact the Rental Car Company.
- At the time of collection of the Rental Car, the original Policy Schedule issued by AIG and a copy of the Accident Report from Audi Customer Service Centre must be produced to the Rental Car Company.
- 4. The number of days of loss of use entitlement is based on the period your vehicle is in the repair workshop subject to a maximum of 15 days.
- Rental cars are strictly for use in Singapore only.
- 6. Any extension of use of rental car beyond the period approved by AIG's surveyor will be chargeable by the Rental Car Company on a per day basis and will not be covered under the Loss of Use Car Replacement Benefit but will be payable by you to the Rental Car Company directly.
- Upgrade of Rental Car is available upon request subject to any additional charges by the Rental Car Company. Any costs relating to such upgrade will not be covered under the Loss of Use Car Replacement Benefit but will be payable by you to the Rental Car Company directly
- 8. The rental car will be delivered to you (within Singapore), and YOU MUST RETURN IT TO Audi Customer Service Centre upon collection of your accident car.

'ental Car Company: Premium Automobiles Pte. Ltd.

Activation Hotline: 64741223 55 Ubi Road 1 Singapore 408699

Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 1pm

"The Rental Car Company's Terms & Conditions apply (i.e. refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc.)

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Accident Repairs Estimate Workshop : Ubi Road 1 6366 2323 Contact No 6841 1183 Fax No

PA/OD/0895/2017/NK Reference

14-Sep-17 Date

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Telephone

Vehicle No

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Mr. Tang Wei Xiang, Thomas Owner's Name

Address Blk 663 Buffalo Road

#08-11

Singapore 210663 HP +65 96238918 Own Damage Claims

Type of Claim 1700016560 Policy No. SJG 5111 A

Audi A4 Sedan 1.4 TFSI Model Code

lun-17 Model / Year CVN 038980 **Engine No**

WAUZZZF46HA163038 Chassis No

Mileage Date In Liability **Excess Cost**

Johnny Boo / Allan Wu Estimated By

14-Sep-17 **Accident Date** Place of Accident Hampshire Road

Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJG 5111 A

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer lhs front and rear door's multi lock system and power window devices.	S/N	\$ 560.00	
2	To dismantle and renew lhs front and rear doors, align to position. Repair lhs sill panel and rear fender. Reinstall all parts removed.		\$ 2,400.00	1300
3	To respray lhs front and rear doors, door handles, lhs sill panel and lhs rear fender. To carry out stone chip treatment.		\$ 3,500.00	1925
4	To renew lhs rear rim and carry out wheel alignment.	S/N	\$ 280.00	/ /
5	To carry out diagnostic check.	S/N	\$ 192.00	/ /
	TOTAL LABOUR CHARGES	:	\$ 6,932.00	1) 2)

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJG 5111 A

			Damage Part	s & Prices
S/N	Parts Description	S	NETT RE	MARKS
1	FRONT DOOR Devled	\$	1,855.00	- 1484
2	FRONT DOOR OUTER SEAL LH	\$	167.00	- 133.20
	BONDING AGENT HE NEW	\$	42.00	1 >
3	FRONT DOOR ATTACHMENTS PARTS The New	\$		7 ×
4 5	DOOR CATCH	s	89.00	x. V
6	TRIM PLATE FOR DOOR HANDLE LH	\$	21.00	
7	REAR DOOR LH Dested	\$	1,745.00	- 1396
8	REAR DOOR OUTER SEAL LH	\$	167.00	- 133 20
9	BONDING AGENT THE NEW	\$	42.00	2 6
10	SEALING STRIP THE NEW	\$	14.00	7 9
11	DOOR CATCH	\$	102.00	+ 6
12	TRIM PLATE FOR DOOR HANDLE LH	\$	21.00	4.4
13	ALUMINIUM RIM REAR LH	\$	465.00	- 372
14	STONE CHIP Men	S/N \$	180.00	<i>k</i> .
15	SUNDRIES There well	\$	300.00	7 \$ 4.80
10	TOTAL SPARE PARTS	: \$	5,650.00	- 1.3
	TOTAL LABOUR CHARGES	\$	6,932.00	<u></u>
	GRAND TOTAL	\$	12,582.00	_
		_		- 50

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Hot Authorsed, 05 Ry

Please Note

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) dur = q resurvey
- Parts prices at a subject to come at all on.
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature: Date:

Johnny Boo

Body Repair Manager

Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1

Contact No : 6366 2323 Fax No : 6841 1183

Reference : PA/OD/0895/2017/NK

Date : 14-Sep-17

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tang Wei Xiang, Thomas

Address : Blk 663 Buffalo Road

#08-11

Hi Adrian

5 days of repairs - ok - jb

Singapore 210663 **Telephone** : HP +65 96238918

Type of Claim : Own Damage Claims

Policy No. : 1700016560

Vehicle No : SJG 5111 A

Model Code : Audi A4 Sedan 1.4 TFSI

 Model / Year
 : Jun-17

 Engine No
 : CVN 038980

Chassis No : WAUZZZF46HA163038

Mileage :

Date In :

Estimated By : Johnny Boo / Allan Wu

Accident Date : 14-Sep-17
Place of Accident : Hampshire Road

Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJG 5111 A

S/N	Nature of Jobs		Estimated Charges		urveyor's mmendation
1	To remove and transfer lhs front and rear door's multi lock system and power window devices.	S/N	\$ 560.00	\$	560.00
2	To dismantle and renew lhs front and rear doors, align to position. Repair lhs sill panel and rear fender. Reinstall all parts removed.		\$ 2,400.00	\$	1,500.00
3	To respray lhs front and rear doors, door handles, lhs sill panel and lhs rear fender. To carry out stone chip treatment.		\$ 3,500.00	\$	1,925.00
4	To renew lhs rear rim and carry out wheel alignment.	S/N	\$ 280.00	S	280.00
5	To carry out diagnostic check.	S/N	\$ 192.00	\$	192.00
	TOTAL LABOUR CHARGES	:	\$ 6,932.00	\$	4,457.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJG 5111 A

				Damage Pa	rts &	Prices
S/N	Parts Description		S	NETT RE	MARI	KS
1	FRONT DOOR		\$	1,855.00	\$	1,484.00
2	FRONT DOOR OUTER SEAL LH		\$	167.00	\$	133.20
3	BONDING AGENT		\$	42.00		
4	FRONT DOOR ATTACHMENTS PARTS		\$	440.00		
5	DOOR CATCH		\$	89.00		
6	TRIM PLATE FOR DOOR HANDLE LH		\$	21.00		
7	REAR DOOR LH		\$	1,745.00	\$	1,396.00
8	REAR DOOR OUTER SEAL LH		\$	167.00	\$	133.20
9	BONDING AGENT		\$	42.00		
10	SEALING STRIP		\$	14.00		
11	DOOR CATCH		\$	102.00		
12	TRIM PLATE FOR DOOR HANDLE LH		\$	21.00		
13	ALUMINIUM RIM REAR LH		\$	465.00	\$	372.00
14	STONE CHIP	S/N	\$	180.00		
15	SUNDRIES		\$	300.00	\$	4.80
	TOTAL SPARE PARTS		\$	5,650.00	\$	3,523.20
	TOTAL LABOUR CHARGES		\$	6,932.00	\$	4,457.00
	GRAND TOTAL		\$	12,582.00	\$	7,980.20

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu

Claims Consultant

...CLAIM SUBFOLDER...(Pending for Survey Report)

	BFOLDER TRAC	Est Submitted	Adj Assigned	Adi Rpt	Adi Submitt	ed Ins Auth'ed	Status
Case	Notified 19 Sep 2017	est submitted	19 Sep 2017 15:02 Edit Adj Rpt	S\$7,980.20 Edit Estimates	S\$7,980.2 View Rpt	0	Pending for Survey Report Cancel Case
	Main	Refer	ence	Claim De	tails \	Documents	Show All
CLATMS	SUBFOLDER DET	AILS	AND DESCRIPTIONS			[Created by in	nsurer]
Insured		TANG WEIXIA	NG, THOMAS, @HOTMAIL.COM	ID: S8310351E,	Tel: +659621	7051, Email:	
Vehicle	Reg. No.:	SJG5111A		Date of	Loss:	14/09/2017 08:	00 - :59
Claim Ty		OD / 602880	07856SG	Policy/	Cover Note No	.: 1700016560 (C	omprehensive)
				Excess		5\$300.00	
Repaire	r:	Premium Aut	omobiles Pte Lt	d (UBI) 55 Ubi A	toad 1, 408699	Ubi - Tel: 67689828/9	9827/9911
Handlin	g Insurer:	kianmena char	main com			00 [Handled by Cha	
Adjuste	r:	28/09/2017		200 2000			ig] [Final Rpt due
Driver/	Custodian:	TANG WEIXIA	NG, THOMAS (34	/ Male), NRIC:	S8310351E, T	fel: +6596217051	
ASSOCI	ATED MAIL REG	CEIVED				View All	Compose Case Mail
- 410 (SG (21/09/2017):	Alert - Adj Mano SJG5111A / OD	date Approved (/ 14/09/2017	S\$8856.00) - 5 / Coverage & E	JG5111A - Cla xcess update	im Handler: Chan, K	(ian
• AIG_	20 (20) 1						
AIG_S	SOCIATED TAS	ĸs		View	All Search T	Completed On	w Task Complete

Claim Documents

*SJG5111A (6028807856SG) OD

Sep 14 2017 8:00AM [TANG WEIXIANG, THOMAS] Premium Automobiles Pte Ltd

	pload Documents		1 per p	age 🔻	0
/ide		the state of the last (URI)		Thumbnail	Print
No:	The state of the s	Premium Automobiles Pte Ltd (UBI) Video - Accident	0	Load MP4	
1		Linked Accident Report Documents)	-	2300	
			1 per p	age 🔻	V
Asse	essment Reports	the temperature (HO)		Thumbnail	Print
No	Control of the Contro	LKK Auto Consultants Pte Ltd (HQ)	0	Load HTM	
1	20/09/17 09:53	Adjuster Immediate Advice			
			3 per j	page 🔻	J
	tos/Images	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
No	and the state of t	General View	6	Load JPG	1
1	20/09/17 09:55	General View	0	Load JPG	V
2	20/09/17 09:55		0	Load JPG	V
3	20/09/17 09:55	General View	0	Load JPG	7
4	20/09/17 09:55	General View	0	Load JPG	V
5	20/09/17 09:55	General View	0	Load JPG	V
6	20/09/17 09:55	General View	0	Load JPG	V
7	20/09/17 09:55	General View	_	100500000000000000000000000000000000000	(V)
8	20/09/17 09:55	General View	0	Load JPG	
9	20/09/17 09:55	General View	0	Load JPG	V
10	20/09/17 09:55	General View	0	Load JPG	7
11	20/09/17 09:55	General View	0	Load JPG	4
12		General View	0	Load JPG	1
	The state of the s	General View	0	Load JPG	1
13		General View	0	Load JPG	1
14		General View	0	Load JPG	J
15	20/09/17 09:55	General view			
			1 per	page 🔻	V
	cumentation	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
No	20/09/17 09:56	Singapore Accident Statement	0	Load PDF	
2		WORKSHOP ESTIMATE	0	Load PDF	
3		Drivers Driving License	0	Load PDF	-
100		Certificate of Insurance	0	Load PDF	-
4		WORKSHOP INVOICE	0	Load PDF	-
5	31/01/18 14:02	DISCHARGE VOUCHER	0	Load PDF	

Linked Accident Report Documents

			1 per	page 🔻	J
Vid	eo			Thumbnail	Print
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	0	Load MP4	
1	14/09/17 11:47	Video - Accident	-	2000	
	h eta eta		1 per	page 🔻	V
Ass	essment Report	's		Thumbnail	Print
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	0	Load HTM	
1	14/09/17 11:50	Accident Statement		1	
			3 per	page 🔻	7
Pho	otos/Images				

1 14/09/17 11:44 Accident Photo 2 14/09/17 11:44 Accident Photo 3 14/09/17 11:44 Accident Photo 4 14/09/17 11:44 Accident Photo 5 14/09/17 11:44 Accident Photo 6 14/09/17 11:44 Accident Photo 7 14/09/17 11:44 Accident Photo 8 14/09/17 11:44 Accident Photo 9 14/09/17 11:44 Accident Photo 1 Load JPG 9 14/09/17 11:44 Accident Photo 1 Load JPG 10 14/09/17 11:44 Accident Photo	Print	Thumbnail		Finalized On Premium Automobiles Pte Ltd (UBI)	0.1
2 14/09/17 11:44 Accident Photo 3 14/09/17 11:44 Accident Photo 4 14/09/17 11:44 Accident Photo 5 14/09/17 11:44 Accident Photo 6 14/09/17 11:44 Accident Photo 7 14/09/17 11:44 Accident Photo 8 14/09/17 11:44 Accident Photo 9 14/09/17 11:44 Accident Photo 10 14/09/17 11:44 Accident Photo 11 14/09/17 11:44 Accident Photo 12 14/09/17 11:44 Accident Photo 13 Load JPG 14/09/17 11:44 Accident Photo 15 Load JPG 16 14/09/17 11:44 Accident Photo 17 14/09/17 11:44 Accident Photo 18 Load JPG 19 14/09/17 11:44 Accident Photo 19 14/09/17 11:44 Accident Photo 10 14/09/17 11:44 Accident Photo 11 14/09/17 11:44 Accident Photo 12 14/09/17 11:44 Accident Photo 13 Load JPG 14 14/09/17 11:44 Accident Photo 15 Load JPG 16 14/09/17 11:44 Accident Photo 17 14/09/17 11:44 Accident Photo 18 Load JPG 19 14/09/17 11:44 Accident Photo 19 14/09/17 11:44 Accident Photo 10 14/09/17 11:44 Accident Photo 10 14/09/17 11:44 Accident Photo 10 14/09/17 11:44 Accident Photo 11 14/09/17 11:44 Accident Photo 12 14/09/17 11:44 Accident Photo 13 Load JPG	V	Load JPG	0	The state of the s	*+
3 14/09/17 11:44 Accident Photo 4 14/09/17 11:44 Accident Photo 5 14/09/17 11:44 Accident Photo 6 14/09/17 11:44 Accident Photo 7 14/09/17 11:44 Accident Photo 8 14/09/17 11:44 Accident Photo 9 14/09/17 11:44 Accident Photo 10 14/09/17 11:44 Accident Photo 11 14/09/17 11:44 Accident Photo 12 14/09/17 11:44 Accident Photo 13 Load JPG 14/09/17 11:44 Accident Photo 15 Load JPG 16 14/09/17 11:44 Accident Photo 17 14/09/17 11:44 Accident Photo 18 Load JPG 19 14/09/17 11:44 Accident Photo 19 14/09/17 11:44 Accident Photo 10 14/09/17 11:44 Accident Photo 11 14/09/17 11:44 Accident Photo 12 14/09/17 11:44 Accident Photo 13 Load JPG 14/09/17 11:44 Accident Photo 15 Load JPG 16 Thimbialized On Premium Automobiles Pte Ltd (UBI)	V	Load JPG	0	1400/11 1111	
4 14/09/17 11:44 Accident Photo 5 14/09/17 11:44 Accident Photo 6 14/09/17 11:44 Accident Photo 7 14/09/17 11:44 Accident Photo 8 14/09/17 11:44 Accident Photo 9 14/09/17 11:44 Accident Photo 10 14/09/17 11:44 Accident Photo 11 14/09/17 11:44 Accident Photo 12 14/09/17 11:44 Accident Photo 13 Load JPG 14/09/17 11:44 Accident Photo 15 Load JPG 16 14/09/17 11:44 Accident Photo 17 14/09/17 11:44 Accident Photo 18 Load JPG 19 14/09/17 11:44 Accident Photo 19 14/09/17 11:44 Accident Photo 10 14/09/17 11:44 Accident Photo 10 14/09/17 11:44 Accident Photo 11 14/09/17 11:44 Accident Photo 12 14/09/17 11:44 Accident Photo 13 Load JPG 14/09/17 11:44 Accident Photo 15 Load JPG 16 Thumbnail	1	Load JPG	0	14/03/17 11117 /100000111 /10000	
5 14/09/17 11:44 Accident Photo 1 Load JPG 6 14/09/17 11:44 Accident Photo 1 Load JPG 7 14/09/17 11:44 Accident Photo 1 Load JPG 8 14/09/17 11:44 Accident Photo 1 Load JPG 9 14/09/17 11:44 Accident Photo 1 Load JPG 10 14/09/17 11:44 Accident Photo 1 Load JPG 11 14/09/17 11:44 Accident Photo 1 Load JPG 12 14/09/17 11:44 Accident Photo 1 Load JPG Documentation No Finalized On Premium Automobiles Pte Ltd (UBI) Thumbnail	7	Load JPG	0		3
6 14/09/17 11:44 Accident Photo 7 14/09/17 11:44 Accident Photo 8 14/09/17 11:44 Accident Photo 9 14/09/17 11:44 Accident Photo 10 14/09/17 11:44 Accident Photo 11 14/09/17 11:44 Accident Photo 12 14/09/17 11:44 Accident Photo 13 Load JPG 14/09/17 11:44 Accident Photo 15 Load JPG 16 14/09/17 11:44 Accident Photo 17 14/09/17 11:44 Accident Photo 18 Load JPG 19 14/09/17 11:44 Accident Photo 19 14/09/17 11:44 Accident Photo 10 14/09/17 11:44 Accident Photo 10 14/09/17 11:44 Accident Photo 11 Per page Thumbnail	V	Load JPG	0	* U WALLAN A BANK CONTRACTOR CONT	
14/09/17 11:44 Accident Photo 1 Load JPG	V	Load JPG	0		
7 14/09/17 11:44 Accident Photo 3 Load JPG 9 14/09/17 11:44 Accident Photo 3 Load JPG 10 14/09/17 11:44 Accident Photo 3 Load JPG 11 14/09/17 11:44 Accident Photo 3 Load JPG 12 14/09/17 11:44 Accident Photo 3 Load JPG 12 14/09/17 11:44 Accident Photo 3 Load JPG 14/09/17 11:44 Accident Photo 3 Load JPG 15 14/09/17 11:44 Accident Photo 1 1 1 1 1 16 17 17 17 17 17 17 17	V	Load JPG		**(**)**	
8 14/09/17 11:44 Accident Photo 9 14/09/17 11:44 Accident Photo 10 14/09/17 11:44 Accident Photo 11 14/09/17 11:44 Accident Photo 12 14/09/17 11:44 Accident Photo 13 Load JPG 14/09/17 11:44 Accident Photo 15 Load JPG 16 Load JPG 17 Indian Photo 18 Load JPG 19 Load JPG 19 Indian Photo 19 Indian Photo 10 Indian Photo 10 Indian Photo 10 Indian Photo 11 Indian Photo 12 Indian Photo 13 Load JPG 14/09/17 11:44 Accident Photo 15 Load JPG 16 Indian Photo 16 Indian Photo 17 Indian Photo 18 Indian Photo 19 Indian Photo 19 Indian Photo 10 Indian Photo 10 Indian Photo 10 Indian Photo 11 Indian Photo 12 Indian Photo 13 Indian Photo 14/09/17 11:44 Accident Photo 15 Indian Photo 16 Indian Photo 17 Indian Photo 18 Indian Photo 19 Indian Photo 19 Indian Photo 10 Indian Photo 11 Indian Photo 12 Indian Photo 13 Indian Photo 14 Indian Photo 15 Indian Photo 16 Indian Photo 17 Indian Photo 18 Indian Photo 19 Indian Photo 19 Indian Photo 10 Indian Photo 11 Indian Photo 12 Indian Photo 13 Indian Photo 14 Indian Photo 15 Indian Photo 16 Indian Photo 17 Indian Photo 18 Indian Photo 19 Indian Photo 19 Indian Photo 10 Indian Photo 11 Indian Photo 12 Indian Photo 13 Indian Photo 14 Indian Photo 15 Indian Photo 16 Indian Photo 16 Indian Photo 17 Indian Photo 18 Indian Photo 18 Indian Photo 19 Indian Photo 19 Indian Photo 10 Indian Photo 11 Indian Photo 12 Indian Photo 12 Indian Photo 14 Indian Photo 15 Indian Photo 16 Indian Ph	V			1 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	7
9 14/09/17 11:44 Accident Photo 10 14/09/17 11:44 Accident Photo 11 14/09/17 11:44 Accident Photo 12 14/09/17 11:44 Accident Photo 13 Load JPG 14/09/17 11:44 Accident Photo 15 Load JPG 16 Load JPG 17 14/09/17 11:44 Accident Photo 18 Load JPG 19 Permium Automobiles Pte Ltd (UBI) 19 Premium Automobiles Pte Ltd (UBI) 10 Thumbnail	7				8
10 14/09/17 11:44 Accident Photo 11 14/09/17 11:44 Accident Photo 12 14/09/17 11:44 Accident Photo 13 Load 3PG 14/09/17 11:44 Accident Photo 15 Load 3PG 16 Documentation 16 Finalized On Premium Automobiles Pte Ltd (UBI) 17 Thumbnail	V			17/07/1-	9
11 14/09/17 11:44 Accident Photo 12 14/09/17 11:44 Accident Photo 1 per page Thumbnail	7	1000000000		14/09/17 11:44 Accident Photo	0
Documentation No Finalized On Premium Automobiles Pte Ltd (UBI) Thumbnail	[V]	100000000000000000000000000000000000000		14/09/17 11:44 Accident Photo	1
Documentation No Finalized On Premium Automobiles Pte Ltd (UBI) Thumbnail	[8]	Load JPG	•	2 14/09/17 11:44 Accident Photo	12
No Finalized On Premium Automobiles Pte Ltd (UBI) Thumbhail	7	page 🕶	1 per		
No Finalized On Premiant Additionality to any	Print	Thumbnail			-
1 14/09/17 11:29 Sketch Plan	7	Load JPG	0		
1 14/09/17 11:29 Sketch Plan 2 14/09/17 11:29 Sketch Plan #2 1 Load JPG	V	Load JPG	0	A.V. V. V. T. (1.7.20.20.) 2000-000-000-000-000-000-000-000-000-00	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	100			
	•			
	*			
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties:				

LKK Auto Consultants Pte Ltd (Co. Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way #07-16

Singapore 079120

Date:

CC3/AIG17018042/ATBN2

31/01/2018

REFERENCE

Date of Loss:

Insured/Claimant:

TANG WEIXIANG, THOMAS

Policy No:

1700016560

Our File No:

Nature of Claim: OD

Rear Right Side:

Claim No: 6028807856SG

WAUZZZF46HA163038

DESCRIPTION & IDENTIFICATION OF VEHICLE

14/09/2017

Reg No:

SJG5111A

Make & Model:

AUDI A4, 1.4 T (A)

13/06/2017 (Man. Year: 2017)

Engine No: Chassis No: Odometer:

CVN038980

5302 km

Reg. Date: Colour:

1395 cc

Engine Capacity: Market Value/New Car Price:

\$\$160,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Front Left Side:

Steering (Serviceable): Yes Engine Modification:

Yes Footbrake (Serviceable): No Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES Front Tyre Size:

205/60R16

Continental 6 mm

Rear Tyre Size: Rear Left Side: Continental 6 mm

205/60R16

Continental 6 mm Continental 6 mm

Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Item		Repairer's 5,650.00 0.00	Adjuster's 3,523.20 0.00	2,126.80 0.00	Diff % 37.64
Labour		6,932.00	4,457.00	2,475.00	35.70
Paintwork Labour		0.00	0.00	0.00	
		0.00	0.00	0.00	
Towing	Calculated Gross Total (S\$) - Excess (S\$)	12,582.00 300.00	7,980.20 300.00	4,601.80 0.00	36.57 0.00
	(S\$)	12,282.00	7,680.20	4,601.80	37.47
	+ GST 7.00/7.00% (S\$)	859.74	537.61	322.13	37.47
	Nett Amount (S\$)	13,141.74	8,217.81	4,923.93	37.47

INSPECTION

Date of Assignment:

19/09/2017

Date Inspected:

19/09/2017 Inspected At:

Premium Automobiles Pte Ltd (HQ)

55 Ubi Road 1 Singapore 408699

Estimated Period of Repair:

5.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded

REPAIR DETAILS

No.			ed Parts Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR *FRONT DOOR OUTER SEAL LH	Dented Necessary	1,855.00 FS 167.00 FS	*1,484.00 FS *133.20 FS
3	1		*BONDING AGENT *FRONT DOOR ATTACHMENTS PARTS	Not Necessary Not Necessary	42.00 FS 440.00 FS	*- FS *- FS
5	1		*DOOR CATCH *TRIM PLATE FOR DOOR HANDLE LH	Not Necessary Not Necessary	89.00 FS 21.00 FS	*-FS
6 7	1		*REAR DOOR LH *REAR DOOR OUTER SEAL LH	Dented Necessary	1,745.00 FS 167.00 FS	*1,396.00 FS *133.20 FS
9	1		*BONDING AGENT *SEALING STRIP	Not Necessary Not Necessary	42.00 FS 14.00 FS	
10	1		*DOOR CATCH *TRIM PLATE FOR DOOR HANDLE LH	Not Necessary Not Necessary	102.00 FS 21.00 FS	
12	1		*ALUMINIUM RIM REAR LH *STONE CHIP	Cut Not Necessary	465.00 FS 180.00 FS	-
14 15	1		*SUNDRIES	Necessary	300.00 FS	*4.80 FS
F=F	ranchise	part. S=Spc	Nett.	Total Parts (S\$)	5,650.00	3,523.20

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommen	hah	l ahour
Recommen	ueu	Laboui

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items	05031-070-1	500.00	560.00
1	TO REMOVE AND TRANSFER LHS FRONT AND REAR DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES	New	560.00	
2	TO DISMANTLE AND RENEW LHS FRONT AND REAR DOORS, ALIGN TO POSITION.REPAIR LHS SILL PANEL AND REAR FENDER.REINSTALL ALL PARTS REMOVED	New	2,400.00	1,500.00
3	TO RESPRAY LHS FRONT AND REAR DOORS,DOOR HANDLES.LHS SILL PANEL AND LHS REAR FENDER.TO CARRY OUT STONE CHIP TREATMENT	New	3,500.00	1,925.00
4	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labo	ur Cost (S\$)	6,932.00	4,457.00
	Report was unsubmitted du	ring this print-out.		

< END OF ESTIMATES >