

ASS. REC. BY:

REF:

CS/UOL17018125/Rlr6n2

Special Instruction:

Surveyor: Rosell

ASSIGNMENT (Office)

From (Person): Jenny Lew

of

UOL

Date/Time: 20092017

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKS 6994L

Insured:

QJM 6848U

at Workshop m/s

Performanca

Tel:

6319 0174

of

308 Alexandra Rd

Policy No:

DHOM120015681500

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16092017

(Client's Record)

CA / REV / REP. / REV 24 HRS ^{wp}

25092017

H.O.D. Endorsement:

Date/Time:

20092017 326pm

Person Contacted:

Caroline

Vehicle IN OUT

Date/Time

Action/Instruction

(✓) Estimate

Zathiran.

SKS 6994L - X

QJM 6848U - X

Confirm P/P \$ 9416.75 , 5 days

Rd : \$ 3989.10 , 30%.

Form

REF: 401

40762

ASSIGNMENT

From: _____ Date: 25/9/17

Estimated Cost: _____

OD / TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKS 6994 L

at Workshop m/s: Performance

of: 303 Alexandra Road

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Ball or Market Value: _____

IDAC Accident Rpt. Consistent? Yes or No

GIA / PR Seen. Consistent? Yes or No

Est. Repairs: _____ days Res. Yes or No

Lum Sum: _____ % 3 Val. Yes or No

CA / REV / REP. / 24 HRS

'up'

Date: _____ Person Contacted: _____

Vehicle IN / OUT

Date / Time Action / Instruction

Veh No: SKS 6994L

Yr Regn: 2015 / APR

Type: M.Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 218I

CC: 1499

Colour: WHITE

A/C Insured / Std / NI / NA

Sp. Reading: 35986

T. Radio Insured / Std / NI / NA

Eng/No: _____

C.No: WHA 2A32050V Z53243

Gen Cond Good (2) / Poor / Burnt

Steering: (2) / Jammed / Leaked / Burnt or

Brake: (2) / Jammed / Leaked / Burnt or

Mod: Nil / (2) / STD A/Rim or

Tyre Size F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CONTINENTAL

Front

Rear

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A: 16/09/17

D.O.I: 25/09/17

Survey held at: PERFORMANCE

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 06 APR 2017

Date/Time File Pass to?

typist

Date/Time File Return to?

2)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: -

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee

Transportation

1 S + RS 1 S

1 Photos

1 Others

TOTAL

Report Format: TP

Lump Sum / I.B.I: (\$ 9416.75)

3x15.45

170 + 45
50

20

285

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
UNITED OVERSEAS INSURANCE LTD		Ref : CS/UOI17018125/R1rb	
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909		Date : 20-09-2017	
		Code : UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJM 6848U	Veh. Inspected	SKS 6994L
Policy No.	DHOM120015681500	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JENNY LEW	Assign Date	20/09/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	16/09/2017	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Celine Fong (LKKAuto)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Tuesday, 21 November 2017 6:23 PM
To: Rasul (LKKAuto); SUR
Subject: FINAL REPORT / SKS6994L
Attachments: Final Report SKS6994L.pdf; Final Report SKS6994L_2.pdf

Dear Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 6,759.00
Total Parts : 2,657.75
Total Labour & Parts : 9,416.75

Repair days: 5

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/09/2017 12:58
Date Of Accident	16/09/2017 13:15
Exact Location Of Accident	JURONG WEST AVE 5 / JLN BAHAR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS6994L
Insured/Policyholder	
Name Of Registered Owner	TAI YOKE YEE
NRIC No	S1664076Z
Email Address	SGBL68@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91295006
Alternative Phone No	OFFICE-96285493

Vehicle Particulars

Manufacturer	BMW
Model	218
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SI17V07304/VPE/R01/E33
Cover Note Number	

Driver

Name of Driver	GOH BAN LENG
NRIC No	S6872302G
Date Of Birth	10/06/1968
Occupation	INDOOR
Date Of Driving Pass	09/12/1991
Driving Experience	25 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96285493
Fax Number	
Contact Number	
Email Address	SGBL68@GMAIL.COM

Address	64 WESTWOOD DRIVE
Postcode	643882
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJM6848U
Vehicle Make/Model/Colour	BMW 3 SERIES BLUE
Details Of Properties	
Name of Driver	MARCUS
NRIC/Passport Number	
Contact Number	82339394
Address	
Postcode	
Insurance Company Name	UNITED OVERSEAS INSURANCE LTD
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time




Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan



Sketch Plan Pg. 2

Describe Circumstances of the Accident


On 16/9/17 at 1316 hrs was traveling from Surong Ave 5 ^{west}
exit into Sultan Bahar and was hit on a rear by SS168484
(attached video)

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &
Time

 18/9/17

Driver's Signature (if driver is not the policyholder) / Date
& Time



Witnessed by Reporting Centre
Personnel

25.09.2017 @ 9:00am

Survey & repair

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

19 SEP 2017

REC: 9.50PM

Estimate No. : b1 44190 1207717
Date Estimated : 19/09/2017
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -Tai Yoke Yee
64 Westwood Drive

Singapore 648882

- ACCOUNT - 115United Overseas Insurance Ltd
3 Anson Road #28-01 Springleaf Tower

Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS6994L	VZ53243	30/04/2015	218iA AT	0

DESCRIPTIONVALUE

To replace rear bumper, tailgate, repair tail panel and attachments including knock out dent area cause by accident.

2580 / 3,400.00

Painting rear bumper, tailgate and tail panel.

2399 / 2,666.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

230 / 271.00

To remove and install rear windscreen glass including conduct water leak tests.

649.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 / 177.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 / 177.00

To carry out body cavity preservation.
(Per panel).

100 / 118.00

Sundries.

80 / 150.00

Total Labour 1: 7,608.00

DESCRIPTIONQTY PRICVALUE

RUBBER MOUNTING	1	17.05
REAR SILENCER	1	1,167.45
REAR BUMPER PANEL PRIMED (PDC)	1	942.75
RR BUMPER LH SIDE GUIDE	1	46.65
REAR BUMPER CARRIER	1	413.45
SUPPORT	1	36.40
REAR BUMPER TRIM STRIP (CHROM)	1	107.55
RR BUMPER LH INNER SIDE GUIDE	1	57.15

1 17.05

1 1,167.45

1 942.75

1 46.65

1 413.45

1 36.40

1 107.55

1 57.15

xsm 17.05

xsm 1,167.45

xsm 942.75

xsm 46.65

xsm 413.45

xsm 36.40

xsm 107.55

xsm 57.15

rec

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190122 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438160
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 44190
Date Estimated : 19/09/2017
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS6994L	VZ53243	30/04/2015	218iA AT	0

DESCRIPTION	QTY	PRIC	VALUE
RR BUMPER RH INNER SIDE GUIDE	1	57.15	57.15
LEFT PROTECT	1	1.95	1.95
SET MOUNTS PDC SENSOR REAR	1	62.50	62.50
LETTERING 218 I	1	61.05	61.05
GROMMET	2	0.75	1.50
BADGE (BMW)	1	67.80	67.80
BUMP STOP	10	3.25	32.50
DECOUPING RING PDC TORQUE CONVERTER	4	4.95	19.80
ULTRASONIC SENSOR ALPINWEISS (U300)	2	374.60	749.20
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85
Total Parts :			4,160.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 25/09/17 01:35 Excess \$ _____

Surveyor's Name Rajan Sign _____

Surveyor's Tel 90010068 Authorized Yes/No _____

Authorized Dec _____ Time _____

Surveyor's Email _____

Time of Visit/Day/Week/Year _____

7 days

Inthiran
26/9/17

5 days

13405.85

Labour 1	:	7,608.00
Parts	:	4,160.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	823.81
Grand Total	:	12,592.51

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co., Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 44190
Date Estimated : 19/09/2017
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Tai Yoke Yee
64 Westwood Drive

- ACCOUNT - 115
United Overseas Insurance Ltd
3 Anson Road #28-01 Springleaf Tower
Singapore 079909

Singapore 648882

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEACE	ORIGINAL PRICE	DISC. %	NETT
SKS6994L	VZ53243	30/04/2015	218iA AT	0			
DESCRIPTION					ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments, trunk lid include making good the tail end panel and knocking out dents caused by the accident					2550.00		2,550.00 ✓
To spray paint rear bumper, tailgate and tail end panel					2399.00		2,399.00 ✓
To remove and install boot compartment carpet and garnish to facilitate repairs					230.00		230.00 ✓
To remove and install rear windscreen glass to facilitate repairs include conducting water leak tests					649.00		649.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function.					150.00		150.00 ✓
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.					150.00		150.00 ✓
To carry out body cavity preservation. (Per panel).					100.00		100.00 ✓
# To transfer lock mechanism from old to new trunk lid include conducting checks on new trunk lid central locking system for proper function					451.00		451.00
Sundries					80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# TRUNK LID *	1,146.30	1.00		1,146.30
REAR BUMPER PANEL PRIMED (PDC)	942.75	1.00		942.75 ✓
REAR BUMPER TRIM STRIP (CHROM)	107.55	1.00		107.55 ✓
LETTERING 218i	61.05	1.00		61.05 ✓
GROMMET	0.75	2.00		1.50 ✓
BADGE (BMW)	67.80	1.00		67.80 ✓
# W/SCREEN RUBBER BUFFER *	1.60	10.00		16.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 44190
Date Estimated : 19/09/2017
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Tai Yoke Yee
64 Westwood Drive

- ACCOUNT - 115
United Overseas Insurance Ltd
3 Anson Road #28-01 Springleaf Tower
Singapore 079909

Singapore 648882

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKS6994L	VZ53243	30/04/2015	218iA AT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To transfer lock mechanism from old to new trunk lid include conducting checks on new trunk lid central locking system for proper function	451.00		451.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# TRUNK LID *	1,146.30	1.00		1,146.30 ✓
# W/SCREEN RUBBER BUFFER *	1.60	10.00		16.00 ✓
# (DG) CLEANER R1 (100ML) *	23.85	1.00		23.85 ✓

Total Labour :	451.00
Total Parts :	1,186.15
Total Labour & Parts :	1,637.15

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

# (DG) CLEANER R1 (100ML) *	23.85	1.00	23.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1.00	27.85

SUPPLEMENTARY ITEMS

Total Labour :	6,759.00
Total Parts :	2,657.75
Total Labour & Parts :	9,416.75
Deduction for Excess :	0.00
Total Repair Costs less Excess:	9,416.75
GST @7%:	659.17
Grand Total :	10,075.92




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
UNITED OVERSEAS INSURANCE LTD		Ref : CS/UOI17018125/R1rbn2	
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909		Date : 09-04-2018	
		Code : UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJM 6848U	Veh. Inspected	SKS 6994L
Policy No.	DHOM120015681500	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JENNY LEW	Assign Date	20/09/2017
2. Vehicle Particulars & Condition			
Make & Model	B.M.W 218i	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WBA2A32050VZ53243	Colour	WHITE
Odometer	35986	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	CONTINENTAL	6 mm
L/H Front Tyre	205/60 R16	CONTINENTAL	6 mm
R/H Rear Tyre	205/60 R16	CONTINENTAL	6 mm
L/H Rear Tyre	205/60 R16	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/09/2017	Inspection Date	25/09/2017
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 6994L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RUBBER MOUNTING (SN)	SERVICEABLE	17.05	-
1	REAR SILENCER (SN)	SERVICEABLE	1,167.45	-
1	REAR BUMPER PANEL PRIMED (PDC)(SN)	TORN	942.75	942.75
1	RR BUMPER LH SIDE GUIDE (SN)	SERVICEABLE	46.65	-
1	REAR BUMPER CARRIER (SN)	SERVICEABLE	413.45	-
1	SUPPORT (SN)	SERVICEABLE	36.40	-
1	REAR BUMPER TRIM STRIP (CHROM)(SN)	NECESSARY	107.55	107.55
1	RR BUMPER LH INNER SIDE GUIDE (SN)	SERVICEABLE	57.15	-
1	RR BUMPER RH INNER SIDE GUIDE (SN)	SERVICEABLE	57.15	-
1	LEFT PROTECT (SN)	SERVICEABLE	1.95	-
1	SET MOUNTS PDC SENSOR REAR (SN)	SERVICEABLE	62.50	-
1	LETTERING 218 I (SN)	NECESSARY	61.05	61.05
2	GROMMET (SN)	NECESSARY	1.50	1.50
1	BADGE (BMW)(SN)	NECESSARY	67.80	67.80
10	BUMP STOP (SN)	SERVICEABLE	32.50	-
4	DECOUPING RING PDC TORQUE CONVERTER (SN)	SERVICEABLE	19.80	-
2	ULTRASONIC SENSOR ALPINWEISS (U300)(SN)	SERVICEABLE	749.20	-
2	(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)(SN)	NECESSARY	263.10	263.10
1	(DG/SL) GLASS PRIMER 30ML (VP206)(SN)	NECESSARY	27.85	27.85
1	(DG/SL) GLASS PRIMER 30ML (VP206)(SN)	NOT NECESSARY	27.85	-
1	TRUNK LID (ADDITIONAL)(SN)	BENT	1,146.30	1,146.30
10	W/SCREEN RUBBER BUFFER (ADDITIONAL)(SN)	NECESSARY	16.00	16.00
1	(DG) CLEANER R1 (100ML) (ADDITIONAL)(SN)	NECESSARY	23.85	23.85
1	SUNDRIES (SN)	NECESSARY	150.00	80.00
			5,496.85	2,737.75
<u>LABOUR</u>				
TO REPLACE REAR BUMPER, TAILGATE, REPAIR TAIL PANEL AND ATTACHMENTS INCLUDING KNOCK OUT DENT AREA CAUSED BY ACCIDENT.			3,400.00	2,550.00
PAINTING REAR BUMPER, TAILGATE AND TAIL PANEL.			2,666.00	2,399.00
TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS.			271.00	230.00
TO REMOVE AND INSTALL REAR WINDSCREEN GLASS INCLUDING CONDUCT WATER LEAK TESTS.			649.00	649.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	150.00
	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.		177.00	150.00
	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL).		118.00	100.00
	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW TRUNK LID INCLUDE CONDUCTING CHECKS ON NEW TRUNK LID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION (ADDITIONAL).		451.00	451.00
			7,909.00	6,679.00
GRAND TOTAL			13,405.85	9,416.75
RECOMMENDED COST OF REPAIRS				9,416.75

Report Ref No. CS/UOI17018125/R1rbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.