

ASS. REC. BY:

REF: CS/FCI19018148/ Drbn2

Special Instruction:

Surveyor
CWS

Bryan

ASSIGNMENT (Office)

From (Person):

Ang Yin Min

of

FCI

Date/Time

20/9/17 4:30pm

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL 47382

Insured:

SHA 8025 B

at Workshop m/s

TeamWork Garage

Tel:

6844 2475

of

53 Ubi Ave 1 # 01-24

Policy No

Claim No

D17008898 MFSH

Sum Insured

Excess

Make of Veh:

(Client's Record)

D.O.A

17/09/17

CA / REV / REP. / REV 24 HRS

'wp'

21.09.2017

H.O.D. Endorsement:

Date/Time:

20/9/17 4:42pm

Person Contacted

chris

Vehicle IN /

OUT

Date/Time	Action/Instruction (✓) Estimate
	SLL 47382 - NA / CFI 17017911 / r3 - D.O.A: 17/09/17
	SHA 8025 B - NA / CFI 17017911 / r3 - D.O.A: 17/09/17
23/1/19	Email preli revised to FCI

REF:

ASSIGNMENT

COE April 2022

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No.:

at Workshop m/s:

of:

Insured:

Policy No.:

Claims No.:

Sum Insured:


Excess:

(Client's Record)

Make of Veh.:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No. 8LL 47382

Yr Regn. 2007 / May

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Axio

C.C. 1496

Colour: Blue

A/C Insured / Std / NI / NA

Sp Reading 112991

T/Radio: Insured / Std / NI / NA

Eng/No: 1N2C570490

C/No: N2E1416029671

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil ☒ S/Rim / STD A/Rim or

Tyre Size: F: 195/60 R15

R: ———

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Bridgestone

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 17/09/2017

D.O.I. 21/09/2017

Survey held at Teamwork Page Ubi

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear 4/5

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

First Capital SHV 8025 B

Note:

MV 24K (EST)

LTA 17K

NIL 7K

22/01/2019 yinane 4/5 2800/- with 4 days of rev (Red 4578-35, 629)

RECEIVED 23 JAN 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 23/1 - typist

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) \$ + RS. \$1

) Photos

) Others

TOTAL

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Report Format :

CWS

Lump Sum / I.B.I. (\$)

2800/2

150

50

50+50

31

331



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D17008898MFSH

Our ref: CS/FCI17018148/Dvb

Date: 23/1/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLL 4738Z


We thank you for your instruction on 20/9/2017

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21/9/2017 at the premises of M/s TEAMWORK GARAGE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$7,378.35
Revised Estimate Amount	: S\$2,800.00 (LUMP SUM)
"Check" Items Amount	: S\$
Book Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear n/s portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Bryan Ang
Motor Surveyor / Investigator

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	18-09-2017	Our Ref No. D17008898MFSH
Accident Date	17-09-2017	Claim Type. Third Party
Insured Vehicle	SHA8025B	Third Party Vehicle. SLL4738Z
Survey Location	53 UBI AVENUE 1 #01-24 PAYA UBI INDUSTRIAL PARK	
Contact Person.	DARREN NG	
Contact No.	68442475/ 0	Fax No. 68442474
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TEAMWORK GARAGE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/228135)



PRI Documents



Close



PRI Header Details

Claim No	D17008898MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & TEAMWOR
Workshop Name	TEAMWORK GARAGE PTE LTD (Contact Person : DARREN NG)	Survey Location & Contact Details	53 UBI AVENUE 1 #01-24 PAYA UBI INDUSTRIAL PARK Mobile: 0 , Phone: 68442475 , Fax: 68442474 EmailId: CLAIMS@TEAMWORKGARAGE.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA8025B	TP Vehicle No	SLL4738Z
PRI Recieved Date	20-09-2017 06:17:39 PM	Surveyor Appointed Date	20-09-2017 04:31:48 PM	Surveyor Accept Date	20-09-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	20-09-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 23 January 2019 9:06 AM
To: 'Claim Workflow System'
Cc: AUNGYINMIN@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17008898MFSH/1, SLL 4738Z
Attachments: SLL 4738Z PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLL 4738Z
Date of survey: 21/9/2017
Number of days : 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 20 September 2017 4:45 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: AUNGYINMIN@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17008898MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Wednesday, 20 September, 2017 4:30 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; AUNGYINMIN@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17008898MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Teamwork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 201015366H

3RD PARTY CLAIM ESTIMATION

First Capital Insurance Ltd

36 Robinson Road
#16-01 City House
Singapore 068877

- LKK Auto Consultants hence notify the Insurer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - 3rd party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurer

Acknowledged by Repairer
Signature:

Vehicle number SLL4738Z
Make / Model TOYOTA/AXIO
Chassis number NZE1416029571
Accident date 17 SEPTEMBER 2017
Reference 1709-16

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	REAR BUMPER <i>Dental</i>	1027.39 ✓
2	REAR BUMPER RETAINER <i>N/S broken 2/S Hnl</i>	281.20 ✓ <i>140.60</i>
2	REAR BUMPER DAMPER <i>HH</i>	270.40 X
1	REAR LH TAILLAMP <i>crack</i>	518.09 ✓
1	REAR LH TAILLAMP SEALER <i>Hnl</i>	60.00 X
1	REAR END PANEL <i>Dental</i>	612.02 ✓
1	REAR END PANEL GARNISH <i>Hnl</i>	317.21 X
1	BOOTLID <i>Hnl</i>	941.34 X
1	BOOTLID LOCK <i>Hnl</i>	315.26 X
1	BOOTLID LOCK STRIKER <i>HH</i>	52.00 X
1	BOOTLID EMBLEM LOGO <i>HH</i>	64.80 X
1	BOOTLID EMBLEM - AXIO <i>Hnl</i>	55.57 X
1	REAR LH FENDER INNER TRIM <i>Hnl</i>	495.85 X
		5011.13
		Less 25%
		1252.78
		Subtotal
		3758.35
		Balance C/F
		3758.35
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
		Balance B/F
		3758.35
1 SET	REAR BUMPER CLIP <i>Hnl</i>	60.00 30/-
1 SET	REAR BUMPER REVERSE SENSOR <i>Shorted</i>	400.00 220/-
1 SET	REAR FENDER INNER TRIM <i>Hnl</i>	50.00 X
1	JOINT SEALANT <i>Hnl</i>	150.00 40/-
		Subtotal
		660.00
		Balance C/F
		4418.35
LABOUR AND MISCELLANEOUS CHARGES		
		Balance B/F
		4418.35
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 30/-
2	REMOVE AND REFIT REAR LINING , TRIM AND GARNISH	200.00 60/-
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 40/-
4	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00 HH
5	PANEL BEATING ON AFFECTED AREAS	1200.00 800/-
6	SPRAY PAINTING ON AFFECTED AREAS	1000.00 600/-
7	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30/-
		Subtotal
		2960.00
		Grand total
		7378.35

2298.10
1723.57

290.00

1560.00

3573.57

4/S 2800/-

21/09/2017 @ 1045h

Hnl Antennal

1/S Hnl

ryan

LKK Auto

4 days.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17018148/Dvbn2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 23-01-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 8025B	Veh. Inspected	SLL 4738Z
Policy No.	D-15072702MFSH	Coverage (\$)	0.00
Claim No.	D17008898MFSH	Excess (\$)	0.00
Assign From	AUNGYM	Assign Date	20/09/2017

2. Vehicle Particulars & Condition

Make & Model	TOYOTA AXIO	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	NZE1416029571	Colour	BLUE
Odometer	112991	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R15	BRIDGESTONE	5 mm
L/H Front Tyre	195/60 R15	BRIDGESTONE	5 mm
R/H Rear Tyre	195/60 R15	BRIDGESTONE	5 mm
L/H Rear Tyre	195/60 R15	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	17/09/2017	Inspection Date	21/09/2017
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 4738Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED	1,027.39	1,027.39
2	REAR BUMPER RETAINER	N/S BROKEN / O/S NOT NECESSARY	281.20	140.60
2	REAR BUMPER DAMPER	NOT NECESSARY	270.40	-
1	REAR LH TAILLAMP	CRACKED	518.09	518.09
1	REAR LH TAILLAMP SEALER	NOT NECESSARY	60.00	-
1	REAR END PANEL	DENTED	612.02	612.02
1	REAR END PANEL GARNISH	NOT NECESSARY	317.21	-
1	BOOTLID	NOT NECESSARY	941.34	-
1	BOOTLID LOCK	NOT NECESSARY	315.26	-
1	BOOTLID LOCK STRIKER	NOT NECESSARY	52.00	-
1	BOOTLID EMBLEM LOGO	NOT NECESSARY	64.80	-
1	BOOTLID EMBLEM-AXIO	NOT NECESSARY	55.57	-
1	REAR LH FENDER INNER TRIM	NOT NECESSARY	495.85	-
	LESS 25% DISCOUNT		-1,252.78	-574.53
			3,758.35	1,723.57
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	60.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	400.00	220.00
1	SET REAR FENDER INNER TRIM (SN)	NOT NECESSARY	50.00	-
1	JOINT SEALANT (SN)	NECESSARY	150.00	40.00
			660.00	290.00
LABOUR				
	CHECK REAR WIRING AND LIGHTING SYSTEM.		60.00	30.00
	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH.		200.00	60.00
	REMOVE AND RENEW REAR REVERSE SENSOR.		150.00	40.00
	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW.	NOT NECESSARY	200.00	-
	PANEL BEATING ON AFFECTED AREAS.		1,200.00	800.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,000.00	600.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	APPLY ANTI RUST ON AFFECTED AREAS.		150.00	30.00
			2,960.00	1,560.00
GRAND TOTAL			7,378.35	3,573.57
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,800.00

Report Ref No. CS/FCI17018148/Dvbn2

MARKET VALUE: \$24,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$17,000.00=NETT VALUE: \$7,000.00

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.