

ASS. REC. BY:

REF: CS/FCI17018245/T/rbn2

Special Instruction:

Survivor

Tawfik

ASSIGNMENT (Office)

CWS

From (Person):

Joanne Yong

of

FCI

Date/Time:

21/9/17 5.43pm

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 7197X

Insured:

SHB 6377 T

at Workshop m/s

Zhong Cheng Enterprise

Tel:

9338 2859

of

Blk 6 Woodlands Rd Yew Tee Ind Estate, 399J

Policy No:

Claim No:

D17008991 MFS4

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

19/9/2017

CA / REV / REP. / REV 24 HRS

'wip'

26.09.2017 @ after 11am

H.O.D. Endorsement

Date/Time:

22/9/17 8.40am

Person Contacted:

Ms. Sini

Vehicle IN / OUT

Date/Time

Action/Instruction

✓

Estimate

SLF 7197X -X

SHB 6377 T - NA / INC 13002130 / m2 - D.O.A: 15/01/2013

Confirm with Sini L1S \$4300 @ 4 days

Red: \$5732.28, 57%.

(08/11/17)

Surveyor:

Tan Min

REF: T02

ASSIGNMENT

From: _____ Date: 26/09/2017

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLF 7197X

at Workshop m/s: Zhong Cheng
of Blk 6 Woodlands New Tee

Insured: 399J

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLF 7197X Yr Regn: 2016 Sep

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel C.C. 1496.

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 17675 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: R41/202943

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 26/9/17

Survey held at Zhong Cheng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S, U/C.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

w/s will pass GIA later.

→ headlight price (is LEA)

RECEIVED 19 SEP 2018

Date/Time, File Pass to?

1) Input

Date/Time, File Return to?

2) _____

☐: Preli. Report☒: Final Report

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: ☐: Site Insp (\$)☐: Interview (\$)☐: Tech. Invs (\$)☐: Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

170

50

41

261

Report Format: TP

Lump Sum / T.B.I. (\$ 4300.00)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17018245/rb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 22-09-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 6377T	Veh. Inspected	SLF 7197X	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17008991MFSH	Excess (\$)	0.00	
Assign From	CWS (JOANNEY YONG)	Assign Date	22/09/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	19/09/2017	Inspection Date		
Survey held at	ZHONG CHENG ENTERPRISE BLK 4 YEW TEE IND 393-H WOODLANDS ROAD SINGAPORE 677969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	20-09-2017	Our Ref No. D17008991MFSH
Accident Date	19-09-2017	Claim Type. Third Party
Insured Vehicle	SHB6377T	Third Party Vehicle. SLF7197X
Survey Location	BLK 6 WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE 399J	
Contact Person.	MS SINI	
Contact No.	0/ 93382859	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ZHONG CHENG ENTERPRISE	Attention. NIL
Cc : TP Solicitor	CHEONGHOH LAW CORPORATION	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY 	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/228262)



PRI Documents



Close



PRI Header Details

Claim No	D17008991MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & CHEONGH
Workshop Name	ZHONG CHENG ENTERPRISE (Contact Person : MS SINI)	Survey Location & Contact Details	BLK 6 WOODLANDS ROAD YEW TEE INDUSTRIAL ESTAT Mobile: 93382859 , Phone: 0 , Fax: 0 EmailId: MAIL@CHEONGHOH.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHB6377T	TP Vehicle No	SLF7197X
PRI Recieved Date	20-09-2017 10:20:10 PM	Surveyor Appointed Date	21-09-2017 05:44:24 PM	Surveyor Accept Date	22-09-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	22-09-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Janice Lee (LKKAUTO)

From: Zhong Cheng <zhongchengauto@gmail.com>
Sent: Friday, September 14, 2018 2:10 PM
To: Janice Lee (LKKAUTO)
Cc: Taufikh (LKKAUTO)
Subject: Re: SLF7197X

Dear Taufikh,

Kindly please reconfirm the list price for the headlamp. Its HID headlamp and I've called up to check again, the list price is \$1794.10.

Please readjust.

Thank you

Best Regards
Sini Tan
Zhong Cheng Enterprise Pte Ltd
Blk 6, 399J
Yew Tee Industrial Est
S678008
HP: 93382859 Fax: 68942883

On Mon, Sep 10, 2018 at 3:36 PM, Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com> wrote:

Dear Sini,

Enclosed marking estimate as per request.

Kindly confirm L/S \$3,700 @ 4 DAYS

Thank you.

Best Regards,



CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

**E-DRIVE AUTHORISED
WORKSHOPS**

MZ300
COMPREHENSIVE
ORIGINAL

CERTIFICATE NO: MPC17A00472400 Agency Name: SGDRIVERS PTE LTD Agency Code: A0000069	Chassis No: RU11202943 Engine No: L15B4402943								
1. Index Mark and Registration Number of Vehicle: SLF7197X									
2. Name of Policyholder: LEONG ZHI XIANG ADRIAN									
3. Period of Insurance (both dates inclusive): 06 September 2017 to 05 September 2018									
4. Persons or Classes of Persons entitled to drive a) The Policyholder and all Named Drivers declared under the policy b) Any other person who is driving on the Policyholder's order or with his permission. Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.									
5. Limitations as to use Use for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover use for hire or reward, tuition, driving test, race, pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.									
6. EXCESS APPLICABLE <table style="width: 100%;"> <tr> <td style="width: 60%;">WINDSCREEN</td> <td style="width: 40%; text-align: right;">SGD 100.00</td> </tr> <tr> <td>SECTION 1 - INSURED/NAMED DRIVER</td> <td style="text-align: right;">SGD 750.00</td> </tr> <tr> <td colspan="2">ADDITIONAL EXCESS OTHER THAN NAMED DRIVERS:</td> </tr> <tr> <td>SECTION 1 - AGE <=25, AGE >70 OR DRIVING EXP <2 YEARS OLD</td> <td style="text-align: right;">SGD 3,000.00</td> </tr> </table>		WINDSCREEN	SGD 100.00	SECTION 1 - INSURED/NAMED DRIVER	SGD 750.00	ADDITIONAL EXCESS OTHER THAN NAMED DRIVERS:		SECTION 1 - AGE <=25, AGE >70 OR DRIVING EXP <2 YEARS OLD	SGD 3,000.00
WINDSCREEN	SGD 100.00								
SECTION 1 - INSURED/NAMED DRIVER	SGD 750.00								
ADDITIONAL EXCESS OTHER THAN NAMED DRIVERS:									
SECTION 1 - AGE <=25, AGE >70 OR DRIVING EXP <2 YEARS OLD	SGD 3,000.00								
7. Hire Purchase Company: MAYBANK									
Signed for and on behalf of ECICS Limited _____ Chief Executive Officer									

Important Notice:

- i) Policyholders are hereby warned that it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid insurance under the Act.
- ii) On the sale of a motor vehicle, Policyholders must surrender all insurance papers issued including the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189).
- iii) The Certificate of Insurance and the Policy will cease to be valid once the motor vehicle has been sold or transferred.
- iv) The Payment Before Cover Warranty or Premium Payment Warranty found in the Policy must be complied with otherwise there would be no liability under the Policy and Certificate of Insurance.

NRIC AND LICENSE Pg. 1

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

PASS DATE

Class 3 Motor Car < 3000kg with < 7 passengers, exclusive of the driver; and other motor vehicles < 2500kg 08 Apr 2006

3430795




NRIC No. S84117431



Date of issue
03-03-2015

Address
APT BLK 633C SENJA ROAD
#14-139
SINGAPORE 673633



License No. S84117431

NP 428A

3476203



NRIC No. S8508860B



Date of issue
27-05-2015

Address
APT BLK 633C SENJA ROAD
#14-139
SINGAPORE 673633

Driver



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S84117431



Name
TAN CHING HUI
陈静慧
Race
CHINESE
Date of birth
19-04-1984
Country/Place of birth
SINGAPORE

Sex
F

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8508860B



Name
LEONG ZHI XIANG, ADRIAN

梁志祥

Race
CHINESE

Date of birth
18-03-1985

Country/Place of birth
SINGAPORE

Sex
M

Owner

Adjustment of Spare Parts Costs for Repairs SLF7197X

Item	Qty	Vehicle parts description	\$	
1	1	Front bumper	781.50	de✓
2	1	Front fender (LH)	595.00	bt✓
3	1	Headlamp (LH)	790 1825.00	cut✓ \$1794.10
4	1	Front wheel arch LH	175.00	cut✓
5	1	Front fender cowling LH	176.00	x nn
6	1	Headlamp bracket LH	65.00	nei✓
7	1	Front bumper retainer LH	28.00	nei✓
8	1	Front bumper lower rubber	200.00	x nn
9	1 set	Front bumper clip @ 5.90 each	59.00	nei✓
10	1 set	Cowling clips @ 5.90 each	59.00	nei✓
11	1	Front lower arm LH	370.00	bt✓
12	1	Front knuckle LH	410.00	bt✓
13	1	Front wheel bearing	205.00	bt✓
14	1	Front bar linkage LH	95.60	x nn
15	1	Front shock abs LH	515.00	x nn
16	1	Front driveshaft LH	1180.00	x
17	1	Towing cover	35.00	x
18	1	Side mirror cover	110.00	x nn
19	1	Side mirror LH	605.00	x
			7489.10	
		Less 20%	1497.82	
			5991.28	
				4572.50 3537.50
				4572.50
				3658
				2850
		Special nett item		
1	1	Front Bumper lower skirt	281.00	cut✓
2	1	Tyre	300.00	x nn
3	1	Rim LH	350.00	cut✓
		Total parts	<u>931.00</u>	531

Adjustment of Labour Costs for Repairs

Spraying of affected areas	1300.00	500
Carry out body cavity preservation	160.00	30
To remove and replaced damaged parts including straightening and repositioning replacement parts & panel beat, front fender LH, bonnet, bumper etc	1050.00	500
Check wiring	80.00	20

To remove & refix rear undercarriage items 350 120 ?

To perform 4 wheel alignment 120 80

To realign headlamp focus 50 20.

1270

Total labour

3110.00

10032.28

5479

5459

41594350

4 days

Taufik 97495749

- WP

26/9/17

4 days

taufik @ lkkauto.com

Lumpsum

Resurvey After repair.


17/9/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) clearly
- Parts prices in a separate list
- Third party supply of parts and accessories
- No illegal modification
- Supplementary items and is subject to final approval by LKK Auto Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17018245/T1rbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 6377T	Veh. Inspected	SLF 7197X	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17008991MFSH	Excess (\$)	0.00	
Assign From	JOANNEY YONG	Assign Date	21/09/2017	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU11202943	Colour	RED	
Odometer	17635	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/09/2017	Inspection Date	26/09/2017	
Survey held at	ZHONG CHENG ENTERPRISE BLK 4 YEW TEE IND 393-H WOODLANDS ROAD SINGAPORE 677969			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 7197X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	781.50	781.50
1	FRONT FENDER (LH)	BENT	595.00	595.00
1	HEADLAMP (LH)	CUT	1,825.00	1,794.10
1	FRONT WHEEL ARCH LH	CUT	175.00	175.00
1	FRONT FENDER COWLING LH	NOT NECESSARY	176.00	-
1	HEADLAMP BRACKET LH	NECESSARY	65.00	65.00
1	FRONT BUMPER RETAINER LH	NECESSARY	28.00	28.00
1	FRONT BUMPER LOWER RUBBER	NOT NECESSARY	200.00	-
1	SET FRONT BUMPER CLIP @\$5.90	NECESSARY	59.00	59.00
1	SET COWLING CLIPS @\$5.90	NECESSARY	59.00	59.00
1	FRONT LOWER ARM LH	BENT	370.00	370.00
1	FRONT KNUCKLE LH	BENT	410.00	410.00
1	FRONT WHEEL BEARING	BENT	205.00	205.00
1	FRONT BAR LINKAGE LH	NOT NECESSARY	95.60	-
1	FRONT SHOCK ABS LH	NOT NECESSARY	515.00	-
1	FRONT DRIVESHAFT LH	NOT NECESSARY	1,180.00	-
1	TOWING COVER	NOT NECESSARY	35.00	-
1	SIDE MIRROR COVER	NOT NECESSARY	110.00	-
1	SIDE MIRROR LH	NOT NECESSARY	605.00	-
	LESS 20% DISCOUNT		-1,497.82	-908.32
			5,991.28	3,633.28
SPECIAL NETT ITEMS				
1	FRONT BUMPER LOWER SKIRT (SN)	CUT	281.00	281.00
1	TYRE (SN)	NOT NECESSARY	300.00	-
1	RIM LH (SN)	CUT	350.00	250.00
			931.00	531.00
LABOUR				
	SPRAYING OF AFFECTED AREAS.		1,300.00	500.00
	CARRY OUT BODY CAVITY PRESERVATION.		160.00	30.00

Report Ref No. CS/FCI17018245/T1rbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING AND REPOSITIONING REPLACEMENT PARTS & PANEL BEAT, FRONT FENDER LH, BONNET, BUMPER ETC.		1,050.00	500.00
	CHECK WIRING.		80.00	20.00
	TO REMOVE & REFIX REAR UNDERCARRIAGE ITEMS.		350.00	120.00
	TO PERFORM 4 WHEEL ALIGNMENT.		120.00	80.00
	TO REALIGN HEADLAMP FOCUS.		50.00	20.00
			3,110.00	1,270.00
	GRAND TOTAL		10,032.28	5,434.28
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,300.00

Report Ref No. CS/FC117018245/T1rbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.