

REF:

CC3 / ALH17018285 / ALB2

ASS. REC. BY: Adrian King

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$1000/-

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 88K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06/8/8 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLQ8720X Yr Regn: 2012 / NovType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q3 c.c. 1984Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 89595 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZ843CR053331Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 235/55R17R: 235/55R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 22/09/17Survey held at PremiumDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	OD AIG.
	SLQ 8720X - X
25/9	Revert via menmen. RECEIVED 29 JAN 2018
25/9	16:59pm Authorise repair by notorkoh
25/9 @	5:06pm email to premium authorise repair excess AUD\$7
	Part by Part \$8824 (Red: 4700; 34%)

Date/Time, File Pass to?

1) 29/11 Typist

Date/Time, File Return to?

2) _____

 : Preli. Report : Final ReportDays Of Repair: 6Resurvey No. of Trip: -Add Fee: : Site Insp (\$ _____)) S + RS _____ SI : Interview (\$ _____)) Photos : Tech. Invs (\$ _____)) Others : Weekend (\$ _____))

Report Format :

Lump Sum / (E): (\$ 8824)

Survey Fee:

Transportation:

Photos

Others

TOTAL

20010210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : OC3/AIG17018285/Atb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 22-09-2017



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLQ 8720X
Policy No.	170040012	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	22/09/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

5. General Information

Accident Date	13/09/2017	Inspection Date	22/09/2017
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 3641E

Vehicle Details

Vehicle No.: SLQ8720X

Vehicle to be Exported: No

Intended De-registration
Date: 25 Sep 2017

Vehicle Make: AUDI

Vehicle Model: Q3 2.0 TFSI QU (170BHP)

Primary Colour: Silver

Manufacturing Year: 2012

Engine No.: CCZ263403

Chassis No.: WAUZZZ8U3CR053331

Maximum Power
Output: 125.0 kW (167 bhp)

Open Market Value: \$35,363.00

Original Registration
Date: 30 Nov 2012

First Registration Date: 30 Nov 2012

Transfer Count: 1

Actual ARF Paid: \$35,363.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 29 Nov 2022

PARF Rebate Amount: \$26,522.00

Intended COE Rebate Details

COE Expiry Date: 29 Nov 2022

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$93,990.00

COE Rebate Amount: \$48,155.00

Total Rebate Amount: \$74,677.00

The information contained herein is correct as at 25 Sep 2017

OK

Land Transport & Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolutionCopyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
Last updated on 17 Sep 2017 at 12:38 AM

View Received Message

This mail is associated with :

***SLQ8720X (2852483884SG)**
OD
Sep 13 2017 12:20PM
[CHIVUKULA LAVANYA @PERVELA LAVANYA]
Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on **25/09/2017 16:59 PM**.
To LKK_HQ
CC Victor_KohCK
Subject Proceed authorise repair.

Hi LKK,

Kindly proceed authorise repair.

Regards
Victor Koh

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 25 September, 2017 5:06 PM
To: 'Claims'; SUR
Subject: RE: SLQ 8720 S - OD CLAIM

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLQ 8720 S (Excess \$1000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)
Sent: Monday, 25 September, 2017 3:26 PM
To: 'Claims' <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SLQ 8720 S - OD CLAIM

Dear Tony,

Can get a copy of insurance cert

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [<mailto:claims@premiumauto.com.sg>]
Sent: Friday, 22 September, 2017 11:09 AM
To: SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: SLQ 8720 S - OD CLAIM

Dear all,

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8063641E



Name
**CHIVUKULA LAVANYA
@PERVELA LAVANYA**

Race
INDIAN
Date of birth **07-08-1980** Sex **F** S8063641E
Country of birth
INDIA

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S8063641E**
Name
**CHIVUKULA LAVANYA
@ PERVELA LAVANYA**
Birth Date **07 Aug 1980**
Issue Date **01 Dec 2012**



9161693



NRIC No. **S8063641E**

Nationality
INDIAN
Date of issue
20-04-2012

3 RHU CROSS #03-03
SINGAPORE 437433
NRIC No: S8063641E

Date: 13/08/2015

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	EFFECTIVE DATE
Class 2B Motorcycles <= 200 cc	01 Dec 2012
Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg	01 Dec 2012



NP 428A

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0901/2017/PH
Date : 15-Sep-17

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Chivukula Lavanya @ Pervela Lavanya
Address : 3 Rhu Cross
#03-03
Singapore 437433
Telephone : HP +65 98558270
Type of Claim : Own Damage Claim
Policy No. : 170040012
Vehicle No : **SLQ 8720 X**
Model Code : Audi Q3 2.0 TFSI
Model / Year : Nov-12
Engine No : CCZ263403
Chassis No : WAUZZZ8U3CR053331
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Sep-17
Place of Accident : BISHAN St 21

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLQ 8720 S.

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer lhs front & rear door's multi-lock system and power window devices.	S/N \$ 560.00 ✓
2	To dismantle and renew lhs front door & lhs rear doors, align to position. Repair lhs sill panel and B pillar. Reinstall all parts removed.	\$ 2,400.00 1500 ✓
3	To respray lhs front & rear doors, lhs sill panel, B pillar and rear bumper.	\$ 3,400.00 1650 ✓
4	To renew lhs rear rim and carry out wheel alignment	S/N \$ 280.00 ✓
5	To carry out diagnostic checks.	S/N \$ 192.00 ✓
TOTAL SPARE PARTS		\$ 6,832.00

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 8720 S.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT DOOR LH <i>Dented</i>	\$ 2,079.00	✓ 1663.20
2	FRONT DOOR SEAL LH <i>new</i>	\$ 137.00	✓ 109.60
3	FRONT DOOR CATCH LH <i>new</i>	\$ 102.00	+ X
4	FRONT DOOR COVER LH <i>cut</i>	\$ 219.00	✓ 174.80
5	REAR DOOR LH <i>Dented</i>	\$ 2,079.00	✓ 1663.20
6	BRACKET FOR DOOR SEAL <i>not new</i>	\$ 15.00	✓ X
7	REAR DOOR CATCH LH <i>new</i>	\$ 102.00	+
8	REAR DOOR OUTER DOOR SEAL LH <i>new</i>	\$ 143.00	- 114.40
9	SILL PANEL SEAL LH <i>2nd new</i>	\$ 53.00	? X
10	REAR DOOR COVER - LH <i>cut</i>	\$ 221.00	✓ 176.40
11	REAR WHEEL ARCH TRIM - LH/RH <i>LH cut</i>	\$ 444.00	222 222 177.60
12	AIRBAG STICKER <i>new</i>	\$ 20.00	✓ 16
13	ALUMINIUM RIM - LH REAR <i>cut</i>	\$ 678.00	✓ 542
14	SUNDRIES <i>new</i>	\$ 400.00	? 4.80
TOTAL SPARE PARTS		\$ 6,692.00	
TOTAL LABOUR CHARGES		\$ 6,832.00	
GRAND TOTAL		\$ 13,524.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Lim*
Surveyed Date : *22/09/17*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 06 Days.*

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0901/2017/PH
Date : 15-Sep-17

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
6 days -ok - jb -8/11

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Chivukula Lavanya @ Pervela Lavanya
Address : 3 Rhu Cross
#03-03
Singapore 437433
Telephone : HP +65 98558270
Type of Claim : Own Damage Claim
Policy No. : 170040012
Vehicle No : **SLQ 8720 X**
Model Code : Audi Q3 2.0 TFSI
Model / Year : Nov-12
Engine No : CCZ263403
Chassis No : WAUZZZ8U3CR053331
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Sep-17
Place of Accident : BISHAN St 21

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLQ 8720 S.

S/N	Nature of Jobs	Estimated Charges	
1	To remove and transfer lhs front & rear door's multi-lock system and power window devices.	S/N \$	560.00 \$ 560.00
2	To dismantle and renew lhs front door & lhs rear doors, align to position. Repair lhs sill panel and B pillar. Reinstall all parts removed.	\$	2,400.00 \$ 1,500.00
3	To respray lhs front & rear doors, lhs sill panel, B pillar and rear bumper.	\$	3,400.00 \$ 1,650.00
4	To renew lhs rear rim and carry out wheel alignment	S/N \$	280.00 \$ 280.00
5	To carry out diagnostic checks.	S/N \$	192.00 \$ 192.00
TOTAL SPARE PARTS		\$	6,832.00 \$ 4,182.00

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 8720 S.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT DOOR LH	\$ 2,079.00	\$ 1,663.20
2	FRONT DOOR SEAL LH	\$ 137.00	\$ 109.60
3	FRONT DOOR CATCH LH	\$ 102.00	
4	FRONT DOOR COVER LH	\$ 219.00	\$ 174.80
5	REAR DOOR LH	\$ 2,079.00	\$ 1,663.20
6	BRACKET FOR DOOR SEAL	\$ 15.00	
7	REAR DOOR CATCH LH	\$ 102.00	
8	REAR DOOR OUTER DOOR SEAL LH	\$ 143.00	\$ 114.40
9	SILL PANEL SEAL LH	\$ 53.00	
10	REAR DOOR COVER - LH	\$ 221.00	\$ 176.40
11	REAR WHEEL ARCH TRIM - LH/RH	\$ 444.00	\$ 177.60
12	AIRBAG STICKER	\$ 20.00	\$ 16.00
13	ALUMINIUM RIM - LH REAR	\$ 678.00	\$ 542.00
14	SUNDRIES	\$ 400.00	\$ 4.80
	TOTAL SPARE PARTS	\$ 6,692.00	\$ 4,642.00
	TOTAL LABOUR CHARGES	\$ 6,832.00	\$ 4,182.00
	GRAND TOTAL	\$ 13,524.00	\$ 8,824.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLQ 8720 X

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0901/2017/MAS

19 Jan 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLQ 8720 X, Audi Q3 2.0 TFSI

With reference to the above-mentioned vehicle, no **SLQ 8720 X**, claimant, **Ms. Chivukula Lavanya @Pervela Lavanya**, please find the related document per attached.

1. A copy of the Original invoice no. 85012024 – S\$8,371.68
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLQ 8720 X

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Sep 2017		22 Sep 2017 15:41 Edit Adj Rpt	S\$8,824.00 Edit Estimates	S\$8,824.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	CHIVUKULA LAVANYA @PERVELA LAVANYA, ID: S8063641E, Tel: +6598558270, Email: LAVANYA.PERVELA@GMAIL.COM	
Vehicle Reg. No.:	SLQ8720X	Date of Loss: 13/09/2017 12:00 - :59
Claim Type:	OD / 2852483884SG	Policy/Cover Note No.: 1700040012 (Comprehensive) Coverage: 23/08/2017 - 29/11/2018
		Excess: S\$1,000.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911	
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 03/10/2017]	
Driver/Custodian:	CHIVUKULA LAVANYA @PERVELA LAVANYA (37 / Female), NRIC: S8063641E, Tel: +6598558270	
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail
<ul style="list-style-type: none"> AIG_SG (25/09/2017): Proceed authorise repair. AIG_SG (25/09/2017): SLQ8720X / OD / 13/09/2017 / Coverage & Excess update AIG_SG (25/09/2017): Authorization on hold, coverage not confirm yet. AIG_SG (25/09/2017): Alert - Adj Mandate Approved (S\$9995.00) - SLQ8720X - Claim Handler: Dally Amri,... 		
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete
Due Date	Priority	Type
Task Group	Subject	Handler
Assigned By	Completed On	Created On
Done?	No results.	

Claim Documents

*SLQ8720X (2852483884SG)
OD
Sep 13 2017 12:00PM
[CHIVUKULA LAVANYA @PERVELA LAVANYA]
Premium Automobiles Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	Use Viewer <input type="checkbox"/>
Assessment Reports					1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	25/09/17 09:37	Adjuster Immediate Advice	1	Load HTM		
Photos/Images					3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	25/09/17 09:26	General View	1	Load JPG	<input checked="" type="checkbox"/>	
2	25/09/17 09:26	General View	1	Load JPG	<input checked="" type="checkbox"/>	
3	25/09/17 09:26	General View	1	Load JPG	<input checked="" type="checkbox"/>	
4	25/09/17 09:26	General View	1	Load JPG	<input checked="" type="checkbox"/>	
5	25/09/17 09:26	General View	1	Load JPG	<input checked="" type="checkbox"/>	
6	25/09/17 09:26	General View	1	Load JPG	<input checked="" type="checkbox"/>	
7	25/09/17 09:26	General View	1	Load JPG	<input checked="" type="checkbox"/>	
8	25/09/17 09:26	General View	1	Load JPG	<input checked="" type="checkbox"/>	
9	25/09/17 09:26	General View	1	Load JPG	<input checked="" type="checkbox"/>	
10	25/09/17 09:26	General View	1	Load JPG	<input checked="" type="checkbox"/>	
11	25/09/17 09:26	General View	1	Load JPG	<input checked="" type="checkbox"/>	
12	25/09/17 09:26	General View	1	Load JPG	<input checked="" type="checkbox"/>	
13	25/09/17 09:26	General View	1	Load JPG	<input checked="" type="checkbox"/>	
14	25/09/17 09:26	General View	1	Load JPG	<input checked="" type="checkbox"/>	
15	25/09/17 09:26	General View	1	Load JPG	<input checked="" type="checkbox"/>	
16	25/09/17 09:26	General View	1	Load JPG	<input checked="" type="checkbox"/>	
17	25/09/17 09:26	General View	1	Load JPG	<input checked="" type="checkbox"/>	
18	25/09/17 09:26	General View	1	Load JPG	<input checked="" type="checkbox"/>	
19	25/09/17 09:26	General View	1	Load JPG	<input checked="" type="checkbox"/>	
20	25/09/17 09:26	General View	1	Load JPG	<input checked="" type="checkbox"/>	
21	25/09/17 09:26	General View	1	Load JPG	<input checked="" type="checkbox"/>	
22	25/09/17 09:26	General View	1	Load JPG	<input checked="" type="checkbox"/>	
23	25/09/17 09:26	General View	1	Load JPG	<input checked="" type="checkbox"/>	
Documentation					1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	25/09/17 09:27	Police Report	1	Load PDF		
2	25/09/17 09:27	Certificate of Insurance	1	Load PDF		
3	25/09/17 09:27	Singapore Accident Statement	1	Load PDF		
4	25/09/17 09:27	Workshop Estimate	1	Load PDF		
5	31/01/18 15:43	WORKSHOP INVOICE	1	Load PDF		
6	31/01/18 15:43	DISCHARGE VOUCHER	1	Load PDF		

Linked Accident Report Documents

					View	Use Viewer <input type="checkbox"/>
Assessment Reports					1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print	
1	13/09/17 19:01	Accident Statement	1	Load HTM		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	13/09/17 18:55	Police Report	Load JPG	<input checked="" type="checkbox"/>
2	13/09/17 18:55	Police Report	Load JPG	<input checked="" type="checkbox"/>
3	13/09/17 18:55	Police Report	Load JPG	<input checked="" type="checkbox"/>
4	13/09/17 18:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	13/09/17 18:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	13/09/17 18:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	13/09/17 18:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	13/09/17 18:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	13/09/17 18:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	13/09/17 18:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	13/09/17 18:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	13/09/17 18:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	13/09/17 18:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	13/09/17 18:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
15	13/09/17 18:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	13/09/17 18:54	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	13/09/17 18:54	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST [Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG17018285/ATBN2

Date: 31/01/2018

REFERENCE

Insured/Claimant: CHIVUKULA LAVANYA @PERVELA
LAVANYA

Policy No: 1700040012

Date of Loss: 13/09/2017

Nature of Claim: OD **Claim No:** 2852483884SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ8720X	Engine No:	CCZ263403
Make & Model:	AUDI Q3, 2.0 TFSI quattro (170 BHP) (A)	Chassis No:	WAUZZZ8U3CR053331
Reg. Date:	30/11/2012 (Man. Year: 2012)	Odometer:	89595 km
Colour:	Silver		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$88,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R17	Rear Tyre Size:	235/55R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,692.00	4,642.00	2,050.00	30.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,832.00	4,182.00	2,650.00	38.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,524.00	8,824.00	4,700.00	34.75
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	12,524.00	7,824.00	4,700.00	37.53
+ GST 7.00/7.00% (S\$)	876.68	547.68	329.00	37.53
Nett Amount (S\$)	13,400.68	8,371.68	5,029.00	37.53

INSPECTION

Date of Assignment: 22/09/2017

Date Inspected: 22/09/2017 **Inspected At:**

Premium Automobiles Pte Ltd (HQ)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Dented	2,079.00 FS	*1,663.20 FS
2	1		*FRONT DOOR SEAL LH	Necessary	137.00 FS	*109.60 FS
3	1		*FRONT DOOR CATCH LH	Not Necessary	102.00 FS	*- FS
4	1		*FRONT DOOR COVER LH	Cut	219.00 FS	*174.80 FS
5	1		*REAR DOOR LH	Dented	2,079.00 FS	*1,663.20 FS
6	1		*BRACKET FOR DOOR SEAL	Not Necessary	15.00 FS	*- FS
7	1		*REAR DOOR CATCH LH	Not Necessary	102.00 FS	*- FS
8	1		*REAR DOOR OUTER DOOR SEAL LH	Necessary	143.00 FS	*114.40 FS
9	1		*SILL PANEL SEAL LH	Not Necessary	53.00 FS	*- FS
10	1		*REAR DOOR COVER-LH	Cut	221.00 FS	*176.40 FS
11	1		*REAR WHEEL ARCH TRIM-LH/RH	N/s Cut	444.00 FS	*177.60 FS
12	1		*AIRBAG STICKER	Necessary	20.00 FS	*16.00 FS
13	1		*ALUMINIUM RIM-LH REAR	Cut	678.00 FS	*542.00 FS
14	1		*SUNDRIES	Necessary	400.00 FS	*4.80 FS
Total Parts (\$\$)					6,692.00	4,642.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER LHS FRONT & REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES	New	560.00	560.00
2	TO DISMANTLE AND RENEW LHS FRONT DOOR & LHS REAR DOORS,ALIGN TO POSITION.REPAIR LHS SILL PANEL AND B PILLAR.REINSTALL ALL PARTS REMOVED	New	2,400.00	1,500.00
3	TO RESPRAY LHS FRONT & REAR DOORS.LHS SILL PANEL,B PILLAR AND REAR BUMPER	New	3,400.00	1,650.00
4	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			6,832.00	4,182.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >