

ASS. REC. BY:	REF CS/MSG17018326/R17b02		Special Instructions:
SURVEYOR	Rasul	ASSIGNMENT (Office)	
From (Person):	Pearlynn Keng	of	MSIG
Estimated Cost:		Bill to:	
<input checked="" type="radio"/> OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS			
To Inspect Vehicle No:	S1R7730 T	Insured:	
at Workshop m/s	Performance Motors	Tel:	63190174
of	303 Alexandra Road		
Policy No:	29014001QMY	Claim No:	530432
Sum Insured:		Excess:	\$1,000.00
Make of Veh:		D.O.A.	21/9/17
(Client's Record)			
CA / <input checked="" type="radio"/> REV /	REP. / REV 24 HRS	H.O.D. Endorsement:	
Date/Time:	22/9/17 5:00pm	Person Contacted:	caroline
		Vehicle <input checked="" type="radio"/> IN <input type="radio"/> OUT	
Date/Time	Action/Instruction	Estimate	
	S1R7730 T-X		
25/9	Report via menmen		
25/9	16:04 inform authorise repair by keng Ang		
25/9 @ 4:24pm	email to gary authorise repair \$1000/-		

Raul

REF: MS19

1068w

ASSIGNMENT

From: _____ Date: 25/9/17

Estimated Cost: _____

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To inspect Vehicle No: SLR 7730T

at Workshop m/s: Performance Motors

of: 303 Alexandra Road

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: \$1,000.00


(Client's Record)

Make of Veh: _____

10am

(Policy Condition) . . .

Remark: The veh had commenced its repair at the time of inspection.



Ball or Market Value: 182K

IDAC Accident Rpt: _____ Consistent? Yes or No

GIA / PR Seen: _____ Consistent? Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time: _____ Action / Instruction: _____

29/11 - confirm \$7926.55, 5 days (Red: 3080.80 : 277%)

Veh No: SLR 7730T Yr Regn: 2017 / AUG

Type: ☒ M.Cas / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or _____

Make: B.M.W X3 cc: 1997

Colour: BLUE A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Sp. Reading: 01199 T Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng No: _____

C No: WBAW4920700X01183

Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 245/55R18

R: _____

BS / ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☒ PIR / ☐ SUMI /

TOYO / YOKO or _____

Front: _____ Rear: _____

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 21/09/17 D.O.I: 25/09/17

Survey held at: PERFORMANCE

Des. of Damages: ☐ Fnt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

N/D FR

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 05 DEC 2017

Date/Time: _____ File Pass to?

Artyst

Date/Time: _____ File Return to?

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech Invs (\$

☐ Weekend (\$

Survey Fee

Transportation

5 + RS 5

☐ Photos

☐ Others

☐

TOTAL

Report Format: OD

Lump Sum / I.B.I. (\$) 7926.55

300
10
310



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG17018326/R1tb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 25-09-2017	
			Code : MSG	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		SLR 7730T
Policy No.	29014001QMY	Coverage (\$)	0.00	
Claim No.	530432	Excess (\$)	1,000.00	
Assign From	MERIMEN (PEARLYNN KONG)	Assign Date	25/09/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c		0
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/09/2017	Inspection Date	25/09/2017	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Sep 2017		22 Sep 2017 16:54 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SIME DARBY SERVICES PTE LTD, Co. Reg. No.: 197501065W								
Vehicle Reg. No.:	SLR7730T	Date of Loss:	21/09/2017 07:00 - :59						
Claim Type:	OD / 530432	Policy/Cover Note No.:	29014001QMY (Comprehensive) Coverage: 28/08/2017 - 27/08/2018						
		Excess:	S\$1,000.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pearllyn Kang Yen Lin - 6594 2588]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/09/2017]								
Driver/Custodian:	SHAW WILLIAM ROBERT CHARLES (47 / Male), NRIC: G5269220U								
Adj Asg. Remarks:	Please revert. Performance Motors arranged survey appointment on 25/09/2017 at 10am. Please confirm and arranged the appointment with Performance Motors. Thank you								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

***SLR7730T (530432)**
OD
Sep 21 2017 7:00AM
[SIME DARBY SERVICES PTE LTD]
Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 25/09/2017 16:04 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8143.45) - SLR7730T - Claim Handler: Pearlyn Kang Yen Lin

Approved:8143.45:a if c

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pearllyn Kang Yen Lin

Date: 25 Sep 2017

Preliminary Advice

Vehicle No	: SLR7730T	Accident Date	: 21/09/2017
Make	: BMW X1	Policy No.	: 29014001QMY
Assignment Date	: 22/09/2017	Excess	: S\$1,000.00
Date of Inspection	: 25/09/2017	Est. Duration of Repair	: 5.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,625.92
Revised Amount	:S\$	7,724.55
Check Items (Estimated)	:S\$	418.90
Total	:S\$	8,143.45
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	182,000.00
COE / PARF Rebate	:S\$	82,516.00
Salvage Value	:S\$	
Margin for Repair	:S\$	99,484.00

Remarks

(x) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 25 September, 2017 4:24 PM
To: Gary Poh Chai Hoon
Cc: Chua Kee Sin; SUR
Subject: AUTHORIZATION FRO SLR 7730T MSIG OWN DAMAGE

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLR7730T (Excess \$1000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company
Owner ID: 1065W

Vehicle Details

Vehicle No.: SLR7730T
Vehicle to be Exported: No
Intended De-registration Date: 26 Sep 2017
Vehicle Make: B.M.W.
Vehicle Model: X3 SDRIVE 20i HID SR NAV
Primary Colour: Blue
Manufacturing Year: 2017
Engine No.: A1001692N20B20A
Chassis No.: WBAWY920700X01183
Maximum Power Output: 135.0 kW (181 bhp)
Open Market Value: \$36,108.00
Original Registration Date: 28 Aug 2017
First Registration Date: 28 Aug 2017
Transfer Count: 0
Actual ARF Paid: \$42,552.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Aug 2027
PARF Rebate Amount: \$31,914.00

Intended COE Rebate Details

COE Expiry Date: 27 Aug 2027
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$51,000.00
COE Rebate Amount: \$50,588.00

Total Rebate Amount: \$82,502.00

The information contained herein is correct as at 26 Sep 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
Last updated on 17 Sep 2017 at 12:38 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/09/2017 17:15
Date Of Accident	21/09/2017 07:20
Exact Location Of Accident	BUONA VISTA FLYOVER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR7730T
Insured/Policyholder	
Name Of Registered Owner	SIME DARBY SERVICES PTE LTD
Co Reg No	S197501065W
Email Address	WILLIAM@TEXELFINANCE.COM
Mobile Phone No	
Alternative Phone No	OFFICE-97729996

Vehicle Particulars

Manufacturer	BMW
Model	X3
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	SHAW WILLIAM ROBERT CHARLES
Passport No/FIN	G5269220U
Date Of Birth	10/01/1970
Occupation	INDOOR
Date Of Driving Pass	11/01/2013
Driving Experience	4 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97729996
Fax Number	
Contact Number	
Email Address	WILLIAM@TEXELFINANCE.COM

Address	38B JALAN MAT JAMBOL 02-12
Postcode	119520
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - LEASING
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC6812B
Vehicle Make/Model/Colour	SUBARU BLUE
Details Of Properties	
Name of Driver	GOH CHOO SENG
NRIC/Passport Number	S7337220H
Contact Number	96677170
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	RIGHT
No. Of Passenger (Including Driver)	1

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

 21/9/17 3:24pm
Driver's Signature (if driver is not the policyholder) / Date & Time

21/9/17 3:24

Witnessed by Reporting Centre Personnel

Sketch Plan



Sketch Plan Pg. 2

Describe Circumstances of the Accident


I was in traffic on South Buona Vista road approaching Buona Vista Flyover. I indicated to turn into the next left lane to enter the Flyover. I did not see (blind spot) the vehicle SLC6812B driven by Mr Goh and scratched the right hand side of his car across two doors. My car has some small damage on the left front side. We exchanged details.

Declaration

We declare the foregoing particulars are true in every respect.

 SERVICES PTE LTD

Policyholder's Signature / Date & Time

 21/9/17 3:29pm

Driver's Signature (If driver is not the policyholder) / Date & Time

21/9/17 3:29

GARY POH CHAI HOON
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159041

Witnessed by Reporting Centre Personnel

Employer
TEXEL ASIA PTE. LIMITED



Name
SHAW WILLIAM ROBERT CHARLES
Occupation
MANAGING DIRECTOR

FIN
G5269220U

Date of Application
24-10-2014
Date of Issue
07-11-2014
Date of Expiry
13-04-2018



L5038204



REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **G 5269220U**

Name:
SHAW WILLIAM ROBERT CHARLES


Birth Date: **10 Jan 1970**
Issue Date: **11 Jan 2013**
Valid Till: **10 Jan 2018**

002140980B



VISIT PASS
Immigration Regulations

Name
SHAW WILLIAM ROBERT CHARLES



Date of Birth	Sex	Nationality
10-01-1970	M	BRITISH
FIN	Date of Issue	Date of Expiry
G5269220U	07-11-2014	13-04-2018

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars =< 3000kg with =< 7 passengers, exclusive of the driver, and other motor vehicles =< 2500kg 11 Jan 2013



License No: G5269220U



MSIG

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Attn: Gary

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.Z.400
Car for Hire

MOTOR MAX PLUS
Comprehensive

Certificate No. B 29014001 QMY

Excess : SGD2,000

Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
SLR7730T

2. Name of Policyholder
Sime Darby Services Pte Ltd

3. Effective Date of the Commencement of Insurance for the purposes of the Act
28/08/2017

4. Date of Expiry of Insurance
27/08/2018

5. Persons or Classes of Persons entitled to drive*

Shaw William Robert Charles

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use for the carriage of passengers or goods in connection with the Policyholder's business.

Use for social domestic and pleasure purposes.

The Policy does not cover

- (1) Use for racing pace-making reliability trial or speed-testing.
- (2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT ANY WORKSHOP OF YOUR CHOICE OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.

Approved Insurers

for Chief Executive Officer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 44211
Date Estimated : 21/09/2017
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Sime Darby Services Private Limited
305 Alexandra Road
#02-01 Vantage Automotive Centre

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 159942

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLR7730T	0X01183	28/08/2017	X3 sDrive20	0
DESCRIPTION		ORIGINAL PRICE	DISC. %	NETT
To replace front LH fender, front LH wheel arch cover include making good the front bumper and knocking out dents caused by the accident		1700.00		1,700.00
* To spray paint front bumper and front LH fender		1996.00		1,996.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.		150.00		150.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.		150.00		150.00
To carry out body cavity preservation. (Per panel).		100.00		100.00
To replace LH bi xenon headlight include programming and conducting tests for proper function		451.00		451.00
Sundries.		80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT LH FENDER	765.70	1.00		765.70
FRT LH WHEEL ARCH COVER	179.20	1.00		179.20
LH BI XENON HEADLIGHT	2,354.65	1.00		2,354.65

SUPPLEMENTARY ITEMS

Total Labour :	4,627.00
Total Parts :	3,299.55
Total Labour & Parts :	7,926.55
Deduction for Excess :	1,000.00
Total Repair Costs less Excess:	6,926.55
GST @7%:	484.86
Grand Total :	7,411.41

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63442773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 44211
Date Estimated : 21/09/2017
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -
Sime Darby Services Private Limited
305 Alexandra Road
#02-01 Vantage Automotive Centre
Singapore 159942

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLR7730T	0X01183	28/08/2017	X3 sDrive20	0

DESCRIPTION

To replace front bumper, left front fender, wheel arch and attachment include knocking cause the accident

painting front bumper, left front fender.

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

To carry out body cavity preservation.
(Per panel).

To replace left front rim including balancing. (1x).

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1X).

To replace left headlight including conduct tests for proper function.

Sundries.

VALUE

2,550.00

2218

2,076.00

177.00

177.00

118.00

94.00

531.00

531.00

150.00

Total Labour 1: 6,404.00

DESCRIPTION

ALLOY RIM 8JX18 DOUBLE SPK 605
FRT LH FENDER
CLADDING BUMPER FRT (PDC/SCHWARZ)
FRT LH WHEEL ARCH COVER
LH BI XENON HEADLIGHT

QTY	PRIC	VALUE
1	919.90	919.90
1	765.70	765.70
1	241.90	241.90
1	179.20	179.20
1	2,354.65	2,354.65

Total Parts : 4,461.35

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64794770

280, Kampong Arang Road
East Coast Centre
Singapore 438180

Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944

Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 44211
Date Estimated : 21/09/2017
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLR7730T	0X01183	28/08/2017	X3 sDrive20	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 25/09/17 01:25 Excess \$S 1000Surveyor's Name RAM Sign _____Surveyor's Tel 90010068 Authorised Yes / C REVERT

Authorised Date _____ Time _____

RESURVEY / EXCESS / YOR Yes / NO PML Yes / NO

Surveyor's E-mail _____

No. of Working Days Recommend 5 days

Return by part

Labour 1	:	6,404.00
Parts	:	4,461.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	760.57
Grand Total	:	11,625.92

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

11777.86

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Sep 2017		22 Sep 2017 16:54 Edit Adj Rpt	S\$7,926.55 Edit Estimates	S\$7,926.55 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SIME DARBY SERVICES PTE LTD, Co. Reg. No.: 197501065W								
Vehicle Reg. No.:	SLR7730T	Date of Loss:	21/09/2017 07:00 - :59						
Claim Type:	OD / 530432	Policy/Cover Note No.:	29014001QMY (Comprehensive) Coverage: 28/08/2017 - 27/08/2018						
		Excess:	S\$1,000.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pearllyn Kang Yen Lin - 6594 2588]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 22/10/2017]								
Driver/Custodian:	SHAW WILLIAM ROBERT CHARLES (47 / Male), NRIC: G5269220U								
Adj Asg. Remarks:	Please revert. Performance Motors arranged survey appointment on 25/09/2017 at 10am. Please confirm and arranged the appointment with Performance Motors. Thank you								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (25/09/2017): Alert - Adj Mandate Approved (S\$8143.45) - SLR7730T - Claim Handler: Pearllyn Ka... MSIG_SG (25/09/2017): SLR7730T (530432) 									
<div> <input type="checkbox"/> </div> ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLR7730T (530432)
OD
Sep 21 2017 7:00AM
[SIME DARBY SERVICES PTE LTD]
Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			View Use Viewer		
Video									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print	
1	22/09/17 10:59	Video from TP							Load MP4		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	25/09/17 13:55	Adjuster Immediate Advice							Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
2	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
3	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
4	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
5	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
6	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
7	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
8	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
9	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
10	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
11	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
12	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
13	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
14	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
15	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
16	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
17	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
18	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
19	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
20	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
21	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
22	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
23	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
24	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
25	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
26	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
27	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
28	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
29	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
30	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
31	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
32	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
33	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	
34	05/12/17 09:51	General View							Load JPG	<input checked="" type="checkbox"/>	

35	05/12/17 09:51	General View		Load JPG	<input checked="" type="checkbox"/>
36	05/12/17 09:51	General View		Load JPG	<input checked="" type="checkbox"/>
37	05/12/17 09:51	General View		Load JPG	<input checked="" type="checkbox"/>
38	05/12/17 09:51	General View		Load JPG	<input checked="" type="checkbox"/>
39	05/12/17 09:51	General View		Load JPG	<input checked="" type="checkbox"/>
40	05/12/17 09:51	General View		Load JPG	<input checked="" type="checkbox"/>
Documentation					
			1 per page ▼		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	22/09/17 10:27	Road Tax - Paid		Load PDF	
2	22/09/17 10:27	COE Rebate		Load PDF	
3	22/09/17 10:27	DL- valid		Load PDF	
4	22/09/17 10:42	Estimate repair cost + DL + visit pass + CI		Load PDF	
5	22/09/17 10:42	Insured GIA report		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/09/17 13:56	workshop estimate		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17018326/R1TBE2

Date: 05/12/2017

REFERENCE

Insured/Claimant: SIME DARBY SERVICES PTE LTD

Policy No: 29014001QMY

Date of Loss: 21/09/2017

Nature of Claim: OD

Claim No: 530432

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR7730T	Engine No:	A1001692N20B20A
Make & Model:	BMW X1, 2.0 SDRIVE20i (A)	Chassis No:	WBAWY920700X01183
Reg. Date:	28/08/2017 (Man. Year: 2017)	Odometer:	1199 km
Colour:	Blue		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	S\$182,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/55 R18	Rear Tyre Size:	245/55 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,611.35	3,379.55	1,231.80	26.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,396.00	4,547.00	1,849.00	28.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,007.35	7,926.55	3,080.80	27.99
- Excess (\$\$)	1,000.00	1,000.00	0.00	0.00
(\$\$)	10,007.35	6,926.55	3,080.80	30.79
+ GST 7.00/7.00% (\$\$)	700.51	484.86	215.65	30.78
Nett Amount (\$\$)	10,707.86	7,411.41	3,296.45	30.79

INSPECTION

Date of Assignment: 22/09/2017

Date Inspected: 25/09/2017 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Dec 2017)
Parts:	M1-SUV	BMW X1 2.0 SDRIVE20i (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR7730T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*ALLOY RIM 8JX18 DOUBLE SPK 605	Serviceable	919.90 FS	*- FS
3	1		*FRT LH FENDER	Bent	765.70 FS	*765.70 FS
4	1		*CLADDING BUMPER FRT (PDC/SCHWARZ)	Serviceable	241.90 FS	*- FS
5	1		*FRT LH WHEEL ARCH COVER	Deformed	179.20 FS	*179.20 FS
6	1		*LH BI XENON HEADLIGHT	Cracked	2,354.65 FS	*2,354.65 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **4,611.35** **3,379.55**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRONT BUMPER, LEFT FRONT FENDER, WHEEL ARCH AND ATTACHMENT INCLUDE KNOCKING CAUSE THE ACCIDENT	New	2,550.00	1,700.00
2	PAINTING FRONT BUMPER, LEFT FRONT FENDER	New	2,218.00	1,996.00
3	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
4	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
5	TO REPLACE LEFT FRONT RIM INCLUDING BALANCING (1X)	New	94.00	0.00
6	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS (1X)	New	531.00	0.00
7	TO REPLACE LEFT HEADLIGHT INCLUDING CONDUCT TESTS FOR PROPER FUNCTIONS	New	531.00	451.00
8	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
Gross Labour Cost (\$\$)			6,396.00	4,547.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >