

ASS. REC. BY:

REF: CS/FCI/7018378/11/rbcl

Special Instruction:

SURVEY

CWS

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time:

25/9/17 3:55pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFN 8877P

Insured:

SHD 4496K

at Workshop m/s

Performance Motors

Tel:

6319 0174

of

303 Alexandra Road

Policy No:

Claim No:

D17009090MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 22/09/17

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

25/9/17

4:02pm

Person Contacted

Caroline

Vehicle IN

OUT

Date/Time

Action/Instruction

(✓) Estimate

SFN 8877P - X

SHD 4496K - CS3/FCI/5013403/21/6d1 - D.O.A: 3/8/2015

Confirm

\$20,106.45, 10 days

Red:

\$3712.10

15%

Surveyor: Tanphi

REF:

FCI

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFN 8877Pat Workshop m/s Performance Motor

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

28/9/2017 12.30pm Owner Driving

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: Plan.

Vehicle: IN / OUT

Veh No: SFN 8877P Yr Regn: 2013, June.Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 316i c.c. 1598Colour: Black. A/C: Insured / Std / NI / NASp. Reading: 54/61 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBA 3A1603 UNP99361Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/50R17

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. \_\_\_\_\_ D.O.I. 28/9/17Survey held at PM L.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 05 JUL 2018

Monte  
5/7/2018

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Preli. Report☒ : Final ReportDays Of Repair: 60Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation: 5050Photos OSPOthers 5/18

TOTAL

Report Format: TPLump Sum / I.B.I. (\$) 20106.45

13x15=195

170+195

505039504



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17018378/T1rb

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 25-09-2017



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4496K	Veh. Inspected	SFN 8877P
Policy No.		Coverage (\$)	0.00
Claim No.	D17009090MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	25/09/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	22/09/2017	Inspection Date	25/09/2017
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## MOTOR SURVEY ASSIGNMENT

<b>Date</b>	25-09-2017	<b>Our Ref No.</b> D17009090MFSH
<b>Accident Date</b>	22-09-2017	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHD4496K	<b>Third Party Vehicle.</b> SFN8877P
<b>Survey Location</b>	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE	
<b>Contact Person.</b>	CAROLINE	
<b>Contact No.</b>	63190174/ 0	<b>Fax No.</b> 64794601
<b>Survey Type</b>	WITHOUT PREJUDICE:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

## FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

<b>Cc : Workshop</b>	PERFORMANCE MOTORS LIMITED	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	KARENT	

## IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Remarks

Save

Phur 28/09 @ 12.30 pm

SPN8877P

80

BMW Dealer

## Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180

Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944

Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

22 SEP 2017

### ESTIMATE

REC: 5.58 PM

Estimate No. : b1 44223  
Date Estimated : 22/09/2017  
Prepared By : Han Kwan Yong

Page No. : 1 of 2

#### - ESTIMATE REPAIR FOR -

Lim Geok Yian  
21 Jalan Raja Udang  
#16-03

Singapore 329215

#### - ACCOUNT - 40000

Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFN8877P	NP99361	26/06/2013	316iA/4	0

#### DESCRIPTION

#### VALUE

To replace left rear door, left rear fender including to knock out rear left wheel house and dented area caused by the accident

6800 - 7,650.00

To respray front left door, rear left door, rear bumper, rear left fender, tail panel, left roof frame, left running board panel and boot compartment

5617 - 6,241.00

To carry out body cavity preservation.  
(Per panel).

100 - 118.00

To carry out body cavity preservation.  
(For cut panel).

451 - 531.00

To replace rear windscreen glass including conduct water leak tests.

✓ 649.00

To remove and install rear door fixed window glass to facilitate repairs including conduct water leak tests.

413 ~~381~~ 413.00

To supply and install front or rear quarter glass solar film.

ny X? 425.00

To supply and install rear windscreen solar film.

ny X? 531.00

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1X).

451 - 531.00

To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.

742 - 873.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

230 - 271.00

To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper

451 - 531.00

## Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road

East Coast Centre  
Singapore 436180Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road

Sime Darby Business Centre

Singapore 159944

Tel. 63190528

63190533 (Motorrad)

Fax. 64796601

64796624

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- All repairs are subject to confirmation
- All repair survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company



GST REG. NO : M2 - 0020081-x

## ESTIMATE

Acknowledged by Repairer

Signature:

Date:

Estimate No. : b1 44223  
Date Estimated : 22/09/2017  
Prepared By : Han Kwan Yong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFN8877P	NP99361	26/06/2013	316iA/4	0

## DESCRIPTION

function. (1 door).

## VALUE

To remove and install fuse box at the rear section to facilitate repairs.

photo 451 531.00

To reconnect electrical components and wirings at the rear section including conduct checks for proper function.

300 354.00

Sundries.

150.00

Total Labour 1: 19,799.00

## DESCRIPTION

BLIND PLUG  
RR LH FENDER  
REAR LH DOOR  
DOOR WEATHERSTRIP REAR  
REAR LH SIDE WINDOW FIXED  
# REAR LH WHEEL HOUSING COVER  
BLIND RIVET HEMLOCK 813  
BLIND RIVET AVIBVLB  
SCREW (SF PLUS M5X15)  
(DG/SL) BODY ADHESIVE K5B (195ML)  
PUNCH RIVET N4  
(DG) BODYWORK ADHESIVE K5A (50ML)  
(DG) CLEANER R1 (100ML)  
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)  
(DG/SL) GLASS PRIMER 30ML (VP206)  
(S/L) SEAM SEAL 300ML

QTY	PRIC	VALUE
3	1.00	3.00
1	1,487.45	1,487.45
1	1,206.45	1,206.45
1	134.60	134.60
1	163.45	163.45
1	140.95	140.95
10.3	2.65	7.95
20.15	0.55	8.25
10.5	0.55	2.75
1	281.55	281.55
60.45	0.55	24.75
1	118.35	118.35
2	23.85	47.70
2	131.55	263.10
1	27.85	27.85
3	33.80	101.40

Total Parts : 4,019.55

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date &amp; Time: 28/9/17 1230 Excess \$:

Signature: [Signature]

Surveyor's Tel: 97495709 Authorised Yes / No:

Authorised Date: Time:

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No RML Yes / No

Surveyor's E-mail: tanfah @ lkkauto.com

No. of Working Days Recommend: 10 - 11 days

Labour 1	:	19,799.00
Parts	:	4,019.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,667.30
Grand Total	:	25,485.85

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE \*\*

23855.85



PERFORMANCE MOTORS L PML Service

.b1csa2.

22/09/17

\*\*\* REPLY OUTSTANDING \*\*\*

<Vehicle Information>

Reg'n...: SFN8877P	Model: 3A26 F30/3161A LZA RL/N13	Last R/O...: 1178883 W3
Stock...: 00050155	Color: 475 SAPPHIRE BLACK	Last Mile...: 50,576
Chassis...: NP99361	Trim: LCL3 LEATHER DAKOTA BLACK/RED	Last S/Date: 05/06/2017
V.Type...: nc	InsCo: 66 MSIG Insurance (S) Pte Ltd	Next S/Date: 26/06/2013
FullChs: WBA3A16030NP99361	IU No: 1125029917	MOT Due Dt.: 15/05/2013
Reg'dt.: 26/06/2013	Wty Exp...:	
Prod'dt: 1130412013-04	E-Wty Exp:	
S/Area...: U1	Key A.....:	
Engine...: A183J441N13B16A	Key B.....:	
RadioCd:	StockDate:	

Option Sub Option Description

dfa	ai1	FOC:3M mat-black
>dfa	sol1	FOC:SOLAR FILM PREMIUM PACKAGE (SG 0
DFA	VOU	PML Voucher \$2,000/-

F4=Enquiry F3=Exit F7=Accept F12=Previous







44223

[illegible]



# Performance Motors Limited

A member of Sime Darby Group

## Acknowledgement

Accident Involving SFN8877P and PH04496K on 22/09/17

I, Ms Lim Geck Yian the owner of Vehicle Registration Number SFN8877P, have been advised by Customer Service Adviser and understand the content of my motor claim as specify herein:

- (1) Type of claim: ☐ Claiming own-policy only.  
☐ Claiming own-policy and uninsured losses.  
☒ Direct settlement with 3<sup>rd</sup>-Party Insurer [Any reversion to own-policy claim shall be submitted to my insurer within **14 days** from date of accident as required by my Policy].
- (2) Performance Motors Limited being an appointed Approved Reporting Centre is bound by GIA not to induce, instigate, encourage or procure any owner or driver of any motor vehicle to engage the services of any solicitors to make any third party claims.
- (3) The estimated repair costs shall be subjected to insurer surveyors' finalisation on completion of job and after considering additional parts and/or labours discovered in the course of repair.
- (4) A compulsory policy excess \_\_\_\_\_, stated in the Motor Policy taken up by you, is applicable for own-damage claim.
- (5) **Loss of Use** and **Cost of Rental** shall be computed in accordance to the number of days as recommended by the surveyor and the Benchmark Rates published in State Courts Practice Directions for Non-injury Motor Accident (NIMA) Claims.
- (6) I am fully aware that Performance Motors Limited is assisting me in my claim against the third-party insurer. I shall release Performance Motors Limited against any liability, loss claim or proceedings which may arise out of or in the course of or by reasons of execution of the services.
- (7) In the event that ~~my insurer or~~ third party insurer is not prepared to settle the claim due to breach of policy or other reasons, I shall pay Performance Motors Limited the full repair bill.
- (8) A towing charge of ~~\$195.00~~, administration fee of \$300.00 and storage fee ~~\$50.00~~ per day is chargeable to me if my vehicle is not repaired by Performance Motors Limited.
- (9) The average time span to settle a claim is **6 months** or longer for complex cases. Any correspondence or status enquiry of the mentioned claim shall be directed to the under-mentioned personnel:

Name: Ms Caroline Tan  
Tel.: 6319 0174  
email: pml-pbsp@sime-darby.com.sg

10. Special Instructions:

Signed by: /

Name: LIM GECK YIAN  
NRIC No.: S1551726C  
Date: 22/09/17

## LETTER OF AUTHORISATION

ACCIDENT INVOLVING SPN8877P & SHD4496K ON 22/09/17.


I, Mrs Lim Geok Han owner of Vehicle Registration No. SPN8877P  
hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and  
settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all  
documents whatsoever in relation to this matter and to accept and receive any payment due  
to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation  
on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if  
the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement  
amount in respect of such claim shall constitute the full discharge of my claim in respect of  
such loss and damage.

Signed by:

  
x  
Name: LIM GEOK HAN (Date) 22/09/17  
NRIC No.: S1551726C

In the presence of:

  
Name: \_\_\_\_\_ (Date) 22/09/17  
NRIC No.: \_\_\_\_\_  
  
HAN RYAN YONG  
Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/09/2017 16:25
Date Of Accident	22/09/2017 09:55
Exact Location Of Accident	VELOCITY @ NOVENA SQUARE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFN8877P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM GEOK YIAN
NRIC No	S1551726C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97905222
Alternative Phone No	OFFICE-97905222

### Vehicle Particulars

Manufacturer	BMW
Model	316
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B27540306SMP
Cover Note Number	

### Driver

Name of Driver	LIM GEOK YIAN
NRIC No	S1551726C
Date Of Birth	19/04/1962
Occupation	INDOOR
Date Of Driving Pass	25/09/1991
Driving Experience	25 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97905222
Fax Number	
Contact Number	OFFICE-97905222
Email Address	NOEMAIL

Address	21 JALAN RAJA UDANG #16-03
Postcode	329215
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD4496K
Vehicle Make/Model/Colour	HYUNDAI COMFORT
Details Of Properties	
Name of Driver	KANG CHONG THIAM
NRIC/Passport Number	S1289133D
Contact Number	97479429
Address	
Postcode	
Insurance Company Name	FIRST CAPITAL INSURANCE LTD
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
Phone Number	
Email Address	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :


(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 22/9/17  
Policyholder's Signature / Date & Time

 22/9/17  
Driver's Signature (If driver is not the policyholder) / Date & Time  
(3.36pm)

  
Witnessed by Reporting Centre Personnel

**Sketch Plan**



## Sketch Plan Pg. 2

### Describe Circumstances of the Accident

When I was driving out of the carpark at Velocity, Nova Square, the other car was turning out from the drop off point and collided with the left hand side of my car.

### Declaration

We declare the foregoing particulars are true in every respect.

X [Signature] 2/19/12  
Policyholder's Signature / Date &  
Time

Driver's Signature (If driver is not the policyholder) / Date & Time  
(3.36pm)

Witnessed by Reporting Centre Personnel

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 44223  
Date Estimated : 22/09/2017  
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -  
Lim Geok Yian  
21 Jalan Raja Udang  
#16-03

- ACCOUNT - 303  
First Capital Insurance Limited  
36 Robinson Road  
#16-01 City House  
Singapore 068877

Singapore 329215

REGN. NO	CHASSIS NO	REGN. DATE	MODEL	MILEAGE
SFN8877P	NP99361	26/06/2013	316iA/4	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear LH door and attachments, rear LH fender include making good the rear bumper, front LH door, tail end panel, LH roof frame, LH running board panel, trunk floor plate and knocking out dents caused by the accident	6800.00		6,800.00	
To respray front LH door, rear LH door, rear bumper, rear LH fender, tail end panel, LH roof frame, LH running board panel and trunk floor plate	5617.00		5,617.00	
To carry out body cavity preservation. (Per panel).	100.00		100.00	
To carry out body cavity preservation. (For cut panel).	451.00		451.00	
To remove and install rear windscreen glass include conducting water leak tests	649.00		649.00	
* To remove and install rear LH door fixed window glass to facilitate repairs include conducting water leak tests	413.00		413.00	
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)	451.00		451.00	
To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.	742.00		742.00	
To remove and install boot compartment carpet and garnish to facilitate repairs	230.00		230.00	
To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper function	451.00		451.00	
To remove and install fuse box at the rear section to facilitate repairs.	451.00		451.00	
To reconnect electrical components and wirings at the rear section including conduct checks for proper function. (For cut panel)	300.00		300.00	



# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## FINAL REPORT

Sundries	150.00	150.00
----------	--------	--------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BLIND PLUG	1.00	8.00		8.00
RR LH FENDER	1,487.45	1.00		1,487.45
REAR LH DOOR	1,206.45	1.00		1,206.45
DOOR WEATHERSTRIP REAR	134.60	1.00		134.60
BLIND RIVET HEMLOCK 813	2.65	10.00		26.50
BLIND RIVET AVIBVLB	0.55	20.00		11.00
SCREW (SF PLUS M5X15)	0.55	10.00		5.50
(DG/SL) BODY ADHESIVE K5B (195ML)	281.55	1.00		281.55
PUNCH RIVET N4	0.55	60.00		33.00
(DG) BODYWORK ADHESIVE K5A (50ML)	118.35	1.00		118.35
(DG) CLEANER R1 (100ML)	23.85	2.00		47.70
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00		263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1.00		27.85
(S/L) SEAM SEAL 300ML	33.80	3.00		101.40

### # SUPPLEMENTARY ITEMS

Total Labour :	16,805.00
Total Parts :	3,752.45
Total Labour & Parts :	20,557.45
Deduction for Excess :	
Total Repair Costs less Excess:	20,557.45
GST @7%:	1,439.02
Grand Total :	21,996.47

**Janice Lee (LKKAuto)**

---

**From:** PBSP <pml-pbsp@simedarby.com.sg>  
**Sent:** Tuesday, December 26, 2017 5:08 PM  
**To:** Taufikh (LKKAuto); SUR  
**Subject:** URGENT / FINAL REPORT / SFN8877P  
**Attachments:** Final Report SFN8877P.pdf

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour :16,805.00

Total Parts :3,752.45

Total Labour & Parts :20,557.45

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17018378/T1rbe2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 12-07-2018



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4496K	Veh. Inspected	SFN 8877P
Policy No.	D-15072701MFSH	Coverage (\$)	0.00
Claim No.	D17009090MFSH	Excess (\$)	0.00
Assign From	KAREN TAN	Assign Date	25/09/2017

### 2. Vehicle Particulars & Condition

Make & Model	B.M.W. 316I	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WBA3A16030NP99361	Colour	BLACK
Odometer	54161	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	PIRELLI	6 mm
L/H Front Tyre	225/50 R17	PIRELLI	6 mm
R/H Rear Tyre	225/50 R17	PIRELLI	6 mm
L/H Rear Tyre	225/50 R17	PIRELLI	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	22/09/2017	Inspection Date	28/09/2017
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

### 5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFN 8877P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	SUNDRIES (SN)	NECESSARY	150.00	150.00
3	BLIND PLUG (SN)	NECESSARY	8.00	8.00
1	RR LH FENDER (SN)	BENT	1,487.45	1,487.45
1	REAR LH DOOR (SN)	DENTED	1,206.45	1,206.45
1	DOOR WEATHERSTRIP REAR (SN)	NECESSARY	134.60	134.60
1	REAR LH SIDE WINDOW FIXED (SN)	NOT NECESSARY	163.45	-
1	REAR LH WHEEL HOUSING COVER (SN)	NOT NECESSARY	140.95	-
10	BLIND RIVET HEMLOCK 813 (SN)	NECESSARY	26.50	26.50
20	BLIND RIVET AVIBVLB (SN)	NECESSARY	11.00	11.00
10	SCREW (SF PLUS M5X15) (SN)	NECESSARY	5.50	5.50
1	(DG/SL) BODY ADHESIVE K5B (195ML) (SN)	NECESSARY	281.55	281.55
60	PUNCH RIVET N4 (SN)	NECESSARY	33.00	33.00
1	(DG) BODYWORK ADHESIVE K5A (50ML)	NECESSARY	118.35	118.35
2	(DG) CLEANER R1 (100ML) (SN)	NECESSARY	47.70	47.70
2	(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) (SN)	NECESSARY	263.10	263.10
1	(DG/SL) GLASS PRIMER 30ML (VP206) (SN)	NECESSARY	27.85	27.85
3	(S/L) SEAM SEAL 300ML (SN)	NECESSARY	101.40	101.40
			4,206.85	3,902.45
<b>LABOUR</b>				
TO REPLACE LEFT REAR DOOR, LEFT REAR FENDER INCLUDING TO KNOCK OUT REAR LEFT WHEEL HOUSE AND DENTED AREA CAUSED BY THE ACCIDENT.			7,650.00	6,800.00
TO RESPRAY FRONT LEFT DOOR, REAR LEFT DOOR, REAR BUMPER, REAR LEFT FENDER, TAIL PANEL, LEFT ROOF FRAME, LEFT RUNNING BOARD PANEL AND BOOT COMPARTMENT.			6,241.00	5,617.00
TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL).			118.00	100.00
TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL).			531.00	451.00
TO REPLACE REAR WINDSCREEN GLASS INCLUDING CONDUCT WATER LEAK TESTS.			649.00	649.00

Report Ref No. CS/FCI17018378/T1rbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND INSTALL REAR DOOR FIXED WINDOW GLASS TO FACILITATE REPAIRS, INCLUDING CONDUCT WATER LEAK TESTS.		413.00	413.00
	TO SUPPLY AND INSTALL FRONT OR REAR QUARTER GLASS SOLAR FILM.	NOT NECESSARY	425.00	-
	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM.	NOT NECESSARY	531.00	-
	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS. (1 X)		531.00	451.00
	TO REMOVE AND INSTALL REAR HAT-TRAY, REAR SEAT, CARPET AND ROOF TOP LINING TO FACILITATE REPAIRS.		873.00	742.00
	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS.		271.00	230.00
	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (1 DOOR)		531.00	451.00
	TO REMOVE AND INSTALL FUSE BOX AT THE REAR SECTION TO FACILITATE REPAIRS	NOT NECESSARY	531.00	-
	TO RECONNECT ELECTRICAL COMPONENTS AND WIRINGS AT THE REAR SECTION INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.		354.00	300.00
			19,649.00	16,204.00
<b>GRAND TOTAL</b>			<b>23,855.85</b>	<b>20,106.45</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>20,106.45</b>

Report Ref No. CS/FCI17018378/T1rbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.