

IN: ASE OWNER

CC 4 / QBE170

LKK:
IDAC

ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II : \$5

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

OI GIA R

Insured Li

BS / NO



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

16/11/19

11/19

8/12/19

14/1/20

3/8/19

4/3/2020

5/12/19 - 16/11/19 - 11/19 - 8/12/19 - 14/1/20 - 3/8/19 - 4/3/2020

16/11/19 - 11/19

Old rear endent p.

File pass to type mandaoe

Penalty TP due to sent mandaoe

File PM to HML to LOSE

- Wt figure diff to sufficient amount -
(Inclusive Lang).

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List:

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(

Agreed / Assessed)

BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

\$5 4600.00

Loss of Rental (LOR):

\$5

(

days)

Loss of Use (LOU):

\$5 400.00

(\$

80 x 5 days)

Loss of Income (LOI):

\$5

(\$

x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost

\$5

Total:

\$5 5000.00

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5 5000.00

Name 1:

T & C Automotive

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$400

COPY SENT
8/3/2020



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD			Ref : CC4/QBE17018436/App3	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583			Date : 26-09-2017	
			Code : QBE	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 8585S	Veh. Inspected	SJG 7189M	
Policy No.		Coverage (\$)	0.00	
Claim No.	VC010734	Excess (\$)	0.00	
Assign From		Assign Date	26/09/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/09/2017	Inspection Date	26/09/2017	
Survey held at	T & C AUTOMOTIVE NO.1 KAKI BUKIT AVENUE 6 #01-71 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

ESTIMATE

T&C AUTOMOTIVE

No.1 Kaki Bukit Ave. 6, #01-49 Autobay
Singapore 417883

Date: 23/09/2017

Vehicle Number : SJG7189M
Model : Mazda 3
Chassis : JM6BK106280425939

TPOBE

Xiao Tony

2008 July

JM6BK106280425939

No.	Descriptions	Quantity	Unit Price	Amount
Parts				
1	Rear bumper <i>Refined</i>	1	\$974.80	\$974.80 799.60
2	Rear bumper clip <i>New</i>	10	\$5.00	\$50.00 50
3	Rear bumper reinforcement <i>Best</i>	1	\$491.70	\$491.70 ✓
5	Rear bumper side retainer RH <i>Green</i>	1	\$67.40	\$67.40 ✓
6	Rear bumper side retainer LH	1	\$67.40	\$67.40 ✓
7	Rear bumper reflector RH <i>Painted</i>	1	\$84.80	\$84.80 ✓
8	Rear bumper reflector LH	1	\$84.80	\$84.80 ✓
9	Rear bumper splash shields <i>new</i>	2	\$55.80	\$111.60 x
10	Rear bumper fastener set <i>new</i>	1	\$50.00	\$50.00 x
11	Rear chamber extractors <i>new</i>	2	\$91.80	\$183.60 x
12	Boot lid <i>Repair</i>	1	\$1,026.70	\$1,026.70 x
13	Boot lid hinges <i>Paint</i>	2	\$249.40	\$498.80 x
14	Boot lid cover dampers	2	\$153.20	\$306.40 x
15	Boot lid cover trim <i>new</i>	1	\$164.60	\$164.60 x
16	Boot lid weatherstrip <i>Paint</i>	1	\$86.80	\$86.80 x
17	Boot lid lock	1	\$187.50	\$187.50 x
18	Boot lid lock stricker <i>Paint</i>	1	\$68.90	\$68.90 x
19	Boot lid lock cable	1	\$41.40	\$41.40 x
20	Boot lid lamp RH <i>Paint</i>	1	\$439.80	\$439.80 x
21	Boot lid lamp LH	1	\$439.80	\$439.80 x
22	Boot lid 3rd brake lamp <i>new</i>	1	\$229.10	\$229.10 x
23	Boot lid "Mazda" logo	1	\$52.10	\$52.10 ✓
24	Boot lid "Mazda" emblem <i>new</i>	1	\$54.00	\$54.00 ✓
25	Boot lid "3" emblem	1	\$38.60	\$38.60 ✓
26	Boot lid "SP" emblem	1	\$48.60	\$48.60 ✓
27	Key lock set <i>new</i>	1	\$886.60	\$886.60 x
28	Rear number plate lamp set <i>Painted</i>	1	\$215.60	\$215.60 ✓
29	Rear end panel <i>Painted</i>	1	\$348.10	\$348.10 ✓
30	Rear end panel garnish <i>Refined</i>	1	\$271.10	\$271.10 ✓
31	Rear end panel garnish clip <i>new</i>	8	\$5.00	\$40.00 10
32	Spare tyre board <i>new</i>	1	\$472.60	\$472.60 x
33	Spare tyre panel <i>Repair</i>	1	\$875.00	\$875.00 x
34	Tail lamp RH <i>Painted</i>	1	\$733.40	\$733.40 ✓
35	Tail lamp LH	1	\$733.40	\$733.40 ✓
36	Tail lamp lower bracket RH <i>Paint</i>	1	\$108.00	\$108.00 x
37	Tail lamp lower bracket LH	1	\$108.00	\$108.00 x
38	Tail lamp panel RH <i>Repair</i>	1	\$194.20	\$194.20 x
39	Tail lamp panel LH	1	\$194.20	\$194.20 x
40	Rear fender RH <i>Paint</i>	1	repair	repair x
41	Rear fender LH	1	repair	repair x
42	Rear fender trim RH <i>Paint</i>	1	\$192.80	\$192.80 x
43	Rear fender trim LH	1	\$192.80	\$192.80 x
44	Rear fender trim lid RH	1	\$97.70	\$97.70 x
45	Rear fender trim lid LH	1	\$97.70	\$97.70 x
46	Exhaust silencer w/chrome tail pipe <i>Best</i>	1	\$982.40	\$982.40 ✓
				\$12,592.80
				Less 20%
				\$2,518.56

5113

408040

Pearl77y/6@gmail.com

No.	Descriptions	Quantity	Unit Price	Amount
			Sub Total 1	\$10,074.24
	S/Nett			
1	Rear number plate <i>couled</i>	1	\$35.00	\$35.00 <i>25</i>
2	Rear bumper pad <i>plm</i>	1	\$350.00	\$350.00 <i>x</i>
3	Rear bumper side flair (set) <i>700m</i>	1	\$450.00	\$450.00 <i>x</i>
4	Boot lid spoiler <i>700m</i>	1	\$500.00	\$500.00 <i>x</i>
5	Reverse sensor (Set) <i>225</i>	1	\$250.00	\$250.00 <i>200</i>
			Sub Total 2	\$1,585.00
	Labour			
1	Remove and replace, to cut, knock and reshape damaged parts & areas.			\$1,800.00 <i>600</i>
2	Spray painting all affected parts.			\$1,600.00 <i>600</i>
3	Check wiring			\$80.00 <i>30</i>
4	Anti-rust undercoating.			\$120.00 <i>40</i>
5	Remove and replace exhaust silencer.			\$200.00 <i>80</i>
6	Remove and refit rear wheelhouse inner garnish, floor carpet & upholstery to facilitate repairs.			\$250.00 <i>80</i>
7	To apply machine press on knuckle arm bearing.			\$70.00 <i>x</i>
			Total Labour	\$4,120.00
			Total Repair Cost	\$15,779.24

1430

total: 5745.4

4/5 4.6K
0.5Days

4.6K

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer
Signature:
Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: VC010734
Our ref: CC4/QBE17018436/Apb3

Date: 14.12.2017

The Motor Claims Department
M/s QBE Insurance (Singapore) Pte Ltd

Dear Sirs/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJG 7189M

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26/09/2017 at the premises of M/s T & C AUTOMOTIVE and have the following to report:-

Workshop Estimate Amount	: S\$	15,779.24
Revised Estimate Amount	: S\$	5,745.40
"Check" Items Amount	: S\$	
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5.0 days

Yours faithfully,

ADRIAN LING
Licensed Appraiser

Catherine Chong (LKK Auto)

From: Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>
Sent: Monday, 25 September, 2017 1:26 PM
To: assignments
Subject: NEW ASSIGNMENT : ACCIDENT INVOLVING GBB8585S AND SJG7189M ON 22/09/2017

Importance: High

Dear LKK,

New Assignment .

Please proceed TP Direct settlement.

TP workshop agree to withdraw from lawyer.

25092017 @ 1.41pm
Ah Chai veh not in.

YSK AUTO WORKSHOP

No. 1 Kaki Bukit Ave 6
#01-71 AutoBay, Singapore 417883
Tel: 9640 2541 Fax: 6556 0801
Email: danny.skyeo@gmail.com

26092017
Ack/tem

Kindly contact AH CHAI : 9007 5148

Syaheeda Othman

Senior Executive, Claims
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd
DID: +6477 1130 Fax: +6533 3270
Email: syaheeda.othman@qbe.com
Visit us on the web at www.qbe.com.sg

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

Shu Pei (LKKAuto)

From: Shu Pei (LKKAuto)
Sent: Monday, 13 November, 2017 4:55 PM
To: 'Syaheeda Nacah Binte Mohamed Othman'; 'Jenny Toh'
Cc: Admin A; Hsiao Tong (LKKAuto); Zaini (LKK Auto)
Subject: RE: NEW ASSIGNMENT : ACCIDENT INVOLVING GBB8585S AND SJG7189M ON 22/09/2017 ***LKK REF:CC4/QBE17018436/Apb3
Attachments: TP GIA REPORT.pdf

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SJG 7189M at M/s T & C Automotive.

Enclosed for your perusal is:
- TP's GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 25 September, 2017 1:43 PM
To: 'Syaheeda Nacah Binte Mohamed Othman' <syaheeda.othman@qbe.com>; assignments <assignments@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: NEW ASSIGNMENT : ACCIDENT INVOLVING GBB8585S AND SJG7189M ON 22/09/2017

Dear Syaheeda Othman,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Syaheeda Nacah Binte Mohamed Othman [<mailto:syaheeda.othman@qbe.com>]

Sent: Monday, 25 September, 2017 1:26 PM

To: assignments <assignments@lkkauto.com>

Subject: NEW ASSIGNMENT : ACCIDENT INVOLVING GBB8585S AND SJG7189M ON 22/09/2017

Importance: High

Dear LKK,

New Assignment .

Please proceed TP Direct settlement.

TP workshop agree to withdraw from lawyer.

LKK AUTO WORKSHOP

No. 1 Kaki Bukit Ave 6

#01-71 AutoBay, Singapore 417883

Tel: 9640 2541 Fax: 6556 0801

Email: dannyskyeo@gmail.com

Kindly contact AH CHAI : 9007 5148

Syaheeda Othman

Senior Executive, Claims

QBE Asia Pacific - Singapore

QBE Insurance (Singapore) Pte Ltd

DP: +6477 1130 Fax: +6533 3270

Email: syaheeda.othman@qbe.com

Visit us on the web at www.qbe.com.sg

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

Shu Pei (LKKAuto)

From: Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>
Sent: Wednesday, 15 November, 2017 10:15 AM
To: Shu Pei (LKKAuto); Jenny Toh
Cc: Admin A; Hsiao Tong (LKKAuto); Zaini (LKK Auto)
Subject: RE: NEW ASSIGNMENT : ACCIDENT INVOLVING GBB8585S AND SJG7189M ON 22/09/2017 ***LKK REF:CC4/QBE17018436/Apb3
Attachments: SAS2280534.pdf

Dear Shu Pei,

Please see attached report.

Our claim ref: VC010734

Thanks.

Syaheeda Othman

Senior Executive, Claims
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd
DID: +6477 1130 Fax : +6533 3270
Email: syaheeda.othman@qbe.com
Visit us on the web at www.qbe.com.sg

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Monday, 13 November, 2017 4:55 PM
To: Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>; Jenny Toh <jenny.toh@qbe.com>
Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Zaini (LKK Auto) <Zaini@lkkauto.com>
Subject: RE: NEW ASSIGNMENT : ACCIDENT INVOLVING GBB8585S AND SJG7189M ON 22/09/2017 ***LKK REF:CC4/QBE17018436/Apb3

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SJG 7189M at M/s T & C Automotive.

Enclosed for your perusal is:
- TP's GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Monday, 25 September, 2017 1:43 PM

To: 'Syaheeda Nacah Binte Mohamed Othman' <syaheeda.othman@qbe.com>; assignments <assignments@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: NEW ASSIGNMENT : ACCIDENT INVOLVING GBB8585S AND SJG7189M ON 22/09/2017

Dear Syaheeda Othman,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Syaheeda Nacah Binte Mohamed Othman [<mailto:syaheeda.othman@qbe.com>]

Sent: Monday, 25 September, 2017 1:26 PM

To: assignments <assignments@lkkauto.com>

Subject: NEW ASSIGNMENT : ACCIDENT INVOLVING GBB8585S AND SJG7189M ON 22/09/2017

Importance: High

Dear LKK,

New Assignment .

Please proceed TP Direct settlement.

TP workshop agree to withdraw from lawyer.

YSK AUTO WORKSHOP

No. 1 Kaki Bukit Ave 6

#01-71 AutoBay, Singapore 417883

Tel: 9640 2541 Fax: 6556 0801

Email: dannyskyeo@gmail.com

Kindly contact AH CHAI : 9007 5148

Syaheeda Othman

Senior Executive, Claims
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd
DID: +6477 1130 Fax : +6533 3270
Email: syatheeda.othman@qbe.com
Visit us on the web at www.qbe.com.sg

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/QBE17018436/Apb3

11 DECEMBER 2017

SIMPLEX (PTE) LTD
33 GUL DRIVE
SINGAPORE 629481
ATTN: THE MANAGEMENT

Dear Sir/Madam,

**ACCIDENT INVOLVING GBB 8585S & SJG 7189M ALONG/AT UPPER PAYA
LEBAR ROAD - UNDERPASS ON 22/09/2017**

We refer to the above accident where we are acting for QBE Insurance (Singapore) Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG (Ms)

Case Handler

DID: 6742 3197

FAX: 6741 4108

Email: chewht@lkkauto.com

c.c. *QBE Insurance (Singapore) Pte Ltd*
(Motor Claims Dept)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CC4/QBE17018436/Ada3q2

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 12-03-2020



Code : QBE

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 8585S	Veh. Inspected	SJG 7189M
Policy No.	8-V0003202-MVA-R007	Coverage (\$)	0.00
Claim No.	VC010734	Excess (\$)	0.00
Assign From	SYAHEEDA NACAH	Assign Date	25/09/2017

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JM6BK106280425939	Colour	GREY
Odometer	377206	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	CONTINENTAL	6 mm
L/H Front Tyre	205/55 R16	CONTINENTAL	6 mm
R/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm
L/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	22/09/2017	Inspection Date	26/09/2017
Survey held at	T & C AUTOMOTIVE NO.1 KAKI BUKIT AVENUE 6 #01-71 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJG 7189M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	974.80	799.60
10	REAR BUMPER CLIP @\$5.00	NECESSARY	50.00	30.00
1	REAR BUMPER REINFORCEMENT	BENT	491.70	491.70
1	REAR BUMPER SIDE RETAINER RH	NECESSARY	67.40	67.40
1	REAR BUMPER SIDE RETAINER LH	NECESSARY	67.40	67.40
1	REAR BUMPER REFLECTOR RH	CRACKED	84.80	84.80
1	REAR BUMPER REFLECTOR LH	CRACKED	84.80	84.80
2	REAR BUMPER SPLASH SHIELDS @\$55.80	NOT NECESSARY	111.60	-
1	SET REAR BUMPER FASTENER	NOT NECESSARY	50.00	-
2	REAR CHAMBER EXTRACTORS @\$91.80	NOT NECESSARY	183.60	-
1	BOOT LID	TO REPAIR SEE LABOUR	1,026.70	-
2	BOOT LID HINGES @\$249.40	NOT NECESSARY	498.80	-
2	BOOT LID COVER DAMPERS @\$153.20	NOT NECESSARY	306.40	-
1	BOOT LID COVER TRIM	NOT NECESSARY	164.60	-
1	BOOT LID WEATHERSTRIP	NOT NECESSARY	86.80	-
1	BOOT LID LOCK	NOT NECESSARY	187.50	-
1	BOOT LID LOCK STRICKER	NOT NECESSARY	68.90	-
1	BOOT LID LOCK CABLE	NOT NECESSARY	41.40	-
1	BOOT LID LAMP RH	NOT NECESSARY	439.80	-
1	BOOT LID LAMP LH	NOT NECESSARY	439.80	-
1	BOOT LID 3RD BRAKE LAMP	NOT NECESSARY	229.10	-
1	BOOT LID 'MAZDA' LOGO	NECESSARY	52.10	52.10
1	BOOT LID 'MAZDA' EMBLEM	NECESSARY	54.00	54.00
1	BOOT LID '3' EMBLEM	NECESSARY	38.60	38.60
1	BOOT LID 'SP' EMBLEM	NECESSARY	48.60	48.60
1	SET KEY LOCK	NOT NECESSARY	886.60	-
1	SET REAR NUMBER PLATE LAMP	CRACKED	215.60	215.60
1	REAR END PANEL	DENTED	348.10	348.10
1	REAR END PANEL GARNISH	DEFORMED	271.10	271.10
8	REAR END PANEL GARNISH CLIP @\$5.00	NECESSARY	40.00	10.00

Report Ref No. CC4/QBE17018436/Ada3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPARE TYRE BOARD	NOT NECESSARY	472.60	-
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	875.00	-
1	TAIL LAMP RH	CRACKED	733.40	733.40
1	TAIL LAMP LH	CRACKED	733.40	733.40
1	TAIL LAMP LOWER BRACKET RH	NOT NECESSARY	108.00	-
1	TAIL LAMP LOWER BRACKET LH	NOT NECESSARY	108.00	-
1	TAIL LAMP PANEL RH	TO REPAIR SEE LABOUR	194.20	-
1	TAIL LAMP PANEL LH	TO REPAIR SEE LABOUR	194.20	-
1	REAR FENDER RH (NPA)	NOT NECESSARY	-	-
1	REAR FENDER RH (NPA)	NOT NECESSARY	-	-
1	REAR FENDER TRIM RH	NOT NECESSARY	192.80	-
1	REAR FENDER TRIM LH	NOT NECESSARY	192.80	-
1	REAR FENDER TRIM LID RH	NOT NECESSARY	97.70	-
1	REAR FENDER TRIM LID LH	NOT NECESSARY	97.70	-
1	EXHAUST SILENCER W/CHROME TAIL PIPE	BENT	982.40	982.40
	LESS 20% DISCOUNT		-2,518.56	-1,022.60
			10,074.24	4,090.40
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	CRACKED	35.00	25.00
1	REAR BUMPER PAD (SN)	NOT NECESSARY	350.00	-
1	SET REAR BUMPER SIDE FLAIR (SN)	NOT NECESSARY	450.00	-
1	BOOT LID SPOILER (SN)	NOT NECESSARY	500.00	-
1	SET REVERSE SENSOR (SN)	DAMAGED	250.00	200.00
			1,585.00	225.00
	LABOUR			
	REMOVE AND REPLACE ,TO CUT ,KNOCK AND RESHAPE DAMAGED PARTS & AREAS.INCLUSIVE OF THE REPAIR OF BOOTLID,SPARE TYRE PANEL,TAIL LAMP PANEL RH AND TAIL LAMP PANEL LH.		1,800.00	600.00
	SPRAY PAINTING ALL AFFECTED PARTS.		1,600.00	600.00
	CHECK WIRING .		80.00	30.00

Report Ref No. CC4/QBE17018436/Ada3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	ANTI-RUST UNDERCOATING.		120.00	40.00
	REMOVE AND REPLACE EXHAUST SILENCER .		200.00	80.00
	REMOVE AND REFIT REAR WHEELHOUSE INNER GARNISH ,FLOOR CARPET & UPHOLSTERY TO FACILITATE REPAIRS .		250.00	80.00
	TO APPLY MACHINE PRESS ON KNUCKLE ARM BEARING.	NOT NECESSARY	70.00	-
			4,120.00	1,430.00
GRAND TOTAL			15,779.24	5,745.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,600.00

Report Ref No. CC4/QBE17018436/Ada3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.