

2020/2021

ASS. REC. BY:

REF: CS/FCI17018489/Gibn

Special Instructions

Surveyor

GO

ASSIGNMENT (Office)

CWS

May chuan

of FCI

Date/Time: 26/9/17 2:40pm

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKN 9166 S

Insured: SHC 32902

at Workshop n/s Weeimes Automotive

Tel:

of 249 Alexandra Road

Policy No

Claim No: D17009087 MFSH

Sum Insured

Excess:

Make of Veh:

D.O.A 22/09/17

(Client's Record)

CA / REV / REP. / REV 24 HRS

! up / 20.11.2017 @ after lunch.

H.O.D. Endorsement

Date/Time: 26/9/17 4:50pm

Person Contacted: Paul Ong

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKN 9166 S - X
	SHC 32902 - X
22/11/17 @ 3:53pm	revised to May chuan by email.
14/3/18 @ 11:32am	confirmed with Paul Paul Ag #4701, 3 days. (Red #4555.90, 42%)

REF:

Tci

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

WEARNES

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR. Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SKN/91665

Yr Regn:

30 Jul 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Country D2

Make:

Volvo V40 cross cc 1560

Colour:

Brown

A/C: Insured / Std / NI / NA

Sp. Reading

67428

T/Radio: Insured / Std / NI / NA

Eng/No:

YUIM8845 BF2059448

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45 R18

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

20-11-17

Survey held at

w/s

3:20pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 16 MAR 2018

Date/Time, File Pass to?

11/5/3 4/15/14

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

3

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ - RS \$

Photos

Others

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

7p

4701

TOTAL

170

50

07

247



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17018489/Gqb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 26-09-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3290Z	Veh. Inspected	SKN 9166S
Policy No.		Coverage (\$)	0.00
Claim No.	D17009087MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	26/09/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	22/09/2017	Inspection Date
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	25-09-2017	Our Ref No.	D17009087MFSH
Accident Date	22-09-2017	Claim Type.	Third Party
Insured Vehicle	SHC3290Z	Third Party Vehicle.	SKN9166S
Survey Location	BODY AND PAINT DEPT 249 ALEXANDRA ROAD		
Contact Person.	PAUL ONG		
Contact No.	64304899/ 81261237	Fax No.	0
Survey Type	DIRECT SETTLEMENT: QUANTUM TO BE AGREED (EST. COR - \$9,840.70)		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WEARNES AUTOMOTIVE PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	MAY CHUA		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/228379)



PRI Documents



Close



PRI Header Details

Claim No	D17009087MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & WEARNES
Workshop Name	WEARNES AUTOMOTIVE PTE LTD (Contact Person : PAUL ONG)	Survey Location & Contact Details	BODY AND PAINT DEPT 249 ALEXANDRA ROAD Mobile: 81261237 , Phone: 64304899 , Fax: 0 EmailId: PAUL.ONG@WEARNES.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT: QUANTUM TO BE AGREED (EST. (		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC3290Z	TP Vehicle No	SKN9166S
PRI Recieved Date	26-09-2017 02:57:37 PM	Surveyor Appointed Date	26-09-2017 02:39:41 PM	Surveyor Accept Date	26-09-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	26-09-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 14 March 2018 11:32 AM
To: Paul Ong Qing Yong
Cc: SUR
Subject: RE: SKN9166S Finalise

Sensitivity: Confidential

Dear Paul,

Confirm final fig \$4,701.00 before GST and 3 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 14 March 2018 10:40 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: paul.ong (paul.ong@wearnes.com) <paul.ong@wearnes.com>
Subject: FW: SKN9166S Finalise
Sensitivity: Confidential

Dear Shiau Chan,

FYNA-CS/FCI17018489/Gqb

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Paul Ong Qing Yong [<mailto:paul.ong@wearnes.com>]
Sent: Wednesday, 14 March 2018 10:37 AM
To: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>
Cc: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: FW: SKN9166S Finalise
Sensitivity: Confidential

Can close?

Best Regards,

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 22 November, 2017 3:53 PM
To: 'Claim Workflow System'; assignments
Cc: MAYCHUA@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17009087MFSH/1
Attachments: CSFCI17018489Gqb.pdf

Dear May,

Enclosed herewith preliminary advice of SKN 9166S.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 26 September, 2017 6:05 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17009087MFSH/1

Dear Paul,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Tuesday, 26 September, 2017 2:38 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; MAYCHUA@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17009087MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17009087MFSH
Our Ref: CS/FCI17018489/Gqb

Date: 22 November 2017

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKN 9166S .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/11/2017 at the premises of M/s WEARNES AUTOMOTIVE . and have the following to report:-

Workshop Estimate Amount	: S\$ 9,256.90 .
Revised Estimate Amount	: S\$ 5,000.00 .
"Check" Items Amount	: S\$ 2,683.00 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Guo Qiang
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	5406B

Vehicle Details

Vehicle No.	SKN9166S
Vehicle to be Exported	No
Intended De-registration Date	21 Nov 2017
Vehicle Make	VOLVO
Vehicle Model	V40 CROSS COUNTRY D2
Primary Colour	Orange
Manufacturing Year	2014
Engine No.	D4162T2948951
Chassis No.	YV1MZ845BF2059448
Maximum Power Output	84.0 kW (112 bhp)
Open Market Value	\$26,601.00
Original Registration Date	30 Jul 2014
First Registration Date	30 Jul 2014
Transfer Count	0
Actual ARF Paid	\$14,242.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	29 Jul 2024
PARF Rebate Amount	\$10,681.00

Intended COE Rebate Details

COE Expiry Date	29 Jul 2024
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$61,990.00
COE Rebate Amount	\$41,459.00
Total Rebate Amount	\$52,140.00

The information contained herein is correct as at 21 Nov 2017

OK

2846

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Complete and submit this Form to Allied World's Authorised Reporting Centre ("ARC") for filing.
2. Please report correctly the details of the accident to speed up the claims process.
3. This Form must be completed by the Policyholder and/or the Authorised Driver.
4. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
5. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
6. Any false reporting may be referred to the Traffic Police Department for investigation.

ACCIDENT STATEMENT

Date and Time of Accident	Date: 22/09/17 Time: 0805
Exact Location of Accident	R01 EAST COAST PARKWAY

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKN 9166S
-----------------------------	-----------

INSURED / POLICYHOLDER (OWN VEHICLE)

Name of Registered Owner (See Insurance Cert.)	TAN LI ZI
Personal Identification - NRIC (Singaporean/PR)	S8015406B
- FIN/Passport Number	
- Not Applicable	

VEHICLE PARTICULARS (OWN VEHICLE)

Vehicle Make / Model	Manufacturer <u>VALEO</u> Model <u>V40CC</u>
Type of Vehicle*	☐ Saloon ☒ MPV ☐ CRV ☐ Van ☐ Lorry ☐ Bus ☐ M/cycle ☐ Others, _____
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	☐ Yes ☒ No (If No, Pls select: ☒ Third Party ☐ Reporting)
Vehicle Category*	☒ Private ☐ Commercial ☐ Motorcycle

INSURANCE COMPANY (OWN VEHICLE)

Name of Insurance Company *	CN TAIPING
Type of Policy	☒ Comprehensive ☐ Third Party Fire & Theft ☐ TP Only
Fleet Policy	☐ Yes ☒ No
Policy Number	DMP CSN1532601702
Motor CI	

DRIVER

	☒ Same as Insured above	
Name of Driver		
Personal Identification - NRIC (Singaporean/PR)		
- FIN/Passport Number		
Date of Birth	24 dd/ 05 mm/ 1980 yy	
Driving Date Pass	15 dd/ 07 mm/ 2005 yy	
Year of Driving Experience	Year(s)	Month(s)
Occupation	☒ Indoor ☐ Outdoor	
Gender	☒ Male ☐ Female	
Contact Number / Mobile Phone / Fax No.	9710 3813	

Address of Driver	1 RAMBONG KAYU RD #04-18	Postcode (431 001)
Email Address		
Was driver an employee of the Insured's Company?	☐ Yes ☒ No	
If No, Relationship of the Driver with the Insured	OWNER	
Vehicle Registration Number of Driver's Own	☐ Yes ☒ No	
Vehicle Registration Number of Driver's Own Vehicle (if applicable)		
Insurance Company of Driver's Own Vehicle (if applicable)		

GENERAL INFORMATION OF THE ACCIDENT

Type of Collision (Eg. Chain collision, Head-On collision, Side Swipe, Front to Rear)	CHAIN COLLISION		
Weather Conditions	☒ Clear	☐ Raining	☐ Others, _____
Road Surface	☒ Dry	☐ Wet	☐ Others, _____

OTHER INFORMATION

Was any foreign vehicle involved in this accident?	☐ Yes ☒ No
Was any body injured in the accident?	☒ Yes ☐ No
Was any other vehicle or property damaged?	☒ Yes ☐ No
Was there any video captured by Car Camera?	☒ Yes ☐ No
Number of Passengers (Including Driver)	02

DETAILS OF POLICE ACTION

Was the Accident reported to the Police?	☒ Yes ☐ No (If Yes, please state which Police Station.)
Police Station Name	MARINE PARADE NPL
Police Station Address	
Police Station Contact	Tel No. _____ Fax No. _____
Was notice of intended Prosecution given?	☐ Yes ☐ No (If Yes, against whom?)

DETAILS OF OTHER VEHICLE / PROPERTY 1

Vehicle Registration Number	SNC 3290Z
Vehicle Make/ Model/ Colour	
Details of Properties	
Name of Driver	
Personal Identification - NRIC (Singaporean/PR)	
- FIN/Passport Number	
Contact Number	
Address	
Name of Insurance Company	
Nature of Damage	
No. of Passenger (Including Driver)	

(Note - Please use page 6 if you need to add more vehicles.)

DETAILS OF OTHER VEHICLE / PROPERTY 2

Vehicle Registration Number	SHE 208 S
Vehicle Make/ Model/ Colour	
Details of Properties	
Name of Driver	
Personal Identification - NRIC (Singaporean/PR)	
- FIN/Passport Number	
Contact Number	
Address	
Name of Insurance Company	
Nature of Damage	
No. of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE / PROPERTY 3

Vehicle Registration Number	
Vehicle Make/ Model/ Colour	
Details of Properties	
Name of Driver	
Personal Identification - NRIC (Singaporean/PR)	
- FIN/Passport Number	
Contact Number	
Address	
Name of Insurance Company	
Nature of Damage	
No. of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE / PROPERTY 4

Vehicle Registration Number	
Vehicle Make/ Model/ Colour	
Details of Properties	
Name of Driver	
Personal Identification - NRIC (Singaporean/PR)	
- FIN/Passport Number	
Contact Number	
Address	
Name of Insurance Company	
Nature of Damage	
No. of Passenger (Including Driver)	

SERVICE ESTIMATE

77895 - C00001

SL: SERVICE SALES - PC

Mr Tan Li Zi

Blk 1 Kampong Kayu Road
#04-18

Singapore 431001

Inv.No. : B&P 0 Page 1
Inv.date : 14/11/2017

WIP No. : 20846

Veh.In/Out:

*Tel.No. : Mobile: 97103813

Reg.No. : SKN9166S

Reg.date : 30/07/2014

Mileage : 0

Chassis No: YV1MZ845BF2059448

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Tan Li Zi

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE REAR BUMPER, LOWER BUMPER, SKID PLATE,	0	1600.00	0		1,600.00 S	800
800	TO PUTTY SPRAY PAINT ON REAR BUMPER, LOWER BUMPER, BOOTLID	0	1400.00	0		1,400.00 S	700
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0		450.00 S	-
R06	REAR NUMBER PLATE & HOLDER	0	60.00	0		60.00 S	-
	BUMPER COVER REAR V4	1.0 EA	1428.70	1285.33		1,428.70 S	-
	TOW COVER REAR V40CC	1.0 EA	73.90			73.90 S	-
	BUMPER LOWER REAR D2	1.0 EA	599.30	579.37		599.30 S	-
	SKID PLATE REAR V40C	1.0 EA	642.70	578.43		642.70 S	-
	BUMPER BRACKET LHR V	1.0 EA	88.70			88.70 S	-
	BUMPER BRACKET RHR V	1.0 EA	88.70			88.70 S	-
	BUMPER RAIL (BEAM) R	1.0 EA	1336.30			1,336.30 S	-
	FOG LAMP RHR V40 13-	1.0 EA	88.90	80.01		88.90 S	-

3 Days.

Que Qiang @ lkk auto. com

Que Qiang - 82880282

before paint photos.

20/11/17

[Signature]
23/11/17.

SERVICE ESTIMATE

77895 - C00001
 Mr Tan Li Zi
 Blk 1 Kampong Kayu Road
 #04-18

SL: SERVICE SALES - PC

Singapore 431001

Closed by : Paul Ong Qing Yong
 Svc Consultant :
 Remarks : Mr Tan Li Zi

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 2
 Inv.date. : 14/11/2017
 WIP No. . : 20846
 Veh.In/Out:
 *Tel.No. . : Mobile: 97103813
 Reg.No. . : SKN9166S
 Reg.date. : 30/07/2014
 Mileage . : 0
 Chassis No: YV1MZ845BF2059448

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BLIND RIVET 4.0*21MM	10.0 EA	3.00			30.00	S
	BUMPER CLIP	10.0 EA	4.80			48.00	S
	PLASTIC RIVET P/W RA	10.0 EA	6.90			69.00	S
	BUMPER INSTALLING MT	1.0 EA	83.40			83.40	S
	PARK ASSIST, REAR V4	1.0 EA	1169.30			1,169.30	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Labour Total 3,510.00
 Parts Total 5,746.90
 Package Total 0.00

Gross Total. 9,256.90
 Net..... 9,256.90
 GST @ 7.0% 647.98
 Total..... 9,904.90
 Paid..... 0.00
 Please Pay.. 9,904.90

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

O - F00003 SL: FIRST CAPITAL INSURANCE LTD
 FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01, CITY HOUSE
 SINGAPORE
 Singapore 068877

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 22/02/2018

WIP No. . : 20846

Veh.In/Out: 20/11/2017 23/11/2017

*Tel.No. . :

Reg.No. . : SKN9166S

Reg.date . : 30/07/2014

Mileage . : 67,428

Chassis No: YV1MZ845BF2059448

Closed by : Paul Ong Qing Yong
 Svc Consultant : ACC
 Remarks : Mr Tan Li Zi

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER,	0	800.00	0		800.00	S
	LOWER BUMPER, SKID PLATE,						
800	TO PUTTY SPRAY PAINT ON	0	700.00	0		700.00	S
	REAR BUMPER, LOWER BUMPER,						
	BOOTLID						
280	TO CHECK WIRING INCLUDE	0	450.00	0		450.00	S
	RESETTING OF ALL ELECTRICAL						
	MODULES						
R06	REAR NUMBER PLATE & HOLDER	0	60.00	0		60.00	S
	BUMPER COVER REAR V4	1.0 EA	1428.70	10		1,285.83	S
	BUMPER LOWER REAR D2	1.0 EA	599.30	10		539.37	S
	SKID PLATE REAR V40C	1.0 EA	642.70	10		578.43	S
	FOG LAMP RHR V40 13-	1.0 EA	88.90	10		80.01	S
	BLIND RIVET 4.0*21MM	10.0 EA	3.00	10		27.00	S
	BUMPER CLIP	10.0 EA	4.80	10		43.20	S
	PLASTIC RIVET P/W RA	10.0 EA	6.90	10		62.10	S
	BUMPER INSTALLING MT	1.0 EA	83.40	10		75.06	S

Gross Total. 4,701.00

Labour Total 2,010.00
 Parts Total 2,691.00
 Package Total 0.00

Net..... 4,701.00
 GST @ 7.0% 329.07
 Total..... 5,030.07
 Paid..... 0.00
 Please Pay.. 5,030.07

GST: S=StdRated; O=OutOfScope; Z=ZeroRated



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17018489/Gqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 16-03-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SHC 3290Z	Veh. Inspected
			SKN 9166S
	Policy No.	D-15072701MFSH	Coverage (\$)
			0.00
	Claim No.	D17009087MFSH	Excess (\$)
			0.00
	Assign From	MAY CHUA	Assign Date
			26/09/2017
2. Vehicle Particulars & Condition			
	Make & Model	VOLVO V40 CROSS COUNTRY D2	c.c
			1560
	Engine No.	HIDDEN	Year of Reg.
			2014
	Chassis No.	YV1MZ845BF2059448	Colour
			BROWN
	Odometer	67428	Steering
			IN ORDER
	Brakes	IN ORDER	Modification
			SPORTS RIM
	General	GOOD	
3. Conditions of Tyres			
		Size	Make
			Balance
	R/H Front Tyre	225/45 R18	BRIDGESTONE
			6 mm
	L/H Front Tyre	225/45 R18	BRIDGESTONE
			6 mm
	R/H Rear Tyre	225/45 R18	BRIDGESTONE
			6 mm
	L/H Rear Tyre	225/45 R18	BRIDGESTONE
			6 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.		
	DAMAGES SEE DETAILS.		
5. General Information			
	Accident Date	22/09/2017	Inspection Date
			20/11/2017
	Survey held at	WEARNES AUTOMOTIVE PTE LTD	
		249 ALEXANDRA ROAD	
		SINGAPORE 159935	
5a. Remarks			
	A) DAMAGES CONSISTENT TO ACCIDENT REPORT.		
	B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.		
	C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKN 9166S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR NUMBER PLATE & HOLDER (SN)	CUT	60.00	60.00
1	BUMPER COVER REAR V4 (SN)	DEFORMED	1,428.70	1,285.83
1	TOW COVER REAR V40CC (SN)	NOT NECESSARY	73.90	-
1	BUMPER LOWER REAR D2 (SN)	SCRATCHED	599.30	539.37
1	SKID PLATE REAR V40C (SN)	CUT	642.70	578.43
1	BUMPER BRACKET LHR V (SN)	NOT NECESSARY	88.70	-
1	BUMPER BRACKET RHR V (SN)	NOT NECESSARY	88.70	-
1	BUMPER RAIL (BEAM) R (SN)	NOT NECESSARY	1,336.30	-
1	FOG LAMP RHR V40 13 (SN)	SCRATCHED	88.90	80.01
10	BLIND RIVET 4.0*21MM (SN)	NECESSARY	30.00	27.00
10	BUMPER CLIP (SN)	NECESSARY	48.00	43.20
10	PLASTIC RIVET P/W RA (SN)	NECESSARY	69.00	62.10
1	BUMPER INSTALLING MT (SN)	NECESSARY	83.40	75.06
1	PARK ASSIST, REAR V4 (SN)	NOT NECESSARY	1,169.30	-
			5,806.90	2,751.00
LABOUR				
TO REPLACE REAR BUMPER, LOWER BUMPER, SKID PLATE.			1,600.00	800.00
TO PUTTY SPRAY PAINT ON REAR BUMPER, LOWER BUMPER, BOOTLID.			1,400.00	700.00
TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.			450.00	450.00
			3,450.00	1,950.00
GRAND TOTAL			9,256.90	4,701.00
RECOMMENDED COST OF REPAIRS				4,701.00

Report Ref No. CS/FCI17018489/Gqbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.