

ASS. REC. BY:

REF: CS/CT117018508/Rib22

Special Instruction:

Surveyor:

RUSU

ASSIGNMENT (Office)

Prelimin

From (Person):

Irene Tay

of

CTL

Date/Time:

26092017 5:14pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKS 1857H

Insured:

SJA 7642C

at Workshop m/s

Kah motor

Tel:

8288 6309

of

15 Ubi Road 4

Policy No:

DMHCSN1734441700

Claim No:

SNM17D03430C02/2

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08062017

CA / REV / REP. / REV 24 HRS 'wp'

6A Mandai Estate

(Tue morning)

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Juson

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SJA 7642 - CC3/AIG11003158/H1a2b3g 2 - 29/01/2011

Confirm final figure \$5,158.37. 6 days

Red: \$4671.63, 48%.

Palm

REF: CTI

24268

ASSIGNMENT

From _____ Date 31/10/17
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No SKS 1857 H
 at Workshop mis Kah Motor
 of GA Mandai Estate
 Insured _____
 Policy No _____
 Claims No _____
 Sum Insured _____ Excess _____
 (Client's Record)
 Make of Veh _____

Morning



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal or Market Value: _____
 OAC Accident Report Consistent? : Yes or No
 GIA / PR Seen Consistent? : Yes or No
 Est. Repairs _____ days Res. Yes or No
 Lum Sum _____ % 3-Val Yes or No

CA / REV / REP. / 24 HRS wp'

Date: _____ Person Contacted _____

Vehicle IN / OUT

Date / Time Action / Instruction

Veh No SKS 1857H Yr Regn 2015 / MP
 Type Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make Honda Odyssey 2.4A cc 2356
 Colour GRN A/C Insured / Std / NI / NA
 Sp Reading 050529 T.Radio Insured / Std / NI / NA

Eng No _____
 C No JHMRC 18907C200148

Gen. Cond. Good / Fair / Poor / Burnt
 Steering In order / Jammed / Leaked / Burnt or
 Brake In order / Jammed / Leaked / Burnt or
 Mod Nil / SRM / STD A/Rim or

Tyre Size F: 215/55R17
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front	Rear
R Bal <u>6</u> mm	R Bal <u>6</u> mm
L Bal <u>6</u> mm	L Bal <u>6</u> mm
D.O.A <u>08/02/17</u>	D.O.I <u>03/10/17</u>

Survey held at Kah Motor
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 22 NOV 2017

Date/Time File Pass to:

typst

Date/Time File Return to:

☐ : Prel. Report
☒ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee

Transportation

S + RS

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Report Format: TP

Lump Sum / I.B.I: (\$) 5158.37

200
200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CS/CTI17018508/R1rb	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 27-09-2017	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJA 7642C	Veh. Inspected	SKS 1857H	
Policy No.	DMHCSN1734441700	Coverage (\$)	0.00	
Claim No.	SNM17D0343OC2/2	Excess (\$)	0.00	
Assign From	IRENE TAY (MERIMEN)	Assign Date	26/09/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c			
Engine No.	Year of Reg.			
Chassis No.	Colour			
Odometer	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/06/2017	Inspection Date		
Survey held at				
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jun 2017		26 Sep 2017 17:14 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	KIRALY AUTOMOBILE PTE LTD, Co. Reg. No.: 201436970K		
Main Claimant:	SIN LAI FONG, ID: S7132426E		
Vehicle Reg. No.:	SKS1857H	Date of Loss:	08/06/2017 08:00 - :59
Claim Type:	TP / SNM17D03430C02/2	Policy/Cover Note No.:	DMHCSN1734441700 (Comprehensive)
Vehicle Reg. No. (Insured):	SJA7642C	Policy No. (Claimant):	17-MW002806-R02
		Excess:	\$0.00
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/10/2017]		
Driver/Custodian (Insured):	SHAMSURIA BIN HANAFI (52 / Male), NRIC: S1713427B, Tel: +6584242623		
Adj Asg. Remarks:	PLEASE ASSIST TO CONDUCT A PRS AND REVERT WITH YOUR RECOMMENDATION		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Vehicle only in on Tue.
morning - Survey / Repair

Catherine Chong (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Tuesday, 26 September, 2017 4:33 PM
To: assignments@lkkauto.com; Admin A
Cc: Jason Heng
Subject: CTP REF NO. SNM17D03430C02 HONDA REF NO. SKS1857H - ACCIDENT INVOLVING SJA7642C AND SKS1857H ON 08 JUNE 2017

Dear Sir/Mdm,

We refer to the above matter and the email below.

Please assist to get your surveyor, Marcus Tay from your end to liaise with Jason from Kah Motor

Regards

Irene Tay

Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389-6192
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: irene.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Jason Heng [mailto:jasonheng@honda.com.sg]
Sent: Tuesday, 26 September, 2017 4:21 PM
To: Irene Tay <irene.tay@sg.cntaiping.com>
Subject: RE: SNM17D03430C02 & SNM16D05651C02
Importance: High

Dear Irene,

Kindly appoint Marcus Tay to survey SKS1857H.

Thank you

Regards,
Jason

Mandai Body & Paint Centre
Kah Motor Sdn Bhd
Mobile: 82886309

From: Jason Heng
Sent: Wednesday, 20 September, 2017 6:59 PM
To: 'Irene Tay' <irene.tay@sg.cntaiping.com>
Subject: RE: SNM17D03430C02 & SNM16D05651C02

Dear Irene,

Has the assignment been given to the surveyors? I have not heard back from them.

Regards,
Jason

Mandai Body & Paint Centre
Kah Motor Sdn Bhd
Mobile: 82886309

From: Irene Tay [mailto:irene.tay@sg.cntaiping.com]
Sent: Monday, 18 September, 2017 4:41 PM
To: Jason Heng <jasonheng@honda.com.sg>
Cc: Jerome Tan <jerometan@honda.com.sg>; Randell Goon <randellgoon@honda.com.sg>
Subject: RE: SNM17D03430C02 & SNM16D05651C02

WITHOUT PREJUDICE
Save As To Costs

Dear Sir/Mdm,

We refer to your pre-repair survey request / email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop.

Here are the list of surveyors ;

Marcus Chua
Edward Cho
Tay Beng Hee
See Chew Seng
Dereck Oh Siong Wee
Mohd Fadhilah Bin Osman
Cedric Ng
Steven Foong
Adrian Ling
Henry Ng

We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Irene Tay

Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E

DID: 6389-6192
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: irene.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Jason Heng [<mailto:jasonheng@honda.com.sg>]
Sent: Thursday, 14 September, 2017 9:16 AM
To: Irene Tay <irene.tay@sg.cntaiping.com>
Cc: Jerome Tan <jerometan@honda.com.sg>; Randell Goon <randellgoon@honda.com.sg>
Subject: SNM17D03430C02 & SNM16D05651C02

Dear Irene,

I will be taking the email below as liability is cleared and fully in both my client's favour. Please advise who you would like to appoint the survey the 2 vehicles.

Thank you.

Regards,
Jason

Mandai Body & Paint Centre
Kah Motor Sdn Bhd
Mobile: 82886309

From: Randell Goon
Sent: Friday, 8 September, 2017 2:58 PM
To: Irene Tay <irene.tay@sg.cntaiping.com>
Cc: Jason Heng <jasonheng@honda.com.sg>; Jerome Tan <jerometan@honda.com.sg>
Subject: RE:

Dear Irene,

Noted on the below reply. Kindly liaise with our BP SA Mr Jason Heng. Thank you.

Best regards,
Randell

From: Irene Tay [<mailto:irene.tay@sg.cntaiping.com>]
Sent: Friday, 8 September, 2017 2:53 PM
To: Randell Goon <randellgoon@honda.com.sg>
Subject:

Dear Sir,

We refer to the telephonic conversation between you and our Ms So Chow on the even date.
Refer to the following claims;

CTP Ref No. SNM17D03430C02 KM Ref No. SKS1857H DOL. 08 June 2017
CTP Ref No. SNM16D05651C02 KM Ref No. SGQ444E DOL. 28 Nov 2016


Liability is down on our insured.

Hence, we are prepare to do a direct settlement with you.

Regards,


Irene Tay

Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389-6192
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: irene.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Record's Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/06/2017 15:20
Date Of Accident	08/06/2017 08:30
Exact Location Of Accident	NORTH BUONA VISTA RD TOWARDS COMMONWEALTH AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS1857H
Insured/Policyholder	
Name Of Registered Owner	SIN LAI FONG
NRIC No	S7132426E
Email Address	SINLFL@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-90666119
Alternative Phone No	OTHERS-90666119

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY-2.4 EXV-S (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	17-MW002806-R02
Cover Note Number	

Driver

Name of Driver	LEE CHEW HUNG
NRIC No	S6918582G
Date Of Birth	05/06/1969
Occupation	INDOOR
Date Of Driving Pass	25/09/1996
Driving Experience	20 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81121917
Fax Number	
Contact Number	
Email Address	LCHEWHUN@GMAIL.COM

Address	BLK 503 JELAPANG RD #20-366
Postcode	670503
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION- HEAD TO REAR (TP HIT INSURED)
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACHED STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJA7642C
Vehicle Make/Model/Colour	SUZUKI SX4 ORANGE
Details Of Properties	FRONT PROTION DAMAGE
Name of Driver	SHAMSURIA BIN HANAFI
NRIC/Passport Number	S1713427B
Contact Number	84242623
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan Pg. 1

Vehicle No	SKS1857H	Annex E
Describe Circumstances of the Accident		
We were knocked from behind by a Suzuki (SJA 7642C) on the third lane on North Suona Vista Road before the turning junction to Commonwealth Avenue at around 8.30 am. Our car was stationary at the time of the accident. The light was red for a while and it was not turning green.		
Declaration		
We declare the foregoing particulars are true in every respect.		
 Policyholder's Signature / Date & Time	 Driver's Signature (If driver is not the policyholder) / Date & Time	 Witnessed by Reporting Centre Personnel
8/6/17 9.20 am	8/6/17 9.20 am	8/6/17 9.20 am

Vehicle No SKS1857H

SKETCH PLAN

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


[Signature] 8 June 17
9.20am
Policyholder's Signature / Date & Time

[Signature] 8/6/17
9.10 am
Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature] 8/6/17
9.20am
Witnessed by Reporting Centre Personnel

Sketch Plan

A = SKS1857H
B = SJA 7642C



Please continue to Annex E



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SKS1857H
Chassis No : JHMRC1890FC200148
Model : ODYSSEY 2.4 EXV-S 15YM
Owner's Name : SIN LAI FONG
Ins Policy No. : 17-MW002806-R02
Date of Accident : 8/6/2017

Document No. : SQT17002698
Date : 22. Jun 2017
Customer No. : WZC008
Svc Advisor : JASON HENG
Engine No : K24W71010060
Date | Time : 22. Jun 2017 6:12:18 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount Incl GST
	THIRD PARTY CLAIMS (J/NO: 10128) OWNER: SIN LAI FONG OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 8/6/17 SURVEYED BY: DATE: TP INSURER: CHINA TAIPING INSURANCE (S'PORE) PTE L TP VEH: SJA7642C						
04715-T6A-900ZZ	FACERR.BUMPER	1	557.20	25	417.90	29.25	447.15
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
74940-TR0-003	BUZZER ASSYSMART	1	58.90	25	44.17	3.09	47.26
91505-TM8-003	CLIPBUMPER	7	2.00	25	10.50	0.74	11.24
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1	18.70	25	14.02	0.98	15.00
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	18.70	25	14.02	0.98	15.00
66100-T6A-300ZZ	PANEL COMPRR.	1	451.80	25	338.85	23.72	362.57
68100-T6A-Q10ZZ	TAILGATE COMP	1	1049.80	25	787.35	55.11	842.46
75701-T6A-000	EMBLEMH	1	25.80	25	19.35	1.35	20.70
74827-S2G-010	PROTECTORLICENSE PLATE	2	2.00	25	3.00	0.21	3.21
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER	1	202.20	25	151.65	10.62	162.27
84640-T6A-003ZA	LINING ASSYRR.PANEL	1	101.60	25	76.20	5.33	81.53
74800-TF0-J02	LOCKTAILGATE	1	181.70	25	136.27	9.54	145.81
73211-T6A-Q02	GLASS SET,RR.WINDSHIELD	1	991.30	25	743.47	52.04	795.51
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	17.60		35.20	2.46	37.66
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	16.60		16.60	1.16	17.76
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	16.60		16.60	1.16	17.76
73221-SR4-000	SPACERRR.W/SHIELD	4	3.90		15.60	1.09	16.69
73225-TM8-000	RUBBER A WINDSHIELD DAM	1	3.60		3.60	0.25	3.85
73226-SZW-000	DAMPERSTD 5X5	2	8.30		16.60	1.16	17.76
76711-T6A-003	CAPPIVOT	1	4.70		4.70	0.33	5.03



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SKS1857H
Chassis No : JHMRC1890FC200148
Model : ODYSSEY 2.4 EXV-S 15YM
Owner's Name : SIN LAI FONG
Ins Policy No. : 17-MW002806-R02
Date of Accident : 8/6/2017

Document No. : SQT17002698
Date : 22. Jun 2017
Customer No. : WZC008
Svc Advisor : JASON HENG
Engine No : K24W71010060
Date | Time : 22. Jun 2017 6:12:18 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
Sum Item					3305.65	231.37	3,537.02
BOSUN	SUNDRIES	1	50.00		50.00	3.50	53.50
BG02R	REPLACE RR. WINDSCREEN.(N)	1	300.00		300.00	21.00	321.00
BODAMKIT	WINDSCREEN DAM KIT.	1	80.00		80.00	5.60	85.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BOJSE	BODY JOINT SEALANT FOR END PANEL (N)	1	80.00		80.00	5.60	85.60
BOJSE	BODY JOINT SEALANT FOR TAILGATE (N)	1	80.00		80.00	5.60	85.60
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00		650.00	45.50	695.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00		650.00	45.50	695.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	160.00		160.00	11.20	171.20
BMU30A	STRAIGHTEN ALIGN & PULL BACK EXHAUST SYSTEM. (N)	1	180.00		180.00	12.60	192.60
BOMISC1	REMOVE & INSTALL REAR-VIEW CAMERA (N)	1	140.00		140.00	9.80	149.80
BOMISC1	RESET & CALIBRATE VEHICLE SMART ENTRY SYSTEM (N)	1	140.00		140.00	9.80	149.80
BOMISC1	REMOVE & TRANSFER TAILGATE SPOILER	1	140.00		140.00	9.80	149.80
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	4000.00		4000.00	280.00	4280.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	3000.00		3000.00	210.00	3210.00
Sum Labor					9830.00	688.10	10,518.10

Survey By

Date & Time

Excess

Status

Signature

Total Amount 13,135.65 919.47 14,055.12

Total (Inclusive of GST) 14,055.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 3/10/2017 10:41:39 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING
Chassis No: JHMRC1890FC200148
License No: SKS1857H
Mileage: 50529
Engine No: K24W71010060

Document No: SVO17063284
Printed By: JASONHENG
Order Date: 3. October 2017
Order Time: 3:20:24 PM
Service Advisor: JASON HENG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	GST Amt	Amount Incd GST
	THIRD PARTY CLAIMS (J/NO: 10128) OWNER: SIN LAI FONG OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 8/6/17 SURVEYED BY: RASUL DATE: 3/9/17 TP INSURER: CHINA TAIPING INSURANCE (S'PORE) PTE L TP VEH: SJA7642C						
68100-T6A-Q10ZZ	TAILGATE COMP	1	1,049.80 ✓	25	787.35	55.11	842.46
75701-T6A-000	EMBLEMH	1	25.80 ✓	25	19.35	1.35	20.70
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	17.60 ✓	25	26.40	1.85	28.25
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	16.60 ✓	25	12.45	0.87	13.32
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	16.60 ✓	25	12.45	0.87	13.32
73221-SR4-000	SPACERRR.W/SHIELD	4	3.90 ✓	25	11.70	0.82	12.52
73225-TM8-000	RUBBER A WINDSHIELD DAM	1	3.60 ✓	25	2.70	0.19	2.89
73226-SZW-000	DAMPERSTD 5X5	2	8.30 ✓	25	12.45	0.87	13.32
76711-T6A-003	CAPPVOT	1	4.70 ✓	25	3.52	0.25	3.77
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00 ✓		120.00	8.40	128.40
	SUM PARTS:				1,008.37	70.58	1,078.95
BOSUN	0701 SUNDRIES	1	30.00 ✓		30.00	2.10	32.10
BG02R	1757 REPLACE RR. WINDSCREEN.(N)	1	280.00 ✓		280.00	19.60	299.60
BODAMKIT	0701 WINDSCREEN DAM KIT.	1	80.00 ✓		80.00	5.60	85.60
BOJSE	1374 BODY JOINT SEALANT FOR TAILGATE (N)	1	80.00 ✓		80.00	5.60	85.60
BKTG02R	1466 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	560.00 ✓		560.00	39.20	599.20
BML02I	1466 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	140.00 ✓		140.00	9.80	149.80
BOMISC1	1466 REMOVE & INSTALL REAR-VIEW CAMERA (N)	1	140.00 ✓		140.00	9.80	149.80
BOMISC1	1466 RESET & CALIBRATE VEHICLE SMART ENTRY SYSTEM (N)	1	140.00 ✓		140.00	9.80	149.80
BOMISC1	1466 REMOVE & TRANSFER TAILGATE SPOILER	1	120.00 ✓		120.00	8.40	128.40
BKRP02M	1466 CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS.	1	1,680.00 ✓		1,680.00	117.60	1,797.60
BP05R	1718	1	900.00 ✓		900.00	63.00	963.00



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING
Chassis No: JHMRC1890FC200148
License No: SKS1857H
Mileage: 50529
Engine No: K24W71010060

Document No: SVO17063284
Printed By: JASONHENG
Order Date: 3. October 2017
Order Time: 3:20:24 PM
Service Advisor: JASON HENG

SPRAY PAINTING ON REPAIRED OR
REPLACED AREAS.(5P)

SUM LABOUR:	4,150.00	290.50	4,440.50
TOTAL SGD	5,158.37	361.08	5,519.45

Total Payable (SGD) 5,519.45

GST Amount is calculated from individual line(s)

Janice Lee (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Tuesday, November 21, 2017 9:13 AM
To: Jason Heng
Cc: Rasul (LKKAuto); SUR
Subject: FW: Finalization For SKS1857H - DOA 18/7/17 *LKK Ref: CS/CTI17018508/R1rb
Attachments: Resurvey B4 Paint _ SKS 1857 H; 0397_001.pdf

Without Prejudice

Hi Jason,

Thank you for your email.

Hi Rasul/ Janice,

FYNA. CS/CTI17018508/R1rb

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jason Heng [mailto:jasonheng@honda.com.sg]
Sent: Tuesday, 21 November, 2017 9:01 AM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: FW: Finalization For SKS1857H - DOA 18/7/17

Dear Rasul/Hsiao Tong,

Please see attached. An incorrect invoice was attached in the previous email. Kindly refer to the attached invoice.

Regards,
Jason

Mandai Body & Paint Centre
Kah Motor Sdn Bhd
Mobile: 82886309

From: Jason Heng
Sent: Monday, 20 November, 2017 2:51 PM

To: 'Rasul@lkkauto.com' <Rasul@lkkauto.com>; 'Hsiao Tong (LKKAUTO)' <chewht@lkkauto.com>
Subject: Finalization For SKS1857H - DOA 18/7/17

Dear Rasul,

We enclosed the total final repair costs for,

Vehicle No.	SKS1857H
Final Repair Costs (exclude GST)	\$5,158.37
Repair Period* (Days)	6 days

***Note: Repair period does include Sunday and Public Holiday.**

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

In addition, I have attached photos of before paint, '?' items and supplementary parts (if any) for your records.

Regards,
Jason

Jason Heng
Kah Motor Body & Paint Centre
6A Mandai Estate
Singapore 729903
DID: 65145248
Mobile: 82886309
Email: jasonheng@honda.com.sg

KAHMOTOR
(A MEMBER OF ORIENTAL HOLDINGS BERHAD)
HONDA
The Power of Dreams



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Jun 2017		26 Sep 2017 17:14 Edit Adj Rpt	S\$5,158.37 Edit Estimates	S\$5,158.37 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	KIRALY AUTOMOBILE PTE LTD , Co. Reg. No.: 201436970K		
Main Claimant:	SIN LAI FONG , ID: S7132426E		
Vehicle Reg. No.:	SKS1857H	Date of Loss:	08/06/2017 08:00 - :59
Claim Type:	TP / SNM17D03430C02/2	Policy/Cover Note No.:	DMHCSN1734441700 (Comprehensive)
Vehicle Reg. No. (Insured):	SJA7642C	Policy No. (Claimant):	17-MW002806-R02
		Excess:	S\$0.00
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 05/10/2017]		
Driver/Custodian (Insured):	SHAMSURIA BIN HANAFI (52 / Male), NRIC: S1713427B, Tel: +6584242623		
Adj Asg. Remarks:	PLEASE ASSIST TO CONDUCT A PRS AND REVERT WITH YOUR RECOMMENDATION		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKS1857H (SNM17D03430C02/2)
[SJA7642C]
TP
SIN LAI FONG
Jun 8 2017 8:00AM
[KIRALY AUTOMOBILE PTE LTD]
Kah Motor Co Sdn Bhd

Upload Documents			Upload Photos			Compose New Letter			View Use Viewer		
Video									1 per page		☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)						Thumbnail		Print	
1	08/06/17 15:28	Video - Accident [Linked Accident Report Documents]						1 Load MP4			
Assessment Reports									1 per page		☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)						Thumbnail		Print	
1	08/06/17 15:28	Accident Statement						1 Load HTM			
Photos/Images									3 per page		☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)						Thumbnail		Print	
1	08/06/17 15:27	Accident Photo [Linked Accident Report Documents]						1 Load JPG		☒	
2	08/06/17 15:27	Accident Photo [Linked Accident Report Documents]						1 Load JPG		☒	
3	08/06/17 15:27	Accident Photo [Linked Accident Report Documents]						1 Load JPG		☒	
4	08/06/17 15:27	Accident Photo [Linked Accident Report Documents]						1 Load JPG		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	22/11/17 09:58	General View						1 Load JPG		☒	
2	22/11/17 09:58	General View						1 Load JPG		☒	
3	22/11/17 09:58	General View						1 Load JPG		☒	
4	22/11/17 09:58	General View						1 Load JPG		☒	
5	22/11/17 09:58	General View						1 Load JPG		☒	
6	22/11/17 09:58	General View						1 Load JPG		☒	
7	22/11/17 09:58	General View						1 Load JPG		☒	
8	22/11/17 09:58	General View						1 Load JPG		☒	
9	22/11/17 09:58	General View						1 Load JPG		☒	
10	22/11/17 09:58	General View						1 Load JPG		☒	
11	22/11/17 09:58	General View						1 Load JPG		☒	
12	22/11/17 09:58	General View						1 Load JPG		☒	
13	22/11/17 09:58	General View						1 Load JPG		☒	
14	22/11/17 09:58	General View						1 Load JPG		☒	
15	22/11/17 09:58	General View						1 Load JPG		☒	
16	22/11/17 09:58	General View						1 Load JPG		☒	
17	22/11/17 09:58	General View						1 Load JPG		☒	
18	22/11/17 09:58	General View						1 Load JPG		☒	
19	22/11/17 09:58	General View						1 Load JPG		☒	
20	22/11/17 09:58	General View						1 Load JPG		☒	
21	22/11/17 09:58	General View						1 Load JPG		☒	
22	22/11/17 09:58	General View						1 Load JPG		☒	
23	22/11/17 09:58	General View						1 Load JPG		☒	
24	22/11/17 09:58	General View						1 Load JPG		☒	
25	22/11/17 09:58	General View						1 Load JPG		☒	

26	22/11/17 09:58	General View	1	Load JPG	✓
27	22/11/17 09:58	General View	1	Load JPG	✓
28	22/11/17 09:58	General View	1	Load JPG	✓
29	22/11/17 09:58	General View	1	Load JPG	✓
30	22/11/17 09:58	General View	1	Load JPG	✓
31	22/11/17 09:58	General View	1	Load JPG	✓
32	22/11/17 09:58	General View	1	Load JPG	✓
33	22/11/17 09:58	General View	1	Load JPG	✓
34	22/11/17 09:58	General View	1	Load JPG	✓
35	22/11/17 09:58	Reinspection Photo	1	Load JPG	✓
36	22/11/17 09:58	Reinspection Photo	1	Load JPG	✓
37	22/11/17 09:58	Reinspection Photo	1	Load JPG	✓
Documentation				1 per page	✓
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	12/06/17 14:10	ASSIGNMENT	1	Load PDF	
2	12/06/17 14:10	OI GIA REPORT	1	Load PDF	
3	12/06/17 14:10	ESTIMATES	1	Load PDF	
4	26/09/17 17:15	GIA REPORT SJA7642C	1	Load PDF	
5	26/09/17 17:15	EMAIL FROM HONDA	1	Load PDF	
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	08/06/17 15:27	Sketch Plan [Linked Accident Report Documents]	1	Load TIF	

Linked Accident Report Documents

				View	Use Viewer
				1 per page	✓
Video					
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	08/06/17 15:28	Video - Accident	1	Load MP4	
Assessment Reports				1 per page	✓
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	08/06/17 15:28	Accident Statement	1	Load HTM	
2	22/06/17 18:01	Addendum Sheet	1	Load TIF	
3	22/06/17 18:01	Accident Statement Addm. #1	1	Load HTM	
Photos/Images				3 per page	✓
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	08/06/17 15:27	Accident Photo	1	Load JPG	✓
2	08/06/17 15:27	Accident Photo	1	Load JPG	✓
3	08/06/17 15:27	Accident Photo	1	Load JPG	✓
4	08/06/17 15:27	Accident Photo	1	Load JPG	✓
Documentation				1 per page	✓
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	08/06/17 15:27	Sketch Plan	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer			

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI17018508/R1RBE2
 Date: 12/12/2017

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMHCSN1734441700	
Claimant Vehicle No: SKS1857H	Insured Vehicle No: SJA7642C	
Date of Loss: 08/06/2017	Nature of Claim: TP	Claim No: SNM17D03430C02/2

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKS1857H		Engine No: K24W71010060
Make & Model: HONDA ODYSSEY, 2.4 EXV-S (A)		Chassis No: JHMRC1890FC200148
Reg. Date: 30/03/2015 (Man. Year: 2015)		Odometer: 50529 km
Colour: Grey		
Engine Capacity: 2356 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55R17	Rear Tyre Size: 215/55R17	
Front Left Side: Dunlop 6 mm	Rear Left Side: Dunlop 6 mm	
Front Right Side: Dunlop 6 mm	Rear Right Side: Dunlop 6 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,355.65	1,038.37	2,317.28	69.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,780.00	4,120.00	5,660.00	57.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,135.65	5,158.37	7,977.28	60.73
+ GST 7.00/7.00% (S\$)	919.50	361.09	558.41	60.73
Nett Amount (S\$)	14,055.15	5,519.46	8,535.69	60.73

INSPECTION

Date of Assignment: 26/09/2017		
Date Inspected: 08/10/2017	Inspected At:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4 Singapore 408610
Estimated Period of Repair: 6.0 days		

Adjuster: MOHD RASUL

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Dec 2017)
Parts:	M1-SUV	HONDA ODYSSEY 2.4 EXV-S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS1857H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACERR.BUMPER	Serviceable	417.90 FS	*- FS
2	1		*4PCS ACT RR.SENSOR	Serviceable	320.00 FS	*- FS
3	1		*BUZZER ASSYSMART	Serviceable	44.17 FS	*- FS
4	7		*CLIPBUMPER	Not Necessary	10.50 FS	*- FS
5	1		*SPACERR.RR.BUMPER SIDE	Not Necessary	14.02 FS	*- FS
6	1		*SPACERL.RR.BUMPER SIDE	Not Necessary	14.02 FS	*- FS
7	1		*PANEL COMPRR	Serviceable	338.85 FS	*- FS
8	1		*TAILGATE COMP	Bent	787.35 FS	*787.35 FS
9	1		*EMBLEMH	Necessary	19.35 FS	*19.35 FS
10	2		*PROTECTORLICENSE PLATE	Serviceable	3.00 FS	*- FS
11	1		*LINING ASSYRR.PANEL	Serviceable	76.20 FS	*- FS
12	1		*LOCKTAILGATE	Serviceable	136.27 FS	*- FS
13	1		*GLASS SET,RR.WINDSHIELD	Serviceable	743.47 FS	*- FS
14	2		*MOLDINGRR.WINDSHIELD SIDE	Necessary	35.20 FS	*26.40 FS
15	1		*MOLDINGL.RR.WINDSHIELD CORNER	Necessary	16.60 FS	*12.45 FS
16	1		*MOLDINGR.RR.WINDSHIELD CORNER	Necessary	16.60 FS	*12.45 FS
17	1		*SPACERR.W/SHIELD (4 PCS)	Necessary	15.60 FS	*11.70 FS
18	1		*RUBBER A/WINDSHIELD DAM	Necessary	3.60 FS	*2.70 FS
19	1		*DAMPERSTD 5X5 (2 PCS)	Necessary	16.60 FS	*12.45 FS
20	1		*CAPPIVOT	Necessary	4.70 FS	*3.52 FS
21	2		*WINDSCREEN SEALANT (N)	Necessary	120.00 FS	*120.00 FS
22	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
23	1		*LINING ASSYTAILGATE LOWER	Serviceable	151.65 FS	*- FS
					Total Parts (\$\$)	3,355.65 1,038.37

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE RR. WINDSCREEN (N)	New	300.00	280.00
2	WINDSCREEN DAM KIT	New	80.00	80.00
3	REMOVE & RENEW REVERSE SENSOR - 4 PCS (N)	New	180.00	0.00
4	BODY JOINT SEALANT FOR END PANEL (N)	New	80.00	80.00
5	BODY JOINT SEALANT FOR TAILGATE (N)	New	80.00	0.00
6	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	New	650.00	560.00
7	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	650.00	0.00
8	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	New	160.00	140.00
9	STRAIGHTEN ALIGN & PULL BACK EXHAUST SYSTEM (N)	New	180.00	0.00
10	REMOVE & INSTALL REAR-VIEW CAMERA (N)	New	140.00	140.00
11	RESET & CALIBRATE VEHICLE SMART ENTRY SYSTEM (N)140	New	140.00	140.00
12	REMOVE & TRANSFER TAILGATE SPOILER	New	140.00	120.00
13	CUT OFF & RENEW RR PANEL. STRAIGHTEN	New	4,000.00	1,680.00
14	SPRAY PAINTING ON REPAIRED ON REPLACE AREAS. (5P)	New	3,000.00	900.00
Gross Labour Cost (S\$)			9,780.00	4,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >