

ASS. REC. BY:

RETC33/LPC17018510/Grb

Special Instruction:

Subject: Guo Qiang

ASSIGNMENT (Office)

From (Person): Eric

of Longpac Insurance

Date/Time: 27/9/2017

Estimated Cost:

Kill to

OD (TP) / WS / TP RES / OD RES / EVA / ENV / MV / CS

To Inspect Vehicle No: FBD 2507 Y

Insured:

at Workshop m/s Speedy Motor

Tel: 64815567

of #05-21 BIK 10 Ang Mo Kio Industrial Park 2A SC (56847)

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

CA / REV / REP. / REV 24 HRS WP

Anytime today 27/9

H.O.D. Endorsement:

Date/Time: 27/9/2017

Person Contacted: Miss Tan

Vehicle: IN/OUT

Date/Time

Action/Instruction ( X ) Estimate

SLS 4879Z - CS/LPC17016825/Kvb - 20/8/2017

Submit LIS \$7900, 7 days

Red: \$600, 7%.





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC17018510/Grb

300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 27-09-2017



Code : LPC2

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLQ 4879Z	Veh. Inspected	FBD 2507Y
Policy No.		Coverage (\$)	0.00
Claim No.	17/17/17VP00/020060	Excess (\$)	0.00
Assign From	ERIC WOO	Assign Date	27/09/2017

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	20/08/2016	Inspection Date	27/09/2017
Survey held at	SPEEDY		
Repairer	SPEEDY MOTOR CYCLE SERVICE CENTRE		

## 5a. Remarks

<p>A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.          B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.          THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.          C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.</p>
---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

**Catherine Chong (LKK Auto)**

---

**From:** ERIC WOO JUN KIAT <ericwoo@lonpac.com>  
**Sent:** Wednesday, 27 September, 2017 9:41 AM  
**To:** assignments@lkkauto.com  
**Cc:** MT\_Claim\_SG  
**Subject:** Our Ref: 17/17/17/VP00/020060 Accident involving SLQ4879Z & FBD2507Y  
along Boon Lay Way on 20/8/17  
**Attachments:** 27092017093807.pdf

Dear Catherine,

Kindly refer to our attachment.

Please proceed to conduct a survey of the vehicle FBD 2507Y on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,  
Eric Woo  
Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/09/2017 13:37
Date Of Accident	20/08/2017 17:00
Exact Location Of Accident	JURONG EAST CENTRAL
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBD2507Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SHARVIN S/O BHASKARAN
NRIC No	S9336840A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98184307
Alternative Phone No	OTHERS-98184307

### Vehicle Particulars

Manufacturer	HONDA
Model	CB400
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	MSD/VMT/17-361449
Cover Note Number	

### Driver

Name of Driver	SHARVIN S/O BHASKARAN
NRIC No	S9336840A
Date Of Birth	28/09/1993
Occupation	INDOOR
Date Of Driving Pass	27/10/2015
Driving Experience	1 YEAR AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98184307
Fax Number	
Contact Number	OTHERS-98184307
EMail Address	NOEMAIL

Address , BLK 529 JURONG WEST ST 52 #10-369  
 Postcode 640529  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident SIDE SWIPE  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? YES  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes,Please state which Police Station  
 Police Station Name TRAFFIC POLICE DIVISION HQ  
 Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 65470000 - FAX NO:  
 Was notice of intended Prosecution given? NO  
 If Yes,against whom?

**Circumstances of Accident**

AS PER POLICE REPORT No.T/20170825/7024. ATTENDED BY SITI

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLQ4879Z  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

**Details of Witness**

Name  
 Phone Number

Email Address

**DETAILS OF INJURED PERSON 1**

Name	SHARVIN S/O BHASKARAN
Approximate Age	23
Injuries Sustain	
Injured person in which vehicle?	FBD2507Y
Were seat belts worn?	NO
Was injured conveyed to hospital by ambulance?	YES
Address	BLK 529 JURONG WEST ST 52 #10-369
Postcode	640529

Text size + -

**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 6840A

**Vehicle Details**

Vehicle No.: FBD2507Y

Vehicle to be Exported: No

Intended De-registration Date: 28 Sep 2017

Vehicle Make: HONDA

Vehicle Model: CB400SFVT

Primary Colour: Black

Manufacturing Year: 1999

Engine No.: NC23E2004419

Chassis No.: NC391004410

Maximum Power Output: -

Open Market Value: \$8,396.00

Original Registration Date: 20 Oct 1999

First Registration Date: 20 Oct 1999

Transfer Count: 10

Actual ARF Paid: \$1,260.00

**Intended PARF Rebate Details**

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Expiry Date: 30 Sep 2019

COE Category: D - Motorcycle

COE Period(Years): 10

PQP Paid: \$894.00

COE Rebate Amount: \$179.00

**Total Rebate Amount: \$179.00**

The information contained herein is correct as at 28 Sep 2017



Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Last updated on 17 Sep 2017 at 12:38 AM

## Catherine Chong (LKK Auto)

---

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Thursday, 1 February, 2018 4:57 PM  
**To:** Catherine Chong (LKK Auto); assignments@lkkauto.com  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: Our Ref: 17/17/17/VP00/020060 Accident involving SLQ4879Z & FBD2507Y along Boon Lay Way on 20/8/17  
**Attachments:** 20060 TP SR.pdf; 20060 TP PHOTOA.pdf; 20060 TP PHOTOB.pdf

Hi Catherine

Attached is the TP survey report with photographs.

Please let us have your surveyor's comment.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

---

**From:** Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]  
**Sent:** Wednesday, 27 September, 2017 10:32 AM  
**To:** ERIC WOO JUN KIAT; assignments@lkkauto.com  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: Our Ref: 17/17/17/VP00/020060 Accident involving SLQ4879Z & FBD2507Y along Boon Lay Way on 20/8/17

Dear Eric,

Thank you for the assignment.

Best Regards,

**Celine Fong**

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** ERIC WOO JUN KIAT [mailto:ericwoo@lonpac.com]  
**Sent:** Wednesday, 27 September, 2017 9:41 AM  
**To:** [assignments@lkkauto.com](mailto:assignments@lkkauto.com)  
**Cc:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>  
**Subject:** Our Ref: 17/17/17/VP00/020060 Accident involving SLQ4879Z & FBD2507Y along Boon Lay Way on 20/8/17

Dear Catherine,

Kindly refer to our attachment.

Please proceed to conduct a survey of the vehicle FBD 2507Y on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

Loss Adjuster, Consulting Automotive Engineer, Accident Reconstruction &amp; Analyst.

**VEHICLE APPRAISAL REPORT**

Mr Sharvin  
S/o Bhaskaran  
Apt Blk 529  
Jurong West Street 52 # 10-369  
Singapore- 640529

Our Ref : TP/1709/FBD2507/ws  
Date : 29 November 2017

**REFERENCE PARTICULARS**

Your Reference No : Not Advised  
Date of Accident : 20 Aug 2017

Date of Assignment : 26 Sept 2017  
Date of Inspection : 26 Sept 2017  
Date of Re-inspn. : 28 Sept & 24 Oct 2017

**PARTICULARS OF VEHICLE**

Regn. No : FBD 2507Y  
Make : HONDA  
Model : CB400SFVT  
Year : 1999 (COE.Exp : Sep 2019)

Odometer : Meter Damage  
Color : Black  
Chassis No. : NC391004410  
Engine No : NC23E2004419

**TYRE / CONDITION**

<u>Location</u>	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front	Metzeler	160/60-17	4 mm
Rear	Metzeler	160/60-17	4 mm

**DAMAGE PROFILE**

The motor cycle sustained damage on all sides

Please refer to photographs and assessment of repairs for details.

**ASSESSMENT SUMMARY**

Repair cost to the vehicle is assessed as \$ **8,500.00 lump sum.**

Survey conducted at: Speedy Motor Cycle Service Centre.

Enclosed (52) photographs depicting damage to the vehicle.

Estimated time required for repairs: (10) days.

The survey was conducted on a **WITHOUT PREJUDICE BASIS.**

ASSESSMENT FOR REPAIR : FBD 2507 Y

<u>Qty</u>	<u>Description</u>	<u>Condition</u>	<u>Repairer's Estimate</u>	<u>Our Assessment</u>
1 pc	Handle bar (RENTHAL)	Bent	240.00	240.00
1 set	Handle balancer	Cut	50.00	50.00
1 set	Handle grip	Cut	52.00	52.00
1 pc	Clutch lever	Bent/cut	32.00	32.00
1 pc	Clutch lever holder	Cut/crack	62.00	62.00
1 pc	Brake lever	Bent	43.00	43.00
1 set	Throttle cable	Usable <i>NN</i>	62.00	~
2 pcs	Mirror assy @\$65.00	Bent/cut	130.00	130.00
1 pc	Meter assy	Broken	1120.00	1120.00
1 pc	Head lamp assy	Cracked	265.00	265.00
1 set	Headlamp body	Dented	165.00	165.00
1 set	Head lamp bracket/holder	Bent	56.00	56.00
2 pcs	Front signal @\$75.00	LH broken	150.00	75.00
1 pc	Front mudguard	Cracked	255.00	255.00
2 pcs	Front fork assy @ \$680/-	Repair <i>BT</i>	1360.00	S.N. 300.00
1 pc	Fork under bracket	Distorted	255.00	255.00
1 pc	Front rim	Warped/cut	780.00	780.00
2 pcs	Front brake disc @\$420	Warped LH	840.00	<del>840.00</del> <i>420</i>
1 pc	Horn	Dented	32.00	32.00
1 pc	Radiator	Dented	625.00	625.00
1 set	Radiator guard	Cut/deformed	128.00	128.00
1 pc	Fuel tank	Badly dented	985.00	985.00
1 pc	Engine cover RH	Cracked	285.00	285.00
1 pc	Cam cover	Cut	655.00	655.00
1 pc	Engine block	Cut/repair <i>Cwt</i>	995.00	S.N. 250.00
2 pcs	Front footrest @\$75	Bent	150.00	150.00
2 pcs	Front footrest bracket @\$195	Bent	390.00	390.00
1 pc	Brake pedal	Bent	68.00	68.00
1 pc	Gear pedal	Usable <i>NN</i>	55.00	~
2 pcs	Rear signal <del>LN</del> @\$48	Cut LH <i>NN-RH</i>	90.00	45.00
1 pc	Tail board assy	Cut/deformed	520.00	520.00
1 pc	Tail lamp	Dislodged	435.00	435.00
1 pc	Rear mudguard	Dislodged	185.00	185.00
2 pcs	Rear signal lamp assy @\$75	Dislodged	150.00	150.00
1 set	Exhaust header	Repair <i>Cwt</i>	895.00	S.N. 100.00
1 pc	Exhaust muffler	Dented	980.00	980.00
			<u>13540.00</u>	<u>10053.00</u>
	Less 10%		1354.00	1005.30
			<u>12186.00</u>	<u>9047.70</u>
	Add special nett from above			650.00
1 pc	Front number plate	Bent	12.00	12.00
1 set	Steering cone & bearing	Necessary	120.00	60.00
1 set	Engine OH gasket	Necessary	256.00	256.00
1 set	Exhaust gasket	Necessary	46.00	46.00
4 ltr	Engine oil	Necessary	80.00	40.00

*9633*  
*8669.7*

Our Ref.: TP/1709/FBD2507/ws

1 pc	ERP IU	Cut	160.00	160.00	
2 set	Engine guard @\$150	Bent cut	300.00	300.00	
	Towing fee		60.00	50.00	40
	Chassis frame repair		300.00	<del>250.00</del>	X NN
	Labour charge		600.00	<del>500.00</del>	300
			<u>14120.00</u>	<u>11371.70</u>	
	Lump sum repair adjustment			<u>8500.00</u>	

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle. We have listed the breakdown of our findings and our recommendation as per assessment above.

Inspected by

Bok Jee Tan



Faithfully Yours  
L H TEO Appraisal Services

Teo Liak Hoo  
Advance Automotive Engineer (UK)  
Dip. Mech. Engr. M Prof BTM(Dip.BTM)  
MPE, MIMI, AMSIM an



10533.7  
25%: 7900



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CS3/LPC17018510/Grbe2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 20-03-2018	
		Code : LPC2	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SLQ 4879Z	Veh. Inspected	FBD 2507Y
Policy No.		Coverage (\$)	0.00
Claim No.	17/17/17VP00/020060	Excess (\$)	0.00
Assign From	ERIC WOO	Assign Date	27/09/2017
2. Vehicle Particulars & Condition			
Make & Model	HONDA CB400	c.c	399
Engine No.	HIDDEN	Year of Reg.	1999
Chassis No.	NC391004410	Colour	BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	120/70 ZR17	METZELER	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	160/60 ZR17	METZELER	5 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORTION, N/S AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	20/08/2017	Inspection Date	27/09/2017
Survey held at	SPEEDY MOTOR CYCLE SERVICE CENTRE BLK 10 ANG MO KIO IND. PARK 2A #05-21 SINGAPORE 568047		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBD 2507Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	HANDLE BAR (RENTHAL)	BENT	240.00	240.00
1	SET HANDLE BALANCER	CUT	50.00	50.00
1	SET HANDLE GRIP	CUT	52.00	52.00
1	CLUTCH LEVER	BENT / CUT	32.00	32.00
1	CLUTCH LEVER HOLDER	CUT / CRACKED	62.00	62.00
1	BRAKE LEVER	BENT	43.00	43.00
1	SET THROTTLE CABLE	NOT NECESSARY	62.00	-
2	MIRROR ASSY @\$65.00	BENT / CUT	130.00	130.00
1	METER ASSY	BROKEN	1,120.00	1,120.00
1	HEAD LAMP ASSY	CRACKED	265.00	265.00
1	SET HEADLAMP BODY	DENTED	165.00	165.00
1	SET HEAD LAMP BRACKET/HOLDER	BENT	56.00	56.00
2	FRONT SIGNAL @\$75.00	N/S BROKEN	150.00	75.00
1	FRONT MUDGUARD	CRACKED	255.00	255.00
1	FORK UNDER BRACKET	DISTORTED	255.00	255.00
1	FRONT RIM	WARPED / CUT	780.00	780.00
2	FRONT BRAKE DISC @\$420.00	N/S WARPED	840.00	420.00
1	HORN	DENTED	32.00	32.00
1	RADIATOR	DENTED	625.00	625.00
1	SET RADIATOR GUARD	CUT / DEFORMED	128.00	128.00
1	FUEL TANK	BADLY DENTED	985.00	985.00
1	ENGINE COVER RH	CRACKED	285.00	285.00
1	CAM COVER	CUT	655.00	655.00
2	FRONT FOOTREST @\$75.00	BENT	150.00	150.00
2	FRONT FOOTREST BRACKET @\$195.00	BENT	390.00	390.00
1	BRAKE PEDAL	BENT	68.00	68.00
1	GEAR PEDAL	NOT NECESSARY	55.00	-
2	REAR SIGNAL @\$48.00	N/S CUT / O/S NOT NECESSARY	90.00	45.00
1	TAIL BOARD ASSY	CUT / DEFORMED	520.00	520.00
1	TAIL LAMP	DISLODGE	435.00	435.00

Report Ref No. CS3/LPC17018510/Grbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR MUDGUARD	DISLODGE	185.00	185.00
2	REAR SIGNAL LAMP ASSY @\$75.00	DISLODGE	150.00	150.00
1	EXHAUST MUFFLER	DENTED	980.00	980.00
	LESS 10% DISCOUNT		-1,029.00	-963.30
			9,261.00	8,669.70
2	FRONT FORK ASSY @\$680.00 (LOCAL REPAIR)(SN)	BENT	1,360.00	300.00
1	ENGINE BLOCK (SN)	CUT	995.00	250.00
1	SET EXHAUST HEADER (SN)	CUT	895.00	100.00
	LESS 10% DISCOUNT		-325.00	-
			2,925.00	650.00
	<b>SPECIAL NETT ITEMS</b>			
1	FRONT NUMBER PLATE (SN)	BENT	12.00	12.00
1	SET STEERING CONE & BEARING (SN)	NECESSARY	120.00	60.00
1	SET ENGINE OH GASKET (SN)	NECESSARY	256.00	256.00
1	SET EXHAUST GASKET (SN)	NECESSARY	46.00	46.00
4	ENGINE OIL (SN)	NECESSARY	80.00	40.00
1	ERP IU (SN)	CUT	160.00	160.00
2	SET ENGINE GUARD @\$150.00 (SN)	BENT	300.00	300.00
			974.00	874.00
	<b>LABOUR</b>			
	TOWING FEE.		60.00	40.00
	CHASSIS FRAME REPAIR.	NOT NECESSARY	300.00	-
	LABOUR CHARGE.		600.00	300.00
			960.00	340.00
	<b>GRAND TOTAL</b>		<b>14,120.00</b>	<b>10,533.70</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>7,900.00</b>
-----------------------------------------------------------------------------	--	--	-----------------

Report Ref No. CS3/LPC17018510/Grbe2

MARKET VALUE: \$4,500.00 (EST)-LTA REIMBURSEMENT VALUE: \$179.00=NETT VALUE: \$4,321.00

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.