

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref: CC4/ASM17018578/M1ps3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KWEE MAY			Date: 17-04-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SGA 9687X	Veh. Inspected	SJJ 9336B	
	Policy No.	P1124483	Coverage (\$)	0.00	
	Claim No.	S7M0026D	Excess (\$)	0.00	
	Assign From		Assign Date	27/09/2017	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA CAMRY 2.0	c.c	1998	
	Engine No.	HIDDEN	Year of Reg.	200	
	Chassis No.	MR053BK4107033241	Colour	BLACK	
	Odometer	237729	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	215/60 R16	DUNLOP	8 mm	
	L/H Front Tyre	215/60 R16	DUNLOP	8 mm	
	R/H Rear Tyre	215/60 R16	DUNLOP	8 mm	
	L/H Rear Tyre	215/60 R16	DUNLOP	8 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	22/09/2017	Inspection Date	28/09/2017	
	Survey held at	ACCORD AUTO SERVICES PTE LTD			
		10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days				