

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AXA Insurance Singapore Pte Ltd
8 Shenton Way,
#27-01/02 AXA Tower
Singapore 068811
Attn: Motor Claims Department

Date : 26/09/2017
Vehicle No : SJJ9336B
Veh Make/Model : Toyota Camry 2.0 Auto
YOM : 2008
Chassis No : MR053BK4107033241
Date of Accident : 22/09/2017

No	Qty	Description	Amount \$
		<u>List Items:-</u>	
1	1	Front bumper <i>def</i>	\$ 597.60 -
2	10	Front bumper clip <i>rec. ✓</i>	\$ 57.00 -
3	1	Front bumper side retainer - RH <i>dis.</i>	\$ 59.89 -
4	1	Front RH fender assy <i>def. ✓</i>	\$ 682.80
5	1	Front RH fender splash shield <i>def. ✓</i>	\$ 136.40
6	8	Front RH fender splash shield clip <i>rec. ✓</i>	\$ 56.00
7	1	Front RH fender inner bracket <i>R. X</i>	\$ 131.20
8	1	Front RH fender inner sponge <i>rec. X</i>	\$ 121.10
9	1	Front RH fender "VVTI" emblem <i>rec. ✓</i>	\$ 41.00
10	1	Front RH door assy <i>X</i>	\$ 1,245.00
11	2	Front RH door hinge <i>X</i>	\$ 161.40
12	1	Front RH door checker <i>X</i>	\$ 161.20
13	1	Front RH door chrome (top) <i>X</i>	\$ 181.80
14	6	Front RH door chrome clip <i>X</i>	\$ 77.40
15	1	Front RH door protector <i>✓</i>	\$ 131.10
16	4	Front RH door protector clip <i>✓</i>	\$ 28.00
17	1	Front RH door protector chrome <i>✓</i>	\$ 83.10
18	1	Front RH door pillar garnish <i>X</i>	\$ 41.00
19	1	Front RH door glass outer moulding (lower) <i>X</i>	\$ 172.20
20	1	Rear RH door assy <i>X</i>	\$ 1,151.80
21	1	Rear RH door protector <i>X</i>	\$ 131.20
22	4	Rear RH door protector clip <i>X</i>	\$ 28.00
23	1	Rear RH door chrome <i>X</i>	\$ 83.10
24	1	Rear RH door chrome (top) <i>X</i>	\$ 186.10
25	6	Rear RH door chrome clip <i>X</i>	\$ 77.40
26	1	Rear RH door pillar garnish <i>X</i>	\$ 41.00
27	1	Rear RH door outer glass moulding (lower) <i>X</i>	\$ 171.10
28	1	Rear RH fender assy <i>X</i>	\$ 971.80
29	1	Rear RH fender splash shield <i>X</i>	\$ 136.40
30	8	Rear RH fender splash shield clip <i>X</i>	\$ 56.00
Total - List Item			\$ 6,484.60
Less 25%			\$ 1,621.15
Total			\$ 4,863.45

1856.89
464.22
1392.67

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AXA Insurance Singapore Pte Ltd
8 Shenton Way,
#27-01/02 AXA Tower
Singapore 068811
Attn: Motor Claims Department

Date : 26/09/2017
Vehicle No : SJJ9336B
Veh Make/Model : Toyota Camry 2.0 Auto
YOM : 2008
Chassis No : MR053BK4107033241
Date of Accident : 22/09/2017

No	Qty	Description	Amount \$
		Balance c/f	\$ 4,863.45
		<u>Special Nett Items:-</u>	
1		Front RH door glass solar film <i>N/A</i>	\$ 180.00 X
2		Rear RH door glass solar film <i>N/A</i>	\$ 180.00 X
3		Rear RH door quarter glass solar film <i>N/A</i>	\$ 80.00 X
		Total - SN Item	\$ 440.00
		<u>Labour Charges:-</u>	
1		Spray painting on all affected area.	\$ 1,500.00 900
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ 1,500.00 1200
3		To apply anti rust treatment.	\$ 180.00 80
4		To check door wiring.	\$ 100.00 X
5		To remove and refix interior upholstery.	\$ 120.00 X
6		To transfer front RH door mechanism.	\$ 100.00 X
7		To transfer rear RH door mechanism.	\$ 100.00 X
		Total - L/C	\$ 3,600.00 2180.00
		<i>Not Authorised</i>	
		<i>H/S Repair</i>	
		<i>After repair photo</i>	
		<i>Acc Auto (M.R.)</i>	
		<i>2nd day \$</i>	list 1392.67
		<i>28/9/2017</i>	1/C 2180.00
			3572.67
		-20%	714.53
			2858.14
		Sub-Total	\$ 8,903.45
		7% GST	\$ 623.24
		Total	\$ 9,526.69