

- 5 CHECK REAR WHEEL ALIGNMENT
- 6 REMOVE AND RENEW REAR UNDERCARRIAGE PARTS
- 7 TRANSFER PARTS ATTACHMENT FROM REAR OLD DOOR TO NEW
- 8 PANEL BEATING ON AFFECTED AREAS
- 9 SPRAY PAINTING ON AFFECTED AREAS
- 10 APPLY ANTI RUST ON AFFECTED AREAS

2310/-

150.00 60/-  
 200.00 180/-  
 200.00 60/-  
 1200.00 1000/-  
 1000.00 800/-  
 150.00 40/-

Subtotal

3460.00

Grand total

12908.03

28/09/2017 @ 1100w

Hot Antirust

2/3mm

5 dgs

LKK Auto

7685.89

4/5 6100/-

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Check  
Part  
Prices.