

ASS. REC. BY:

REF:

CS/MSG 17018640 /Dgb⁷²

Special Instructions:

Surveyor
Merrin

Bryan

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSG

Date/Time:

28/09/17 @ 9.58am

Estimated Cost:

Bill to:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 42J

Insured:

SGT 727 Z

at Workshop m/s

Teamwork Garage

Tel:

6844 2475

of

53 ubi Ave | #01-24, 408934

Policy No:

28853835 QMX

Claim No:

531026

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A:

24/09/17

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

28/9/17 1038am

Person Contacted:

Christina

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLJ 42J - NA / MSG 17018518 / 24 - D.O.A: 24/09/17

SGT 727 Z - NA / MSG 17018518 / 24 - D.O.A: 24/09/17

19/10/17 @ 1.19pm revised to Christina Wong via Merrin.

108/11/13

REF:

Surrey

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SL3425

Yr Regn:

2017, July

Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Wish

C.C:

1798

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

13155

T/Radio: Insured / Std / NI / NA

Eng/No:

22R1860508

C/No:

JTDGG20W005006093

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Goodyear

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

24/09/2017

D.O.A.

28/09/2017

Survey held at

Teamwork Page 451

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Body 4 N/S RW

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/12/17 MSIG 8GT 727Z
Jmgn 4/5 61001- with 5 days. 8/12
Ched 4 6808.03, 53%.

RECEIVED 12 DEC 2017

Date/Time, File Pass to?



: Preli. Report

1) 12/12/17



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

300

10

310

Report Format :

MERTP

Lump Sum / I.B.I. (\$

6100



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17018640/Dqb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 28-09-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGT 727Z	Veh. Inspected	SLJ 42J
Policy No.	28853835QMX	Coverage (\$)	0.00
Claim No.	531026	Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	28/09/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	24/09/2017	Inspection Date	28/09/2017
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Reference No. : C/MSK/7018640/D96
Policy Type: OD / TP / TP RES / TL / EVA

SLJ 42J

Typist

(1) Office Assign Form

C	Reference No.		
C	Customer Code		
N	Assign From		
C	Assign Date		
C	Veh No (Inspected)		
C	Veh No (Insured)		
C	D.O.A		
C	Policy No		
C	Claim No		
C	Insurance Authorisation (CA /REV/REP)		
C	Report Type		
C	Weekend Charges		
N	Survey held at/Repairer		
C	Excess		

(1) Assignment Form

C	Vehicle No		
C	Regn Month/Year		
N	Vehicle Type		
N	Make & Model		
C	Engine Capacity. (C.C)		
N	Colour		
C	Odometer. (Sp.Reading)		
C	Chassis No		
N	General Condition		
N	Steering		
N	Brake		
N	Modification (Modi)		
C	Tyre Size		
N	Tyre Make		
C	Tyre Balance		
C	Date of Inspection		
N	Survey held		
N	Des.of Damages		

C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

N	ALL Parts condition
C	Market Value for OD cases
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)
C	Days of repair
C	Finalised Amount
C	Re-inspection Cases to Finalize within 5 Days

✓	
✓	
✓	

C Resurvey photo Uploaded

Case Handler

Date _____

21/05/2014

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Sep 2017		28 Sep 2017 09:58 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	HAMZAH BIN ABDUL KARIM, ID: S1284649E		
Main Claimant:	EHB LIMOUSINE PTE LTD, Co. Reg. No.: 201536531R		
Vehicle Reg. No.:	SLJ42J	Date of Loss:	24/09/2017 08:00 - :59
Claim Type:	TP / 531026	Policy/Cover Note No.:	28853835QMX (Comprehensive) Coverage: 18/11/2016 - 17/11/2017
Vehicle Reg. No. (Insured):	SGT727Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/09/2017]		
Driver/Custodian (Insured):	MOHAMMAD ISKANDAR BIN HAMZAH (), NRIC: S8601641I, Tel: +6597128907		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 19 Oct 2017

Preliminary Advice

Insured Vehicle No	: SGT727Z	Accident Date	: 24/09/2017
TP Vehicle No	: SLJ42J	Assignment Date	: 28/09/2017
Make	: TOYOTA WISH	Est. Duration of Repair	: 5.00
Date of Inspection	: 28/09/2017		
Inspection At	: TEAMWORK GARAGE PTE LTD (HQ) 53 UBI AVE 1 #01-24, PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body & n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,908.03
Revised Amount	:S\$	8,803.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,803.80

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	6531R
Vehicle Details	
Vehicle No.	SLJ42J
Vehicle to be Exported	No
Intended De-registration Date	19 Oct 2017
Vehicle Make	TOYOTA
Vehicle Model	WISH 1.8 CVT
Primary Colour	Black
Manufacturing Year	2016
Engine No.	2ZR1860508
Chassis No.	JTDGG20W00J006093
Maximum Power Output	105.0 kW (140 bhp)
Open Market Value	\$19,955.00
Original Registration Date	19 Jul 2017
First Registration Date	19 Jul 2017
Transfer Count	0
Actual ARF Paid	\$19,955.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	18 Jul 2027
PARF Rebate Amount	\$14,966.00
Intended COE Rebate Details	
COE Expiry Date	18 Jul 2027
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$50,110.00
COE Rebate Amount	\$48,835.00
Total Rebate Amount	\$63,801.00

The information contained herein is correct as at 19 Oct 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/09/2017 14:21
Date Of Accident	24/09/2017 09:30
Exact Location Of Accident	MARINA BLVD TWDS SHEARES AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ42J
Insured/Policyholder	
Name Of Registered Owner	EHB LIMOUSINE PTE LTD
Co Reg No	201536531R
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97757275
Alternative Phone No	OFFICE-96490220

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH 1.8 CVT
Exact Purpose for which vehicle was being used at time of accident	WORK

Are you claiming under your own insurance policy for repair to your vehicle?	NO
--	----

If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5075309111-01
Cover Note Number	

Driver

Name of Driver	MOHAMED FARRIS BIN MOHAMED ZAINUDDIN
NRIC No	S7442116D
Date Of Birth	12/12/1974
Occupation	OUTDOOR
Date Of Driving Pass	03/11/1994
Driving Experience	22 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97757275
Fax Number	
Contact Number	OTHERS-96490220
Email Address	NOEMAIL

Address	BLK 638 HOUGANG AVENUE 8 #03-101
Postcode	530638
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	REVERT
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGT727Z
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF INJURED PERSON 1

Name	MOHAMED FARRIS BIN MOHAMED ZAINUDDIN
Approximate Age	
Injuries Sustain	NECK / BACK PAIN
Injured person in which vehicle?	SLJ42J
Were seat belts worn?	YES
Was injured conveyed to hospital by ambulance?	
Address	
Postcode	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident in speed as the Disk is permanent.
2. This form will be submitted by the Policyholder or the Authorized Driver.
3. Info reported provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may affect the insurance companies to rescind the policy liability.
4. The issuance of assistance of this form by insurance companies is not an admission of liability/absence on the part of the insurance company.
5. Any false report will only be referred to the Police for investigation.
6. The report will be furnished by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the signing of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 - I understand, acknowledge, agree and ensure that:
 - (a) My insurer, my insurer and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating this accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/Pass No.:

Sketch Plan #2



My vehicle was travelling along the middle lane. At the point of time, traffic was green in my favor, therefore with my left signal light on; I proceed to make a left turn towards Sheares Ave. While I was in the process of making a left turn, vehicle B which was travelling on my left the 4th lane was also making a left turn. However, the driver of vehicle B makes a wide left turn, misjudge and cut into my lane resulted his car hit and graze onto the left side portion of my vehicle. I wish to state that I reported this accident late because the driver of vehicle B wanted to make a private settlement with me. However due to the damage of my vehicle, both parties agreed to proceed for insurance claims instead. I wish to state that my left rear rim also damage.

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/ID No.:

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way #21-01
SGX Centre 2
Singapore 068807

Vehicle number	:	SLJ42J
Make / Model	:	TOYOTA/WISH
Chassis number	:	JTDGG20W00J006093
Accident date	:	24 September 2017
Reference	:	1709-28

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER <i>cut</i>	665.10 868.40 ✓
2	REAR BUMPER RETAINER <i>SV2</i>	220.10 X
1	REAR LH FENDER <i>Revised</i>	971.10 1380.40 ✓
1	REAR LH FENDER INNER TRIM <i>mounting chrome NW</i>	690.30 X
1	REAR LH FENDER INNER SHIELD <i>NW</i>	171.30 X
1	REAR LH SILL GARNISH <i>chrome mounting 1 cut</i>	903.20 ✓
1	REAR LH DOOR PANEL <i>rayon</i>	1289.40 X
1	REAR LH DOOR CHROME MOULDING <i>cut</i>	219.34 ✓
1	REAR LH DOOR INNER TRIM <i>mounting chrome</i>	579.91 ✓
1	REAR LH DOOR LOCK ASSY <i>SV2</i>	781.20 X
1	REAR LH DOOR REGULATOR ASSY <i>SV2</i>	486.60 620.40 ✓
1	REAR AXLE BEAM <i>distorted</i>	2017.80 2531.62 ✓
1	REAR LH WHEEL HUB WITH BEARING <i>distorted</i>	484.80 715.13 ✓
		10970.70
	Less 25 %	2742.67
	Subtotal	8228.03
	Balance C/F	8228.03
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	8228.03
1 SET	REAR BUMPER CLIP <i>NW</i>	60.00 30/-
1 SET	REAR LH DOOR INNER TRIM CLIP <i>NW</i>	60.00 20/-
1	RIM <i>cut</i>	800.00 500/-
1	WINDSCREEN SEALNT <i>NW</i>	150.00 40/-
1	JOINT SEALANT <i>NW</i>	150.00 40/-
	Subtotal	1220.00
	Balance C/F	9448.03

Vehicle number : SLJ42J

Make Model : TOYOTA/WISH

Reference : 1709-28

Qty	Particulars	Unit Price - SGD \$
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	9448.03
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 NW
2	REMOVE AND REFIT LINING, TRIM AND GARNISH	200.00 80/-
3	REMOVE AND REFIT REAR REVERSE SENSOR	150.00 40/-
4	REMOVE AND REFIT REAR LH QUARTER GLASS	150.00 50/-

5	CHECK REAR WHEEL ALIGNMENT	150.00	60/-
6	REMOVE AND RENEW REAR UNDERCARRIAGE PARTS	200.00	180/-
7	TRANSFER PARTS ATTACHMENT FROM REAR OLD DOOR TO NEW	200.00	60/-
8	PANEL BEATING ON AFFECTED AREAS	1200.00	1000/-
9	SPRAY PAINTING ON AFFECTED AREAS	1000.00	800/-
10	APPLY ANTI RUST ON AFFECTED AREAS	150.00	40/-
		2310/-	
Subtotal		3460.00	
Grand total		12908.03	
		7685.89	
		4/5 6100/-	

28/09/2017 @ 1100hr

Hot Antinul

L/Smm

5 dgs

Lkk Auto



Check
Part
Prices.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17018640/DQBN2

Date: 13/12/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28853835QMX
Claimant Vehicle No :	SLJ42J	Insured Vehicle No :	SGT727Z
Date of Loss:	24/09/2017	Nature of Claim:	TP
		Claim No:	531026

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ42J	Engine No:	2ZR1860508
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Chassis No:	JTDGG20W00J006093
Reg. Date:	19/07/2017 (Man. Year: 2016)	Odometer:	13155 km
Colour:	Black		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,448.02	5,375.89	4,072.13	43.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,460.00	2,310.00	1,150.00	33.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,908.02	7,685.89	5,222.13	40.46
Approved Total (Overridden) (S\$)		6,100.00		
(S\$)	12,908.02	6,100.00	6,808.02	52.74
+ GST 7.00/7.00% (S\$)	903.56	427.00	476.56	52.74
Nett Amount (S\$)	13,811.58	6,527.00	7,284.58	52.74

INSPECTION

Date of Assignment:	28/09/2017	
Date Inspected:	28/09/2017 Inspected At:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Dec 2017)
Parts: M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLJ42J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	868.40 FL	*665.10 FL
2	2		*REAR BUMPER RETAINER	Serviceable	220.10 FL	*- FL
3	1		*REAR LH FENDER	Dented	1,380.40 FL	*971.10 FL
4	1		*REAR LH FENDER INNER TRIM	Not Necessary	690.30 FL	*- FL
5	1		*REAR LH FENDER INNER SHIELD	Not Necessary	171.30 FL	*- FL
6	1		*REAR LH SILL GARNISH	Mtg Cracked/Cut	903.20 FL	*903.20 FL
7	1		*REAR LH DOOR PANEL	Repair	1,289.40 FL	*- FL
8	1		*REAR LH DOOR CHROME MOULDING	Bent	219.34 FL	*219.34 FL
9	1		*REAR LH DOOR INNER TRIM	Mtg Cracked	579.91 FL	*579.91 FL
10	1		*REAR LH DOOR LOCK ASSY	Serviceable	781.20 FL	*- FL
11	1		*REAR LH DOOR REGULATOR ASSY	Bent	620.40 FL	*486.60 FL
12	1		*REAR AXLE BEAM	Distorted	2,531.62 FL	*2,017.80 FL
13	1		*REAR LH WHEEL HUB WITH BEARING	Distorted	715.13 FL	*484.80 FL
14	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
15	1		*SET REAR LH DOOR INNER TRIM CLIP	Necessary	60.00 FS	*20.00 FS
16	1		*RIM	Cut	800.00 FS	*500.00 FS
17	1		*WINDSCREEN SEALANT	Necessary	150.00 FS	*40.00 FS
18	1		*JOINT SEALANT	Necessary	150.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,190.70	6,957.85
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,742.68	1,581.96
Total Parts (\$\$)	9,448.02	5,375.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	60.00	-
2	REMOVE AND REFIT LINING, TRIM AND GARNISH	New	200.00	80.00
3	REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	40.00
4	REMOVE AND REFIT REAR LH QUARTER GLASS	New	150.00	50.00
5	CHECK REAR WHEEL ALIGNMENT	New	150.00	60.00
6	REMOVE AND RENEW REAR UNDERCARRIAGE PARTS	New	200.00	180.00
7	TRANSFER PARTS ATTACHMENT FROM REAR OLD DOOR TO NEW	New	200.00	60.00
8	PANEL BEATING ON AFFECTED AREAS	New	1,200.00	1,000.00
9	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	800.00
10	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	40.00
Gross Labour Cost (\$\$)			3,460.00	2,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >