

*Not Notarised*  
*11 Sep 8*

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHB 9532S -**

**AAD1709-261**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHB 9532S - CANDY**

KL1LA69RJBB122525

CHEVROLET

EPICA 2.0

23.09.2017

*China Taiping*

**PART**

**LIST**

|    |   |                                        |    |                       |   |
|----|---|----------------------------------------|----|-----------------------|---|
| 1  | 1 | Front Bumper                           | \$ | <i>Avulm</i> 1,202.00 | ✓ |
| 2  | 1 | Front Bumper Retainer RH               | \$ | <i>CM</i> 102.00      | ✓ |
| 3  | 1 | Front Bumper Retainer LH               | \$ | <i>Sm</i> 102.00      | X |
| 4  | 1 | Front Bumper Reinforcement             | \$ | <i>Ry</i> 295.25      | ✓ |
| 5  | 1 | Front Bumper Lower Absorber            | \$ | <i>CM</i> 180.00      | ✓ |
| 6  | 1 | Front Bumper Lower Stiffener           | \$ | <i>R</i> 134.37       | X |
| 7  | 1 | Front Bumper Lower Grille              | \$ | <i>Sm</i> 78.00       | X |
| 8  | 1 | Front Headlamp RH                      | \$ | <i>Bz</i> 816.00      | ✓ |
| 9  | 1 | Front Headlamp LH                      | \$ | <i>Sm</i> 816.00      | X |
| 10 | 1 | Front Bumper Fog Lamp Outer Cover LH   | \$ | <i>Sm</i> 32.40       | X |
| 11 | 1 | Front Bumper Fog Lamp Outer Cover RH   | \$ | <i>Sm</i> 32.40       | X |
| 12 | 1 | Front Support Panel Assy (Panel A-Frt) | \$ | <i>Bz</i> 1,222.32    | — |
| 13 | 1 | Bonnet (Panel A-Hood)                  | \$ | <i>Bz</i> 1,250.00    | ✓ |
| 14 | 1 | Centre 'CHEVROLET' Logo Badge          | \$ | <i>nm</i> 144.30      | ✓ |
| 15 | 1 | Bonnet Moulding                        | \$ | <i>nc</i> 257.00      | ✓ |
| 16 | 1 | Bonnet Insulator                       | \$ | <i>Sm</i> 84.63       | X |
| 17 | 1 | Bonnet hinge RH                        | \$ | <i>R</i> 36.00        | X |
| 18 | 1 | Bonnet hinge LH                        | \$ | <i>R</i> 36.00        | X |
| 19 | 1 | Bonnet cable                           | \$ | <i>Sm</i> 150.00      | X |
| 20 | 1 | Bonnet lock                            | \$ | <i>D,1</i> 200.00     | ✓ |
| 21 | 2 | HORN LH                                | \$ | <i>Sm</i> 320.00      | X |
| 22 | 1 | Radiator Grille ( Grille A-Rad )       | \$ | <i>CM</i> 367.00      | ✓ |
| 23 | 1 | Radiator Grille Top Cover              | \$ | <i>D,1</i> 45.02      | ✓ |
| 24 | 1 | Radiator Assembly ( Radiator A )       | \$ | <i>Hwt Bz</i> 618.00  | ✓ |
| 25 | 1 | Radiator upper hose                    | \$ | <i>Pu</i> 30.00       | ✓ |
| 26 | 1 | Radiator lower hose                    | \$ | 120.00                | ? |
| 27 | 1 | Radiator expansion tank                | \$ | <i>nc</i> 45.00       | ✓ |
| 28 | 1 | Aircon Condenser ( Condenser A )       | \$ | <i>Pu</i> 600.00      | ✓ |
| 29 | 1 | Aircon hose - condenser to compressor  | \$ | 215.40                | ? |
| 30 | 1 | Aircon hose - compressor to evaporator | \$ | 316.20                | ? |
| 31 | 1 | Aircon hose - condenser to evaporator  | \$ | 332.10                | ? |
| 32 | 1 | Aircon compressor - pump               | \$ | 1,847.95              | ? |

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**AAD1709-261****SHB 9532S -**

|    |   |                                               |    |     |          |     |
|----|---|-----------------------------------------------|----|-----|----------|-----|
| 33 | 1 | Aircon compressor bracket                     | \$ | R   | 245.30   | X   |
| 34 | 1 | Air Cleaner Assembly                          | \$ | Sn  | 112.00   | <   |
| 35 | 1 | Air Intercooler                               | \$ |     | 652.00   | ?   |
| 36 | 1 | Fan Blade (Small )                            | \$ | cm  | 536.00   | ✓   |
| 37 | 1 | Fan Blade ( Big )                             | \$ |     | 634.00   | ?   |
| 38 | 1 | Windscreen Washer Tank - Filler Neck          | \$ | nd  | 4.80     | ✓   |
| 39 | 1 | Windscreen Washer Tank (Reservoir A-W/Shield) | \$ |     | 62.00    | ?   |
| 40 | 1 | Windscreen Washer Tank Motor (Pump Wswa)      | \$ |     | 51.00    | ?   |
| 41 | 1 | TANK, WIPER HOSE                              | \$ |     | 21.00    | ?   |
| 42 | 1 | Power steering pump                           | \$ |     | 1,755.31 | ?   |
| 43 | 1 | Power steering reservoir tank                 | \$ |     | 120.00   | ?   |
| 44 | 1 | Power steering inlet / outlet pipe            | \$ |     | 65.00    | ?   |
| 45 | 1 | Power steering pump pulley                    | \$ |     | 66.00    | ?   |
| 46 | 1 | Power steering hose - pressure                | \$ |     | 256.00   | ?   |
| 47 | 1 | Power steering hose - non pressure            | \$ |     | 312.11   | ?   |
| 48 | 1 | Front Fender LH                               | \$ | R   | 837.60   | X   |
| 49 | 1 | Front Fender RH                               | \$ | Bu  | 837.60   | ✓   |
| 50 | 1 | Front Fender Liner LH                         | \$ | Sn  | 47.00    | X   |
| 51 | 1 | Front Fender Liner RH                         | \$ | DIT | 47.00    | ✓   |
| 52 | 1 | Front Door LH                                 | \$ | Bz  | 1,133.00 | ✓   |
| 53 | 1 | Front Door RH                                 | \$ | R   | 1,133.00 | X   |
| 54 | 1 | Front Door Hinge Upper RH                     | \$ | R   | 65.00    | } X |
| 55 | 1 | Front Door Hinge Lower RH                     | \$ | R   | 65.00    |     |
| 56 | 1 | Front Door Hinge Upper LH                     | \$ | R   | 65.00    |     |
| 57 | 1 | Front Door Hinge Lower LH                     | \$ | R   | 65.00    |     |
| 58 | 1 | Front Side View Mirror RH                     | \$ | Sn  | 939.00   | }   |
| 59 | 1 | Front Side View Mirror LH                     | \$ | Sn  | 939.00   |     |
| 60 | 1 | Front Windscreen                              | \$ | Sn  | 1,304.00 |     |
| 61 | 1 | Front Windscreen Moulding                     | \$ | Sn  | 196.00   | }   |
| 62 | 1 | Rear Bumper                                   | \$ | Tu  | 1,202.00 |     |
| 63 | 1 | Rear Bumper Beam                              | \$ | Bz  | 239.94   | ✓   |
| 64 | 1 | Rear Bumper Centre Absorber                   | \$ | cm  | 260.00   | ✓   |
| 65 | 1 | Rear Bumper Side Retainer RH                  | \$ | cm  | 68.76    | ✓   |
| 66 | 1 | Rear Bumper Side Retainer LH                  | \$ | cm  | 68.76    | ✓   |
| 67 | 1 | Rear Bumper Side Support RH                   | \$ | cm  | 25.00    | ✓   |
| 68 | 1 | Rear Bumper Side Support LH                   | \$ | cm  | 25.00    | ✓   |
| 69 | 1 | Rear Bumper Reflectors RH                     | \$ | Bz  | 119.74   | ✓   |
| 70 | 1 | Rear Bumper Reflectors LH                     | \$ | Bz  | 119.74   | ✓   |
| 71 | 1 | Rear Bumper Stay RH                           | \$ | Sn  | 35.00    | X   |
| 72 | 1 | Rear Bumper Stay LH                           | \$ | Sn  | 35.00    | X   |
| 73 | 1 | Rear Bumper Tow Hook Cover                    | \$ | mi  | 93.00    | ✓   |

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHB 9532S -****AAD1709-261**

|     |   |                                        |    |              |          |       |
|-----|---|----------------------------------------|----|--------------|----------|-------|
| 63  | 1 | Rear Luggage Floor Panel               | \$ | <i>Bz</i>    | 973.00   | —     |
| 64  | 1 | Rear Luggage Floor Panel Insulator     | \$ | <i>nc</i>    | 63.50    | —     |
| 65  | 1 | Rear Luggage Floor Panel Trim Board    | \$ |              | 378.00   | ?     |
| 66  | 1 | Rear End Panel Inner                   | \$ | <i>Bz</i>    | 336.84   | —     |
| 67  | 1 | Rear End Panel Outer                   | \$ | <i>Bz</i>    | 623.76   | —     |
| 68  | 1 | Rear End Panel Inner Trim              | \$ | <i>cm</i>    | 263.84   | —     |
| 69  | 1 | Bootlid                                | \$ | <i>Bz</i>    | 973.00   | —     |
| 70  | 1 | Bootlid inner trim board               | \$ | <i>sn</i>    | 400.00   | X     |
| 71  | 1 | Bootlid Weatherstrip                   | \$ | <i>cm</i>    | 344.28   | 508sn |
| 72  | 1 | Bootlid Lock - Top                     | \$ | <i>nd</i>    | 466.56   | —     |
| 73  | 1 | Bootlid lock - bottom                  | \$ | <i>n</i>     | 39.40    | X     |
| 74  | 1 | Bootlid 'CHEVROLET' Badge              | \$ | <i>nc</i>    | 120.62   | —     |
| 75  | 1 | Bootlid Logo                           | \$ | <i>nc</i>    | 138.84   | —     |
| 76  | 1 | Bootlid 'EPICA LT' Badge               | \$ | <i>nc</i>    | 119.84   | —     |
| 77  | 1 | Bootlid inner handle                   | \$ | <i>sn</i>    | 45.55    | X     |
| 78  | 1 | Bootlid Reflector Centre               | \$ | <i>cm</i>    | 217.97   | —     |
| 79  | 1 | Bootlid Reflector RH                   | \$ | <i>cm</i>    | 128.40   | —     |
| 80  | 1 | Bootlid Reflector LH                   | \$ | <i>cm</i>    | 128.40   | —     |
| 81  | 1 | Bootlid Hinge RH                       | \$ | <i>Bz</i>    | 120.00   | —     |
| 82  | 1 | Bootlid Hinge LH                       | \$ | <i>n</i>     | 120.00   | X     |
| 83  | 1 | Rear Gas T/Gate Spring RH              | \$ | <i>sn</i>    | 286.90   | X     |
| 84  | 1 | Rear Gas T/Gate Spring LH              | \$ | <i>sn</i>    | 286.90   | X     |
| 85  | 1 | Rear number plate lamp RH              | \$ | <i>sn</i>    | 25.00    | X     |
| 86  | 1 | Rear number plate lamp LH              | \$ | <i>sn</i>    | 25.00    | X     |
| 87  | 1 | Third brake light                      | \$ | <i>sn</i>    | 350.64   | X     |
| 88  | 1 | Rear Tail Lamp RH                      | \$ | <i>Bz</i>    | 479.30   | —     |
| 89  | 1 | Rear Tail Lamp Panel RH                | \$ | <i>Bz</i>    | 359.00   | —     |
| 90  | 1 | Rear Tail Lamp LH                      | \$ | <i>nc cm</i> | 479.30   | —     |
| 91  | 1 | Rear Tail Lamp Panel LH                | \$ | <i>nc</i>    | 359.00   | —     |
| 92  | 1 | Rear Exhaust Pipe                      | \$ | <i>n</i>     | 1,110.00 | X     |
| 93  | 1 | Rear Exhaust Box (Muffler A-EXH,RR)    | \$ | <i>n</i>     | 1,110.00 | X     |
| 94  | 1 | Centre Exhaust Pipe                    | \$ | <i>n</i>     | 403.00   | X     |
| 95  | 1 | Rear Fender RH                         | \$ | <i>Bz</i>    | 1,145.00 | —     |
| 96  | 1 | Rear Fender Inner Cowling RH           | \$ | <i>cm</i>    | 298.00   | —     |
| 97  | 1 | Rear Fender Inner Trim RH              | \$ | <i>nc cm</i> | 418.44   | —     |
| 98  | 1 | Rear Fender Inner Wheel House Panel LH | \$ | <i>n</i>     | 2,556.35 | X     |
| 99  | 1 | Rear Fender LH                         | \$ | <i>Bz</i>    | 1,145.00 | —     |
| 100 | 1 | Rear Fender Inner Cowling LH           | \$ | <i>cm</i>    | 298.00   | —     |
| 101 | 1 | Rear Fender Inner Trim LH              | \$ | <i>cm</i>    | 418.44   | —     |
| 102 | 1 | Rear Fender Inner Wheel House Panel RH | \$ |              | 2,556.35 | ?     |
| 103 | 1 | Rear Door LH (Panel A-RR DR RH)        | \$ | <i>n</i>     | 1,133.00 | X     |

**TRANS-CAB AUTO SERVICES PTE LTD****AAD1709-261**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHB 9532S -**

|     |   |                                                |    |          |   |
|-----|---|------------------------------------------------|----|----------|---|
| 103 | 1 | Rear Door RH (Panel A-RR DR LH)                | \$ | 1,133.00 | ✓ |
| 104 | 1 | Rear Door weatherstrip - Inner RH              | \$ | 41.40    | ✓ |
| 105 | 1 | Rear Door weatherstrip - 2nd Frame RH          | \$ | 25.90    | ✓ |
| 106 | 1 | Rear Door top hinge RH                         | \$ | 35.00    | ✓ |
| 107 | 1 | Rear Door bottom hinge RH                      | \$ | 35.00    | ✓ |
| 108 | 1 | Rear Door inner lock RH                        | \$ | 425.00   | ? |
| 109 | 1 | Rear Door check / arrestor RH                  | \$ | 65.00    | ✓ |
| 110 | 1 | Rear Door outer weatherstrip moulding RH       | \$ | 85.00    | ✓ |
| 111 | 1 | Rear Door outer handle RH                      | \$ | 60.00    | ✓ |
| 112 | 1 | Rear Door outer handle - rubber seal RH        | \$ | 25.00    | ✓ |
| 113 | 1 | Rear Door inner trim board RH                  | \$ | 455.69   | ✓ |
| 114 | 1 | Rear Door window glass channel weatherstrip    | \$ | 143.25   | ✓ |
| 115 | 1 | Rear Door window glass channel holder          | \$ | 205.60   | ✓ |
| 116 | 1 | Rear Door channel weatherstrip / felt          | \$ | 89.50    | ✓ |
| 117 | 1 | Rear Door power window motor (master)          | \$ | 274.97   | ✓ |
| 118 | 1 | Rear Windscreen Glass                          | \$ | 960.00   | ? |
| 119 | 1 | Rear Windscreen Glass With Mounding            | \$ | 1,647.00 | ? |
| 120 | 1 | Rear Windscreen Weatherstrip Seal              | \$ | 68.50    | ? |
| 121 | 1 | Rear windscreen inner garnish side RH          | \$ | 185.00   | ✓ |
| 122 | 1 | Rear windscreen inner garnish side LH          | \$ | 185.00   | ✓ |
| 123 | 1 | Rear windscreen inner top garnish              | \$ | 80.00    | ✓ |
| 124 | 1 | Tyre mechanical jack                           | \$ | 220.00   | ✓ |
| 125 | 1 | Tyre mechanical jack holder bracket            | \$ | 24.81    | ✓ |
| 126 | 1 | Rear shock absorber LH                         | \$ | 243.57   | ✓ |
| 127 | 1 | Rear shock absorber top mounting LH            | \$ | 51.65    | ✓ |
| 128 | 1 | Rear shock absorber RH                         | \$ | 243.57   | ? |
| 129 | 1 | Rear shock absorber top mounting RH            | \$ | 51.65    | ? |
| 130 | 1 | Upr Arm RH (Arm A-Upr RH)                      | \$ | 343.00   | ? |
| 131 | 1 | Upr Arm LH (Arm A-Upr LH)                      | \$ | 343.00   | ✓ |
| 132 | 1 | Rear Knuckle Arm LH                            | \$ | 350.00   | ✓ |
| 133 | 1 | Rear Knuckle Arm RH                            | \$ | 350.00   | ? |
| 134 | 1 | Rear Axle Housing (Axle A-RR)                  | \$ | 711.00   | ? |
| 135 | 1 | Parallel Link RR (Link A-Parallel RR)          | \$ | 93.00    | ? |
| 136 | 1 | Parallel Link Frt (Link A-Parallel Frt)        | \$ | 93.00    | ? |
| 137 | 1 | Stabilizer Bar RR (Bar RR Stabilizer)          | \$ | 97.00    | ? |
| 138 | 1 | Trailing Link RR RH (Link A-Trailing RR RH)    | \$ | 90.00    | ? |
| 139 | 1 | Trailing Link RR LH (Link A-Trailing RR LH)    | \$ | 90.00    | ? |
| 140 | 1 | Rear Seat LOWER                                | \$ | 734.50   | ? |
| 141 | 1 | Rear Seat Garnish TOPPER                       | \$ | 1,012.35 | ? |
| 142 | 1 | Diesel Tank (Tank A-Fuel)                      | \$ | 717.00   | ? |
| 143 | 1 | Diesel Tank Filler Pipe ( Tube A Fuel Filler ) | \$ | 157.00   | ? |

**TRANS-CAB AUTO SERVICES PTE LTD****AAD1709-261**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHB 9532S -**

|     |   |                                               |    |    |          |   |
|-----|---|-----------------------------------------------|----|----|----------|---|
| 145 | 1 | Diesel Tank Cap ( Cap A Fuel Filler )         | \$ | Pl | 46.00    | X |
| 146 | 1 | Diesel Tank Door Panel ( Door A Fuel Filler ) | \$ | Pl | 75.00    | X |
| 147 | 1 | Holder A Fuel Filler                          | \$ | Pl | 50.00    | X |
| 148 | 1 | Cable A Fuel Filler                           | \$ | Pl | 160.00   | X |
| 149 | 1 | Cable Lock A Fuel Filler                      | \$ | Pl | 25.00    | X |
| 150 | 1 | Longitudinal A-RR LH                          | \$ | Pl | 709.20   | X |
| 151 | 1 | Longitudinal A-RR RH                          | \$ |    | 709.20   | 7 |
| 152 | 1 | PANEL A-ROOF                                  | \$ | Pl | 1,800.00 | X |
| 153 | 1 | Roof side moulding - roof gutter LH           | \$ | Pl | 45.00    | X |
| 154 | 1 | Roof side moulding - roof gutter RH           | \$ | Pl | 45.00    | X |
| 155 | 1 | Roof lining                                   | \$ | Pl | 1,345.60 | X |
| 156 | 1 | Rear roof side panel inner RH                 | \$ | Pl | 450.00   | X |
| 157 | 1 | Rear roof side panel outer RH                 | \$ | Pl | 480.00   | X |
| 158 | 1 | PANEL A-BACK UPR (under windscreen )          | \$ | Pl | 800.00   | X |
| 159 | 1 | SHELF A-BACK UPR INCL(TRIM)                   | \$ | Pl | 400.00   | X |
| 160 | 1 | Rear hand brake cable                         | \$ | Pl | 1,021.90 | X |
| 161 | 1 | Rear hand brake cable o/s                     | \$ | Pl | 231.90   | X |

|              |           |                  |
|--------------|-----------|------------------|
| <b>TOTAL</b> | <b>\$</b> | <b>68,764.13</b> |
| <b>10%</b>   | <b>\$</b> | <b>6,876.41</b>  |
|              | <b>\$</b> | <b>61,887.72</b> |

**Specical Nett**

|    |      |                                    |    |    |        |       |
|----|------|------------------------------------|----|----|--------|-------|
| 1  | 1Set | Front Bumper Fastener Clip         | \$ | Pl | 24.00  | ✓     |
| 2  | 1Set | Front Licence Plate With Holder    | \$ | Pl | 192.00 | 455Pl |
| 3  | 2    | Front windscreen sealant           | \$ | Pl | 80.00  | X     |
| 4  | 1    | Front windscreen inner sponge seal | \$ | Pl | 100.00 | X     |
| 5  | 2    | Front ERP Sticker                  | \$ | Pl | 40.00  | X     |
| 6  | 1Set | Bonnet Insulator Clip              | \$ | Pl | 40.00  | ✓     |
| 7  | 1Set | Radiator Grille Clip               | \$ | Pl | 18.00  | ✓     |
| 8  | 1Set | Radiator Grille Top Cover Clip     | \$ | Pl | 10.00  | X     |
| 9  | 1Set | Front Fender Liner Clip LH         | \$ | Pl | 40.00  | X     |
| 10 | 1Set | Front Fender Liner Clip RH         | \$ | Pl | 40.00  | ✓     |
| 11 | 1Set | Engine Splash Cover Clip RH        | \$ | Pl | 12.00  | X     |
| 12 | 1Set | Engine Splash Cover Clip LH        | \$ | Pl | 12.00  | X     |
| 13 | 1Set | Rear Bumper Parking Sensor         | \$ | Pl | 300.00 | ✓     |
| 14 | 1Set | Rear Bumper Fastener Clip          | \$ | Pl | 30.00  | ✓     |
| 15 | 2Set | Rear Fender inner cowling clip LH  | \$ | Pl | 30.00  | X     |
| 16 | 2Set | Rear Fender inner cowling clip RH  | \$ | Pl | 30.00  | ✓     |
| 17 | 1Set | Rear Fender Inner Trim Clip RH     | \$ | Pl | 30.00  | ✓     |

**TRANS-CAB AUTO SERVICES PTE LTD****AAD1709-261**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHB 9532S -**

|    |       |                                          |    |    |        |       |
|----|-------|------------------------------------------|----|----|--------|-------|
| 18 | 1Set  | Rear Fender Inner Trim Clip LH           | \$ | na | 30.00  | X     |
| 19 | 1Set  | Rear Bumper End Dust Cover Clip          | \$ | na | 30.00  | X     |
| 20 | 1     | Rear Boot Sticker 'Trans-cab'            | \$ | na | 30.00  | —     |
| 21 | 1     | Rear Boot Sticker '6555-3333'            | \$ | na | 30.00  | —     |
| 22 | 1Set  | Bootlid inner trim board Clip            | \$ | na | 40.00  | X     |
| 23 | 1     | Door Sticker " Trans-cab " LH            | \$ | na | 80.00  | 60.00 |
| 24 | 1     | Door Sticker " Trans-cab " RH            | \$ | na | 80.00  | X     |
| 25 | 1     | Rear Door Sticker '6555-3333' LH         | \$ | na | 30.00  | X     |
| 26 | 1     | Rear Door Sticker '6555-3333' RH         | \$ | na | 30.00  | X     |
| 27 | 1Set  | Rear Door inner trim board clip RH       | \$ | na | 45.00  | X     |
| 28 | 1     | Front Side Rocker Panel Carnish clip LH  | \$ | na | 25.00  | X     |
| 29 | 1     | Front Side Rocker Panel Garnish clip RH  | \$ | na | 25.00  | X     |
| 30 | 2     | Rear Exhaust Mounting                    | \$ | sn | 40.00  | X     |
| 31 | 1     | Rear Bumper End Sealant                  | \$ | na | 80.00  | X     |
| 32 | 1     | Front Tyre LH                            | \$ | sn | 180.00 | X     |
| 33 | 1     | Front Wheel Rim LH                       | \$ | sn | 126.74 | X     |
| 34 | 1     | Front Tyre RH                            | \$ | sn | 180.00 | X     |
| 35 | 1     | Front Wheel Rim RH                       | \$ | sn | 126.74 | X     |
| 36 | 1     | Rear Tyre LH                             | \$ | sn | 180.00 | X     |
| 37 | 1     | Rear Wheel Rim LH                        | \$ | sn | 126.74 | X     |
| 38 | 1     | Rear Tyre RH                             | \$ | sn | 180.00 | 60.00 |
| 39 | 1     | Rear Wheel Rim RH                        | \$ | sn | 126.74 | 50.00 |
| 40 | 1     | Spare Tyre                               | \$ |    | 180.00 | 7     |
| 41 | 1     | Spare Wheel Rim                          | \$ |    | 126.74 | 7     |
| 42 | 1     | Spare Tyre Board                         | \$ | sn | 10.00  | X     |
| 43 | 1     | Spare tyre fastener bolt                 | \$ |    | 65.00  | 7     |
| 44 | 2     | Rear Windscreen Sealant                  | \$ | na | 80.00  | 40.00 |
| 45 | 1     | Rear Windscreen Inner Sponge Seal        | \$ | na | 100.00 | 30.00 |
| 46 | 1 Set | SHELF A-BACK UPR INCL(TRIM)Clip          | \$ | na | 20.00  | X     |
| 47 | 1 Set | Roof side moulding - roof gulter clip LH | \$ | na | 10.00  | X     |
| 48 | 1 Set | Roof side moulding - roof gulter clip RH | \$ | na | 10.00  | X     |
| 49 | 1     | Roof lining clip                         | \$ | na | 40.00  | X     |
| 50 | 1     | Rear Exhaust Heat Shield                 | \$ |    | 57.00  | 7     |
| 51 | 1     | Rear exhaust box - J hook                | \$ | sn | 25.00  | X     |
| 52 | 1     | Rear exhaust box chrome pipe             | \$ | n  | 791.00 | X     |
| 53 | 1     | Rear Exhaust Mounting Bracket            | \$ | n  | 27.00  | X     |
| 54 | 1     | Centre Exhaust Pipe                      | \$ | n  | 403.00 | X     |

|                    |           |                  |
|--------------------|-----------|------------------|
| <b>TOTAL</b>       | <b>\$</b> | <b>4,794.70</b>  |
| <b>TOTAL PARTS</b> | <b>\$</b> | <b>66,682.42</b> |

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHB 9532S -****AAD1709-261**

|                                                                                                                           |    |          |         |
|---------------------------------------------------------------------------------------------------------------------------|----|----------|---------|
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ | 8,100.00 | 3000    |
| To Check Electrical Lighting Concerned.                                                                                   | \$ | 170.00   | 401     |
| To Rust-Proofing Of The Affected Areas.                                                                                   | \$ | 170.00   | ✓       |
| Putty And Spray Painting Of The Affected                                                                                  | \$ | 8,400.00 | 2200    |
| To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.                                                   | \$ | 170.00   | nn X    |
| To dismantle and refit rear undercarriage parts, final checking and testing.                                              | \$ | 380.00   | } 22401 |
| To dismantle and refit rear axle housing assy, remove and renewal of parts, final checking and                            | \$ | 380.00   |         |
| Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.                                           | \$ | 380.00   | 2501    |
| To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.                                      | \$ | 170.00   | } 601   |
| To repair and realign rear exhaust pipe.                                                                                  | \$ | 170.00   |         |
| To reinstall rear bumper parking sensor.                                                                                  | \$ | 170.00   | 601     |
| To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.       | \$ | 380.00   | nn X    |
| To supply and re-do rear luggage floor panel insulation padding.                                                          | \$ | 380.00   | } 1201  |
| To transfer of end panel fittings and conduct water seepage test.                                                         | \$ | 170.00   |         |
| To transfer of luggage floor panel fittings and conduct water seepage test.                                               | \$ | 170.00   |         |

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHB 9532S -****AAD1709-261**

|                                                                                                                                                 |    |        |      |
|-------------------------------------------------------------------------------------------------------------------------------------------------|----|--------|------|
| To transfer of boot fittings and conduct water seepage test.                                                                                    | \$ | 170.00 | 601  |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                                                 | \$ | 380.00 | nn X |
| To transfer of Fender fittings, attachments and perform water seepage test.                                                                     | \$ | 170.00 | nn X |
| To check steering geometry and computer wheel alignment                                                                                         | \$ | 220.00 | 601  |
| To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.                                                                          | \$ | 170.00 | 1201 |
| To transfer of tire, rim and on wheel balancing.                                                                                                | \$ | 170.00 | 201  |
| To check ABS brake efficiency, final checking and testing.                                                                                      | \$ | 380.00 | nn X |
| To vacuum, replace, refix and recharge air                                                                                                      | \$ | 380.00 | 1001 |
| To replace, refix and top up coolant for radiator                                                                                               | \$ | 170.00 | 501  |
| To vacuum, replace, refix and recharge Air                                                                                                      | \$ | 170.00 | nn X |
| Towing Fees.                                                                                                                                    | \$ | 120.00 | 501  |
| To transfer of door fittings, attachment and perform water seepage test.                                                                        | \$ | 170.00 | 601  |
| To dismantle and refit rear seat, backrest, trimings, garnish, roof-lining, speaker shelfboard, carpeting and other to enable body work repair. | \$ | 380.00 | nn X |
| To remove and renew power steering pump, oil cooler pipe and final checking and testing.                                                        | \$ | 440.00 | nn X |
| To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.                                                    | \$ | 380.00 | nn X |



**TRANS-CAB AUTO SERVICES PTE LTD****AAD1709-261**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHB 9532S -**

|              |    |                  |
|--------------|----|------------------|
|              | \$ | 23,630.00        |
| <b>TOTAL</b> | \$ | <b>90,312.42</b> |

**Repair Days**~~30 Days~~

28 days

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: