

ASS. REQ. BY: REF CS/EQ117018714/T1rb 92 Special Instruction:
 SUBJECT: Taufikh ASSIGNMENT (Office)
 From (Person): Elaine Cheong of EQI Date/Time: 28/9/17 5.40pm
 Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS
 To inspect Vehicle No: YP 1617 J Insured:
 at Workshop n/s: Wah Hong Motors Tel: 65155988
 of 38 Toh Guan Rd East
 Policy No: DMCPHQ17-001588 Claim No: DM17H002096
 Sum Insured: Excess: \$ 3750.00
 Make of Veh: D.O.A 18/09/17
 (Client's Record)

CA / REV / REP. / REV 24 HRS (9788 0700) H.O.D. Endorsement:
 Date/Time: 29/9/17 8.54am Person Contacted: Michael Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
2/10/17	Sent poli through menimich
3/10/17	Elaine called to on hold authorise because is a midnight case. Pending for investigation.
9/11/17	Inform Michael authorise repair and excess

709 9221
 10/11/17 7272

REF: EQ

ASSIGNMENT

From _____ Date 29/9/2017

Veh No YP1617J Yr Regn 20/6, Mon

Estimated Cost _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or _____

To inspect Vehicle No. YP1617J

Make Mitsubishi Canter CC 2998

at Workshop in/s Wah Hong Motor

Colour white A.C. Insured / Std / NI / NA

of 38 Toh Guan Rd East #, 01-57, 608581

Sp Reading _____ T Radc. Insured / Std / NI / NA

Insured _____

Eng No. _____

Policy No. _____

C No. FEB21EA 20255

Claims No. _____

Gen. Cond. Good / Fair / Poor / Burnt

Sum Insured: _____ Excess \$3750

Steering Inorder / Jammed / Leaked / Burnt or _____

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or _____

Make of Veh _____

Mod: Nil / SiRim / STD A/Rim or _____

(Policy Condition)

4:30pm



Tyre Size F: 195/85R15

R: _____

Remark: The veh had commenced its repair at the time of inspection.

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Ball or Market Value: \$90K - \$85K

Front _____ Rear _____

DAC Accident Report: _____ Consistent? Yes or No

R Bal 6 mm R Bal 6/6 mm

GIA PR Seen: _____ Consistent? Yes or No

L Bal 6 mm L Bal 6/6 mm

Est Repairs: _____ days Res: Yes or No

D.O.A. _____ D.O.I. 29/9/17

Lum Sum: _____ % 3 Val: Yes or No

Survey held at: Wah Hong

CA REV / REP. / 24 HRS copy

Des of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date _____ Person Contacted _____

Frt O/S, U/C

Date _____ Time _____ Action / Instruction _____

The U/C / Chassis frame / Body Structure affected due to collision

Email Michel repair limit \$55K.

28/12/17 Anthorse on hold due to owner want to replace all new parts
Pending instruction from Elaine; because owner intent to loss the vehicle
5/1/18 According to Elaine, this case is TL; Repairer is aware this is a total loss case.
We will submit our report accordingly
Submit uneconomical total loss report
MV: \$ 90K, LTA: \$ 30,063.00, NV: \$ 59,937.00

RECEIVED 05 JAN 2018

Date/Time File Pass:to? : Preli. Report Days Of Repair: _____

1: typist : Final Report Resurvey No. of Trip: _____

Date/Time File Return:to? _____ Survey Fee _____

2: _____ Add Fee: Site Insp (\$) _____

Report Format: Uneconomical TL Interview (\$) _____

Lump Sum / I.B.I: (\$) _____ Tech. Invs (\$) _____

_____ Weekend (\$) _____

TOTAL: _____

250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CS/EQ117018714/T1rb

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 29-09-2017



Code : EQI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	YP 1617J
Policy No.	DMCPHQ17-001588	Coverage (\$)	0.00
Claim No.	DM17HO02096	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	29/09/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/09/2017	Inspection Date	29/09/2017
Survey held at	WAH HONG & CREDIT PTE LTD 38 TOH GUAN ROAD EAST #01-57 ENTERPRISE HUB SINGAPORE 608581		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Sep 2017 18:25	28 Sep 2017 11:26	28 Sep 2017 17:40				New Assignment Cancel Case
	Sendback Est	S\$61,833.10	Assign				

Main
Reference
Claim Details
Documents
Show All

CLAIM SUBFOLDER DETAILS

Insured:	SR ELECTRICAL ENGINEERING PTE LTD , Co. Reg. No.: 201015110K		
Vehicle Reg. No.:	YP1617J	Date of Loss:	18/09/2017 03:00 - :59
Claim Type:	OD / DM17HO02096	Policy/Cover Note No.:	DMCPHQ17-001588 (Comprehensive)
		Excess:	S\$3,750.00
Repairer:	Wah Hong Motors & Credit Pte Ltd (HQ) 38 Toh Guan Road East, #01-57, Enterprise Hub, 608581 Jurong East - Tel: +65 65155988		
Handling Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by Elaine Cheong - 6500 6772]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/10/2017]		

ASSOCIATED MAIL RECEIVED
[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block
MND Complex
Singapore 069110

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Cheong

Date: 02 Oct 2017

Preliminary Advice

Vehicle No	: YP1617J	Accident Date	: 18/09/2017
Make	: MITSUBISHI CANTER	Policy No.	: DMCPHQ17-001588
Assignment Date	: 28/09/2017	Excess	: S\$3,750.00
Date of Inspection	: 29/09/2017	Est. Duration of Repair	: 30.00
Inspection At	: WAH HONG MOTORS & CREDIT PTE LTD (HQ) 38 TOH GUAN ROAD EAST, #01-57, ENTERPRISE HUB SINGAPORE 608581		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages undercarriage and front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	61,833.10
Revised Amount	:S\$	49,338.10
Check Items (Estimated)	:S\$	10,395.00
Total	:S\$	59,733.10

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	90,000.00
COE / PARF Rebate	:S\$	30,063.00
Salvage Value	:S\$	
Margin for Repair	:S\$	59,937.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Repairer agree to repair Lump sum basis.

top-up total 1.35

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block
MND Complex
Singapore 069110

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Cheong

Date: 09 Nov 2017

Preliminary Advice

Vehicle No	: YP1617J	Accident Date	: 18/09/2017
Make	: MITSUBISHI CANTER	Policy No.	: DMCPHQ17-001588
Assignment Date	: 28/09/2017	Excess	: S\$3,750.00
Date of Inspection	: 29/09/2017	Est. Duration of Repair	: 30.00
Inspection At	: WAH HONG MOTORS & CREDIT PTE LTD (HQ) 38 TOH GUAN ROAD EAST, #01-57, ENTERPRISE HUB SINGAPORE 608581		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	61,833.10
Revised Amount	:S\$	49,338.10
Check Items (Estimated)	:S\$	10,395.00
Total	:S\$	59,733.10
Lump Sum Repair	:S\$	47,500.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	90,000.00
COE / PARF Rebate	:S\$	30,063.00
Salvage Value	:S\$	
Margin for Repair	:S\$	59,937.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Repairer agree to repair Lump sum basis.

Print Received Message

This mail is associated with :

YP1617J (DM17HO02096)

OD

Sep 18 2017 3:00AM

[SR ELECTRICAL ENGINEERING PTE LTD]

Wah Hong Motors & Credit Pte Ltd

From EQ Insurance Company Ltd (HQ) (EQI_HQ), sent on 09/11/2017 11:26 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$47500.00) - YP1617J - Claim Handler: Elaine Cheong

Approved:47500.00:Please authorise repair if damage is consistent. Thanks.

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Thursday, November 09, 2017 12:48 PM
To: 'michael@wahhong.sg'
Cc: SUR
Subject: YP 1617J EQI OD DOA : 18/09/2017

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **YP 1617J (excess \$3,750.00/-)**. Please note that **repair on Lump Sum basis**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/09/2017 16:13
Date Of Accident	18/09/2017 03:30
Exact Location Of Accident	JUNCTION OF TUAS VIEW LINK & TUAS VIEW WALK 1
Country/State of Loss	SINGAPORE

*12-MORNING
midnight
case*

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP1617J
Insured/Policyholder	
Name Of Registered Owner	SR ELECTRICAL ENGINEERING PTE LTD
Co Reg No	201015110K
Email Address	INFO@SRELECTRICAL.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-81914400

*on hold
investigation*

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FEB21CR4SDEB-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCPHQ17-001588
Cover Note Number	

Driver

Name of Driver	MATHAR VADIVEL
NRIC No	G2564647P
Date Of Birth	22/05/1992
Occupation	OUTDOOR
Date Of Driving Pass	10/08/2016
Driving Experience	1 YEAR AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-81914400
Fax Number	
Contact Number	
EEmail Address	INFO@SRELECTRICAL.COM.SG

Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? YES

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

Please refer to the attached Sketch Plan and the accident details

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number WC5257E

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 0

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name MATHAR VADIVEL

Approximate Age

Injuries Sustain

Injured person in which vehicle?

YP1617J

Were seat belts worn?

Was injured conveyed to hospital by ambulance? YES

Address

1 SUNVIEW ROAD #06-24

Postcode

627615

1/4

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



✓ M. Vadivel

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

please refer to the attachment

2/4

Describe Circumstances of the Accident

Please Refer to the attachment

Declaration

We declare the foregoing particulars are true in every respect.


19 Sep 2017

Policyholder's Signature / Date & Time


x M. Vadivel

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

3/4

Tuas south Ave 6



M. Kadiveri
 ENGINEERING PTE. LTD. * SR ELECTRICAL

Tuas view walk 2

Dormitory

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 5110K

Vehicle Details

Vehicle No.: YP1617J

Vehicle to be Exported: No

Intended De-registration Date: 02 Oct 2017

Vehicle Make: MITSUBISHI

Vehicle Model: CANTER FEB21ER4SDEB (CBU)

Primary Colour: White

Manufacturing Year: 2015

Engine No.: 4P10B99505

Chassis No.: FEB21EA20255

Maximum Power Output: -

Open Market Value: \$29,920.00

Original Registration Date: 30 Mar 2016

First Registration Date: 30 Mar 2016

Transfer Count: 0

Actual ARF Paid: \$1,496.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 29 Mar 2026

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$35,414.00

COE Rebate Amount: \$30,063.00

Total Rebate Amount: \$30,063.00

The information contained herein is correct as at 02 Oct 2017

OK



Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
Last updated on 17 Sep 2017 at 12:38 AM

A-Assurance
Assurance in Insurance

Car Insurance Expiring?
We get you the cheapest insurance renewal

[Click to get quote](#)



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Volkswagen New Beetle 1.6A.



Milky White Cute, Sporty,
Attractive, Unique, Eye Catching
Beauty, Low Mileage.
Direct Owner: [StarAd](#)

Hill
HoBee Group
One S
Finance,
New and





Browse by Category

Sort by Da

5 vehicles

mitsubishi feb21

Advanced S

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
Search Selection	mitsubishi feb21		Any	Any	2016	Any	An
	Mitsubishi	Fuso Canter FEB21	\$89,800	\$9,730 /yr	23-Dec-2016	2,998 cc	12,00C
	Fuel Type: Diesel High Trade In For Your Old Vehicle. 100% In House Loan Available! Call Us Now For Viewing!						
	Abwin Truck Pte Ltd Posted: 02-Oct-2017 Tags: 2016 Mitsubishi Fuso, 2016 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Fuso, Used Mitsubishi						
	Mitsubishi	Fuso Canter FEB21	-	N.A	18-Oct-2016	2,998 cc	-
	Fuel Type: Diesel Auction Closing Time: 11th Oct 2017 at 11:00 PM GST Registered. 2 Keys Available. Road Tax Expiry On 17/10/2017. Mileage Of 13947km. Financing Up To 100% Possible Sul Call Us To Enquire.						
	Posted: 28-Sep-2017 Tags: 2016 Mitsubishi Fuso, 2016 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Fuso, Used Mitsubishi						
	Mitsubishi	Fuso Canter FEB21	\$95,800	\$11,000 /yr	17-Jun-2016	2,998 cc	-
	Fuel Type: Diesel Almost Brand New Unit! The Most Reliable Japanese 14 Footer Lorry, Low Interest Rate Of 2.99%! Class 3 License, No Need Warranty Or 100000km Whichever Comes First. Immedaite Registr...						
	Net Link Partners Pte Ltd Posted: 25-Sep-2017 Tags: 2016 Mitsubishi Fuso, 2016 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Fuso, Used Mitsubishi						
	Mitsubishi	Fuso Canter FEB21	\$96,800	\$10,980 /yr	25-Jul-2016	2,998 cc	-
	Fuel Type: Diesel High Trade In For Your Old Vehicle. High Loan Is Possible. We Can Quote Your Insurance For You. Hurry While Stock Last.						
	KSL Automotive Pte Ltd Posted: 22-Sep-2017 Tags: 2016 Mitsubishi Fuso, 2016 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Fuso, Used Mitsubishi						

Car Buying

Car Selling

Car Aftermarket

Compare

p

On The Move

Lifestyle



Wah Hong Motors & Credit Pte Ltd (Co.Reg.No:199806235M)

38 Toh Guan Road East, #01-57, Enterprise Hub

Singapore 608581

Tel: +65 65155988 Fax: +65 68966321 Email: nicholas@wahhong.sg

INSURER: **EQ Insurance Company Ltd (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	170916
Policy No:	DMCPHQ17-001588	Date of Loss:	18/09/2017
Vehicle Reg. No.:	YP1617J	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SR ELECTRICAL ENGINEERING PTE LTD		

Make/Model:	MITSUBISHI CANTER, 3.0 D FEB21ER4SDEB (CBU) (M)	Vehicle Reg. Date:	30/03/2016
Vehicle Colour:	WHITE	Chassis No:	FEB21EA20255
Engine No:	4P10B99505		
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	32

30 days
Lumpsum
Tan Jiah 97495749
Ex \$ 3750.
Revert
** To check repair limit.*
Resurvey after paint.
29/9/17.

Present Location: WAH HONG MOTORS & CREDIT PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	55,133.10
Miscellaneous Items	0.00
Labour	6,700.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	61,833.10
+ GST 7.00% (S\$)	4,328.32
Nett Amount (S\$)	66,161.42

Sur @ lkkauto.com
Tan Jiah @ Meantown
2/10/17

This claim is handled by: MICHEAL TEE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Generated using Merimen e-Claims Internet Estimation & Adjusting System

86635.40

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 28 Sep 2017)

Parts: N/A MITSUBISHI CANTER 3.0 D FEB21ER4SDEB (CBU) (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Wah Hong Motors & Credit Pte Ltd/YP1617J/28/09/2017 11:26

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 Unit FEB21ER4SDEB Cabin	0.00	0.00	bt ✓ *19,500.00 F
2	1		*1 Pc Air Con Blower With Heater	0.00	0.00	con ✓ *2,025.00 F
3	1		*1 Pc Front Bumper	0.00	0.00	bt ✓ *850.00 F
4	1		*1 Pc Front R/H Side Bumper Bracket	0.00	0.00	bt ✓ *155.00 F
5	1		*1 Pc Front L/H Side Bumper Bracket	0.00	0.00	bt ✓ *155.00 F
6	1		*1 Pc Front R/H Side Headlamp	0.00	0.00	con ✓ *480.00 F
7	1		*1 Pc Front L/H Side Headlamp	0.00	0.00	mis ✓ *480.00 F
8	1		*1 Pc Front R/H Side Lamp	0.00	0.00	mis ✓ *158.00 F
9	1		*1 Pc Front L/H Side Lamp	0.00	0.00	mis ✓ *158.00 F
10	1		*1 Pc Front Grille	0.00	0.00	mis ✓ *830.00 F
11	1		*1 Pc Front R/H Side Air Bag	0.00	0.00	act ✓ *3,650.00 F
12	1		*1 set Front R/H & L/H Side Safety Belt	0.00	0.00	act ✓ *750.00 F
13	1		*1 Pc Front Air Bag Control (ECU)	0.00	0.00	act ✓ *1,850.00 F
14	1		*1 Pc Front R/H Door	0.00	0.00	bt ✓ *1,550.00 F
15	1		*1 Pc Front L/H Door	0.00	0.00	bt ✓ *1,550.00 F
16	1		*1 Pc Steeling Box	0.00	0.00	bro ✓ *1,900.00 F
17	1		*1 Pc Steeling Rack	0.00	0.00	? *6,500.00 F
18	1		*1 Pc Radiator	0.00	0.00	? *2,950.00 F
19	1		*1 Pc Front Dashboard	0.00	0.00	de ✓ *2,600.00 F
20	1		*1 Pc Front Windscreens	0.00	0.00	con ✓ *950.00 F
21	1		*1 Pc Front Windscreens Moulding	0.00	0.00	con ✓ *220.00 F
22	1		*1 Pc Top Roof Panel Liner	0.00	0.00	de ✓ *860.00 F

F=Franchise part.

Sub Total (S\$)	50,121.00
+ Margin on L,N Items 10.00% (S\$)	5,012.10
Total Parts (S\$)	55,133.10

Wah Hong Motors & Credit Pte Ltd/YP1617J/28/09/2017 11:26. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	remove & replace all the parts mentioned above knocking straighten up necessary affected & dashboard & air bag	New	3600 5,500.00
2	spray painting on affected areas	New	1000 1,200.00
Gross Labour Cost (S\$)			6,700.00

Wah Hong Motors & Credit Pte Ltd/YP1617J/28/09/2017 11:26. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Wah Hong Motors & Credit Pte Ltd (Co.Reg.No:199806235M)38 Toh Guan Road East, #01-57, Enterprise Hub
Singapore 608581

Tel: +65 65155988 Fax: +65 68966321 Email: nicholas@wahhong.sg

(SUPPLEMENTARY)INSURER: **EQ Insurance Company Ltd (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	170916
Policy No:	DMCPHQ17-001588	Date of Loss:	18/09/2017
Vehicle Reg. No.:	YP1617J	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SR ELECTRICAL ENGINEERING PTE LTD		
Make/Model:	mitsubishi canter, 3.0 D FEB21ER4SDEB (CBU) (M)	Vehicle Reg. Date:	30/03/2016
Vehicle Colour:	White	Chassis No:	FEB21EA20255
Engine No:	4P10B99505		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	32		
Remarks:	INTERCOOLER		
Present Location:	WAH HONG MOTORS & CREDIT PTE LTD (HQ)		

COST OF CLAIMS**Amount**

Parts	18,802.30
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
	Gross Total (S\$) 18,802.30
	+ GST 7.00% (S\$) 1,316.16
	Nett Amount (S\$) 20,118.46
	+ Previous Estimates (S\$) 66,161.42
	Claim Total (S\$) 86,279.88

Revised 14/11/17

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 14 Nov 2017)
 Parts: N/A MITSUBISHI CANTER 3.0 D FEB21ER4SDEB (CBU) (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Wah Hong Motors & Credit Pte Ltd/YP1617J/14/11/2017 15:30
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 Pc Intercooler	0.00	0.00	*2,350.00 F <i>bt</i>
2	1		*1 Pc Turbo Cooler	0.00	0.00	*3,500.00 F <i>bt</i>
3	1		*1 Pc Radiator Fan Blade	0.00	0.00	*210.00 F <i>one</i>
4	1		*1 Set Front Brake Pipe	0.00	0.00	*460.00 F <i>bt</i>
5	1		*1 Pc Front Master Brake Pump	0.00	0.00	*2,250.00 F <i>bt</i>
6	1		*1 Pc Front Cabin Bar & Lock	0.00	0.00	*950.00 F <i>bt</i>
7	1		*1 Pc Front R/H Door Mirror	0.00	0.00	*235.00 F <i>one</i>
8	1		*1 Pc Front L/H Door Mirror	0.00	0.00	*250.00 F <i>one</i>
9	1		*1 Pc Front R/H Door Board	0.00	0.00	*165.00 F <i>de</i>
10	1		*1 Pc Front L/H Door Board	0.00	0.00	*165.00 F <i>de</i>
11	1		*1 Set Engine Mounting	0.00	0.00	*265.00 F <i>bt</i>
12	1		*1 Set Gear Box Mounting	0.00	0.00	*280.00 F <i>bt</i>
13	1		*1 Set Air Con Pipe Condenser	0.00	0.00	*290.00 F <i>bt</i>
14	1		*1 Set Air Con Heater Pipe	0.00	0.00	*360.00 F <i>bt</i>
15	1		*1 Pc Front R/H Door Inner Garnish	0.00	0.00	*185.00 F <i>de</i>
16	1		*1 Pc Front L/H Door Inner Garnish	0.00	0.00	*185.00 F <i>de</i>
17	1		*1 Pc Front R/H Door Inner Rubber	0.00	0.00	*125.00 F <i>one</i>
18	1		*1 Pc Front L/H Door Inner Rubber	0.00	0.00	*125.00 F <i>one</i>
19	1		*1 Set Wrapper Arm	0.00	0.00	*105.00 F <i>bt</i>
20	1		*1 Set Wrapper Blade	0.00	0.00	*38.00 F <i>one</i>
21	1		*1 Pc Front Forcement	0.00	0.00	*650.00 F <i>bt</i>
22	1		*1 Set Front Seats (R/H & L/H)	0.00	0.00	*950.00 F <i>one</i>
23	1		*1 Unit 14 Ft Steel Body	0.00	0.00	*3,000.00 F <i>bt</i>
Sub Total (S\$)						17,093.00
+ Margin on L,N Items 10.00% (S\$)						1,709.30
Total Parts (S\$)						18,802.30

F=Franchise part.

Wah Hong Motors & Credit Pte Ltd/YP1617J/14/11/2017 15:30. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Wah Hong Motors & Credit Pte Ltd/YP1617J/14/11/2017 15:30. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Sep 2017 18:25 Sendback Est	28 Sep 2017 11:26 S\$61,833.10	28 Sep 2017 17:40 Edit Adj Rpt	S\$68,140.40 Edit Estimates	S\$68,140.40 View Rpt		Pending for Survey Report Cancel Case
Supp #1	14 Nov 2017 15:15	14 Nov 2017 15:30 S\$18,802.30	14 Nov 2017 15:30			(Combined)	Combined with Main Uncombine Suppl.

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS			
Insured:	SR ELECTRICAL ENGINEERING PTE LTD, Co. Reg. No.: 201015110K		
Vehicle Reg. No.:	YP1617J	Date of Loss:	18/09/2017 03:00 - :59
Claim Type:	OD / DM17HO02096	Policy/Cover Note No.:	DMCPHQ17-001588 (Comprehensive)
		Excess:	S\$3,750.00
Repairer:	Wah Hong Motors & Credit Pte Ltd (HQ) 38 Toh Guan Road East, #01-57, Enterprise Hub, 608581 Jurong East - Tel: +65 65155988		
Handling Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by Elaine Cheong - 6500 6772]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 09/10/2017]		
Driver/Custodian:	MATHAR VADIVEL (), NRIC: G2564647P		

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
<ul style="list-style-type: none"> EQ1_HQ (07/12/2017): Alert - Adj Mandate Maintained - YP1617J - Claim Handler: Elaine Cheong EQ1_HQ (09/11/2017): Alert - Adj Mandate Approved (S\$47500.00) - YP1617J - Claim Handler: Elaine Cheo... 			

ALL ASSOCIATED TASKS											View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?					
No results.														

Claim Documents

YP1617J (DM17HO02096)
OD
Sep 18 2017 3:00AM
[SR ELECTRICAL ENGINEERING PTE LTD]
Wah Hong Motors & Credit Pte Ltd

Upload Documents Upload Photos Compose New Letter			View <input type="button" value="View in Browser"/>
Assessment Reports			1 per page <input type="button" value=""/>
No	Finalized On	Wah Hong Motors & Credit Pte Ltd (HQ)	Thumbnail Print
1	28/09/17 11:26	Repairer Estimates	<input type="button" value="1"/> Load HTM <input type="checkbox"/>
2	14/11/17 15:30	Repairer Estimates Suppl. #1	<input type="button" value="1"/> Load HTM <input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	02/10/17 15:04	Adjuster Immediate Advice	<input type="button" value="1"/> Load HTM <input type="checkbox"/>
2	09/11/17 10:34	Adjuster Immediate Advice	<input type="button" value="1"/> Load HTM <input type="checkbox"/>
3	04/12/17 11:41	Adjuster Immediate Advice	<input type="button" value="1"/> Load HTM <input type="checkbox"/>
Photos/Images			3 per page <input type="button" value=""/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
2	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
3	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
4	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
5	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
6	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
7	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
8	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
9	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
10	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
11	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
12	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
13	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
14	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
15	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
16	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
17	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
18	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
19	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
20	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
21	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
22	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
23	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
24	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
25	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
26	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
27	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
28	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
29	02/10/17 15:08	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>

30	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
31	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
32	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
33	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
34	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
35	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
36	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
37	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
38	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
39	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
40	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
41	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
42	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
43	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
44	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
45	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
46	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
47	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
48	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
49	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
50	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
51	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
52	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
53	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
54	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
55	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
56	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
57	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
58	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
59	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
60	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
61	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
62	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
63	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
64	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
65	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
66	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
67	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
68	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
69	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
70	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
71	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
72	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
73	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
74	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
75	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
76	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
77	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
78	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>
79	02/10/17 15:08	General View		Load JPG	<input checked="" type="checkbox"/>

80	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
81	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
82	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
83	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
84	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
85	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
86	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
87	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
88	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
89	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
90	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
91	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
92	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
93	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
94	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
95	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
96	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
97	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
98	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
99	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
100	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
101	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
102	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
103	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
104	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
105	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
106	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
107	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
108	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
109	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
110	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
111	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
112	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
113	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
114	02/10/17 15:08	General View	1	Load JPG	<input checked="" type="checkbox"/>
115	02/10/17 15:09	General View	1	Load JPG	<input checked="" type="checkbox"/>
116	02/10/17 15:09	General View	1	Load JPG	<input checked="" type="checkbox"/>
117	02/10/17 15:09	General View	1	Load JPG	<input checked="" type="checkbox"/>
118	02/10/17 15:09	General View	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/01/18 14:18	LTA REBATE 02 OCT 2017	1	Load PDF	
2	10/01/18 14:18	SUPPLEMENTARY	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Repairer Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block, MND Complex
Singapore 069110

Our File No: CS/EQ117018714/T1RBS2
Date: 10/01/2018

REFERENCE

Insured/Claimant:	SR ELECTRICAL ENGINEERING PTE LTD	Policy No:	DMCPHQ17-001588	Claim No:	DM17HO02096
Date of Loss:	18/09/2017	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP1617J	Engine No:	4P10B99505
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER4SDEB (CBU) (M)	Chassis No:	FEB21EA20255
Reg. Date:	30/03/2016 (Man. Year: 2015)	Odometer:	0 km
Colour:	White		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	S\$90,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/85R15	Rear Tyre Size:	195/85R15 (D)
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6/6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	73,935.40	63,540.40	10,395.00	14.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,700.00	4,600.00	2,100.00	31.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	80,635.40	68,140.40	12,495.00	15.50
- Excess (S\$)	0.00	3,750.00	-3,750.00	
(S\$)	80,635.40	64,390.40	16,245.00	20.15
+ GST 7.00/0.00% (S\$)	5,644.48	0.00	5,644.48	100.00
Nett Amount (S\$)	86,279.88	64,390.40	21,889.48	25.37

INSPECTION

Date of Assignment: 28/09/2017 Present Location:
Date Inspected: 29/09/2017 Inspected At:

Wah Hong Motors & Credit Pte Ltd (HQ)
Wah Hong Motors & Credit Pte Ltd (HQ)
38 Toh Guan Road East, #01-57,
Enterprise Hub
Singapore 608581

Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(EXCLUDE CHECK ITEMS S\$10,395.00 NETT)

TOTAL LOSS ASPECT

Market Value : \$90,000.00
OMV : \$29,920.00
PARF Rebate (1) : \$0.00
Quota Premium Paid : \$35,414.00
COE Rebate (2) : \$30,063.00
Total Rebate (1) + (2) = : \$30,063.00

The total amount incurred will be Market Value \$90,000.00 minus Total Rebate \$30,063.00 = \$59,937.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Jan 2018)
Parts:	N/A MITSUBISHI CANTER 3.0 D FEB21ER4SDEB (CBU) (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP1617J)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 Unit FEB21ER4SDEB Cabin (WCP)	Bent	19,500.00 F	*19,500.00 F
2	1		*1 Pc Air Con Blower With Heater (WCP)	Cracked	2,025.00 F	*2,025.00 F
3	1		*1 Pc Front Bumper (WCP)	Bent	850.00 F	*850.00 F
4	1		*1 Pc Front R/H Side Bumper Bracket (WCP)	Bent	155.00 F	*155.00 F
5	1		*1 Pc Front L/H Side Bumper Bracket (WCP)	Bent	155.00 F	*155.00 F
6	1		*1 Pc Front R/H Side Headlamp (WCP)	Cracked	480.00 F	*480.00 F
7	1		*1 Pc Front L/H Side Headlamp (WCP)	Missing	480.00 F	*480.00 F
8	1		*1 Pc Front R/H Side Lamp (WCP)	Missing	158.00 F	*158.00 F
9	1		*1 Pc Front L/H Side Lamp (WCP)	Missing	158.00 F	*158.00 F
10	1		*1 Pc Front Grille (WCP)	Missing	830.00 F	*830.00 F
11	1		*1 Pc Front R/H Side Air Bag (WCP)	Cut	3,650.00 F	*3,650.00 F
12	1		*1 set Front R/H & L/H Side Safety Belt (WCP)	Cut	750.00 F	*750.00 F
13	1		*1 Pc Front Air Bag Control (ECU) (WCP)	Cut	1,850.00 F	*1,850.00 F
14	1		*1 Pc Front R/H Door (WCP)	Bent	1,550.00 F	*1,550.00 F
15	1		*1 Pc Front L/H Door (WCP)	Twisted	1,550.00 F	*1,550.00 F
16	1		*1 Pc Steeling Box (WCP)	Broken	1,900.00 F	*1,900.00 F
17	1		*1 Pc Steeling Rack (WCP)	*Check	6,500.00 F	*- F
18	1		*1 Pc Radiator (WCP)	*Check	2,950.00 F	*- F
19	1		*1 Pc Front Dashboard (WCP)	Deformed	2,600.00 F	*2,600.00 F
20	1		*1 Pc Front Windscreens (WCP)	Cracked	950.00 F	*950.00 F
21	1		*1 Pc Front Windscreens Moulding (WCP)	Necessary	220.00 F	*220.00 F
22	1		*1 Pc Top Roof Panel Liner (WCP)	Dented	860.00 F	*860.00 F
Supplementary #1						
23	1		*1 Pc Intercooler (WCP)	Bent	2,350.00 F	*2,350.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
24	1		*1 Pc Turbo Cooler (WCP)	Bent	3,500.00 F	*3,500.00 F	
25	1		*1 Pc Radiator Fan Blade (WCP)	Cracked	210.00 F	*210.00 F	
26	1		*1 Set Front Brake Pipe (WCP)	Bent	460.00 F	*460.00 F	
27	1		*1 Pc Front Master Brake Pump (WCP)	Bent	2,250.00 F	*2,250.00 F	
28	1		*1 Pc Front Cabin Bar & Lock (WCP)	Bent	950.00 F	*950.00 F	
29	1		*1 Pc Front R/H Door Mirror (WCP)	Cracked	235.00 F	*235.00 F	
30	1		*1 Pc Front L/H Door Mirror (WCP)	Cracked	250.00 F	*250.00 F	
31	1		*1 Pc Front R/H Door Board (WCP)	Deformed	165.00 F	*165.00 F	
32	1		*1 Pc Front L/H Door Board (WCP)	Deformed	165.00 F	*165.00 F	
33	1		*1 Set Engine Mounting (WCP)	Bent	265.00 F	*265.00 F	
34	1		*1 Set Gear Box Mounting (WCP)	Bent	280.00 F	*280.00 F	
35	1		*1 Set Air Con Pipe Condenser (WCP)	Bent	290.00 F	*290.00 F	
36	1		*1 Set Air Con Heater Pipe (WCP)	Bent	360.00 F	*360.00 F	
37	1		*1 Pc Front R/H Door Inner Garnish (WCP)	Deformed	185.00 F	*185.00 F	
38	1		*1 Pc Front L/H Door Inner Garnish (WCP)	Deformed	185.00 F	*185.00 F	
39	1		*1 Pc Front R/H Door Inner Rubber (WCP)	Necessary	125.00 F	*125.00 F	
40	1		*1 Pc Front L/H Door Inner Rubber (WCP)	Necessary	125.00 F	*125.00 F	
41	1		*1 Set Wrapper Arm (WCP)	Bent	105.00 F	*105.00 F	
42	1		*1 Set Wrapper Blade (WCP)	Cut	38.00 F	*38.00 F	
43	1		*1 Pc Front Forcement (WCP)	Bent	650.00 F	*650.00 F	
44	1		*1 Set Front Seats (R/H & L/H) (WCP)	Twisted	950.00 F	*950.00 F	
45	1		*1 Unit 14 Ft Steel Body (WCP)	Bent	3,000.00 F	*3,000.00 F	
					Sub Total (S\$)	67,214.00	57,764.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	6,721.40	5,776.40
					Total Parts (S\$)	73,935.40	63,540.40

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	remove & replace all the parts mentioned above knocking straighten up necessary affected & dashboard & air bag	New	5,500.00	3,600.00
2	spray painting on affected areas	New	1,200.00	1,000.00
Gross Labour Cost (S\$)			<u>6,700.00</u>	<u>4,600.00</u>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >