

22/03/2007

ASS. REC. BY:

REF: CS/FCI17018719/71962

Special Instruction:

Survivor

CWS

Taufik

ASSIGNMENT (Office)

From (Person):

Joanne Yong

of

FCI

Date/Time: 29/9/17 3:05pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 492L

Insured:

SHB 6357B

at Workshop m/s

Mova Automotive

Tel:

62723892

of Blk 1008 Bkt Merah Lane 3 #01-04 / 06/08

Policy No:

P-15072701 MFSH

Claim No:

D17009249 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

27/09/17

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement

Date/Time:

29/9/17 3:15pm

Person Contacted:

Eric

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLP 492L - NA/AVA17018525/24 - D.O.A: 27/09/17

SHB 6357B - NA/INC15012594/13 - D.O.A: 9/7/15

07/10/17 @

4-10pm revised to Joanne Yong by email.

Pls note: \*

SLP 492L CC4/17016784/Tipa3 DOB: 14/8/17

25/6/18 @ 8.55am

confirmed with Keong is \$22400, 16 days by email.

Cred \$11501.12, 2472r



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17018719/T1qb

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 29-09-2017



Code : FCI2

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SHB 6357B	Veh. Inspected	SLP 492L
Policy No.		Coverage (\$)	0.00
Claim No.	D17009249MFSH	Excess (\$)	0.00
Assign From	CWS ( JOANNEY YONG)	Assign Date	29/09/2017

**2. Vehicle Particulars & Condition**

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

**4. Description of Damages**

--

**5. General Information**

Accident Date	27/09/2017	Inspection Date	29/09/2017
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

# First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C  
GST Reg. No. M2-0001676-9

## MOTOR SURVEY ASSIGNMENT

<b>Date</b>	28-09-2017	<b>Our Ref No.</b> D17009249MFSH
<b>Accident Date</b>	27-09-2017	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHB6357B	<b>Third Party Vehicle.</b> SLP492L
<b>Survey Location</b>	BLOCK 1008 BUKIT MERAH LANE 3 #01-04/06/08	
<b>Contact Person.</b>	ERIC KI	
<b>Contact No.</b>	62723892/ 0	<b>Fax No.</b> 62721527
<b>Survey Type</b>	WITHOUT PREJUDICE:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

## FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

<b>Cc : Workshop</b>	MOVA AUTOMOTIVE PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	JOANNEY	

## IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/228572)



PRI Documents



Close



## PRI Header Details

Claim No	D17009249MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & MOVA AUT
Workshop Name	MOVA AUTOMOTIVE PTE LTD (Contact Person : ERIC KI)	Survey Location & Contact Details	BLOCK 1008 BUKIT MERAH LANE 3 #01-04/06/08 Mobile: 0 , Phone: 62723892 , Fax: 62721527 EmailId: ERIC@MOVA.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHB6357B	TP Vehicle No	SLP492L
PRI Recieved Date	28-09-2017 09:44:40 PM	Surveyor Appointed Date	29-09-2017 03:04:57 PM	Surveyor Accept Date	29-09-2017 0.

## Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	29-09-2017	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	----------------------	----------------------	------------	-------------------------	--

## Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks

## Shiau Chan (LKKAUTO)

---

**From:** Keong <keong@mov.com.sg>  
**Sent:** Monday, 25 June 2018 8:53 AM  
**To:** Shiau Chan (LKKAUTO)  
**Cc:** SUR; Taufikh (LKKAUTO); 'Enny'; 'Suann'; 'Vivian'  
**Subject:** RE: SLP492L Ready For Finalise \*LKK REF CS/FCI17018719/T1qb

Dear Shiau Chan  
Confirmed ,Thanks

Best Regards,  
Goh Chai Hock (Keong)  
Estimator  
Mova Automotive Pte Ltd  
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

---

**From:** Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]  
**Sent:** Thursday, 21 June 2018 3:51 PM  
**To:** Keong  
**Cc:** SUR; Taufikh (LKKAUTO)  
**Subject:** RE: SLP492L Ready For Finalise \*LKK REF CS/FCI17018719/T1qb

Dear Keong,

Offer Lump Sum \$22,400 before GST and 16 repair days.

Kindly confirm.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Hsiao Tong (LKKAUTO)  
**Sent:** Wednesday, 13 June 2018 12:40 PM  
**To:** Keong <keong@mov.com.sg>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Taufikh (LKKAUTO) <[Taufikh@lkkauto.com](mailto:Taufikh@lkkauto.com)>  
**Subject:** FW: SLP492L Ready For Finalise \*LKK REF CS/FCI17018719/T1qb

Without Prejudice

Hi Keong,

Contents noted.

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Monday, 2 October, 2017 4:10 PM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D17009249MFSH/1  
**Attachments:** CSFCI17018719T1qb.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SLP 492L.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Friday, 29 September, 2017 3:21 PM  
**To:** 'Claim Workflow System' <[cwsmotorclaims@first-insurance.com.sg](mailto:cwsmotorclaims@first-insurance.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D17009249MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]  
**Sent:** Friday, 29 September, 2017 3:05 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG](mailto:CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG); [JOANNEYONG@FIRST-INSURANCE.COM.SG](mailto:JOANNEYONG@FIRST-INSURANCE.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D17009249MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17009249MFSH  
Our Ref: CS/FCI17018719/T1qb

Date: 02 October 2017

The Motor Claims Department  
First Capital Insurance Ltd


Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SLP 492L .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 29/09/2017 at the premises of M/s MOVA, and have the following to report:-

Workshop Estimate Amount	: S\$ 33,901.12 .
Revised Estimate Amount	: S\$ 21,442.00 .
"Check" Items Amount	: S\$ 9,792.72 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:  
The vehicle sustained damages  
at the front & rear portion.



Yours faithfully

Taufikh  
Automotive Assessor



Text size + -

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 1240Z

Vehicle Details

Vehicle No.: SLP492L  
Vehicle to be Exported: No  
Intended De-registration Date: 02 Oct 2017  
Vehicle Make: MAZDA  
Vehicle Model: MAZDA2 5-DOOR HATCHBACK 1.5L SP.6EAT  
Primary Colour: Pink  
Manufacturing Year: 2015  
Engine No.: P520342268  
Chassis No.: JM6DJ2HAA01100754  
Maximum Power Output: 85.0 kW (113 bhp)  
Open Market Value: \$16,198.00  
Original Registration Date: 28 Jan 2016  
First Registration Date: 28 Jan 2016  
Transfer Count: 1  
Actual ARF Paid: \$6,198.00

Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 27 Jan 2026  
PARF Rebate Amount: \$4,648.00

Intended COE Rebate Details

COE Expiry Date: 27 Jan 2026  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$51,301.00  
COE Rebate Amount: \$42,668.00  
Total Rebate Amount: \$47,316.00

The information contained herein is correct as at 02 Oct 2017

OK



Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).  
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.  
Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution  
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)  
Last updated on 17 Sep 2017 at 12:38 AM

Cheap Car Insurance Renewal

Is your car insurance expiring soon?  
Receive best quotations from multiple insurers in as little as 2 hours.

Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

March 2010 Hyundai Santa FE Special Offer At \$44,800



In House Finance & Low  
Monthly Available! Low Mlg  
Done! Well Maintain, Low Depre  
Speedo Motoring StarAd



Browse by Category

Sort by Da

3 vehicles

mazda 2

Advanced S

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
Search Selection	mazda 2		Any	Any	2016	Any	Any
	Mazda 2 1.5A HB (OPC)		\$64,800	\$7,510 /yr	15-Jan-2016	1,496 cc	7,700
3 Years Warranty And All Times Free Serviced And Maintained By Agent, Hardly Use, Very Low Mileage Only! Mazda Connect Low Down Payment, Bank/In House Loan Available, Lowest Down ...							
Carway							
Posted: 28-Sep-2017 Tags: 2016 Mazda 2, 2016 Mazda 2, Mazda 2, Mazda 2, Mazda, 2, 2, Used Mazda							
	Mazda 2 1.5A HB (OPC)		\$60,000	\$6,400 /yr	28-Jul-2016	1,496 cc	13,000
1 Driver, Relocating, Original Bodykit, Seldom Driven. Negotiable.							
Posted: 20-Sep-2017 Tags: 2016 Mazda 2, 2016 Mazda 2, Mazda 2, Mazda 2, Mazda, 2, 2, Used Mazda							
	Mazda 2 SP 1.5A		\$76,800	\$8,410 /yr	22-Apr-2016	1,496 cc	10,269
Viewing Strictly By Appointment Only. 3 Years Warranty And All Times Serviced And Maintained By Agent. Hardly Use, Very L 10269Km.Still Free 2 Years Servicing And Up To 60000km Whicheve...							
Posted: 30-Jul-2017 Tags: 2016 Mazda 2, 2016 Mazda 2, Mazda 2, Mazda 2, Mazda, 2, 2, Used Mazda							

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage

For old advertisements, view Expired ads

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, to stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & 2 Singapore, used mazda 2 Singapore, used mazda 2, used vehicles Singapore or even buy used mazda 2 Singapore. We have new car dealers comprising parallel i dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, massage servic discussion, forum discussion, commercial vehicle leasing & COE results.

Compare

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	27/09/2017 08:55
Date Of Accident	27/09/2017 08:10
Exact Location Of Accident	ECP
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLP492L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	RYAN JOSEPH TAN YAO WEI
NRIC No	S9111240Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98212292
Alternative Phone No	OFFICE-NOPHONE
<b>Vehicle Particulars</b>	
Manufacturer	MAZDA
Model	MAZDA2 5-DOOR HATCHBACK 1.5L SP.6EAT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	ETIQA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	M0008720
Cover Note Number	
<b>Driver</b>	
Name of Driver	VANESSA JOSEPHINE TAN SHU FEN
NRIC No	S9308634A
Date Of Birth	08/03/1993
Occupation	INDOOR
Date Of Driving Pass	30/09/2014
Driving Experience	2 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97875995
Fax Number	
Contact Number	
Email Address	VANESSAJOSEPHINETAN@GMAIL.COM

Address  
Postcode  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured RELATIVE  
Vehicle Registration Number of Driver's Own Vehicle -  
-  
-  
Insurance Company of Driver's Own Vehicle -  
-  
-

#### General Information of the Accident

Type Of Accident CHAIN COLLISION  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Was any body injured in the Accident? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? YES  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHB6357B  
Vehicle Make/Model/Colour  
Details Of Properties  
Name of Driver KOH CHYE HEE  
NRIC/Passport Number S7346140E  
Contact Number 97381861  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### Details of Witness

Name  
Phone Number  
Email Address

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SCX4886S  
Vehicle Make/Model/Colour

• Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**Details of Witness**

Name

Phone Number

Email Address

## Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

#### Sketch Plan



**Sketch Plan Pg. 2**

Describe Circumstances of the Accident	LICENSE PLATE NUMBER: SL492 L
ACCIDENT DATE: 27 September 2017	CONTACT NUMBER: 97875995
ACCIDENT TIME: 8:11 AM	EMAIL: -
LOCATION: ECP	
<p><del>Travelling along ECP, car in front car taxi hit my back and I hit the car in front of me.</del></p> <p>I was travelling on the ECP, and a white taxi car from the back behind me came and hit me by the back. The impact was hard and it pushed my car forward, hitting the car in front of me. We pulled to the road shoulder immediately and swapped particulars and took photos.</p>	
<p>NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY.</p> <p>PLEASE CHECK YOUR POLICY FOR MORE INFORMATION.</p>	
Please state:	
<input type="checkbox"/> Claim Own Policy <input checked="" type="checkbox"/> Claim Third Party <input type="checkbox"/> Claim OD/TP at other workshop <input type="checkbox"/> Reporting Only	

## Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &  
Time

Driver's Signature (If driver is not the policyholder) / Date  
& Time

Witnessed by Reporting Centre  
Personnel

**Main Office:**

Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel : (65) 6476 3333  
Fax : (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**

Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722

Tel : (65) 6272 3892  
Fax : (65) 6270 8314

Co. Reg. 198904033G  
GST Reg. M2-0088864-2

# Estimate

27/09/2017

**FIRST CAPITAL INSURANCE LTD**  
**36 Robinson Road**  
**#16-01 City House**  
**Singapore 068877.**

Attention :- **XA026**

Page # :- 1

Veh # :- SLP492L

Veh Model :- MAZDA2

Estimate# :- CK416447

Claim # :-

ACC. Date :- 27/09/17

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
<b>LIST ITEMS :</b>				
1.	REAR BOOT	1 PC	1,321.70	1,321.70
2.	REAR BOOT LOGO	1 PC	75.80	75.80
3.	REAR BOOT EMBLEM 'MAZDA2'	1 PC	86.40	86.40
4.	REAR BOOT EMBLEM 'SKYACTIVE'	1 PC	89.60	89.60
5.	REAR BOOT WINDSCREEN MOULDING	1 PC	171.20	171.20
6.	REAR BOOT LOCK	1 PC	289.60	289.60
7.	REAR BOOT CATCH	1 PC	46.70	46.70
8.	REAR BOOT RUBBER	1 PC	190.20	190.20
9.	REAR BOOT PUSH BUTTON	1 PC	171.30	171.30
10.	REAR BOOT INNER HANDLE	1 PC	81.60	81.60
11.	REAR BOOT INNER TRIM CLIP	10 PC	5.80	58.00
12.	REAR BOOT WIPER MOTOR	1 PC	398.60	398.60
13.	REAR BOOT HINGES LH	1 PC	38.40	38.40
14.	REAR BOOT HINGES RH	1 PC	38.40	38.40
15.	REAR BOOT LAMP LH	1 PC	281.40	281.40
16.	REAR BOOT LAMP RH	1 PC	281.40	281.40
17.	TAILLAMP LH	1 PC	788.60	788.60
18.	TAILLAMP RH	1 PC	788.60	788.60
19.	TAILLAMP CLIP LH	1 PC	9.20	9.20
20.	TAILLAMP CLIP RH	1 PC	9.20	9.20
21.	TAILLAMP PANEL LH	1 PC	295.10	295.10
22.	REAR PANEL OUTER	1 PC	592.60	592.60
23.	REAR PANEL INNER	1 PC	382.80	382.80
24.	REAR PANEL INNER TRIM	1 PC	174.30	174.30
25.	REAR PANEL INNER TRIM CLIP	6 PC	5.80	34.80
26.	SPARE TYRE BOARD	1 PC	371.40	371.40
27.	SPARE TYRE PANEL	1 PC	1,183.60	1,183.60
28.	SPARE TYRE UNDER COVER	1 PC	103.70	103.70
29.	REAR TOOL TRAY	1 PC	286.40	286.40
30.	REAR BUMPER	1 PC	962.10	962.10
31.	REAR BUMPER SPONGE — photo	1 PC	78.30	78.30
32.	REAR BUMPER REINFORCEMENT — photo	1 PC	379.60	379.60
33.	REAR BUMPER BRACKET LH	1 PC	44.30	44.30
34.	REAR BUMPER BRACKET RH	1 PC	44.30	44.30
35.	REAR BUMPER SIDE BRACKET LH	1 PC	48.20	48.20
36.	REAR BUMPER SIDE BRACKET RH	1 PC	48.20	48.20
37.	REAR BUMPER SIDE RETAINER LH	1 PC	39.60	39.60
38.	REAR BUMPER SIDE RETAINER RH	1 PC	39.60	39.60
39.	REAR BUMPER CLIP	10 PC	5.60	56.00
40.	REAR BUMPER NUMBER PLATE LAMP LH	1 PC	83.90	83.90
41.	REAR BUMPER NUMBER PLATE LAMP RH	1 PC	83.90	83.90
42.	REAR BUMPER CAMERA	1 PC	895.60	895.60
43.	REAR BUMPER BRACKET CENTRE	1 PC	90.70	90.70
44.	REAR FENDER INNER TRIM	2 PC	321.60	643.20
45.	REAR FENDER INNER TRIM CLIP	10 PC	6.80	68.00
46.	REAR FENDER INNER TRIM TOP LH	1 PC	168.70	168.70
47.	REAR FENDER AIR VENT LH	1 PC	114.60	114.60
48.	REAR EXHAUST PIPE — photo	1 PC	1,053.60	1,053.60
49.	REAR EXHAUST REPAIR KIT	1 PC	55.10	55.10
50.	REAR EXHAUST MOUNTING	1 PC	42.10	42.10
51.	REAR EXHAUST HEAT SHIELD	1 PC	153.60	153.60



**Main Office:**

Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel : **(65) 6476 3333**  
Fax : (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**

Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722  
Tel : **(65) 6272 3892**  
Fax : (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-008864-2

# Estimate

27/09/2017

**FIRST CAPITAL INSURANCE LTD**  
**36 Robinson Road**  
**#16-01 City House**  
**Singapore 068877.**

Attention :- **XA026**

Page # :- 1 129494

Veh # :- SLP492L

Veh Model :- MAZDA2

Estimate# :- CK416447

Claim # :-

ACC. Date :- 27/09/17

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
52.	CENTRE EXHAUST PIPE	1 PC	1,151.70	1,151.70 <i>bt</i>
53.	CENTRE EXHAUST HEAT SHIELD	1 PC	171.20	171.20 <i>bt</i>
54.	REAR SHOCK ABSORBER LH	1 PC	267.10	267.10 <i>bt</i>
55.	REAR AXLE BEAM	1 PC	2,450.30	2,450.30 <i>bt</i>
56.	BONNET	1 PC	820.10	820.10 <i>bt</i>
57.	BONNET LOCK	1 PC	170.60	170.60 <i>bt</i>
58.	BONNET HINGES LH	1 PC	64.70	64.70 <i>bt</i>
59.	BONNET HINGES RH	1 PC	64.70	64.70 <i>bt</i>
60.	BONNET RUBBER	2 PC	117.20	234.40 <i>bt</i>
61.	FRONT HEADLAMP LH	1 PC	2,896.60	2,896.60 <i>bt</i>
62.	FRONT HEADLAMP RH	1 PC	2,893.60	2,893.60 <i>bt</i>
63.	HEADLAMP LOWER BRACKET LH	1 PC	43.20	43.20 <i>bt</i>
64.	HEADLAMP LOWER BRACKET RH	1 PC	43.20	43.20 <i>bt</i>
65.	SUPPORT PANEL	1 PC	395.10	395.10 <i>bt</i>
66.	SUPPORT PANEL SIDE COVER LH	1 PC	38.60	38.60 <i>bt</i>
67.	SUPPORT PANEL SIDE COVER RH	1 PC	38.60	38.60 <i>bt</i>
68.	SUPPORT PANEL TOP COVER	1 PC	139.70	139.70 <i>bt</i>
69.	SUPPORT PANEL TOP COVER CLIP	10 PC	5.90	59.00 <i>bt</i>
70.	BRACE PANEL	1 PC	143.10	143.10 <i>bt</i>
71.	FRONT BUMPER	1 PC	893.70	893.70 <i>bt</i>
72.	FRONT BUMPER TOP COVER	1 PC	182.10	182.10 <i>bt</i>
73.	FRONT BUMPER CLIP	10 PC	4.80	48.00 <i>bt</i>
74.	FRONT BUMPER LOGO	1 PC	34.60	34.60 <i>bt</i>
75.	FRONT BUMPER BEAM TOP	1 PC	91.70	91.70 <i>bt</i>
76.	FRONT BUMPER CLIP LH GRAY	1 PC	10.60	10.60 <i>bt</i>
77.	FRONT BUMPER CLIP RH GRAY	1 PC	10.60	10.60 <i>bt</i>
78.	FRONT BUMPER CHROME LH	1 PC	185.70	185.70 <i>bt</i>
79.	FRONT BUMPER CHROME RH	1 PC	185.70	185.70 <i>bt</i>
80.	FRONT BUMPER SPONGE	1 PC	171.10	171.10 <i>bt</i>
81.	FRONT BUMPER REINFORCEMENT	1 PC	500.80	500.80 <i>bt</i>
82.	FRONT BUMPER BRACKET LH	1 PC	49.70	49.70 <i>bt</i>
83.	FRONT BUMPER BRACKET RH	1 PC	49.70	49.70 <i>bt</i>
84.	FRONT BUMPER SIDE BRACKET LH	1 PC	54.60	54.60 <i>bt</i>
85.	FRONT BUMPER SIDE BRACKET RH	1 PC	54.60	54.60 <i>bt</i>
86.	FRONT GRILLE	1 PC	393.60	393.60 <i>bt</i>
87.	FRONT GRILLE GARNISH	1 PC	96.50	96.50 <i>bt</i>
88.	A/C CONDENSER	1 PC	803.10	803.10 <i>bt</i>
89.	RADIATOR	1 PC	1,490.70	1,490.70 <i>bt</i>
LIST TOTAL S\$				31,226.40
20% DISCOUNT S\$				-6,245.28
				24,981.12

**SPECIAL NET ITEMS :**

1.	REAR BOOT WINDSCREEN SEALANT	1 PC	80.00	80.00 <i>bt</i>
2.	SPARE TYRE PANEL SEALANT	1 PC	200.00	200.00 <i>bt</i>
3.	TRIANGLE PLATE	1 PC	100.00	100.00 <i>bt</i>
4.	REAR BUMPER SENSOR	1 PC	250.00	250.00 <i>bt</i>
5.	FRONT NUMBER PLATE	1 PC	50.00	50.00 <i>bt</i>
6.	REAR NUMBER PLATE	1 PC	50.00	50.00 <i>bt</i>

**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel : (65) 6476 3333  
Fax : (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722  
Tel : (65) 6272 3892  
Fax : (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-008864-2

# Estimate

27/09/2017

**FIRST CAPITAL INSURANCE LTD**  
**36 Robinson Road**  
**#16-01 City House**  
**Singapore 068877.**

Attention :- XA026

Page # :- 1 129494  
Veh # :- SLP492L  
Veh Model :- MAZDA2  
Estimate# :- CK416447  
Claim # :-  
ACC. Date :- 27/09/17  
Terms :- C.O.D Days  
Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	SPECIAL NET TOTAL S\$			730.00
	LABOUR :			
	TOWING CHARGE			80.00
	TO CUT/WELD REAR PANEL, REAR FLOOR PANEL, REAR CHASSIS MEMBER, TO REPAIR REAR FENDER LH & RH, REAR CHASSIS MEMBER, FRONT FENDER LH & RH, FRONT DOOR LH, REAR DOOR LH, TO REMOVE AND REFIX DAMAGED PARTS, STRAIGHTEN AND REALIGN AFFECTED AREA		2000.	2,500.00
	TO SPRAY AFFECTED AREA		1800	2,000.00
	TO REMOVE AND REFIX REAR BOOT MECHANISM, CHECK AND TEST WIPER MOTOR AND CENTRE LOCKING SYSTEM		50.	100.00
	TO REMOVE AND REFIX REAR WINDSCREEN GLASS		120.	180.00
	TO REMOVE & REFIX REAR LUGGAGE COMPARTMENT, SIDE COVER, SIDE GARNISH, CARPET AND OTHER ATTACHMENT PARTS		60.	120.00
	TO REMOVE & REFIX REAR CUSHION, REAR SAFETY BELT AND OTHER ATTACHMENT PARTS		80.	150.00
	TO REMOVE AND REFIX REAR EXHAUST PIPE CENTRE EXHAUST PIPE AND HEAT SHIELD		80.	100.00
	TO REMOVE AND REFIX FUEL TANK		photo? Xnn	80.00
	TO REMOVE AND REFIX REAR SHOCK ABSORBER REAR AXLE BEAM AND OTHER ATTACHMENT PARTS		photo 120?	250.00
	TO REMOVE AND REFIX A/C CONDENSER RADIATOR AND ATTACHMENT PARTS		120.	150.00
	TO RUST PROOF AFFECTED AREA		100.	180.00
	SUPPLY LABOUR AND MATERIAL (WRAP CAR BODY STICKER)		1000.	1,500.00
	TO CHECK WHEEL ALIGNMENT		80.	100.00
	TO CHECK BODY STRUCTURE AND CHASSIS ALIGNMENT (USE LASER LOCK SYSTEM)		photo & Report Xnn	400 500.00
	TO CHECK ABS, SRS, SYSTEM		100	200.00

**Main Office:**

Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel : **(65) 6476 3333**  
Fax : (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**

Block 1008  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722  
Tel : **(65) 6272 3892**  
Fax : (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0088864-2

# Estimate

27/09/2017

**FIRST CAPITAL INSURANCE LTD**  
**36 Robinson Road**  
**#16-01 City House**  
**Singapore 068877.**

Attention :- **XA026**

Page # :- 1 129494

Veh # :- SLP492L

Veh Model :- MAZDA2

Estimate# :- CK416447

Claim # :-

ACC. Date :- 27/09/17

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	LABOUR TOTAL S\$			8,190.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 33,901.12

GST @ 7 % 2,373.08

AMOUNT DUE S\$ 36,274.20

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Tan Guan 97495744  
'wp'  
29/9/17 C 1144  
To check p/p or L/S  
To resurvey before or after paint.  
16 days.  
Snr @ LKKauto.com

**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722

Tel: (65) 6272 3892  
Fax: (65) 6270 8314

Co. Reg. 198904033G  
GST Reg. M2-0088864-2

## Estimate

27/09/2017

**FIRST CAPITAL INSURANCE LTD**  
36 Robinson Road  
#16-01 City House  
Singapore 068877.

Attention :- XA026

Page # :- 1

Veh # :- SLP492L

Veh Model :- MAZDA2

Estimate# :- CK416447


Claim # :-

ACC. Date :- 27/09/17

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BOOT	1 PC	1,321.70	1,321.70 ✓
2.	REAR BOOT LOGO	1 PC	75.80	75.80 ✓
3.	REAR BOOT EMBLEM 'MAZDA2'	1 PC	86.40	86.40 ✓
4.	REAR BOOT EMBLEM 'SKYACTIVE'	1 PC	89.60	89.60 ✓
5.	REAR BOOT WINDSCREEN MOULDING	1 PC	171.20	171.20 ✓
6.	REAR BOOT LOCK	1 PC	289.60	289.60 ✓
7.	REAR BOOT CATCH	1 PC	46.70	46.70 ✓
8.	REAR BOOT RUBBER	1 PC	190.20	190.20 ✓
9.	REAR BOOT PUSH BUTTON	1 PC	171.30	171.30 ✓
10.	REAR BOOT INNER HANDLE	1 PC	81.60	81.60 ✓
11.	REAR BOOT INNER TRIM CLIP	10 PC	5.80	58.00 ✓
12.	REAR BOOT WIPER MOTOR	1 PC	398.60	398.60 X
13.	REAR BOOT HINGES LH	1 PC	38.40	38.40 X
14.	REAR BOOT HINGES RH	1 PC	38.40	38.40 X
15.	REAR BOOT LAMP LH	1 PC	281.40	281.40 ✓
16.	REAR BOOT LAMP RH	1 PC	281.40	281.40 ✓
17.	TAILLAMP LH	1 PC	788.60	788.60 ✓
18.	TAILLAMP RH	1 PC	788.60	788.60 ✓
19.	TAILLAMP CLIP LH	1 PC	9.20	9.20 ✓
20.	TAILLAMP CLIP RH	1 PC	9.20	9.20 ✓
21.	TAILLAMP PANEL LH	1 PC	295.10	295.10 X
22.	REAR PANEL OUTER	1 PC	592.80	592.80 ✓
23.	REAR PANEL INNER	1 PC	382.80	382.80 ✓
24.	REAR PANEL INNER TRIM	1 PC	174.30	174.30 ✓
25.	REAR PANEL INNER TRIM CLIP	6 PC	5.80	34.80 ✓
26.	SPARE TYRE BOARD	1 PC	371.40	371.40 ✓
27.	SPARE TYRE PANEL	1 PC	1,183.60	1,183.60 ✓
28.	SPARE TYRE UNDER COVER	1 PC	103.70	103.70 ✓
29.	REAR TOOL TRAY	1 PC	286.40	286.40 ✓
30.	REAR BUMPER	1 PC	962.10	962.10 ✓
31.	REAR BUMPER SPONGE — photo	1 PC	78.30	78.30 ✓
32.	REAR BUMPER REINFORCEMENT — photo	1 PC	379.60	379.60 ✓
33.	REAR BUMPER BRACKET LH	1 PC	44.30	44.30 ✓
34.	REAR BUMPER BRACKET RH	1 PC	44.30	44.30 ✓
35.	REAR BUMPER SIDE BRACKET LH	1 PC	48.20	48.20 ✓
36.	REAR BUMPER SIDE BRACKET RH	1 PC	48.20	48.20 ✓
37.	REAR BUMPER SIDE RETAINER LH	1 PC	39.60	39.60 ✓
38.	REAR BUMPER SIDE RETAINER RH	1 PC	39.60	39.60 ✓
39.	REAR BUMPER CLIP	10 PC	5.60	56.00 ✓
40.	REAR BUMPER NUMBER PLATE LAMP LH	1 PC	83.90	83.90 ✓
41.	REAR BUMPER NUMBER PLATE LAMP RH	1 PC	83.90	83.90 ✓
42.	REAR BUMPER CAMERA	1 PC	895.60	895.60 ✓
43.	REAR BUMPER BRACKET CENTRE	1 PC	90.70	90.70 ✓
44.	REAR FENDER INNER TRIM	2 PC	321.60	643.20 ✓
45.	REAR FENDER INNER TRIM CLIP	10 PC	6.80	68.00 ✓
46.	REAR FENDER INNER TRIM TOP LH	1 PC	168.70	168.70 ✓
47.	REAR FENDER AIR VENT LH	1 PC	114.60	114.60 ✓
48.	REAR EXHAUST PIPE — photo	1 PC	1,053.60	1,053.60 ✓
49.	REAR EXHAUST REPAIR KIT	1 PC	55.10	55.10 ✓
50.	REAR EXHAUST MOUNTING	1 PC	42.10	42.10 X
51.	REAR EXHAUST HEAT SHIELD	1 PC	153.60	153.60 X



Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel : (65) 6476 3333  
Fax : (65) 6271 5891  
[www.mova.com.sg](http://www.mova.com.sg)

Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722

Tel : (65) 6272 3892  
Fax : (65) 6270 8314

Co. Reg. 198904033G  
GST Reg. M2-0088864-2

27/09/2017

**Singapore 068877.**

Page # :- 1 129494

Veh # :- SLP492L

Veh Model :- MAZDA2

Estimate# :- CK416447

Claim # :-

ACC. Date :- 27/09/17

Terms :- C.O.D Days

Remarks :-

Attention :- XA026

No.	Description	Qty	U.Price	Amounts S\$
52.	CENTRE EXHAUST PIPE	1 PC	1,151.70	1,151.70 ✓
53.	CENTRE EXHAUST HEAT SHIELD	1 PC	171.20	171.20 ✓
54.	REAR SHOCK ABSORBER LH	1 PC	267.10	267.10 ✓
55.	REAR AXLE BEAM	1 PC	2,450.30	2,450.30 ✓
56.	BONNET	1 PC	820.10	820.10 ✓
57.	BONNET LOCK	1 PC	170.60	170.60 ✓
58.	BONNET HINGES LH	1 PC	64.70	64.70 ✓
59.	BONNET HINGES RH	1 PC	64.70	64.70 ✓
60.	BONNET RUBBER	2 PC	117.20	234.40 ✓
61.	FRONT HEADLAMP LH	1 PC	2,896.60	2,896.60 ✓
62.	FRONT HEADLAMP RH	1 PC	2,893.60	2,893.60 ✓
63.	HEADLAMP LOWER BRACKET LH	1 PC	43.20	43.20 ✓
64.	HEADLAMP LOWER BRACKET RH	1 PC	43.20	43.20 ✓
65.	SUPPORT PANEL	1 PC	395.10	395.10 ✓
66.	SUPPORT PANEL SIDE COVER LH	1 PC	38.60	38.60 X
67.	SUPPORT PANEL SIDE COVER RH	1 PC	38.60	38.60 X
68.	SUPPORT PANEL TOP COVER	1 PC	139.70	139.70 ✓
69.	SUPPORT PANEL TOP COVER CLIP	10 PC	5.90	59.00 ✓
70.	BRACE PANEL	1 PC	143.10	143.10 ✓
71.	FRONT BUMPER	1 PC	893.70	893.70 ✓
72.	FRONT BUMPER TOP COVER	1 PC	182.10	182.10 ✓
73.	FRONT BUMPER CLIP	10 PC	4.80	48.00 ✓
74.	FRONT BUMPER LOGO	1 PC	34.60	34.60 ✓
75.	FRONT BUMPER BEAM TOP	1 PC	91.70	91.70 ✓
76.	FRONT BUMPER CLIP LH GRAY	1 PC	10.60	10.60 ✓
77.	FRONT BUMPER CLIP RH GRAY	1 PC	10.60	10.60 ✓
78.	FRONT BUMPER CHROME LH	1 PC	185.70	185.70 ✓
79.	FRONT BUMPER CHROME RH	1 PC	185.70	185.70 ✓
80.	FRONT BUMPER SPONGE	1 PC	171.10	171.10 ✓
81.	FRONT BUMPER REINFORCEMENT	1 PC	500.80	500.80 ✓
82.	FRONT BUMPER BRACKET LH	1 PC	49.70	49.70 ✓
83.	FRONT BUMPER BRACKET RH	1 PC	49.70	49.70 ✓
84.	FRONT BUMPER SIDE BRACKET LH	1 PC	54.60	54.60 ✓
85.	FRONT BUMPER SIDE BRACKET RH	1 PC	54.60	54.60 ✓
86.	FRONT GRILLE	1 PC	393.60	393.60 ✓
87.	FRONT GRILLE GARNISH	1 PC	96.50	96.50 ✓
88.	A/C CONDENSER	1 PC	803.10	803.10 ✓
89.	RADIATOR	1 PC	1,490.70	1,490.70 ✓
	LIST TOTAL S\$			31,226.40
	20% DISCOUNT S\$			-6,245.28
				24,981.12
	SPECIAL NET ITEMS :			
1.	REAR BOOT WINDSCREEN SEALANT	1 PC	80.00	80.00 ✓
2.	SPARE TYRE PANEL SEALANT	1 PC	200.00	200.00 ✓
3.	TRIANGLE PLATE	1 PC	100.00	100.00 X
4.	REAR BUMPER SENSOR	1 PC	250.00	250.00 ✓
5.	FRONT NUMBER PLATE	1 PC	50.00	50.00 ✓
6.	REAR NUMBER PLATE	1 PC	50.00	50.00 ✓

**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: (65) 6478 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722

Tel: (65) 6272 3892  
Fax: (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0088864-2

Page # :- 1 129494

Veh # :- SLP492L

Veh Model :- MAZDA2

Estimate# :- CK416447

Claim # :-

ACC. Date :- 27/09/17

Terms :- C.O.D Days

Remarks :-

# Estimate

27/09/2017

**FIRST CAPITAL INSURANCE LTD**  
36 Robinson Road  
#16-01 City House  
Singapore 068877.

Attention :- XA026

No.	Description	Qty	U.Price	Amounts S\$
	SPECIAL NET TOTAL S\$		450	730.00
	LABOUR :			
	TOWING CHARGE		✓	80.00
	TO CUT/WELD REAR PANEL. REAR FLOOR PANEL, REAR CHASSIS MEMBER. TO REPAIR REAR FENDER LH & RH, REAR CHASSIS MEMBER, FRONT FENDER LH & RH, FRONT DOOR LH, REAR DOOR LH. TO REMOVE AND REFIX DAMAGED PARTS, STRAIGHTEN AND REALIGN AFFECTED AREA		2000.	2,500.00
	TO SPRAY AFFECTED AREA		1800	2,000.00
	TO REMOVE AND REFIX REAR BOOT MECHANISM. CHECK AND TEST WIPER MOTOR AND CENTRE LOCKING SYSTEM		50.	100.00
	TO REMOVE AND REFIX REAR WINDSCREEN GLASS		120.	180.00
	TO REMOVE & REFIX REAR LUGGAGE COMPARTMENT, SIDE COVER, SIDE GARNISH, CARPET AND OTHER ATTACHMENT PARTS		60.	120.00
	TO REMOVE & REFIX REAR CUSHION, REAR SAFETY BELT AND OTHER ATTACHMENT PARTS		80.	150.00
	TO REMOVE AND REFIX REAR EXHAUST PIPE CENTRE EXHAUST PIPE AND HEAT SHIELD		80.	100.00
	TO REMOVE AND REFIX FUEL TANK		photo. 7	80.00 X
	TO REMOVE AND REFIX REAR SHOCK ABSORBER REAR AXLE BEAM AND OTHER ATTACHMENT PARTS		✓ photo 120?	250.00
	TO REMOVE AND REFIX A/C CONDENSER RADIATOR AND ATTACHMENT PARTS		120.	150.00
	TO RUST PROOF AFFECTED AREA		100.	180.00
	SUPPLY LABOUR AND MATERIAL (WRAP CAR BODY STICKER)		1200.	1,500.00
	TO CHECK WHEEL ALIGNMENT		80.	100.00
	TO CHECK BODY STRUCTURE AND CHASSIS ALIGNMENT (USE LASER LOCK SYSTEM)		photo & Report. 7	400 500.00
	TO CHECK ABS, SRS, SYSTEM		100	200.00

# Estimate

27/09/2017

**FIRST CAPITAL INSURANCE LTD**  
36 Robinson Road  
#16-01 City House  
Singapore 068877.

Attention :- XA026

Page # :- 1 129494  
Veh # :- SLP492L  
Veh Model :- MAZDA2  
Estimate# :- CK416447  
Claim # :-  
ACC. Date :- 27/09/17  
Terms :- C.O.D Days  
Remarks :-

**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg  
**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722  
Tel: (65) 6272 3892  
Fax: (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
	LABOUR TOTAL S\$			8,190.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 33,901.12  
GST @ 7 % 2,373.08

AMOUNT DUE S\$ 36,274.20

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Tan Jiah 97495744  
wp  
22/9/17 C 1140  
To check p/p or L/S  
To return before or after print.  
16 days.  
See @ 11kanto.com




**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17018719/T1qbe2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 04-07-2018	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHB 6357B	Veh. Inspected	SLP 492L	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17009249MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	29/09/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MAZDA2	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JM6DJ2HAA01100754	Colour	BLACK	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/60 R16	TOYO	6 mm	
L/H Front Tyre	185/60 R16	TOYO	6 mm	
R/H Rear Tyre	185/60 R16	TOYO	6 mm	
L/H Rear Tyre	185/60 R16	TOYO	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	27/09/2017	Inspection Date	29/09/2017	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		16 Working Days		





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 492L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BOOT	BENT	1,321.70	1,321.70
1	REAR BOOT LOGO	NECESSARY	75.80	75.80
1	REAR BOOT EMBLEM 'MAZDA2'	NECESSARY	86.40	86.40
1	REAR BOOT EMBLEM 'SKYACTIVE'	NECESSARY	89.60	89.60
1	REAR BOOT WINDSCREEN MOULDING	NECESSARY	171.20	171.20
1	REAR BOOT LOCK	BENT	289.60	289.60
1	REAR BOOT CATCH	BENT	46.70	46.70
1	REAR BOOT RUBBER	TWISTED	190.20	190.20
1	REAR BOOT PUSH BUTTON	DISTORTED	171.30	171.30
1	REAR BOOT INNER HANDLE	DEFORMED	81.60	81.60
10	REAR BOOT INNER TRIM CLIP @\$5.80	NECESSARY	58.00	58.00
1	REAR BOOT WIPER MOTOR	NOT NECESSARY	398.60	-
1	REAR BOOT HINGES LH	TO REPAIR SEE LABOUR	38.40	-
1	REAR BOOT HINGES RH	TO REPAIR SEE LABOUR	38.40	-
1	REAR BOOT LAMP LH	CRACKED	281.40	281.40
1	REAR BOOT LAMP RH	CRACKED	281.40	281.40
1	TAILLAMP LH	CRACKED	788.60	788.60
1	TAILLAMP RH	CRACKED	788.60	788.60
1	TAILLAMP CLIP LH	NECESSARY	9.20	9.20
1	TAILLAMP CLIP RH	NECESSARY	9.20	9.20
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	295.10	-
1	REAR PANEL OUTER	BENT	592.60	592.60
1	REAR PANEL INNER	BENT	382.80	382.80
1	REAR PANEL INNER TRIM	DEFORMED	174.30	174.30
6	REAR PANEL INNER TRIM CLIP @\$5.80	NECESSARY	34.80	34.80
1	SPARE TYRE BOARD	DEFORMED	371.40	371.40
1	SPARE TYRE PANEL	BUCKLED	1,183.60	1,183.60
1	SPARE TYRE UNDER COVER	DEFORMED	103.70	103.70
1	REAR TOOL TRAY	CRACKED	286.40	286.40

Report Ref No. CS/FCI17018719/T1qbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER	DEFORMED	962.10	962.10
1	REAR BUMPER SPONGE	CRACKED	78.30	78.30
1	REAR BUMPER REINFORCEMENT	BENT	379.60	379.60
1	REAR BUMPER BRACKET LH	NECESSARY	44.30	44.30
1	REAR BUMPER BRACKET RH	NECESSARY	44.30	44.30
1	REAR BUMPER SIDE BRACKET LH	NECESSARY	48.20	48.20
1	REAR BUMPER SIDE BRACKET RH	NECESSARY	48.20	48.20
1	REAR BUMPER SIDE RETAINER LH	NECESSARY	39.60	39.60
1	REAR BUMPER SIDE RETAINER RH	NECESSARY	39.60	39.60
10	REAR BUMPER CLIP @\$5.60	NECESSARY	56.00	56.00
1	REAR BUMPER NUMBER PLATE LAMP LH	DISTORTED	83.90	83.90
1	REAR BUMPER NUMBER PLATE LAMP RH	DISTORTED	83.90	83.90
1	REAR BUMPER CAMERA	CRACKED	895.60	895.60
1	REAR BUMPER BRACKET CENTRE	DEFORMED	90.70	90.70
2	REAR FENDER INNER TRIM @\$321.60	DEFORMED	643.20	643.20
10	REAR FENDER INNER TRIM CLIP @\$6.80	NECESSARY	68.00	68.00
1	REAR FENDER INNER TRIM TOP LH	CUT	168.70	168.70
1	REAR FENDER AIR VENT LH	DEFORMED	114.60	114.60
1	REAR EXHAUST PIPE	BENT	1,053.60	1,053.60
1	REAR EXHAUST REPAIR KIT	NECESSARY	55.10	55.10
1	REAR EXHAUST MOUNTING	NOT NECESSARY	42.10	-
1	REAR EXHAUST HEAT SHIELD	NOT NECESSARY	153.60	-
1	CENTRE EXHAUST PIPE	BENT	1,151.70	1,151.70
1	CENTRE EXHAUST HEAT SHIELD	BENT	171.20	171.20
1	REAR SHOCK ABSORBER LH	NOT NECESSARY	267.10	-
1	REAR AXLE BEAM	NOT NECESSARY	2,450.30	-
1	BONNET	BENT	820.10	820.10
1	BONNET LOCK	BENT	170.60	170.60
1	BONNET HINGES LH	NOT NECESSARY	64.70	-
1	BONNET HINGES RH	NOT NECESSARY	64.70	-
2	BONNET RUBBER @\$117.20	CUT	234.40	234.40
1	FRONT HEADLAMP LH	CRACKED	2,896.60	2,896.60
1	FRONT HEADLAMP RH	CRACKED	2,893.60	2,893.60

Report Ref No. CS/FCI17018719/T1qbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HEADLAMP LOWER BRACKET LH	NECESSARY	43.20	43.20
1	HEADLAMP LOWER BRACKET RH	NECESSARY	43.20	43.20
1	SUPPORT PANEL	CRACKED	395.10	395.10
1	SUPPORT PANEL SIDE COVER LH	NOT NECESSARY	38.60	-
1	SUPPORT PANEL SIDE COVER RH	NOT NECESSARY	38.60	-
1	SUPPORT PANEL TOP COVER	CRACKED	139.70	139.70
10	SUPPORT PANEL TOP COVER CLIP @\$5.90	NECESSARY	59.00	59.00
1	BRACE PANEL	BENT	143.10	143.10
1	FRONT BUMPER	DEFORMED	893.70	893.70
1	FRONT BUMPER TOP COVER	DEFORMED	182.10	182.10
10	FRONT BUMPER CLIP @\$4.80	NECESSARY	48.00	48.00
1	FRONT BUMPER LOGO	CUT	34.60	34.60
1	FRONT BUMPER BEAM TOP	BENT	91.70	91.70
1	FRONT BUMPER CLIP LH GRAY	CRACKED	10.60	10.60
1	FRONT BUMPER CLIP RH GRAY	CRACKED	10.60	10.60
1	FRONT BUMPER CHROME LH	CRACKED	185.70	185.70
1	FRONT BUMPER CHROME RH	CRACKED	185.70	185.70
1	FRONT BUMPER SPONGE	DEFORMED	171.10	171.10
1	FRONT BUMPER REINFORCEMENT	BENT	500.80	500.80
1	FRONT BUMPER BRACKET LH	DEFORMED	49.70	49.70
1	FRONT BUMPER BRACKET RH	DEFORMED	49.70	49.70
1	FRONT BUMPER SIDE BRACKET LH	DEFORMED	54.60	54.60
1	FRONT BUMPER SIDE BRACKET RH	DEFORMED	54.60	54.60
1	FRONT GRILLE	CUT	393.60	393.60
1	FRONT GRILLE GARNISH	DEFORMED	96.50	96.50
1	A/C CONDENSER	BENT	803.10	803.10
1	RADIATOR	BENT	1,490.70	1,490.70
	LESS 20% DISCOUNT		-6,245.28	-5,467.24
			24,981.12	21,868.96
	<b>SPECIAL NETT ITEMS</b>			
1	REAR BOOT WINDSCREEN SEALANT (SN)	NECESSARY	80.00	60.00
1	SPARE TYRE PANEL SEALANT (SN)	NECESSARY	200.00	100.00
1	TRIANGLE PLATE (SN)	NOT NECESSARY	100.00	-

Report Ref No. CS/FCI17018719/T1qbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER SENSOR (SN)	NOT WORKING	250.00	200.00
1	FRONT NUMBER PLATE (SN)	CUT	50.00	45.00
1	REAR NUMBER PLARE (SN)	CRACKED	50.00	45.00
			730.00	450.00
	<b>LABOUR</b>			
	TOWING CHARGE.		80.00	80.00
	TO CUT/WELD REAR PANEL, REAR FLOOR PANEL, REAR CHASSIS MEMBER. TO REPAIR REAR FENDER LH & RH, REAR CHASSIS MEMBER, FRONT FENDER LH & RH, FRONT DOOR LH, REAR DOOR LH. TO REMOVE AND REFIX DAMAGED PARTS, STRAIGHTEN AND REALIGN AFFECTED AREA. INCLUSIVE OF THE REPAIR OF REAR BOOT HINGES LH, REAR BOOT HINGES RH AND TAILLAMP PANEL LH.		2,500.00	2,000.00
	TO SPRAY AFFECTED AREA.		2,000.00	1,800.00
	TO REMOVE AND REFIX REAR BOOT MECHANISM. CHECK AND TEST WIPER MOTOR AND CENTRE LOCKING SYSTEM.		100.00	50.00
	TO REMOVE AND REFIX REAR WINDSCREEN GLASS,		180.00	120.00
	TO REMOVE & REFIX REAR LUGGAGE COMPARTMENT, SIDE COVER, SIDE GARNISH, CARPET AND OTHER ATTACHMENT PARTS.		120.00	60.00
	TO REMOVE & REFIX REAR CUSHION, REAR SAFETY BELT AND OTHER ATTACHMENT PARTS.		150.00	80.00
	TO REMOVE AND REFIX REAR EXHAUST PIPE CENTRE EXHAUST PIPE AND HEAT SHIELD.		100.00	80.00
	TO REMOVE AND REFIX FUEL TANK.	NOT NECESSARY	80.00	-
	TO REMOVE AND REFIX REAR SHOCK ABSORBER REAR AXLE BEAM AND OTHER ATTACHMENT PARTS.		250.00	120.00
	TO REMOVE AND REFIX A/C CONDENSER RADIATOR AND ATTACHMENT PARTS.		150.00	120.00
	TO RUST PROOF AFFECTED AREA.		180.00	100.00
	SUPPLY LABOUR AND MATERIAL (WRAP CAR BODY STICKER)		1,500.00	1,000.00
	TO CHECK WHEEL ALIGNMENT.		100.00	80.00
	TO CHECK BODY STRUCTURE AND CHASSIS ALIGNMENT (USE LASER LOCK SYSTEM)	NOT NECESSARY	500.00	-

Report Ref No. CS/FCI17018719/T1qbe2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ABS, SRS, SYSTEM.		200.00	100.00
			8,190.00	5,790.00
GRAND TOTAL			33,901.12	28,108.96
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				22,400.00

Report Ref No. CS/FCI17018719/T1qbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.