

22/09/2002

ASS. REC. BY:

REF: CS/C7117018731/R1962

Special Instruction:

Supervisor
Mamman

Racul

ASSIGNMENT (Office)

From (Person):

Alfred Toh

of

C71

Date/Time:

29/9/17 10:57am

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 6602 R

Insured:

GBD1304 Y

at Workshop m/s

Kah Motor Co

Tel:

of

255 Alexandra Road

Policy No:

DMCVSN 3048041700

Claim No:

SNM17D0 5677 C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/09/2017

CA / REV / REP. / REV 24 HRS

'wpi'

2/10/2017

Date/Time:

29/9/17

11:56am

Person Contacted:

Mr Ng

H.O.D. Endorsement

Vehicle IN OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-------------------|--|
| | SLC 6602 R - X |
| | GBD 1304 Y - X |
| 08/6/18 @ 11:33am | Confirmed with Ng Sm Hain final fig to 1136.15, 10 days, used to 7729.69, 17%. |

Rasul

REF: CT1

63863

ASSIGNMENT

From _____ Date 02/10/17

Estimated Cost: _____

OD / ☒ PTWS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No SLC 6602 R

at Workshop no's Kah Motor

of 255 Alexandra Road

Insured _____

Policy No _____

Claims No _____

Sum Insured _____ Excess _____

(Client's Record)

Make of Veh _____

(Policy Condition) _____

Remark: The veh had commenced its repair at the time of inspection.

Bal or Market Value _____

IDAC Accident Rpt. _____ Consistent? Yes or No

GIA / PR Seen _____ Consistent? Yes or No

Est. Repairs _____ days Res. Yes or No

Lum Sum _____ % 3 Val Yes or No

CA / REV / REP. / 24 HRS wp

Date _____ Person Contacted _____

Date Time Action / Instruction

Veh No. SLC 6602 R Yr Regn 2016 / MAY

Type ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make Honda Jazz 1.5 VTR cc 1498

Colour BLUG A/C Insured / Std / NI / NA

Sp. Reading 021910 T. Radio Insured / Std / NI / NA

Eng No _____

C No JHMGK 5850 GX 20276K

Gen. Cond. Good / ☒ Fair / Poor / Burnt

Steering ☒ Inorder / Jammed / Leaked / Burnt or

Brake ☒ Inorder / Jammed / Leaked / Burnt or

Modi Nil / ☒ S/Rim / STD A/Rim or

Tyre Size F: 185/55R16 R: _____

BS ☒ DUM / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R. Bal 6 mm R. Bal 6 mm


L. Bal 6 mm L. Bal 6 mm

D.O.A. 28/09/17 D.O.I. 02/10/17

Survey held at KAH MOTOR

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision



[Signature]
8/6/2018

RECEIVED 08 JUN 2018

Date/Time File Pass to?

08/6/18

Date/Time File Return to?

☐

Preli. Report

☐

Final Report

Days Of Repair: 10

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Survey Fee

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

200

200

Report Format:

Lump Sum / I.B.I: (\$)

MER 7P

1136.15



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|---|---------------------------|------------|---|
| CHINA TAIPING INSURANCE (S) PTE LTD | | Ref : CS/CTI17018731/R1qb | | |
| 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909 | | Date : 29-09-2017 | |  |
| | | Code : CTI | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | GBD 1304Y | Veh. Inspected | SLC 6602R | |
| Policy No. | DMCVSN3048041700 | Coverage (\$) | 0.00 | |
| Claim No. | SNM17D05677C02 | Excess (\$) | 0.00 | |
| Assign From | MERIMEN (ALFRED TOH) | Assign Date | 29/09/2017 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | c.c | | 0 | |
| Engine No. | HIDDEN | Year of Reg. | | |
| Chassis No. | | Colour | | |
| Odometer | - | Steering | | |
| Brakes | | Modification | | |
| General | | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | | | mm | |
| L/H Front Tyre | | | mm | |
| R/H Rear Tyre | | | mm | |
| L/H Rear Tyre | | | mm | |
| 4. Description of Damages | | | | |
| | | | | |
| 5. General Information | | | | |
| Accident Date | 28/09/2017 | Inspection Date | 02/10/2017 | |
| Survey held at | KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937 | | | |
| 5a. Remarks | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |

12/03/2002

ASS. REC. BY:

REF: CS/C7117018731/R1262

Special Instruction:

Survivor
Mortgage

Recd

ASSIGNMENT (Office)

From (Person):

Alfred Toh

of

C71

Date/Time:

29/9/17 10:57am

Estimated Cost:

Bill to:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 6602 R

Insured:

GBD1304 Y

at Workshop m/s

Kah Motor Co

Tel:

of

255 Alexandra Road

Policy No:

DMCVSN 3048041700

Claim No:

SNM17D0 5677 C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/09/2017

CA / REV / REP. / REV 24 HRS

lwp

2/10/2017

Date/Time:

29/9/17

11:56am

Person Contacted:

Mr Ng

H.O.D. Endorsement

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction

☒

Estimate

SLC 6602 R - X

GBD 1304 Y - X

06/10/17 @ 11:33am Confirmed with Ng Sim Hui final fig to 11:36.15, 10 days,
 Ured to 7739.69, 17%.

Rasul

REF: CT1

63863

ASSIGNMENT

From _____ Date 02/10/17

Estimated Cost _____

OD / ☒ P / NS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No SLC 6602 R

at Workshop mis Kah Motor

of 255 Alexandra Road

Insured _____

Policy No _____

Claims No _____

Sum Insured _____ Excess _____

(Client's Record)

Make of Veh _____

(Policy Condition) _____

Remark: The veh had commenced its repair at the time of inspection.

Bal or Market Value _____

IDAC Accident Rpt. _____ Consistent? Yes or No

GIA PR Seen _____ Consistent? Yes or No

Est. Repairs _____ days Res. Yes or No

Lum Sum _____ % 3 Val Yes or No

CA / REV / REP. / 24 HRS wp

Date _____ Person Contacted _____

Date / Time _____ Action / Instruction _____

Vehicle: IN / OUT

Veh No SLC 6602 R Yr Regn 2016 / may

Type ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make HONDA JAZZ 1.5 VTIK cc 1498

Colour BLUG A C Insured / Std / NI / NA

Sp. Reading 021910 T Radio Insured / Std / NI / NA

Eng No _____

C No JHMGK 8850 G X 202 76K

Gen. Cond: Good / ☒ Poor / Burnt

Steering ☒ In order / Jammed / Leaked / Burnt or

Brake ☒ In order / Jammed / Leaked / Burnt or

Modi Nil / ☒ STD A/Rim or

Tyre Size F: 185/55R16

R: _____

BS ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R Bal 6 mm R Bal 6 mm


L Bal 6 mm L Bal 6 mm

D.O.A 28/09/17 D.O.I 02/10/17

Survey held at: KAH MOTOR

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision



[Signature]
8/6/2018

RECEIVED 08 JUN 2018

Date/Time File Pass to?

08/6/18

Date/Time File Return to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 10

Resurvey No. of Trip: 1

Survey Fee

Transportation

S + RS S

Photos

Others

TOTAL

200

200

Add Fee:

☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)
☐

Report Format:

Lump Sum / I.B.I. (\$)

WP 7P

11136.15



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|---|---------------------------|------------|---|
| CHINA TAIPING INSURANCE (S) PTE LTD | | Ref : CS/CTI17018731/R1qb | | |
| 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909 | | Date : 29-09-2017 | |  |
| | | Code : CTI | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | GBD 1304Y | Veh. Inspected | SLC 6602R | |
| Policy No. | DMCVSN3048041700 | Coverage (\$) | 0.00 | |
| Claim No. | SNM17D05677C02 | Excess (\$) | 0.00 | |
| Assign From | MERIMEN (ALFRED TOH) | Assign Date | 29/09/2017 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | c.c | | 0 | |
| Engine No. | HIDDEN | Year of Reg. | | |
| Chassis No. | Colour | | | |
| Odometer | - | Steering | | |
| Brakes | Modification | | | |
| General | | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | | | mm | |
| L/H Front Tyre | | | mm | |
| R/H Rear Tyre | | | mm | |
| L/H Rear Tyre | | | mm | |
| 4. Description of Damages | | | | |
| | | | | |
| 5. General Information | | | | |
| Accident Date | 28/09/2017 | Inspection Date | 02/10/2017 | |
| Survey held at | KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937 | | | |
| 5a. Remarks | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |

...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|---------|---------------|-------------|--|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 28 Sep 2017 | | 29 Sep 2017 10:57 Assign | | | | New Assignment Cancel Case |

| | | | | |
|------|-----------|---------------|-----------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|------|-----------|---------------|-----------|--------------------------|

CLAIM SUBFOLDER DETAILS [Created by insurer]

| | | | |
|-----------------------------|---|------------------------|------------------------|
| Insured: | M/S HARA HONG TIM SUM PTE LTD | | |
| Main Claimant: | TSANG WEN HAO FREDERICK | | |
| Vehicle Reg. No.: | SLC6602R | Date of Loss: | 28/09/2017 09:00 - :59 |
| Claim Type: | TP / SNM17D05677C02 | Policy/Cover Note No.: | DMCVSN3048041700 |
| Vehicle Reg. No. (Insured): | GBD1304Y | Policy No. (Claimant): | |
| | | Excess: | S\$0.00 |
| Repairer: | Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD, - Alexandra - Tel: | | |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Alfred Toh - 6389 6183] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/10/2017] | | |
| Adj Asg. Remarks: | PELASE SURVEY THIRD PARTY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS. OUR INSURED HAD NOT FILED SAS REPORT. | | |

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 8 June 2018 11:33 AM
To: 'Ng Sin Hai'; SUR
Subject: RE: Submission Pre-Invoice for vehicle SLC6602R

Dear Sin Hai,

Confirm final fig \$11,136.15 before GST and 10 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Sin Hai [mailto:shng@kahmotor.onmicrosoft.com]
Sent: Monday, 7 May 2018 11:38 AM
To: SUR <sur@lkkauto.com>
Subject: FW: Submission Pre-Invoice for vehicle SLC6602R

Dear All,

Attached is the pre-invoice

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai

Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

255 Alexandra Road

Singapore 159937

DID: 6471 5419

HP: 9072 1769

E-mail: shng@honda.com.sg



BLUE SKY FOR
OUR CHILDREN



Visit our
Facebook page

Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|--------------------------------------|
| Date Of Report | 28/09/2017 19:36 |
| Date Of Accident | 28/09/2017 09:15 |
| Exact Location Of Accident | MARIS STELLA PRIMARY SCHOOL COMPOUND |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|------------------------|
| Vehicle Registration Number | SLC6602R |
| Insured/Policyholder | |
| Name Of Registered Owner | TSANG WENHAO FREDERICK |
| NRIC No | S8206356J |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-96442254 |
| Alternative Phone No | OFFICE-96442254 |

Vehicle Particulars

| | |
|--|--------------|
| Manufacturer | HONDA |
| Model | JAZZ-1.5 (A) |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|---------------------------|
| Name of Insurance Company | LIBERTY INSURANCE PTE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | LOH YUN LEI HANNAH |
| NRIC No | S8606005A |
| Date Of Birth | 16/03/1986 |
| Occupation | INDOOR |
| Date Of Driving Pass | 20/04/2007 |
| Driving Experience | 10 YEARS AND 5 MONTHS |
| Gender | FEMALE |
| Mobile Number | (LOCAL) +65-96442254 |
| Fax Number | |
| Contact Number | OFFICE-96442254 |
| Email Address | NOEMAIL |

Address
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured SPOUSE
Vehicle Registration Number of Driver's Own Vehicle -
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD1304Y
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

Sketch Plan

Vehicle No SLC6602R

SKETCH PLAN

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
 8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

[Signature]

Witnessed by Reporting Centre Personnel

Sketch Plan



Please continue to Annex E

Vehicle No SLC6602R

Annex E


Describe Circumstances of the Accident

My vehicle A was parked stationary at the school compound. At around 0915 am the school operation manager called me and inform me that my vehicle A was damaged. When I reach my vehicle A, I ~~see~~ saw my vehicle A rear portion was damaged and vehicle B indicate to me that he was doing a 3 point turn and accidentally hit onto my vehicle A.

You had been advised by the workshop that in the event that you wish to claim against your own policy (OD claim), there is a fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

REPUBLIC OF SINGAPORE DRIVING LICENCE


 Licence Number: **S8606005A**
 Name: **LOH YUN LEI, HANNAH**
 Birth Date: **16 Mar 1986**
 Issue Date: **04 May 2007**

001497480B

REPUBLIC OF SINGAPORE DRIVING LICENCE


 Licence Number: **S8206356J**
 Name: **TSANG WENHAO, FREDERICK**
(ZENG WENHAO, FREDERICK)
 Birth Date: **21 Feb 1982**
 Issue Date: **14 May 2003**

000477552A

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

| Class | Description | PASS DATE |
|---------|--|-------------|
| Class 3 | Motor Cars $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of the driver; and other motor vehicles $\leq 2500\text{kg}$ | 20 Apr 2007 |

NP 428A

Licence No: S8606005A

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

| Class | Description | PASS DATE |
|---------|--|-------------|
| Class 3 | Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms | 13 May 2003 |

NP 428A

Licence No: S8206356J

Certificate of Insurance

Motor Vehicles (Third-Party Risks And Compensation) Act (Chapter 189); Motor Vehicles (Third-Party Risks And Compensation) Rules, 1960; Road Transport Act, 1987 (Malaysia); Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

| | | |
|--|---|--|
| Name of Policyholder: TSANG WENHAO, FREDERICK (ZENG WENHAO, FREDERICK) | | Certificate No.: SI17V07247/ VPC / R01 |
| Date of Issue: 26 Apr 2017 | Effective Date of Commencement: 20 May 2017 00:00 | Date of Expiry: 19 May 2018 23:59 |
| Registration No.: SLC6602R | Chassis No.: JHMGK5850GX202764 | Type of Certificate: MX1 |

Persons or Classes of Persons entitled to drive*:

A) The Policyholder.

B) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

Limitations as to use:

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover:

A) Use for hire or reward.


B) Use for racing, pace-making, reliability trials or speed-testing.

C) Use for the carriage of goods (other than samples) in connection with any trade or business.

D) Use for any purpose in connection with the Motor Trade.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).


For and on behalf of
LIBERTY INSURANCE PTE LTD
Approved Insurers

For Information Only:

| | |
|--------------------------|--|
| Coverage(s): | Comprehensive, Unlimited Windscreen |
| Sum Insured: | MARKET VALUE AT THE TIME OF LOSS |
| Excess: | Section I S\$600, Additional Excess for Young, Elderly & Inexperienced Drivers S\$3000, Windscreen Excess S\$100 |
| Name of Finance Company: | OVERSEA-CHINESE BANKING CORPORATION LTD |
| Name of Producer: | KAH MOTOR COMPANY SDN BERHAD (A1572-7) |

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

| | | | | | |
|------------------|---------------------------|--------------------|---------------------------|------|---|
| Customer | : CHINA TAIPING INSURANCE | Document No. | : SQT17004006 | Page | 1 |
| | 3 ANSON ROAD #16-00 | Date | : 28. Sep 2017 | | |
| | SPRINGLEAF TOWER | Customer No. | : WZC008 | | |
| | SINGAPORE 079909 | Svc Advisor | : | | |
| Registration No | : SLC6602R | Engine No | : L15B31021120 | | |
| Chassis No | : JHMGK5850GX202764 | Date Time | : 28. Sep 2017 1:20:10 PM | | |
| Model | : JAZZ 1.5VTIR CVT 16YM | Surveyor Name | : | | |
| Owner's Name | : TSANG WENHAO FREDERICK | Survey Date | : | | |
| Ins Policy No. | : | Authorisation Date | : | | |
| Date of Accident | : 28/9/2017 | | | | |

| Item | Description | Qty | Unit Price | Disc % | Amount | GST Amt | Amount incld GST |
|-----------------|--|-----|--------------------|--------|----------------|---------------|------------------|
| | TP DIRECT SETTLEMENT (J/NO:) OWNER:TSANG WENHAO FREDERICK OWNER INSURER:LIBERTY INSURANCE ACC DATE:28/09/2017 SURVEYED BY: DATE: REF NO: TP INSURER:CHINA TAIPING INSURANCE (S'PORE) PTE LT TP VEH:GBB1304Y | | | | | | |
| 04715-T5B-000ZZ | FACERR.BUMPER | 1 | 492.70 <i>20</i> | 25 | 369.52 | 25.87 | 395.39 |
| NMRS-4P-TM3040L | 4PCS ACT RR.SENSOR | 1 | 320.00 <i>an</i> | | 320.00 | 22.40 | 342.40 |
| 71507-T5A-000 | GARNISHL.RR.BUMPER | 1 | 6.30 <i>X an</i> | 25 | 4.72 | 0.33 | 5.05 |
| 71593-T5A-000 | SPACERR.RR.BUMPER | 1 | 11.50 <i>an</i> | 25 | 8.62 | 0.60 | 9.22 |
| 71598-T5A-000 | SPACERL.RR.BUMPER | 1 | 11.50 <i>an</i> | 25 | 8.62 | 0.60 | 9.22 |
| 91505-TM8-003 | CLIPBUMPER | 5 | 2.00 <i>an</i> | 25 | 7.50 | 0.53 | 8.03 |
| 68100-TAS-Z50ZZ | TAILGATE COMP | 1 | 716.30 <i>PA</i> | 25 | 537.22 | 37.61 | 574.83 |
| 75722-T5L-T01 | EMBLEMRR. | 1 | 10.30 <i>an</i> | 25 | 7.72 | 0.54 | 8.26 |
| 74440-T5A-003 | WEATHERSTRIPTAILGATE | 1 | 92.30 <i>an</i> | 25 | 69.22 | 4.85 | 74.07 |
| 73127-TY0-000 | RUBBER CWINDOWSHIELD DAMPER | 1 | 11.20 <i>an</i> | 25 | 8.40 | 0.59 | 8.99 |
| 73214-T5A-013 | RUBBERWINDOWSHIELD DAMPER | 2 | 6.20 <i>an</i> | 25 | 9.30 | 0.65 | 9.95 |
| 73226-SZW-000 | DAMPERSTD 5X5 | 1 | 8.30 <i>an</i> | 25 | 6.22 | 0.44 | 6.66 |
| BO-WS-SEALANT | WINDSCREEN SEALANT (N) | 2 | 60.00 <i>an</i> | | 120.00 | 8.40 | 128.40 |
| 33550-T5A-J02 | TAILLIGHT ASSYL. | 1 | 212.50 <i>X an</i> | 25 | 159.37 | 11.16 | 170.53 |
| 66100-TAR-T10ZZ | PANEL COMPRR. | 1 | 314.10 <i>PA</i> | 25 | 235.57 | 16.49 | 252.06 |
| 84640-T5A-003ZA | LINING ASSYRR.PANEL | 1 | 60.80 <i>TSU</i> | 25 | 45.60 | 3.19 | 48.79 |
| Sum Item | | | | | <u>1917.60</u> | <u>134.25</u> | <u>2,051.85</u> |
| BOSUN | SUNDRIES | 1 | 100.00 <i>30</i> | | 100.00 | 7.00 | 107.00 |
| BG02R | REPLACE RR. WINDSCREEN.(N) | 1 | 560.00 | | 560.00 | 39.20 | 599.20 |



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

| | | | | | |
|-------------------------|--|---------------------|---------------------------|---------------------------|----------------|
| Customer | : CHINA TAIPING INSURANCE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 | Document No. | : SQT17004006 | Page | 2 |
| Registration No | : SLC6602R | Date | : 28. Sep 2017 | Customer No. | : WZC008 |
| Chassis No | : JHMGK5850GX202764 | Svc Advisor | : | Engine No | : L15B31021120 |
| Model | : JAZZ 1.5VTIR CVT 16YM | Date Time | : 28. Sep 2017 1:20:10 PM | Surveyor Name | : |
| Owner's Name | : TSANG WENHAO FREDERICK | Survey Date | : | Authorisation Date | : |
| Ins Policy No. | : | | | | |
| Date of Accident | : 28/9/2017 | | | | |

| Item | Description | Qty | Unit Price | Disc % | Amount | GST Amt | Amount incld GST |
|-----------|--|-----|------------|--------|---------|---------|------------------|
| BODAMKIT | WINDSCREEN DAM KIT. | 1 | 80.00 | | 80.00 | 5.60 | 85.60 |
| BOMISC1 | REMOVE, INSTALL & CALIBRATE RR VIEW CAMERA | 1 | 380.00 | | 380.00 | 26.60 | 406.60 |
| BOJSE | BODY JOINT SEALANT FOR TAILGATE (N) | 1 | 80.00 | | 80.00 | 5.60 | 85.60 |
| BA02R | REMOVE & RENEW REVERSE SENSORS-4 PCS (N) | 1 | 180.00 | | 180.00 | 12.60 | 192.60 |
| BML02I | INSPECT RR LIGHTING MECHANISMS. PERFORM WATER | 1 | 180.00 | | 180.00 | 12.60 | 192.60 |
| BKTG02R | REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & | 1 | 560.00 | | 560.00 | 39.20 | 599.20 |
| BMI03D | REMOVE & INSTALL REAR COMPARTMENT LININGS | 1 | 560.00 | | 560.00 | 39.20 | 599.20 |
| BKRP02M | CUT OFF & RENEW RR PANEL. STRAIGHTEN | 1 | 3000.00 | | 3000.00 | 210.00 | 3210.00 |
| BP05R | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P) | 1 | 3000.00 | | 3000.00 | 210.00 | 3210.00 |
| Sum Labor | | | | | 8680.00 | 607.60 | 9,287.60 |

Survey By

Date & Time

Excess

Status

Signature

Total Amount 10,597.60 741.85 11,339.45

Total (Inclusive of GST) 11,339.45

6 days + 4 = 10 days
Resy by part

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 28/9/2017 1:27:18 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

13375.84

[illegible]



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

| | | | | | |
|------------------|--|--------------------|----------------------------|------|---|
| Customer | : CHINA TAIPING INSURANCE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 | Document No. | : SQT17004200 | Page | 2 |
| Registration No | : SLC6602R | Date | : 12. Oct 2017 | | |
| Chassis No | : JHMGK5850GX202764 | Customer No. | : WZC008 | | |
| Model | : JAZZ 1.5VTIR CVT 16YM | Svc Advisor | : | | |
| Owner's Name | : TSANG WENHAO FREDERICK | Engine No | : L15B31021120 | | |
| Ins Policy No. | : | Date Time | : 12. Oct 2017 11:22:25 AM | | |
| Date of Accident | : 28/9/2017 | Surveyor Name | : | | |
| | | Survey Date | : | | |
| | | Authorisation Date | : | | |

| Item | Description | Qty | Unit Price | Disc % | Amount | GST Amt | Amount incl GST |
|-----------|-------------|-----|------------|--------|--------|------------|--------------------|
| Signature | _____ | | | | | | |

Printed on 12/10/2017 11:28:40 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

Jojo Ngai

From: Jojo Ngai
Sent: Thursday, 6 December, 2012 10:23 AM
To: 'Sally Chong'
Cc: Hsiao Tong; 'admin@jpknights.com'
Subject: RE: Your Ref: AW1-scv-Ins-E21-85017-12 (mx) *Our Ref: CC7/AIG12016080/M1pb3q2 – 1 - 800597693

Dear Sally,

We refer to the below email.

We confirmed the re-inspection schedule as follows: -

Date & Time : 12/12/2012 @ 9.30am
Workshop : E M Solution
Contact Person : Mr Bernard
Contact Number : 9101 8302
LKK Surveyor : Mr Ma (8402 8474)

Thanks & Regards

Jojo Ngai

LKK Auto Consultants Pte Ltd

DID : 6742 8617

Fax : 6741 4108

Email : jojongai@lkkauto.com



Save the trees - Do you really need to print this e-mail?

From: Jojo Ngai
Sent: Friday, 30 November, 2012 3:44 PM
To: Sally Chong
Cc: Hsiao Tong; admin@jpknights.com
Subject: Your Ref: AW1-scv-Ins-E21-85017-12 (mx) *Our Ref: CC7/AIG12016080/M1pb3q2 – 1 - 800597693

Your Ref: AW1-scv-Ins-E21-85017-12 (mx)

Our Ref: CC7/AIG12016080/M1pb3q2 – 1 - 800597693

Dear Sally,

We refer to the above matter.

Please be informed that we have our principal's instruction to conduct a re-inspection on your client's vehicle SB 1700X.

Please arrange an appropriate date and time (Monday – Friday) one week in advance to enable our surveyor to conduct a re-inspection of your client's vehicle to verify the damages on without prejudice basis.

Appreciate an early reply.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING
Chassis No: JHMGK5850GX202764
License No: SLC6602R
Mileage: 14840
Engine No: L15B31021120

Document No: SVO17063011
Printed By: SHNG
Order Date: 2. October 2017
Order Time: 2:00:46 PM
Service Advisor: NG SIN HAI

| ITEM | DESCRIPTION | QTY | UNIT | DISC % | AMOUNT | GST Amt | Amount incld GST |
|-------------------|--|-----|--------|--------|-----------------|---------------|---------------------|
| | TP DIRECT SETTLEMENT (J/NO:) OWNER:TSANG WENHAO FREDERICK OWNER INSURER:LIBERTY INSURANCE ACC DATE:28/09/2017 SURVEYED BY:RASUL DATE:02/10/2017 REF NO: TP INSURER:CHINA TAIPING INSURANCE (S'PORE) PTE LT TP VEH:GBD1304Y ADDITIONAL PART | | | | | | |
| 04715-T5B-000ZZ | FACERR.BUMPER | 1 | 492.70 | 25 | 369.52 | 25.87 | 395.39 |
| NMRS-4P-TM3040L | 4PCS ACT RR.SENSOR | 1 | 320.00 | | 320.00 | 22.40 | 342.40 |
| 71593-T5A-000 | SPACERR.RR.BUMPER | 1 | 11.50 | 25 | 8.62 | 0.60 | 9.22 |
| 71598-T5A-000 | SPACERL.RR.BUMPER | 1 | 11.50 | 25 | 8.62 | 0.60 | 9.22 |
| 91505-TM8-003 | CLIPBUMPER | 5 | 2.00 | 25 | 7.50 | 0.53 | 8.03 |
| 68100-TAS-Z50ZZ | TAILGATE COMP | 1 | 716.30 | 25 | 537.22 | 37.61 | 574.83 |
| 75722-T5L-T01 | EMBLEMRR. | 1 | 10.30 | 25 | 7.72 | 0.54 | 8.26 |
| 74440-T5A-003 | WEATHERSTRIPTAILGATE | 1 | 92.30 | 25 | 69.22 | 4.85 | 74.07 |
| 73127-TY0-000 | RUBBER CWINDOWSHIELD DAMPER | 1 | 11.20 | 25 | 8.40 | 0.59 | 8.99 |
| 73214-T5A-013 | RUBBERWINDOWSHIELD DAMPER | 2 | 6.20 | 25 | 9.30 | 0.65 | 9.95 |
| 73226-SZW-000 | DAMPERSTD 5X5 | 1 | 8.30 | 25 | 6.22 | 0.44 | 6.66 |
| BO-WS-SEALANT | WINDSCREEN SEALANT (N) | 2 | 60.00 | | 120.00 | 8.40 | 128.40 |
| 66100-TAR-T10ZZ | PANEL COMPRR. | 1 | 314.10 | 25 | 235.57 | 16.49 | 252.06 |
| - 63320-T5A-300ZZ | GUTTER COMPR.RR. | 1 | 75.30 | 25 | 56.47 | 3.95 | 60.42 |
| 71502-T5A-000 | GARNISHR.RR.BUMPER | 1 | 6.30 | 25 | 4.72 | 0.33 | 5.05 |
| 73211-T5A-J01 | GLASS SETRR.WINDSHIELD | 1 | 625.60 | 25 | 469.20 | 32.84 | 502.04 |
| 33500-T5A-J02 | TAILLIGHT ASSYR. | 1 | 212.50 | 25 | 159.37 | 11.16 | 170.53 |
| 34150-T5A-J01 | LIGHT ASSYR.LID | 1 | 77.50 | 25 | 58.12 | 4.07 | 62.19 |
| 90650-SZT-003 | GROMMETRR.COMBINATION LIGHT | 1 | 2.50 | 25 | 1.87 | 0.13 | 2.00 |
| 90650-TX6-A01 | CLIPRR.COMBINATION LIGHT | 1 | 1.90 | 25 | 1.42 | 0.10 | 1.52 |
| 84601-TAR-Z03ZA | LINING ASSYR.TRUNK | 1 | 165.70 | 25 | 124.27 | 8.70 | 132.97 |
| 74890-T5B-911 | GARNISH ASSYRR.LICENSE | 1 | 190.40 | 25 | 142.80 | 10.00 | 152.80 |
| | SUM PARTS: | | | | 2,726.15 | 190.85 | 2,917.00 |
| BOSUN | 0701 SUNDRIES | 1 | 30.00 | | 30.00 | 2.10 | 32.10 |
| BG02R | 1757 REPLACE RR. WINDSCREEN.(N) | 1 | 560.00 | | 560.00 | 39.20 | 599.20 |
| BODAMKIT | 0701 WINDSCREEN DAM KIT. | 1 | 80.00 | | 80.00 | 5.60 | 85.60 |
| BOMISC1 | 1757 REMOVE, INSTALL & CALIBRATE RR VIEW CAMERA | 1 | 380.00 | | 380.00 | 26.60 | 406.60 |
| BOJSE | 1374 BODY JOINT SEALANT FOR TAILGATE (N) | 1 | 80.00 | | 80.00 | 5.60 | 85.60 |
| BA02R | 1729 REMOVE & RENEW REVERSE SENSORS-4 PCS (N) | 1 | 180.00 | | 180.00 | 12.60 | 192.60 |

Vehicle No: SB 1700 X
Report No: TP / 08-12075/DY / 2012

LABOUR COST

| S/No | Job Descriptions | Workshop's Estimation | Our Revised Estimation |
|------|------------------|-----------------------|------------------------|
|------|------------------|-----------------------|------------------------|

| | | | |
|---|--|------------|------------|
| 1 | To disconnect and reconnect, check electrical wiring, harness wires, sockets, replace damaged parts. | \$ 9995.05 | \$ 9903.55 |
|---|--|------------|------------|

| | | | |
|---|---|-----------|-----------|
| 2 | To remove and replace air-con system, refill gas and test for leakages. | \$ 180.00 | \$ 120.00 |
|---|---|-----------|-----------|

| | | | |
|---|---|------------|-----------|
| 3 | To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools. | \$ 1000.00 | \$ 750.00 |
|---|---|------------|-----------|

| | | | |
|---|---|-----------|-----------|
| 4 | To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available. | \$ 800.00 | \$ 660.00 |
|---|---|-----------|-----------|

| | | | |
|---|--|-----------|----------|
| 5 | To apply undercoating on the repaired and replaced panels for rust protection. | \$ 150.00 | \$ 60.00 |
|---|--|-----------|----------|

| | | |
|-------|-------------|-------------|
| Total | \$ 12225.05 | \$ 11533.55 |
|-------|-------------|-------------|

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of: \$ 9200.00

SDLS: NINE THOUSAND TWO HUNDRED ONLY

Qualified Appraiser



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING
Chassis No: JHMGK5850GX202764
License No: SLC6602R
Mileage: 14840
Engine No: L15B31021120

Document No: SVO17063011
Printed By: SHNG
Order Date: 2. October 2017
Order Time: 2:00:46 PM
Service Advisor: NG SIN HAI

| | | | | | | |
|-------------|--|---|----------|-----------|--------|-----------|
| BML02I | 1729 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N) | 1 | 180.00 | 180.00 | 12.60 | 192.60 |
| BKTG02R | 1729 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE. | 1 | 560.00 | 560.00 | 39.20 | 599.20 |
| BMI03D | 1729 REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES. | 1 | 560.00 | 560.00 | 39.20 | 599.20 |
| BKRP02M | 1729 CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS. | 1 | 2,240.00 | 2,240.00 | 156.80 | 2,396.80 |
| BP05R | 1718 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P) | 1 | 1,800.00 | 1,800.00 | 126.00 | 1,926.00 |
| BKRP02M | 0701 CUT OFF & RENEW RR PANEL AND LHR GUTTER | 1 | 1,680.00 | 1,680.00 | 117.60 | 1,797.60 |
| BOJSE | 0701 SEALANT FOR REAR END PANEL | 1 | 80.00 | 80.00 | 5.60 | 85.60 |
| SUM LABOUR: | | | | 8,410.00 | 588.70 | 8,998.70 |
| TOTAL SGD | | | | 11,136.15 | 779.55 | 11,915.70 |


Total Payable (SGD)

11,915.70

GST Amount is calculated from individual line(s)



PALESTER
SITE LTD. * PALS
S.T.A.S.



PALESTER
SITE LTD. * PALS
S.T.A.S.



**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

| | | | | | |
|------------------|---------------------------|--------------------|----------------------------|------|---|
| Customer | : CHINA TAIPING INSURANCE | Document No. | : SQT17004200 | Page | 1 |
| | 3 ANSON ROAD #16-00 | Date | : 12. Oct 2017 | | |
| | SPRINGLEAF TOWER | Customer No. | : WZC008 | | |
| | SINGAPORE 079909 | Svc Advisor | : | | |
| Registration No | : SLC6602R | Engine No | : L15B31021120 | | |
| Chassis No | : JHMGK5850GX202764 | Date Time | : 12. Oct 2017 11:22:25 AM | | |
| Model | : JAZZ 1.5VTIR CVT 16YM | Surveyor Name | : | | |
| Owner's Name | : TSANG WENHAO FREDERICK | Survey Date | : | | |
| Ins Policy No. | : | Authorisation Date | : | | |
| Date of Accident | : 28/9/2017 | | | | |

| Item | Description | Qty | Unit Price | Disc % | Amount | GST Amt | Amount Incl GST |
|-----------------|---|-----|------------|--------|---------|---------|-----------------|
| | TP DIRECT SETTLEMENT (J/NO:) | | | | | | |
| | OWNER: | | | | | | |
| | OWNER INSURER: | | | | | | |
| | ACC DATE: | | | | | | |
| | SURVEYED BY: | | | | | | |
| | DATE: | | | | | | |
| | REF NO: | | | | | | |
| | TP INSURER: | | | | | | |
| | TP VEH: | | | | | | |
| | SUPPLEMENTARY | | | | | | |
| BKRP02M | CUT OFF & RENEW RR PANEL AND LHR GUTTER | 1 | 1680.00 | | 1680.00 | 117.60 | 1797.60 |
| BOJSE | SEALANT FOR REAR END PANEL | 1 | 80.00 | | 80.00 | 5.60 | 85.60 |
| | Sum Labor | | | | 1760.00 | 123.20 | 1,883.20 |
| 63320-T5A-300ZZ | GUTTER COMPR.RR. | 1 | 75.30 | 25 | 56.47 | 3.95 | 60.42 |
| 71502-T5A-000 | GARNISHR.RR.BUMPER | 1 | 6.30 | 25 | 4.72 | 0.33 | 5.05 |
| 73211-T5A-J01 | GLASS SETRR.WINDSHIELD | 1 | 625.60 | 25 | 469.20 | 32.84 | 502.04 |
| 33500-T5A-J02 | TAILLIGHT ASSYR. | 1 | 212.50 | 25 | 159.37 | 11.16 | 170.53 |
| 34150-T5A-J01 | LIGHT ASSYR.LID | 1 | 77.50 | 25 | 58.12 | 4.07 | 62.19 |
| 90650-SZT-003 | GROMMETRR.COMBINATION LIGHT | 1 | 2.50 | 25 | 1.87 | 0.13 | 2.00 |
| 90650-TX6-A01 | CLIPRR.COMBINATION LIGHT | 1 | 1.90 | 25 | 1.42 | 0.10 | 1.52 |
| 84601-TAR-Z03ZA | LINING ASSYR.TRUNK | 1 | 165.70 | 25 | 124.27 | 8.70 | 132.97 |
| 74890-T5B-911 | GARNISH ASSYRR.LICENSE | 1 | 190.40 | 25 | 142.80 | 10.00 | 152.80 |
| | Sum Item | | | | 1018.24 | 71.28 | 1,089.52 |

Survey By


Date & Time

Excess

Status

Total Amount 2,778.24 194.48 2,972.72

Total (Inclusive of GST) 2,972.72








































...CLAIM SUBFOLDER...(Pending for Survey Report)





























| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|---|---|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 28 Sep 2017 | | 29 Sep 2017 10:57 Edit Adj Rpt | S\$11,136.15 Edit Estimates | S\$11,136.15 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|---|------------------------|---|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: M/S HARA HONG TIM SUM PTE LTD, Co. Reg. No.: - | | | | | | | | | |
| Main Claimant: TSANG WEN HAO FREDERICK | | | | | | | | | |
| Vehicle Reg. No.: | SLC6602R | Date of Loss: | 28/09/2017 09:00 - :59 [16 Months and 8 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / SNM17D05677C02 | Policy/Cover Note No.: | DMCVSN3048041700 | | | | | | |
| Vehicle Reg. No. (Insured): | GBD1304Y | Policy No. (Claimant): | | | | | | | |
| | | Excess: | S\$0.00 | | | | | | |
| Repairer: | Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD, - Alexandra - Tel: | | | | | | | | |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Alfred Toh - 6389 6183] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 10/10/2017] | | | | | | | | |
| Adj Asg. Remarks: | PELASE SURVEY THIRD PARTY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS. OUR INSURED HAD NOT FILED SAS REPORT. | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

***SLC6602R (SNM17D05677C02)**
[GBD1304Y]
TP
TSANG WEN HAO FREDERICK
Sep 28 2017 9:00AM
[M/S HARA HONG TIM SUM PTE LTD]
Kah Motor Co Sdn Bhd

| Upload Documents Upload Photos Compose New Letter | | | View View in Browser | |
|---|-----------------|-----------------------------------|--|-------------------------------------|
| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 08/06/18 11:30 | Odometer Reading |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 08/06/18 11:30 | Chassis Number |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 8 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 9 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 10 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 11 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 12 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 13 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 14 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 15 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 16 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 17 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 18 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 19 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 20 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 21 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 22 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 23 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 24 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 25 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 26 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 27 | 08/06/18 11:30 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 28 | 08/06/18 11:31 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 29 | 08/06/18 11:31 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 30 | 08/06/18 11:31 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 31 | 08/06/18 11:31 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 32 | 08/06/18 11:31 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 33 | 08/06/18 11:31 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 34 | 08/06/18 11:31 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 35 | 08/06/18 11:31 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 08/06/18 11:31 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 08/06/18 11:31 | General View |  Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|--|--|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 38 | 08/06/18 11:31 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 08/06/18 11:31 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 08/06/18 11:31 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 08/06/18 11:31 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 08/06/18 11:31 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 08/06/18 11:31 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 08/06/18 11:31 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 08/06/18 11:31 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 08/06/18 11:31 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 08/06/18 11:31 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 08/06/18 11:31 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 08/06/18 11:31 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 08/06/18 11:31 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 08/06/18 11:31 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 08/06/18 11:31 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 08/06/18 11:31 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 08/06/18 11:31 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 08/06/18 11:31 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 08/06/18 11:31 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 08/06/18 11:31 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 08/06/18 11:31 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 08/06/18 11:31 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 08/06/18 11:31 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 08/06/18 11:31 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 08/06/18 11:31 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 08/06/18 11:31 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
| 1 | 29/09/17 10:58 | THIRD PARTY SLC6602R -FROM KAH MOTOR -ESTIMATE |  Load PDF | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 12/06/18 10:58 | Supplementary |  Load PDF | |

Documents Checklist

| DOCUMENTS CHECKLIST | | Reset | Save | Print |
|--|--|-------|------|-------|
| There are no document checklists configured. | | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div> | | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI17018731/R1QBE2

Date: 12/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3048041700

Claimant Vehicle
No : SLC6602RInsured Vehicle
No : GBD1304Y

Date of Loss: 28/09/2017

Nature of Claim: TP

Claim
No: SNM17D05677C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLC6602R

Make & Model: HONDA JAZZ, 1.5 VTIR CVT (A)

Engine No: L15B31021120

Reg. Date: 20/05/2016 (Man. Year: 2016)

Chassis No: JHMGK5850GX202764

Colour: Blue

Odometer: 21910 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 185/55 R16 | Rear Tyre Size: | 185/55 R16 |
| Front Left Side: | Dunlop 6 mm | Rear Left Side: | Dunlop 6 mm |
| Front Right Side: | Dunlop 6 mm | Rear Right Side: | Dunlop 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|------------------|------------------|-----------------|--------------|
| Parts | 3,035.84 | 2,756.15 | 279.69 | 9.21 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 10,340.00 | 8,380.00 | 1,960.00 | 18.96 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 13,375.84 | 11,136.15 | 2,239.69 | 16.74 |
| + GST 7.00/7.00% (S\$) | 936.31 | 779.53 | 156.78 | 16.74 |
| Nett Amount (S\$) | 14,312.15 | 11,915.68 | 2,396.47 | 16.74 |

INSPECTION

Date of Assignment: 29/09/2017

Date Inspected: 02/10/2017 Inspected At:

Kah Motor Co Sdn Bhd (ALEXANDRA)
255 ALEXANDRA ROAD
Singapore -

Estimated Period of Repair: 10.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 12 Jun 2018) |
| Parts: | 144 | HONDA JAZZ 1.5 VTIR CVT (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SLC6602R) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|------------------------------|---------------|------------|------------|
| 1 | 1 | | *FACERR.BUMPER | Deformed | 369.52 FS | *369.52 FS |
| 2 | 1 | | *4PCS ACT RR.SENSOR | Not Working | 320.00 FS | *320.00 FS |
| 3 | 1 | | *GARNISHL.RR.BUMPER | Not Necessary | 4.72 FS | *- FS |
| 4 | 1 | | *SPACERR.RR.BUMPER | Necessary | 8.62 FS | *8.62 FS |
| 5 | 1 | | *SPACERL.RR.BUMPER | Necessary | 8.62 FS | *8.62 FS |
| 6 | 5 | | *CLIPBUMPER | Necessary | 7.50 FS | *7.50 FS |
| 7 | 1 | | *TAILGATE COMP | Bent | 537.22 FS | *537.22 FS |
| 8 | 1 | | *EMBLEMRR | Necessary | 7.72 FS | *7.72 FS |
| 9 | 1 | | *WEATHERSTRIPTAILGATE | Necessary | 69.22 FS | *69.22 FS |
| 10 | 1 | | *RUBBER C WINDSHIELD DAMPER | Necessary | 8.40 FS | *8.40 FS |
| 11 | 2 | | *RUBBER WINDSHIELD DAMPER | Necessary | 9.30 FS | *9.30 FS |
| 12 | 1 | | *DAMPERSTD 5X5 | Necessary | 6.22 FS | *6.22 FS |
| 13 | 2 | | *WINDSCREEN SEALANT | Necessary | 120.00 FS | *120.00 FS |
| 14 | 1 | | *TAILLIGHT ASSYL | Not Necessary | 159.37 FS | *- FS |
| 15 | 1 | | *PANEL COMPRR | Bent | 235.57 FS | *235.57 FS |
| 16 | 1 | | *LINING ASSYRR.PANEL | Serviceable | 45.60 FS | *- FS |
| 17 | 1 | | *SUNDRIES | Necessary | 100.00 FS | *30.00 FS |
| 18 | 1 | | *GUTTER COMPR.RR | Cracked | 56.47 FS | *56.47 FS |
| 19 | 1 | | *GARNISHR.RR.BUMPER | Cut | 4.72 FS | *4.72 FS |
| 20 | 1 | | *GLASS SETRR.WINDSHIELD | Necessary | 469.20 FS | *469.20 FS |
| 21 | 1 | | *TAILLIGHT ASSYR | Scratched | 159.37 FS | *159.37 FS |
| 22 | 1 | | *LIGHT ASSYR.LID | Scratched | 58.12 FS | *58.12 FS |
| 23 | 1 | | *GROMMETRR.COMBINATION LIGHT | Necessary | 1.87 FS | *1.87 FS |
| 24 | 1 | | *CLIPRR.COMBINATION LIGHT | Necessary | 1.42 FS | *1.42 FS |
| 25 | 1 | | *LINING ASSYR.TRUNK | Deformed | 124.27 FS | *124.27 FS |
| 26 | 1 | | *GARNISH ASSYRR.LICENSE | Cracked | 142.80 FS | *142.80 FS |

F=Franchise part. S=SpcNett.

| | | |
|--------------------------|-----------------|-----------------|
| Total Parts (S\$) | 3,035.84 | 2,756.15 |
|--------------------------|-----------------|-----------------|

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|---|----------|------------------|-----------------|
| Labour Items | | | | |
| 1 | REPLACE RR.WINDSCREEN | New | 560.00 | 560.00 |
| 2 | WINDSCREEN DAM KIT | New | 80.00 | 80.00 |
| 3 | REMOVE, INSTALL & CALIBRATE RR VIEW CAMERA | New | 380.00 | 380.00 |
| 4 | BODY JOINT SEALANT FOR TAILGATE | New | 80.00 | 80.00 |
| 5 | REMOVE & RENEW REVERSE SENSORS-4PCS | New | 180.00 | 180.00 |
| 6 | INSPECT RR LIGHTING MECHANISMS. PERFORM WATER | New | 180.00 | 180.00 |
| 7 | REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST & | New | 560.00 | 560.00 |
| 8 | REMOVE & INSTALL REAR COMPARTMENT LININGS | New | 560.00 | 560.00 |
| 9 | CUT OFF & RENEW RR PANEL. STRAIGHTEN | New | 3,000.00 | 2,240.00 |
| 10 | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (5P) | New | 3,000.00 | 1,800.00 |
| 11 | CUT OFF & RENEW RR PANEL AND LHR GUTTER | New | 1,680.00 | 1,680.00 |
| 12 | SEALANT FOR REAR END PANEL | New | 80.00 | 80.00 |
| Gross Labour Cost (S\$) | | | 10,340.00 | 8,380.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >