

ASS/REC BY: REF: CS/FC117018789/Rhbnz Special Instructions:
SURVEYOR: RCUU ASSIGNMENT (Office)
From (Person): LWS Joanne Yong of FC1 Date/Time: 29/9/17 5:57pm

Estimated Cost: Bill to:
OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKW 3262 P Insured: SH 7307C

at Workshop m/s: Nova Automotive Tel: 62723892

of Blk 1008 Bukit Merah Lane 3 # 01-04/06/08

Policy No: D-15077901MFSH Claim No: D17009254 MFSH

Sum Insured: Excess:

Make of Veh: D.O.A: 28/09/2017
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp' 11.10.2017 H.O.D. Endorsement:

Date/Time: 2/10/17 9:26am Person Contacted: ERIC Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SKW 3262 P - x
	SH 7307C - NS/INC. 11008371/H1gn - D.O.A: 5/4/2011
12/10/17 @	5:35pm revised to Joanne Yong by email.
08/11/17 @	11:30am Rami finalised with Billy final fig \$3741.25, 5 days. Cled \$220, 67.)

ASSIGNMENT

From:

Date: 11/10/17

Estimated Cost:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKW 3262 P

at Workshop m/s: Nova Automotive

of Blk 1008 Bkt Merah Lane 3 # 01-04/06/08

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SKW 3262 P

Yr Regn: 2015 OCT

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA WISH-F

c.c 1798

Colour:

GREY

A/C: Insured / Std / NI / NA

Sp. Reading:

51850

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDGG20W 60J 002873

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

28/09/17

D.O.I.

11/10/17

Survey held at

NOVA (CR7)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

11/12/17

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) 374.25

☐ : Preli. Report☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

130

50

50

42

272

RECEIVED 1 DEC 2017



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17018789/R1qb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 02-10-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7307C	Veh. Inspected	SKW 3262P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17009254MFSH	Excess (\$)	0.00	
Assign From	CWS (JOANNE YONG)	Assign Date	02/10/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/09/2017	Inspection Date		
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Policy Type: OD / TP / TP RES / TL / EVA

Typist

21/05/2014

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	28-09-2017	Our Ref No. D17009254MFSH
Accident Date	28-09-2017	Claim Type. Third Party
Insured Vehicle	SH7307C	Third Party Vehicle. SKW3262P
Survey Location	BLOCK 1008 BUKIT MERAH LANE 3 #01-04/06/08	
Contact Person.	ERIC KI	
Contact No.	62723892/ 0	Fax No. 62721527
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MOVA AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/228576)



PRI Documents



Close



PRI Header Details

Claim No	D17009254MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & MOVA AUT
Workshop Name	MOVA AUTOMOTIVE PTE LTD (Contact Person : ERIC KI)	Survey Location & Contact Details	BLOCK 1008 BUKIT MERAH LANE 3 #01-04/06/08 Mobile: 0 , Phone: 62723892 , Fax: 62721527 EmailId: ERIC@MOVA.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH7307C	TP Vehicle No	SKW3262P
PRI Recieved Date	28-09-2017 11:17:55 PM	Surveyor Appointed Date	29-09-2017 05:56:38 PM	Surveyor Accept Date	02-10-2017 0

Survey Report Upload

Surveyor Inspection Date *		Surveyor Report Date	02-10-2017	Upload Survey Report *	Choose File
----------------------------	--	----------------------	------------	------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Shiau Chan (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Friday, 8 December, 2017 11:35 AM
To: Billy
Cc: SUR; CS A Team
Subject: RE: Re:SKW3262

Hi Billy,

Finalised amount at \$ 3,741.25 / 5 days P/P confirmed

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Billy [<mailto:billy@nova.com.sg>]
Sent: Tuesday, 5 December, 2017 4:02 PM
To: Rasul (LKKAUTO)
Cc: SUR; CS A Team
Subject: FW: Re:SKW3262

Hi Sir,

Attach with Finalization report, please advice. Thank You.

Best Regard's

Billy Liaw

From: Billy [<mailto:billy@nova.com.sg>]
Sent: 29 November 2017 13:46
To: 'Rasul (LKKAUTO)'
Cc: 'sur@lkkauto.com'
Subject: FW: Re:SKW3262

Hi Sir,

Please help to Finalize above mention case, Thank You.

Best Regard's

Billy Liaw

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 12 October, 2017 5:35 PM
To: 'Claim Workflow System'; assignments
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17009254MFSH/1
Attachments: CSFCI17018789R1qb.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SKW 3262P.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 2 October, 2017 9:36 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17009254MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Friday, 29 September, 2017 5:57 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; JOANNEYONG@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17009254MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17009254MFSH

Date: 12th October 2017

Our Ref: CS/FCI17018789/R1qb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKW 3262P

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/10/2017 at the premises of M/s MOVA AUTOMOTIVE, and have the following to report:-

Workshop Estimate Amount	: S\$ 3,961.25 .
Revised Estimate Amount	: S\$ 3,741.25 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the o/s rear portion.



Yours faithfully

Mohd Rasul
Automotive Assessor

Estimate

28/09/2017

FIRST CAPITAL INSURANCE LTD
36 Robinson Road
#16-01 City House
Singapore 068877.

Page # :- 1

Veh # :- SKW3262P

Veh Model :- TOYOTA WISH

Estimate# :- CK416450

Claim # :-

ACC. Date :- 28/09/17

Terms :- C.O.D Days

Remarks :-

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel : (65) 6476 3333
 Fax : (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 100B,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722
 Tel : (65) 6272 3892
 Fax : (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Attention :- XA026

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR DOOR RH	1 PC	1,059.00	1,059.00
2.	REAR DOOR STICKER RH	1 PC	43.00	43.00
3.	REAR DOOR LOWER MOULDING RH - CHECK	1 PC		
4.	ROCKER PANEL GARNISH RH	1 PC	1,382.00	1,382.00
5.	REAR BUMPER	1 PC	574.00	574.00
6.	REAR BUMPER RETAINER RH	1 PC	67.00	67.00
7.	REAR BUMPER CLIPS	10 PC	5.00	50.00
8.	REAR FENDER RH - REPAIR	1 PC		
	LIST TOTAL S\$			3,175.00
	25% DISCOUNT S\$			-793.75
				2,381.25
LABOUR :				
	TO KNOCK AND STRAIGHTEN REAR FENDER RH.			
	REMOVE AND REPLACE ACCIDENT DAMAGED PARTS			
	REALIGN ALL CONNECTION			
	SPRAY PAINT REAR DOOR RH, ROCKER PANEL			
	GARNISH RH, REAR FENDER RH, REAR BUMPER			
	REMOVE AND REPLACE REAR DOOR TRIM BOARD.			
	MECHANISM AND CHECK LOCKING SYSTEM			
	REMOVE AND REPLACE REAR FENDER INNER TRIM.			
	GARNISH, COVERING			
	REMOVE AND REPLACE REVERSE SENSOR AND			
	CHECK FUNCTION			
	RUST PROOF AFFECTED AREA			
	LABOUR TOTAL S\$			1,580.00
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				
Acknowledged by Repairer Signature:				
E & O.E				
NON-TAX AMOUNT S				3,961.25
AMOUNT S\$				277.29
GST @ 7 %				
AMOUNT DUE S\$				4,238.54

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Attn: Ah Khen

Estimate

28/09/2017

FIRST CAPITAL INSURANCE LTD
36 Robinson Road
#16-01 City House
Singapore 068877.

Attention :- XA026

Page # :- 1 129530
Veh # :- SKW3262P
Veh Model :- TOYOTA WISH
Estimate# :- CK416450
Claim # :-
ACC. Date :- 28/09/17
Terms :- C.O.D Days
Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg
Workshop Dept:
Block 100B,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR DOOR RH	1 PC	1,059.00	1,059.00 ✓
2.	REAR DOOR STICKER RH	1 PC	43.00	43.00 ✓
3.	REAR DOOR LOWER MOULDING RH - CHECK	1 PC		
4.	ROCKER PANEL GARNISH RH	1 PC	1,382.00	1,382.00 ✓
5.	REAR BUMPER	1 PC	574.00	574.00 ✓
6.	REAR BUMPER RETAINER RH	1 PC	67.00	67.00 ✓
7.	REAR BUMPER CLIPS	10 PC	5.00	50.00 ✓
8.	REAR FENDER RH - REPAIR	1 PC		
LIST TOTAL S\$				3,175.00
25% DISCOUNT S\$				-793.75
				2,381.25 ✓
LABOUR :				
TO KNOCK AND STRAIGHTEN REAR FENDER RH. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS REALIGN ALL CONNECTION				
SPRAY PAINT REAR DOOR RH, ROCKER PANEL GARNISH RH, REAR FENDER RH, REAR BUMPER				
REMOVE AND REPLACE REAR DOOR TRIM BOARD, MECHANISM AND CHECK LOCKING SYSTEM				
REMOVE AND REPLACE REAR FENDER INNER TRIM, GARNISH, COVERING				
REMOVE AND REPLACE REVERSE SENSOR AND CHECK FUNCTION				
RUST PROOF AFFECTED AREA				
LABOUR TOTAL S\$				30.00 ✓

1) PARTS 2381.25
2) LABOUR 1360.00

3741.25 PBP

Please advice. Thank You
BILLY LIAN.

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 3,961.25

GST @ 7 % 277.29

AMOUNT DUE S\$ 4,238.54

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Attn: Ah Khen

Estimate

28/09/2017

FIRST CAPITAL INSURANCE LTD
36 Robinson Road
#16-01 City House
Singapore 068877.

Page # :- 1 129530
Veh # :- SKW3262P
Veh Model :- TOYOTA WISH
Estimate# :- CK416450
Claim # :-
ACC. Date :- 28/09/17
Terms :- C.O.D Days
Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg
Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Attention :- XA026

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1.	REAR DOOR RH	1	PC	1,059.00	1,059.00 ✓
2.	REAR DOOR STICKER RH	1	PC	43.00	43.00 ✓
3.	REAR DOOR LOWER MOULDING RH - CHECK	1	PC		
4.	ROCKER PANEL GARNISH RH	1	PC	1,382.00	1,382.00 ✓
5.	REAR BUMPER	1	PC	574.00	574.00 ✓
6.	REAR BUMPER RETAINER RH	1	PC	67.00	67.00 ✓
7.	REAR BUMPER CLIPS	10	PC	5.00	50.00 ✓
8.	REAR FENDER RH - REPAIR	1	PC		

LIST TOTAL S\$

25% DISCOUNT S\$

3,175.00

-793.75

1) 2,381.25 ✓

LABOUR :

TO KNOCK AND STRAIGHTEN REAR FENDER RH.
REMOVE AND REPLACE ACCIDENT DAMAGED PARTS
REALIGN ALL CONNECTION

SPRAY PAINT REAR DOOR RH, ROCKER PANEL
GARNISH RH, REAR FENDER RH, REAR BUMPER

REMOVE AND REPLACE REAR DOOR TRIM BOARD,
MECHANISM AND CHECK LOCKING SYSTEM

REMOVE AND REPLACE REAR FENDER INNER TRIM,
GARNISH, COVERING

REMOVE AND REPLACE REVERSE SENSOR AND
CHECK FUNCTION

RUST PROOF AFFECTED AREA

LABOUR TOTAL S\$

500 600.00

700 800.00

60 60.00 ✓

40 60.00

30.00 ✓

30.00 ✓

> 1360.00 1,580.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 3,961.25

GST @ 7 % 277.29

AMOUNT DUE S\$ 4,238.54

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17018789/R1qbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 14-12-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7307C	Veh. Inspected	SKW 3262P	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17009254MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	29/09/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH 1.8	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JTDGG20W60J002873	Colour	GREY	
Odometer	51850	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	5 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	5 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/09/2017	Inspection Date	11/10/2017	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 3262P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR DOOR RH	BENT	1,059.00	1,059.00
1	REAR DOOR STICKER RH	NECESSARY	43.00	43.00
1	REAR DOOR LOWER MOULDING RH (NPA)	SERVICEABLE	-	-
1	ROCKER PANEL GARNISH RH	CUT	1,382.00	1,382.00
1	REAR BUMPER	CUT	574.00	574.00
1	REAR BUMPER RETAINER RH	NECESSARY	67.00	67.00
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
1	REAR FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-793.75	-793.75
			2,381.25	2,381.25
	LABOUR			
	TO KNOCK AND STRAIGHTEN REAR FENDER RH.REMOVE AND REPLACE ACCIDENT DAMAGED PARTS.REALIGN ALL CONNECTION.INCLUSIVE OF THE REPAIR OF REAR FENDER RH.		600.00	500.00
	SPRAY PAINT REAR DOOR RH.ROCKER PANEL GARNISH RH.REAR FENDER RH,REAR BUMPER.		800.00	700.00
	REMOVE AND REPLACE REAR DOOR TRIM BOARD,MECHANISM AND CHECK LOCKING SYSTEM.		60.00	60.00
	REMOVE AND REPLACE REAR FENDER INNER TRIM,GARNISH,COVERING.		60.00	40.00
	REMOVE AND REPLACE REVERSE SENSOR AND CHECK FUNCTION.		30.00	30.00
	RUST PROOF AFFECTED AREA.		30.00	30.00
			1,580.00	1,360.00
	GRAND TOTAL		3,961.25	3,741.25
RECOMMENDED COST OF REPAIRS				3,741.25

Report Ref No. CS/FCI17018789/R1qbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.