



**SINGAPORE
POLICE FORCE**



T/20170927/2027

2 of 3

Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999

Report No. T/20170927/2027

CONTINUATION OF REPORT

Driver			
Name	Koh Chin Keong	ID No.	S7309070I
Related Vehicle	GBB2739E (Van)	Contact No.	98307457
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	KHOO HOCK LIONG	ID No.	S1775050Z
Related Vehicle	SHB1166T (Taxi)	Contact No.	81591308
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	25/09/2017	Date Discharge	26/09/2017
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 25/09/2017 @ 2140 hrs, I was driving my taxi SHB1166T along Henderson Road and when the green light was on at the traffic junction of Telok Blangah Way as I am turning right into Telok Blangah Way, a silver colour van GBB 2739E never slow down and bang onto my left side of my taxi causing my left side seriously damaged. I was giddy at that time and I called for Police. Ambulance then conveyed me to SGH. I was admitted and warded for that night. I do not know what happened to the van driver, the van driver gave me his particular.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999



T/20170927/2027

3 of 3

Report No. T/20170927/2027

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /
Sr Staff Sgt TAN CHAI HEE

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /

Contact No.:

Authentication Stamp
NP168

Signature Of Informant: -

Date/Time:
27/09/2017 09:44

Classification Of Case:



SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1166T
 Ref. No : TAX/09/17/2152
 Reg. Date : 07/05/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : KHOO HOCK LIONG
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 25/09/2017 09:40:00 PM
 Accident Reported Date / Time : 27/09/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024092269
 Special Instruction to ARC, if any :
 Towed to TP compound (\$90) / GBB2739E - ERGO
 Prepared Date : 27/09/2017 12:08:13 PM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taylor 97495746

2/10/17 @ 1600

sur @ lkkauto.com

taughten @ lkkauto.com

lumpsum

Resurvey after repair

9 days.

[Signature]
4/10/17

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U905741594

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	2,028.00	0.00
Total Spray Painting Charges	3,150.00	0.00
Total Material Charges	46,967.28	46,967.28
Other Charges	3,076.00	0.00
TOTAL	55,221.28	0.00
Lum Sum Total	55,200.00	0.00
No. of Repair Days	12.00	0.00
Prepared / Adjusted By		
Arc / Surveyor Sing Off Date	29/09/2017 05:34:53 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 29/09/2017 05:34:24 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	2,028.00	0.00 1000
Total Labour	2,028.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	378.00	0.00 200
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 X nn
TO RESPRAY VIEW MIRROR	180.00	0.00 X nn
TO RESPRAY FRONT FENDER RH	378.00	0.00 200
TO RESPRAY RIM	180.00	0.00 X nn
TO RESPRAY FRONT PILLAR RH	180.00	0.00 100
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00 100
TO RESPRAY FRT MEMBER,LH	180.00	0.00 100
TO REPSRAY FRONT HOOD	378.00	0.00 200
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY FRONT PILLAR RH	180.00	0.00 100
Total Spray Painting & Panel Beating	3,150.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

2604

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	126.00	0.00 90-80
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 40
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00 80
TO TRANSFER DOOR MECHANISM	120.00	0.00 x 7
TO REMOVE AND REFIX WING MIRROR	120.00	0.00 x } nn
TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	240.00	0.00 x }
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	240.00	0.00 x }
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 80 ? ✓
TO REMOVE AND REFIT WIRE HARDESS	350.00	0.00 150
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	150.00	0.00 100 120 ? ✓
TO TOP UP A/C GAS	120.00	0.00 100 ? ✓
TO CONDUCT RADIATOR PRESSURE CHECK	100.00	0.00 60 80 ? ✓
TO ALIGN CHASSIS	350.00	0.00 200 250 ✓ photo
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	250.00	0.00 x nn
TO REPLACE SUNDRY PARTS	100.00	0.00 40 ✓
TO WASH AND VACUUM	60.00	0.00 40 ✓
TO CHECK & RESET SYSTEM FUNCTION	350.00	0.00 150 ✓
Total Other Costs	3,076.00	0.00

Part 4 - Spare Parts / Material Usage

67474.20

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
67001-47070		6505528	DOOR FRT/RH	1	894.40	25.00	670.80	Replace	Replace <i>Ry</i>	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace <i>her</i>	No
68710-12151			HINGE UPPER RHF, DOOR	1	80.50	25.00	60.37	Replace	Replace <i>Ry</i>	No
68730-12120			HINGE LOWER RHF, DOOR	1	90.10	25.00	67.57	Replace	Replace <i>Ry</i>	No
68610-47021			CHECK ASSY, FR DOOR,	1	150.30	25.00	112.72	Replace	Replace <i>Ry</i>	No
75851-47900			MOULDING BODY, RH	1	673.60	25.00	505.20	Replace	Replace <i>nn</i> x	No
87910-47330		6505600	MIRROR ASSY, RH	1	1,307.10	25.00	980.32	Replace	Replace <i>nn</i> x	No
87931-47200			MIRROR GLASS RH	1	212.80	25.00	159.60	Replace	Replace <i>nn</i> x	No
81730-52090		6505466	MIRROR LAMP RH	1	65.30	10.00	58.77	Replace	Replace <i>nn</i> x	No
879157-4010		6505598	COVER, OUTER MIRROR, RH	1	107.40	25.00	80.55	Replace	Replace <i>nn</i> x	No
53801-47050		6505557	FENDER FRT/RH	1	723.40	25.00	542.55	Replace	Replace <i>bt</i>	No
75442-47030			NAME PLATE (PRIUS)	1	60.80	25.00	45.60	Replace	Replace <i>nn</i>	No
62110-47021			QUARTER GLASS FRT/RH	1	234.90	25.00	176.17	Replace	Replace <i>nn</i> x	No
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace <i>nn</i> x	No
53875-47030		6505553	FENDER LINER FRT/RH	1	171.70	25.00	128.77	Replace	Replace <i>nn</i> x	No
53851-47040			FENDER LINER PAD, FR WHEEL, RH	1	49.30	25.00	36.97	Replace	Replace <i>nn</i> x	No
42611-47140 (Frt)		6505658	WHEEL DISC. FRONT	1	1,484.20	25.00	1,113.15	Replace	Replace <i>nn</i> x	No
61131-47030			PILLAR, FR BODY	1	363.10	25.00	272.32	Replace	Replace <i>Ry</i>	No
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace <i>dis</i>	No
52116-47040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace <i>nn</i>	No
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Replace <i>nn</i>	No
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace <i>bt</i>	No
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace <i>nn</i>	No
57014-47030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Replace <i>bt</i>	No
57013-47030			ARM SUB-ASSY, FR BUMPER RH	1	250.40	25.00	187.80	Replace	Replace <i>bt</i>	No
81511-47050			LENS & BODY, FR TURN RH	1	511.80	10.00	460.62	Replace	Replace <i>nn</i> x	No
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	Replace	Replace <i>de</i>	No
81210-12230		6505439	FOG LAMP RH	1	295.20	10.00	265.68	Replace	Replace <i>nn</i> x	No

9596.80

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52127-47903			COVER, FR BUMPER HOLE RH	1	18.50	25.00	13.87	Replace	Replace <i>X</i>	No <i>1</i>
52114-47140			BRACKET, FR BUMPER	1	110.40	25.00	82.80	Replace	Replace <i>nn</i>	No
	REAR		NUMBER PLATE	1	30.00	0.00	30.00	Replace	Replace <i>mk</i>	No
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace <i>nn</i>	No
52127-47903			COVER, FR BUMPER HOLE RH	1	18.50	25.00	13.87	Replace	Replace <i>ny X</i>	No
81210-12230		6505439	FOG LAMP RH	1	295.20	10.00	265.68	Replace	Replace <i>nn X</i>	No
53111-47040		6505573	GRILLE, RADIATOR	1	310.60	25.00	232.95	Replace	Replace <i>de</i>	No
75310-47010		6505638	EMBLEM FRONT	1	86.50	25.00	64.87	Replace	Replace <i>nn</i>	No
81521-47050			LENS & BODY, FR TURN LH	1	511.80	10.00	460.62	Replace	Replace <i>ds</i>	No
81529-47040			BRACKET, FR TURN UPPER LH	1	24.40	25.00	18.30	Replace	Replace <i>ds</i>	No
81529-47050			BRACKET, FR TURN LOWER LH	1	26.00	25.00	19.50	Replace	Replace <i>ds</i>	No
81529-47060			BRACKET, FR TURN CENTER LH	1	58.20	25.00	43.65	Replace	Replace <i>ds</i>	No
76851-47020		6505616	BUMPER LIP FRT	1	139.60	25.00	104.70	Replace	Replace <i>de</i>	No
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.77 <i>95.73</i>	Replace	Replace <i>de</i>	No
53113-47040			GRILLE RADIATOR LOWER NO.2	1	94.60	25.00	70.95	Replace	Replace <i>de</i>	No
51410-12105			UNDER COVER CENTER	1	448.30	25.00	336.22	Replace	Replace <i>nn</i>	No
82113-47180			WIRE, ENGINE ROOM, NO.3	1	242.00	10.00	217.80	Replace	Replace <i>cut</i>	No
88790-22131	COMMO N		THERMISTOR ASSY	1	107.00	10.00	96.30	Replace	Replace <i>nn</i>	No
86510-28130			HORN ASSY, HIGH	1	110.40	25.00	82.80	Replace	Replace <i>nn</i>	No
86520-28180			HORN ASSY, LOW	1	110.40	25.00	82.80	Replace	Replace <i>nn</i>	No
53294-47030		6505561	DEFLECTOR, RADIATOR LH	1	77.00	25.00	57.75	Replace	Replace <i>de</i>	No
53293-47040		6505574	DEFLECTOR, RADIATOR RH	1	83.50	25.00	62.62	Replace	Replace <i>nn X</i>	No
88460-47150			A/C CONDENSER	1	1,181.90	25.00	886.42 <i>886.43</i>	Replace	Replace <i>ht</i>	No
G9010-47031			RADIATOR ASSY, UPPER	1	679.60	25.00	509.70	Replace	Replace <i>ht</i>	No
16400-37230		6505302	RADIATOR ASSY	1	1,496.90	25.00	1,122.67 <i>1122.63</i>	Replace	Replace <i>ht</i>	No
16711-37040			FAN SHROUD	1	244.50	25.00	183.37 <i>183.38</i>	Replace	Replace <i>nn</i>	No
16712-37030			FAN SHROUD TOP	1	99.60	25.00	74.70	Replace	Replace <i>ds</i>	No
16363-37010			FAN MOTOR NO 1	1	538.30	25.00	403.72 <i>403.73</i>	Replace	Replace <i>nn</i>	No
16363-37020			FAN MOTOR NO 2	1	538.30	25.00	403.72 <i>403.73</i>	Replace	Replace <i>ds</i>	No
16361-37010			FAN BLADE	1	158.60	25.00	118.95	Replace	Replace <i>nn</i>	No

7980.30

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
16361-28360			FAN BLADE NO 2	1	204.20	25.00	153.15	Replace	Replace <i>cut</i> ?	No
16535-20030			SUPPORT, RADIATOR,	1	18.50	25.00	13.87	Replace	Replace <i>bt</i> ?	No
16534-37010			SUPPORT, RADIATOR, LH	1	17.70	25.00	13.27	Replace	Replace <i>bt</i> ?	No
16533-28051			SUPPORT, RADIATOR, RH	1	54.50	25.00	40.87	Replace	Replace <i>nn</i> ?	No
16523-21050			CUSHION, RADIATOR	2	11.30	25.00	16.95	Replace	Replace <i>nn</i> ?	No
53201-47902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Replace <i>bt</i> ?	No
81170-47500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace <i>ann</i> ?	No
81130-47500		6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace	Replace <i>ann</i> ?	No
16480-28080			COOLANT RESERVE TANK	1	395.30	25.00	296.47	Replace	Replace <i>nn</i> ?	No
16261-37070			RADIATOR HOSE, BYPASS NO.1	1	37.20	25.00	27.90	Replace	Replace <i>nn</i> ?	No
16264-37080			RADIATOR HOSE, BYPASS NO.2	1	29.00	25.00	21.75	Replace	Replace <i>nn</i> ?	No
16267-37030			RADIATOR HOSE, BYPASS NO.3	1	37.20	25.00	27.90	Replace	Replace <i>nn</i> ?	No
16281-37030			RADIATOR HOSE, BYPASS NO.4	1	37.20	25.00	27.90	Replace	Replace <i>nn</i> ?	No
16571-37140		6505303	RADIATOR TOP HOSE NO 1	1	42.40	25.00	31.80	Replace	Replace <i>nn</i> ?	No
16577-37020		6505304	RADIATOR TOP HOSE NO 2	1	126.50	25.00	94.87	Replace	Replace <i>nn</i> ?	No
16572-37120			RADIATOR HOSE LOWER	1	42.40	25.00	31.80	Replace	Replace <i>nn</i> ?	No
88707-47041			TUBE SUB-ASSY, SUCTION	1	371.40	25.00	278.55	Replace	Replace <i>nn</i> ?	No
88703-47040			HOSE SUB-ASSY, DISCHARGE	1	386.90	25.00	290.17	Replace	Replace <i>nn</i> ?	No
88704-47090			HOSE SUB-ASSY, SUCTION	1	405.40	25.00	304.05	Replace	Replace <i>nn</i> ?	No
65319-47120			WIPER WASHER INLET	1	36.90	25.00	27.67	Replace	Replace <i>nn</i> ?	No
17750-37010			INLET ASSY, AIR	1	232.50	25.00	174.37	Replace	Replace <i>nn</i> ?	No
17881-54360	FRONT		AIR DUCT BOX NO 1	1	208.20	25.00	156.15	Replace	Replace <i>nn</i> ?	No
17882-54361	COMMON		AIR DUCT BOX NO 2	1	15.22	25.00	11.41	Replace	Replace <i>nn</i> ?	No
17894-37010			RESONATOR, INTAKE	1	57.20	25.00	42.90	Replace	Replace <i>nn</i> ?	No
17700-38252			AIR CLEANER ASSY	1	929.90	25.00	697.42	Replace	Replace <i>nn</i> ?	No
17111-0P040			MANIFOLD, INTAKE	1	1,055.10	25.00	791.32	Replace	Replace <i>nn</i> ?	No
89421-47010			SENSOR, VACUUM	1	602.10	10.00	541.89	Replace	Replace <i>nn</i> ?	No
11212-37090			COVER, CYLINDER	1	165.20	25.00	123.90	Replace	Replace <i>de</i> ?	No
G9200-49025			INVERTER W CONVERTER	1	5,390.20	10.00	4,851.18	Replace	Replace <i>cre</i> ?	No
G9110-47011			INVERTER BRACKET TRAY	1	251.60	25.00	188.70	Replace	Replace <i>dis</i> ?	No

14573.38

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
G9214-47060			BRACKET, INVERTER, NO.1	1	31.40	25.00	23.55	Replace	Replace ? nn	No
G9140-47010			COVER ASSY, INVERTER, LH	1	54.50	25.00	40.87	Replace	Replace ? nn	No
G9225-47021			HOSE, INVERTER NO.1	1	80.00	25.00	60.00	Replace	Replace ? nn	No
G9229-47020			HOSE, INVERTER COOLING NO.5	1	125.30	25.00	93.97	Replace	Replace ? nn	No
G9236-47031			HOSE, INVERTER COOLING NO.6	1	37.40	10.00	33.66	Replace	Replace ? nn	No
G9226-47020			HOSE, INVERTER COOLING NO.2	1	90.10	10.00	81.09	Replace	Replace ? nn	No
G9040-47090			PUMP ASSY, WATER	1	454.00	25.00	340.50	Replace	Replace ? nn	No
	COMMON		COOLANT	4/2	12.32 / 49.28	0.00	24.64 / 49.28	Replace	Replace ? nn	No
G2148-47051			CABLE, GENERATOR	1	169.10	10.00	152.19	Replace	Replace ? nn	No
G1148-47051			CABLE, MOTOR INVERTER	1	199.10	10.00	179.19	Replace	Replace ? nn	No
82164-47070			WIRE, FRAME	1	1,680.90	25.00	1,260.67	Replace	Replace ? nn	No
82663-47060			FUSE BLOCK, COVER LOWER	1	18.50	10.00	16.65	Replace	Replace ? nn	No
82741-75010			FUSE BLOCK, ENGINE ROOM	1	148.50	10.00	133.65	Replace	Replace ? nn	No
82662-47110			FUSE BLOCK, TOP COVER	1	82.30	10.00	74.07	Replace	Replace ? nn	No
			EDS SYSTEM	1	9,450.00	10.00	8,505.00	Replace	Replace ? nn	No
82111-47772			WIRE, ENGINE ROOM	1	5,567.10	10.00	5,010.39	Replace	Replace ? cut	No
55084-47011			WIPER GARNISH COVER, LH	1	23.80	25.00	17.85	Replace	Replace ? nn	No
55083-47011			WIPER GARNISH COVER, RH	1	23.80	25.00	17.85	Replace	Replace ? di	No
55708-47101			WIPER GARNISH	1	614.00	25.00	460.50	Replace	Replace ? nn	No
51444-12050		6505472	UNDER COVER SIDE/LH	1	46.10	25.00	34.57	Replace	Replace ? de	No
5702812020			MEMBER SUB-ASSY, FR LH	1	810.70	25.00	608.02	Replace	Replace ? Ry	No
57104-47020		6505507	RADIATOR LOWER SUPPORT	1	876.30	25.00	657.22 / 657.23	Replace	Replace ? bt	No
53301-47060		6505555	HOOD PANEL	1	748.10	25.00	561.07 / 561.08	Replace	Replace ? bt	No
53395-47020			HOOD END PANEL SEAL	1	35.50	25.00	26.62	Replace	Replace ? nn	No
53341-47020			HOOD PANEL INSULATOR	1	390.50	25.00	292.87	Replace	Replace ? nn	No
53420-47070			HOOD HINGE LH	1	55.90	25.00	41.92	Replace	Replace ? bt	No
53410-47070			HOOD HINGE RH	1	55.90	25.00	41.92	Replace	Replace ? bt	No
53557-47010			HOOD AUXILIARY CATCH	1	8.60	25.00	6.45	Replace	Replace ? nn	No
53510-47102			HOOD LOCK	1	128.90	25.00	96.67	Replace	Replace ? bt	No
53630-47050			CABLE ASSY, HOOD	1	52.20	25.00	39.15	Replace	Replace ? nn	No

77087.14

27107.78

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
53289-47032			COVER, RADIATOR	1	122.80	25.00	92.10	Replace	Replace <i>de</i>	No
53802-47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace <i>bt</i>	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace <i>ay</i>	No
53876-47030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace <i>fn</i>	No
53852-47020			FENDER LINER PAD, FR WHEEL. LH	1	49.30	25.00	36.97	Replace	Replace <i>nn x</i>	No
42611-47140 (Frt)		6505658	WHEEL DISC. FRONT	1	1,484.20	25.00	1,113.15	Replace	Replace <i>nn x</i>	No
62120-47021			QUARTER GLASS FRT/LH	1	234.90	25.00	176.17	Replace	Replace <i>nn x</i>	No
	COMMO N		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace <i>nn x</i>	No
61132-47030			PILLAR, FR BODY, LH	1	363.10	25.00	272.32	Replace	Replace <i>Ry</i>	No
TOTAL MATERIALS							46,967.52	46,967.28		
TOTAL MATERIALS(Discounted)							46,967.28	46,967.28		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

3238.30

65675.86

24143.65
24141.54

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 5369K

Vehicle Details

Vehicle No.: SHB1166T

Vehicle to be Exported: No

Intended De-registration
Date: 03 Oct 2017

Vehicle Make: TOYOTA

Vehicle Model: PRIUS TAXI (SMRT)

Primary Colour: Maroon

Manufacturing Year: 2014

Engine No.: 2ZR6007034

Chassis No.: JTDKN36U905741594

Maximum Power
Output: 100.0 kW (134 bhp)

Open Market Value: \$33,120.00

Original Registration
Date: 07 May 2014

First Registration Date: 07 May 2014

Transfer Count: 0

Actual ARF Paid: \$8,368.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 06 May 2022

PARF Rebate Amount: \$6,276.00

Intended COE Rebate Details

COE Expiry Date: 06 May 2022

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$60,414.00

COE Rebate Amount: \$34,673.00

Total Rebate Amount: \$40,949.00**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 03 Oct 2017



Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Last updated on 17 Sep 2017 at 12:38 AM



Tow

Attached
Supplement

SMRT Accident Vehicle Repair Estimates

60 Woodlands Industrial Park E4, Singapore 757705
 FAX Number : 63685592
 Estimator Telephone Number : 68662623
 Accident Reporting Number : 68662672

+ 6 DAY
 12-10-17 / 13:00
 13-10-17 / 0800

3-10-17/08:00

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1166T
 Ref. No : TAX/09/17/2152
 Reg. Date : 07/05/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : KHOO HOCK LIONG
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 25/09/2017 09:40:00 PM
 Accident Reported Date / Time : 27/09/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Taufikh
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024092269
 Special Instruction to ARC, if any :

Towed to TP compound (\$90) / GBB2739E - ERGO
 Before paint photo and after paint photo, FOR CHECK ITEM and REPLACE ITEM. PLEASE CALL SURVEYOR
 TAUFIKH, HP 9749 5749/ EMAIL: taufikh@lkkauto.com
 lumpsum repair
 Prepared Date : 27/09/2017 12:08:13 PM

19/10



SW



19/10/17 11:50 GC Reject RIAH/Lamp Crack 14,39 pass
 E 1/2 (1) F
 KM 424307

Recording : ☐ ☒
 Radio Antenna : ☐ ☒
 1st witness : 3-10-17 Date :
 2nd witness : Date :

Time In: 3/10/17 Towing: ☒
 Time In: 13584/10 Driver:
 Time In: 19/10/17 Towing:
 Time In: 1015 Driver:

Received by (SMRT):

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U905741594

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 2,028.00	1,000.00
Total Spray Painting Charges	: 3,150.00	1,400.00
Total Material Charges	: 32,252.43	20,217.01
Other Charges	: 3,426.00	1,240.00
TOTAL	: 40,856.43	23,857.01
Lum Sum Total	: 40,850.00	23,850.00
No. of Repair Days	: 16.00	15.00
Prepared / Adjusted By	:	TAUFIK (LKK)
Arc / Surveyor Sign Off Date	: 29/09/2017 05:34:53 AM	02/10/2017 04:46:01 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 29/09/2017 05:34:24 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1710-0523

Invoice No :

Quotation Date : 22/10

Invoice Date :

Invoice Amount :

Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	2,028.00	1,000.00
Total Labour	2,028.00	1,000.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	378.00	200.00
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00
TO RESPRAY VIEW MIRROR	180.00	0.00
TO RESPRAY FRONT FENDER RH	378.00	200.00
TO RESPRAY RIM	180.00	0.00
TO RESPRAY FRONT PILLAR RH	180.00	100.00
TO REPSRAY FRONT BUMPER	378.00	200.00
TO RESPRAY FRONT SUPPORT PANEL	180.00	100.00
TO RESPRAY FRT MEMBER, LH	180.00	100.00
TO REPSRAY FRONT HOOD	378.00	200.00
TO RESPRAY FRONT FENDER LH	378.00	200.00
TO RESPRAY FRONT PILLAR RH	180.00	100.00
Total Spray Painting & Panel Beating	3,150.00	1,400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses