

|                                                                                 | Quotation from FIVE | Accepted by Surveyor, if applicable |
|---------------------------------------------------------------------------------|---------------------|-------------------------------------|
| TOWING CHARGE                                                                   | 126.00              | 90.00                               |
| TO CHECK WIRING AND SYSTEM FUNCTION                                             | 80.00               | 40.00                               |
| TO APPLY RUST-PROOFING ON AFFECTED AREA                                         | 200.00              | 80.00                               |
| TO TRANSFER DOOR MECHANISM                                                      | 120.00              | 0.00                                |
| TO REMOVE AND REFIX WING MIRROR                                                 | 120.00              | 0.00                                |
| TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS                                    | 240.00              | 0.00                                |
| TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)                                 | 240.00              | 0.00                                |
| TO DO WHEEL ALIGNMENT / TYRE BALANCING                                          | 120.00              | 80.00                               |
| TO REMOVE AND REFIT WIRE HARDESS                                                | 350.00              | 150.00                              |
| TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER | 150.00              | 100.00                              |
| TO TOP UP A/C GAS                                                               | 120.00              | 100.00                              |
| TO CONDUCT RADIATOR PRESSURE CHECK                                              | 100.00              | 60.00                               |
| TO ALIGN CHASSIS                                                                | 350.00              | 200.00                              |
| TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)                               | 250.00              | 0.00                                |
| TO REPLACE SUNDRY PARTS                                                         | 100.00              | 40.00                               |
| TO WASH AND VACUUM                                                              | 60.00               | 40.00                               |
| TO CHECK & RESET SYSTEM FUNCTION                                                | 350.00              | 150.00                              |
| TO REMOVE AND REFIX UNDERCARRIAGE                                               | 350.00              | 120.00 <i>UK</i>                    |
| <b>Total Other Costs</b>                                                        | <b>3,426.00</b>     | <b>1,250.00</b>                     |

# Part 4 - Spare Parts / Material Usage

| Part Number       | Portion | Stock No | Part Name                      | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Recommendation | Surveyor Approved | Photos Attached |
|-------------------|---------|----------|--------------------------------|-----|-----------------|--------------|------------------|--------------------|-------------------|-----------------|
| 37001-47070       |         | 6505528  | DOOR FRT/RH                    | 1   | 894.40          | 100.00       | 0.00             | Replace            | Repair            | No <i>R</i>     |
|                   |         |          | STICKER DECAL SMRT (DOOR)      | 1   | 60.00           | 0.00         | 60.00            | Replace            | Replace           | No <i>/</i>     |
| 68710-12151       |         |          | HINGE UPPER RH, DOOR           | 1   | 80.50           | 100.00       | 0.00             | Replace            | Repair            | No <i>R</i>     |
| 68730-12120       |         |          | HINGE LOWER RH, DOOR           | 1   | 90.10           | 100.00       | 0.00             | Replace            | Repair            | No <i>R</i>     |
| 68610-47021       |         |          | CHECK ASSY, FR DOOR,           | 1   | 150.30          | 100.00       | 0.00             | Replace            | Repair            | No <i>R</i>     |
| 75851-47900       |         |          | MOULDING BODY, RH              | 0   | 673.60          | 25.00        | 0.00             | Replace            | Not given         | No <i>X</i>     |
| 87910-47330       |         | 6505600  | MIRROR ASSY, RH                | 0   | 1,307.10        | 25.00        | 0.00             | Replace            | Not given         | No <i>X</i>     |
| 87931-47200       |         |          | MIRROR GLASS RH                | 0   | 212.80          | 25.00        | 0.00             | Replace            | Not given         | No <i>X</i>     |
| 81730-62090       |         | 6505466  | MIRROR LAMP RH                 | 0   | 65.30           | 10.00        | 0.00             | Replace            | Not given         | No <i>X</i>     |
| 879157-4010       |         | 6505598  | COVER, OUTER MIRROR, RH        | 0   | 107.40          | 25.00        | 0.00             | Replace            | Not given         | No <i>X</i>     |
| 63801-47050       |         | 6505557  | FENDER FRT/RH                  | 1   | 723.40          | 25.00        | 542.55           | Replace            | Replace           | No <i>/</i>     |
| 75442-47030       |         |          | NAME PLATE (PRIUS)             | 1   | 60.80           | 25.00        | 45.60            | Replace            | Replace           | No <i>/</i>     |
| 62110-47021       |         |          | QUARTER GLASS FRT/RH           | 0   | 234.90          | 25.00        | 0.00             | Replace            | Not given         | No <i>X</i>     |
| 53875-47030       | COMMO N |          | SEALANT W/SCREEN               | 0   | 37.00           | 0.00         | 0.00             | Replace            | Not given         | No <i>X</i>     |
| 53851-47040       |         | 6505553  | FENDER LINER FRT/RH            | 0   | 171.70          | 25.00        | 0.00             | Replace            | Not given         | No <i>X</i>     |
| 42611-47140 (Frt) |         |          | FENDER LINER PAD, FR WHEEL, RH | 0   | 49.30           | 25.00        | 0.00             | Replace            | Not given         | No <i>X</i>     |
| 61131-47030       |         | 6505658  | WHEEL DISC, FRONT              | 0   | 1,484.20        | 25.00        | 0.00             | Replace            | Not given         | No <i>X</i>     |
| 62119-47930       |         |          | PILLAR, FR BODY                | 1   | 363.10          | 100.00       | 0.00             | Replace            | Repair            | No <i>R</i>     |
| 52116-47040       |         | 6505517  | BUMPER FRT                     | 1   | 482.00          | 25.00        | 361.50           | Replace            | Replace           | No <i>/</i>     |
| 52021-47023       |         | 6505516  | BUMPER SUPPORT F/LH            | 1   | 76.40           | 25.00        | 57.30            | Replace            | Replace           | No <i>/</i>     |
| 52611-47080       |         | 6505515  | BUMPER SUPPORT F/RH            | 1   | 76.40           | 25.00        | 57.30            | Replace            | Replace           | No <i>/</i>     |
| 57014-47030       |         | 6505539  | BUMPER REINFORCEMENT FRT       | 1   | 498.40          | 25.00        | 373.80           | Replace            | Replace           | No <i>/</i>     |
| 57013-47030       |         | 6505518  | BUMPER ENERGY ABSORBER FRT     | 1   | 78.80           | 25.00        | 59.10            | Replace            | Replace           | No <i>/</i>     |
| 81511-47050       |         |          | ARM SUB-ASSY, FR BUMPER LH     | 1   | 250.40          | 25.00        | 187.80           | Replace            | Replace           | No <i>S</i>     |
| 53102-47020       |         |          | ARM SUB-ASSY, FR BUMPER RH     | 1   | 250.40          | 25.00        | 187.80           | Replace            | Replace           | No <i>S</i>     |
| 81210-12230       |         |          | LENS & BODY, FR TURN RH        | 0   | 511.80          | 10.00        | 0.00             | Replace            | Not given         | No <i>X</i>     |
|                   |         | 6505541  | BUMPER GRILLE SUB-ASSY, LOWER  | 1   | 311.10          | 25.00        | 233.32           | Replace            | Replace           | No <i>/</i>     |
|                   |         | 6505439  | FOG LAMP RH                    | 0   | 295.20          | 10.00        | 0.00             | Replace            | Not given         | No <i>X</i>     |

| Part Number | Position | Stock No | Part Name                  | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Recommendation | Surveyor Approved | Photos Attached |
|-------------|----------|----------|----------------------------|-----|-----------------|--------------|------------------|--------------------|-------------------|-----------------|
| 52127-47903 |          |          | COVER, FR BUMPER HOLE RH   | 0   | 18.50           | 25.00        | 0.00             | Replace            | Not given         | No X            |
| 52114-47140 |          |          | BRACKET, FR BUMPER         | 1   | 110.40          | 25.00        | 82.80            | Replace            | Replace           | No ✓            |
|             | REAR     |          | NUMBER PLATE               | 1   | 30.00           | 0.00         | 30.00            | Replace            | Replace           | No ✓            |
|             |          |          | NUMBER PLATE FRAME         | 1   | 12.00           | 0.00         | 12.00            | Replace            | Replace           | No ✓            |
| 52127-47903 |          |          | COVER, FR BUMPER HOLE RH   | 0   | 18.50           | 25.00        | 0.00             | Replace            | Not given         | No X            |
| 81210-12230 |          | 6505439  | FOG LAMP RH                | 0   | 295.20          | 10.00        | 0.00             | Replace            | Not given         | No X            |
| 53111-47040 |          | 6505573  | GRILLE, RADIATOR           | 1   | 310.60          | 25.00        | 232.95           | Replace            | Replace           | No ✓            |
| 75310-47010 |          | 6505638  | EMBLEM FRONT               | 1   | 86.50           | 25.00        | 64.87            | Replace            | Replace           | No ✓            |
| 81521-47050 |          |          | LENS & BODY, FR TURN LH    | 1   | 511.80          | 10.00        | 460.62           | Replace            | Replace           | No ✓            |
| 81529-47040 |          |          | BRACKET, FR TURN UPPER LH  | 1   | 24.40           | 25.00        | 18.30            | Replace            | Replace           | No ✓            |
| 81529-47050 |          |          | BRACKET, FR TURN LOWER LH  | 1   | 26.00           | 25.00        | 19.50            | Replace            | Replace           | No ✓            |
| 81529-47060 |          |          | BRACKET, FR TURN CENTER LH | 1   | 58.20           | 25.00        | 43.65            | Replace            | Replace           | No ✓            |
| 76851-47020 |          | 6505616  | BUMPER LIP FRT             | 1   | 139.60          | 25.00        | 104.70           | Replace            | Replace S         | No ✓            |
| 62618-47050 |          | 6505540  | BUMPER FRT ABSORBER LOWER  | 1   | 127.70          | 25.00        | 95.78            | Replace            | Replace S         | No ✓            |
| 53113-47040 |          |          | GRILLE RADIATOR LOWER NO.2 | 1   | 94.60           | 25.00        | 70.95            | Replace            | Replace           | No ✓            |
| 51410-12105 |          |          | UNDER COVER CENTER         | 1   | 448.30          | 25.00        | 336.22           | Replace            | Replace           | No ✓            |
| 82113-47180 |          |          | WIRE, ENGINE ROOM, NO.3    | 1   | 242.00          | 10.00        | 217.80           | Replace            | Replace S         | No ✓            |
| 88790-22131 | COMMO N  |          | THERMISTOR ASSY            | 1   | 107.00          | 10.00        | 96.30            | Replace            | Check             | No X            |
| 88510-22130 |          |          | HORN ASSY, HIGH            | 1   | 110.40          | 25.00        | 82.80            | Replace            | Check             | No X            |
| 88520-22180 |          |          | HORN ASSY, LOW             | 1   | 110.40          | 25.00        | 82.80            | Replace            | Check             | No X            |
| 53294-47030 |          | 6505561  | DEFLECTOR, RADIATOR LH     | 1   | 77.00           | 25.00        | 57.75            | Replace            | Replace           | No ✓            |
| 53293-47040 |          | 6505574  | DEFLECTOR, RADIATOR RH     | 0   | 83.50           | 25.00        | 0.00             | Replace            | Not given         | No X            |
| 88460-47150 |          |          | A/C CONDENSER              | 1   | 1,181.90        | 25.00        | 886.43           | Replace            | Replace S         | No ✓            |
| G9010-47031 |          |          | RADIATOR ASSY, UPPER       | 1   | 679.60          | 25.00        | 509.70           | Replace            | Replace S         | No ✓            |
| 16400-37230 |          | 6505302  | RADIATOR ASSY              | 1   | 1,496.90        | 25.00        | 1,122.68         | Replace            | Replace S         | No ✓            |
| 16711-37040 |          |          | FAN SHROUD                 | 1   | 244.50          | 25.00        | 183.38           | Replace            | Replace S         | No ✓            |
| 16712-37030 |          |          | FAN SHROUD TOP             | 1   | 99.60           | 25.00        | 74.70            | Replace            | Replace S         | No ✓            |
| 16363-37010 |          |          | FAN MOTOR NO 1             | 1   | 538.30          | 25.00        | 403.73           | Replace            | Replace S         | No ✓            |
| 16363-37020 |          |          | FAN MOTOR NO 2             | 1   | 538.30          | 25.00        | 403.73           | Replace            | Replace S         | No ✓            |
| 16361-37010 |          |          | FAN BLADE                  | 1   | 158.60          | 25.00        | 118.95           | Replace            | Replace S         | No ✓            |

| Number          |            |         |                               |   | (\$)     | (%)   | (\$)     | Recommen<br>d | Approved  | Attached |
|-----------------|------------|---------|-------------------------------|---|----------|-------|----------|---------------|-----------|----------|
| 16361-<br>28360 |            |         | FAN BLADE NO 2                | 1 | 204.20   | 25.00 | 153.15   | Replace       | Replace S | No ✓     |
| 16535-<br>20030 |            |         | SUPPORT,<br>RADIATOR,         | 1 | 18.50    | 25.00 | 13.87    | Replace       | Replace   | No ✓     |
| 16534-<br>37010 |            |         | SUPPORT,<br>RADIATOR, LH      | 1 | 17.70    | 25.00 | 13.27    | Replace       | Replace   | No ✓     |
| 16533-<br>28051 |            |         | SUPPORT,<br>RADIATOR, RH      | 1 | 54.50    | 25.00 | 40.88    | Replace       | Check     | No X     |
| 16523-<br>21050 |            |         | CUSHION, RADIATOR             | 2 | 11.30    | 25.00 | 16.95    | Replace       | Check     | No X     |
| 63201-<br>47902 |            |         | SUPPORT SUB-ASSY              | 1 | 1,460.40 | 25.00 | 1,095.30 | Replace       | Replace S | No ✓     |
| 81170-<br>47500 |            | 6505436 | HEAD LAMP LH                  | 1 | 945.20   | 10.00 | 850.68   | Replace       | Replace   | No ✓     |
| 81130-<br>47500 |            | 6505437 | HEAD LAMP RH                  | 1 | 945.20   | 10.00 | 850.68   | Replace       | Replace   | No ✓     |
| 16480-<br>28080 |            |         | COOLANT RESERVE<br>TANK       | 1 | 395.30   | 25.00 | 296.48   | Replace       | Check     | No X     |
| 16261-<br>37070 |            |         | RADIATOR HOSE,<br>BYPASS NO.1 | 1 | 37.20    | 25.00 | 27.90    | Replace       | Check     | No X     |
| 16264-<br>37080 |            |         | RADIATOR HOSE,<br>BYPASS NO.2 | 1 | 29.00    | 25.00 | 21.75    | Replace       | Check     | No X     |
| 16267-<br>37030 |            |         | RADIATOR HOSE,<br>BYPASS NO.3 | 1 | 37.20    | 25.00 | 27.90    | Replace       | Check     | No X     |
| 16281-<br>37030 |            |         | RADIATOR HOSE,<br>BYPASS NO.4 | 1 | 37.20    | 25.00 | 27.90    | Replace       | Check     | No X     |
| 16571-<br>37140 |            | 6505303 | RADIATOR TOP<br>HOSE NO 1     | 1 | 42.40    | 25.00 | 31.80    | Replace       | Check     | No X     |
| 16577-<br>37020 |            | 6505304 | RADIATOR TOP<br>HOSE NO 2     | 1 | 126.50   | 25.00 | 94.88    | Replace       | Check     | No X     |
| 16572-<br>37120 |            |         | RADIATOR HOSE<br>LOWER        | 1 | 42.40    | 25.00 | 31.80    | Replace       | Check     | No X     |
| 88707-<br>47041 |            |         | TUBE SUB-ASSY,<br>SUCTION     | 1 | 371.40   | 25.00 | 278.55   | Replace       | Check     | No X     |
| 88703-<br>47040 |            |         | HOSE SUB-ASSY,<br>DISCHARGE   | 1 | 386.90   | 25.00 | 290.18   | Replace       | Check     | No X     |
| 88704-<br>47090 |            |         | HOSE SUB-ASSY,<br>SUCTION     | 1 | 405.40   | 25.00 | 304.05   | Replace       | Check     | No X     |
| 88319-<br>47120 |            |         | WIPER WASHER<br>INLET         | 1 | 36.90    | 25.00 | 27.68    | Replace       | Check     | No X     |
| 17750-<br>37010 |            |         | INLET ASSY, AIR               | 1 | 232.50   | 25.00 | 174.38   | Replace       | Check     | No X     |
| 17881-<br>54360 | FRONT      |         | AIR DUCT BOX NO 1             | 1 | 208.20   | 25.00 | 156.15   | Replace       | Check     | No X     |
| 17882-<br>54361 | COMMO<br>N |         | AIR DUCT BOX NO 2             | 1 | 15.22    | 25.00 | 11.42    | Replace       | Check     | No X     |
| 17894-<br>37010 |            |         | RESONATOR,<br>INTAKE          | 1 | 57.20    | 25.00 | 42.90    | Replace       | Check     | No X     |
| 17700-<br>38252 |            |         | AIR CLEANER ASSY              | 1 | 929.90   | 25.00 | 697.43   | Replace       | Replace S | No ✓     |
| 17111-<br>08040 |            |         | MANIFOLD, INTAKE              | 1 | 1,055.10 | 25.00 | 791.33   | Replace       | Check     | No X     |
| 88421-<br>47010 |            |         | SENSOR, VACUUM                | 1 | 602.10   | 10.00 | 541.89   | Replace       | Check     | No X     |
| 11212-<br>37090 |            |         | COVER, CYLINDER               | 1 | 165.20   | 25.00 | 123.90   | Replace       | Replace S | No ✓     |
| 09200-<br>49025 |            |         | INVERTER W<br>CONVERTER       | 1 | 5,390.20 | 10.00 | 4,851.18 | Replace       | Replace S | No ✓     |
| 09110-<br>47011 |            |         | INVERTER BRACKET<br>TRAY      | 1 | 251.60   | 25.00 | 188.70   | Replace       | Replace S | No ✓     |

| Part Number  | Quantity | Stock No | Part Name                   | Qty | List Price (\$) | Discount (%) | Final Price (\$) | Recommend | Surveyor Approved | Notes Attached |
|--------------|----------|----------|-----------------------------|-----|-----------------|--------------|------------------|-----------|-------------------|----------------|
| G9214-47060  |          |          | BRACKET, INVERTER, NO.1     | 1   | 31.40           | 25.00        | 23.55            | Replace   | Check             | No X           |
| G9140-47010  |          |          | COVER ASSY, INVERTER, LH    | 1   | 54.50           | 25.00        | 40.88            | Replace   | Check             | No X           |
| G9225-47021  |          |          | HOSE, INVERTER NO.1         | 1   | 80.00           | 25.00        | 60.00            | Replace   | Check             | No X           |
| G9229-47020  |          |          | HOSE, INVERTER COOLING NO.5 | 1   | 125.30          | 25.00        | 93.98            | Replace   | Check             | No X           |
| G9236-47031  |          |          | HOSE, INVERTER COOLING NO.6 | 1   | 37.40           | 10.00        | 33.66            | Replace   | Check             | No X           |
| G9226-47020  |          |          | HOSE, INVERTER COOLING NO.2 | 1   | 90.10           | 10.00        | 81.09            | Replace   | Check             | No X           |
| G9040-47090  |          |          | PUMP ASSY, WATER            | 1   | 454.00          | 25.00        | 340.50           | Replace   | Check             | No X           |
|              | COMMO N  |          | COOLANT                     | 4   | 12.32           | 0.00         | 49.28            | Replace   | Replace           | No X           |
| G92148-47051 |          |          | CABLE, GENERATOR            | 1   | 169.10          | 10.00        | 152.19           | Replace   | Check             | No X           |
| G91148-47051 |          |          | CABLE, MOTOR INVERTER       | 1   | 199.10          | 10.00        | 179.19           | Replace   | Check             | No X           |
| G9164-47070  |          |          | WIRE, FRAME                 | 1   | 1,680.90        | 25.00        | 1,260.68         | Replace   | Check             | No X           |
| G92663-47060 |          |          | FUSE BLOCK, COVER LOWER     | 1   | 18.50           | 10.00        | 16.65            | Replace   | Check             | No X           |
| G92741-47010 |          |          | FUSE BLOCK, ENGINE ROOM     | 1   | 148.50          | 10.00        | 133.65           | Replace   | Check             | No X           |
| G92662-47110 |          |          | FUSE BLOCK, TOP COVER       | 1   | 82.30           | 10.00        | 74.07            | Replace   | Check             | No X           |
|              |          |          | EDS SYSTEM                  | 1   | 9,450.00        | 10.00        | 8,505.00         | Replace   | Check             | No X           |
| G92111-47772 |          |          | WIRE, ENGINE ROOM           | 1   | 5,567.10        | 10.00        | 5,010.39         | Replace   | Replace           | No X           |
| G95084-47011 |          |          | WIPER GARNISH COVER, LH     | 1   | 23.80           | 25.00        | 17.85            | Replace   | Check             | No X           |
| G95083-47011 |          |          | WIPER GARNISH COVER, RH     | 1   | 23.80           | 25.00        | 17.85            | Replace   | Replace           | No X           |
| G95708-47101 |          |          | WIPER GARNISH               | 1   | 614.00          | 25.00        | 460.50           | Replace   | Check             | No X           |
| G91444-47050 |          | 6505472  | UNDER COVER SIDE/LH         | 1   | 46.10           | 25.00        | 34.57            | Replace   | Replace           | No X           |
| G902812020   |          |          | MEMBER SUB-ASSY, FR LH      | 1   | 810.70          | 100.00       | 0.00             | Replace   | Repair            | No R           |
| G9104-47020  |          | 6505507  | RADIATOR LOWER SUPPORT      | 1   | 876.30          | 25.00        | 657.23           | Replace   | Replace           | No X           |
| G93301-47060 |          | 6505555  | HOOD PANEL                  | 1   | 748.10          | 25.00        | 561.08           | Replace   | Replace           | No X           |
| G93395-47020 |          |          | HOOD END PANEL SEAL         | 1   | 35.50           | 25.00        | 26.63            | Replace   | Check             | No X           |
| G93341-47020 |          |          | HOOD PANEL INSULATOR        | 1   | 390.50          | 25.00        | 292.87           | Replace   | Replace           | No X           |
| G93420-47070 |          |          | HOOD HINGE LH               | 1   | 55.90           | 25.00        | 41.92            | Replace   | Replace           | No X           |
| G93410-47070 |          |          | HOOD HINGE RH               | 1   | 55.90           | 25.00        | 41.92            | Replace   | Replace           | No X           |
| G93557-47010 |          |          | HOOD AUXILIARY CATCH        | 1   | 8.60            | 25.00        | 6.45             | Replace   | Check             | No X           |
| G93510-47102 |          |          | HOOD LOCK                   | 1   | 128.90          | 25.00        | 96.67            | Replace   | Replace           | No X           |
| G93630-47050 |          |          | CABLE ASSY, HOOD            | 1   | 52.20           | 25.00        | 39.15            | Replace   | Check             | No X           |

| Part Number                 | Portion | Order No | Part Name                      | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Recommendation | Surveyor Approved | Notes Attached             |
|-----------------------------|---------|----------|--------------------------------|-----|-----------------|--------------|------------------|--------------------|-------------------|----------------------------|
| 53289-47032                 |         |          | COVER, RADIATOR                | 1   | 122.80          | 25.00        | 92.10            | Replace            | Replace           | No ✓                       |
| 53802-47050                 |         | 6505558  | FENDER FRT/LH                  | 1   | 723.40          | 25.00        | 542.55           | Replace            | Replace           | No ✓                       |
| 75374-47051                 |         |          | NAME PLATE (HYBRID)            | 1   | 51.90           | 25.00        | 38.92            | Replace            | Replace           | No ✓                       |
| 53876-47030                 |         | 6505554  | FENDER LINER FRT/LH            | 1   | 171.70          | 25.00        | 128.77           | Replace            | Replace           | No ✓                       |
| 53852-47020                 |         |          | FENDER LINER PAD, FR WHEEL LH  | 0   | 49.30           | 25.00        | 0.00             | Replace            | Not given         | No X                       |
| 42611-47140 (Frt)           |         | 6505658  | WHEEL DISC. FRONT              | 0   | 1,484.20        | 25.00        | 0.00             | Replace            | Not given         | No X                       |
| 62120-47021                 |         |          | QUARTER GLASS FRT/LH           | 0   | 234.90          | 25.00        | 0.00             | Replace            | Not given         | No X                       |
|                             | COMMO N |          | SEALANT W/SCREEN               | 0   | 37.00           | 0.00         | 0.00             | Replace            | Not given         | No X                       |
| 61132-47030                 |         |          | PILLAR, FR BODY, LH            | 1   | 363.10          | 100.00       | 0.00             | Replace            | Repair            | No R                       |
| 81220-12230                 |         | 6505438  | FOG LAMP LH                    | 1   | 280.10          | 10.00        | 252.09           | Replace            | Replace S         | No <del>ht</del> <i>ht</i> |
| 12361-37090                 |         |          | ENGINE MOUNTING FRT            | 1   | 198.00          | 25.00        | 148.50           | Replace            | Replace S         | No <del>ht</del> <i>ht</i> |
| 12372-37110                 |         |          | ENGINE MOUNTING LH             | 1   | 210.70          | 25.00        | 158.02           | Replace            | Replace S         | No <del>ht</del> <i>ht</i> |
| 12305-37300                 |         |          | ENGINE MOUNTING RH             | 1   | 276.20          | 25.00        | 207.15           | Replace            | Replace S         | No <del>ht</del> <i>ht</i> |
| 12371-37250                 |         |          | ENGINE MOUNTING REAR           | 1   | 198.70          | 25.00        | 149.02           | Replace            | Replace S         | No <del>ht</del> <i>ht</i> |
| 12311-37090                 |         |          | ENGINE MOUNTING BRACKET, FRONT | 1   | 87.10           | 25.00        | 65.32            | Replace            | Replace S         | No <del>ht</del> <i>ht</i> |
| 51108-47020                 |         |          | SIDE CHASSIC FRT/LH            | 1   | 172.90          | 25.00        | 129.67           | Replace            | Replace S         | No <del>ht</del> <i>ht</i> |
| TOTAL MATERIALS             |         |          |                                |     |                 |              | 40,315.63        | 25,271.27          |                   |                            |
| TOTAL MATERIALS(Discounted) |         |          |                                |     |                 |              | 32,252.43        | 20,217.01          |                   |                            |

Added Spare Parts / Material Usage After Surveyor Signed off

142370

| Part Number                   | Portion | Part Name                      | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check | LT Check |
|-------------------------------|---------|--------------------------------|-----|-----------------|--------------|------------------|-----------|----------------|----------|
| 12220-12230                   |         | FOG LAMP LH                    | 1   | 280.10          | 10.00        | 252.09           | Replace   | Replace        | No       |
| 12361-37090                   |         | ENGINE MOUNTING FRT            | 1   | 198.00          | 25.00        | 148.50           | Replace   | Replace        | No       |
| 12372-37110                   |         | ENGINE MOUNTING LH             | 1   | 210.70          | 25.00        | 158.02           | Replace   | Replace        | No       |
| 12305-37300                   |         | ENGINE MOUNTING RH             | 1   | 276.20          | 25.00        | 207.15           | Replace   | Replace        | No       |
| 12371-37250                   |         | ENGINE MOUNTING REAR           | 1   | 198.70          | 25.00        | 149.02           | Replace   | Replace        | No       |
| 12311-37090                   |         | ENGINE MOUNTING BRACKET, FRONT | 1   | 87.10           | 25.00        | 65.32            | Replace   | Replace        | No       |
| 11108-17020                   |         | SIDE CHASSIC FRT/LH            | 1   | 172.90          | 25.00        | 129.67           | Replace   | Replace        | No       |
| TOTAL SUPPLEMENTARY MATERIALS |         |                                |     |                 |              | 1,109.77         |           |                |          |

25,001.31 25,271.27

20,001.05 - 202

1000 20,217.01

2650 + 1,000.00

23651.05 + 2,650.00

23,867.01

45 \$23,850/-

45 \$23,650



Toyota Prius

Price Range

Depreciation

2015

Vehicle Type

Home » Used Cars » Prime Motor &amp; Leasing » Toyota Prius Hybrid 1.8A

## Tools &amp; Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

## Toyota Prius Hybrid 1.8A

Overview

Financial

Accessories

Similar

Research

Photos

Map



PRIME MOTOR &amp; LEASING

 (CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COM  
 • PRIME CAR RENTAL & TAXI SERVICES PTE LTD • SECTION CREDIT & MOTOR LEASING PTE LTD • BEST PETROL AND DIESEL SUPP

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

## Car Details

Price \$89,900

Depreciation \$11,280 /yr

View models with similar depreciation

Reg Date 28-Aug-2015

(7yrs 8mths 29days COE left)

Manufactured 2015

Mileage 53,100 km (23.5k /yr)

Transmission Auto

Engine Cap 1,797 cc

Curb Weight 1,310 kg

Fuel type Petrol-Electric

**Features** Airbags, ABS, Reliable And Fuel Efficient 1.8L 4 Cylinder Hybrid Engine Producing 134 Bhp, Multi Steering Controls.

**Accessories** Leather Seats, Sports Rims, Audio System.

**Description** Elegant Silver Toyota Prius Hybrid 1.8, With 134 Bhp, One Owner Only, Low Fuel Consumption With Hybrid, Low Maintenance Cost, Very Well Maintained.

COE \$61,001

OMV \$19,152

ARF \$5,000

Dereg Value \$51,013 as of today (change)

No. of Owners 1



## Seller Information

## Company

Address

Location

Office No

## Car Leasing



Compare

## Enquire PARF/COE Rebate for Registered Vehicle

|                                                                                                                                                                                                                         |                                      |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|
| <b>Vehicle Owner Particulars</b>                                                                                                                                                                                        |                                      |
| Owner ID Type                                                                                                                                                                                                           | Company                              |
| Owner ID                                                                                                                                                                                                                | 5369K                                |
| <b>Vehicle Details</b>                                                                                                                                                                                                  |                                      |
| Vehicle No.                                                                                                                                                                                                             | SHB1166T                             |
| Vehicle to be Exported                                                                                                                                                                                                  | No                                   |
| Intended De-registration Date                                                                                                                                                                                           | 29 Nov 2017                          |
| Vehicle Make                                                                                                                                                                                                            | TOYOTA                               |
| Vehicle Model                                                                                                                                                                                                           | PRIUS TAXI (SMRT)                    |
| Primary Colour                                                                                                                                                                                                          | Maroon                               |
| Manufacturing Year                                                                                                                                                                                                      | 2014                                 |
| Engine No.                                                                                                                                                                                                              | 2ZR6007034                           |
| Chassis No.                                                                                                                                                                                                             | JTDKN36U905741594                    |
| Maximum Power Output                                                                                                                                                                                                    | 100.0 kW (134 bhp)                   |
| Open Market Value                                                                                                                                                                                                       | \$33,120.00                          |
| Original Registration Date                                                                                                                                                                                              | 07 May 2014                          |
| First Registration Date                                                                                                                                                                                                 | 07 May 2014                          |
| Transfer Count                                                                                                                                                                                                          | 0                                    |
| Actual ARF Paid                                                                                                                                                                                                         | \$8,368.00                           |
| <b>Intended PARF Rebate Details</b>                                                                                                                                                                                     |                                      |
| PARF Eligibility                                                                                                                                                                                                        | Yes                                  |
| PARF Eligibility Expiry Date                                                                                                                                                                                            | 06 May 2022                          |
| PARF Rebate Amount                                                                                                                                                                                                      | \$6,276.00                           |
| <b>Intended COE Rebate Details</b>                                                                                                                                                                                      |                                      |
| COE Expiry Date                                                                                                                                                                                                         | 06 May 2022                          |
| COE Category                                                                                                                                                                                                            | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years)                                                                                                                                                                                                       | 8                                    |
| PQP Paid                                                                                                                                                                                                                | \$60,414.00                          |
| COE Rebate Amount                                                                                                                                                                                                       | \$33,496.00                          |
| <b>Total Rebate Amount</b>                                                                                                                                                                                              | <b>\$39,772.00</b>                   |
| <b>Message</b>                                                                                                                                                                                                          |                                      |
| Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. |                                      |

The information contained herein is correct as at 29 Nov 2017

89900  
 - 12200  
 77,699  
 - 14100  
 63599

OK



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI17018807/T1qbe2

5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

Date : 20-12-2017



Code : EGI

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |              |                |            |
|--------------|--------------|----------------|------------|
| Insured Veh. | GBB 2739E    | Veh. Inspected | SHB 1166T  |
| Policy No.   |              | Coverage (\$)  | 0.00       |
| Claim No.    | DSMCV1702398 | Excess (\$)    | 0.00       |
| Assign From  | YEE PEI LEE  | Assign Date    | 02/10/2017 |

## 2. Vehicle Particulars & Condition

|              |                   |              |            |
|--------------|-------------------|--------------|------------|
| Make & Model | TOYOTA PRIUS      | c.c          | 1798       |
| Engine No.   | HIDDEN            | Year of Reg. | 2014       |
| Chassis No.  | JTDKN36U905741594 | Colour       | MAROON     |
| Odometer     | -                 | Steering     | IN ORDER   |
| Brakes       | IN ORDER          | Modification | SPORTS RIM |
| General      | GOOD              |              |            |

## 3. Conditions of Tyres

|                | Size       | Make   | Balance |
|----------------|------------|--------|---------|
| R/H Front Tyre | 195/65 R15 | FALKEN | 6 mm    |
| L/H Front Tyre | 195/65 R15 | FALKEN | 6 mm    |
| R/H Rear Tyre  | 195/65 R15 | FALKEN | 6 mm    |
| L/H Rear Tyre  | 195/65 R15 | FALKEN | 6 mm    |

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S, FRONT, FRONT O/S PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

|                |                                                                                      |                 |            |
|----------------|--------------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 25/09/2017                                                                           | Inspection Date | 02/10/2017 |
| Survey held at | SMRT AUTOMOTIVE SERVICES PTE LTD<br>60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 |                 |            |

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 15 Working Days



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1166T

| Qty                         | Description of Parts                     | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|------------------------------------------|-----------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                          |           |                           |                   |
| 1                           | FENDER FRT/RH (DISC 25%)                 | BENT      | 723.40                    | 542.55            |
| 1                           | NAME PLATE (PRIUS) (DISC 25%)            | NECESSARY | 60.80                     | 45.60             |
| 1                           | BUMPER FRT (DISC 25%)                    | DISTORTED | 482.00                    | 361.50            |
| 1                           | BUMPER SUPPORT F/LH (DISC 25%)           | NECESSARY | 76.40                     | 57.30             |
| 1                           | BUMPER SUPPORT F/RH (DISC 25%)           | NECESSARY | 76.40                     | 57.30             |
| 1                           | BUMPER REINFORCEMENT FRT (DISC 25%)      | BENT      | 498.40                    | 373.80            |
| 1                           | BUMPER ENERGY ABSORBER FRT (DISC 25%)    | CRACKED   | 78.80                     | 59.10             |
| 1                           | ARM SUB-ASSY, FR BUMPER LH (DISC 25%)    | BENT      | 250.40                    | 187.80            |
| 1                           | ARM SUB-ASSY, FR BUMPER RH (DISC 25%)    | BENT      | 250.40                    | 187.80            |
| 1                           | BUMPER GRILLE SUB-ASSY, LOWER (DISC 25%) | DEFORMED  | 311.10                    | 233.32            |
| 1                           | BRACKET, FR BUMPER (DISC 25%)            | NECESSARY | 110.40                    | 82.80             |
| 1                           | GRILLE, RADIATOR (DISC 25%)              | DEFORMED  | 310.60                    | 232.95            |
| 1                           | EMBLEM FRONT (DISC 25%)                  | NECESSARY | 86.50                     | 64.87             |
| 1                           | BRACKET, FR TURN UPPER LH (DISC 25%)     | DISTORTED | 24.40                     | 18.30             |
| 1                           | BRACKET, FR TURN LOWER LH (DISC 25%)     | DISTORTED | 26.00                     | 19.50             |
| 1                           | BRACKET, FR TURN CENTER LH (DISC 25%)    | DISTORTED | 58.20                     | 43.65             |
| 1                           | BUMPER LIP FRT (DISC 25%)                | DEFORMED  | 139.60                    | 104.70            |
| 1                           | BUMPER FRT ABSORBER LOWER (DISC 25%)     | DEFORMED  | 127.70                    | 95.78             |
| 1                           | GRILLE RADIATOR LOWER NO.2 (DISC 25%)    | DEFORMED  | 94.60                     | 70.95             |
| 1                           | UNDER COVER CENTER (DISC 25%)            | TORN      | 448.30                    | 336.22            |
| 1                           | DEFLECTOR, RADITAOR LH (DISC 25%)        | DEFORMED  | 77.00                     | 57.75             |
| 1                           | A/C CONDENSER (DISC 25%)                 | BENT      | 1,181.90                  | 886.43            |
| 1                           | RADIATOR ASSY, UPPER (DISC 25%)          | BENT      | 679.60                    | 509.70            |
| 1                           | RADIATOR ASSY (DISC 25%)                 | BENT      | 1,496.90                  | 1,122.68          |
| 1                           | FAN SHROUD (DISC 25%)                    | CRACKED   | 244.50                    | 183.38            |
| 1                           | FAN SHROUD TOP (DISC 25%)                | DISTORTED | 99.60                     | 74.70             |
| 1                           | FAN MOTOR NO 1 (DISC 25%)                | JAMMED    | 538.30                    | 403.73            |
| 1                           | FAN MOTOR NO 2 (DISC 25%)                | DISTORTED | 538.30                    | 403.73            |
| 1                           | FAN BLADE (DISC 25%)                     | CRACKED   | 158.60                    | 118.95            |
| 1                           | FAN BLADE NO 2 (DISC 25%)                | CUT       | 204.20                    | 153.15            |
| 1                           | SUPPORT, RADIATOR (DISC 25%)             | BENT      | 18.50                     | 13.87             |

Report Ref No. CS/EGI17018807/T1qbe2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

| Qty | Description of Parts                         | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|----------------------------------------------|-----------|---------------------------|-------------------|
| 1   | SUPPORT, RADIATOR, LH (DISC 25%)             | BENT      | 17.70                     | 13.27             |
| 1   | SUPPORT SUB-ASSY (DISC 25%)                  | BENT      | 1,460.40                  | 1,095.30          |
| 1   | AIR CLEANER ASSY (DISC 25%)                  | CRACKED   | 929.90                    | 697.43            |
| 1   | COVER, CYLINDER (DISC 25%)                   | DEFORMED  | 165.20                    | 123.90            |
| 1   | INVERTER BRACKET TRAY (DISC 25%)             | DISTORTED | 251.60                    | 188.70            |
| 1   | WIPER GARNISH COVER, RH (DISC 25%)           | DEFORMED  | 23.80                     | 17.85             |
| 1   | UNDER COVER SIDE/LH (DISC 25%)               | DEFORMED  | 46.10                     | 34.57             |
| 1   | RADIATOR LOWER SUPPORT (DISC 25%)            | BENT      | 876.30                    | 657.23            |
| 1   | HOOD PANEL (DISC 25%)                        | BENT      | 748.10                    | 561.08            |
| 1   | HOOD PANEL INSULATOR (DISC 25%)              | TORN      | 390.50                    | 292.87            |
| 1   | HOOD HINGE LH (DISC 25%)                     | BENT      | 55.90                     | 41.92             |
| 1   | HOOD HINGE RH (DISC 25%)                     | BENT      | 55.90                     | 41.92             |
| 1   | HOOD LOCK (DISC 25%)                         | BENT      | 128.90                    | 96.67             |
| 1   | COVER, RADIATOR (DISC 25%)                   | DEFORMED  | 122.80                    | 92.10             |
| 1   | FENDER FRT / LH (DISC 25%)                   | BENT      | 723.40                    | 542.55            |
| 1   | NAME PLATE (HYBRID) (DISC 25%)               | NECESSARY | 51.90                     | 38.92             |
| 1   | FENDER LINER FRT/LH (DISC 25%)               | TORN      | 171.70                    | 128.77            |
| 1   | LENS & BODY, FR TURN LH (DISC 10%)           | DISTORTED | 511.80                    | 460.62            |
| 1   | WIRE, ENGINE ROOM, NO. 3 (DISC 10%)          | CUT       | 242.00                    | 217.80            |
| 1   | HEAD LAMP LH (DISC 10%)                      | CRACKED   | 945.20                    | 850.68            |
| 1   | HEAD LAMP RH (DISC 10%)                      | CRACKED   | 945.20                    | 850.68            |
| 1   | INVERTER W CONVERTER (DISC 10%)              | CRACKED   | 5,390.20                  | 4,851.18          |
| 1   | WIRE, ENGINE ROOM (DISC 10%)                 | CUT       | 5,567.10                  | 5,010.39          |
| 1   | STICKER DECAL SMRT (DOOR) (SN)               | NECESSARY | 60.00                     | 60.00             |
| 1   | NUMBER PLATE (SN)                            | MISSING   | 30.00                     | 30.00             |
| 1   | NUMBER PLATE FRAME (SN)                      | MISSING   | 12.00                     | 12.00             |
| 4   | COOLANT @\$12.32 (SN)                        | NECESSARY | 49.28                     | 49.28             |
| 1   | FOG LAMP LH (ADDITIONAL) (DISC 25%)          | CRACKED   | 280.10                    | 252.09            |
| 1   | ENGINE MOUNTING FRT (ADDITIONAL) (DISC 25%)  | BENT      | 198.00                    | 148.50            |
| 1   | ENGINE MOUNTING LH (ADDITIONAL) (DISC 25%)   | BENT      | 210.70                    | 158.02            |
| 1   | ENGINE MOUNTING RH (ADDITIONAL) (DISC 25%)   | BENT      | 276.20                    | 207.15            |
| 1   | ENGINE MOUNTING REAR (ADDITIONAL) (DISC 25%) | BENT      | 198.70                    | 149.02            |

Report Ref No. CS/EGI17018807/T1qbe2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 6

| Qty | Description of Parts                                   | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------------------------------|---------------|---------------------------|-------------------|
| 1   | ENGINE MOUNTING BRACKET, FRONT (ADDITIONAL) (DISC 25%) | BENT          | 87.10                     | 65.32             |
| 1   | SIDE CHASSIS FRT / LH (ADDITIONAL) (DISC 25%)          | BENT          | 172.90                    | 129.67            |
| 1   | MOULDING BODY, RH                                      | NOT NECESSARY | 673.60                    | -                 |
| 1   | MIRROR ASSY, RH                                        | NOT NECESSARY | 1,307.10                  | -                 |
| 1   | MIRROR GLASS RH                                        | NOT NECESSARY | 212.80                    | -                 |
| 1   | MIRROR LAMP RH                                         | NOT NECESSARY | 65.30                     | -                 |
| 1   | COVER, OUTER MIRROR, RH                                | NOT NECESSARY | 107.40                    | -                 |
| 1   | QUARTER GLASS FRT/RH                                   | NOT NECESSARY | 234.90                    | -                 |
| 1   | SEALANT W/SCREEN                                       | NOT NECESSARY | 37.00                     | -                 |
| 1   | FENDER LINER FRT/RH                                    | NOT NECESSARY | 171.70                    | -                 |
| 1   | FENDER LINER PAD, FR WHEEL RH                          | NOT NECESSARY | 49.30                     | -                 |
| 1   | WHEEL DISC FRONT                                       | NOT NECESSARY | 1,484.20                  | -                 |
| 1   | LENS & BODY, FR TURN RH                                | NOT NECESSARY | 511.80                    | -                 |
| 1   | FOG LAMP RH                                            | NOT NECESSARY | 295.20                    | -                 |
| 1   | COVER, FR BUMPER HOLE RH                               | NOT NECESSARY | 18.50                     | -                 |
| 1   | COVER, FR BUMPER HOLE RH                               | NOT NECESSARY | 18.50                     | -                 |
| 1   | FOG LAMP RH                                            | NOT NECESSARY | 295.20                    | -                 |
| 1   | THERMISTOR ASSY                                        | NOT NECESSARY | 107.00                    | -                 |
| 1   | HORN ASSY, HIGH                                        | NOT NECESSARY | 110.40                    | -                 |
| 1   | HORN ASSY, LOW                                         | NOT NECESSARY | 110.40                    | -                 |
| 1   | DEFLECTOR, RADIATOR RH                                 | NOT NECESSARY | 83.50                     | -                 |
| 1   | SUPPORT, RADIATOR, RH                                  | NOT NECESSARY | 54.50                     | -                 |
| 2   | CUSHION, RADIATOR @\$11.30                             | NOT NECESSARY | 22.60                     | -                 |
| 1   | COOLANT RESERVE TANK                                   | NOT NECESSARY | 395.30                    | -                 |
| 1   | RADIATOR HOSE, BYPASS NO.1                             | NOT NECESSARY | 37.20                     | -                 |
| 1   | RADIATOR HOSE, BYPASS NO.2                             | NOT NECESSARY | 29.00                     | -                 |
| 1   | RADIATOR HOSE BYPASS NO.3                              | NOT NECESSARY | 37.20                     | -                 |
| 1   | RADIATOR HOSE BYPASS NO.4                              | NOT NECESSARY | 37.20                     | -                 |
| 1   | RADIATOR TOP HOSE NO.1                                 | NOT NECESSARY | 42.40                     | -                 |
| 1   | RADIATOR TOP HOSE NO.2                                 | NOT NECESSARY | 126.50                    | -                 |
| 1   | RADIATOR HOSE LOWER                                    | NOT NECESSARY | 42.40                     | -                 |
| 1   | TUBE SUB-ASSY, SUCTION                                 | NOT NECESSARY | 371.40                    | -                 |

Report Ref No. CS/EGI17018807/T1qbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 6

| Qty | Description of Parts          | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------|---------------|---------------------------|-------------------|
| 1   | HOSE SUB-ASSY, DISCHARGE      | NOT NECESSARY | 386.90                    | -                 |
| 1   | HOSE SUB-ASSY, SUCTION        | NOT NECESSARY | 405.40                    | -                 |
| 1   | WIPER WASHER INLET            | NOT NECESSARY | 36.90                     | -                 |
| 1   | INLET ASSY, AIR               | NOT NECESSARY | 232.50                    | -                 |
| 1   | AIR DUCT BOX NO 1             | NOT NECESSARY | 208.20                    | -                 |
| 1   | AIR DUCT BOX NO 2             | NOT NECESSARY | 15.22                     | -                 |
| 1   | RESONATOR INTAKE              | NOT NECESSARY | 57.20                     | -                 |
| 1   | MANIFOLD, INTAKE              | NOT NECESSARY | 1,055.10                  | -                 |
| 1   | SENSOR, VACUUM                | NOT NECESSARY | 602.10                    | -                 |
| 1   | BRACKET, INVERTER, NO.1       | NOT NECESSARY | 31.40                     | -                 |
| 1   | COVER ASSY, INVERTER, LH      | NOT NECESSARY | 54.50                     | -                 |
| 1   | HOSE, INVERTER NO.1           | NOT NECESSARY | 80.00                     | -                 |
| 1   | HOSE, INVERTER COOLING NO.5   | NOT NECESSARY | 125.30                    | -                 |
| 1   | HOSE, INVERTER COOLING NO.6   | NOT NECESSARY | 37.40                     | -                 |
| 1   | HOSE, INVERTER COOLING NO.2   | NOT NECESSARY | 90.10                     | -                 |
| 1   | PUMP ASSY, WATER              | NOT NECESSARY | 454.00                    | -                 |
| 1   | CABLE, GENERATOR              | NOT NECESSARY | 169.10                    | -                 |
| 1   | CABLE, MOTOR INVERTER         | NOT NECESSARY | 199.10                    | -                 |
| 1   | WIRE, FRAME                   | NOT NECESSARY | 1,680.90                  | -                 |
| 1   | FUSE BLOCK, COVER LOWER       | NOT NECESSARY | 18.50                     | -                 |
| 1   | FUSE BLOCK, ENGINE ROOM       | NOT NECESSARY | 148.50                    | -                 |
| 1   | FUSE BLOCK, TOP COVER         | NOT NECESSARY | 82.30                     | -                 |
| 1   | EDS SYSTEM                    | NOT NECESSARY | 9,450.00                  | -                 |
| 1   | WIPER GARNISH COVER, LH       | NOT NECESSARY | 23.80                     | -                 |
| 1   | WIPER GARNISH                 | NOT NECESSARY | 614.00                    | -                 |
| 1   | HOOD END PANEL SEAL           | NOT NECESSARY | 35.50                     | -                 |
| 1   | HOOD AUXILIARY CATCH          | NOT NECESSARY | 8.60                      | -                 |
| 1   | CABLE ASSY, HOOD              | NOT NECESSARY | 52.20                     | -                 |
| 1   | FENDER LINER PAD, FR WHEEL LH | NOT NECESSARY | 49.30                     | -                 |
| 1   | WHEEL DISC FRONT              | NOT NECESSARY | 1,484.20                  | -                 |
| 1   | QUARTER GLASS FRT / LH        | NOT NECESSARY | 234.90                    | -                 |
| 1   | SEALANT W/SCREEN              | NOT NECESSARY | 37.00                     | -                 |

Report Ref No. CS/EGI17018807/T1qbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

| Qty | Description of Parts                                                                                                                                                                                   | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|---------------------------|-------------------|
| 1   | DOOR FRT / RH                                                                                                                                                                                          | TO REPAIR SEE LABOUR | 894.40                    | -                 |
| 1   | HINGE UPPER RHF, DOOR                                                                                                                                                                                  | TO REPAIR SEE LABOUR | 80.50                     | -                 |
| 1   | HINGE LOWER RHF, DOOR                                                                                                                                                                                  | TO REPAIR SEE LABOUR | 90.10                     | -                 |
| 1   | CHECK ASSY, FR DOOR                                                                                                                                                                                    | TO REPAIR SEE LABOUR | 150.30                    | -                 |
| 1   | PILLAR, FR DOOR                                                                                                                                                                                        | TO REPAIR SEE LABOUR | 363.10                    | -                 |
| 1   | PILLAR, FR BODY, LH                                                                                                                                                                                    | TO REPAIR SEE LABOUR | 363.10                    | -                 |
| 1   | MEMBER SUB-ASSY, FR LH                                                                                                                                                                                 | TO REPAIR SEE LABOUR | 810.70                    | -                 |
|     |                                                                                                                                                                                                        |                      | 58,870.20                 | 25,271.31         |
|     | <b>LABOUR</b>                                                                                                                                                                                          |                      |                           |                   |
|     | TO REPAIR FRONT PORTION. INCLUSIVE OF THE REPAIR OF DOOR FRT / RH, HINGE UPPER RHF, DOOR, HINGE LOWER RHF, DOOR, CHECK ASSY, FR DOOR, PILLAR, FR DOOR, PILLAR, FR BODY, LH AND MEMBER SUB-ASSY, FR LH. |                      | 2,028.00                  | 1,000.00          |
|     | TO RESPRAY FRONT DOOR RH.                                                                                                                                                                              |                      | 378.00                    | 200.00            |
|     | TO RESPRAY ROCKER PANEL MOULDING.                                                                                                                                                                      | NOT NECESSARY        | 180.00                    | -                 |
|     | TO RESPRAY VIEW MIRROR.                                                                                                                                                                                | NOT NECESSARY        | 180.00                    | -                 |
|     | TO RESPRAY FRONT FENDER RH.                                                                                                                                                                            |                      | 378.00                    | 200.00            |
|     | TO RESPRAY RIM.                                                                                                                                                                                        | NOT NECESSARY        | 180.00                    | -                 |
|     | TO RESPRAY FRONT PILLAR RH.                                                                                                                                                                            |                      | 180.00                    | 100.00            |
|     | TO RESPRAY FRONT BUMPER.                                                                                                                                                                               |                      | 378.00                    | 200.00            |
|     | TO RESPRAY FRONT SUPPORT PANEL.                                                                                                                                                                        |                      | 180.00                    | 100.00            |
|     | TO RESPRAY FRT MEMBER, LH                                                                                                                                                                              |                      | 180.00                    | 100.00            |
|     | TO RESPRAY FRONT HOOD.                                                                                                                                                                                 |                      | 378.00                    | 200.00            |
|     | TO RESPRAY FRONT FENDER LH                                                                                                                                                                             |                      | 378.00                    | 200.00            |
|     | TO RESPRAY FRONT PILLAR RH.                                                                                                                                                                            |                      | 180.00                    | 100.00            |
|     | TOWING CHARGE.                                                                                                                                                                                         |                      | 126.00                    | 90.00             |
|     | TO CHECK WIRING AND SYSTEM FUNCTION.                                                                                                                                                                   |                      | 80.00                     | 40.00             |
|     | TO APPLY RUST-PROOFING ON AFFECTED AREA.                                                                                                                                                               |                      | 200.00                    | 80.00             |

Report Ref No. CS/EGI17018807/T1qbe2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 6

| Qty                                                                         | Description of Parts                                                             | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|----------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|                                                                             | TO TRANSFER DOOR MECHANISM.                                                      | NOT NECESSARY | 120.00                    | -                 |
|                                                                             | TO REMOVE AND REFIX WING MIRROR.                                                 | NOT NECESSARY | 120.00                    | -                 |
|                                                                             | TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS.                                    | NOT NECESSARY | 240.00                    | -                 |
|                                                                             | TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)                                  | NOT NECESSARY | 240.00                    | -                 |
|                                                                             | TO DO WHEEL ALIGNMENT / TYRE BALANCING.                                          |               | 120.00                    | 80.00             |
|                                                                             | TO REMOVE AND REFIT WIRE HARNESS.                                                |               | 350.00                    | 150.00            |
|                                                                             | TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER. |               | 150.00                    | 100.00            |
|                                                                             | TO TOP UP A/C GAS.                                                               |               | 120.00                    | 100.00            |
|                                                                             | TO CONDUCT RADIATOR PRESSURE CHECK.                                              |               | 100.00                    | 60.00             |
|                                                                             | TO ALIGN CHASSIS.                                                                |               | 350.00                    | 200.00            |
|                                                                             | TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM.                                     | NOT NECESSARY | 250.00                    | -                 |
|                                                                             | TO REPLACE SUNDRY PARTS.                                                         |               | 100.00                    | 40.00             |
|                                                                             | TO WASH AND VACUUM.                                                              |               | 60.00                     | 40.00             |
|                                                                             | TO CHECK & RESET SYSTEM FUNCTION.                                                |               | 350.00                    | 150.00            |
|                                                                             | TO REMOVE AND REFIX UNDERCARRIAGE. (ADDITIONAL)                                  |               | 350.00                    | 120.00            |
|                                                                             |                                                                                  |               | 8,604.00                  | 3,650.00          |
| <b>GRAND TOTAL</b>                                                          |                                                                                  |               | <b>67,474.20</b>          | <b>28,921.31</b>  |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                                  |               |                           | <b>23,850.00</b>  |

Report Ref No. CS/EGI17018807/T1qbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.