

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7671L - AIG*Not Noted**11 Sep @ 11,35d***AAD1709-251**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB7671L - ROEL

KL1LA69RJB077878

CHEVROLET

EPICA 2.0

24.09.2017

AIG**PART****LIST**

1	1	Rear Bumper	\$	<i>Bu</i> 1,202.00	—
2	1	Rear Bumper Beam	\$	<i>Bu</i> 239.94	—
3	1	Rear Bumper Centre Absorber	\$	<i>CM</i> 260.00	—
4	1	Rear Bumper Side Retainer RH	\$	<i>CM</i> 68.76	—
5	1	Rear Bumper Side Retainer LH	\$	<i>CM</i> 68.76	—
6	1	Rear Bumper Reflectors RH	\$	<i>Bu</i> 119.74	—
7	1	Rear Bumper Reflectors LH	\$	<i>Bu</i> 119.74	—
8	1	Rear Bumper Tow Hook Cover	\$	<i>Sn</i> 93.00	X
9	1	Rear Luggage Floor Panel	\$	<i>Bu/Bu</i> 973.00	—
10	1	Rear Luggage Floor Panel Insulator	\$	<i>me</i> 63.50	—
11	1	Rear Luggage Floor Panel Trim Board	\$	<i>Sn</i> 378.00	X
12	1	Rear End Panel Outer	\$	<i>Bu</i> 623.76	—
13	1	Rear end panel inner	\$	<i>Bu</i> 336.50	—
14	1	Rear End Panel Inner Trim	\$	<i>D-1</i> 263.84	—
15	1	Bootlid	\$	<i>Bu</i> 973.00	—
16	1	Bootlid inner trim board	\$	<i>Deform</i> 400.00	—
17	1	Bootlid inner handle	\$	<i>Sn</i> 45.55	X
18	1	Bootlid Weatherstrip	\$	<i>Cr</i> 344.28	<i>50/50 1924850</i>
19	1	Bootlid Lock - Top	\$	<i>Red</i> 466.56	—
20	1	Bootlid 'CHEVROLET' Badge	\$	<i>me</i> 120.62	—
21	1	Bootlid Logo	\$	<i>me</i> 138.84	—
22	1	Bootlid 'EPICA LT' Badge	\$	<i>me</i> 119.84	—
23	1	Bootlid Reflector Centre	\$	<i>CM</i> 217.97	—
24	1	Bootlid Reflector RH	\$	<i>CM</i> 128.40	—
25	1	Bootlid Reflector LH	\$	<i>CM</i> 128.40	—
26	1	Bootlid Hinge RH	\$	<i>R</i> 120.00	X
27	1	Bootlid Hinge LH	\$	<i>R</i> 120.00	X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1709-251

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7671L - AIG

28	1	Rear Gas T/Gate Spring RH	\$	Sn	286.90	X
29	1	Rear Gas T/Gate Spring LH	\$	Sn	286.90	X
30	1	Rear Tail Lamp RH	\$	My car	479.30	—
31	1	Rear Tail Lamp Panel RH	\$	Bn	359.00	—
32	1	Rear Tail Lamp LH	\$	Bn	479.30	—
33	1	Rear Tail Lamp Panel LH	\$	Bn	359.00	—
34	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	R	1,110.00	X
35	1	Rear Fender RH	\$	R Bn	1,145.00	X
36	1	Rear Fender Inner Trim RH	\$	CMA	418.44	—
37	1	Rear Fender LH	\$	Bn	1,145.00	—
38	1	Rear Fender Inner Trim LH	\$	CMA	418.44	—
39	1	Rear number plate lamp RH	\$	Sn	25.00	X
40	1	Rear number plate lamp LH	\$	Sn	25.00	X
41	1	Rear Fender Inner Cowling RH	\$	Sn	76.60	X
42	1	Rear Fender Inner Cowling LH	\$	Sn	76.60	X

TOTAL	\$	14,824.48
10%	\$	1,482.45
	\$	13,342.03

Special Nett

1	1Set	Licence Plate With Holder	\$	Nd	60.00	45Sn
2	1Set	Bootlid inner trim board Clip	\$	me	40.00	—
3	1Set	Rear Bumper Parking Sensor	\$	Nd	300.00	—
4	1Set	Rear Bumper Fastener Clip	\$	Nd	44.00	—
5	1Set	Rear Fender Inner Trim Clip LH	\$	me	30.00	—
6	1Set	Rear Fender Inner Trim Clip RH	\$	me	30.00	—
7	1Set	Rear Bumper End Dust Cover Clip	\$	me	30.00	X
8	1	Rear Boot Sticker 'Trans-cab'	\$	me	30.00	—
9	1	Rear Boot Sticker '6555-3333'	\$	me	30.00	—
10	1	Rear Exhaust Mounting	\$	Sn	10.00	X
11	2	Rear Windscreen Sealant	\$	me	80.00	40Sn
12	1	Rear Windscreen Inner Sponge Seal	\$	me	100.00	30Sn
13	1	Spare Tyre	\$	Sn	180.00	X
14	1	Spare Wheel Rim	\$	me	126.74	X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1709-251**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7671L - AIG

TOTAL	\$	1,090.74
TOTAL PARTS	\$	14,432.77

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,050.00	2000
To Check Electrical Lighting Concerned.	\$	170.00	200
To Rust-Proofing Of The Affected Areas.	\$	170.00	1500
Putty And Spray Painting Of The Affected Portion.	\$	4,200.00	12000
To reinstall rear bumper parking sensor.	\$	170.00	600
To transfer of end panel fittings and conduct water seepage test.	\$	170.00	1000
To transfer of luggage floor panel fittings and conduct water seepage test.	\$	170.00	800
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	1200
To transfer of boot fittings and conduct water seepage test.	\$	170.00	600
To transfer of Fender fittings, attachments and perform water seepage test.	\$	~ 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	~ 380.00	X
To check steering geometry and computer wheel alignment	\$	~ 220.00	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7671L - AIG**AAD1709-251**

	\$	10,210.00
TOTAL	\$	24,642.77

Repair Days**15 Days** ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: