

ASS. REC. BY:

REF: CS/MSG17018938/Tltb m2

Special Instruction:

Surveyor

Taufik

ASSIGNMENT (Office)

From (Person):

Lionel Tan

of

MSIG

Date/Time

3/10/17 1:33pm

Estimated Cost:

Bill to

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SLF6121 X

Insured:

SCH 9111B

at Workshop m/s

Performance Motor

Tel:

63190174

of

303 Alexandra Road, 159941

Policy No.

Claim No.

531587

Sum Insured

Excess:

Make of Veh.

(Client's Record)

D.O.A. 2/10/2017

CA / REV / REP. / REV 24 HRS

'wp'

10-10-2017

H.O.D. Endorsement:

Date/Time 3/10/17 2:00pm

Person Contacted

caroline

Vehicle IN (OUT)

Date/Time

Action/Instruction

(✓) Estimate Chua

SLF6121X - X

SCH 9111B - X

Confirm \$3,212.40, 3 days. (Red: 3569.20 : 52%)

Taught


REF: MS19

ASSIGNMENT

From _____ Date 10/10/17
 Estimated Cost _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No SLF6121 X
 at Workshop / Mile Performance
 at 303 Alexandra Rd, 159941
 Insured _____
 Policy No _____
 Claims No _____
 Sum Insured _____ Excess _____
 (Client's Record) _____
 Make of Van _____

10 am owner waiting

Remark: The veh had commenced its repair at the time of inspection.



Ball or Market Value _____
 D+C Accident Root _____ Consistent? Yes or No
 G/A PR Seen _____ Consistent? Yes or No
 Est. Repairs _____ days Res. Yes or No
 Lum Sum _____ % 3 Val. Yes or No

CA / REV / REP. 1-24 HRS 'wp'

Date _____ Person Contacted Chng Vehicle IN / OUT
 Date Time Action Instruction

Van No SLF6121X Yr Regr 746/Sep
 Type ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____

Make BMW 216D Yr 1996
 Colour white A/C _____ Insured / Std / NI / NA
 Sp Reading 29353 T Ratio Insured / Std / NI / NA

Eng No _____
 C No WBS HZE 520505845075

Gen Cond ☒ Good / Fair / Poor / Burnt
 Steering ☒ In order / Jammed / Leaked / Burnt or _____
 Brake ☒ In order / Jammed / Leaked / Burnt or _____
 Mod Nil / S/Rim / STD A/Rim or _____

Tyre Size P 2.5/55 R17
 R _____

BS / DUN / EXNOVA ☒ FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front _____ Rear _____
 R Ba 6 mm R Ba 6 mm
 L Ba 6 mm L Ba 6 mm
 D.O.A _____ D.O.E 10/10/17 clean

Survey held at PML
 Des of Damages Fr / Rea / O/S / N/S / UIC / Rooftop or _____

The UIC / Chassis frame / Body Structure affected due to collision

RECEIVED 12 FEB 2018

12/2/2018

Date Time File Pass to: ☐ Preli. Report
012 Typist ☒ Final Report
 Date Time File Return to:

Days Of Repair: 3
 Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Invs (\$)
☐ Weekend (\$)

Survey Fee	
Transportation	
1. S-RS	300
2. Photos	10
3. Others	
TOTAL	210

Report Format: TP
 Lump Sum / (B.I.): \$ 3212.40



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17018938/T1tb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 03-10-2017		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SCH 9111B	Veh. Inspected	SLF 6121X	
Policy No.	28992407QMY	Coverage (\$)	0.00	
Claim No.	531587	Excess (\$)	0.00	
Assign From	MERIMEN (LIONEL TAN)	Assign Date	03/10/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/10/2017	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Oct 2017		03 Oct 2017 13:33 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MS LEE MAY LING, ID: S7804262A		
Main Claimant:	TAN HSIAO CHING, ID: S7198105C		
Vehicle Reg. No.:	SLF6121X	Date of Loss:	02/10/2017 16:00 - :59
Claim Type:	TP / 531587	Policy/Cover Note No.:	28992407QMY (Comprehensive) Coverage: 10/08/2017 - 12/08/2018
Vehicle Reg. No. (Insured):	SCH9111B	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/10/2017]		
Adj Asg. Remarks:	Please contact Ms Caroline @ 6319 0174 to arrange for survey.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 12 Oct 2017

Preliminary Advice

Insured Vehicle No : SCH9111B
TP Vehicle No : SLF6121X
Make : BMW 216D
Date of Inspection :
Inspection At :

Accident Date : 02/10/2017
Assignment Date : 03/10/2017
Est. Duration of Repair :

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,256.31
Revised Amount	:S\$	3,046.55
Check Items (Estimated)	:S\$	2,635.65
Total	:S\$	5,682.20
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/10/2017 09:57
Date Of Accident	02/10/2017 16:30
Exact Location Of Accident	TRAFFIC JUNCTION MACRITCHIE RESERVOIR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF6121X
Insured/Policyholder	
Name Of Registered Owner	TAN HSIAO CHING
NRIC No	S7198105C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96773577
Alternative Phone No	OFFICE-96773577

Vehicle Particulars

Manufacturer	BMW
Model	216D TOURER
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN787180
Cover Note Number	

Driver

Name of Driver	TAN HSIAO CHING
NRIC No	S7198105C
Date Of Birth	28/08/1971
Occupation	INDOOR
Date Of Driving Pass	19/03/1996
Driving Experience	21 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96773577
Fax Number	
Contact Number	OFFICE-96773577
EMail Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SCH9111B

Vehicle Make/Model/Colour BLACK

Details Of Properties

Name of Driver LEE MAY LING

NRIC/Passport Number S7804262A

Contact Number 96675059

Address

Postcode

Insurance Company Name MSIG INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage FRONT

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date &
Time


Driver's Signature (if driver is not the policyholder) / Date
& Time


Witnessed by Reporting Centre
Personnel

Sketch Plan




Sketch Plan Pg. 2

Describe Circumstances of the Accident


At Traffic Junction, when traffic light turn green, I about to move off, I felt an impact and notice a car hit me from behind.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time
3 Oct 2017

Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel
3/10/2017
@ 838hr

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



10/10/2017
Morning
Shay & Repin

GST REG. NO : M2 - 0020081 - X

ESTIMATE

03 OCT 2017

Estimate No. : b1 44337
Date Estimated : 03/10/2017
Prepared By : Chua Kee Sin

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -
Tan Hsiao Ching (Chen Xiaojing)
21 Tampines Avenue 8
#14-34

Singapore 529604

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLF6121X	5B45075	01/09/2016	216d G TOURER	0

DESCRIPTION

Replace rear bumper and remove attachment etc include knock on accident dent

850 1,700.00

Spray painting rear bumper

934 1,038.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 177.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

230? 271.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries.

80 150.00

Total Labour 1: 3,513.00

DESCRIPTION

RR BUMPER LH SIDE GUIDE
RR BUMPER RH SIDE GUIDE
REAR BUMPER CARRIER
SUPPORT
RR BUMPER LH INNER SIDE GUIDE
RR BUMPER RH INNER SIDE GUIDE
REAR BUMPER TRIM STRIP (CHROM)
LEFT PROTECT
RIGHT PROTEC
REAR BUMPER PANEL PRIMED (LINES PDC
REAR BUMPER TOWING FLAP EYE PRIMED
DECOUPING RING PDC TORQUE CONVERTER
ULTRASONIC SENSOR MINERALWEISS(WA96

QTY	PRIC	VALUE
1	58.55	? 58.55
1	58.55	? 58.55
1	413.45	? 413.45
1	57.85	? 57.85
1	64.30	? 64.30
1	64.30	? 64.30
1	105.65	? 105.65
1	2.05	? 2.05
1	2.05	? 2.05
1	942.75	? 942.75
1	27.10	? 27.10
4	4.95	? 19.80
4	363.05	? 1,452.20

Total Parts : 3,268.60

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 44337
Date Estimated : 03/10/2017
Prepared By : Chua Kee Sin

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLF6121X	5B45075	01/09/2016	216d G TOURER	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Rgn No. _____ Claim No. _____

Date/Time 10/10/17 @ _____ Excess S\$ _____

Surveyor's Name Tanjiah _____ Sign _____

Surveyor's Tel 97495744 _____ Authorised Yes/No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes/No PML Yes/No

Surveyor's E-mail tanjiah @ lkkauto.com

No. of Working Days Recommend 3 days

Labour 1	:	3,513.00
Parts	:	3,268.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	474.71
Grand Total	:	<u>7,256.31</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 44337
Date Estimated : 03/10/2017
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Tan Hsiao Ching (Chen Xiaojing)
21 Tampines Avenue 8
#14-34

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 529604

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE		
SLF6121X	5B45075	01/09/2016	216d G TOURER	0		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT			
To replace rear bumper and attachment include knocking out dents caused by the accident	850.00		850.00			
To spray paint rear bumper	934.00		934.00			
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00		150.00			
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00			
Sundries.	80.00		80.00			

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER TRIM STRIP (CHROM)	105.65	1.00		105.65
REAR BUMPER PANEL PRIMED (LINES PDC)	942.75	1.00		942.75

SUPPLEMENTARY ITEMS

Total Labour :	2,164.00
Total Parts :	1,048.40
Total Labour & Parts :	3,212.40
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,212.40
GST @7%:	224.87
Grand Total :	3,437.27

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17018938/T1TBN2

Date: 13/02/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28992407QMY
Claimant Vehicle No :	SLF6121X	Insured Vehicle No :	SCH9111B
Date of Loss:	02/10/2017	Nature of Claim:	TP
		Claim No:	531587

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF6121X	Engine No:	39159558B37C15A
Make & Model:	BMW 216D, 1.5 D Gran Tourer (F46) (A)	Chassis No:	WBA2E320305B45075
Reg. Date:	01/09/2016 (Man. Year: 2016)	Odometer:	29353 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R17	Rear Tyre Size:	205/55R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,418.60	1,128.40	2,290.20	66.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,363.00	2,084.00	1,279.00	38.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,781.60	3,212.40	3,569.20	52.63
+ GST 7.00/7.00% (S\$)	474.71	224.87	249.84	52.63
Nett Amount (S\$)	7,256.31	3,437.27	3,819.04	52.63

INSPECTION

Date of Assignment:	03/10/2017	
Date Inspected:	10/10/2017 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Feb 2018)
Parts:	M1-MPV	BMW 216D 1.5 D Gran Tourer (F46) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF6121X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*RR BUMPER LH SIDE GUIDE	Not Necessary	58.55 FS	*- FS
2	1	*RR BUMPER RH SIDE GUIDE	Not Necessary	58.55 FS	*- FS
3	1	*REAR BUMPER CARRIER	Not Necessary	413.45 FS	*- FS
4	1	*SUPPORT	Not Necessary	57.85 FS	*- FS
5	1	*RR BUMPER LH INNER SIDE GUIDE	Not Necessary	64.30 FS	*- FS
6	1	*RR BUMPER RH INNER SIDE GUIDE	Not Necessary	64.30 FS	*- FS
7	1	*REAR BUMPER TRIM STRIP (CHROM)	Necessary	105.65 FS	*105.65 FS
8	1	*LEFT PROTECT	Not Necessary	2.05 FS	*- FS
9	1	*RIGHT PROTECT	Not Necessary	2.05 FS	*- FS
10	1	*REAR BUMPER PANEL PRIMED (LINES PDC)	Deformed	942.75 FS	*942.75 FS
11	1	*REAR BUMPER TOWING FLAP EYE PRIMED	Not Necessary	27.10 FS	*- FS
12	4	*ULTRASONIC SENSOR MINERAL WEISS (WA96)	Not Necessary	1,452.20 FS	*- FS
13	1	*SUNDRIES	Necessary	150.00 FS	*80.00 FS
14	4	*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	19.80 FS	*- FS
F=Franchise part. S=SpcNett.				Total Parts (S\$)	3,418.60 1,128.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT	New	1,700.00	850.00
2	SPRAY PAINTING REAR BUMPER	New	1,038.00	934.00
3	TO REMOVE OLD PDC ASSEMBLY,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
4	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	-
5	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			3,363.00	2,084.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >