

ASS. REC. BY:

REF

CS/MSG17018952/Rlrbez

Special Instructions

SUBJECT

Meimien

RCSU

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSG

Date/Time

3/10/17 3:59pm

Estimated Cost

Ratio

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBA 9207 H

Insured:

YN 6817B

at Workshop m/s

Mora Automotive

Tel:

6272 3892

of

15 Fan Yoong Road, 629792

Policy No

28618297 MKC

Claim No:

531486

Sum Insured

Excess:

Make of Veh:

(Client's Record)

D.O.A

26/09/17

CA / REV / REP. / REV 24 HRS

'wp'

4/10/17

Date/Time:

3/10/17 4:05pm

Person Contacted

ERIC

H.O.D. Endorsement

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction
	(✓) Estimate
	GBA 9207 H - X
	YN 6817B - CS/MSG17008621 / Arbe 2 - D.O.A: 2/5/17
	Sent press through meimien.

Surveyor

REF:

1093N

Let Expires 31/Mar/2018

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 22K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 15 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No:

GBA 9207H

Yr Regn: 2008 APR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

pick-up

Make:

MITSUBISHI L200 D/CAB c.c. 2477

Colour:

BLACK

A/C: Insured / Std / NI / NA

Sp. Reading

369932

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MMB 5NKB407D155 264

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205R16C

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Road stung

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A

26/01/17

D.O.I.

04/10/17

Survey held at

MONA CF4)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

31/10/16 AM Confirmed LS \$14,300f and 15 days with Alan. (Red 6181.75, 30%)

RECEIVED JAN 2018

Date/Time. File Pass to?

☐

Preli. Report

1) \_\_\_\_\_  
Date/Time. File Return to?☐

Final Report

2) \_\_\_\_\_

Days Of Repair: 15Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Report Format: TP

Lump Sum / I.B.I: (\$ 14,300f)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) \$ + RS. \$

) Photos

) Others

TOTAL

300

10

310

# Survey Department Check List (Case Handler)

Reference No. : Q/MAG17018952/R1rb  
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin ( Catherine )**: Case handler to make sure all Information created by the assignment team are **ACCURATE**.

## (1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor ( Raoul )**

: Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

## (2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

## (3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

## (4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

Catherine 31/1/18  
Case Handler Date

\*C: Critical \*N: Non-Critical

21/05/21




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17018952/R1rb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 03-10-2017		
		Code : MSG		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YN 6817B	Veh. Inspected	GBA 9207H	
Policy No.	28618297MKC	Coverage (\$)	0.00	
Claim No.	531486	Excess (\$)	0.00	
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	03/10/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	26/09/2017	Inspection Date		
Survey held at	MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Oct 2017		03 Oct 2017 15:59 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	BAN CHOON MARKETING PTE LTD, Co. Reg. No.: 198304071N		
Main Claimant:	CHINA CONSTRUCTION (SOUTH PACIFIC) DEVELOPMENT CO, Co. Reg. No.: 199201093N		
Vehicle Reg. No.:	GBA9207H	Date of Loss:	26/09/2017 00:00 - :59
Claim Type:	TP / 531486	Policy/Cover Note No.:	28618297MKC Coverage: 10/11/2016 - 09/11/2017
Vehicle Reg. No. (Insured):	YN6817B	Policy No. (Claimant):	
		Excess:	
Repairer:	Mova Automotive Pte Ltd (FAN YOONG BRANCH) 15 Fan Yoong Road, CNG Singapore Centre, 629792 Boon Lay - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/10/2017]		

### ASSOCIATED MAIL RECEIVED

[View All](#) | [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#) | [Search Tasks](#) | [Create New Task](#) | [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Christina Wong

Date: 05 Oct 2017

## **Preliminary Advice**

Insured Vehicle No	: YN6817B	Accident Date	: 26/09/2017
TP Vehicle No	: GBA9207H	Assignment Date	: 03/10/2017
Make	: MITSUBISHI L200	Est. Duration of Repair	: 15.00
Date of Inspection	: 04/10/2017		
Inspection At	: MOVA AUTOMOTIVE PTE LTD (FAN YOONG BRANCH) 15 FAN YOONG ROAD, CNG SINGAPORE CENTRE SINGAPORE 629792		

## **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,481.75
Revised Amount	:S\$	15,625.00
Check Items (Estimated)	:S\$	2,241.75
Total	:S\$	17,866.75

Lump Sum Repair	:S\$
-----------------	------

## **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

## **Remarks**

( ) The vehicle is economical/not economical for repair.

( x ) The above survey was conducted on a 'without prejudice' basis.

## Enquire PARF/COE Rebate for Registered Vehicle

---

### Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	8102R

---

### Vehicle Details

Vehicle No.	GBA9207H
Vehicle to be Exported	Yes
Intended De-registration Date	08 Dec 2017
Vehicle Make	MITSUBISHI
Vehicle Model	L200 DOUBLE CAB 2.5L TURBO 5M/T DIESEL
Primary Colour	Black
Manufacturing Year	2008
Engine No.	4D56UCBB0787
Chassis No.	MMBJNKB407D155264
Maximum Power Output	-
Open Market Value	\$21,535.00
Original Registration Date	01 Apr 2008
First Registration Date	01 Apr 2008
Transfer Count	1
Actual ARF Paid	\$21,535.00

---

### Intended PARF Rebate Details

PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

---

### Intended COE Rebate Details

COE Expiry Date	30 Nov 2027
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	10
PQP Paid	\$45,915.00
COE Rebate Amount	\$45,812.00
Total Rebate Amount	\$45,812.00

The information contained herein is correct as at 08 Dec 2017

OK

Text size + -

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 1093N

### Vehicle Details

Vehicle No.: GBA9207H

Vehicle to be Exported: Yes

Intended De-registration  
Date: 27 Sep 2017

Vehicle Make: MITSUBISHI

Vehicle Model: L200 DOUBLE CAB 2.5L TURBO 5M/T DIESEL

Primary Colour: Black

Manufacturing Year: 2008

Engine No.: 4D56UCBB0787

Chassis No.: MMBJNKB407D155264

Maximum Power  
Output: -

Open Market Value: \$21,535.00

Original Registration  
Date: 01 Apr 2008

First Registration Date: 01 Apr 2008

Transfer Count: 1

Actual ARF Paid: \$21,535.00

### Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry  
Date: -

PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 31 Mar 2018

COE Category: C - Goods Vehicle &amp; Bus

COE Period(Years): 10

QP Paid: \$17,610.00

COE Rebate Amount: \$899.00

**Total Rebate Amount: \$899.00**

The information contained herein is correct as at 27 Sep 2017

OK



TP MSIG

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/09/2017 10:58
Date Of Accident	26/09/2017 17:20
Exact Location Of Accident	ALONG ALEXANDRA ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBA9207H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHINA CONSTRUCTION (SOUTH PACIFIC) DEVELOPMENT CO
Co Reg No	199201093N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64912933

### Vehicle Particulars

Manufacturer	MITSUBISHI
Model	L200 DOUBLE CAB 2.5L TURBO 5M/T DIESEL
Exact Purpose for which vehicle was being used at time of accident	

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

### Driver

Name of Driver	NG KEE LENG
NRIC No	S1425124C
Date Of Birth	26/06/1960
Occupation	INDOOR
Date Of Driving Pass	04/07/1983
Driving Experience	34 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82607873
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address  
Postcode  
Was driver an employee of the Insured's Company YES  
If No, Relationship of the Driver with the Insured  
Vehicle Registration Number of Driver's Own Vehicle -  
Vehicle -  
Insurance Company of Driver's Own Vehicle -  
-

#### General Information of the Accident

Type Of Accident CHAIN COLLISION  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Was any body injured in the Accident? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 2

#### Details of Police Action

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

REFER TO THE SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKJ5876Z  
Vehicle Make/Model/Colour  
Details Of Properties  
Name of Driver  
NRIC/Passport Number  
Contact Number 91558236  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### Details of Witness

Name  
Phone Number  
Email Address

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number YN6817B  
Vehicle Make/Model/Colour

**Details Of Properties**

Name of Driver

NRIC/Passport Number

Contact Number 81209873

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**Details of Witness**

Name

Phone Number

Email Address

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



X

*Ng.*



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

**Sketch Plan**

\_\_\_\_\_ A: SKJ 5876 Z

← \_\_\_\_\_ B: GBA 9207H.

← A \* B \* C \_\_\_\_\_ C: YN 6817B.

← \_\_\_\_\_

# Sketch Plan Pg. 2

Describe Circumstances of the Accident		LICENSE PLATE NUMBER: GBA 9207H.	
ACCIDENT DATE:	26/9/2017.	CONTACT NUMBER:	82607873 / 62274537.
ACCIDENT TIME:	17:20 hr.	EMAIL:	
LOCATION:	Along Alexandra road.		
<p>Along Alexandra road on second lane. I was stopped and wait for the traffic light, suddenly a vehicle (YN6817B) bang me from behind, then make me move forward to hit the front vehicle (SKJ5876Z).</p> <p>There was nobody injury in the accident.</p>			
<p>NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY.</p> <p>PLEASE CHECK YOUR POLICY FOR MORE INFORMATION.</p>			
Please state:			
<input type="checkbox"/> Claim Own Policy <input checked="" type="checkbox"/> Claim Third Party <input type="checkbox"/> Claim OD/TP at other workshop <input type="checkbox"/> Reporting Only			

## Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

x. Ng.

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

## Celine Fong (LKKAUTO)

**From:** Celine Fong (LKKAUTO)  
**Sent:** Wednesday, 31 January 2018 10:48 AM  
**To:** Alan Chng  
**Cc:** Admin A; SUR; Rasul (LKKAUTO); Janice Lee (LKKAUTO)  
**Subject:** RE: 1st reminder finalization for veh no:GBA9207H \*\*\* LKK REF : CS/MSG17018952/R1rb

Dear Alan,

Confirm Lump Sum \$14,300.00 and 15 days of repairs.

Best Regards,

**Celine Fong**

**LKK Auto Consultants Pte Ltd**

phone: 6256-3561 | email: [celinefong@lkkauto.com](mailto:celinefong@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Mei Kwan (LKKAUTO)  
**Sent:** Thursday, 25 January 2018 7:56 AM  
**To:** Alan Chng <tuckmeng@mova.com.sg>; Rasul (LKKAUTO) <Rasul@lkkauto.com>; Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>  
**Cc:** Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** RE: 1st reminder finalization for veh no:GBA9207H \*\*\* LKK REF : CS/MSG17018952/R1rb

Dear Alan,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CS/MSG17018952/R1rb	Janice

*To check availability of the case handler, you may contact the undersigned.*

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

**From:** Alan Chng [<mailto:tuckmeng@mova.com.sg>]

**Sent:** Wednesday, 24 January, 2018 10:17 PM

**To:** Rasul (LKKAUTO) <Rasul@lkkauto.com>



**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159418  
Tel : (65) 6476 3333  
Fax : (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**  
Block 100B,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722

Tel : (65) 6272 3892  
Fax : (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0088864-2

## Estimate

29/09/2017

**MSIG INSURANCE (S) PTE LTD (SGX CENTRE)**  
**16, RAFFLES QUAY**  
**#24-01 HONG LEONG BUILDING**  
**SINGAPORE 048581.**

Attention :- XA013

Page # :- 1

Veh # :- GBA9207H

Veh Model :- MITSUBISHI DOUBLE CAB

Estimate# :- CK416459

Claim # :-

ACC. Date :- 26/09/17

Terms :- C.O.D Days

Remarks :-

*Alan 96869276*

No.	Description	Qty	U.Price	Amounts S\$
<b>LIST ITEMS :</b>				
1.	FRONT BUMPER	1 PC	985.00	985.00
2.	FRONT BUMPER SIDE BRACKET	2 PC	70.00	140.00
3.	FRONT BUMPER GRILLE LH	1 PC	195.00	195.00
4.	FRONT BUMPER GRILLE RH	1 PC	195.00	195.00
5.	FRONT BUMPER LOGO	1 PC	60.00	60.00
6.	FRONT BUMPER LOWER GRILLE	1 PC	230.00	230.00
7.	FRONT BUMPER REINFORCEMENT	1 PC	489.00	489.00
8.	FRONT AIR INTERCOOLER	1 PC	1,300.00	1,300.00
9.	FRONT BUMPER CLIPS	10 PC	5.00	50.00
10.	FRONT HEADLAMP	2 PC	600.00	1,200.00
11.	REAR TAILLAMP	2 PC	495.00	990.00
12.	REAR TAILGATE	1 PC	2,300.00	2,300.00
13.	TAILGATE HINGE	2 PC	160.00	320.00
14.	TAILGATE LOCK	2 PC	160.00	320.00
15.	TAILGATE HANDLE	1 PC	150.00	150.00
16.	TAILGATE 3RD BRAKE LAMP	1 PC	180.00	180.00
17.	TAILGATE (DID) EMBLEM	1 PC	60.00	60.00
18.	TAILGATE (L200) EMBLEM	1 PC	60.00	60.00
19.	TAILGATE LOGO	1 PC	60.00	60.00
20.	REAR BUMPER	1 PC	985.00	985.00
21.	REAR BUMPER REFLECTOR LAMP	2 PC	110.00	220.00
22.	REAR CABIN FLOOR PANEL	1 PC	3,500.00	3,500.00
23.	REAR FENDER	2 PC	2,300.00	4,600.00
24.	REAR MUDFLAP	2 PC	150.00	300.00
25.	REAR REINFORCEMENT	1 PC	400.00	400.00
LIST TOTAL S\$				19,289.00
25% DISCOUNT S\$				-4,822.25
				14,466.75
<b>SPECIAL NET ITEMS :</b>				
1.	FRONT NUMBER PLATE	1 PC	50.00	50.00
2.	REAR NUMBER PLATE	1 PC	50.00	50.00
3.	REAR PARKING SENSOR	1 PC	300.00	300.00
4.	TAILGATE (70KM/H) STICKER	1 PC	15.00	15.00
SPECIAL NET TOTAL S\$				415.00
<b>LABOUR :</b>				
TO INSEPCT FRONT & REAR LIGHTING WATER AND LEAKAGE TEST				60.00
TO REMOVE & INSTALL A/C CONDENSER, RADIATOR IN ORDER TO STRAIGHTEN SUPPORT PANEL				140.00
TO REMOVE & INSTALL REAR CABIN IN ORDER TO CUT OFF DAMAGED PANEL & STRAIGHTEN				1,000.00
TO STRAIGHTEN FRONT SUPPORT PANEL, CUT OFF				



# Estimate

29/09/2017

**MSIG INSURANCE (S) PTE LTD (SGX CENTRE)**  
**16, RAFFLES QUAY**  
**#24-01 HONG LEONG BUILDING**  
**SINGAPORE 048581.**

Attention :- XA013


Page # :- 1 129565  
 Veh # :- GBA9207H  
 Veh Model :- MITSUBISHI DOUBLE CAB  
 Estimate# :- CK416459  
 Claim # :-  
 ACC. Date :- 26/09/17  
 Terms :- C.O.D Days  
 Remarks :-

**Main Office:**  
 Mova Building  
 No. 22, Jalan Kilang  
 Singapore 159419  
 Tel : (65) 6476 3333  
 Fax : (65) 6271 5891  
 www.mova.com.sg

**Workshop Dept:**  
 Block 100B  
 Bukit Merah Lane 3  
 #01-04/06/08/94  
 Singapore 159722  
 Tel : (65) 6272 3892  
 Fax : (65) 6270 8314  
 Co. Reg. 198904033G  
 GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
	REAR CABIN FLOOR PANEL, L/R REAR FENDER, AFFECTED AREA AND RENEW DAMAGED PARTS		2000	2,400.00
	TO APPLY RUST PROOF ON AFFECTED AREA		100	200.00
	TO SPRAY PAINT ON REPLACED, REPAIRED AREA		1000	1,800.00
	LABOUR TOTAL S\$			5,600.00

E. &amp; O.E



NON-TAX AMOUNT S  
 AMOUNT S\$ 20,481.75  
 GST @ 7 % 1,433.72  
 AMOUNT DUE S\$ 21,915.47

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

Rasul  
 14p 90010068  
 15 days  
 4/3  
 04/10/17 @ 1510  
 Reay after repair

Signature  
 5/10/17

## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



14,300 15day

**Estimate**

29/09/2017

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)  
16, RAFFLES QUAY  
#24-01 HONG LEONG BUILDING  
SINGAPORE 048581.

Attention :- XA013

Page # :- 1

Veh # :- GBA9207H

Veh Model :- MITSUBISHI DOUBLE CAB

Estimate# :- CK416459

Claim # :-

ACC. Date :- 26/09/17

Terms :- C.O.D Days

Remarks :- *Alm 96869276*

Main Office:  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159415  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

Workshop Dept:  
Block 100B,  
Bukit Merah Lane 3,  
#01-04/08/09/14  
Singapore 159722

Tel: (65) 6272 3892  
Fax: (65) 8270 8314

Co. Reg. 1989040393G  
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :				
1.	FRONT BUMPER	1	PC 985.00	985.00
2.	FRONT BUMPER SIDE BRACKET	2	PC 70.00	140.00
3.	FRONT BUMPER GRILLE LH	1	PC 195.00	195.00
4.	FRONT BUMPER GRILLE RH	1	PC 195.00	195.00
5.	FRONT BUMPER LOGO	1	PC 60.00	60.00
6.	FRONT BUMPER LOWER GRILLE	1	PC 230.00	230.00
7.	FRONT BUMPER REINFORCEMENT <i>- Rent / dented.</i>	1	PC 489.00	489.00
8.	FRONT AIR INTERCOOLER <i>- Cut / dent</i>	1	PC 1,300.00	1,300.00
9.	FRONT BUMPER CLIPS	10	PC 5.00	50.00
10.	FRONT HEADLAMP <i>- loop cracks</i>	2	PC 600.00	1,200.00
11.	REAR TAILLAMP	2	PC 495.00	990.00
12.	REAR TAILGATE	1	PC 2,300.00	2,300.00
13.	TAILGATE HINGE	2	PC 160.00	320.00
14.	TAILGATE LOCK	2	PC 160.00	320.00
15.	TAILGATE HANDLE	1	PC 150.00	150.00
16.	TAILGATE 3RD BRAKE LAMP	1	PC 180.00	180.00
17.	TAILGATE (OIO) EMBLEM	1	PC 60.00	60.00
18.	TAILGATE (L200) EMBLEM	1	PC 60.00	60.00
19.	TAILGATE LOGO	1	PC 60.00	60.00
20.	REAR BUMPER	1	PC 985.00	985.00
21.	REAR BUMPER REFLECTOR LAMP	2	PC 110.00	220.00
22.	REAR CABIN FLOOR PANEL	1	PC 3,500.00	3,500.00
23.	REAR FENDER	2	PC 2,300.00	4,600.00
24.	REAR MUDFLAP	2	PC 150.00	300.00
25.	REAR REINFORCEMENT	1	PC 400.00	400.00

LIST TOTAL S\$

19,289.00

25% DISCOUNT S\$

-4,822.25

14,466.75

SPECIAL NET ITEMS :				
1.	FRONT NUMBER PLATE	1	PC 50.00	50.00
2.	REAR NUMBER PLATE	1	PC 50.00	50.00
3.	REAR PARKING SENSOR	1	PC 300.00	300.00
4.	TAILGATE (70KM/H) STICKER	1	PC 15.00	15.00

SPECIAL NET TOTAL S\$

415.00

LABOUR :

TO INSECT FRONT &amp; REAR LIGHTING WATER AND LEAKAGE TEST

60.00 30

TO REMOVE &amp; INSTALL A/C CONDENSER, RADIATOR IN ORDER TO STRAIGHTEN SUPPORT PANEL

100 100.00

TO REMOVE &amp; INSTALL REAR CABIN IN ORDER TO CUT OFF DAMAGED PANEL &amp; STRAIGHTEN

600 1,000.00

TO STRAIGHTEN FRONT SUPPORT PANEL, CUT OFF

SIN-335



Main Office:  
Mova Building  
No. 22, Jalan Klang,  
Singapore 169416  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

Workshop Dept:  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/08/08/04  
Singapore 169722  
Tel: (65) 6272 3692  
Fax: (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0000064-2

## Estimate

29/09/2017

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)  
16, RAFFLES QUAY  
#24-01 HONG LEONG BUILDING  
SINGAPORE 048581.

Attention :- XA013

Page # :- 1 129565  
Veh # :- GBA9207H  
Veh Model :- MITSUBISHI DOUBLE CAB  
Estimate# :- CK416459  
Claim # :-  
ACC. Date :- 26/09/17  
Terms :- C.O.D Days  
Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	REAR CABIN FLOOR PANEL, LR REAR FENDER, AFFECTED AREA AND RENEW DAMAGED PARTS		2,400.00	
	TO APPLY RUST PROOF ON AFFECTED AREA		200.00	
	TO SPRAY PAINT ON REPLACED, REPAIRED AREA		1,800.00	
	LABOUR TOTAL S\$			5,600.00

LC-3830

F. &amp; O.E

NON-TAX AMOUNT S

AMOUNT S\$ 20,481.75

GST @ 7 % 1,433.72

AMOUNT DUE S\$ 21,915.47

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

Rasul  
14p 90010068

15 days

4S

04/10/17 @ 1510

Remy after repair

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-13701.75

SH-335.00

LC-3830.00

17,866.75

20848-14,293.4

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Oct 2017		03 Oct 2017 15:59 <a href="#">Edit Adj Rpt</a>	<b>S\$14,300.00</b> <a href="#">Edit Estimates</a>	<b>S\$14,300.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>			<b>[Created by insurer]</b>						
Insured:	BAN CHOON MARKETING PTE LTD, Co. Reg. No.: 198304071N								
Main Claimant:	CHINA CONSTRUCTION (SOUTH PACIFIC) DEVELOPMENT CO, Co. Reg. No.: 199201093N								
Vehicle Reg. No.:	GBA9207H	Date of Loss:	26/09/2017 00:00 - :59						
Claim Type:	TP / 531486	Policy/Cover Note No.:	28618297MKC Coverage: 10/11/2016 - 09/11/2017						
Vehicle Reg. No. (Insured):	YN6817B	Policy No. (Claimant):							
		Excess:							
Repairer:	Mova Automotive Pte Ltd (FAN YOONG BRANCH) 15 Fan Yoong Road, CNG Singapore Centre, 629792 Boon Lay - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 02/11/2017]								
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>			<a href="#">View All</a>	<a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*GBA9207H (531486)**  
**[YN6817B]**

TP

**CHINA CONSTRUCTION (SOUTH PACIFIC) DEVELOPMENT CO**

**Sep 26 2017 12:00AM**

**[BAN CHOON MARKETING PTE LTD]**

**Mova Automotive Pte Ltd**

Upload Documents			Upload Photos			Compose New Letter			View <div>View in Browser</div>		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	05/10/17 16:52	Adjuster Immediate Advice							Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
2	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
3	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
4	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
5	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
6	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
7	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
8	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
9	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
10	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
11	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
12	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
13	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
14	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
15	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
16	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
17	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
18	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
19	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
20	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
21	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
22	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
23	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
24	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
25	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
26	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
27	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
28	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
29	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
30	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
31	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	
32	31/01/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>	

33	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
36	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
41	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
42	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
43	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
44	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
45	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
46	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
47	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
48	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
49	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
50	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
51	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
52	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
53	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
54	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
55	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
56	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
57	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
58	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
59	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
60	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
61	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
62	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
63	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
64	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
65	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
66	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
67	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
68	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
69	31/01/18 12:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
70	31/01/18 12:04	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
71	31/01/18 12:04	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
72	31/01/18 12:04	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
73	31/01/18 12:04	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
74	31/01/18 12:04	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
75	31/01/18 12:04	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
76	31/01/18 12:04	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
77	31/01/18 12:04	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
78	31/01/18 12:04	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
79	31/01/18 12:04	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
80	31/01/18 12:04	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
81	31/01/18 12:04	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
82	31/01/18 12:04	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>

83	31/01/18 12:04	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
84	31/01/18 12:04	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
85	31/01/18 12:04	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
86	31/01/18 12:04	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
87	31/01/18 12:04	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
88	31/01/18 12:04	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
89	31/01/18 12:04	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
90	31/01/18 12:04	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
91	31/01/18 12:05	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
92	31/01/18 12:05	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
93	31/01/18 12:05	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
94	31/01/18 12:05	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
95	31/01/18 12:05	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
96	31/01/18 12:05	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>				1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	02/10/17 15:36	Estimate	1	Load PDF	
2	02/10/17 15:36	GBA9207H GIA Rpt	1	Load PDF	
3	02/10/17 15:42	Email frm TP - PRI	1	Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17018952/R1RBE2

Date: 05/02/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 28618297MKC  
 Claimant Vehicle No: GBA9207H Insured Vehicle No: YN6817B  
 Date of Loss: 26/09/2017 Nature of Claim: TP Claim No: 531486

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **GBA9207H**  
 Make & Model: MITSUBISHI L200, 2.5 D Dbl Cab (M) Engine No: 4D56UCBB0787  
 Reg. Date: 01/04/2008 (Man. Year: 2008) Chassis No: MMBJNKB407D155264  
 Colour: Black Odometer: 369932 km  
 Engine Capacity: 2477 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (\$\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205 R16C Rear Tyre Size: 205 R16C  
 Front Left Side: Roadstone 7 mm Rear Left Side: Roadstone 7 mm  
 Front Right Side: Roadstone 7 mm Rear Right Side: Roadstone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,881.75	14,036.75	845.00	5.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,600.00	3,830.00	1,770.00	31.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>20,481.75</b>	<b>17,866.75</b>	<b>2,615.00</b>	<b>12.77</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>14,300.00</b>		
<b>(\$\$)</b>	20,481.75	14,300.00	6,181.75	30.18
<b>+ GST 7.00/7.00% (\$\$)</b>	1,433.72	1,001.00	432.72	30.18
<b>Nett Amount (\$\$)</b>	<b>21,915.47</b>	<b>15,301.00</b>	<b>6,614.47</b>	<b>30.18</b>

## INSPECTION

Date of Assignment: 03/10/2017

Date Inspected: 04/10/2017 Inspected At:

Mova Automotive Pte Ltd (FAN YOONG  
 BRANCH)  
 15 Fan Yoong Road, CNG Singapore  
 Centre  
 Singapore 629792

Estimated Period of Repair: 15.0 days

---

**Adjuster:** MOHD RASUL**Manager:** Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 05 Feb 2018)  
**Parts:** N/A MITSUBISHI L200 2.5 D Dbl Cab (M) (Model not available in database)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for GBA9207H)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	985.00 FL	*985.00 FL
2	2		*FRONT BUMPER SIDE BRACKET	Necessary	140.00 FL	*140.00 FL
3	1		*FRONT BUMPER GRILLE LH	Deformed	195.00 FL	*195.00 FL
4	1		*FRONT BUMPER GRILLE RH	Deformed	195.00 FL	*195.00 FL
5	1		*FRONT BUMPER LOGO	Necessary	60.00 FL	*60.00 FL
6	1		*FRONT BUMPER LOWER GRILLE	Deformed	230.00 FL	*230.00 FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	489.00 FL	*489.00 FL
8	1		*FRONT AIR INTERCOOLER	Bent	1,300.00 FL	*1,300.00 FL
9	10		*FRONT BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
10	2		*FRONT HEADLAMP	Cracked	1,200.00 FL	*1,200.00 FL
11	2		*REAR TAILLAMP	Cracked	990.00 FL	*990.00 FL
12	1		*REAR TAILGATE	Bent	2,300.00 FL	*2,300.00 FL
13	2		*TAILGATE HINGE	Not Necessary	320.00 FL	*- FL
14	2		*TAILGATE LOCK	Jammed	320.00 FL	*320.00 FL
15	1		*TAILGATE HANDLE	Scratched	150.00 FL	*150.00 FL
16	1		*TAILGATE 3RD BRAKE LAMP	Cracked	180.00 FL	*180.00 FL
17	1		*TAILGATE (DID) EMBLEM	Necessary	60.00 FL	*60.00 FL
18	1		*TAILGATE (L200) EMBLEM	Necessary	60.00 FL	*60.00 FL
19	1		*TAILGATE LOGO	Necessary	60.00 FL	*60.00 FL
20	1		*REAR BUMPER	Bent	985.00 FL	*985.00 FL
21	2		*REAR BUMPER REFLECTOR LAMP	Cracked	220.00 FL	*220.00 FL
22	1		*REAR CABIN FLOOR PANEL	Buckled	3,500.00 FL	*3,500.00 FL
23	2		*REAR FENDER	Buckled	4,600.00 FL	*4,600.00 FL
24	2		*REAR MUDFLAP	Not Necessary	300.00 FL	*- FL
25	1		*REAR REINFORCEMENT	Not Necessary	400.00 FL	*- FL
26	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*35.00 FS
27	1		*REAR NUMBER PLATE	Scratched	50.00 FS	*35.00 FS
28	1		*REAR PARKING SENSOR	Not Working	300.00 FS	*250.00 FS
29	1		*TAILGATE (70KM/H) STICKER	Necessary	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>19,704.00</b>	<b>18,604.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>4,822.25</b>	<b>4,567.25</b>
<b>Total Parts (\$\$)</b>	<b>14,881.75</b>	<b>14,036.75</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO INSPECT FRONT & REAR LIGHTING WATER AND LEAKAGE TEST	New	60.00	30.00
2	TO REMOVE & INSTALL A/C CONDENSER, RADIATOR IN ORDER TO STRAGHTEN SUPPORT PANEL	New	140.00	100.00
3	TO REMOVE & INSTALL REAR CABIN IN ORDER TO CUT OFF DAMAGED PANEL & STRAIGHTEN	New	1,000.00	600.00
4	TO STRAIGHTEN FRONT SUPPORT PANEL, CUT OFF REAR CABIN FLOOR PANEL, L/R REAR FENDER, AFFECTED AREA AND RENEW DAMAGED PARTS	New	2,400.00	2,000.00
5	TO APPLY RUST PROOF ON AFFECTED AREA	New	200.00	100.00
6	TO SPRAY PAINT ON REPLACED, REPAIRED AREA	New	1,800.00	1,000.00
Gross Labour Cost (\$\$)			5,600.00	3,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >