

REF: CS/SM017019101/Mlg6721

Special Instruction:

SUPERVISOR

Ma

ASSIGNMENT (Office)

From (Person):

Sherry Wong

of

SMO

Date/Time:

5/10/17 3:14 pm

Estimated Cost:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SHC 3442C

Insured:

SFM 2454X

at Workshop m/s:

Chunni Motor

Tel:

65425119

of Blk 10 AMK Ind Park 2A, #03-19, S68047

Policy No.:

Claim No.:

CMTD1703475 / THE

Sum Insured:

Excess:

D.O.A.

3/10/17

Make of Veh.:

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 5/10/17 3:32 pm

Person Contacted:

Lynn

H.O.D. Endorsement:

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 3442C - X

SFM 2454X - X

06/10/17 @ 3:30 pm revised to Sherry Wong by email.
 13 @ 1000, 10 days (Red @ 11270.66, 51%).

Bel - 1 yr
4 months

Surveyor

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s CHUNNA

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHC 3442C Yr Regn: 7EB 1201

Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) / Prime Mover /

Truck / Trailer or

Make: HYUNDAI C.C. 1991

Colour: PAVE A/C: Insured / Std / NI / NA

Sp. Reading: 22462 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM1ETHVMB805891

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 02/10/2017 D.O.I. 5/10/2017

Survey held at _____

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Ma,
pls check repair margin.

11K - 10buld

9/10

RECEIVED 05 DEC 2017

Date/Time, File Pass to?

☐ : Preli. Report

11/01/12 by user

☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.A. (\$

7P

11000

Days Of Repair: 10

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

____ \$ + RS. ____ \$

Photos

Others

TOTAL

450



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17019101/M1qb

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 05-10-2017



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFM 2454X	Veh. Inspected	SHC 3442C
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1703475/THE	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	05/10/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	03/10/2017	Inspection Date
Survey held at	CHUNNI MOTOR REPAIRS PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTOPOINT #03-19 SINGAPORE 568047	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1703475/THE

Date: 06 October 2017

Our Ref: CS/SMO17019101/M1qb

Without Prejudice

The Motor Claims Department
Sompo Insurance

Attn: Irene

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SHC 3442C


We thank you for the instruction on 05/10/2017.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 05/10/2017 at the premises of M/s CHUNNI MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$ 22,270.66 .
Revised Estimate Amount	: S\$ 10,562.26 .
"Check" Items Amount	: S\$ 5,717.92 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the front & rear portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 10 days.

We have NOT authorized repair.

Yours faithfully

Ma C.F.
Automobile Assessor

Survey Department Check List (Case Handler)

Reference No.: CG/SMO17019101/M196
Policy Type: OD/TP/TP RES/TL/EVA

Case Handler

SHC 3442C
Typist

Admin (Cater): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA/REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (M.C.F.): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓		
---	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓		
✓		

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

✓		
---	--	--

Check By:

CH 05/12/17
Case Handler Date

Nivitha (LKK Auto)

From: Wong, Shi Yi Shery <Shery.Wong@sompo.com.sg>
Sent: Thursday, 5 October, 2017 3:14 PM
To: assignments@lkkauto.com
Cc: Catherine Chong (LKK Auto); Henry, Irene James; Choo, Thelma
Subject: Our Reference: CMTD1703475/THE ; TP: SHC3422C ; PRI
Attachments: 3475.pdf

Our Reference: CMTD1703475/THE

Hi,

Kindly assign your motor surveyor to conduct motor survey for SHC3422C.

Please refer to attached correspondence for survey details.

Thank you.

Best Regards

Shery Wong

Claims Division

T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.


Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #06-01/02 Singapore Land Tower, Singapore 048623
 Tel: 6451 8586 | Fax: 6221 3302 | Website: www.sompo.com.sg
 Co. Reg. No.: 196906480E | GST Reg. No.: M200603198

Our Reference: CMTD1703475/THE

Your Reference: SHC3422C

Date: 5TH October 2017

Attention:

M/S CHUNNI MOTOR WORK PTE LTD

Dear Sirs,

We refer to your Notice of Accident dated 05/10/2017.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	✓
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Tao See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Yours faithfully,

Shery Wong

Without Prejudice
 Sompo Insurance Singapore Pte. Ltd.
 Claims
 Please fax your reply to: 6221-3147

05 OCT 2017

CHUNNI MOTOR WORK
PTE LTD

CMTD 1703475/1111

Sampo Insurance Singapore Pte. Ltd.	
Claims	
05 OCT 2017	

Date : 05.10.17

To : Sampo Insurance Singapore Pte Ltd

No of Pages : 13

Re : Accident involving veh no: SHC 3422C & SFM 2454X Along
Braddell Rd towards Lornie Rd before CTE Exit on 03.10.17

We refer to the above mention matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly arrange to survey at AMK Autopoint, Soon Hock Motor, #01-05/06,**Tel : 6483 6016.**

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 65427162.

Thank you for your kind assistance.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 6 October, 2017 3:23 PM
To: 'Wong, Shi Yi Shery'; assignments
Cc: 'Henry, Irene James'; 'Choo, Thelma'; SUR
Subject: RE: Our Reference: CMTD1703475/THE ; TP: SHC3442C ; PRI
Attachments: CSSMO17019101M1qb.pdf

Dear Shery,

Enclosed herewith preliminary advice of SHC 3442C.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 5 October, 2017 3:20 PM
To: 'Wong, Shi Yi Shery' <Shery.Wong@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry, Irene James' <irene.henry@sompo.com.sg>; 'Choo, Thelma' <thelma.choo@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: Our Reference: CMTD1703475/THE ; TP: SHC3422C ; PRI

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wong, Shi Yi Shery [<mailto:Shery.Wong@sompo.com.sg>]
Sent: Thursday, 5 October, 2017 3:14 PM
To: assignments@lkkauto.com
Cc: Catherine Chong (LKK Auto); Henry, Irene James; Choo, Thelma
Subject: Our Reference: CMTD1703475/THE ; TP: SHC3422C ; PRI

Our Reference: CMTD1703475/THE

Hi,

Kindly assign your motor surveyor to conduct motor survey for SHC3422C.

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 3821R

Vehicle Details

Vehicle No.: SHC3442C

Vehicle to be Exported: No

Intended De-registration
Date: 06 Oct 2017

Vehicle Make: HYUNDAI

Vehicle Model: SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO

Primary Colour: Blue

Manufacturing Year: 2011

Engine No.: D4EAB936629

Chassis No.: KMHET41VMBA805891

Maximum Power
Output: 110.0 kW (147 bhp)

Open Market Value: \$14,779.00

Original Registration
Date: 28 Feb 2011

First Registration Date: 28 Feb 2011

Transfer Count: 0

Actual ARF Paid: \$14,779.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 27 Feb 2019

PARF Rebate Amount: \$9,606.00

Intended COE Rebate Details

COE Expiry Date: 27 Feb 2019

COE Category: A - Car (1600cc & below)

COE Period(Years): 8

PQP Paid: \$32,767.00

COE Rebate Amount: \$5,717.00

Total Rebate Amount: \$15,323.00**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 06 Oct 2017



Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Last updated on 17 Sep 2017 at 12:38 AM

MCD617131653 / ComfortDelGro Engineering Pte Ltd - Loyang
ENTRY DATE & TIME: 04/10/2017 16:22

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 05/10/2017 08:18

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 04/10/2017 16:22
Date Of Accident 03/10/2017 18:40
Exact Location Of Accident BRADDELL ROAD TOWARDS LORNIE RD BEFORE CTE EXIT
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHC3442C
Insured/Policyholder
Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
Co Reg No 199303821R
Email Address FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No
Alternative Phone No OFFICE-65508768
Vehicle Particulars
Manufacturer HYUNDAI
Model SONATA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category TAXI
Insurance Company
Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy YES
Policy Number MCOM0016
Cover Note Number
Driver
Name of Driver MAIMUNAH BINTI ATAN
NRIC No S1651534E
Date Of Birth 16/12/1964
Occupation OUTDOOR
Date Of Driving Pass 19/11/1997
Driving Experience 19 YEARS AND 10 MONTHS
Gender MALE
Mobile Number
Fax Number
Contact Number
EMail Address AIREENE@SINGNET.COM.SG

Address	BLK 346 ANG MO KIO AVENUE 3 #03-2260
Postcode	560346
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance,	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER POLICE REPORT NO: T/20171004/2107

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFM2454X
Vehicle Make/Model/Colour	HONDA
Details Of Properties	
Name of Driver	VENKATACHALAM VALLIAPPAN
NRIC/Passport Number	S7077847E
Contact Number	98214677
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLL9156U
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	CHAY KENG YU REUBEN
NRIC/Passport Number	S9016701D
Contact Number	81632136
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	
Details of Witness	
Name	
Phone Number	
Email Address	

DETAILS OF INJURED PERSON 1

Name	MAIMUNAH BINTI ATAN
Approximate Age	
Injuries Sustain	BACK, NECK AND BODY
Injured person in which vehicle?	SHC3442C
Were seat belts worn?	YES
Was injured conveyed to hospital by ambulance?	NO
Address	BLK 346 ANG MO KIO AVENUE 3 #03-2260
Postcode	560346

SKETCH PLAN**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 04.10.2017 @ 16:15 Hrs


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Refer to the attachment

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: 04.10.2017 @ 16:15 Hrs

Reporting Centre Personnel's Signature
Name: Rubbini
NRIC/FIN No.:

Braddell Rel.



[Signature]
Maimunah Binti Ato
S165153X E
04/10/2017


**SINGAPORE
POLICE FORCE**


T/20171004/2107

1 of 3

Report No. T/20171004/2107

Police Station Of Origin:
Changkat NPP
109 Tampines Street 11 #01-261
SINGAPORE 521109
Tel No: 1800-7819999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 04/10/2017 14:37		Vide Report No.:		Station Diary No.: 12	
Informants' Particulars					
Name of Informant: MAIMUNAH BINTI ATAN			Address: APT BLK 346 ANG MO KIO AVENUE 3 #03-2260 SINGAPORE 560346		
ID Type / ID No.: NRIC NO / S1651534E			Contact No.: Home/Office: Mobile: 98384361		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 52	Date of Birth: 16/12/1964	Type of Informant: Driver		
Race: Malay			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 03/10/2017 18:40	Type of Location: Straight Road
Location: Along Road 1 BRADDELL ROAD BRADDELL RD TOWARDS LORNIE RD.				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SFM2454X	Car					0
SHC3442C	Car					0
SLL9156U	Car					0



**SINGAPORE
POLICE FORCE**



T/20171004/2107

2 of 3

Police Station Of Origin:
Changkat NPP
109 Tampines Street 11 #01-261
SINGAPORE 521109
Tel No: 1800-7819999

Report No. T/20171004/2107

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	MAIMUNAH BINTI ATAN	ID No.	S1651534E
Related Vehicle	SHC3442C (Car)	Contact No.	98384361
Hospital/Clinic	SUNSHINE CLINIC FAMILY PRACTICE & SURGERY	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	04/10/2017	Date Discharge	NIL
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On 03/10/2017 at about 1840hrs I was driving my taxi(SHC3442C) along Braddell rd towards Lornie Rd Just before the tunnel. It was drizzling heavily and the roads were heavily congested. I was on the most right lane. All vehicles were moving slowly when the vehicle in front of me (SLL9156U) slowed down and stop I also followed accordingly to slow my vehicle down and stop behind the front car. Suddenly I felt an impact from the rear, the car (SFM2454X) had collided into the rear of my taxi. This caused my taxi to surge forward and I collided into the car in front. We got out of our vehicles and exchanged particulars.

Particulars of the drivers

1) SFM2454X
VENKATACHALAM VALLIAPPAN
S7077847E
H/P:98214677

2) SLL 9156U
CHAY KENG YU, REUBEN
S9016701D
H/P:81632136

**SINGAPORE
POLICE FORCE**

T/20171004/2107

3 of 3

Police Station Of Origin:
Changkat NPP
109 Tampines Street 11 #01-261
SINGAPORE 521109
Tel No: 1800-7819999

Report No. T/20171004/2107

CONTINUATION OF REPORT**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 RANDY RONALD MINJOOT

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

SSI KASMAWATI BTE SAMIAN

Contact No.: 65476179

Signature Of Informant:

Date/Time:

04/10/2017 14:37

Classification Of Case:

Authentication Stamp

NP168

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHC 3442C

DATE : 4.10.2017

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI SONATA

FAX : 6542 6039

Lick(ma)

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille		dis	\$ 282.10	
	Radiator Grille U Moulding		dis	\$ 108.90	
	Front Bumper Cover		dis	\$ 538.80	
	Front Bumper Sponge		dis	\$ 136.30	town
	Front Bumper Reinforcement		dis	\$ 504.10	bt.
	Front Bumper Bracket Top (LH/RH)	\$	22.40	\$ 44.80	
	Front Bumper Protector (LH/RH)	\$	29.20	\$ 58.40	
	Front Bumper Bracket (LH/RH)	\$	20.10	\$ 40.20	
	Front Bumper Side Bracket	\$	14.30	\$ 28.60	
	Headlamp Support Panel Assy		bt	\$ 1,023.00	
	Headlamp (LH/RH)	\$	over 97.90	\$ 1,595.80	
	Radiator			\$ 814.80	bt
	Radiator Fan Blade,Cowling,Motor Assy		over	\$ 651.30	
	Radiator Bracket	\$	dis 6.20	\$ 12.40	
	Aircon Condenser			\$ 1,089.90	bt
	Inter Cooler			\$ 771.50	bt
	Inter Cooler Mounting (2 PCS)		over	\$ 24.80	
	Wiring-ECM			\$ 3,107.80	dis
	SUB TOTAL			\$ 10,833.50	
	LESS 20%			\$ 2,166.70	
	DISCOUNTED TOTAL			\$ 8,666.80	
	Front Number Plate		dis 25	\$ 25.00	Nett
	Front No Plate Trim Cover			\$ 30.00	Nett
				\$ 55.00	
	Labour Charge				
	Panel Beating			\$ 1,000.00	500
	Spray Painting Charge			\$ 200.00	180
	Wiring Charge			\$ 50.00	30
	Towing Charge			\$ 50.00	✓
	Remove/Refix Aircon & Refill Gas			\$ 150.00	100
	Remove/Refix Dashboard			\$ 450.00	280
	Remove/Refix Fuse Box			\$ 180.00	X
	TOTAL LABOUR			\$ 2,080.00	

SHC 3442C

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			S 1,600.00 1000
	Spray Painting Charge			S 1,000.00 800
	Wiring Charge			S 50.00 30
	Tuff Kote			S 100.00 60
	Remove/Refix Cushion & Upholstery Rear			S 150.00 60
	Remove/Refix Rear Windscreen Glass			S 120.00 70
	Remove/Refix Reverse Sensor			S 120.00 60
	Remove/Refix Exhaust Pipe			S 150.00 80
	TOTAL LABOUR			S 3,290.00
	ESTIMATE TOTAL			S 22,270.66
<p> <i>x 1000</i> <i>HS Repair</i> <i>After paint photo</i> <i>LKK Auto</i> <i>5/10/2017</i> <i>10w/1days</i> </p> <p> <i>9/10/17</i> </p> <div style="border: 1px solid black; padding: 5px; margin-top: 20px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17019101/M1qbn2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 05-12-2017



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFM 2454X	Veh. Inspected	SHC 3442C
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1703475/THE	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	05/10/2017

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI SONATA	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	KMHET41VMBA805891	Colour	BLUE
Odometer	224612	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	WEST LAKE	8 mm
L/H Front Tyre	215/60 R16	WEST LAKE	8 mm
R/H Rear Tyre	215/60 R16	WEST LAKE	8 mm
L/H Rear Tyre	215/60 R16	WEST LAKE	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	03/10/2017	Inspection Date	05/10/2017
Survey held at	CHUNNI MOTOR REPAIRS PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTOPOINT #03-19 SINGAPORE 568047		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3442C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RADIATOR GRILLE	DISTORTED	282.10	282.10
1	RADIATOR GRILLE U MOULDING	DISTORTED	108.90	108.90
1	FRONT BUMPER COVER	DEFORMED	538.80	538.80
1	FRONT BUMPER SPONGE	TORN	136.30	136.30
1	FRONT BUMPER REINFORCEMENT	BENT	504.10	504.10
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$22.40	DISTORTED	44.80	44.80
2	FRONT BUMPER PROTECTOR (LH/RH) @\$29.20	DISTORTED	58.40	58.40
2	FRONT BUMPER BRACKET (LH/RH) @\$20.10	DISTORTED	40.20	40.20
2	FRONT BUMPER SIDE BRACKET @\$14.30	DISTORTED	28.60	28.60
1	HEADLAMP SUPPORT PANEL ASSY	BENT	1,023.00	1,023.00
2	HEADLAMP (LH/RH) @\$797.90	CRACKED	1,595.80	1,595.80
1	RADIATOR	BENT	814.80	814.80
1	RADIATOR FAN BLADE,COWLING,MOTOR ASSY	SERVICEABLE	651.30	-
2	RADIATOR BRACKET @\$6.20	DISTORTED	12.40	12.40
1	AIRCON CONDENSER	BENT	1,089.90	1,089.90
1	INTER COOLER	BENT	771.50	771.50
1	INTER COOLER MOUNTING (2 PCS)	SERVICEABLE	24.80	-
1	WIRING-ECM	DISTORTED	3,107.80	3,107.80
1	BOOT LID	BENT	1,349.50	1,349.50
1	BOOT LID RUBBER	DISTORTED	110.90	110.90
1	BOOT LID LOCK UPPER	BENT	132.10	132.10
1	BOOT LID LOCK LOWER	TO REPAIR SEE LABOUR	30.30	-
1	BOOT LID SONATA PLATE	NECESSARY	43.60	43.60
1	BOOT LID HYUNDAI PLATE	NECESSARY	24.20	24.20
1	BOOT LID "H" EMBLEM	NECESSARY	26.10	26.10
1	BOOT LID CRDI PLATE	NECESSARY	22.70	22.70
2	BOOT LID LAMP (LH/RH) @\$230.20	CRACKED	460.40	460.40
1	BOOT LID TRIMBOARD	SERVICEABLE	165.40	-
11	BOOT LID TRIMBOARD CLIPS	NECESSARY	11.00	11.00
1	REAR BUMPER	DEFORMED	578.40	578.40
1	REAR BUMPER REINFORCEMENT	BENT	483.30	483.30
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
2	REAR BUMPER BRACKET @\$49.00	BENT	98.00	98.00

Report Ref No. CS/SMO17019101/M1qbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER SPONGE	TORN	137.40	137.40
1	REAR BUMPER UNDER COVER	SERVICEABLE	185.80	-
2	REAR BUMPER PROTECTOR (LH/RH) @\$38.00	SERVICEABLE	76.00	-
2	TAIL LAMP (LH/RH) @\$344.00	CRACKED	688.00	688.00
1	REAR PANEL	BENT	391.80	391.80
1	REAR PANEL GARNISH	DISTORTED	95.80	95.80
1	SPARE TYRE HOLDER	SERVICEABLE	27.60	-
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	863.00	-
1	SPARE TYRE PANEL CUSHION	SERVICEABLE	200.30	-
1	REAR TOWING HOOK	SERVICEABLE	135.30	-
1	MEMBER ASSY-REAR FLOOR CENTRE	TO REPAIR SEE LABOUR	163.60	-
1	EXHAUST PIPE INSULATOR	SERVICEABLE	56.10	-
1	EXHAUST SILENCER	BENT	723.00	723.00
1	EXHAUST PIPE HANGER	TO REPAIR SEE LABOUR	56.10	-
1	REAR FENDER (RH)	TO REPAIR SEE LABOUR	1,935.90	-
1	REAR FENDER INNER LINING (RH)	SERVICEABLE	74.10	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	60.00	-
	LESS 20% DISCOUNT		-4,052.24	-3,111.12
			16,208.96	12,444.48
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NO PLATE TRIM COVER (SN) }	DISTORTED	30.00	40.00
1	FRONT NUMBER PLATE (SN) }	DISTORTED	25.00	-
1	BOOT LID COMFORT LOGO & TEL NO STICKER (SN)	NECESSARY	30.00	30.00
1	BOOT LID ADVERTISEMENT LOGO (SN)	NECESSARY	100.00	100.00
1	REAR NO PLATE (SN)	SERVICEABLE	25.00	-
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	135.70	135.70
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
			691.70	605.70

Report Ref No. CS/SMO17019101/M1qbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF BOOT LID LOCK LOWER,SPARE TYRE PANEL,MEMBER ASSY-REAR FLOOR CENTRE,EXHAUST PIPE HANGER AND REAR FENDER (RH).		2,600.00	1,500.00
	SPRAY PAINTING CHARGE.		1,200.00	980.00
	WIRING CHARGE.		100.00	60.00
	TOWING CHARGE.		50.00	50.00
	REMOVE/REFIX AIRCON & REFILL GAS.		150.00	100.00
	REMOVE/REFIX DASHBOARD.		450.00	280.00
	REMOVE/REFIX FUSE BOX.	NOT NECESSARY	180.00	-
	TUFF KOTE.		100.00	60.00
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	60.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	REMOVE/REFIX REVERSE SENSOR.		120.00	60.00
	REMOVE/REFIX EXHAUST PIPE.		150.00	80.00
			5,370.00	3,230.00
	GRAND TOTAL		22,270.66	16,280.18
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			11,000.00

Report Ref No. CS/SMO17019101/M1qbn2

MA CHIN FOOK
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.