

ASS. REC BY:

REF: CS/MSG17019108/Ti2ber

Special Instruction:

Surveyor

Taufik

ASSIGNMENT (Office)

MEXIMEN

From (Person)

Elaine Ngu

of

MSG

Date/Time

5/10/17 10:18am

Estimated Cost

Bill to

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLA 1926A

Insured:

SJH 7900 X

at Workshop m/s

Hitachi Capital Asia

Tel:

64663022

Jia Liang

of No. 8 Fourth Lok Yang Road, 629705

Policy No:

A80440002QMX

Claim No:

531909

Sum Insured

Excess:

Make of Veh:

(Client's Record)

D.O.A

4/10/17

CA / REV / REP. / REV 24 HRS

'wp'

06-10-2017

H.O.D. Endorsement:

Date/Time:

5/10/17

10:46am

Person Contacted:

Chong

Vehicle IN OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLA 1926A - X

SJH 7900X - X

10/10/17 @ 5.06pm revised to Elaine Ngu via MEXIMEN.

04/11/18 @ 9.12am re-finalized with Kevin final fig \$4891.20, 7 days by email
(Ref \$6734.75, 59%)

Tanji

REF: MSIG

ASSIGNMENT

From _____ Date 6/10/17

Estimated Cost _____

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No SLA 1926 A

at Workshop / Mile Hitachi Capital Asia

at No.8 Fourth Lok Yang Road, 629705

Insured _____

Policy No _____

Claims No _____

Sum Insured _____ Excess _____

(Client's Record)

Make of Van _____

Policy Condition _____

Remark: The veh had commenced its repair at the time of inspection.

Bar or Market Value 845K

DAC Accident Report Consistent? Yes or No

GIA PR Seen Consistent? Yes or No

Est. Repairs 7 days Res: Yes or No

Lump Sum _____ % 3 Val Yes or No

CA / REV / REP / 24 HRS wp

Date _____ Person Contacted _____

Vehicle IN / OUT

Veh No SLA 1926A Vt Reg 2016, Feb

Type ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make Honda Vezel. CC 1496

Colour Black. AC Insured / Std / NI / NA

Se Reading 56661 T-Read Insured / Std / NI / NA

Eng No _____

C No KU11107758

Gen Cond ☒ Good / Fair / Poor / Burnt

Steering ☒ Inorder / Jammed / Leaked / Burnt or

Brake ☒ Inorder / Jammed / Leaked / Burnt or

Mod Nil / R / STD A/Rim or

Tyre Size 225/45R18

R _____

BS / DUN / EXNOVA / GY / FS / LIZA ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R Ba 6 mm R Ba 8 mm

L Ba 6 mm L Ba 6 mm

D O A _____ D O I 6/10/17

Survey held at Hitachi Capital

Des of Damages: Frt ☒ Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

85441.20, 7 days - email to Grant.
 open 85884.75, 52%

24/04/2018

RECEIVED 04 MAY 2018

Date/Time File Pass to: 04/5/17

Date/Time File Return to: _____

2

Report Format: MER-TP

Lump Sum / I.B.I: (S) 5441.20

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (S)
☐ Interview (S)
☐ Tech Invs (S)
☐ Weekend (S)

Survey Fee: 300

Transportation: _____

IS - RE: (S) _____

Photos: _____

Others: _____

TOTAL: 300



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG17019108/T1qb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 05-10-2017	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJH 7900X		Veh. Inspected	SLA 1926A
Policy No.	A80440002QMX		Coverage (\$)	0.00
Claim No.	531909		Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)		Assign Date	05/10/2017
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	04/10/2017		Inspection Date	
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Oct 2017 Sendback Est	04 Oct 2017 18:33 \$11,159.85	05 Oct 2017 10:18 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	LEOW RONG QING, ID: S8139384B		
Main Claimant:	SUM KAR SENG, EDDIE, ID: S8018412C		
Vehicle Reg. No.:	SLA1926A	Date of Loss:	04/10/2017 08:00 - :59
Claim Type:	TP / 531909	Policy/Cover Note No.:	A80440002QMX Coverage: 25/08/2017 - 24/08/2018
Vehicle Reg. No. (Insured):	SJH7900X	Policy No. (Claimant):	SD17V02124/VPE/R01
		Excess:	
Repairer:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/10/2017]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Kevin, MJ Leong <kevinleong@hcspl.com.sg>
Sent: Friday, 4 May 2018 9:12 AM
To: Shiau Chan (LKKAUTO); Jamilah, Binte MohdKassim
Cc: SUR
Subject: RE: LKK OUTSTANDING CASE FINALISE (BY GRANT CHONG) - URGENT

Dear Shiau Chan,

Ok. Accepted.

Thank you.

Kevin Leong
Service Manager
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
t: 6833 6273 h: 9710 7240
e: KevinLeong@hcspl.com.sg
w: www.hitachi-capital.com.sg

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Thursday, May 03, 2018 2:04 PM
To: Kevin, MJ Leong <kevinleong@hcspl.com.sg>; Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: LKK OUTSTANDING CASE FINALISE (BY GRANT CHONG) - URGENT

Dear Kevin,

We wish to re-finalise of SLA 1926A at repair cost \$4,591.20 (instead of \$5,441.20) before GST and 7 repair days.

Kindly confirm.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 25 April 2018 10:29 AM
To: Kevin, MJ Leong <kevinleong@hcspl.com.sg>; Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: LKK OUTSTANDING CASE FINALISE (BY GRANT CHONG) - URGENT

Dear Kevin,

Please find the attached.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 10 Oct 2017

Preliminary Advice

Insured Vehicle No	: SJH7900X	Accident Date	: 04/10/2017
TP Vehicle No	: SLA1926A	Assignment Date	: 05/10/2017
Make	: HONDA VEZEL	Est. Duration of Repair	: 7.00
Date of Inspection	: 06/10/2017		
Inspection At	: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ) NO 8 FOURTH LOK YANG ROAD SINGAPORE 629705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,159.85
Revised Amount	:S\$	5,275.60
Check Items (Estimated)	:S\$	1,299.25
Total	:S\$	6,574.85
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/10/2017 17:18
Date Of Accident	04/10/2017 08:10
Exact Location Of Accident	JURONG WEST ST 93
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA1926A
Insured/Policyholder	
Name Of Registered Owner	SUM KAR SENG, EDDIE
NRIC No	S8018412C
Email Address	EDDIESUM534@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97955607
Alternative Phone No	OTHERS-97955607

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD17V02124/VPE/R01
Cover Note Number	

Driver

Name of Driver	SUM KAR SENG, EDDIE
NRIC No	S8018412C
Date Of Birth	03/07/1980
Occupation	INDOOR
Date Of Driving Pass	26/09/2005
Driving Experience	12 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97955607
Fax Number	
Contact Number	OTHERS-97955607
Email Address	EDDIESUM534@HOTMAIL.COM

Address	BLK 90 DAWSON ROAD #30-16
Postcode	142090
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJH7900X
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	LEOW RONG QING
NRIC/Passport Number	S8139384B
Contact Number	93377548
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF INJURED PERSON 1

Name	SUM KAR SENG, EDDIE
Approximate Age	

Injuries Sustain

Injured person in which vehicle?

SLA1926A

Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PCPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Sum Icar Seng Ecolike

Policyholder's Signature / Date & Time


[Signature]

Driver's Signature (If driver is not the policyholder) / Date & Time

[Signature]

Witnessed by Reporting Centre Personnel

Sketch Plan




Sketch Plan Pg. 2

Describe Circumstances of the Accident

I was at the traffic light, slow down and stop. Suddenly the car SJH 7900X hit me from behind.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

HITACHI
 Inspire the Next

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)
SUM KAR SENG, EDDIE
 BLK 90 DAWSON ROAD #30-16
 Singapore 142090

Claimant Insurer: Liberty Insurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	04/10/2017
Vehicle Reg. No.:	SLA1926A	Driveable?	
Party At Fault:	UNKNOWN	Driver (Insured):	SUM KAR SENG, EDDIE
Driver (TP):	SUM KAR SENG, EDDIE		

Make/Model:	HONDA VEZEL, 1.5 (A)	Vehicle Reg. Date:	24/02/2016
Vehicle Colour:	BLACK	Chassis No:	RU11107758
Engine No:	L15B4027761		
Odometer:	20000 KM		

Paint Type:
 Total Loss? **NO**
 Est. Duration of Repair (day) **14**

*Tanpin 27495749.
 'WP' 6/10/17 @ 1545
 Resurvey before paint.
 6-7 days*

sur @ Thantanto.com

Description of Accident/Loss: **REFER TO ATTACHMENT**
 Present Location: **HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)**

[Signature]
 11/10/17

COST OF CLAIMS	Amount
Parts	4,219.85
Miscellaneous Items	0.00
Labour	6,940.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	11,159.85
+ GST 7.00% (S\$)	781.19
Nett Amount (S\$)	11,941.04

This claim is handled by: GRANT CHONG

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Generated using Merimen e-Claims Internet Estimation & Adjusting System

11325.45

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Oct 2017)

Parts: M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SLA1926A/04/10/2017 18:33

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Rear bumper	0.00	0.00	*450.00 F de ✓
2	10		*Rear bumper clips	0.00	0.00	*15.00 F ne ✓
3	2		*Rear bumper retainer LH/RH	0.00	0.00	*24.00 F nh ✓
4	1		*Rear reverse sensor set	0	0.00	*250.00 FS 200nn ✓
5	1		*Rear end panel	0.00	0.00	*280.00 F ? x nh Rx ✓
6	1		*End panel garnish	0.00	0.00	*35.00 F ? nh ✓
7	1		*Tailgate	0.00	0.00	*580.00 F bt ✓
8	1		*Tailgate lock	0.00	0.00	*55.00 F bt ✓
9	1		*Tailgate inner trim board	0.00	0.00	*100.00 F ? nh ✓
10	2		*Tailgate hinge LH/RH	0.00	0.00	*50.00 F Rx ✓
11	1		*Rear bumper lower skirting	0	0.00	*600.00 FS de ✓
12	1		*Taillamp lower garnish RH	0.00	0.00	*80.00 F Rx ✓
13	1		*Taillamp lower garnish LH	0.00	0.00	*80.00 F Rx ✓
14	1		*Taillamp LH	0.00	0.00	*240.00 F x nh ✓
15	1		*Taillamp RH	0.00	0.00	*240.00 F x nh ✓
16	1		*Rear wheel arch garnish RH	0.00	0.00	*110.00 F de ✓
17	1		*Rear wheel arch garnish LH	0.00	0.00	*110.00 F x nh ✓
18	1		*Rear fender RH	0.00	0.00	-
			Repair and respray			
19	1		*Rear door RH	0.00	0.00	-
			Repair and respray			
20	1		*Rear fender LH	0.00	0.00	-
			Repair and respray			
21	1		*Rear door LH	0.00	0.00	-
			Repair and respray			
22	2		*Rear windscreen moulding LH/RH	0.00	0.00	*30.00 F ne ✓
23	2		*Rear windscreen moulding top and bottom	0.00	0.00	*30.00 F ne ✓
24	1		*Rear windscreen sealant	0	0.00	*60.00 FS ne ✓
25	1		*Tailgate reflector light LH	0.00	0.00	*140.00 F ? nh ✓
26	1		*Tailgate reflector light RH	0.00	0.00	*140.00 F ? nh ✓
27	1		*Rear number plate with casing	0	0.00	*45.00 FS x nh ✓
28	1		*Tailgate weatherstripe	0.00	0.00	*50.00 F nh ✓
29	1		*Spare tyre compartment	0.00	0.00	-
			Repair and respray			

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	3,794.00
+ Margin on L,N Items 15.00% (\$\$)	425.85
Total Parts (\$\$)	4,219.85

Hitachi Capital Asia Pacific Pte. Ltd/SLA1926A/04/10/2017 18:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New	2,400.00
2	Putty, blend and paint affected area	New	2,000.00
3	Check Wiring and ensure proper function	New	80.00
4	Remove & reinstall bumper sensors	New	120.00
5	Cavity Treatment on New Parts (tailgate, rear end panel, spare tyre compartment)	New	240.00
6	Conduct four wheel alignment	New	120.00
7	Realign chassis member	New	500.00
8	Remove & reinstall Rear reverse camera	New	120.00
9	Remove & re-install fuel tank to facilitate cutting and repairing work	New	180.00
10	Remove & re-install Rear Windscreen	New	180.00
11	Transfer tailgate lock & mechanism to new tailgate	New	180.00
12	Conduct water seepage test	New	120.00
13	Remove & re-install rear trim compartment to facilitate cutting and repairing work	New	150.00
14	Remove, refix & replace rear bumper lower skirting, tailgate spoiler	New	300.00
15	Diagnostic Check & Reset	New	250.00
Gross Labour Cost (S\$)			6,940.00

Hitachi Capital Asia Pacific Pte. Ltd./SLA1926A/04/10/2017 18:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

HITACHI
Inspire the Next

(SUPPLEMENTARY)

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)
LEOW RONG QING
Blk 932 Jurong West St 92
#12-189 Singapore 640932
Singapore

Claimant Insurer: Liberty Insurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	A80440002QMX	Date of Loss:	04/10/2017
Vehicle Reg. No.:	SLA1926A	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	SUM KAR SENG, EDDIE		
Make/Model:	HONDA VEZEL, 1.5 (A)	Vehicle Reg. Date:	24/02/2016
Vehicle Colour:	BLACK		
Engine No:	L15B4027761	Chassis No:	RU11107758
Odometer:	56661 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Description of Accident/Loss	REFER TO ATTACHMENT		
Present Location:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)		

COST OF CLAIMS	Amount
Parts	165.60
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	165.60
+ GST 7.00% (S\$)	11.59
Nett Amount (S\$)	177.19
+ Previous Estimates (S\$)	11,941.04
Claim Total (S\$)	12,118.23

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Jan 2018)
 Parts: M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SLA1926A/17/01/2018 18:17
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Rear smart buzzer	0.00	0.00	*45.00 F <i>na</i>
2	1		*Rear undercover	0.00	0.00	*90.00 F <i>de</i>
3	3		*Tailgate spoiler clip	0.00	0.00	*9.00 F <i>de</i>
Sub Total (S\$)						144.00
+ Margin on L,N Items 15.00% (S\$)						21.60
Total Parts (S\$)						165.60

F=Franchise part.

Hitachi Capital Asia Pacific Pte. Ltd/SLA1926A/17/01/2018 18:17. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Oct 2017 Sendback Est	04 Oct 2017 18:33 \$511,159.85	05 Oct 2017 10:18 Edit Adj Rpt	\$55,441.20 Edit Estimates	\$55,441.20 View Rpt		Pending for Survey Report Cancel Case
Supp #1	17 Jan 2018 18:13	17 Jan 2018 18:17 \$5165.60	17 Jan 2018 18:17			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	LEOW RONG QING, ID: S8139384B								
Main Claimant:	SUM KAR SENG, EDDIE, ID: S8018412C								
Vehicle Reg. No.:	SLA1926A	Date of Loss:	04/10/2017 08:00 - :59 [19 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 531909	Policy/Cover Note No.:	A80440002QMX Coverage: 25/08/2017 - 24/08/2018						
Vehicle Reg. No. (Insured):	SJH7900X	Policy No. (Claimant):	SD17V02124/VPE/R01						
		Excess:							
Repairer:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 04/11/2017]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLA1926A (531909)
[SJH7900X]
TP
SUM KAR SENG, EDDIE
Oct 4 2017 8:00AM
[LEOW RONG QING]
Hitachi Capital Asia Pacific Pte. Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Video				1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)		Thumbnail	Print
1	04/10/17 17:33	Video - Accident [Linked Accident Report Documents]		Load MOV	
2	04/10/17 17:33	Video - Accident [Linked Accident Report Documents]		Load MOV	
3	04/10/17 17:33	Video - Accident [Linked Accident Report Documents]		Load MOV	

Assessment Reports				1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)		Thumbnail	Print
1	04/10/17 17:51	Accident Statement		Load HTM	
2	04/10/17 18:33	Repairer Estimates		Load HTM	
3	17/01/18 18:17	Repairer Estimates Suppl. #1		Load HTM	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/04/18 17:30	General View		Load JPG	☒
2	19/04/18 17:30	General View		Load JPG	☒
3	19/04/18 17:30	General View		Load JPG	☒
4	19/04/18 17:30	General View		Load JPG	☒
5	19/04/18 17:30	General View		Load JPG	☒
6	19/04/18 17:30	General View		Load JPG	☒
7	19/04/18 17:30	General View		Load JPG	☒
8	19/04/18 17:30	General View		Load JPG	☒
9	19/04/18 17:30	General View		Load JPG	☒
10	19/04/18 17:30	General View		Load JPG	☒
11	19/04/18 17:30	General View		Load JPG	☒
12	19/04/18 17:30	General View		Load JPG	☒
13	19/04/18 17:30	General View		Load JPG	☒
14	19/04/18 17:30	General View		Load JPG	☒
15	19/04/18 17:30	General View		Load JPG	☒
16	19/04/18 17:30	General View		Load JPG	☒
17	19/04/18 17:30	General View		Load JPG	☒
18	19/04/18 17:30	General View		Load JPG	☒
19	19/04/18 17:30	General View		Load JPG	☒
20	19/04/18 17:30	General View		Load JPG	☒
21	19/04/18 17:30	General View		Load JPG	☒
22	19/04/18 17:30	General View		Load JPG	☒
23	19/04/18 17:30	General View		Load JPG	☒
24	19/04/18 17:30	General View		Load JPG	☒

Video			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
25	19/04/18 17:30	General View	 Load JPG	☒
26	19/04/18 17:30	General View	 Load JPG	☒
27	19/04/18 17:30	General View	 Load JPG	☒
28	19/04/18 17:30	General View	 Load JPG	☒
29	19/04/18 17:30	General View	 Load JPG	☒
30	19/04/18 17:30	General View	 Load JPG	☒
31	19/04/18 17:30	General View	 Load JPG	☒
32	19/04/18 17:30	General View	 Load JPG	☒
33	19/04/18 17:30	General View	 Load JPG	☒
34	19/04/18 17:30	General View	 Load JPG	☒
35	19/04/18 17:30	General View	 Load JPG	☒
36	19/04/18 17:30	General View	 Load JPG	☒
37	19/04/18 17:30	General View	 Load JPG	☒
38	19/04/18 17:30	General View	 Load JPG	☒
39	19/04/18 17:30	General View	 Load JPG	☒
40	19/04/18 17:30	General View	 Load JPG	☒
41	19/04/18 17:30	General View	 Load JPG	☒
42	19/04/18 17:30	General View	 Load JPG	☒
43	19/04/18 17:30	General View	 Load JPG	☒
44	19/04/18 17:30	General View	 Load JPG	☒
45	19/04/18 17:30	General View	 Load JPG	☒
46	19/04/18 17:30	General View	 Load JPG	☒
47	19/04/18 17:30	General View	 Load JPG	☒
48	19/04/18 17:30	General View	 Load JPG	☒
49	19/04/18 17:30	General View	 Load JPG	☒
50	19/04/18 17:30	General View	 Load JPG	☒
51	19/04/18 17:30	General View	 Load JPG	☒
52	19/04/18 17:30	General View	 Load JPG	☒
53	19/04/18 17:30	General View	 Load JPG	☒
54	19/04/18 17:30	General View	 Load JPG	☒
55	19/04/18 17:30	General View	 Load JPG	☒
56	19/04/18 17:30	General View	 Load JPG	☒
57	19/04/18 17:30	General View	 Load JPG	☒
58	19/04/18 17:30	General View	 Load JPG	☒
59	19/04/18 17:31	Replacement Part Photo	 Load JPG	☒
60	19/04/18 17:31	Replacement Part Photo	 Load JPG	☒
61	19/04/18 17:31	Replacement Part Photo	 Load JPG	☒
62	19/04/18 17:31	Replacement Part Photo	 Load JPG	☒
63	19/04/18 17:32	Replacement Part Photo	 Load JPG	☒
64	19/04/18 17:32	Replacement Part Photo	 Load JPG	☒
65	19/04/18 17:32	Replacement Part Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	04/10/17 17:51	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/05/18 11:06	Supplementary	 Load PDF	

Linked Accident Report Documents

View View in Browser			
Video			
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail Print
1	04/10/17 17:33	Video - Accident	 Load MOV
2	04/10/17 17:33	Video - Accident	 Load MOV
3	04/10/17 17:33	Video - Accident	 Load MOV
Assessment Reports			
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail Print
1	04/10/17 17:51	Accident Statement	 Load HTM
Photos/Images			
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail Print
1	04/10/17 17:24	Accident Photo	 Load JPG
2	04/10/17 17:24	Accident Photo	 Load JPG
3	04/10/17 17:24	Accident Photo	 Load JPG
4	04/10/17 17:24	Accident Photo	 Load JPG
5	04/10/17 17:24	Accident Photo	 Load JPG
6	04/10/17 17:24	Accident Photo	 Load JPG
7	04/10/17 17:24	Accident Photo	 Load JPG
8	04/10/17 17:24	Accident Photo	 Load JPG
9	04/10/17 17:33	Accident Photo	 Load JPG
10	04/10/17 17:33	Accident Photo	 Load JPG
11	04/10/17 17:33	Accident Photo	 Load JPG
12	04/10/17 17:33	Accident Photo	 Load JPG
13	04/10/17 17:33	Accident Photo	 Load JPG
Documentation			
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail Print
1	04/10/17 17:51	Sketch Plan	 Load TIF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17019108/T1QBE2
Date: 07/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80440002QMX
Claimant Vehicle No :	SLA1926A	Insured Vehicle No :	SJH7900X
Date of Loss:	04/10/2017	Nature of Claim:	TP
		Claim No:	531909

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA1926A	Engine No:	L15B4027761
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11107758
Reg. Date:	24/02/2016 (Man. Year: 2015)	Odometer:	56661 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,385.45	2,571.20	1,814.25	41.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,940.00	2,870.00	4,070.00	58.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,325.45	5,441.20	5,884.25	51.96
+ GST 7.00/7.00% (S\$)	792.78	380.88	411.90	51.96
Nett Amount (S\$)	12,118.23	5,822.08	6,296.15	51.96

INSPECTION

Date of Assignment:	05/10/2017 Present Location:	Hitachi Capital Asia Pacific Pte. Ltd (HQ)
Date Inspected:	06/10/2017 Inspected At:	No 8 Fourth Lok Yang Road
		Singapore 629705

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA1926A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Rear bumper (WCP)	Deformed	450.00 F	*450.00 F
2	10		*Rear bumper clips (WCP)	Necessary	15.00 F	*15.00 F
3	2		*Rear bumper retainer LH/RH (WCP)	Necessary	24.00 F	*24.00 F
4	1		*Rear reverse sensor set	Not Working	250.00 FS	*200.00 FS
5	1		*Rear end panel (WCP)	Repair	280.00 F	*- F
6	1		*End panel garnish (WCP)	Not Necessary	35.00 F	*- F
7	1		*Tailgate (WCP)	Bent	580.00 F	*580.00 F
8	1		*Tailgate lock (WCP)	Bent	55.00 F	*55.00 F
9	1		*Tailgate inner trim board (WCP)	Not Necessary	100.00 F	*- F
10	2		*Tailgate hinge LH/RH (WCP)	Repair	50.00 F	*- F
11	1		*Rear bumper lower skirting	Deformed	600.00 FS	*600.00 FS
12	1		*Taillamp lower garnish RH (WCP)	Repair	80.00 F	*- F
13	1		*Taillamp lower garnish LH (WCP)	Repair	80.00 F	*- F
14	1		*Taillamp LH (WCP)	Not Necessary	240.00 F	*- F
15	1		*Taillamp RH (WCP)	Not Necessary	240.00 F	*- F
16	1		*Rear wheel arch garnish RH (WCP)	Deformed	110.00 F	*110.00 F
17	1		*Rear wheel arch garnish LH (WCP)	Not Necessary	110.00 F	*- F
18	1		*Rear fender RH (WCP)(NPA)	Repair and respray	-	-
19	1		*Rear door RH (WCP)(NPA)	Repair and respray	-	-
20	1		*Rear fender LH (WCP)(NPA)	Repair and respray	-	-
21	1		*Rear door LH (WCP)(NPA)	Repair and respray	-	-
22	2		*Rear windscreen moulding LH/RH (WCP)	Necessary	30.00 F	*30.00 F
23	2		*Rear windscreen moulding top and bottom (WCP)	Necessary	30.00 F	*30.00 F
24	1		*Rear windscreen sealant	Necessary	60.00 FS	*60.00 FS
25	1			Not Necessary	140.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*Tailgate reflector light LH (WCP)			
26	1		*Tailgate reflector light RH (WCP)	Not Necessary	140.00 F	*- F
27	1		*Rear number plate with casing	Not Necessary	45.00 FS	*- FS
28	1		*Tailgate weatherstripe (WCP)	Twisted	50.00 F	*50.00 F
29	1		*Spare tyre compartment (WCP)(NPA)	Repair and respray	-	-
Supplementary #1						
30	1		*Rear smart buzzer (WCP)	Cracked	45.00 F	*45.00 F
31	1		*Rear undercover (WCP)	Deformed	90.00 F	*90.00 F
32	3		*Tailgate spoiler clip (WCP)	Necessary	9.00 F	*9.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	3,938.00	2,348.00
+ Margin on L,N Items 15.00/15.00% (S\$)	447.45	223.20
Total Parts (S\$)	4,385.45	2,571.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New	2,400.00	1,000.00
2	Putty, blend and paint affected area	New	2,000.00	1,200.00
3	Check Wiring and ensure proper function	New	80.00	30.00
4	Remove & reinstall bumper sensors	New	120.00	30.00
5	Cavity Treatment on New Parts (tailgate, rear end panel, spare tyre compartment)	New	240.00	60.00
6	Conduct four wheel alignment	New	120.00	-
7	Realign chassis member	New	500.00	-
8	Remove & reinstall Rear reverse camera	New	120.00	30.00
9	Remove & re-install fuel tank to facilitate cutting and repairing work	New	180.00	-
10	Remove & re-install Rear Windscreen	New	180.00	120.00
11	Transfer tailgate lock & mechanism to new tailgate	New	180.00	60.00
12	Conduct water seepage test	New	120.00	30.00
13	Remove & re-install rear trim compartment to facilitate cutting and repairing work	New	150.00	60.00
14	Remove, refix & replace rear bumper lower skirting, tailgate spoiler	New	300.00	100.00
15	Diagnostic Check & Reset	New	250.00	150.00
Gross Labour Cost (S\$)			6,940.00	2,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >