

ACT. REC. BY:

REF: CS/MSQ17019144/T1qber

Special Instruction:

Submitted by:

Merimen

Taufik

ASSIGNMENT (Office)

From (Person):

Vimmala

of

MSIG

Date/Time:

5/10/17 4:00pm

Estimated Cost:

Bill to:

☒ OD ☐ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐ CS

To Inspect Vehicle No:

GBB 72664

Insured:

at Workshop m/s

Hitachi Capital Asia

Tel:

64663022

of

No. 8 Fourth Lok Yung Rd, 629705 Pioneer

Policy No:

A28854994MKC

Claim No:

531924

Sum Insured:

Excess:

\$600.00

Make of Veh:

(Client's Record)

D.O.A.

3/10/17

CA

☒ REV

/ REP. / REV 24 HRS

Date/Time:

6/10/17 9:00am

Person Contacted:

Phoon

H.O.D. Endorsement:

Vehicle:

☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓)

Estimate

GBB 72664-X

9/10-

Revert via merimen

09/10/17 @ 3.44pm

Authorise repair by Huey Ni.

09/10/17 @ 4.19pm

Informed Hitachi Capital C/A S EX: \$600 by email.

19/9/18 @ 5.35pm

2nd revert to Vimmala via merimen (supplementing).

Tan Jiah

REF MSIG

ASSIGNMENT

From _____ Date 6/10/17

Estimated Cost _____

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. _____

at Worked in Hitachi Capital Asia

at No. 8 Fourth Lok Yang Rd, 629705 Pioneer

Insured _____

Policy No. _____

Claims No. _____

Sum Insured _____

Excess \$ 600.00

(Client's Record) _____

Name of van _____

(Policy Condition) _____

Remark: The veh had commenced its repair at the time of inspection



Bar or Marker Value _____

823K

D/O Accident Report _____ Consistent? Yes or No

G/L PR Seen _____ Consistent? Yes or No

Est. Repairs 8 days Res Yes or No

Lump Sum _____ % 3 Val Yes or No

CA / ☒ REV / REF. / 24 HRS

Date _____

Person Contacted _____

Vehicle IN / OUT

Date Time Action Instruction

29/8/17

Confirm 1597.60, 8 days (Red \$ 3724.40, 38/-)

RECEIVED 24 SEP 2018

Van No. G6672664 Vr Reg. 2009 / Dec.

Type M.Car / M.Cycle / Bus / Van / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make Mitsubishi FB 70

CC 277

Colour White AD Insured / Std / N / NA

Sp Reading 226232 T Ratio Insured / Std / N / NA

Eng No. _____

C No. FB 70 BSA 20134

Gen Cond Good / Fair / Poor / Burnt

Steering Indented / Jammed / Leaked / Burnt or

Brake Indented / Jammed / Leaked / Burnt or

Mod N / S Rim / STD A/Rim or

Tyre Size F 145/45
R 17

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUM /
TOYO / YOKO or

Front _____

Rear _____

R Ba 6 mm R Ba 6 mm

L Ba 6 mm L Ba 6 mm

D/O A _____ D/O I 6/10/17

Survey held at Hitachi Capital

Des of Damages ☒ Fr / Rear / O/S / N/S / UC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date Time File Pass to:

29/9/2018

Date Time File Return to:

☐ Prelim. Report

☐ Final Report

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp \$

☐ Interview \$

☐ Techn. Invs \$

☐ Weekend \$

Report Format: WER-01

Lump Sum / I.B.I: \$ 5971.60

Survey Fee

Transponder

\$ - \$

Phone

Other

TOTAL

200
10
210

19/9/2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17019144/T1qb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 06-10-2017		
		Code : MSG		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		GBB 7266U
Policy No.	A28854994MKC	Coverage (\$)		0.00
Claim No.	531924	Excess (\$)		600.00
Assign From	MERIMEN (VIMMALA)	Assign Date		06/10/2017
2. Vehicle Particulars & Condition				
Make & Model		c.c		0
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date		03/10/2017	Inspection Date	
Survey held at		HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705		
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Oct 2017 Sendback Est	05 Oct 2017 10:42 \$9,278.00	05 Oct 2017 16:00 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	CNC GENERAL CONTRACTORS PTE LTD , Co. Reg. No.: 200917807R		
Vehicle Reg. No.:	GBB7266U	Date of Loss:	03/10/2017 18:00 - :59
Claim Type:	OD / 531924	Policy/Cover Note No.:	A28854994MKC (Comprehensive) Coverage: 21/12/2016 - 20/12/2017
		Excess:	S\$600.00
Repairer:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/10/2017]		
Driver/Custodian:	TEO THIAM HUAT (56 / Male), NRIC: S15126011, Tel: +6598278797		
Adj Asg. Remarks:	TO REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	05 Oct 2017 10:11	Clim Veh Model Changed	(202205) MITSUBISHI FB70BB1SRDEA 3.0 D (M).	[R] Grant Chong Kean Yap
2	05 Oct 2017 10:11	Clim Created	Reg No: GBB7266U, Policy No: A28854994MKC, Acct Date: 2017/10/03, Claim Type: OD, Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ), Workshop: Hitachi Capital Asia Pacific Pte. Ltd (HQ), Created from SAS:MJT117131725	[R] Grant Chong Kean Yap
3	05 Oct 2017 10:42	Clim Submitted	9278.00.	[R] Grant Chong Kean Yap
4	05 Oct 2017 13:42	Clim Registration Modified	Excess: -> 600.00.	[I] Jocelyn Ng Shin Bun
5	05 Oct 2017 14:36	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):TO AUTHORIZE REPAIR I F DAMAGES ARE CONSISTENT.	[I] Koh Ming Shao
6	05 Oct 2017 14:36	Adj Next Rpt Changed	Next Rpt:Im, Advice, Due Date:2017/10/06	[I] Koh Ming Shao
7	05 Oct 2017 14:36	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Koh Ming Shao
8	05 Oct 2017 15:23	Assignment 1st Accessed		[A] Pauline Soh Li Ping
9	05 Oct 2017 15:59	Adj Assignment Cancelled		[I] Jocelyn Ng Shin Bun
10	05 Oct 2017 15:59	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Jocelyn Ng Shin Bun
11	05 Oct 2017 16:00	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):TO REVERT	[I] Jocelyn Ng Shin Bun
12	05 Oct 2017 16:00	Adj Next Rpt Changed	Next Rpt:Im, Advice, Due Date:2017/10/06	[I] Jocelyn Ng Shin Bun
13	05 Oct 2017 16:00	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Jocelyn Ng Shin Bun
14	05 Oct 2017 16:04	Assignment 1st Accessed		[A] Nivitha Govindasamy
15	06 Oct 2017 13:22	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH	[A] CATHERINE CHONG KAI LING
16	09 Oct 2017 12:08	Adj Rpt Initiated		[A] DENISE TAY KWEE CHENG
17	09 Oct 2017 12:14	Adj Im, Advice Submitted	Next Rpt:Final Rpt, Due Date:2017/11/04	[A] DENISE TAY KWEE CHENG
18	09 Oct 2017 12:14	Adj Next Rpt Changed	Next Rpt:Final Rpt, Due Date:2017/11/04	[A] DENISE TAY KWEE CHENG
19	09 Oct 2017 12:14	Adj Mandate Request	Cur,Req:6419.00:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
20	09 Oct 2017 15:44	Adj Next Rpt Changed	Next Rpt:Final Rpt, Due Date:2017/11/04	[I] Eng Huey Ni
21	09 Oct 2017 15:44	Adj Mandate Set	Approved:6419.00.	[I] Eng Huey Ni
22	17 Jan 2018 16:53	Clim Supp Created (S:675897)		[R] Grant Chong Kean Yap
23	17 Jan 2018 16:53	Clim Submitted (S:675897)	418.00.	[R] Grant Chong Kean Yap
24	17 Jan 2018 16:53	Adj Co Assigned (S:675897)	LKK Auto Consultants Pte Ltd (HQ):	[I] Merimen Administrator
25	14 Mar 2018 08:57	Supp Combined (S:675897)		[A] SHIAU CHAN
26	19 Sep 2018 17:34	Adj Im, Advice Submitted	Next Rpt:Final Rpt, Due Date:2017/11/04	[A] SHIAU CHAN
27	19 Sep 2018 17:35	Adj Mandate Request	Cur,Req:5971.60:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
28	21 Sep 2018 17:07	Adj Next Rpt Changed	Next Rpt:Final Rpt, Due Date:2017/11/04	[I] Eng Huey Ni
29	21 Sep 2018 17:07	Adj Mandate Set	Approved:5971.60.	[I] Eng Huey Ni

Date From



Date To



Audit Type None

Go

ACTIVITY

[05/10/2017 15:34] Pauline Soh Li Ping:
Car in, IHS unable to attend (ET-MC, AL-Paperwork, DC- Appt Full)
[05/10/2017 15:25] Pauline Soh Li Ping:
No one pick call

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1601939	05/10/2017 10:11	Motor	Hitachi Capital Asia Pacific Pte. Ltd	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	GBB7266U		xx.xx
1604725	09/10/2017 12:08	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBB7266U		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimimala D/O Raja Singam

Date: 19 Sep 2018

Preliminary Advice

Vehicle No	: GBB7266U	Accident Date	: 03/10/2017
Make	: MITSUBISHI FB70BB1SRDEA	Policy No.	: A28854994MKC
Assignment Date	: 05/10/2017	Excess	: S\$600.00
Date of Inspection	: 06/10/2017	Est. Duration of Repair	: 8.00
Inspection At	: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ) NO 8 FOURTH LOK YANG ROAD SINGAPORE 629705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,696.00	(ESTIMATE \$9,278.00 + SUPPLEMENTARY \$418.00)
Revised Amount	:S\$	5,971.60	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	5,971.60	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	23,000.00
COE / PARF Rebate	:S\$	4,106.00
Salvage Value	:S\$	
Margin for Repair	:S\$	18,894.00

Remarks

(X) The vehicle is economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. KINDLY APPROVE ON SUPPLEMENTARY.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 9 October, 2017 4:19 PM
To: 'keanyap.chong@hcspl.com.sg'; 'SunZhuMei@hcspl.com.sg'; 'PatrickLK.Mok@hcspl.com.sg'
Cc: SUR
Subject: GBB 7266U OWN DAMAGE MSIG

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **GBB 7266U (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

GBB7266U (531924)

OD

Oct 3 2017 6:00PM

[CNC GENERAL CONTRACTORS PTE LTD]

Hitachi Capital Asia Pacific Pte. Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 09/10/2017 15:44 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6419.00) - GBB7266U - Claim Handler: Vimmala D/O Raja Singam

Approved:6419.00.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimimala D/O Raja Singam

Date: 09 Oct 2017

Preliminary Advice

Vehicle No	: GBB7266U	Accident Date	: 03/10/2017
Make	: MITSUBISHI FB70BB1SRDEA	Policy No.	: A28854994MKC
Assignment Date	: 05/10/2017	Excess	: S\$600.00
Date of Inspection	: 06/10/2017	Est. Duration of Repair	: 8.00
Inspection At	: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ) NO 8 FOURTH LOK YANG ROAD SINGAPORE 629705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,278.00
Revised Amount	:S\$	5,918.00
Check Items (Estimated)	:S\$	501.00
Total	:S\$	6,419.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	23,000.00
COE / PARF Rebate	:S\$	4,106.00
Salvage Value	:S\$	
Margin for Repair	:S\$	18,894.00

Remarks

(x) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 7807R

Vehicle Details

Vehicle No.: GBB7266U

Vehicle to be Exported: No

Intended De-registration Date: 09 Oct 2017

Vehicle Make: MITSUBISHI

Vehicle Model: FB70BB1SRDEA

Primary Colour: White

Manufacturing Year: 2009

Engine No.: 4M42A74832

Chassis No.: FB70BBA20134

Maximum Power Output: -

Open Market Value: \$28,238.00

Original Registration Date: 21 Dec 2009

First Registration Date: 21 Dec 2009



Transfer Count:

Actual ARF Paid: \$1,412.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE No.: 2010010105000073K

COE Expiry Date: 20 Dec 2019

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$18,289.00

COE Rebate Amount: \$4,016.00

Total Rebate Amount: \$4,016.00

The information contained herein is correct as at 09 Oct 2017

OK

 Land Transport Authority (<https://www.lta.gov.sg>)

Please read through the [Privacy Statement](#), [Terms of Use](#), and [Disclaimer](#).

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) |

[Rate this e-Service \(https://www.lta.gov.sg/feedback/PublicSurvey.aspx?SurveyDetlNum=S201400011\)](https://www.lta.gov.sg/feedback/PublicSurvey.aspx?SurveyDetlNum=S201400011)

Last updated on 08 Oct 2017 at 01:03 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/10/2017 17:09
Date Of Accident	03/10/2017 18:10
Exact Location Of Accident	ANG MO KIO AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBB7266U
Insured/Policyholder	
Name Of Registered Owner	CNC GENERAL CONTRACTORS PTE LTD
Co Reg No	200917807R
Email Address	GENERAL@CNC.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-67957378

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FB70BB1SRDEA-3.0 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A28854994MKC
Cover Note Number	

Driver

Name of Driver	TEO THIAM HUAT
NRIC No	S1512601I
Date Of Birth	27/09/1961
Occupation	OUTDOOR
Date Of Driving Pass	10/05/1982
Driving Experience	35 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98278797
Fax Number	
Contact Number	
Email Address	GENERAL@CNC.COM.SG

Address	BLK 467A FERNVALE LINK #11-513
Postcode	791467
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	9

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKB3628D
Vehicle Make/Model/Colour	AUDI
Details Of Properties	
Name of Driver	ANG WEISI DIXSON
NRIC/Passport Number	S8131803D
Contact Number	90699589
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A: G537266U
B: SKR36280



Describe Circumstances of the Accident

On 03 Oct 2018 @ 1810 HRS MY PICKUP GRB 1266U HIT TO THE VEHICLE AUBE SKB 3628D. DURING THE TIME I WAS PICKUP MY COMPANY WORKERS BACK TO DORMITORY. ON MY WAY THERE WAS A RAINING. WHEN I ALIGHT ANG MD KID AVE OI 'T' JUNCTION TRAFFIC SIGNAL LIGHTS. THERE WAS CAR IN FRONT OF MY VEHICLE I TRY TO STOP MY VEHICLE. IT'S SLIP DUE TO WET ROAD AND HIT THE FRONT VEHICLE (SKB 3628D). AS A RESULT BOTH VEHICLE WERE DAMAGED (REFER TO THE ATTACHED IMAGES)

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

HITACHI
 Inspire the Next
INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	A28854994MKC	Date of Loss:	03/10/2017
Vehicle Reg. No.:	GBB7266U	Driveable?	
Driver Age/Info:	56 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CNC GENERAL CONTRACTORS PTE LTD		
Driver:	TEO THIAM HUAT		
Make/Model:	MITSUBISHI FB70BB1SRDEA, 3.0 D (M)	Vehicle Reg. Date:	21/12/2009
Vehicle Colour:	WHITE		
Engine No:	4M42A74832	Chassis No:	FB70BBA20134
Odometer:	100000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO ATTACHMENT		
Present Location:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)		

Tanphie 97495749
Ex \$600
Reserv 6/10/17 @ 1335
8 days
Reserv before paint
sur @ 1/10/17

COST OF CLAIMS

Parts		Amount
Miscellaneous Items		
Labour		
Paintwork Labour		
Towing		
	Calculated Gross Total (\$\$)	9,278.00
	- Excess (\$\$)	600.00
	(\$\$)	8,678.00
	+ GST 7.00% (\$\$)	607.46
	Nett Amount (\$\$)	9,285.46

LKK Auto Consultants hereby notify the Repairer of the following:

- To be surveyed before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

This claim is handled by: **GRANT CHONG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 05 Oct 2017)

Parts: N/A MITSUBISHI FB70BB1SRDEA 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Hitachi Capital Asia Pacific Pte. Ltd/GBB7266U/05/10/2017 10:42

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Wiper base garnish set	0.00	0.00	*380.00 F <i>al</i>
2	1		*Front top panel assembly	0.00	0.00	*480.00 F <i>bt</i>
3	2		*Front corner panel LH/RH	0.00	0.00	*490.00 F <i>Rx</i>
4	1		*Front grille	0.00	0.00	*360.00 F <i>com</i>
5	1		*Front grille logo	0.00	0.00	*55.00 F <i>nh</i>
6	1		*Front emblem Fuso (grille)	0.00	0.00	*85.00 F <i>nh</i>
7	8 <i>4</i>		*Front grille clip	0.00	0.00	*48.00 F <i>nh</i>
8	2		*Signal lamp top LH/RH	0.00	0.00	*320.00 F <i>ov</i>
9	2		*Side lamp LH/RH <i>LH-04, RH-38 NH</i>	0.00	0.00	*220.00 F
10	2		*Headlamp LH/RH	0.00	0.00	*700.00 F <i>an</i>
11	2		*Headlamp lower garnish LH/RH	0.00	0.00	*52.00 F <i>de</i>
12	1		*Front bumper	0.00	0.00	*480.00 F <i>bt</i>
13	2		*Front bumper bracket LH/RH	0.00	0.00	*220.00 F <i>bt</i>
14	1		*Aircon blower motor	0.00	0.00	-
15	1		*Aircon blower motor casing set	0.00	0.00	-
16	1		*Aircon suction pipe	0.00	0.00	-
17	1		*Aircon discharge pipe	0.00	0.00	-
18	1		*Front lower cooling fan	0.00	0.00	-
19	1		*Front lower cooling fan blade	0.00	0.00	-
20	1		*Front lower cooling fan motor	0.00	0.00	-
21	1		*Dashboard assembly	0.00	0.00	*750.00 F <i>xw</i>
22	1		*Front windscreen moulding	0.00	0.00	*240.00 F <i>nh</i>
23	1		*Sealant	0	0.00	*45.00 FS <i>an</i>
24	2		*Front door LH/RH	0.00	0.00	-
25	1		*Front number plate	0	0.00	*45.00 FS <i>bt 30</i>

F=Franchise part. S=SpcNett.

Sub Total (S\$)	4,970.00
+ Margin on L,N Items 10.00% (S\$)	488.00
Total Parts (S\$)	5,458.00

Hitachi Capital Asia Pacific Pte. Ltd/GBB7266U/05/10/2017 10:42 Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New	1,600.00 900 ✓
2	Putty, blend and paint affected area	New	1,400.00 800 ✓
3	Check Wiring, re-align headlamps and ensure proper function	New	80.00 40 ✓
4	Refill compressor oil, vacuum and refill aircond gas	New	180.00 100 ✓
5	Remove & re-install Front Windscreen	New	RM X 180.00 120 ✓
6	Remove & re-install front trim compartment and dashboard assembly to facilitate cutting and repairing work	New	380.00 200 ✓
Gross Labour Cost (S\$)			3,820.00 plus

Hitachi Capital Asia Pacific Pte. Ltd/GBB7266U/05/10/2017 10:42. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

@ Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835

www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

HITACHI
 Inspire the Next

INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	A28854994MKC	Date of Loss:	03/10/2017
Vehicle Reg. No.:	GBB7266U	Driveable?	
Driver Age/Info:	56 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CNC GENERAL CONTRACTORS PTE LTD		
Driver:	TEO THIAM HUAT		
Make/Model:	MITSUBISHI FB70BB1SRDEA, 3.0 D (M)	Vehicle Reg. Date:	21/12/2009
Vehicle Colour:	WHITE	Chassis No:	FB70BBA20134
Engine No:	4M42A74832		
Odometer:	100000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO ATTACHMENT		
Present Location:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)		

Tanpin 97495744.
 Ex \$600
 Repair 6/10/17 @ 1535
 8 days
 Resumy before paint
 Sur @ 1/10/2017

COST OF CLAIMS	Amount
Parts	5,458.00
Miscellaneous Items	0.00
Labour	3,820.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	9,278.00
- Excess (S\$)	600.00
(S\$)	8,678.00
+ GST 7.00% (S\$)	607.46
Nett Amount (S\$)	9,285.46

This claim is handled by: GRANT CHONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 05 Oct 2017)

Parts: N/A MITSUBISHI FB70BB1SRDEA 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Hitachi Capital Asia Pacific Pte. Ltd/GBB7266U/05/10/2017 10:42

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Wiper base garnish set	0.00	0.00	✓ *380.00 F al ✓
2	1		*Front top panel assembly	0.00	0.00	✓ *480.00 F bt ✓
3	2		*Front corner panel LH/RH	0.00	0.00	X *490.00 F Ry ✓
4	1		*Front grille	0.00	0.00	✓ *360.00 F con ✓
5	1		*Front grille logo	0.00	0.00	X *55.00 F rh ✓
6	1		*Front emblem Fuso (grille)	0.00	0.00	X *85.00 F rh ✓
7	8	A	*Front grille clip 46 X 4 = 424	0.00	0.00	424 ✓ *48.00 F rh ✓
8	2		*Signal lamp top LH/RH	0.00	0.00	✓ *320.00 F on ✓
9	2		*Side lamp LH/RH LH-CA / RH-? ✓	0.00	0.00	✓ *220.00 F 4110 ✓
10	2		*Headlamp LH/RH	0.00	0.00	✓ *700.00 F an ✓
11	2		*Headlamp lower garnish LH/RH	0.00	0.00	✓ *52.00 F de ✓
12	1		*Front bumper	0.00	0.00	✓ *480.00 F bt ✓
13	2		*Front bumper bracket LH/RH	0.00	0.00	✓ *220.00 F bt ✓
14	1		*Aircon blower motor	0.00	0.00	X
15	1		*Aircon blower motor casing set	0.00	0.00	X
16	1		*Aircon suction pipe	0.00	0.00	X
17	1		*Aircon discharge pipe	0.00	0.00	X
18	1		*Front lower cooling fan	0.00	0.00	X
19	1		*Front lower cooling fan blade	0.00	0.00	X
20	1		*Front lower cooling fan motor	0.00	0.00	X
21	1		*Dashboard assembly	0.00	0.00	X *750.00 F X
22	1		*Front windscreen moulding	0.00	0.00	X *240.00 F rh ✓
23	1		*Sealant	0	0.00	✓ *45.00 FS an ✓
24	2		*Front door LH/RH	0.00	0.00	
			Repair			
25	1		*Front number plate	0	0.00	✓ *45.00 FS bt 30 ✓
Sub Total (S\$)						4,970.00 3126
+ Margin on L,N Items 10.00% (S\$)						488.00 380
Total Parts (S\$)						5,458.00 3856.60
						84-75

F=Franchise part. S=SpcNett.

Hitachi Capital Asia Pacific Pte. Ltd/GBB7266U/05/10/2017 10:42. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

supplementary
1) Aircon condenser \$200 / rh bt ✓
2) Aircon fan assembly \$180 / rh on ✓

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New	1,600.00 900 ✓
2	Putty, blend and paint affected area	New	1,400.00 800 ✓
3	Check Wiring, re-align headlamps and ensure proper function	New	80.00 40 ✓
4	Refill compressor oil, vacuum and refill aircond gas	New	180.00 100 ✓
5	Remove & re-Install Front Windscreen	New	X180.00 120 ✓
6	Remove & re-install front trim compartment and dashboard assembly to facilitate cutting and repairing work	New	380.00 200 ✓
Gross Labour Cost (S\$)			3,820.00 2040 ✓

Hitachi Capital Asia Pacific Pte. Ltd/GBB7266U/05/10/2017 10:42. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

© Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax: 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

supplementary item \$ 380 + 10% = \$ 418

parts \$ 3126 + 10% = \$ 3438.60

stnkt \$ 75

labour \$ 2040

* Total p/p \$ 5971.60 * (2) 8 day *

(SUPPLEMENTARY)

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	A28854994MKC	Date of Loss:	03/10/2017
Vehicle Reg. No.:	GBB7266U	Driveable?	
Driver Age/Info:	56 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CNC GENERAL CONTRACTORS PTE LTD		
Driver:	TEO THIAM HUAT		
Make/Model:	MITSUBISHI FB70BB1SRDEA, 3.0 D (M)	Vehicle Reg. Date:	21/12/2009
Vehicle Colour:	WHITE		
Engine No:	4M42A74832	Chassis No:	FB70BBA20134
Odometer:	100000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO ATTACHMENT		
Present Location:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)		

COST OF CLAIMS	Amount
Parts	418.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	418.00
+ GST 7.00% (S\$)	29.26
Nett Amount (S\$)	447.26
+ Previous Estimates (S\$)	9,285.46
Claim Total (S\$)	9,732.72

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 17 Jan 2018)**Parts:** N/A MITSUBISHI FB70BB1SRDEA 3.0 D (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Hitachi Capital Asia Pacific Pte. Ltd/GBB7266U/17/01/2018 16:53**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Aircon condensor	0.00	0.00	*200.00 F
2	1		*Aircon fan assembly	0.00	0.00	*180.00 F
						Sub Total (S\$)
						380.00
						+ Margin on L,N Items 10.00% (S\$)
						38.00
						Total Parts (S\$)
						418.00

F=Franchise part.

Hitachi Capital Asia Pacific Pte. Ltd/GBB7266U/17/01/2018 16:53. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

豐裕工業 (私營) 有限公司
FONG EE INDUSTRIAL (PTE) LIMITED

(AUTOMOTIVE DIVISION)
No. 3 Kallang Way 2A Fong Tat Building Singapore 347493 Tel: 67489588/67489589 Fax: 67485888/67485889
25 Kallang Road 4, #01-23 Synergy @ KB Singapore 417900 Tel: 6395 6369 / 6394 2226 Fax: 6394 2245
Blk SBS #01-324 Race Course Road Singapore 210685 Tel: 62964551 Fax: 62970774
Co. Reg No.: 197802013M



GST Reg. No.: M2-00252314

INVOICE
HITACHI CAPITAL ASIA PACIFIC PTE LTD
8, FOURTH LOK YANG RD
SINGAPORE 629705
GEB 7266 U
ORDER BY: GRANT

TAX INVOICE NO.: TL123769
INVOICE DATE : 10/10/2017
CREDIT TERMS : CASH
SALES ORDER-NO.:
SALESMAN : LLK
PAGE(S) : 1

PARTS NO.	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE (SIN)	AMOUNT (SIN)
ORDER BY: GRANT					
MK403437	WIPER GARNISH		1 PCS	380.000	380.00
MK997155	FR PANEL		1 PCS	480.000	480.00
MK546829	FR GRILLE		1 PCS	360.000	360.00
MK484432	CLIP, FR GRILLE		2 PCS	6.000	12.00
MC149236	CLIP, FR GRILLE		2 PCS	6.000	12.00
MK427117	SIGNAL LAMP, LH		1 PCS	160.000	160.00
MK427118	SIGNAL LAMP, RH		1 PCS	160.000	160.00
MK353663	SIDE LAMP, LH		1 PCS	110.000	110.00
MK353631	HEADLAMP, LH		1 PCS	350.000	350.00
MK353632	HEADLAMP, RH		1 PCS	350.000	350.00
MK545840	BEZEL, HEADLAMP		2 PCS	26.000	52.00

FONG EE INDUSTRIAL (PTE) LIMITED
GOODS SOLD ARE NOT RETURNABLE FOR CASH
GOODS RECEIVED
TOTAL

AUTHORISED SIGNATURE

10:30

SIGNATURE



豐裕工業 (私營) 有限公司
FONG EE INDUSTRIAL (PTE) LIMITED
(AUTOMOTIVE DIVISION)

No. 3 Kallang Way 2A Fong Tat Building Singapore 347493 Tel: 67403588/67486358 Fax: 67405868/67435007
25 Kallang Road 4, #01-02 Synergy @ Kallang Singapore 3417600 Tel: 6306 6099 / 6304 2225 Fax: 6304 2245
Bk 685 901-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774
Co. Reg. No.: 197802013M

GST Reg. No.: M2-00252314

INVOICE
HYTACHI CAPITAL ASIA PACIFIC PTE LTD
8, FOURTH LOK YANG RD
SINGAPORE 629705
G8B 7266 U
ORDER BY: GRANT



PORSCHE

TAX INVOICE NO.: TL123769
INVOICE DATE : 10/10/2017
CREDIT TERMS : CASH
SALES ORDER NO.:
SALESMAN : LLK
PAGE(S) : 2

TAX INVOICE

PARTS NO.	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE (SIN)	AMOUNT (SIN)
MK403828	ORDER BY: GRANT FR BUMPER		1 PCS	480.000	480.00
MK402478	FR BUMPER BRACKET, LH		1 PCS	110.000	110.00
MK402479	FR BUMPER BRACKET, RH		1 PCS	110.000	110.00
GST Excl Amount :					3126.00
Special Discount :					218.82
GST @ 7 %					

FONG EE INDUSTRIAL (PTE) LIMITED GOODS SOLD ARE NOT RETURNABLE FOR CASH GOODS RECEIVED

PRINT BY :

LLK 10/10/2017 16:30:37

AUTHORISED SIGNATURE

SIGNATURE

3344.82

TOTAL



豐裕工業 (私營) 有限公司
FONG EE INDUSTRIAL (PTE) LIMITED
 (AUTOMOTIVE DIVISION)

No. 3 Kallang Way 2A Fong Tai Building Singapore 347493 Tel: 67495866/67495958 Fax: 67495866/67495907
 25 Kallit Road 4, #01-23 Synergy @ JB Singapore 417800 Tel: 6396 6395 / 6394 2235 Fax: 6394 2245
 Blk 665 #01-324 Hase Course Road Singapore 210685 Tel: 62954551 Fax: 62970774
 Co. Reg. No.: 197602013M



GST Reg. No.: M2-00252314

INVOICE TO: HATCHI CAPITAL ASIA PACIFIC PTE LTD
 8, FOURTH LOK YANG RD
 SINGAPORE 629705
 GBB 7266 U
 ORDER BY: GRANT

TAX INVOICE NO.: TL123773
 INVOICE DATE : 11/10/2017
 CREDIT TERMS : CASH
 SALES ORDER NO.:
 SALESMAN : LLK
 PAGE(S) : 1

PARTS NO.	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE (SIN)	AMOUNT (SIN)
92110/FB70B	ORDER BY: GRANT A/C CONDENSER		1 PCS	200.000	200.00
97380/FB70B	A/C FAN ASSY		1 PCS	180.000	180.00
	GST Excl Amount :				380.00
	Special Discount :				26.60
	GST @ 7 %				

FONG EE INDUSTRIAL (PTE) LIMITED GOODS SOLD ARE NOT RETURNABLE FOR CASH GOODS RECEIVED
 PRINT BY :
 LLK 11/10/2017 10:10:19
TOTAL 406.60

AUTHORISED SIGNATURE

SIGNATURE

[Signature]

10:25-
10:25

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Oct 2017 Sendback Est	05 Oct 2017 10:42 \$9,278.00	05 Oct 2017 16:00 Edit Adj Rpt	\$5,971.60 Edit Estimates	\$5,971.60 View Rpt		Pending for Survey Report Cancel Case
Supp #1	17 Jan 2018 16:53	17 Jan 2018 16:53 \$418.00	17 Jan 2018 16:53			(Combined)	Combined with Main Uncombine Suppl

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	CNC GENERAL CONTRACTORS PTE LTD, Co. Reg. No.: 200917807R		
Vehicle Reg. No.:	GBB7266U	Date of Loss:	03/10/2017 18:00 - :59 [93 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 531924	Policy/Cover Note No.:	A28854994MKC (Comprehensive) Coverage: 21/12/2016 - 20/12/2017
		Excess:	\$5600.00
Repairer:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmla D/O Raja Singam - 65942471]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 04/11/2017]		
Driver/Custodian:	TEO THIAM HUAT (56 / Male), NRIC: S15126011, Tel: +6598278797		
Adj Asg. Remarks:	TO REVERT		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- MSIG_SG (21/09/2018): Alert - Adj Mandate Approved (\$5971.60) - GBB7266U - Claim Handler: Vimmla D/O...
- MSIG_SG (13/09/2018): GBB7266U (531924)
- MSIG_SG (24/07/2018): GBB7266U (531924)
- MSIG_SG (09/10/2017): Alert - Adj Mandate Approved (\$6419.00) - GBB7266U - Claim Handler: Vimmla D/O...

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

GBB7266U (531924)
OD
Oct 3 2017 6:00PM
[CNC GENERAL CONTRACTORS PTE LTD]
Hitachi Capital Asia Pacific Pte. Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	04/10/17 17:52	Accident Statement	 Load HTM	
2	05/10/17 10:42	Repairer Estimates	 Load HTM	
3	17/01/18 16:53	Repairer Estimates Suppl. #1	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/10/17 12:14	Adjuster Immediate Advice	 Load HTM	
2	19/09/18 17:34	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	04/10/17 17:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
2	04/10/17 17:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
3	04/10/17 17:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
4	04/10/17 17:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
5	04/10/17 17:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
6	04/10/17 17:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
7	04/10/17 17:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
8	04/10/17 17:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
9	04/10/17 17:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
10	04/10/17 17:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
11	04/10/17 17:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
12	04/10/17 17:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/09/18 18:12	General View	 Load JPG	☒
2	18/09/18 18:12	General View	 Load JPG	☒
3	18/09/18 18:12	General View	 Load JPG	☒
4	18/09/18 18:12	General View	 Load JPG	☒
5	18/09/18 18:12	General View	 Load JPG	☒
6	18/09/18 18:12	General View	 Load JPG	☒
7	18/09/18 18:12	General View	 Load JPG	☒
8	18/09/18 18:12	General View	 Load JPG	☒
9	18/09/18 18:12	General View	 Load JPG	☒
10	18/09/18 18:12	General View	 Load JPG	☒
11	18/09/18 18:12	General View	 Load JPG	☒
12	18/09/18 18:12	General View	 Load JPG	☒
13	18/09/18 18:12	General View	 Load JPG	☒
14	18/09/18 18:12	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
15	18/09/18 18:12	General View	 Load JPG	☒
16	18/09/18 18:12	General View	 Load JPG	☒
17	18/09/18 18:12	General View	 Load JPG	☒
18	18/09/18 18:12	General View	 Load JPG	☒
19	18/09/18 18:12	General View	 Load JPG	☒
20	18/09/18 18:12	General View	 Load JPG	☒
21	18/09/18 18:12	General View	 Load JPG	☒
22	18/09/18 18:12	General View	 Load JPG	☒
23	18/09/18 18:12	General View	 Load JPG	☒
24	18/09/18 18:12	General View	 Load JPG	☒
25	18/09/18 18:12	General View	 Load JPG	☒
26	18/09/18 18:12	General View	 Load JPG	☒
27	18/09/18 18:12	General View	 Load JPG	☒
28	18/09/18 18:12	General View	 Load JPG	☒
29	18/09/18 18:12	General View	 Load JPG	☒
30	18/09/18 18:12	General View	 Load JPG	☒
31	18/09/18 18:12	General View	 Load JPG	☒
32	18/09/18 18:12	General View	 Load JPG	☒
33	18/09/18 18:12	General View	 Load JPG	☒
34	18/09/18 18:12	General View	 Load JPG	☒
35	18/09/18 18:12	General View	 Load JPG	☒
36	18/09/18 18:12	General View	 Load JPG	☒
37	18/09/18 18:12	General View	 Load JPG	☒
38	18/09/18 18:12	General View	 Load JPG	☒
39	18/09/18 18:12	General View	 Load JPG	☒
40	18/09/18 18:12	General View	 Load JPG	☒
41	18/09/18 18:12	General View	 Load JPG	☒
42	18/09/18 18:12	General View	 Load JPG	☒
43	18/09/18 18:12	General View	 Load JPG	☒
44	18/09/18 18:12	General View	 Load JPG	☒
45	18/09/18 18:12	General View	 Load JPG	☒
46	18/09/18 18:12	General View	 Load JPG	☒
47	18/09/18 18:12	General View	 Load JPG	☒
48	18/09/18 18:12	General View	 Load JPG	☒
49	18/09/18 18:12	General View	 Load JPG	☒
50	18/09/18 18:12	General View	 Load JPG	☒
51	18/09/18 18:12	General View	 Load JPG	☒
52	18/09/18 18:12	General View	 Load JPG	☒
53	18/09/18 18:12	General View	 Load JPG	☒
54	18/09/18 18:12	General View	 Load JPG	☒
55	18/09/18 18:12	General View	 Load JPG	☒
56	18/09/18 18:12	General View	 Load JPG	☒
57	18/09/18 18:12	General View	 Load JPG	☒
58	18/09/18 18:12	General View	 Load JPG	☒
59	18/09/18 18:12	General View	 Load JPG	☒
60	18/09/18 18:12	General View	 Load JPG	☒
61	18/09/18 18:12	General View	 Load JPG	☒
62	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
63	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
64	18/09/18 18:14	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
65	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
66	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
67	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
68	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
69	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
70	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
71	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
72	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
73	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
74	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
75	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
76	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
77	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
78	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
79	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
80	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
81	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
82	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
83	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
84	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
85	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
86	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
87	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
88	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
89	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
90	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
91	18/09/18 18:14	Reinspection Photo	 Load JPG	☒
92	18/09/18 18:14	Replacement Part Photo	 Load JPG	☒
93	18/09/18 18:14	Replacement Part Photo	 Load JPG	☒
94	18/09/18 18:14	Replacement Part Photo	 Load JPG	☒
95	18/09/18 18:14	Replacement Part Photo	 Load JPG	☒
96	18/09/18 18:15	Photo After Spray	 Load JPG	☒
97	18/09/18 18:15	Photo After Spray	 Load JPG	☒
98	18/09/18 18:15	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/10/17 14:16	Police Report of O1 From: TP - Reg. No: SKB3628D, Claimant: ANG WEISI DIXSON	 Load PDF	
2	24/10/17 14:17	Police Report of O1 From: TP - Reg. No: SKB3628D, Claimant: ANG WEISI DIXSON	 Load PDF	
3	24/10/17 14:18	Police Report of O1 From: TP - Reg. No: SKB3628D, Claimant: ANG WEISI DIXSON	 Load PDF	
4	05/10/17 13:50	Enquire transfer fee details	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/10/17 12:15	WORKSHOP ESTIMATE	 Load PDF	
2	19/09/18 17:37	REVISED ESTIMATE	 Load PDF	
3	19/09/18 17:37	SUPPLEMENTARY LIST	 Load PDF	
4	24/09/18 17:24	Parts Invoice	 Load PDF	

Linked Accident Report Documents

View

Assessment Reports			1 per page	☒
No.	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	04/10/17 17:52	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No.	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	04/10/17 17:17	Accident Photo	 Load JPG	☒
2	04/10/17 17:17	Accident Photo	 Load JPG	☒
3	04/10/17 17:17	Accident Photo	 Load JPG	☒
4	04/10/17 17:17	Accident Photo	 Load JPG	☒
5	04/10/17 17:17	Accident Photo	 Load JPG	☒
6	04/10/17 17:17	Accident Photo	 Load JPG	☒
7	04/10/17 17:17	Accident Photo	 Load JPG	☒
8	04/10/17 17:17	Accident Photo	 Load JPG	☒
9	04/10/17 17:17	Accident Photo	 Load JPG	☒
10	04/10/17 17:17	Accident Photo	 Load JPG	☒
11	04/10/17 17:17	Accident Photo	 Load JPG	☒
12	04/10/17 17:17	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No.	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	04/10/17 17:52	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17019144/T1QBE2

Date: 25/09/2018

REFERENCE

Insured/Claimant: CNC GENERAL CONTRACTORS PTE LTD Policy No: A28854994MKC
Date of Loss: 03/10/2017 Nature of Claim: OD Claim No: 531924

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB7266U	Engine No:	4M42A74832
Make & Model:	MITSUBISHI FB70BB1SRDEA, 3.0 D (M)	Chassis No:	FB70BBA20134
Reg. Date:	21/12/2009 (Man. Year: 2009)	Odometer:	226232 km
Colour:	White		
Engine Capacity:	2977 cc		
Market Value/New Car Price:	S\$23,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,876.00	3,931.60	1,944.40	33.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,820.00	2,040.00	1,780.00	46.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,696.00	5,971.60	3,724.40	38.41
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	9,096.00	5,371.60	3,724.40	40.95
+ GST 7.00/7.00% (S\$)	636.72	376.01	260.71	40.95
Nett Amount (S\$)	9,732.72	5,747.61	3,985.11	40.95

INSPECTION

Date of Assignment:	05/10/2017 Present Location:	Hitachi Capital Asia Pacific Pte. Ltd (HQ)
Date Inspected:	06/10/2017 Inspected At:	Hitachi Capital Asia Pacific Pte. Ltd (HQ)
		No 8 Fourth Lok Yang Road
		Singapore 629705
Estimated Period of Repair:	8.0 days:	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 24 Sep 2018)	
Parts:	N/A	mitsubishi FB70BB1SRDEA 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB7266U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Wiper base garnish set (WCP)	Cut	380.00 F	*380.00 F
2	1		*Front top panel assembly (WCP)	Bent	480.00 F	*480.00 F
3	2		*Front corner panel LH/RH (WCP)	Repair	490.00 F	*- F
4	1		*Front grille (WCP)	Cracked	360.00 F	*360.00 F
5	1		*Front grille logo (WCP)	Not Necessary	55.00 F	*- F
6	1		*Front emblem Fuso (grille) (WCP)	Not Necessary	85.00 F	*- F
7	1		*Front grille clip (8PCS) (WCP)	Necessary-ONLY 4PCS	48.00 F	*24.00 F
8	2		*Signal lamp top LH/RH (WCP)	Cracked	320.00 F	*320.00 F
9	1		*Side lamp LH/RH (WCP)	N/S Cracked / O/S NotNecessary	220.00 F	*110.00 F
10	2		*Headlamp LH/RH (WCP)	Cracked	700.00 F	*700.00 F
11	2		*Headlamp lower garnish LH/RH (WCP)	Deformed	52.00 F	*52.00 F
12	1		*Front bumper (WCP)	Bent	480.00 F	*480.00 F
13	2		*Front bumper bracket LH/RH (WCP)	Bent	220.00 F	*220.00 F
14	1		*Aircon blower motor (NPA) (WCP)	Not Necessary	-	*- F
15	1		*Aircon blower motor casing set (NPA) (WCP)	Not Necessary	-	*- F
16	1		*Aircon suction pipe (NPA) (WCP)	Not Necessary	-	*- F
17	1		*Aircon discharge pipe (NPA) (WCP)	Not Necessary	-	*- F
18	1		*Front lower cooling fan (NPA) (WCP)	Not Necessary	-	*- F
19	1		*Front lower cooling fan blade (NPA) (WCP)	Not Necessary	-	*- F
20	1		*Front lower cooling fan motor (NPA) (WCP)	Not Necessary	-	*- F
21	1		*Dashboard assembly (WCP)	Not Necessary	750.00 F	*- F
22	1		*Front windscreen moulding (WCP)	Not Necessary	240.00 F	*- F
23	1		*Sealant	Necessary	45.00 FS	*45.00 FS
24	2		*Front door LH/RH (NPA) (WCP)	Repair	-	-

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
25	1		*Front number plate	Bent	45.00 FS	*30.00 FS
Supplementary #1						
26	1		*Aircon condensor (WCP)	Bent	200.00 F	*200.00 F
27	1		*Aircon fan assembly (WCP)	Cracked	180.00 F	*180.00 F
					Sub Total (S\$)	5,350.00 3,581.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	526.00 350.60
					Total Parts (S\$)	5,876.00 3,931.60

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New	1,600.00	900.00
2	Putty, blend and paint affected area	New	1,400.00	800.00
3	Check Wiring, re-align headlamps and ensure proper function	New	80.00	40.00
4	Refill compressor oil, vacuum and refill aircond gas	New	180.00	100.00
5	Remove & re-install Front Windscreen	New	180.00	0.00
6	Remove & re-install front trim compartment and dashboard assembly to facilitate cutting and repairing work	New	380.00	200.00
Gross Labour Cost (\$\$)			3,820.00	2,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >