

(SUPPLEMENTARY)

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	A28854994MKC	Date of Loss:	03/10/2017
Vehicle Reg. No.:	GBB7266U	Driveable?	
Driver Age/Info:	56 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CNC GENERAL CONTRACTORS PTE LTD		
Driver:	TEO THIAM HUAT		

Make/Model:	mitsubishi FB70BB1SRDEA, 3.0 D (M)	Vehicle Reg. Date:	21/12/2009
Vehicle Colour:	WHITE		
Engine No:	4M42A74832	Chassis No:	FB70BBA20134
Odometer:	100000 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10

Description of Accident/Loss	REFER TO ATTACHMENT
Present Location:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)

COST OF CLAIMS**Amount**

Parts	418.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (\$)	418.00
-------------------------	---------------

+ GST 7.00% (\$)	29.26
-------------------------	--------------

Nett Amount (\$)	447.26
-------------------------	---------------

+ Previous Estimates (\$)	9,285.46
----------------------------------	-----------------

Claim Total (\$)	9,732.72
-------------------------	-----------------

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 17 Jan 2018)**Parts:** N/A MITSUBISHI FB70BB1SRDEA 3.0 D (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Hitachi Capital Asia Pacific Pte. Ltd/GBB7266U/17/01/2018 16:53**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Aircon condensor	0.00	0.00	*200.00 F <i>bt</i>
2	1		*Aircon fan assembly	0.00	0.00	*180.00 F <i>wa</i>
Sub Total (S\$)						380.00
+ Margin on L,N Items 10.00% (S\$)						38.00
Total Parts (S\$)						418.00

F=Franchise part.

Hitachi Capital Asia Pacific Pte. Ltd/GBB7266U/17/01/2018 16:53. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Hitachi Capital Asia Pacific Pte. Ltd/GBB7266U/17/01/2018 16:53. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835

www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591