

ASS. REC. BY:

REF:

CS/SMO17019149/Gabnz

Special Instruction:

Supervisor:

GAB

ASSIGNMENT (Office)

From (Person):

Shany Wong

of

SMO

Date/Time:

05/02/07 5:02pm

Estimated Cost:

Bill to:

OD TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SKZ 5053Y

Insured:

GY 84163

at Workshop m/s

Vision Autowork

Tel:

6341 6789

of

8 Kaki Bukit Ave 4 #08-09

Policy No:

Claim No:

CMD1703474/THF

Sum Insured:

Excess:

Make of Veh:

D.O.A

30/09/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS '0p1

06/02/07

H.O.D. Endorsement:

Date/Time:

05/02/07 5:23pm

Person Contacted:

Michelle

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKZ 5053Y. x

GY 84163 - CS/TCI15004431 / Rgbd1

DCA: 11/03/15

Surrey

XMR

ASSIGNMENT

26 Jan 2016

From: Date: 06102017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKZ 5053Y

at Workshop m/s: Vision Autowork

of 8 Kaki Bukit Ave 4 #08-09

Insured: 98564815 - Michelle

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKZ5053Y Yr Regn: 17 Aug 2016

Type: M.Cas / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wellfire o.c. 2494

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 118308 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTN6F3DH508003715

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/50R18

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or MAXXIS

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 06-10-17

Survey held at WLS 11AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/10/17 email preli to shery.

18/12 Finalized \$5000 with michelle.

Cred. 13131.83, 12%.

RECEIVED 10 DEC 2017

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

) S + RS \$

) Photos

) Others

Report Format: TP

Lump Sum / I.B.I. (\$) 5000

TOTAL

450



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO17019149/Ggb		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 06-10-2017		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GY 8416S	Veh. Inspected	SKZ 5053Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1703474/THE	Excess (\$)	0.00	
Assign From	SHERY WONG	Assign Date	05/10/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	30/09/2017	Inspection Date	06/10/2017	
Survey held at	VISION AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Ai Phing (LKKAuto)

From: Ai Phing (LKKAuto)
Sent: Thursday, 12 October, 2017 8:16 PM
To: 'Wong, Shi Yi Shery'
Cc: 'Henry, Irene James'; 'Choo, Thelma'; SUR
Subject: RE: SKZ5053Y (Pre-Inspection)
Attachments: SKZ 5053Y.pdf

Dear Shery,

Enclosed herewith preliminary advise of vehicle SKZ 5053Y.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 5 October, 2017 5:25 PM
To: 'Wong, Shi Yi Shery' <Shery.Wong@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry, Irene James' <irene.henry@sompo.com.sg>; 'Choo, Thelma' <thelma.choo@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SKZ5053Y (Pre-Inspection)

Dear Shery,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wong, Shi Yi Shery [<mailto:Shery.Wong@sompo.com.sg>]
Sent: Thursday, 5 October, 2017 5:02 PM
To: visionautowork@gmail.com; assignments@lkkauto.com
Cc: Henry, Irene James <irene.henry@sompo.com.sg>; Choo, Thelma <thelma.choo@sompo.com.sg>; Catherine Chong (LKK Auto) <admin-d@lkkauto.com>
Subject: FW: SKZ5053Y (Pre-Inspection)

Our Claim Reference : CMTD1703474/THE

Hi ,

We acknowledged receipt of your claim documents.

Catherine Chong (LKK Auto)

From: Wong, Shi Yi Shery <Shery.Wong@sompo.com.sg>
Sent: Thursday, 5 October, 2017 5:02 PM
To: visionautowork@gmail.com; assignments@lkkauto.com
Cc: Henry, Irene James; Choo, Thelma; Catherine Chong (LKK Auto)
Subject: FW: SKZ5053Y (Pre-Inspection)
Attachments: 05102017162820.pdf

Our Claim Reference : CMTD1703474/THE

Hi ,

We acknowledged receipt of your claim documents.

Aside to LKK AUTO,

Kindly assign your motor surveyor to conduct motor survey of the mentioned (SKZ5053Y).

Thank you.

Best Regards

Shery Wong

Claims Division

D: 6329 5339 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Henry, Irene James
Sent: Thursday, October 05, 2017 4:37 PM
To: Wong, Shi Yi Shery
Subject: FW: SKZ5053Y (Pre-Inspection)

Dear Shery,

Kindly attend to the PRI

Thanks!

From: Vision Autowork [<mailto:visionautowork@gmail.com>]
Sent: Thursday, 5 October, 2017 4:35 PM

To: Henry, Irene James <irene.henry@sompo.com.sg>
Subject: SKZ5053Y (Pre-Inspection)

Dear Irene,

Please arrange **LKK Auto Consultants Pte Ltd** pre-inspection for the above vehicle.

Thank You

Yours faithfully,

Michelle
Hp: 9856 4815

8 Kaki Bukit Avenue 4,
#08-09, Premier @ Kaki Bukit,
Singapore 41875
Tel: 6341 6789
Fax: 6341 6778



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1703474/THE

Date: 12-10-2017

Our Ref: CS/SMO17019149/Ggb

The Motor Claims Department
Sompō Insurance Pte Ltd

Without Prejudice

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SKZ 5053Y.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 06-10-2017 at the premises of M/s VISION AUTOWORK and have the following to report:-

Workshop Estimate Amount	: S\$ 18,131.83
Revised Estimate Amount	: S\$ 4,403.08
"Check" Items Amount	: S\$ 4,094.25
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Xing Guo Qiang
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	7397C

Vehicle Details

Vehicle No.	SKZ5053Y
Vehicle to be Exported	No
Intended De-registration Date	11 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	VELLFIRE 2.5 CVT S/R
Primary Colour	Black
Manufacturing Year	2015
Engine No.	2ARH671438
Chassis No.	JTNGF3DH508003715
Maximum Power Output	134.0 kW (179 bhp)
Open Market Value	\$45,427.00
Original Registration Date	26 Jan 2016
First Registration Date	26 Jan 2016
Transfer Count	0
Actual ARF Paid	\$55,598.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	25 Jan 2026
PARF Rebate Amount	\$41,698.00

Intended COE Rebate Details

COE Expiry Date	25 Jan 2026
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$55,001.00
COE Rebate Amount	\$44,666.00
Total Rebate Amount	\$86,364.00

The information contained herein is correct as at 11 Dec 2017

OK

► Toyota Vellfire Used Vehicle List (4 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Toyota Vellfire 2.4A X Hybrid (Petrol-Electric)	\$146,800	\$15,320 /yr	01-Feb-2016	2,362 cc	-	Prime Motor & Leasing	Available
Elegant White Toyota Vellfire Hybrid, Low Fuel Consumption With Hybrid, Powerful Drive With 187 Bhp, One Owner Only, 7 Seater Unit, Very Well Maintained, Flexible In-House Loan Packages Available. Office No. - 68723113 Jack - 91096509 Larry - 96861029 Eliz - 88680011							
Toyota Vellfire 2.5A Z	\$175,899	\$17,330 /yr	27-Jun-2016	2,494 cc	50,000 km	Ken Garage Pte Ltd	Available
Agent Maintained. Still Under Warranty. Providing You With Spacious And Comfortable Interior. Fuel Efficiency Has Always Been The Priority Of Toyota. Captain Seat, Full Leather. Consignment Unit. Office No. - 64637008 Ken - 85699983 Dennis - 92722615 Koh - 81181378 Ben - 84888677							
Toyota Vellfire 2.5A Z G-Edition	\$197,988	\$20,520 /yr	30-Jun-2016	2,493 cc	10,000 km	Carz World Pte Ltd	Available
Down Payment From 10%, The Most Popular And Elegant People Carrier Available In The Market. Free 2 Servicing Provided. Alpine Player With Garmin GPS Included. Low Mileage Less Than 10k Km A Year! Do N... Office No. - 65709482 Ben - 87428218 Gary - 90928643 Terry - 98371577 Zach - 82611888							
Toyota Vellfire 2.5A Z A-Edition	\$168,888	\$16,490 /yr	30-Aug-2016	2,493 cc	44,500 km	TTS Eurocars	Available
Immaculate White Exterior Paired With Black Interior. The Most Popular And Elegant First Class MPV That Offers Tons Of Comfort, Spacious And Exterior Design That Makes Every Journey Enjoyable. Well Ta... Office No. - 68422222 Noel - 91011079 Rachel - 94898861 Mr Chan - 92958333 Ivan Ong - 96359315							

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, massage services, real estate properties for sale, beauty and wellness, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2017 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/10/2017 10:32
Date Of Accident	30/09/2017 04:10
Exact Location Of Accident	BUANG KOK DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ5053Y
Insured/Policyholder	
Name Of Registered Owner	ASIA CAR LEASING PTE LTD
Co Reg No	201437397C
Email Address	KRISTINE@ASIACARRENTAL.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62828585

Vehicle Particulars

Manufacturer	TOYOTA
Model	VELLFIRE 2.5 CVT S/R
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995241/100781383-00000
Cover Note Number	

Driver

Name of Driver	KOH LIAN SING
NRIC No	S6808541A
Date Of Birth	02/03/1968
Occupation	INDOOR
Date Of Driving Pass	29/05/1989
Driving Experience	28 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92402808
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 3 BEDOK SOUTH AVENUE 1 #14-839
Postcode	460003
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GY8416S
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJH3814M
Vehicle Make/Model/Colour	

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



Sketch Plan Pg. 2

Describe Circumstances of the Accident	LICENSE PLATE NUMBER:
ACCIDENT DATE:	CONTACT NUMBER:
ACCIDENT TIME:	EMAIL:
LOCATION:	
<p>As I was driving along Buangkok Dr, stop at the traffic junction between Upper Serangoon Rd. As the light turn green I move forward. Suddenly I felt a jerk I stop the car, and found that a Van had hit the back of my car.</p>	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION.	
Please state: <input type="checkbox"/> Claim Own Policy <input type="checkbox"/> Claim Third Party <input type="checkbox"/> Claim OD/TP at other workshop <input type="checkbox"/> Reporting Only	

Declaration

We declare the foregoing particulars are true in every respect.



Policy holder  Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:visionautowork@gmail.com

DATE : 05.10.17

TO : **SOMPO** MOTOR CLAIMS DEPTS
VEHICLE NO : **SKZ5053Y**
MODEL : **TOYOTA VELLFIRE**
DATE OF ACCIDENT : 30.09.17
TIME OF ACCIDENT : 04:10HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER / Re	1	\$ 1,609.00	\$ 1,609.00
2	REAR BUMPER REFLECTOR LH / BR	1	\$ 98.00	\$ 98.00
3	REAR BUMPER SIDE UPPER GARNISH LH / CAA	1	\$ 248.00	\$ 248.00
4	REAR BUMPER TOW HOOK COVER LH X / CAA	1	\$ 45.00	\$ 45.00
5	REAR BUMPER SIDE RETAINER (FRONT) X	2	\$ 95.00	\$ 190.00
6	REAR BUMPER SIDE RETAINER (REAR) LH / CAA	2	\$ 95.00	\$ 190.00
7	REAR BUMPER SIDE INNER GARNISH LH / CAA	1	\$ 158.00	\$ 158.00
8	REAR BUMPER SENSOR / DM	2	\$ 397.00	\$ 1,588.00
9	REAR BUMPER SENSOR HOLDER X / CAA	1	\$ 45.00	\$ 180.00
10	REAR BUMPER SENSOR WIRE HARNESS X	1	\$ 524.00	\$ 524.00
11	TAILGATE X repair	1	\$ 1,850.00	\$ 1,850.00
12	TAIL GATE EMBLEM 'VELLFIRE' / CAA	1	\$ 115.00	\$ 115.00
13	TAIL GATE LOGO / CAA	1	\$ 75.00	\$ 75.00
14	TAILGATE BUZZER / DM	1	\$ 145.00	\$ 145.00
15	TAILGATE SWITCH CONNECTOR / DM	1	\$ 655.00	\$ 655.00
16	TAILGATE TOP LOCK X / CAA	1	\$ 768.00	\$ 768.00
17	TAILGATE LOWER LOCK X / CAA	1	\$ 35.00	\$ 35.00
18	TAILGATE WEATHER STRIP / TAN	1	\$ 392.00	\$ 392.00
19	TAILGATE WINDSCREEN C/W MOULDING X / CAA	1	\$ 1,400.00	\$ 1,400.00
20	REAR FENDER INNER TRIM LH / CAA	2	\$ 1,370.00	\$ 2,740.00
21	REAR FENDER COWLING X / CAA	2	\$ 165.00	\$ 330.00
22	REAR END PANEL TOP GARNISH / Re	1	\$ 299.10	\$ 299.10
23	REAR END PANEL (OUTER) / Bnc.	1	\$ 920.00	\$ 920.00
24	REAR STORAGE COVER BOARD / CAA	1	\$ 860.00	\$ 1,720.00
25	REAR SEAT ROLLER COVER BOARD / Re	1	\$ 395.00	\$ 395.00

TOTAL PRICE \$ 16,669.10
LESS 25% \$ 4,167.28
SUB TOTAL PRICE \$ 12,501.83

65
65
95
730
65
70
60
145
357
1044.6
167
686
475
220
6194.6
259.4645.95

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE X NN	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIPS (SET) / NBL	1	\$ 50.00	\$ 50.00
3	REAR BUMPER SIDE UPPER GARNISH CLIP LH (SET) / NBL	1	\$ 30.00	\$ 30.00
4	TAIL LAMP CLIP (SET) X NN	1	\$ 30.00	\$ 30.00
5	TAILGATE INNER TRIM CLIP (SET) X NN	1	\$ 50.00	\$ 50.00
6	TAILGATE UPPER INNER TRIM CLIP (SET) X NN	1	\$ 50.00	\$ 50.00
7	TAILGATE WINDSCREEN SEALANT X NN	1	\$ 80.00	\$ 80.00
8	TAILGATE WINDSCREEN INNER SEAL X NN	1	\$ 60.00	\$ 60.00
9	REAR FENDER INNER TRIM CLIP (SET) / NBL	1	\$ 50.00	\$ 50.00
10	REAR FENDER INNER COWLING CLIP (SET) X NN	1	\$ 50.00	\$ 50.00
11	REAR END PANEL TOP GARNISH CLIPS (SET) X NN	1	\$ 30.00	\$ 30.00
12	REAR END PANEL INSULATION SEAL X NN	1	\$ 150.00	\$ 150.00
13	REVERSE CAMERA X NN	1	\$ 450.00	\$ 450.00

TOTAL \$ 1,130.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	700
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	600
3	TUFF COAT	\$ 250.00	60
4	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	60
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	40
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	40
7	REAR CHASSIS ALIGNMENT	\$ 250.00	X / NN
8	REMOVE AND REFIX TAILGATE GLASS	\$ 80.00	X / NN
9	TRANSFER TAILGATE MECHANISM	\$ 80.00	40
10	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X / NN
11	REMOVE, REFIX AND RESET REAR VIDEO RECORDER	\$ 250.00	X / NN

1540

12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X NN
----	---	-----------	------

TOTAL \$4,500.00

TOTAL PARTS COST : \$ 13,631.83
TOTAL LABOUR COST : \$ 4,500.00
TOTAL REPAIR COST : \$ 18,131.83

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR

ABBY

HP : 9856 4815

Guo Qiang - 8288 0282

lump sum repair

After repair photos.

06/10/17

5 Days.

6255.95

40%: 5000

[Signature]
13/10/17

<p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>
--



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17019149/Ggbn2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 27-12-2017



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GY 8416S	Veh. Inspected	SKZ 5053Y
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1703474/THE	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	05/10/2017

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VELLFIRE	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTNGF3DH508003715	Colour	BLACK
Odometer	118308	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/50 R18	MAXXIS	6 mm
L/H Front Tyre	235/50 R18	MAXXIS	6 mm
R/H Rear Tyre	235/50 R18	MAXXIS	6 mm
L/H Rear Tyre	235/50 R18	MAXXIS	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	30/09/2017	Inspection Date	06/10/2017
Survey held at	VISION AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 5053Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	1,609.00	1,609.00
1	REAR BUMPER REFLECTOR LH	BROKEN	98.00	65.00
1	REAR BUMPER SIDE UPPER GARNISH LH	CRACKED	248.00	248.00
1	REAR BUMPER TOW HOOK COVER LH	NOT NECESSARY	45.00	-
2	REAR BUMPER SIDE RETAINER (FRONT) @\$95.00	NOT NECESSARY	190.00	-
2	REAR BUMPER SIDE RETAINER (REAR) @\$95.00	N/S CRACKED / O/S NOT NECESSARY	190.00	95.00
1	REAR BUMPER SIDE INNER GARNISH LH	CRACKED	158.00	158.00
4	REAR BUMPER SENSOR @\$397.00	DAMAGED	1,588.00	730.00
4	REAR BUMPER SENSOR HOLDER @\$45.00	NOT NECESSARY	180.00	-
1	REAR BUMPER SENSOR WIREHARNES	NOT NECESSARY	524.00	-
1	TAILGATE	TO REPAIR SEE LABOUR	1,850.00	-
1	TAIL GATE EMBLEM "VELLFIRE"	NECESSARY	115.00	65.00
1	TAIL GATE LOGO	NECESSARY	75.00	70.00
1	TAILGATE BUZZER	DAMAGED	145.00	60.00
1	TAILGATE SWITCH CONNECTOR	DAMAGED	655.00	145.00
1	TAILGATE TOP LOCK	NOT NECESSARY	768.00	-
1	TAILGATE LOWER LOCK	NOT NECESSARY	35.00	-
1	TAILGATE WEATHER STRIP	TORN	392.00	357.00
1	TAILGATE WINDSCREEN C/W MOULDING	NOT NECESSARY	1,400.00	-
2	REAR FENDER INNER TRIM @\$1370.00	N/S CRACKED / O/S NOT NECESSARY	2,740.00	1,044.60
2	REAR FENDER COWLING @\$165.00	NOT NECESSARY	330.00	-
1	REAR END PANEL TOP GARNISH	DEFORMED	299.10	167.00
1	REAR END PANEL (OUTER)	BUCKLED	920.00	686.00
2	REAR STORAGE COVER BOARD @\$860.00	N/S DEFORMED / O/S NOT NECESSARY	1,720.00	475.00
1	REAR SEAT ROLLER COVER BOARD	DEFORMED	395.00	220.00
	LESS 25% DISCOUNT		-4,167.27	-1,548.65
			12,501.83	4,645.95
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00

Report Ref No. CS/SMO17019149/Ggbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR BUMPER SIDE UPPER GARNISH CLIP LH (SN)	NECESSARY	30.00	10.00
1	SET TAIL LAMP CLIP (SN)	NOT NECESSARY	30.00	-
1	SET TAIL GATE INNER TRIM CLIP (SN)	NOT NECESSARY	50.00	-
1	SET TAIL GATE UPPER INNER TRIM CLIP (SN)	NOT NECESSARY	50.00	-
1	TAILGATE WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	TAILGATE WINDSCREEN INNER SEAL (SN)	NOT NECESSARY	60.00	-
1	SET REAR FENDER INNER TRIM CLIP (SN)	NECESSARY	50.00	30.00
1	SET REAR FENDER INNER COWLING CLIP (SN)	NOT NECESSARY	50.00	-
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
1	REAR END PANEL INSULATION SEAL (SN)	NOT NECESSARY	150.00	-
1	REVERSE CAMERA (SN)	NOT NECESSARY	450.00	-
			1,130.00	70.00
	LABOUR			
	PANEL BEATING,REMOVAL AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF TAILGATE.		1,400.00	700.00
	TO SPRAY PAINT AFFECTED AREA.		1,400.00	600.00
	TUFF COAT.		250.00	60.00
	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR.		350.00	60.00
	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING.		80.00	40.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	40.00
	REAR CHASSIS ALIGNMENT.	NOT NECESSARY	250.00	-
	REMOVE AND REFIX TAILGATE GLASS.	NOT NECESSARY	80.00	-
	TRANSFER TAILGATE MECHANISM.		80.00	40.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	100.00	-
	REMOVE,REFIX AND RESET REAR VIDEO RECORDER.	NOT NECESSARY	250.00	-
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
	-		-	-
	-		-	-
	-		-	-
			4,500.00	1,540.00
	GRAND TOTAL		18,131.83	6,255.95

Report Ref No. CS/SMO17019149/Ggbn2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,000.00
---	--	--	----------

Report Ref No. CS/SMO17019149/Ggbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.