MWM6) From (Person):	Joslin Lim	AS of	SIGNMENT M	(Office)	Dat	e/Time:	05102017	449p
Estimated Cost:	00-11-1		Bi	ll to:				
To Inspect Vehi	REGISTER STATE	SLT	89854		_ Insured: Tel:	. 63	05 7216	
	S		Howagen are	Danil	_ 101			
of Policy No:	5050 5727		Alexandia	Claim No: _		984		
Sum Insured:				Excess: _	₩ 50	0.00		
	rep. / rev 24 Hrs 05 102017 157 pm		06-1020	ately const			Idotzement	
Date/I me;		V)	Estimate.					
Date/Time: Date/Time	Action/Instruction (10			

ite/Time, File Pass to?	: Preli. Report		ays Of Repair: 4		
ate/Time, File Return to?	: Final Report	F	Resurvey No. of Trip:	Survey Fee: Transportation:	300
=15		Add Fee:)S+RS,SI	
10	War and		: Interview .(\$) Photos	
	00		: Tech. Invs (\$) Others	
ump Sum / IBA:	\$ 3507.99)	: Weekend (\$)	10
				TOTAL	310



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

М	SIG INSURANCE	Affiliated to Federation Interna (SINGAPORE) PTE LTD	Ref : CS/MSG1701			
16 #2	RAFFLES QUAY 4-01 HONG LEON			9150/Ggb		
1.		Policy Particu	lars :- OWN DAMAGE	Technology of the Park		
	Insured Veh.		Veh. Inspected	Substituting of the second		
	Policy No.	50505727	Coverage (\$)	SLT 8985H		
	Claim No.	531984	Excess (\$)	0.00		
	Assign From	MERIMEN (JOSLIN LIM)	Assign Date	500.00 05/10/2017		
2.	e moin personal	Vehicle Part	iculars & Condition	05/10/2017		
	Make & Model	vernote Part				
	Engine No.	HIDDEN	C.C	0		
	Chassis No. Odometer - Brakes		Year of Reg.			
			Colour			
			Steering			
	General		Modification			
		Condition	The second second			
		Size	ons of Tyres			
	R/H Front Tyre	- Oile	Make	Balance		
	L/H Front Tyre			mm		
	R/H Rear Tyre			mm		
	L/H Rear Tyre		C HILL CONTROL OF THE	mm		
45		Table to the second court and the second		mm		
	T	Description	on of Damages			
	ENGLISHA	Committee	In F. Co.			
	Accident Date	04/40/004=	Information	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
	Survey held at		Inspection Date	06/10/2017		
		247 ALEXANDRA ROAD SINGAPORE 159934	OKE PTE LTD			
		MAD IN TRAILS AND A STATE OF THE PARTY.	marks			
	A)THE MARKET V	ALUE IS S\$(EST. AVERA EE TO YOUR INSTRUCTIONS, WE				

...CLAIM SUBFOLDER...(New Assignment)



Ai Phing (LKKAuto)

From:

Ai Phing (LKKAuto)

Sent:

Monday, 11 December, 2017 12:16 PM

To:

Cheong, Pearlyn (VWG Singapore)

Cc:

'Kong, Charmaine (VWG Singapore)'; 'Wong, Meiy (VWG Singapore)'

Subject:

RE: SLT8985H - FINALISE

Dear Pearlyn,

Confirmed final fig \$3,507.99 before Excess \$500 and GST.

04 Days of repair.

Please send invoice direct to MSIG.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Guo Qiang (LKKAuto)

Sent: Monday, 11 December, 2017 11:51 AM To: Ai Phing (LKKAuto) <aiphing@lkkauto.com>

Subject: FW: SLT8985H - FINALISE

From: Cheong, Pearlyn (VWG Singapore) [mailto:Pearlyn.cheong@vw.com.sg]

Sent: Thursday, 19 October, 2017 6:50 PM

To: Guo Qiang (LKKAuto)

Cc: Kong, Charmaine (VWG Singapore); Wong, Meiy (VWG Singapore); Foo, John (VWG Singapore)

Subject: SLT8985H - FINALISE

Dear Guo Xiang,

Please confirmed

COR \$ 3007.99 after less excess before GST.

Best regards,

Pearlyn Cheong Service Advisor Aftersales Body & Paint Department

Volkswagen Group Singapore (Alexandra)

Ai Phing (LKKAuto)

From:

Ai Phing (LKKAuto)

Sent:

Monday, 9 October, 2017 5:40 PM

To:

Wong, Meiy (VWG Singapore); Tang, Shu Shi (VWG Singapore); Ong, Germaine (VWG

Singapore); Tan, William (VWG Singapore); Cheong, Pearlyn (VWG Singapore); Kong,

Charmaine (VWG Singapore)

Cc:

SUR

Subject:

SLT 8985H MSIG-OD (DOA 04-10-2017)

Dear Meiy,

As instructed by our client, please proceed to repair the insured vehicle SLT 8985H (Excess \$500).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

Claim Audit

No.	On		Remarks	Ву
NO.	05 Oct 2017		Remarks	[I] Joslin
1	15:34	Changed	(202731) VOLKSWAGEN GOLF 1.4 TSI (A).	Lim
2	05 Oct 2017 15:34	Clm Created	Reg No: SLT8985H. Policy No: 50505727. Acct Date: 2017/10/04. Claim Type: OD. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Ins.Status => Incoming Claim. Created from SAS:MVGS17131695	[I] Joslin Lim
3	05 Oct 2017 15:43	Clm Registration Modified	IsCoverNote:Yes->No.	[I] Joslin Lim
4	05 Oct 2017 16:05	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):a if c	[I] Lui Siev Wei
5	05 Oct 2017 16:05	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/10/06	[I] Lui Siev Wei
6	05 Oct 2017 16:05	Adj Mandate Set	Approved: 25000.00.Reinsp: Adj decides.	[I] Lui Siev Wei
7	05 Oct 2017 16:24	Assignment 1st Accessed		[A] Pauline Soh Li Ping
8	05 Oct 2017 16:46	Adj Assignment Cancelled	1.H.S appointment full. Survey appointment is 10,30 am on 6/10/17.	[1] Joslin Lim
9	05 Oct 2017 16:46	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Joslin Lim
10	05 Oct 2017 16:49	Clm Registration Modified	Rep:1137->200076.	[I] Joslin Lim
11	05 Oct 2017 16:49	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ): "Volkswagen scheme" To survey at 10.30 am on 06/10/17 Please contact Meiy.	[I] Joslin Lim
12	05 Oct 2017 16:49	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/10/06	[I] Joslin Lim
	05 Oct 2017 16:49	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Joslin Lim
	05 Oct 2017 17:19	Assignment 1st Accessed		[A] CATHERIN CHONG KAI LING
15	06 Oct 2017 11:46	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH	[A] CATHERIN CHONG KAI LING [A]
16	09 Oct 2017 11:41	Adj Adjuster Assigned	MOHD TAUFIKH -> XING GUO QIANG	CATHERIN CHONG KAI LING
17	09 Oct 2017 12:56	Adj Rpt Initiated		[A] LOW A PHING
18	13:55	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/11/04	[A] LOW A PHING
19	09 Oct 2017 13:55	Adj Next Rpt Changed	Next Rpt:Final Rpt,Due Date:2017/11/04	[A] LOW A PHING
20	09 Oct 2017 13:56	Adj Mandate Request	Cur.Req:7900.43:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL.	[A] LOW A PHING
21	09 Oct 2017 17:31	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date: 2017/11/04	[I] Eng Huey Ni
22	09 Oct 2017 17:31	Adj Mandate Set	Approved:7900.43:	[I] Eng Huey Ni

ACTIVITY

[05/10/2017 16:24] Pauline Soh Li Ping: Pending for workshop to arrange and revert with survey appt.

derimen Billin	g for this case -	Transaction	History				
Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1604808	09/10/2017 12:56	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLT8985H		10.70

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Joslin Lim

Date: 09 Oct 2017

Preliminary Advice

Vehicle No

: SLT8985H

Accident Date

: 04/10/2017

Make

: VOLKSWAGEN GOLF

Policy No.

: 50505727

Assignment Date : 05/10/2017

Excess

: S\$500.00

Date of Inspection: 06/10/2017

Inspection At

Est. Duration of Repair : 3.00

: VOLKSWAGEN CENTRE SINGAPORE (ALEXANDRA)

247 ALEXANDRA ROAD SINGAPORE 159934

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,556.46
Revised Amount	:S\$	3,012.35
Check Items (Estimated)	:S\$	4,888.08
Total	:S\$	7,900.43

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :5\$ 117,000.00 :S\$ COE / PARF Rebate 48,657.00

Salvage Value :S\$

:S\$ 68,343.00 Margin for Repair

Remarks

(X) The vehicle is economical for repair.

We have not authorise repair.

) The above survey was conducted on a 'without prejudice' basis.

A A A

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC	
Owner ID:	4857G	
Vehicle Details		
Vehicle No.:	SLT8985H	
Vehicle to be Exported:	No	
Intended De-registration Date:	09 Oct 2017	
Vehicle Make:	VOLKSWAGEN	
Vehicle Model:	GOLF 1.4 TSI AT 5G13HZ	
Primary Colour:	Red	
Manufacturing Year:	2016	
Engine No.:	CZC146060	
Chassis No.:	WVWZZZAUZHW116097	
Maximum Power Output:	92.0 kW (123 bhp)	
Open Market Value:	\$17,881.00	
Original Registration Date:	27 Sep 2017	
First Registration Date:	27 Sep 2017	≈
	0	

Transfer Count:	
Actual ARF Paid:	\$7,881.00
ntended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Sep 2027
PARF Rebate Amount:	\$5,910.00
ntended COE Rebate Details	
COE No.:	2017100101001818R
COE Expiry Date:	26 Sep 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,902.00
COE Rebate Amount:	\$42,747.00
Total Rebate Amount:	\$48,657.00

The information contained herein is correct as at 09 Oct 2017

OK

Land Transport Authority (https://www.lta.gov.sg)

Please read through the Privacy Statement, Terms of Use, and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright © 2017 LTA | Privacy Statement | Terms of Use | Disclaimer | Rate the Website |

Rate this e-Service (https://www.lta.gov.sg/feedback/PublicSurvy.aspx?SurveyDetlNum=S201400011)

Last updated on 08 Oct 2017 at 01:03 AM

MVGS17131695 / Volkswagen Centre Singapore - HQ ENTRY DATE & TIME: 04/10/2017 16:47

SINGAPORE ACCIDENT STATEMENT

MSIG OD China

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT	P ASSISTANCE AND ASSI
Date Of Report	04/10/2017 16:47	
Date Of Accident	04/10/2017 09:45	
Exact Location Of Accident	ALONG DUNEARN ROAD	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	SET OF THE REPORT OF THE PERSON NAMED IN
MALL BOOK NOW	CLTROREH	·

Vehicle Registration Number	SLT8985H

Insured/Policyholder

SIM KING YAW Name Of Registered Owner

S8334857G NRIC No

KINGYAW@GMAIL.COM Email Address Mobile Phone No (LOCAL) +65-98461560

Alternative Phone No

Vehicle Particulars

VOLKSWAGEN Manufacturer

GOLF A7 1.4 CL 92 (DSG) Model

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE

OFFICE-98461560

Are you claiming under your own insurance policy

for repair to your vehicle?

If No. Please state action to be taken

PRIVATE CAR Vehicle Category

Insurance Company

MSIG INSURANCE (SINGAPORE) PTE. LTD. Name of Insurance Company

COMPREHENSIVE Type Of Coverage

Fleet Policy NO

Policy Number

50505727 Cover Note Number

Driver

TAN HUI LING (CHEN HUILING) Name of Driver

S8526084G NRIC No 09/08/1985 Date Of Birth INDOOR Occupation 30/03/2006 Date Of Driving Pass

11 YEARS AND 6 MONTHS Driving Experience

FEMALE Gender

(LOCAL) +65-96511523 Mobile Number (LOCAL) +65-96511523 Fax Number

Contact Number

TAN.HUILING1@GMAIL.COM EMail Address

Address

927 BUKIT TIMAH ROAD #08-16

Postcode

589641

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

SPOUSE

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Was any body injured in the Accident?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJN5632B

Vehicle Make/Model/Colour

Details Of Properties

LELA

Name of Driver

NRIC/Passport Number Contact Number

90233400

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the 8. Consent under the Personal Data Protection Act (PDPA)

l understand, acknowledge, agree and consent that

- (a) My insurer, my w orkshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my haurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers law yers/law firms, the Monetary Authority of Singapore and any relevant
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to (ii) investigating the accident and/or my claims,
- (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Time Sketch Pla	Signature / Date &	Oriver's Signat & Time	4-10-12 ure (If driver is not the p	oficyholder) / Date	Witnessed by Reporting Centre Personnel
A: SJN5632B	Frank II	1		1 Road v	Vovks
3: SLT8985H			A		
	100			4	
			В		
				1 1	
				1	

	TE MINI , MIDNA	& DUNCARY	Road			
4/10/2017 9		10000001	Parist			
Car A turned into	conter lane of	10 to 100	Lunches on	Det	to all la	1 . 1
CAY IS ANY WAY BY	t can h braked	and the F	at could	Dr.	right	iane.
		1	or course	Tru/	eteb in	the fine.
		-				As process than I the Arms
				OUT THE		
car A - Driver :	CARA Amil 24.2					
	1047 540)				
				hide Park		
					-	
		dissisting.		-		
	5000 Sec 11 mp.					
				4,754		
				- In the second		
		X255	4554-520-0			
		-				
		-				
	A STATE OF THE STA			_		
			C 8-2-1 (C 82 - C)			
				-		
				-		
aration						7
fectare the foregoing particular	rs are true in every respe	ct				
Ti W	ordry respe	W.				6
W.v.						
	o t	50				19 1520
1	1 1 12					my.
	415					76-50 (f)
holder's Signature / Date &	Driver's Signature (if dr	iver is not the o	olicubolida e 4 D			to the second second
	& Time	must trie p	anaymorder) / Da	ie .	Witnessed	by Reporting Centre

S8526084G laste Date 30 Mar 2006

917 8085H

MSIG Consider v

Ch: St 50 572".

HEPU

DENTITY CARD NO \$8526084G





TAN HUI LING (CHEN HUILING) 陳慧珍



CHINESE 09-08-1985 SINGAPORE



96511503

ton-Mulling 1 @ amal-com

: Mdm Goh Swoon Keow 94484220

MASS DATE

Class 3 Motor Carses 3000kg with =<7 passangers, exclusive 30 Mar 2006 of the dram, and office course vehicles as 2500(a).



5575512



6-03-2016

927 BUKIT TIWAH ROAD 108-16 SINGAPORE 58964

Date :
Dear Sir or Madam :
To whom it may concern,
RE: Authorization to act on behalf
Vehicle No.:
would like to authorize, bearing NRIC Number, bearing NRIC
Number, bearing NRIC, to act on my behalf for all documents
and repair for the above said vehicle.
Thank You.
Yours Sincerely,
W.A.
Signature
Signature

MSIG (WINNAS)

PDITUAS. OD emast: Ds/10/17

DV/900000 LKK

Phone No. Fax No. E-Mail

VAT Registration No. M20098505-2 Tax No. 199101494Z

Service Quote

Customer No. Quote No.

CV038860

QuoteDate

SER/QUO/1701689 05/10/17

Salesperson

Shawn Lim

Page

THIS IS NOT AN OFFICIAL TAX INVOICE

1

Make

PDI TUAS

#08-16

Singapore

SIM KING YAW

(SHEN QINGYAO) 927 BUKIT TIMAH ROAD

Singapore, 589641

Volkswagen Passeng

License No.

SLT8985H **Engine Code** Model Description

GOLF A7 1.4 CL 92 (DSG)

MG Cam Q) a 651 15 TV
ROAD
-cont. o 6 / 10 / 12 -

WVWZZZAUZHW116097

Labor Type

GP NEVSONS Som 12 /10/17 -> 18710/17

1T

Mileage

Initial Registration

27/09/17

Engine No. CZC 146060 Service Advisor Cheong Pearlyn

Sales Advisor

Shawn Lim

Model Code 5G13HZ

	No.	Description	Qty.	UoM	Unit Price	Amount
В	B&P ALEX LABOUR	LABOUR	5	UNIT	a	2,375.00
D	B&P ALEX PAINT	SPRAY PAINT	- 3			Cap 1,500.00
D	B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	-	pcs		/80.00
P	B&P AIRCON	VACUUM & REGAS AIRCON-NET NETT PRICE	0.5		/	VN 7× 237.50
Р	B&P AIRCON GAS	B&P AIRCON GAS	48	Time Un		/ ×60.00
50		SUPPLY OF B&P AIRCON GASS				50 60 60 60 Vine 13 Assertance 50
Р	B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		360.00
		COMPULSORY TO DO AFTER AC				# 5000000 LW
P	B&P MECH	ELECT WIRING & MECH COMPO	1	Time Un		200.00
		Nett				
		Sum Labor				4,812.50
		$7_{ imes}$		E ANDRONOUS S		NN DODGE
P	5G0805588AC	LOCK CARRIER	1	Pieces		892.50
		Predecessor 5G0805588Q	con.	EVENOUS		28-95 40.21
P	5G0805705G	FRONT CENTER GUIDE 7/	Jun 1	Pieces		187.63
P	5G0805915 9B9	BUMPER LOWER SPOILER	1	Pieces		1 TO SEC. A CONTROL OF THE PARTY OF THE PART
F	5G0805931	HEADLIGHT BRACE LHS ?	0/4	Pieces		34.83
F	5G0805932	HEADLIGHT BRACE RHS 2	1010	Pieces		34.83
F	5G0807049A	BUMPER BRACKET LHS ?	1	Pieces		19.54
F	5G0807050A	BUMPER BRACKET RHS ?	1	Pieces		19.54
F	5G0807109H	BUMPER REINFORCEMENT Use Predecessor 5G0807109B	BT 1	Pieces		382-9-531.87
-	FOROZOTA ZDNODU	FRONT BUMPER	9	Pieces		830.03 1,152.82/
- 1	5G0807217BNGRU	FROM I BOIMFER	18	. 10000		

Sum carried forward

1 Pieces

7,766.44

40.17×

P 5G0807248F

FOAM INSERT 7X

Use Predecessor 5G0807248D

PDI TUAS

PDI TUAS

SIM KING YAW (SHEN QINGYAO) 927 BUKIT TIMAH ROAD #08-16 Singapore, 589641 Singapore

Gress: \$500 Not Anthorised Guo Giang - 82880282 3Dongs. before paint photos. 06/10/17.

Phone No. Fax No. E-Mail

VAT Registration No. M20098505-2 199101494Z Tax No.

Service Quote

Customer No. Quote No.

CV038860 SER/QUO/1701689

QuoteDate Salesperson

05/10/17

Page

Shawn Lim 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make

Volkswagen Passeng

License No.

SLT8985H **Engine Code** Model Description

GOLF A7 1.4 CL 92 (DSG)

WVWZZZAUZHW116097

Labor Type

1T

Mileage

Initial Registration

27/09/17

Engine No.

CZC 146060

Service Advisor

Cheong Pearlyn

Sales Advisor Shawn Lim

Model Code

5G13HZ

		Continued	7,766.44
P 5G0853651G ZLL	UPPER CENTER GRILLE ?X \ MU	Pieces	509.37×
P 5G0853677 9B9	LOWER CENTER GRILLE 2X 1 1	Pieces	134.01 X
P 5G0919493	SENSOR BRACKET 2 / 1	Pieces	10.58 14.70 ∕
P 5G0919493A		Pieces	71-17-29.40
P 5G0919494		Pieces	10.5814.70
P 5G2941005E		Pieces	1,073.04 ×
P 5G2941006E	Use Predessessor 5G2941005	Pieces	1,073.04
	Use Predecessor 5G2941006		r 40
P 5Q0919133 9B9	SENSOR O RING // / 4	Pieces	5.70 7.92
P D 180KU2A1	2KADHESIVE / MC 1	Pieces	A4.63103.65
P D 822150A1	BONDAGENT 1	Pieces	53.40 74.16
54 FG 755	Sum Item		5,987.93

Explanations P = Proportions	the Repairer of the following: To resurvey before latter spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
	Acknowledged by Repairer \$SignatureNo Credit

Payments to:

- BBN: - Acc.-No ..:

Sum Labor 4.812.50 5,987.93 Sum Item

Total 10,800.43 10,800.43 756.03 7% GST

11,556.46 Total SGD Incl. GST

Service Order Confirmation

SERVICE ORDER NO: 17/P2778

CUSTOMER NO.: CV038860

CUSTOMER NAME: SIM KING YAW

TELEPHONE NO.:

ADDRESS:

927 BUKIT TIMAH ROAD #08-16

Singapore

VEH No.: SLT8985H

Order Date: 06/10/17

Reg Date:

27/09/17

KM:

VIN NO.:

WVWZZZAUZHW116097

485 ENGINE NO:

SA: Cheong Pearlyn

MODEL:

GOLF A7 1.4 CL 92 (DSG)

MODEL NO.: 5G13HZ

	No.	DESCRIPTION	QTY	<u>uom</u>	UNIT PRICE	DISC %	AMOUNT
	Labor						
1	B&P DIAG	PROGRAMMING & CALIBRATION- NETT	35	TU	360		360
2	B&P MECH	ELECT WIRING & MECH COMPONENT CHECK NETT	1	TU	200		200
3	B&P INSURANCE EXCESS	INSURANCE EXCESS / DEDUCTIBLE	1	TU	-500		-500
4	B&P ALEX LABOUR	LABOUR + 1day to replace reinforcement	2	UNIT	475		950
5	B&P ALEX PAINT	SPRAY PAINT	1	UNIT	500		500
6	B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	1	ST	80		80
7	EXT00037	Tow SVC- Quality Recovery Services	31	UNIT	0		0
8	EXT00037	Tow SVC- Quality Recovery Services	1	UNIT	0		0
	Item						
9	5G0807217BNGRU	FRONT BUMPER	91	PCS	1,152.82	28	830.03
10	5G0919494	SENSOR BRACKET	1	PCS	14.70	28	10.58
11	5G0919493A	SENSOR BRACKET	2	PCS	14.70	28	21.17
12	5G0919493	SENSOR BRACKET	3	PCS	14.70	28	10.58
13	5Q0919133 9B9	SENSOR O RING	4	PCS	1.98	28	5.70
14	D 822150A1	BONDAGENT	1	PCS	74.16	28	53.40
15	D 180KU2A1	2KADHESIVE	84	PCS	103.65	28	74.63
16	5G0805705G	FRT CENTRE GUIDE	1	PCS	40.21	28	28.95
17	5G0807109H	BUMPER REINFORCEMENT	1	PCS	531.87	28	382.95

Remarks : MSIG WINNER OD

DOA 04/10/2017

SURVEYOR LKK

EXCESS \$ 500

Service Order Confirmation

SERVICE ORDI	ER NO: 17/P2778						
CUSTOMER NO							
CUSTOMER NA	AME: SIM KING YAW						
TELEPHONE N	10.:						
ADDRESS:	927 BUKIT TIMAH ROAL Singapore	0 #08-16					
VEH No							
Order Date:	06/10/17						
Reg Date:	27/09/17	KM: 485					
VIN NO.:	WVWZZZAUZHW116097	ENGINE NO:				SA	Cheong Pearlyn
MODEL:	GOLF A7 1.4 CL 92 (DSG)	MODEL NO.: 5G13HZ					
No.	DESCRIPT	CION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
				то	TAL		3,007.99
				GS	ST AMOUNT		210.56
				т	OTAL AMOUNT		3,218.55
		On Behalf Of "COMPANY"			Certified Goods	Service received	d:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way, #21-01 SGX Centre 2

Singapore 068807

Our File No:

CS/MSG17019150/GGBN2

Date:

12/12/2017

REFERENCE

Insured/Claimant: Date of Loss:

SIM KING YAW 04/10/2017

Policy No: Nature of Claim: 50505727

OD

Claim No:

531984

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLT8985H

Make & Model:

VOLKSWAGEN GOLF, 1.4 TSI (A)

Engine No:

CZC146060

337 km

Reg. Date:

Red

27/09/2017 (Man. Year: 2016)

Chassis No: Odometer:

WWZZZAUZHW116097

Colour:

1395 cc

Market Value/New Car Price:

S\$117,000.00

Sum Insured (S\$):

Engine Capacity:

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

265/40R18

Rear Tyre Size:

265/40R18

Front Left Side:

Michelin 9 mm

Rear Left Side: Rear Right Side: Michelin 9 mm Michelin 9 mm

Front Right Side: Michelin 9 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,067.93	1,497.99	4,569.94	75.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,732.50	2,010.00	2,722.50	57.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,800.43	3,507.99	7,292.44	67.52
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	10,300.43	3,007.99	7,292.44	70.80
+ GST 7.00/7.00% (S\$)	721.03	210.56	510.47	70.80
Nett Amount (S\$)	11,021.46	3,218.55	7,802.91	70.80

INSPECTION

Date of Assignment:

05/10/2017

Date Inspected:

06/10/2017 Inspected At:

Volkswagen Centre Singapore

(Alexandra)

247 Alexandra Road Singapore 159934

Estimated Period of Repair:

4.0 days

Adjuster: XING GUO QIANG

Manager: LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 12 Dec 2017)

Parts:

VOLKSWAGEN GOLF 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLT8985H)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LOCK CARRIER	Not Necessary	892.50 FS	*-FS
2	1		*FRONT CENTER GUIDE	Cracked	40.21 FS	*28.95 FS
3	1		*BUMPER LOWER SPOILER	Not Necessary	187.63 FS	*-FS
4	1		*HEADLIGHT BRACE LHS	Not Necessary	34.83 FS	*-FS
5	1		*HEADLIGHT BRACE RHS	Not Necessary	34.83 FS	*-FS
6	1		*BUMPER BRACKET LHS	Not Necessary	19.54 FS	*-FS
7	1		*BUMPER BRACKET RHS	Not Necessary	19.54 FS	*-FS
8	1		*BUMPER REINFORCEMENT	Bent	531.87 FS	*382.95 FS
9	1		*FRONT BUMPER	Deformed	1,152.82 FS	*830.03 FS
10	1		*FOAM INSERT	Not Necessary	40.17FS	*-FS
11	1		*UPPER CENTER GRILLE	Not Necessary	509.37 FS	*-FS
12	1		*LOWER CENTER GRILLE	Not Necessary	134.01 FS	*-FS
13	1		*SENSOR BRACKET	Necessary	14.70 FS	*10.58 FS
14	1		*SENSOR BRACKET (2 Pcs)	Necessary	29.40 FS	*21.17FS
15	1		*SENSOR BRACKET	Necessary	14.70FS	*10.58 FS
16	1		*HEADLAMP LHS	Not Necessary	1,073.04 FS	*-FS
17	1		*HEADLAMP RHS	Not Necessary	1,073.04FS	*-FS
18	1		*SENSOR O RING (4 pcs)	Necessary	7.92 FS	*5.70 FS
19	1		*2KADHESIVE	Necessary	103.65 FS	*74.63 FS
20	1		*BONDAGENT	Necessary	74.16 FS	*53.40 FS
21 F=Fr	1 anchise	part. S=SpcNe	*B&P NUMBER PLATE	Bent	80.00 FS	*80.00FS
		parties applied		Total Parts (S\$)	6,067.93	1,497.99

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR	New	2,375.00	950.00
2	SPRAY PAINT	New	1,500.00	500.00
3	VACUUM & REGAS AIRCON	New	237.50	
4	B&P AIRCON GAS	New	60.00	
5	SUPPLY OF B&P AIRCON GAS PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	New	360.00	360.00
6	ELECT WIRING & MECH COMPO	New	200.00	200.00
	Gross Lal	bour Cost (S\$)	4,732.50	2,010.00
	Report was unsubmitted of	Juring this print-out.		

< END OF ESTIMATES >