

REC BY:

REF: CS/SM017019201 /Grbm2

Special Instruction:

Submajor

(713)

ASSIGNMENT (Office)

From (Person):

Sherry Woney

of

SMO

Date/Time:

6/10/17 12.56pm

Estimated Cost:

Bill to:

OD / (FP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGG 9884 L

Insured:

GBA 7610 P

at Workshop n/s

Zoom Autowerkes

Tel:

9450 7920

of

832 Sims Avenue, Eunosville #12-884, 400832

Policy No:

Claim No:

CMTD1703500/Hcy

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 5/10/2017

9/10/17

@ 8 Kaki Bukit Ave 4 #03-14

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement

Date/Time:

6/10/17 4:30

Person Contacted:

Elin

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SGG 9884 L-X

GBA 7610 P-X

Sent poli thru email

Xbrl

REF: SMO

ASSIGNMENT

From _____ Date 9/10/17
 Estimated Cost _____
 OD (TP) WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No SGG 9884L
 At Workshop / M/s Zoom Autowerks
 of 8 kaki Bukit Ave 4, # 03-14, 416875
 Insured _____
 Policy No _____
 Claim No _____
 Sum Insured _____ Excess _____
 (Others Record) _____
 Make of Van _____
 Policy Condition _____
 Remark: The veh had commenced its repair at the time of inspection.
 Bail or Market Value _____
 D/O Accident Report _____ Consistent? Yes or No
 G/A PR Seen _____ Consistent? Yes or No
 Est Repairs 5 days Res: Yes or No
 Lump Sum 20 % 3 Val: Yes or No
 CA / REV / REP / 24 HRS (wp)
 Date _____ Person Contacted _____ Vehicle IN / OUT
 Date Time Action Instruction _____

Van No SGG 9884L Yr Regt 19 May 2016
 Type M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make Honda veez CC 1496
 Colour white AC Insured / Std / N / NA
 Sp Reading 55574 T Radio Insured / Std / N / NA
 Eng No _____
 C No RU11109356
 Gen Cond Good / Fair / Poor / Burnt
 Steering In order / Jammed / Leaked / Burnt or _____
 Brake In order / Jammed / Leaked / Burnt or _____
 Mod Nil / S Rim / STD A/Rim or _____
 Tyre Size F: 215/60R16
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / NIQ / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R Ba 6 mm R Ba 6 mm
 L Ba 6 mm L Ba 6 mm
 D/O A _____ D/O I 09-10-17
 Survey held at w/s 4:45pm
 Des of Damages o/s FA
 The UIC / Chassis frame / Body Structure affected due to collision

Confirm \$3650.00, 5 days
 Red: \$11121.52, 75%

RECEIVED 03 FEB 2018

Date Time File Pass to: ☐ : Preli. Report
traps ☒ : Final Report
 Date Time File Return to:

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee
 Transportation

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Invs (\$)
☐ Weekend (\$)
☐ Others

Photos
 Others

TOTAL

350

Report Format: TPLump Sum / H.B.I. (\$) 3650



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17019201/Grb

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 06-10-2017



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 7610L	Veh. Inspected	SGG 9884L
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1703500/HCY	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	06/10/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	05/10/2017	Inspection Date
Survey held at	-	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Nivitha (LKK Auto)

From: Wong, Shi Yi Shery <Shery.Wong@sompo.com.sg>
Sent: Friday, 6 October, 2017 12:56 PM
To: assignments@lkkauto.com
Cc: Catherine Chong (LKK Auto); Henry, Irene James; Han, Bernard; zoomautowerks@gmail.com
Subject: FW: Pre-Repair Inspection for SGG 9884 L // Accident on 05/10/2017 @ 10:45HR along Sims Avenue, before Lor 35 Geylang involving Vehicle Number SGG 9884 L & GBA 7610 P

Our Reference: CMTD1703500/HCY

Hi,

Kindly assign your motor surveyor to conduct motor survey of the mentioned (SGG9884L).

Please refer to the email correspondence below.

Best Regards

Shery Wong

Claims Division

D: 6329 5339 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Zoom Autowerks [mailto:zoomautowerks@gmail.com]

Sent: Friday, October 06, 2017 11:56 AM

To: Wong, Shi Yi Shery

Cc: Henry, Irene James; Han, Bernard

Subject: Re: FW: Pre-Repair Inspection for SGG 9884 L // Accident on 05/10/2017 @ 10:45HR along Sims Avenue, before Lor 35 Geylang involving Vehicle Number SGG 9884 L & GBA 7610 P

Dear All,

Please arrange:

LKK Auto Consultants

Mohd Rasul (West area)

Warmest Regards,
Elin Cai

Zoom Autowerks Pte Ltd
832 Sims Avenue, Eunosville
#12-884, Singapore 400832
☎9450 7920
✉zoomautowerks@gmail.com

On Thu, Oct 5, 2017 at 5:07 PM, Wong, Shi Yi Shery <Shery.Wong@sompo.com.sg> wrote:

Our Reference: CMTD1703500/HCY

Your Reference: SGG9884L

Date: 05TH October 2017

Without Prejudice

BY EMAIL ONLY

Attention:

M/S ZOOM AUTOWERKS PTE LTD

Accident involving SGG 9884 L & GBA 7610 P on 05/10/2017

Dear Sir

We refer to your Notice of Accident via email dated 05/10/2017.

Please be informed that Bernard is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Ma Chin Fook (North area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Shery Wong

Claims Division

D: 6329 5339 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: claimsreport
Sent: Thursday, October 05, 2017 4:16 PM
To: Motor Survey
Subject: Pre-Repair Inspection for SGG 9884 L // Accident on 05/10/2017 @ 10:45HR along Sims Avenue, before Lor 35 Geylang involving Vehicle Number SGG 9884 L & GBA 7610 P

Dear Shery,

FYNA

Best Regards

Angel Tan

Claims Division

D: 6329 5222 | T: 6461 6555 | F: 6221 3147

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Zoom Autowerks [<mailto:zoomautowerks@gmail.com>]

Sent: Thursday, 5 October, 2017 4:15 PM

To: claimsreport <claimsreport@sompo.com.sg>

Subject: Pre-Repair Inspection for SGG 9884 L // Accident on 05/10/2017 @ 10:45HR along Sims Avenue, before Lor 35 Geylang involving Vehicle Number SGG 9884 L & GBA 7610 P

Dear Sir/Madam,

We are instructed by Foo Chia Shing to notify you of a road traffic accident on 05/10/2017 at about 10:45HR at Sims Avenue, before Lor 35 Geylang involving our client's/customer's vehicle registration number SGG 9884 L and vehicle registration number GBA 7610 P driven by your insured at the material time.

A copy of the Singapore accident statement /traffic police report filed is enclosed. As a result of the accident, our client's /customer's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to repair the vehicle without further reference to you.

Please contact me @ 9450 7920, should you require more information.

Warmest Regards,

Elin Cai

Zoom Autowerks Pte Ltd

832 Sims Avenue, Eunosville

#12-884, Singapore 400832

☎9450 7920

✉zoomautowerks@gmail.com



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1703500/HCY
Our Ref: CS/SMO17019201/Grb

The Motor Claims Department
SOMPO INSURANCE SINGAPORE PTE LTD

Without Prejudice

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO. SGG 9884L .

We thank you for the instruction on 06/10/2017.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 09/10/2017 at the premises of M/s ZOOM AUTOWERKS and have the following to report:-

Workshop Estimate Amount	: S\$ 14,771.52 .
Revised Estimate Amount	: S\$ 4,611.12 .
"Check" Items Amount	: S\$.
Market Value	: S\$.
LTA Reimbursement Value	: S\$.
Nett Value	: S\$.

Description of Damage:
The vehicle sustained damages
at the o/s front portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully

XING GUO QIANG
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6381A
Vehicle Details	
Vehicle No.:	SGG9884L
Vehicle to be Exported:	No
Intended De-registration Date:	13 Oct 2017
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	L15B4029357
Chassis No.:	RU11109356
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,784.00
Original Registration Date:	19 May 2016
First Registration Date:	19 May 2016
Transfer Count:	0
Actual ARF Paid:	\$11,098.00
Intended PARF Rebate Details	

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 May 2026
PARF Rebate Amount:	\$8,323.00
Intended COE Rebate Details	
COE Expiry Date:	18 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,020.00
COE Rebate Amount:	\$40,422.00
Total Rebate Amount:	\$48,745.00

The information contained herein is correct as at 13 Oct 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/10/2017 17:21
Date Of Accident	05/10/2017 10:45
Exact Location Of Accident	SIMS AVENUE BEFORE LOR 35 GEYLANG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGG9884L
Insured/Policyholder	
Name Of Registered Owner	FOO CHIA SHING
NRIC No	S2156381A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93801718
Alternative Phone No	OFFICE-93801718

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 28956606 QMX
Cover Note Number	

Driver

Name of Driver	FOO CHIA SHING
NRIC No	S2156381A
Date Of Birth	17/05/1955
Occupation	INDOOR
Date Of Driving Pass	09/01/1976
Driving Experience	41 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93801718
Fax Number	
Contact Number	OFFICE-93801718
Email Address	NOEMAIL

Address	BLK 633A PUNGGOL DRIVE #06-677
Postcode	821633
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA7610P
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date & time, I, vehicle A, SGA 9884L, was travelling straight along the stated venue. Suddenly, vehicle B, ABA 7610P, cut out from the first lane & collided onto my vehicle's front right portion, damaging my front right bumper, fender, tyre & rim.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



ZOOM AUTOWERKS PTE LTD

832 Sims Avenue, Eunosville

#12-884 Singapore 400832

Tel: 9450 7920

* zoomautowerks@gmail.com

D.O.A : 05 OCTOBER 2017

DATE : 06 OCTOBER 2017

OWNER : FOO CHIA SHING

REG NO. : SGG 9884 L

MAKE/MODEL : HONDA VEZEL

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(S\$)
<u>LIST ITEMS</u>		
1	Front bonnet X NN	\$ 1,151.70 X
1	Front bonnet rubber X	\$ 78.30 X
1	Front headlamp -R/H / Scr repair	\$ 1,759.40 1492
1	Front headlamp top panel X	\$ 175.30 X
1	Front headlamp lower bracket X NN	\$ 78.00 X
1	Front grille X	\$ 285.00 X
1	Front grille logo X NN	\$ 45.70 X
1	Front grille chrome moulding X	\$ 285.00 X
1	Front bumper / TV	\$ 1,085.40 727.5
1	Front bumper centre grille X NN	\$ 167.00 X
1	Front bumper fog lamp X	\$ 327.70 X
1	Front bumper fog lamp cover X	\$ 45.20 X
1	Front bumper reinforcement X BT	\$ 321.40 /
2	Front bumper side retainers X MC	\$ 120.60 46
1	Front bumper signal lamp X NN	\$ 285.00 X
1	Front bumper tow hook cover X	\$ 45.00 X
1	Front fender -R/H X Repair	\$ 580.40 X
1	Front fender inner garnish X NN	\$ 180.50 X
1	Front fender inner shield X de	\$ 155.50 130
1	Front fender wheel arch garnish X cut	\$ 488.30 153
1	Front support panel X Repair	\$ 576.00 X
1	Front wheel hub -R/H X NN	\$ 299.70 X
1	Front wheel bearing -R/H X MC	\$ 181.50 /
1	Front shock absorber -R/H X	\$ 501.20 X
1	Front knuckle arm -R/H X NN	\$ 600.70 X
1	Front tie rod X	\$ 120.50 X
1	Front lower arm -R/H X	\$ 426.00 X
		\$ 10,366.00

List Items Sub Total c/f:

\$ 10,366.00

LIST ITEMS

1	Front stabilizer bar	X 4NN	\$ 175.90	X
1	Front drive shaft -R/H	X	\$ 985.00	X
			\$ 11,526.90	
			\$ 2,305.38	
			\$ 9,221.52	

Less 20%

351.4
20%: 2441.2

SPECIAL NETT ITEMS

1	Front bumper clip (1 set)	/ 16c	\$ 45.00	30
1	Front bumper lower spoiler	/ 16c	\$ 480.00	280
1	Front fender inner shield clip (1 set)	/ 16c	\$ 45.00	30
1	Front tyre -R/H	/ 16c	\$ 350.00	210
1	Front sport rim -R/H	/ 16c	\$ 750.00	380
			\$ 1,670.00	

930

S/N

LABOUR CHARGES

1	To check wiring and reset headlamps focussing.	\$ 80.00	30
2	To remove and refit inner garnishes.	\$ 150.00	X NN
3	To remove and refit front undercarriage.	\$ 450.00	50
4	To conduct wheel alignment.	\$ 150.00	60
5	To apply undercoating.	\$ 150.00	X NN
6	Panel beating.	\$ 1,500.00	400
7	To re-spray painting on the affected areas.	\$ 1,400.00	700
		\$ 3,880.00	1240

4611.12
20%: 3650

GRAND TOTAL :

\$ 14,771.52

5 Days.
Lump sum repair.
After repair photos.
Gm. Q&A - 82880282.
09/10/17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17019201/Grbn2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 13-02-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 7610P	Veh. Inspected	SGG 9884L
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1703500/HCY	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	06/10/2017

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11109356	Colour	WHITE
Odometer	55574	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	MICHELIN	6 mm
L/H Front Tyre	215/60 R16	MICHELIN	6 mm
R/H Rear Tyre	215/60 R16	MICHELIN	6 mm
L/H Rear Tyre	215/60 R16	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	05/10/2017	Inspection Date	09/10/2017
Survey held at	8 KAKI BUKIT AVE 4 #03-14		
Repairer	ZOOM AUTOWERKS PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGG 9884L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET	NOT NECESSARY	1,151.70	-
1	FRONT BONNET RUBBER	NOT NECESSARY	78.30	-
1	FRONT HEADLAMP-R/H	SCRATCHED	1,759.40	1,492.00
1	FRONT HEADLAMP TOP PANEL	TO REPAIR SEE LABOUR	175.30	-
1	FRONT HEADLAMP LOWER BRACKET	NOT NECESSARY	78.00	-
1	FRONT GEILLE	NOT NECESSARY	285.00	-
1	FRONT GEILLE LOGO	NOT NECESSARY	45.70	-
1	FRONT GEILLE CHROME MOULDING	NOT NECESSARY	285.00	-
1	FRONT BUMPER	TORN	1,085.40	727.50
1	FRONT BUMPER CENTRE GRILLE	NOT NECESSARY	167.00	-
1	FRONT BUMPER FOG LAMP	NOT NECESSARY	327.70	-
1	FRONT BUMPER FOG LAMP COVER	NOT NECESSARY	45.20	-
1	FRONT BUMPER REINFORCEMENT	BENT	321.40	321.40
2	FRONT BUMPER SIDE RETAINERS	NECESSARY	120.60	46.00
1	FRONT BUMPER SIGNAL LAMP	NOT NECESSARY	285.00	-
1	FRONT BUMPER TOW HOOK COVER	NOT NECESSARY	45.00	-
1	FRONT FENDER-R/H	TO REPAIR SEE LABOUR	580.40	-
1	FRONT FENDER INNER GARNISH	NOT NECESSARY	180.50	-
1	FRONT FENDER INNER SHIELD	DEFORMED	155.50	130.00
1	FRONT FENDER WHEEL ARCH GARNISH	CUT	488.30	153.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	576.00	-
1	FRONT WHEEL HUB-R/H	NOT NECESSARY	299.70	-
1	FRONT WHEEL BEARING-R/H	NECESSARY	181.50	181.50
1	FRONT SHOCK ABSORBER-R/H	NOT NECESSARY	501.20	-
1	FRONT KNUCKLE ARM-R/H	NOT NECESSARY	600.70	-
1	FRONT TIE ROD	NOT NECESSARY	120.50	-
1	FRONT LOWER ARM-R/H	NOT NECESSARY	426.00	-
1	FRONT STABILIZER BAR	NOT NECESSARY	175.90	-
1	FRONT DRIVE SHAFT-R/H	NOT NECESSARY	985.00	-
	LESS 20% DISCOUNT		-2,305.38	-610.28
			9,221.52	2,441.12

Report Ref No. CS/SMO17019201/Grbn2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	45.00	30.00
1	FRONT BUMPER LOWER SPOILER (SN)	DEFORMED	480.00	280.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	45.00	30.00
1	FRONT TYRE-R/H (SN)	SCRATCHED	350.00	210.00
1	FRONT SPORT RIM-R/H (SN)	CUT	750.00	380.00
			1,670.00	930.00
	<u>LABOUR</u>			
	TO CHECK WIRING AND RESET HEADLAMPS FOCUSSING.		80.00	30.00
	TO REMOVE AND REFIT INNER GARNISHES.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.		450.00	50.00
	TO CONDUCT WHEEL ALIGNMENT.		150.00	60.00
	TO APPLY UNDERCOATING.	NOT NECESSARY	150.00	-
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT HEADLAMP TOP PANEL,FRONT FENDER-R/H AND FRONT SUPPORT PANEL.		1,500.00	400.00
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS.		1,400.00	700.00
			3,880.00	1,240.00
	GRAND TOTAL		14,771.52	4,611.12
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,650.00

Report Ref No. CS/SMO17019201/Grbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
 No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.