

ASS. REC. BY:

REF: CS/FCI17019276/R19602

Special Instruction:

SUMMARY:

CSJS

Rasul

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time: 7/10/17 12.22pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJJ 5985D

Insured:

SH 8288 S

at Workshop m/s

Kah Motor

Tel:

90721769 / 6471 9419

of

255 Alexandra Road

Policy No:

Claim No:

D1700 9471 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 4/10/17

CA / REV / REP. / REV 24 HRS

DS

H.O.D. Endorsement

Date/Time:

9/10/17 9:30am

Person Contacted:

Mr. Ng

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJJ 5985D - X

SH 8288 S - CS/FCI16021014 / Gvby 2-D.O.A. 2/11/2016

Signature: Rasul

REF:


36557

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: 833 59850
 at Workshop m/s: KAT MOTOR
 of: 285, ALKAMRA RD
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition) after 10m

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 20K
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 8 days Res.: Yes or No
 Lum Sum: 1-B-1 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: 833 59850 Yr Regn: 2008 / 86P
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda Civic 1.6 A c.c. 1595
 Colour: Red A/C: Insured / Std / NI / NA
 Sp. Reading: 149710 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JHMF046208S 20.2249
 Gen. Cond: Good (Fair) / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / SRM / STD A/Rim or
 Tyre Size: F: 205/55R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. 04/10/17 D.O.I. 02/10/17
 Survey held at KAT MOTOR
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
RGAR N/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
10/10/17 0920	Email to KAT motor SA SINHA regarding the nett amount to repair this veh. B 9K only.
10/10/17	email preli to Eileen.
28/12/17	confirmed final fig \$9000 with Mr Ng. Cred: 6313.53, 41%.

* MV: \$20,000, LTA: \$10204, NV: \$9796

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

Days Of Repair: 8

Resurvey No. of Trip: _____

Survey Fee: 1704.60

Transportation: 50

S + RS: 50

Photos: 55

Others: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐

☐ : Interview (\$ _____)

☐

☐ : Tech. Invs (\$ _____)

☐

☐ : Weekend (\$ _____)

☐

TOTAL

385

Report Format: TP

Lump Sum / B.I. (\$ 9000)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17019276/R1gb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 09-10-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 8288S	Veh. Inspected	SJJ 5985D
Policy No.		Coverage (\$)	0.00
Claim No.	D17009471MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	09/10/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	04/10/2017	Inspection Date	09/10/2017
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	06-10-2017	Our Ref No. D17009471MFSH
Accident Date	04-10-2017	Claim Type. Third Party
Insured Vehicle	SH8288S	Third Party Vehicle. SJJ5985D
Survey Location	BODY REPAIR & PAINT CENTRE 255 ALEXANDRA ROAD	
Contact Person.	NG SIN HAI	
Contact No.	64715419/ 90721769	Fax No. 0
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAH MOTOR CO SDN BHD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/228833)



PRI Documents



Close



PRI Header Details

Claim No	D17009471MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & KAH MOTOR
Workshop Name	KAH MOTOR CO SDN BHD (Contact Person : NG SIN HAI)	Survey Location & Contact Details	BODY REPAIR & PAINT CENTRE 255 ALEXANDRA ROAD Mobile: 90721769 , Phone: 64715419 , Fax: 0 EmailId: SHNG@KAHMOTOR.ONMICROSOFT.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH8288S	TP Vehicle No	SJJ5985D
PRI Recieved Date	06-10-2017 03:41:45 PM	Surveyor Appointed Date	07-10-2017 12:22:19 PM	Surveyor Accept Date	09-10-2017 11:00:00 AM

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	09-10-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Ai Phing (LKKAUTO)

From: Ai Phing (LKKAUTO)
Sent: Tuesday, 10 October, 2017 3:33 PM
To: 'Claim Workflow System'
Cc: EILEENLEE@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17009471MFSH/1
Attachments: SJJ 5985D.pdf

Dear Eileen,

Enclosed herewith preliminary advise of SJJ 5985D.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 9 October, 2017 9:20 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17009471MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Saturday, 7 October, 2017 12:22 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; EILEENLEE@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17009471MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Rasul (LKKAuto)

From: Rasul (LKKAuto)
Sent: Tuesday, 10 October, 2017 9:23 AM
To: 'Ng Sin Hai'
Subject: SJJ 5985D doa : 04/10/2017

Hi Sin Hai,

As spoken, the NETT amount to repair this vehicle is 9K ONLY

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Assessor
S(408933)

Save the Earth. Print only when necessary.

Rasul (LKKAuto)

From: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>
Sent: Tuesday, 10 October, 2017 9:27 AM
To: Rasul (LKKAuto)
Subject: RE: SJJ 5985D doa : 04/10/2017

Dear Rasul,

Thanks for the amount.
I will repair at this limit.

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai
Kah Motor Co. Sdn. Bhd
(A member of Oriental Holdings Berhad)
Body Repair & Paint Centre
255 Alexandra Road
Singapore 159937
DID: 6471 5419
HP: 9072 1769
E-mail: shng@honda.com.sg



Visit our
Facebook page



CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

From: Rasul (LKKAuto) [<mailto:Rasul@lkkauto.com>]
Sent: Tuesday, 10 October, 2017 9:23 AM

To: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>
Subject: SJJ 5985D doa : 04/10/2017

Hi Sin Hai,

As spoken, the NETT amount to repair this vehicle is 9K ONLY

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



ASSAULT
2-10-2017-2018
Pte Ltd

Save the Earth. Print only when necessary.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17009471MFSH

Date: 10-10-2017

Our Ref: CS/FCI17019276/R1gb

The Motor Claims Department
First Capital Insurance Ltd

Without Prejudice

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJJ 5985D.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 09-10-2017 at the premises of M/s KAH MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$ <u>15,313.53</u>
Revised Estimate Amount	: S\$ <u>9,150.24</u>
"Check" Items Amount	: S\$ <u>349.41</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>


Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Yours faithfully

Mohamed Rasul
Automotive Assessor



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 3655I

Vehicle Details

Vehicle No.: SJJ5985D

Vehicle to be Exported: No

Intended De-registration Date: 10 Oct 2017

Vehicle Make: HONDA

Vehicle Model: CIVIC 1.6L VTI AUTO

Primary Colour: Red

Manufacturing Year: 2008

Engine No.: R16A13006628

Chassis No.: JHMFD46208S202249

Maximum Power Output: 92.0 kW (123 bhp)

Open Market Value: \$18,625.00

Original Registration Date: 19 Sep 2008

First Registration Date: 19 Sep 2008

0

Transfer Count:

Actual ARF Paid: \$18,625.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 18 Sep 2018

PARF Rebate Amount: \$9,312.00

Intended COE Rebate Details

COE Expiry Date: 18 Sep 2018

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$9,501.00

COE Rebate Amount: \$892.00

Total Rebate Amount: \$10,204.00

The information contained herein is correct as at 10 Oct 2017

OK

20,500
10,204

9,796

Land Transport  Authority (<https://www.lta.gov.sg>)

Please read through the Privacy Statement, Terms of Use, and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) |

[Rate this e-Service \(https://www.lta.gov.sg/feedback/PublicSurvey.aspx?SurveyDetlNum=S201400011\)](https://www.lta.gov.sg/feedback/PublicSurvey.aspx?SurveyDetlNum=S201400011)

Last updated on 08 Oct 2017 at 01:03 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/10/2017 15:47
Date Of Accident	04/10/2017 16:40
Exact Location Of Accident	PIE TOWARDS JURONG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJJ5985D
Insured/Policyholder	
Name Of Registered Owner	EUGENA LEE E-HUEI
NRIC No	S7343655I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96838496
Alternative Phone No	OFFICE-96838496

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.6 L (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO

Policy Number

Cover Note Number

Driver

Name of Driver	EUGENA LEE E-HUEI
NRIC No	S7343655I
Date Of Birth	03/12/1973
Occupation	INDOOR
Date Of Driving Pass	08/11/1996
Driving Experience	20 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96838496
Fax Number	
Contact Number	OFFICE-96838496
EMail Address	NOEMAIL

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Vehicle No. SJ55985D

Annex E

Describe Circumstances of the Accident

refer to police report T/20171004/2168

You had been advised by the workshop that in the event that you wish to claim against your own policy (OD claim), there is a fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel



**SINGAPORE
POLICE FORCE**



T/20171004/2168

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

2 of 3



Report No. T/20171004/2168

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	EUGENA LEE E-HUEI	ID No.	S7343655I
Related Vehicle	NIL	Contact No.	96838496
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	WONG LIANG BENG	ID No.	S0026117C
Related Vehicle	NIL	Contact No.	98320055
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 04/10/2017 at 1640hrs I was driving my vehicle, V1 SJJ5985D along PIE towards Jurong. the traffic was congested so I had to slow down. subsequently, the car in front jammed on the brakes which caused me to slow down and during that moment the vehicle behind me, V2 SH8288S bumped on to my rear twice. Both of the drivers including me came out and we made checks and exchanged particulars. the driver of V2 left the scene after I took down his particulars. furthermore there were two young boys representing the company named Torque 5 pte ltd driving a yellow vehicle who came up to offer tow truck and car repair services. I wish to state that I politely declined their offer for several times. They still insisted to offer their services until I shifted my vehicle V2 to the road shoulder. Traffic police arrived at the scene at 1712hrs and subsequently EMAS towing service came down access the situation and the traffic police officer advised me to make a report at the nearest police station as soon as possible. The EMAS towing service also assessed told me that I can drive my car.



**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SJJ5985D
Chassis No : JHMF46208S202249
Model : CIVIC 1.6L AUTO
Owner's Name : EUGENA LEE E-HUEI
Ins Policy No. :
Date of Accident : 4/10/2017

Document No. : SQT17004108 Page 1
Date : 5. Oct 2017
Customer No. : WZF002
Svc Advisor : NG SIN HAI
Engine No : R16A13006628
Date | Time : 5. Oct 2017 4:32:19 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:EUGENA LEE E-HUEI OWNER INSURER:DIRECT ASIA ACC DATE:04/10/2017 SURVEYED BY: DATE: REF NO: TP INSURER:FIRST CAPITAL INSURANCE LTD TP VEH:SH8288S						
BOSUN	SUNDRIES	1	100.00 <i>30</i>		100.00	7.00	107.00
BA01R	REMOVE & RENEW REVERSE SENSORS-2 PCS (N)	1	150.00		150.00	10.50	160.50
BOJSE	SEALANT FOR REAR END PANEL	1	80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	X 80.00 <i>X</i>		80.00	5.60	85.60
BOJSE	SEALANT FOR TRUNK	1	X 80.00		80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	150.00		150.00	10.50	160.50
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	X 560.00 <i>X</i>		560.00	39.20	599.20
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	560.00 <i>465.23</i>		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00 <i>280</i>		560.00	39.20	599.20
BKRP02B	CUT OFF & RENEW RR FLOOR PANEL FENDERS.STRAIGHTEN	1	5000.00 <i>2800</i>		5000.00	350.00	5350.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3000.00 <i>2700</i>		3000.00	210.00	3210.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	450.00 <i>X X</i>		450.00	31.50	481.50
			Sum Labor		10770.00	753.90	11,523.90
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00 <i>CRA</i>		45.00	3.15	48.15
RS-2P	BUMPER SENSOR 2PCS	1	150.00 <i>SVL</i>		150.00	10.50	160.50
33501-SNB-003	LAMP UNIT R	1	236.80 <i>7-X</i>	25	177.60	12.43	190.03
33551-SNB-003	LAMP UNIT L	1	236.80 <i>CRA</i>	25	177.60	12.43	190.03

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SJJ5985D

Chassis No : JHMF46208S202249

Model : CIVIC 1.6L AUTO

Owner's Name : EUGENA LEE E-HUEI

Ins Policy No. :

Date of Accident : 4/10/2017

Document No. : SQT17004108 Page 2

Date : 5. Oct 2017

Customer No. : WZF002

Svc Advisor : NG SIN HAI

Engine No : R16A13006628

Date | Time : 5. Oct 2017 4:32:19 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
34151-SNB-023	LAMP UNITR.	1	152.80 R	25	114.60 X	8.02	122.62
34156-SNB-023	LAMP UNITL.	1	152.80 CR	25	114.60	8.02	122.62
74890-SNB-000ZJ	GARNISHRR.LICENCE	1	127.30 ? X	25	95.47	6.68	102.15
68500-SNB-G00ZZ	LIDTRUNK	1	610.70 HA	25	458.02	32.06	490.08
68610-SNA-000ZZ	HINGE COMPR.TRUNK.	1	50.90 ? X	25	38.17	2.67	40.84
68660-SNA-000ZZ	HINGE COMPL.TRUNK.	1	50.90 ? X	25	38.17	2.67	40.84
74851-SNA-G22	LOCK TRUNK	1	203.60 HA	25	152.70	10.69	163.39
74862-SE3-003	STRIKERTRUNK	1	11.60 ne	25	8.70	0.61	9.31
74865-SNA-003	W/STRIPTRUNK LID	1	91.70 ut	25	68.77	4.81	73.58
75701-SNB-003	EMBLEMRR (H)	1	28.00 ne	25	21.00	1.47	22.47
75722-SNB-J01	EMBLEMRR (CIVIC)	1	30.50 ne	25	22.87	1.60	24.47
75725-SNA-K01	EMBLEMRR (I-VTEC)	1	34.70 ne	25	26.02	1.82	27.84
75731-SNB-K31	EMBLEMREAR (1.6)	1	17.80 ne	25	13.35	0.93	14.28
71501-SNL-Q01ZZ	BUMPER	1	638.00 DE	25	478.50	33.50	512.00
71593-SNA-A01	SPACERR.RR.BUMPER SIDE	1	15.30 ne	25	11.47	0.80	12.27
71598-SNA-A01	SPACERL RR BPR SIDE	1	15.30 ne	25	11.47	0.80	12.27
91503-SZ3-003	CLIP ABUMPER	2	3.90 ne	25	5.85	0.41	6.26
91505-S9A-003	CLIP ABUMPER	8	3.90 ne	25	23.40	1.64	25.04
66100-SNA-U02ZZ	PANELREAR	1	305.40 HA	25	229.05	16.03	245.08
04655-SNA-U01ZZ	PANELRR.FLOOR.	1	890.30 R	25	667.72 X	46.74	714.46
72841-SH3-315	OILSHEET	3	39.90 X	25	89.77 X	6.28	96.05
84521-SNA-A00ZA	LID COMPSPARE TIRE	1	340.70 CR	25	255.52	17.89	273.41
84640-SNA-A01ZA	LININGRR.PANEL	1	61.80 DE	25	46.35	3.24	49.59
Sum Item					3541.74	247.89	3,789.63

Survey By Rasm - Hp 90010068

Date & Time

04/10/17 @ 1420

8 days

Total Amount 14,311.74 1,001.79 15,313.53

Excess

Total (Inclusive of GST) 15,313.53

Status

Resurvey by part

Signature

Printed on 5/10/2017 6:07:54 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SJJ5985D

Chassis No : JHMFD46208S202249

Model : CIVIC 1.6L AUTO

Owner's Name : EUGENA LEE E-HUEI

Ins Policy No. :

Date of Accident : 4/10/2017

Document No. : SQT17004108

Page 3

Date : 5. Oct 2017

Customer No. : WZF002

Svc Advisor : NG SIN HAI

Engine No : R16A13006628

Date | Time : 5. Oct 2017 4:32:19 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incl GST
------	-------------	-----	------------	--------	--------	------------	--------------------

Printed on 5/10/2017 6:07:54 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZF002 / FIRST CAPITAL
Chassis No: JHMFD46208S202249
License No: SJJ5985D
Mileage: 149493
Engine No: R16A13006628

Document No: SVO17064455
Printed By: SHNG
Order Date: 9. October 2017
Order Time: 3:00:01 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:EUGENA LEE E-HUEI OWNER INSURER:DIRECT ASIA ACC DATE:04/10/2017 SURVEYED BY:RASUL DATE:09/10/2017 REF NO: TP INSURER:FIRST CAPITAL INSURANCE LTD TP VEH:SH8288S						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
RS-2P	BUMPER SENSOR 2PCS	1	150.00		150.00	10.50	160.50
33551-SNB-003	LAMP UNIT L	1	236.80	25	177.60	12.43	190.03
34156-SNB-023	LAMP UNITL	1	152.80	25	114.60	8.02	122.62
68500-SNB-G00ZZ	LIDTRUNK	1	610.70	25	458.02	32.06	490.08
74851-SNA-G22	LOCK TRUNK	1	203.60	25	152.70	10.69	163.39
74862-SE3-003	STRIKERTRUNK	1	11.60	25	8.70	0.61	9.31
74865-SNA-013	W/STRIPTRUNK LID	1	96.40	25	72.30	5.06	77.36
75701-SNB-003	EMBLEMRR (H)	1	28.00	25	21.00	1.47	22.47
75722-SNB-J01	EMBLEMRR (CIVIC)	1	30.50	25	22.87	1.60	24.47
75725-SNA-K01	EMBLEMRR (I-VTEC)	1	34.70	25	26.02	1.82	27.84
75731-SNB-K31	EMBLEMREAR (1.6)	1	17.80	25	13.35	0.93	14.28
04715-SNB-010ZZ	FACEREAR BUMPER ^	1	694.90	25	521.17	36.48	557.65
71593-SNA-A01	SPACERR.RR.BUMPER SIDE	1	15.30	25	11.47	0.80	12.27
71598-SNA-A01	SPACERL RR BPR SIDE	1	15.30	25	11.47	0.80	12.27
91503-SZ3-003	CLIP ABUMPER	2	3.90	25	5.85	0.41	6.26
91505-S9A-003	CLIP ABUMPER	8	3.90	25	23.40	1.64	25.04
66100-SNA-U02ZZ	PANELREAR	1	305.40	25	229.05	16.03	245.08
84521-SNA-A01ZA	LID COMPSPARE TIRE	1	311.80	25	233.85	16.37	250.22
84640-SNA-A01ZA	LININGRR.PANEL	1	61.80	25	46.35	3.24	49.59
	SUM PARTS:				2,344.77	164.11	2,508.88
BOSUN	0701 SUNDRIES	1	30.00		30.00	2.10	32.10
BA01R	0669 REMOVE & RENEW REVERSE SENSORS-2 PCS (N)	1	150.00		150.00	10.50	160.50
BOJSE	1374 SEALANT FOR REAR END PANEL	1	80.00		80.00	5.60	85.60
BML02I	0669 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	150.00		150.00	10.50	160.50
BMI02D	1757 REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N)	1	465.23		465.23	32.57	497.80
BKTG02R	0669 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	280.00		280.00	19.60	299.60



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZF002 / FIRST CAPITAL
Chassis No: JHMF046208S202249
License No: SJJ5985D
Mileage: 149493
Engine No: R16A13006628

Document No: SVO17064455
Printed By: SHNG
Order Date: 9. October 2017
Order Time: 3:00:01 PM
Service Advisor: NG SIN HAI

BKRP02B	0669	1	2,800.00	2,800.00	196.00	2,996.00
	CUT OFF & RENEW RR FLOOR PANEL					
	FENDERS.STRAIGHTEN					
	ALIGN RR CHASSIS & RENEW DAMAGE					
	PARTS.					
BP06R	1610	1	2,700.00	2,700.00	189.00	2,889.00
	SPRAY PAINTING ON REPAIRED OR					
	REPLACED AREAS. (6P)					
			SUM LABOUR:	6,655.23	465.87	7,121.10
			TOTAL SGD	9,000.00	629.98	9,629.98
Total Payable (SGD)						9,629.98

GST Amount is calculated from individual line(s)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17019276/R1gbe2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 04-01-2018	
			Code : FCI2	
1. Policy Particulars : THIRD PARTY CLAIM				
Insured Veh.	SH 8288S	Veh. Inspected	SJJ 5985D	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17009471MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	07/10/2017	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC 1.6 A	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JHMFD46208S202249	Colour	RED	
Odometer	149710	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	CONTINENTAL	6 mm	
L/H Front Tyre	205/55 R16	CONTINENTAL	6 mm	
R/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm	
L/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/10/2017	Inspection Date	09/10/2017	
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 5985D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
1	NUMBER PLATE WITH CASING (SN)	CRACKED	45.00	45.00
2	BUMPER SENSOR (SN)	NECESSARY	150.00	150.00
1	LAMP UNIT R (SN)	SERVICEABLE	177.60	-
1	LAMP UNIT L (SN)	CRACKED	177.60	177.60
1	LAMP UNITR (SN)	TO REPAIR SEE LABOUR	114.60	-
1	LAMP UNITL (SN)	CRACKED	114.60	114.60
1	GARNISHRR.LICENCE (SN)	SERVICEABLE	95.47	-
1	LIDTRUNK (SN)	BENT	458.02	458.02
1	HINGE COMPR.TRUNK (SN)	SERVICEABLE	38.17	-
1	HINGE COMPL.TRUNK (SN)	SERVICEABLE	38.17	-
1	LOCK TRUNK (SN)	BENT	152.70	152.70
1	STRIKER TRUNK (SN)	NECESSARY	8.70	8.70
1	W/STRIPTRUNK LID (SN)	CUT	72.30	72.30
1	EMBLEMRR (H) (SN)	NECESSARY	21.00	21.00
1	EMBLEMRR (CIVIC) (SN)	NECESSARY	22.87	22.87
1	EMBLEMRR (I-VTEC) (SN)	NECESSARY	26.02	26.02
1	EMBLEMREAR (1.6) (SN)	NECESSARY	13.35	13.35
1	BUMPER (SN)	DEFORMED	521.17	521.17
1	SPACERR.RR.BUMPER SIDE (SN)	NECESSARY	11.47	11.47
1	SPACERL RR BPR SIDE (SN)	NECESSARY	11.47	11.47
2	CLIP ABUMPER (SN)	NECESSARY	5.85	5.85
8	CLIP ABUMPER (SN)	NECESSARY	23.40	23.40
1	PANELREAR (SN)	BENT	229.05	229.05
1	PANELRR.FLOOR (SN)	TO REPAIR SEE LABOUR	667.72	-
3	OILSHEET (SN)	NOT NECESSARY	89.77	-
1	LID COMPSARE TIRE (SN)	CRACKED	255.52	233.85
1	LININGRR.PANEL (SN)	DEFORMED	46.35	46.35
			3,687.94	2,374.77

Report Ref No. CS/FC117019276/R1gbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop(\$)	Qty Adjusted (\$)
	LABOUR			
	REMOVE & RENEW REVERSE SENSORS - 2PCS.		150.00	150.00
	SEALANT FOR REAR END PANEL.		80.00	80.00
	SEALANT FOR REAR FLOOR PANEL.	NOT NECESSARY	80.00	-
	SEALANT FOR TRUNK.	NOT NECESSARY	80.00	-
	REMOVE & INSTALL FUEL TANK FUEL PIPES.	NOT NECESSARY	560.00	-
	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK.		560.00	465.23
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST.		560.00	280.00
	CUT OFF & RENEW RR FLOOR PANEL FENDERS. STRAIGHTEN. INCLUSIVE OF THE REPAIR OF LAMP UNITR AND PANELRR.FLOOR.		5,000.00	2,800.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)		3,000.00	2,700.00
	REMOVE & RENEW RR FLOOR INSULATOR.	NOT NECESSARY	450.00	-
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		150.00	150.00
			10,670.00	6,625.23
	GRAND TOTAL		14,357.94	9,000.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			9,000.00
---	--	--	-----------------

Report Ref No. CS/FCI17019276/R1gbe2

MARKET VALUE: \$20,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$10,204.00=NETT VALUE: \$9,796.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.