

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SJJ5985D
Chassis No : JHMF46208S202249
Model : CIVIC 1.6L AUTO
Owner's Name : EUGENA LEE E-HUEI
Ins Policy No :
Date of Accident : 4/10/2017

Document No. : SQT17004108
Date : 5. Oct 2017
Customer No. : WZF002
Svc Advisor : NG SIN HAI
Engine No : R16A13006628
Date | Time : 5. Oct 2017 4:32:19 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
34151-SNB-023	LAMP UNITR.	1	152.80 R	25	114.60 X	8.02	122.62
34156-SNB-023	LAMP UNITL.	1	152.80 CR	25	114.60	8.02	122.62
74890-SNB-000ZJ	GARNISHRR.LICENCE	1	127.30 ? X	25	95.47	6.68	102.15
68500-SNB-G00ZZ	LIDTRUNK	1	610.70 HA	25	458.02	32.06	490.08
68610-SNA-000ZZ	HINGE COMPR.TRUNK.	1	50.90 ? X	25	38.17	2.67	40.84
68660-SNA-000ZZ	HINGE COMPL.TRUNK.	1	50.90 ? X	25	38.17	2.67	40.84
74851-SNA-G22	LOCK TRUNK	1	203.60 HA	25	152.70	10.69	163.39
74862-SE3-003	STRIKERTRUNK	1	11.60 ne	25	8.70	0.61	9.31
74865-SNA-003	W/STRIPTRUNK LID	1	91.70 cut	25	68.77	4.81	73.58
75701-SNB-003	EMBLEMRR (H)	1	28.00 ne	25	21.00	1.47	22.47
75722-SNB-J01	EMBLEMRR (CIVIC)	1	30.50 ne	25	22.87	1.60	24.47
75725-SNA-K01	EMBLEMRR (I-VTEC)	1	34.70 ne	25	26.02	1.82	27.84
75731-SNB-K31	EMBLEMREAR (1.6)	1	17.80 ne	25	13.35	0.93	14.28
71501-SNL-Q01ZZ	BUMPER	1	638.00 DE	25	478.50	33.50	512.00
71593-SNA-A01	SPACERR.RR.BUMPER SIDE	1	15.30 ne	25	11.47	0.80	12.27
71598-SNA-A01	SPACERL RR BPR SIDE	1	15.30 ne	25	11.47	0.80	12.27
91503-SZ3-003	CLIP ABUMPER	2	3.90 ne	25	5.85	0.41	6.26
91505-S9A-003	CLIP ABUMPER	8	3.90 ne	25	23.40	1.64	25.04
66100-SNA-U02ZZ	PANELREAR	1	305.40 HA	25	229.05	16.03	245.08
04655-SNA-U01ZZ	PANELRR.FLOOR.	1	890.30 R	25	667.72 X	46.74	714.46
72841-SH3-315	OILSHEET	3	39.90 X nn	25	89.77 X	6.28	96.05
84521-SNA-A00ZA	LID COMPSPARE TIRE	1	340.70 CR	25	255.52	17.89	273.41
84640-SNA-A01ZA	LININGRR.PANEL	1	61.80 DE	25	46.35	3.24	49.59
Sum Item					3541.74	247.89	3,789.63

Survey By : Rasm - Hp 90010068
Date & Time : 02/10/17 @ 1420
Excess :
Status : Resurvey by part
Signature : [Signature]

LKK Auto Consultants hence notify

the Repairer of the following amount 14,311.74 1,001.79 15,313.53
Total (Inclusive of GST) 15,313.53

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 5/10/2017 6:07:54 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)