

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Premium Auto
of _____


Insured: _____

Policy No. 2100389641Claims No. 884579437456Sum Insured: _____ Excess: 0

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$122K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKP 8816 X Yr Regn: 17 Oct 2014Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Audi A6 C.C. 1984Colour: white A/C: ☒ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading _____ T/Radio: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: WAU 888 464 EN 054174Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD / ☐ A/Rim orTyre Size: F: 255/35 R20R: 11BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 06-10-17Survey held at w/s 3:30pmDes. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop orand Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SKP 8816 X - X
10/10/17 @ 10.55am	request to Victor via Messenger.
11/10/17 @ 11.15am	Victor informed C/A by email.
11/10/17 @ 2.25pm	informed Phua C/A & ex: \$ 0 by email.
19/11/18 @ 2.16pm	2nd request to Victor via Messenger. (supplementary)
23/11/18 @ 12.33pm	Victor informed C/A at \$36k via Messenger.
23/11/18 @ 3.44pm	confirmed with Carmine Pinau Rg \$36000, 9 days.
	(Red \$13016.50, 27%.)

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 9

1) 27/2/2018

☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS = \$

Photos

Others

TOTAL

Report Format: MER-00Lump Sum / I.B.I: (\$ 36000)

200

10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG17019366/Gqb	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 10-10-2017	
Code : AIG			
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SKP 8816X
Policy No.	2100389641	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	06/10/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	04/10/2017	Inspection Date	06/10/2017
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1. SINGAPORE 408699		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

Survey Department Check List (Case Handler)

Reference No. CC3/ALG/17019366/Gg
Policy Type: OD / TP / TP RES / TL / EVA

SKP 8816X

Case Handler

Typist

Admin (Cath): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		

Surveyor (Gao Bui): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

✓			
---	--	--	--

Check By:

Cath 23/1/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 23 January 2018 3:44 PM
To: 'Carrine Leong'; SUR
Cc: 'Boo seng yak'; 'Nora Khai'; 'Claims'
Subject: RE: FINAL REVISION SKP8816X - OD AIG - SURVEYED 6 OCT 17

Dear Carrine,

Confirm final fig \$36,000.00 before GST and 9 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong [mailto:carrine.leong@premiumauto.com.sg]
Sent: Thursday, 18 January 2018 9:57 AM
To: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: 'Boo seng yak' <boojohnny@gmail.com>; 'Nora Khai' <nora.khai@premiumauto.com.sg>; 'Claims' <claims@premiumauto.com.sg>
Subject: RE: FINAL REVISION SKP8816X - OD AIG - SURVEYED 6 OCT 17
Importance: High

Dear Guo Qiang and all,

Please help to confirm urgently. We need to close off by today. Many thanks.

Thanks & Best Regard

Carrine Leong

Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		[] Merimen Administrator
1	05 Oct 2017 11:24	Clim Veh Model Changed			
2	05 Oct 2017 11:24	Clim Created	Reg No: SKP8816X. Policy No: 2100389641-03. Acct Date: 2017/10/04. Claim Type: S C. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA117131910		[I] Merimen Administrator
3	10 Oct 2017 09:00	Clim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.		[] CATHERINE CHONG KAI LING
4	10 Oct 2017 09:00	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)		[] CATHERINE CHONG KAI LING
5	10 Oct 2017 09:00	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[A] CATHERINE CHONG KAI LING
6	10 Oct 2017 09:00	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/10/20		[A] CATHERINE CHONG KAI LING
7	10 Oct 2017 09:00	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.		[A] CATHERINE CHONG KAI LING
8	10 Oct 2017 09:00	Clim Registration Modified	Rep:1137->200611.		[A] CATHERINE CHONG KAI LING
9	10 Oct 2017 09:00	Clim Veh Model Changed	(201410) AUDI A6 2.0 TFSI MU (A).		[A] CATHERINE CHONG KAI LING
10	10 Oct 2017 09:01	Adj Adjuster Assigned	[None] -> XING GUO QIANG		[A] CATHERINE CHONG KAI LING
11	10 Oct 2017 09:45	Adj Rpt Initiated			[A] SHIAU CHAN
12	10 Oct 2017 09:45	Clim Details Notified			[A] SHIAU CHAN
13	10 Oct 2017 10:58	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/10/20		[A] SHIAU CHAN
14	10 Oct 2017 10:58	Adj Mandate Request	Cur.Req:24540.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.		[A] SHIAU CHAN
15	10 Oct 2017 16:01	Clim Registration Modified	Init.Est.:>5,000 - 6,000. Excess: -> 0.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.		[I] Loo, Tong Shing
16	10 Oct 2017 16:01	Label Added	(20226):Coverage Confirmed.		[A] Merimen Administrator
17	11 Oct 2017 11:15	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/10/20. Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.		[I] Koh, Victor-CK
18	11 Oct 2017 11:15	Adj Mandate Set	Approved:22988.00:Re-inspection to be done for damage check and supplementary items / labour. Reinsp:Yes.		[I] Koh, Victor-CK
19	19 Jan 2018 14:13	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/10/20		[A] SHIAU CHAN
20	19 Jan 2018 14:16	Adj Mandate Request	Cur.Req:44977.50:DAMAGES CONSISTENT. REPAIRER AGREED REPAIR COST NOT MORE THAN \$36,000.00. KINDLY APPROVE ON SUPPLEMENTARY.		[A] SHIAU CHAN
21	23 Jan 2018 12:33	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2017/10/20. Mandate Remarks: Repair limit at \$36,000.00.		[I] Koh, Victor-CK
22	23 Jan 2018 12:33	Adj Mandate Set	Approved:36000.00:Repair limit at \$36,000.00. Reinsp:Adj decides.		[I] Koh, Victor-CK

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1605935	10/10/2017 09:45	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKP8816X		10.70

1/19/2018

Adjuster Immediate Advice

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 19 Jan 2018

Preliminary Advice

Vehicle No	: SKP8816X	Accident Date	: 04/10/2017
Make	: AUDI A6	Policy No.	: 2100389641-03
Assignment Date	: 10/10/2017	Excess	: S\$0.00
Date of Inspection	: 06/10/2017	Est. Duration of Repair	: 9.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (HQ) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s, front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	49,016.50	(ESTIMATE \$28,579.00 + SUPPLEMENTARY \$20,437.50)
Revised Amount	:S\$	43,425.50	
Check Items (Estimated)	:S\$	1,552.00	
Total	:S\$	44,977.50	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	122,000.00
COE / PARF Rebate	:S\$	85,269.00
Salvage Value	:S\$	
Margin for Repair	:S\$	36,731.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER AGREED REPAIR COST NOT MORE THAN \$36,000.00.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 11 October, 2017 2:25 PM
To: Claims Department; SUR
Subject: RE: SKP 8816 X Own Damage Claim (Vehicle IN)

Dear Phua,

As instructed by our client AIG insurance, please proceed to repair the insured vehicle **SKP 8816X (Excess \$0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 11 October, 2017 10:06 AM
To: Claims Department <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SKO 8816 X Own Damage Claim (Vehicle IN)

Dear Phua,

Please be informed that we are pending for insurance's approval. Once approve, we will send you an email.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Department [<mailto:claims@premiumauto.com.sg>]
Sent: Wednesday, 11 October, 2017 9:57 AM
To: 'Claims Department' <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SKO 8816 X Own Damage Claim (Vehicle IN)

Dear All,

Kindly advise approval?

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	05 Oct 2017 11:24	Clm Veh Model Changed		[] Merimen Administrator
2	05 Oct 2017 11:24	Clm Created	Reg No: SKP8816X, Policy No: 2100389641-03, Acct Date: 2017/10/04, Claim Type: SC, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Ins.Status => Notification. Created from SAS:MPA117131910	[I] Merimen Administrator
3	10 Oct 2017 09:00	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CATHERINE CHONG KAI LING
4	10 Oct 2017 09:00	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CATHERINE CHONG KAI LING
5	10 Oct 2017 09:00	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING
6	10 Oct 2017 09:00	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/10/20	[A] CATHERINE CHONG KAI LING
7	10 Oct 2017 09:00	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
8	10 Oct 2017 09:00	Clm Registration Modified	Rep:1137->200611.	[A] CATHERINE CHONG KAI LING
9	10 Oct 2017 09:00	Clm Veh Model Changed	(201410) AUDI A6 2.0 TFSI MU (A).	[A] CATHERINE CHONG KAI LING
10	10 Oct 2017 09:01	Adj Adjuster Assigned	[None] -> XING GUO QIANG	[A] CATHERINE CHONG KAI LING
11	10 Oct 2017 09:45	Adj Rpt Initiated		[A] SHIAU CHAN
12	10 Oct 2017 09:45	Clm Details Notified		[A] SHIAU CHAN
13	10 Oct 2017 10:58	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/10/20	[A] SHIAU CHAN
14	10 Oct 2017 10:58	Adj Mandate Request	Cur.Req:24540.00:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
15	10 Oct 2017 16:01	Clm Registration Modified	Init.Est.:>5,000 - 6,000. Excess: -> 0.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Loo, Tong Shing
16	10 Oct 2017 16:01	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
17	11 Oct 2017 11:15	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/10/20. Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
18	11 Oct 2017 11:15	Adj Mandate Set	Approved:22988.00:Re-inspection to be done for damage check and supplementary items / labour. Reinsp:Yes.	[I] Koh, Victor-CK

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Est Ref No	Bill Date	Acc Type	Acc Name	Est Name (Branch)	Est No	Ref No	Amount
1605935	10/10/2017 09:45	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKP8816X		10.70

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 10 Oct 2017

Preliminary Advice

Vehicle No	: SKP8816X	Accident Date	: 04/10/2017
Make	: AUDI A6	Policy No.	: 2100389641-03
Assignment Date	: 10/10/2017	Excess	: S\$0.00
Date of Inspection	: 06/10/2017	Est. Duration of Repair	: 6.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (HQ) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s & front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,579.00
Revised Amount	:S\$	22,988.00
Check Items (Estimated)	:S\$	1,552.00
Total	:S\$	24,540.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	122,000.00
COE / PARF Rebate	:S\$	85,269.00
Salvage Value	:S\$	
Margin for Repair	:S\$	36,731.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 3833J

Vehicle Details

Vehicle No.: SKP8816X

Vehicle to be Exported: No

Intended De-registration Date: 09 Oct 2017

Vehicle Make: AUDI

Vehicle Model: A6 2.0 TFSI MU (NAVIGATION)

Primary Colour: White

Manufacturing Year: 2013

Engine No.: CDN378893

Chassis No.: WAUZZZ4G4EN054174

Maximum Power Output: 132.0 kW (177 bhp)

Open Market Value: \$42,246.00

Original Registration Date: 17 Oct 2014

First Registration Date: 17 Oct 2014

Transfer Count:

Actual ARF Paid: \$46,145.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 16 Oct 2024

PARF Rebate Amount: \$34,608.00

Intended COE Rebate Details

COE No.: 2014110103000399W

COE Expiry Date: 16 Oct 2024

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$72,180.00

COE Rebate Amount: \$50,661.00

Total Rebate Amount: \$85,269.00

The information contained herein is correct as at 09 Oct 2017

OK

Land Transport  Authority (<https://www.lta.gov.sg>)

Please read through the [Privacy Statement](#), [Terms of Use](#), and [Disclaimer](#).

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) |
[Rate this e-Service \(https://www.lta.gov.sg/feedback/PublicSurvey.aspx?SurveyDetlNum=5201400011\)](https://www.lta.gov.sg/feedback/PublicSurvey.aspx?SurveyDetlNum=5201400011)

Last updated on 08 Oct 2017 at 01:03 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/10/2017 11:07
Date Of Accident	04/10/2017 19:15
Exact Location Of Accident	ALONG BRADDELL ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKP8816X
Insured/Policyholder	
Name Of Registered Owner	HENRY VICTOR ROCK
NRIC No	S7273833J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81390053
Alternative Phone No	OFFICE-81390053

Vehicle Particulars

Manufacturer	AUDI
Model	A6 C7 2.0 TFSI MU
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100389641-03
Cover Note Number	

Driver

Name of Driver	HENRY VICTOR ROCK
NRIC No	S7273833J
Date Of Birth	24/03/1972
Occupation	INDOOR
Date Of Driving Pass	20/10/2007
Driving Experience	9 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81390053
Fax Number	
Contact Number	OFFICE-81390053
Email Address	NOEMAIL

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SBT6292E

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness


Name

Phone Number

Email Address

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I was driving along Braddell Road with the intention to get into Woodleigh Park. Traffic on the left lane along Braddell Road was heavy. As I was travelling on the middle lane, I put on my left indicator light and was waiting to be given way to get into the left lane.

A light lorry (GDE 7403L) had lost control and collided with my car. My vehicle's right side was impacted. The force of the

Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : HENRY VICTOR ROCK
Period of Insurance : 17 Oct 2017 To 16 Oct 2018
Engine No. : CDN378893
Chassis No. : WAUZZZ4G4EN054174

Vehicle No. : SKP8816X
Policy No. : 2100389641-03
Endorsement No. :
Issued Date : 21 Sep 2017

ABOUT THE COVER

Make/Model : AUDI A6 C7 2.0 TFSI MU (ULTRA EDITION)
Engine Capacity/Tonnage : 1,984.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2014
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings

EXCESS

Section 1

Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

HENRY VICTOR ROCK - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125240

PREMIUM LEASING -PP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Mobile


AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSPCAR

REPUBLIC OF SINGAPORE DRIVING LICENCE



24 Oct 2007
25 Oct 2007



002114469F

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7273833J



Name

HENRY VICTOR ROCK

Race

INDIAN

Date of birth

24-03-1972

Sex

M

Country of birth

MALAYSIA


S7273833J

YOU ARE LICENSED TO DRIVE VEHICLES OF THE FOLLOWING CLASS

EXPIRY DATE

Class 3 Motor Cars=< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg 20 Oct 2007

NP 428A



Licence No: S7273833J

4736802



NRIC No: S7273833J



Date of issue

22-06-2011

20 JAN 2011 701-18

S7273833J

S7273833J

Date: 23/03/2012

No: 7054054

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0980/2017/PH
Date : 6-Oct-17

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Henry Victor Rock
Address : 2 Jalan Hajjah
01-18
Singapore 468726
Telephone : HP +65 9838 0089
Type of Claim : Own Damage Claim
Policy No. : 2100389641-03
Vehicle No : **SKP 8816 X**
Model Code : Audi A6 C7 2.0 TFSI Mu
Model / Year : Oct-14
Engine No :
Chassis No : CDN 378893
Mileage : WAUZZZ4G4EN054174
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 4-Oct-17
Place of Accident : Along Braddell Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks


: Gino Gvp - 82880282

: Not Authorised

: before part photos.

: 06/10/17

: 9 Days.


10/10/17.

Please Note

- : This estimate is based on visual inspection of the affected vehicle. .
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKP 8816 X.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy with parking aid assy.	S/N \$ 480.00	✓
2	To remove & transfer rhs front door's multi-lock system & power window devices.	S/N \$ 280.00	✓
3	To remove front fittings, dismantle & renew front bumper, rhs front fender, hinges, wing mirror assy. Repair rhs A pillar, renew both headlamps and all damaged fittings. Re-install all parts removed.	\$ 3,600.00	1500 2000
4	To respray front bumper, bonnet, lhs front fender, rhs front fender, rhs front door, rhs wing mirror cover. A pillar and hinges.	\$ 3,500.00	1850
5	To renew rhs front rim & tire, and carry out wheel alignment.	S/N \$ 280.00	✓
4	To carry out diagnostic checks.	S/N \$ 192.00	✓
TOTAL SPARE PARTS		<u>\$ 8,332.00</u>	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKP 8816 X.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER / CA	\$ 2,225.00	/ 1860
2	1 SET FIXING PARTS FOR BUMPER X BE NN	\$ 231.00	X
3	RADIATOR GRILLE COVER / m's	\$ 31.00	/ 24.08
4	GRILLE RH / m's	\$ 127.00	/ 101.20
5	COVER CAP FOR VEHICLES WITH HEADLIGHT. X NN	\$ 47.00	X
6	COVER CAP FOR VEHICLES WITH HEADLIGHT WASHER SY: S X NN	\$ 47.00	X
7	GUIDE PIECE RH / m's	\$ 31.00	/ 24.08
8	PARKING AID SENSOR X NN	\$ 244.00	X
9	SEAL RING SIDE X NN	2 \$ 28.00	X
10	HEAD LIGHT FOR GAS DISCHARGE LAMP LH & RH / CA	\$ 5,702.00	/ 4561.60
11	ADJUSTMENT ELEMENT X NN	2 \$ 76.00	X
12	COMPENSATING PIECE X NN	4 \$ 147.00	X
13	FRONT FENDER RH / Blue	\$ 1,158.00	/ 976.40
14	ATTACHMENT PARTS FOR ONE FENDER X BE NN	\$ 35.00	X
15	STONE GUARD FILM WING / m's	\$ 102.00	/ 81.60
16	FRONT BRACE WING RH X BT	\$ 70.00	/ 55.44
17	WHEEL HOUSING LINER RH X NN	\$ 238.00	X
18	STONE GUARD FILM WING DOORS LH / m's	\$ 102.00	/ 81.60
19	1 SET ATTACHMENT PARTS FOR WHEEL HOUSING LINER X NN	\$ 67.00	X
20	FRONT WHEEL SPOILER RH X re.	\$ 195.00	/ 156
TOTAL SPARE PARTS :		<u>\$ 10,903.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Condition

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKP 8816 X.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT DOOR RH / <i>buc</i>	\$ 2,910.00	/ 7328
22	FRONT STONE GUARD WING RH / <i>MC</i>	\$ 102.00	/ 81.60
23	1 SET ATTACHMENT PARTS FOR DOOR / <i>MC</i>	\$ 160.00	/ 80.80
24	OUTER DOOR SEAL / <i>MC</i>	\$ 192.00	/ 153.60
25	BONDING AGENT /	\$ 42.00	/ 33.60
26	CLEANING SOLUTION X <i>NN</i>	\$ 63.00	X
27	SOUND ABSORBER / <i>MC</i>	\$ 107.00	/ 85.60
28	DOOR HINGE RH UPPER X <i>NN</i>	\$ 91.00	X
29	DOOR HINGE RH LOWER X <i>NN</i>	\$ 91.00	X
30	EXTERIOR MIRROR HOUSING /	\$ 154.00	/ 122.80
31	TURN SIGNAL INDICATOR /	\$ 109.00	/ 87.20
32	WING MIRROR MOUNTING - RHS / <i>MC</i>	4 \$ 1,197.00	/ 957.60
33	MIRROR GLASS RH / <i>MC</i>	\$ 1,451.00	/ 1160.80
34	ALUMINIUM RIM / <i>Cut</i>	\$ 1,505.00	/ 1204
35	PIRELLI P ZERO TYRE '20' / <i>Cut</i>	\$ 670.00	//
36	SUNDRIES X <i>MC</i>	\$ 500.00	/ 290
TOTAL SPARE PARTS		\$ 20,247.00	
LABOUR CHARGES		\$ 8,332.00	
GRAND TOTAL		\$ 28,579.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

49085-96

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. PA/OD/0980/2017/PH Date 19-Oct-17 Service Advisor Chang Pages 1 Regn No SKP 8816 K Model No Audi A6 C7 2.0 TFSI MU	
Quantity	Description	Unit Price	Amount
Labours			
1	To suspend engine, dismantle front suspension assy. S/N Inspect damages and renew accordingly.	\$ 2,800.00	/
TOTAL LABOURS :		\$ 2,800.00	
Parts			
1	FRONT UPPER LINK - RH FRT	\$ 462.00	369.60
2	FRONT UPPER LINK - RH REAR	\$ 462.00	369.60
3	FRONT LOWER LINK - RH	\$ 832.00	665.60
4	FRONT WISHBONE LINK - RH	\$ 462.00	369.60
5	FRONT SWIVEL JOINT - RH	\$ 157.00	125.60
6	FRONT WHEEL BEARING - RH	\$ 652.00	521.60
7	FRONT SUSPENSION FORKS - RH	\$ 194.00	155.20
8	FRONT COUPLING ROD - RH	\$ 121.00	96.40
9	FRONT GAS SHOCK ABSORBER - RH	\$ 447.00	357.60
10	FRONT SUPPORT FRAME	\$ 3,301.00	2640.80
11	FRONT SUPPORT FRAME BOLT SET	\$ 174.00	139.20
12	STEERING GEAR	\$ 5,882.00	4705.60
13	TIE ROD END - RH	\$ 149.00	119.20
14	FRONT WHEEL BEARING HOUSING - RH	\$ 962.00	769.20
TOTAL PARTS :		\$ 14,257.00	
Grand Total :		\$ 17,057.00	

15. Gas Bulb 393.50
 16. Ballast 2006.00
 17. power Module 457.00

314.50
 1603.20
 786.40

For Premium Automobiles Pte Ltd



Authorised Signature

14106 96

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0980/2017/PH
Date : 6-Oct-17

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120



Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr.Henry Victor Rock
Address : 2 Jalan Hajjah
01-18
Singapore 468726
Telephone : HP +65 9838 0089
Type of Claim : Own Damage Claim
Policy No. : 2100389641-03
Vehicle No : **SKP 8816 X**
Model Code : Audi A6 C7 2.0 TFSI Mu
Model / Year : Oct-14
Engine No :
Chassis No : CDN 378893
Mileage : WAUZZZ4G4EN054174
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 4-Oct-17
Place of Accident : Along Braddell Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKP 8816 X.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy with parking aid assy.	S/N \$ 480.00	\$ 480.00
2	To remove & transfer rhs front door's multi-lock system & power window devices.	S/N \$ 280.00	\$ 280.00
3	To remove front fittings,dismantle & renew front bumper,rhs front fender,hinges,wing mirror assy.Repair rhs A pillar,renew both headlamps and all damaged fittings.Re-install all parts removed. <i>(Front fender - 1,000, door - 500 , 2 Headlamp - 500.00 =\$2000.00</i>	\$ 3,600.00	\$ 2,000.00
4	To respray front bumper ,bonnet,lhs front fender,rhs front fender,rhs front door,rhs wing mirror cover.A pillar and hinges.	\$ 3,500.00	\$ 1,850.00
5	To renew rhs front rim & tire,and carry out wheel alignment.	S/N \$ 280.00	\$ 280.00
4	Added labour charges	\$ 2,800.00	\$ 2,800.00
5	To carry out diagnostic checks.	S/N \$ 192.00	\$ 192.00
TOTAL SPARE PARTS		\$ 11,132.00	\$ 7,882.00

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKP 8816 X.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,225.00	\$ 1,860.00
2	1 SET FIXING PARTS FOR BUMPER	\$ 231.00	
3	RADIATOR GRILLE COVER	\$ 31.00	\$ 24.08
4	GRILLE RH	\$ 127.00	\$ 101.20
5	COVER CAP FOR VEHICLES WITH HEADLIGHT.	\$ 47.00	
6	COVER CAP FOR VEHICLES WITH HEADLIGHT WASHER	\$ 47.00	
7	GUIDE PIECE RH	\$ 31.00	\$ 24.08
8	PARKING AID SENSOR	\$ 244.00	
9	SEAL RING SIDE	2 \$ 28.00	
10	HEAD LIGHT FOR GAS DISCHARGE LAMP LH & RH	2 \$ 5,702.00	\$ 4,561.60
11	ADJUSTMENT ELEMENT	2 \$ 76.00	
12	COMPENSATING PIECE	4 \$ 147.00	
13	FRONT FENDER RH	\$ 1,158.00	\$ 926.40
14	ATTACHMENT PARTS FOR ONE FENDER	\$ 35.00	
15	STONE GUARD FILM WING	\$ 102.00	\$ 81.60
16	FRONT BRACE WING RH	\$ 70.00	\$ 55.44
17	WHEEL HOUSING LINER RH	\$ 238.00	
18	STONE GUARD FILM WING DOORS LH	\$ 102.00	\$ 81.60
19	1 SET ATTACHMENT PARTS FOR WHEEL HOUSING LINE	\$ 67.00	
20	FRONT WHEEL SPOILER RH	\$ 195.00	\$ 156.00
TOTAL SPARE PARTS		\$ 10,903.00	\$ 7,872.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKP 8816 X.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
			\$ 7,872.00
21	FRONT DOOR RH	\$ 2,910.00	\$ 2,328.00
22	FRONT STONE GUARD WING RH	\$ 102.00	\$ 81.60
23	1 SET ATTACHMENT PARTS FOR DOOR	\$ 160.00	\$ 80.80
24	OUTER DOOR SEAL	\$ 192.00	\$ 153.60
25	BONDING AGENT	\$ 42.00	\$ 33.60
26	CLEANING SOLUTION	\$ 63.00	
27	SOUND ABSORBER	\$ 107.00	\$ 85.20
28	DOOR HINGE RH UPPER	\$ 91.00	
29	DOOR HINGE RH LOWER	\$ 91.00	
30	EXTERIOR MIRROR HOUSING	\$ 154.00	\$ 122.80
31	TURN SIGNAL INDICATOR	\$ 109.00	\$ 86.80
32	WING MIRROR MOUNTING - RHS	4 \$ 1,197.00	\$ 957.60
33	MIRROR GLASS RH	\$ 1,451.00	\$ 1,160.80
34	ALUMINIUM RIM	\$ 1,505.00	\$ 1,204.00
35	PIRELLI P ZERO TYRE '20'	\$ 670.00	\$ 670.00
36	<i>Added parts - see attached</i>	\$ 17,637.50	\$ 14,106.96
38	SUNDRIES	\$ 500.00	\$ 290.00
	TOTAL SPARE PARTS	\$ 37,884.50	\$ 29,233.76
	LABOUR CHARGES	\$ 11,132.00	\$ 7,882.00
	GRAND TOTAL	\$ 49,016.50	\$ 37,115.76

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. PA/OD/0980/2017/PH Date 19-Oct-17 Service Advisor Chang Pages 1 Regn No SKP 8816 K Model No Audi A6 C7 2.0 TFSI MU	
Quantity	Description	Unit Price	Amount
Labours			
1	To suspend engine, dismantle front suspension assy. S/N Inspect damages and renew accordingly.	\$ 2,800.00	\$ 2,800.00
	TOTAL LABOURS :	\$ 2,800.00	\$ 2,800.00
Parts			
1	FRONT UPPER LINK - RH FRT	\$ 462.00	\$ 369.60
2	FRONT UPPER LINK - RH REAR	\$ 462.00	\$ 369.60
3	FRONT LOWER LINK - RH	\$ 832.00	\$ 665.60
4	FRONT WISHBONE LINK - RH	\$ 462.00	\$ 369.60
5	FRONT SWIVEL JOINT - RH	\$ 157.00	\$ 125.60
6	FRONT WHEEL BEARING - RH	\$ 652.00	\$ 521.60
7	FRONT SUSPENSION FORKS - RH	\$ 194.00	\$ 155.20
8	FRONT COUPLING ROD - RH	\$ 121.00	\$ 96.40
9	FRONT GAS SHOCK ABSORBER - RH	\$ 447.00	\$ 357.60
10	FRONT SUPPORT FRAME	\$ 3,301.00	\$ 2,640.80
11	FRONT SUPPORT FRAME BOLT SET	\$ 174.00	\$ 136.96
12	STEERING GEAR	\$ 5,882.00	\$ 4,705.60
13	TIE ROD END - RH	\$ 149.00	\$ 119.20
14	FRONT WHEEL BEARING HOUSING - RH	\$ 962.00	\$ 769.20
15	GAS BULD	\$ 393.50	\$ 314.80
16	BALLAST 2PCS	\$ 2,004.00	\$ 1,603.20
17	POWER MODULE 2PCS	\$ 983.00	\$ 786.40
	TOTAL PARTS :	\$ 17,637.50	\$ 14,106.96
	TOTAL LABOUR	\$ 2,800.00	\$ 2,800.00
	Grand Total :	\$ 20,437.50	\$ 16,906.96

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKP 8816 X

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0980/2017/MAS

17 Feb 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SKP 8816 X, Audi A6 C7 2.0 TFSI MU

With reference to the above-mentioned vehicle, no **SKP 8816 X**, claimant, **Mr. Henry Victor Rock**, please find the related document per attached.

1. A copy of the Original invoice no. 85012130 – S\$38,520.00
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SKP 8816 X

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore

281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre

281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre

55 Ubi Road 1
Singapore 408055
Telephone 6841 1183
Telefax 6841 1183

Customer Service

Service Appointment
Breakdown Service

6366 2323
9828 1233

customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg No. 199902271W
GST Reg. No. 199902271W

Page 1 17:27

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012130 Date: 06/02/2018 Order: SKP8816X Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SKP8816X Regn Date: 17/10/2014 Mileage: 72937 WIP NO: 40716

Model: A6 C7 2.0 TFSI MU Chassis: WAUZZZ4G4EN054174 Engine: CDN 378893 Dept: U

VSU No:

You have been assisted by:- UB-Carrine (11)

		Details	Qty	Unit Price	Amount
S	SUBLET	To carry out contractual LIMIT-sum repair basis as agreed	1.00	36,000.00	36,000.00

Parts 0.00
Labour 0.00
Sublet 36,000.00
Menus 0.00
Lubricant 0.00



Sub-Total	36,000.00
7% GST	2,520.00
Grand Total	38,520.00

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SKP 8816 X

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0980/2017/PH
26 Oct 2017

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A6 C7 2.0 TFSI MU

Vehicle Chassis No. : WAUZZZ4G4EN054174

Vehicle Regn No. : **SKP 8816 X**

Vehicle Mileage : **22937 KM**

Vehicle Owner : Mr Henry Victor Rock

Certificate No : 2100389641 - 03

Policy Excess : NA

Accident Date : 04 October 2017

Place : Along Braddell Road

Repair Cost : \$ 38,520.00

WIP No. : 40716

Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733


Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :



26/10/17

REPUBLIC OF SINGAPORE DRIVING LICENCE



002114460F

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7273833J



Name
HENRY VICTOR ROCK

Race
INDIAN

Date of birth
24-03-1972

Sex
M

Country of birth
MALAYSIA

S7273833J

Class 3 Motor Cars < 3000kg with < 7 passengers, exclusive of the driver; and other motor vehicles < 2500kg 20 Oct 2007

NP 428A

Licence No: S7273833J

4736602



NRIC No. S7273833J



Date of issue
22-06-2011

2011 MAR 11 11:11 701-18

57273833

Date: 23/03/2012 No: 7054054

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : HENRY VICTOR ROCK
Period of Insurance : 17 Oct 2017 To 16 Oct 2018
Engine No. : CDN378893
Chassis No. : WAUZZZ4G4EN054174

Vehicle No. : SKP8816X
Policy No. : 2100389641-03
Endorsement No. :
Issued Date : 21 Sep 2017

ABOUT THE COVER

Make/Model : AUDI A6 C7 2.0 TFSI MU (ULTRA EDITION)
Engine Capacity/Tonnage : 1,984.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2014
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :
 a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.
 You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

HENRY VICTOR ROCK - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

24125240

EMIUM LEASING -PP

1 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

1GAPORE 159938

Insured by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SSPCAR

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Oct 2017 09:45		10 Oct 2017 09:00 Edit Adj Rpt	S\$37,115.76 Edit Estimates	S\$37,115.76 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HENRY VICTOR ROCK, ID: S7273833J, Tel: +6581390053, Email: NOEMAIL		
Vehicle Reg. No.:	SKP8816X	Date of Loss:	04/10/2017 19:00 - :59
Claim Type:	OD / 8845794374SG	Policy/Cover Note No.:	2100389641-03 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 20/10/2017]		
Driver/Custodian:	HENRY VICTOR ROCK (45 / Male), NRIC: S7273833J, Tel: +6581390053		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG (23/01/2018): Alert - Adj Mandate Approved (S\$36000.00) - SKP8816X - Claim Handler: Loo, Tong ...
- AIG_SG (11/10/2017): Alert - Adj Mandate Approved (S\$22988.00) - SKP8816X - Claim Handler: Loo, Tong ...
- AIG_SG (10/10/2017): SKP8816X / OD / 04/10/2017 / Coverage & Excess update

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKP8816X (8845794374SG)**

OD

Oct 4 2017 7:15PM

[HENRY VICTOR ROCK]

Premium Automobiles Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#) ▼

Assessment Reports			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/10/17 10:58	Adjuster Immediate Advice	 Load HTM	☐
2	19/01/18 14:13	Adjuster Immediate Advice	 Load HTM	☐
Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/10/17 09:41	General View	 Load JPG	☒
2	10/10/17 09:41	General View	 Load JPG	☒
3	10/10/17 09:41	General View	 Load JPG	☒
4	10/10/17 09:41	General View	 Load JPG	☒
5	10/10/17 09:41	General View	 Load JPG	☒
6	10/10/17 09:41	General View	 Load JPG	☒
7	10/10/17 09:41	General View	 Load JPG	☒
8	10/10/17 09:41	General View	 Load JPG	☒
9	10/10/17 09:41	General View	 Load JPG	☒
10	10/10/17 09:41	General View	 Load JPG	☒
11	10/10/17 09:41	General View	 Load JPG	☒
12	10/10/17 09:41	General View	 Load JPG	☒
13	10/10/17 09:41	General View	 Load JPG	☒
14	10/10/17 09:41	General View	 Load JPG	☒
15	10/10/17 09:41	General View	 Load JPG	☒
16	10/10/17 09:41	General View	 Load JPG	☒
17	10/10/17 09:41	General View	 Load JPG	☒
18	10/10/17 09:41	General View	 Load JPG	☒
19	10/10/17 09:41	General View	 Load JPG	☒
20	10/10/17 09:41	General View	 Load JPG	☒
21	10/10/17 09:41	General View	 Load JPG	☒
22	10/10/17 09:41	General View	 Load JPG	☒
23	10/10/17 09:41	General View	 Load JPG	☒
24	10/10/17 09:41	General View	 Load JPG	☒
25	10/10/17 09:41	General View	 Load JPG	☒
26	10/10/17 09:41	General View	 Load JPG	☒
27	10/10/17 09:41	General View	 Load JPG	☒
28	10/10/17 09:41	General View	 Load JPG	☒
29	19/01/18 10:09	Reinspection Photo	 Load JPG	☒
30	19/01/18 10:09	Reinspection Photo	 Load JPG	☒
31	19/01/18 10:09	Reinspection Photo	 Load JPG	☒

32	19/01/18 10:09	Reinspection Photo	1	Load JPG	☒
33	19/01/18 10:09	Reinspection Photo	1	Load JPG	☒
34	19/01/18 10:09	Reinspection Photo	1	Load JPG	☒
35	19/01/18 10:09	Reinspection Photo	1	Load JPG	☒
36	19/01/18 10:09	Reinspection Photo	1	Load JPG	☒
37	19/01/18 10:09	Reinspection Photo	1	Load JPG	☒
38	19/01/18 10:09	Reinspection Photo	1	Load JPG	☒
39	19/01/18 10:09	Reinspection Photo	1	Load JPG	☒
40	19/01/18 10:09	Reinspection Photo	1	Load JPG	☒
41	19/01/18 10:09	Reinspection Photo	1	Load JPG	☒
42	19/01/18 10:09	Reinspection Photo	1	Load JPG	☒
43	19/01/18 10:09	Reinspection Photo	1	Load JPG	☒
44	19/01/18 10:09	Reinspection Photo	1	Load JPG	☒
45	19/01/18 10:09	Reinspection Photo	1	Load JPG	☒
46	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
47	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
48	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
49	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
50	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
51	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
52	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
53	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
54	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
55	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
56	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
57	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
58	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
59	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
60	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
61	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
62	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
63	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
64	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
65	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
66	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
67	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
68	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
69	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
70	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
71	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
72	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
73	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
74	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒
75	19/01/18 10:10	Reinspection Photo	1	Load JPG	☒

Documentation

1 per page ▼



No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/10/17 09:40	Singapore Accident Statement	1	Load PDF	
2	10/10/17 09:40	Certificate of Insurance	1	Load PDF	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG17019366/GQBE2

Date: 26/02/2018

REFERENCE

Insured/Claimant:	HENRY VICTOR ROCK	Policy No:	2100389641-03	
Date of Loss:	04/10/2017	Nature of Claim:	OD	Claim No: 8845794374SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP8816X	Engine No:	CDN378893
Make & Model:	AUDI A6, 2.0 TFSI MU (A)	Chassis No:	WAUZZZ4G4EN054174
Reg. Date:	17/10/2014 (Man. Year: 2013)	Odometer:	0 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$122,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R20	Rear Tyre Size:	255/35 R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,353.96	29,233.76	5,120.20	14.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,132.00	7,882.00	3,250.00	29.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	45,485.96	37,115.76	8,370.20	18.40
+ GST 7.00/7.00% (\$\$)	3,184.02	2,598.10	585.92	18.40
Nett Amount (\$\$)	48,669.98	39,713.86	8,956.12	18.40

INSPECTION

Date of Assignment:	10/10/2017		
Date Inspected:	06/10/2017	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	9.0 days		

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Cut	2,225.00 FS	*1,860.00 FS
2	1	*SET FIXING PARTS FOR BUMPER	Not Necessary	231.00 FS	*- FS
3	1	*RADIATOR GRILLE COVER	Missing	31.00 FS	*24.08 FS
4	1	*GRILLE RH	Missing	127.00 FS	*101.20 FS
5	1	*COVER CAP FOR VEHICLES WITH HEADLIGHT	Not Necessary	47.00 FS	*- FS
6	1	*COVER CAP FOR VEHICLE WITH HEADLIGHT WASHER SYSTEM	Not Necessary	47.00 FS	*- FS
7	1	*GUIDE PIECE RH	Necessary	31.00 FS	*24.08 FS
8	1	*PARKING AIR SENSOR	Not Necessary	244.00 FS	*- FS
9	2	*SEAL RING SIDE	Not Necessary	28.00 FS	*- FS
10	2	*HEAD LIGHT FOR GAS DISCHARGE LAMP LH & RH	Cut	5,702.00 FS	*4,561.60 FS
11	2	*ADJUSTMENT ELEMENT	Not Necessary	76.00 FS	*- FS
12	4	*COMPENSATING PIECE	Not Necessary	147.00 FS	*- FS
13	1	*FRONT FENDER RH	Buckled	1,158.00 FS	*926.40 FS
14	1	*ATTACHMENT PARTS FOR ONE FENDER	Not Necessary	35.00 FS	*- FS
15	1	*STONE GUARD FILM WING	Necessary	102.00 FS	*81.60 FS
16	1	*FRONT BRACE WING RH	Bent	70.00 FS	*55.44 FS
17	1	*WHEEL HOUSING LINER RH	Not Necessary	238.00 FS	*- FS
18	1	*STONE GUARD FILM WING DOORS LH	Necessary	102.00 FS	*81.60 FS
19	1	*SET ATTACHMENT PARTS FOR WHEEL HOUSING LINER	Not Necessary	67.00 FS	*- FS
20	1	*FRONT WHEEL SPOILER RH	Deformed	195.00 FS	*156.00 FS
21	1	*FRONT DOOR RH	Buckled	2,910.00 FS	*2,328.00 FS
22	1	*FRONT STONE GUARD WING RH	Necessary	102.00 FS	*81.60 FS
23	1	*SET ATTACHMENT PARTS FOR DOOR	Necessary	160.00 FS	*80.80 FS
24	1	*OUTER DOOR SEAL	Necessary	192.00 FS	*153.60 FS
25	1	*BONDING AGENT	Necessary	42.00 FS	*33.60 FS
26	1	*CLEANING SOLUTION	Not Necessary	63.00 FS	*- FS
27	1	*SOUND ABSORBER	Necessary	107.00 FS	*85.20 FS
28	1	*DOOR HINGE RH UPPER	Not Necessary	91.00 FS	*- FS
29	1	*DOOR HINGE RH LOWER	Not Necessary	91.00 FS	*- FS
30	1	*EXTERIOR MIRROR HOUSING	Distorted	154.00 FS	*122.80 FS
31	1	*TURN SIGNAL INDICATOR	Distorted	109.00 FS	*86.80 FS
32	4	*WING MIRROR MOUNTING - RHS	Distorted	1,197.00 FS	*957.60 FS
33	1	*MIRROR GLASS RH	Missing	1,451.00 FS	*1,160.80 FS
34	1	*ALUMINIUM RIM	Cut	1,505.00 FS	*1,204.00 FS
35	1	*SUNDRIES	Necessary	500.00 FS	*290.00 FS
36	1	*FRONT UPPER LINK - RH FRT	Bent	369.60 FS	*369.60 FS
37	1	*FRONT UPPER LINK - RH REAR	Bent	369.60 FS	*369.60 FS
38	1	*FRONT LOWER LINK - RH	Not Necessary	665.60 FS	*665.60 FS
39	1	*FRONT WISHBONE LINK - RH	Bent	369.60 FS	*369.60 FS
40	1	*FRONT SWIVEL JOINT	Bent	125.60 FS	*125.60 FS
41	1	*FRONT WHEEL BEARING - RH	Bent	521.60 FS	*521.60 FS
42	1	*FRONT SUSPENSION FORKS - RH	Bent	155.20 FS	*155.20 FS
43	1	*FRONT COUPLING ROD - RH	Bent	96.40 FS	*96.40 FS
44	1	*FRONT GAS SHOCK ABSORBER - RH	Bent	357.60 FS	*357.60 FS
45	1	*FRONT SUPPORT FRAME	Bent	2,640.80 FS	*2,640.80 FS
46	1	*SET FRONT SUPPORT FRAME BOLT	Bent	136.96 FS	*136.96 FS
47	1	*STEERING GEAR	Bent	4,705.60 FS	*4,705.60 FS
48	1	*FRONT WHEEL BEARING HOUSING - RH	Bent	769.20 FS	*769.20 FS
49	1	*GAS BULB	Not Working	314.80 FS	*314.80 FS
50	1	*BALLAST	Not Working	1,603.20 FS	*1,603.20 FS
51	1	*POWER MODULE	Not Working	786.40 FS	*786.40 FS

Report was unsubmitted during this print-out.

2/26/2018

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*TIE ROD END - RH	Bent	119.20 FS	*119.20 FS
53	1		*PIRELLI P ZERO TYRE 20	Cut	670.00 FS	*670.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					34,353.96	29,233.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY WITH PARKING AID ASSY	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM & POWER WINDOW DEVICES	New	280.00	280.00
3	TO REMOVE FRONT FITTINGS, DISMANTLE & RENEW FRONT BUMPER, RHS FRONT FENDER, HINGES, WING MIRROR ASSY. REPAIR RHS A-PILLAR, RENEW BOTH HEADLAMPS AND ALL DAMAGED FITTINGS. RE-INSTALL ALL PARTS REMOVED	New	3,600.00	2,000.00
4	TO RESPRAY FRONT BUMPER, BONNET, LHS FRONT FENDER, RHS FRONT FENDER, RHS FRONT DOOR, RHS WING MIRROR COVER. A PILLAR AND HINGES	New	3,500.00	1,850.00
5	TO RENEW RHS FRONT RIM & TIRE, AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
7	TO SUSPEND ENGINE, DISMANTLE FRONT SUSPENSION ASSY. INSPECT DAMAGES AND RENEW ACCORDINGLY	New	2,800.00	2,800.00
Gross Labour Cost (S\$)			11,132.00	7,882.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >