

22/03/2002

AS REC. BY:

REF: CS / GAL17019379 / THb

Special Instruction:

Survivor: Taufiq

ASSIGNMENT (Office)

From (Person): Shuron Ng

of

GAL

Date/Time: 10.10.2017 1:37pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 3201T

Insured:

at Workshop m/s

Edwin Garage

Tel:

9785 6612

of

5032 AMK Ind Park 2 #01-295

Policy No:

Claim No:

Sum Insured:

Excess:

TBA

Make of Veh:

(Client's Record)

D.O.A. 10.10.2017

CA / REV / REP. / REV 24 HRS

12.10.2017

H.O.D. Endorsement:

Date/Time:

10.10.2017

1:48pm

Person Contacted:

Edwin

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLF 3201T - X

1. Lump Sum \$247007 (Red: 12612.52 ; 42%)

REF: GAL

ASSIGNMENT

From:

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess: TBA

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: ☒ M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

L/Bal.

D.O.A.

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

☒

Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend .(\$

) S + RS. SI

) Photos

) Others

)

TOTAL

450

450

Catherine Chong (LKK Auto)

From: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Sent: Tuesday, 10 October, 2017 1:37 PM
To: sur@lkkauto.com
Cc: assignments@lkkauto.com
Subject: FW: SLF3210T OD claim

Importance: High

Hi Catherine

Please conduct OD survey and revert.

GIA report and estimates please obtain from workshop.

Excess : TBA

Regards
Sharon
Great American

-----Original Message-----

From: Edwin SgGarage [mailto:edwin@sagarage.com]
Sent: Tuesday, October 10, 2017 11:05 AM
To: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Subject: SLF3210T OD claim

Hi Sharon

As spoken, pls assign surveyor down to take photo for OE. Estimate has been prepared

Edwin
97856612

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/10/2017 11:10
Date Of Accident	10/10/2017 06:45
Exact Location Of Accident	JUNCTION OF AMK STREET 44 AND AMK AVE 10
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF3201T
Insured/Policyholder	
Name Of Registered Owner	YEO KAH KIAT
NRIC No	S8851437H
Email Address	YEO_KAHKIAT88@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-98353321
Alternative Phone No	OFFICE-98353321

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MOMVP000002581-00-000
Cover Note Number	

Driver

Name of Driver	YEO KAH KIAT
NRIC No	S8851437H
Date Of Birth	19/12/1988
Occupation	INDOOR
Date Of Driving Pass	26/06/2009
Driving Experience	8 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98353321
Fax Number	(LOCAL) +65-98353321
Contact Number	OFFICE-98353321
Email Address	YEO_KAHKIAT88@HOTMAIL.COM

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 13 October, 2017 5:57 PM
To: 'Ng, Sharon'; SUR; assignments
Subject: RE: TP survey to SFW894U - Insd: SLF3201T DOA: 10/10/17
Attachments: CSGAI17019379T1tb.pdf

Dear Sharon,

Enclosed herewith preliminary advice of SLF 3201T.
We are pending for repair cost from repairer.

We have not authorise repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 12 October, 2017 5:23 PM
To: 'Ng, Sharon' <Sharon.Ng@sg.gaig.com>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: TP survey to SFW894U - Insd: SLF3201T DOA: 10/10/17

Dear Sharon,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng, Sharon [<mailto:Sharon.Ng@sg.gaig.com>]
Sent: Thursday, 12 October, 2017 4:42 PM
To: 'SUR' <sur@lkkauto.com>; assignments@lkkauto.com
Subject: TP survey to SFW894U - Insd: SLF3201T DOA: 10/10/17

Dear Sir

OD surveyed by your office.

Please conduct pre-repair to SFW894U.

Details as follows:-



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: -

Date: 13th October 2017

Our Ref: CS/GAI17019379/T1tb

The Motor Claims Department
Great American Insurance Company

Attn: Sharon

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SLF 3201T


We thank you for the instruction on 10/10/2017.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/10/2017 at the premises of M/s EDWIN GARAGE and have the following to report:-

Workshop Estimate Amount	: S\$ <u>38,440.20</u>
Revised Estimate Amount	: S\$ <u>20,326.14</u>
"Check" Items Amount	: S\$ <u>5,691.64</u>
Market Value	: S\$ <u>85,000.00</u>
Salvage Value	: S\$ <u>54,945.00</u>
Nett Value	: S\$ <u>30,055.00</u>

Description of Damage:

The vehicle sustained damages at the front o/s portion. The chassis frame affected due to collision.



Comments/ Present Status:

Damages consistent.

Pending repair cost from repairer.

We have NOT authorise repair.

Yours faithfully

Taufikh
Automotive Assessor

Denise Tay (LKKAuto)

To: Admin-D (LKKAuto); 'Insurance SgGarage'; SUR
Cc: assignments
Subject: RE: ESTIMATE FOR SLF3201T HONDA VEZEL
Attachments: SLF 3201T ESTIMATE.pdf

Dear Sir,

Refer to our conversation, attached the estimate of our surveyor marking.

Based on the above calculation,

Parts will apply the trade discount at 20% + labour = subtotal and Lump sum at 20%.

As instructed by our client, please proceed to repair the insured vehicle SLF 3201T (Excess \$TBA/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,

#02-25 | S(408933) -----Original Message-----

From: Admin-D (LKKAuto)

Sent: Monday, 16 October, 2017 10:41 AM

To: 'Insurance SgGarage' <insurance@snggarage.com>; SUR <sur@lkkauto.com>

Cc: assignments <assignments@lkkauto.com>

Subject: RE: ESTIMATE FOR SLF3201T HONDA VEZEL

Dear Edwin,

Thank you for your email.

Dear Denise / Shiau Chan,

FYNA. Our Ref: CS/GAI17019379/T1tb

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Insurance SgGarage [mailto:insurance@snggarage.com]

Sent: Monday, 16 October, 2017 10:06 AM

To: assignments@lkkauto.com

Subject: ESTIMATE FOR SLF3201T HONDA VEZEL

Attached is the ESTIMATE FOR SLF3201T HONDA VEZEL.

Highlighted in yellow are those item newly added for resurvey.

Below are pending item which LKK surveyor said to be resurvey after start work.

Celine Fong (LKKAUTO)

From: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Sent: Wednesday, 25 October, 2017 10:15 AM
To: KKLau; Bryan Ang (LKKAUTO)
Cc: Denise Tay (LKKAUTO); Lam, Donovan; Ngian, Kelvyna
Subject: URGENT - ESTIMATE FOR SLF3201T HONDA VEZEL - Our ref: CLMOMVP000000392

Importance: High

Dear Mr Lau & Bryan

Please see email from our agent, specifically comments about your company.

Can you help us look into this urgently? How did the lump sum \$16,250 figure comes about? The amount was not reflected in our mandate approval too.

Thanks & Best Regards,

Sharon Ng, Assistant Manager, Claims | P. +65 6804 7845 | Fax. +65 6235 3354 sharon.ng@sg.gaig.com



Claims Division | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



Moody's
A1 (Good)
Assigned June 15, 2015

Standard & Poor's
A+ (Strong)
Assigned March 2, 2016

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: Denise Tay (LKKAUTO) [<mailto:denisetay@lkkauto.com>]
Sent: Wednesday, October 25, 2017 9:45 AM
To: Team 2 <admin1@oneaug.com>
Cc: edwin@sagarage.com; SUR <sur@lkkauto.com>; Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>; Insurance SgGarage <insurance@sagarage.com>
Subject: RE: ESTIMATE FOR SLF3201T HONDA VEZEL

Dear Glen,

We will explain to the workshop.

Denise Tay (LKKAUTO)

To: 'Insurance SgGarage'
Cc: Admin-D (LKKAUTO); SUR; assignments
Subject: RE: ESTIMATE FOR SLF3201T HONDA VEZEL
Attachments: PAGE 1.tif; PAGE 2.tif; PAGE 3.tif

Dear Sir,

approval
As instructed by our client, please proceed to repair the insured vehicle **SLF3201T (Excess \$400/-)**. *based* Based on the first approval checklist (with max cap at SGD28k). Reimbursement to be based on itemised invoice against checklist and photos of repaired vehicle.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

The final repair cost is subjected to our *surveyor* ~~surveyor's~~ finalisation upon completion of repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Insurance SgGarage [mailto:insurance@sugarage.com]
Sent: Tuesday, 24 October, 2017 4:36 PM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Cc: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: Re: ESTIMATE FOR SLF3201T HONDA VEZEL

Dear Denise,

Pls explain how do you derive the figure of \$16,2500 with my submitted estimate of \$36,000.

Secondly , in the email you stated lump sum but on the phone you mentioned part by part after change out. Pls verify.

Edwin
97856612

> On 24 Oct 2017, at 4:01 PM, Denise Tay (LKKAUTO) <denisetay@lkkauto.com> wrote:

- >
- > Dear Sir,
- >
- > Refer to our conversation,
- >
- > Basing on the estimate calculation, the current mandate approval is at Lump sum \$16,250.00, check item to be confirm upon dismantling.
- >
- > Parts will apply the trade discount at 20% + labour = subtotal and Lump sum at 20%.
- >
- > As instructed by our client, please proceed to repair the insured vehicle SLF 3201T (Excess \$TBA/-).
- >
- > If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.
- >
- > All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.
- >

Denise Tay (LKKAUTO)

To: Admin-D (LKKAUTO); 'Insurance SgGarage'; SUR
Cc: assignments
Subject: RE: ESTIMATE FOR SLF3201T HONDA VEZEL
Attachments: SLF 3201T ESTIMATE_0001.pdf

Dear Sir,

Refer to our conversation,

Basing on the estimate calculation, the current mandate is at Lump sum \$16,250.00, check item to be confirm upon dismantling.

base on market practice

(Parts will apply the trade discount at 20% + labour = subtotal and Lump sum at 20%.)

As instructed by our client, please proceed to repair the insured vehicle SLF 3201T (Excess \$TBA/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,

#02-25 | S(408933) -----Original Message-----

From: Admin-D (LKKAUTO)

Sent: Monday, 16 October, 2017 10:41 AM

To: 'Insurance SgGarage' <insurance@snggarage.com>; SUR <sur@lkkauto.com>

Cc: assignments <assignments@lkkauto.com>

Subject: RE: ESTIMATE FOR SLF3201T HONDA VEZEL

Dear Edwin,

Thank you for your email.

Dear Denise / Shiau Chan,

FYNA. Our Ref: CS/GAI17019379/T1tb

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Insurance SgGarage [mailto:insurance@snggarage.com]

Sent: Monday, 16 October, 2017 10:06 AM

To: assignments@lkkauto.com

Subject: ESTIMATE FOR SLF3201T HONDA VEZEL

Attached is the ESTIMATE FOR SLF3201T HONDA VEZEL.

Highlighted in yellow are those item newly added for resurvey.

Below are pending item which LKK surveyor said to be resurvey after start work.

From: Team 2 <admin1@oneaug.com>
Sent: Wednesday, 25 October, 2017 9:26 AM
To: Denise Tay (LKKAuto)
Cc: edwin@sgarage.com; SUR; kervyna.ngiam@sg.gaig.com; Insurance SgGarage; Andrew.Teo@sg.gaig.com; YuanLong.Wong@sg.gaig.com
Subject: Re: ESTIMATE FOR SLF3201T HONDA VEZEL

Hi Denise

We are the corporate agency representing Great American and our insured is the owner of the subject Vezel.

We will need you to send instructions to authorise SGgarage to repair the subject vehicle basis the first approved checklist (with max cap at SGD28k before gst and excluding policy benefits eg transport allowance). Repairs are also to be done without interference from LKK. Reimbursement to be based on itemised invoice against checklist and photos of repaired vehicle.

LKK has caused the delay to these repairs by not fully understanding the scope of works and flip flopping on terms.

If we do not hear from you by 10am today. We will take it that LKK is agreeable to the above and will warrant the same to Great American.

Thank you.

Kind regards
Glen

Glenford Tan
One August Risk Management Pte Ltd
+65 9794 2887

On 25 Oct 2017, at 01:10, Insurance SgGarage <insurance@sgarage.com> wrote:

Dear Glenn,

PDF file (SLF 3201T ESTIMATE_0001.pdf) is the original approved checklist in the first survey done by LKK surveyor. (Handwritten)

PDF file (Accident Estimate new.pdf) is the updated check list filtered and the additional item proposed to be resurveyed later on throughout the course of repair)

There is ambiguity in the formulae proposed by LKK (trade discount at 20% + labour = subtotal and Lump sum at 20%). Does that means a total of 40% reduction?

Denise Tay (LKKAuto)

To: 'Insurance SgGarage'
Cc: Admin-D (LKKAuto); SUR; assignments
Subject: RE: ESTIMATE FOR SLF3201T HONDA VEZEL
Attachments: PAGE 1.tif; PAGE 2.tif; PAGE 3.tif

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **GBD 366A (Excess \$400/-)**.

the subject vehicle basis the first approved checklist (with max cap at SGD28k) ~~before gst and excluding policy benefits eg transport allowance~~

Reimbursement to be based on itemised invoice against checklist and photos of repaired vehicle.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Insurance SgGarage [mailto:insurance@sggarage.com]
Sent: Tuesday, 24 October, 2017 4:36 PM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Cc: Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: Re: ESTIMATE FOR SLF3201T HONDA VEZEL

Dear Denise,

Pls explain how do you derive the figure of \$16,2500 with my submitted estimate of \$36,000.

Secondly , in the email you stated lump sum but on the phone you mentioned part by part after change out. Pls verify.

Edwin
97856612

> On 24 Oct 2017, at 4:01 PM, Denise Tay (LKKAuto) <denisetay@lkkauto.com> wrote:

>

> Dear Sir,

>

> Refer to our conversation,

>

> Basing on the estimate calculation, the current mandate approval is at Lump sum \$16,250.00, check item to be confirm upon dismantling.

>

> Parts will apply the trade discount at 20% + labour = subtotal and Lump sum at 20%.

>

> As instructed by our client, please proceed to repair the insured vehicle SLF 3201T (Excess \$TBA/-).

>

> If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

>

> All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.


 Username / Email Add
 password
 Submit Qu
 Connect Sign Up New Account
 Forgot Password


Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Zero Down Payment! Cheapest Price In The Market!


 Best For Short Term Usage!
 Le Motor Enterprise StarAd


Browse by Category

« Back (1 2) Next »

Sort by Date Posted

20 results/page

40 vehicles

Vezel 1.5A X

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Vezel 1.5A X		Any	Any	2016	Any	Any	Any	Available
	Honda Vezel 1.5A X		\$89,800	\$9,620 /yr	05-Aug-2016	1,496 cc	-	SUV	Available
Elegant White SUV, Almost Brand New, One Owner Only, Low Maintenance Cost, With Warranty, Very Well Maintained, Flexible In-house Loan Packages Available.									
Prime Motor & Leasing									
Posted: 13-Oct-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda									
	Honda Vezel 1.5A X		\$83,800	\$9,030 /yr	22-Jun-2016	1,496 cc	-	SUV	Available
New Face Lift Cinnamon Bronze! 10% Down Payment 10 Years Repayment, In House Loan Or Balloon Scheme Available! Low Interest Rate. Lowest Depreciation Ever! Make And Assemble In Japan. 3 Years Or 100000...									
Trust Motoring									
Posted: 13-Oct-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda									
	Honda Vezel Hybrid 1.5A X		\$94,800	\$10,410 /yr	24-Aug-2016	1,496 cc	-	SUV	Available
Fuel Type: Petrol-Electric									
Almost New Honda Vezel Hybrid With Honda Sensing Lane Departure, Pre-Collision Sensing, Paddle Shifter, New Facelift Crystal Red, 10% Down Payment 10 Years Repayment, In House Loan Or Balloon Scheme A...									
Trust Motoring									
Posted: 13-Oct-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda									
	Honda Vezel 1.5A X		\$83,800	\$9,030 /yr	22-Jun-2016	1,496 cc	-	SUV	Available
New Facelift Luna Silver! 10% Down Payment 10 Years Repayment, In House Loan Or Balloon Scheme Available! Low Interest Rate. Lowest Depreciation Ever! Make And Assemble In Japan. 3 Years Or 100000km Warra...									
Trust Motoring									
Posted: 13-Oct-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda									
Car Buying Car Ownership Car Selling On The Move Car Aftermarket Lifestyle Buy Tyres Online Latest Special Offers from Tyrepac!									
	Honda Vezel 1.5A X		\$83,800	\$9,030 /yr	21-Jun-2016	1,496 cc	-	SUV	Available
Facelift Crystal Red! 10% Down Payment 10 Years Repayment, In House Loan Or Balloon Scheme Available! Low Interest Rate. Lowest Depreciation Ever! Make And Assemble In Japan. 3 Years Or 100000km Warra...									
Trust Motoring									
Posted: 13-Oct-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda									
	Honda Vezel 1.5A X		\$88,800	\$9,980 /yr	09-Mar-2016	1,496 cc	22,000 km	SUV	Available
10% Downpayment! No Waiting Game For COE. Huge Savings From New! The Most Popular Honda Compact SUV! 1 Owner Low Mileage In Fantastic Condition. Warranty Till Mar 2019. Last Servicing Done. White With...									
Dynamic Motoring									
Posted: 13-Oct-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda									
	Honda Vezel 1.5A X		\$86,000	\$9,240 /yr	15-Jul-2016	1,496 cc	11,900 km	SUV	Available
1st Owner, Low Mileage, Full Service Record, Almost Brand New Condition.									
Carro									
Posted: 13-Oct-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda									
Compare	Honda Vezel 1.5A X		\$85,000	\$9,510 /yr	15-Mar-2016	1,496 cc	25,000 km	SUV	Available

	Honda Vezel X. Very Nice Combination Of Black Exterior Paint With Brown Leather Seats. Bought From Reputable PT And Only Serviced At Authorised Workshop. Personal Vehicle, Not Used For Private Hire (U... Carm Posted: 13-Oct-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda	
	Honda Vezel 1.5A X \$85,800 \$9,800 /yr 26-Jan-2016 1,496 cc - SUV Available Extremely Well Maintained! Buy With A Peace Of Mind From A Company Accredited With Outstanding Awards, Professional After Sales Service Assured, No Hassle When We Can Proceed With Immediate Transfer W... Dickson Automobile Posted: 13-Oct-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda	
	Honda Vezel 1.5A X \$85,800 \$9,370 /yr 25-May-2016 1,496 cc 37,780 km SUV Available One Owner, Low Mileage. Need Not Introduce Much. If You Have Did Research About This Car You Are On The Right Page. Definitely A Good Catch With 5 Out Of 5 In Terms Of Looks, Fuel Consumption And Perf... Benefit Auto Enterprise Pte Ltd Posted: 11-Oct-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda	 PREMIUM ID
	Honda Vezel 1.5A X \$84,800 \$9,640 /yr 04-Feb-2016 1,496 cc - SUV Available Henly Enterprises Co Posted: 11-Oct-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda	
	Honda Vezel Hybrid 1.5A X \$91,333 \$10,440 /yr 15-Apr-2016 1,496 cc - SUV Available Fuel Type: Petrol-Electric Honda Vezel 1.5X Hybrid, 3 Years Or 100,000km Warranty Provided, Ultimate Finance Packages Available At Competitive Rates, In House/Loan Available. Do Call Now! Posted: 11-Oct-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda	 PREMIUM ID
	Honda Vezel 1.5A X \$83,800 \$9,500 /yr 23-Feb-2016 1,496 cc 29,000 km SUV Available One Owner, Almost Like New, Pioneer AVH 5850BT Worth \$1,100, Traffic Camera I-road V9 Worth \$550, V-kool Solar Film Worth \$1,000, Please Call To Arrange For Viewing. Posted: 09-Oct-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda	
	Honda Vezel 1.5A X \$89,988 \$9,700 /yr 05-Jul-2016 1,496 cc 15,900 km SUV Available Super Low Mileage Clocked Due To Company Relocation. 3 Digit Bidded Number Plate To Go Along. Tastefully Done Up By Car Enthusiastic. Zero Mishap. Viewing Strictly Via Appointment Only. To Avoid Disap... Posted: 09-Oct-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda	
	Honda Vezel 1.5A X \$85,900 \$9,640 /yr 08-Mar-2016 1,496 cc 22,000 km SUV Available Selling On Behalf Of Private Owner Please Call Before Viewing. Posted: 09-Oct-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda	 GOVERNMENT
	Honda Vezel 1.5A X \$99,888 \$10,680 /yr 11-Aug-2016 1,496 cc 55 km SUV Available 2016 New Facelift Honda Vezel! 90% 10 Years Loan Available! Package With Pioneer DVD AVH-X8850BT, In Car Camera, Reverse Sensor, Reverse Camera, Full Leather And Many More! JDM Cars Posted: 09-Oct-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda	
	Honda Vezel 1.5A X \$86,800 \$9,270 /yr 27-Jul-2016 1,496 cc 15,000 km SUV Available One Owner, Original Paintwork And Condition, Like New, View To Appreciate. Appointment Only. Posted: 07-Oct-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda	
	Honda Vezel 1.5A X \$87,800 \$10,000 /yr 05-Feb-2016 1,496 cc 11,081 km SUV Available No Gimmicks! Only 10% (\$8,580) Downpayment Needed! Monthly \$1010! Showroom Condition, As Good As Brand New! Previous Owner Is A High Flying Wealth Manager Who Upgraded To A BMW! Very Underutilized And... Car House Pte Ltd Posted: 07-Oct-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda	
	Honda Vezel Hybrid 1.5A X \$107,000 \$12,570 /yr 04-Feb-2016 1,496 cc 22,000 km SUV Available Fuel Type: Petrol-Electric Ideal Car For Singapore Roads, Save On Petrol, Road Tax And Instalment. Warranty Inclusive! Drive Away With Downpayment Of \$8888. High Trade In And Loan Available! Call Us For A Viewing Now! (By Appoi... Cars 88 Pte Ltd Posted: 04-Oct-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda	 PREMIUM ID
Compare	Honda Vezel 1.5A X \$89,800 \$9,580 /yr 26-Aug-2016 1,496 cc 12,000 km SUV Available	



1 Owner, Low Mileage, Immaculate Condition, Accident Free, 10 Years 200k Km Warranty, Road Tax Renewed In Aug 17, Full Servicing Records.
Please Drop A Message Or WhatsApp If I Did Not Answer Your Call...

DIRECT OWNER

Posted: 01-Oct-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda

Details

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view **Expired ads**

◀ Back (1 2) Next ▶

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Vezel 1.5A X, Vezel 1.5A X Singapore, used Vezel 1.5A X Singapore, used Vezel 1.5A X, used vehicles Singapore or even buy used Vezel 1.5A X Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, massage services, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2017 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Compare

Denise Tay (LKKAuto)

To: Ng, Sharon
Cc: SUR
Subject: RE: SLF3201T OD claim (Pending authorization) - Our ref: CLMOMVP000000392

Dear Sharon,

Refer to telephone conversation with Bryan, the part price is based on list price and repairer will carry out the repair on lump sum basis.

Please see breakdown below for easy reference.

Revised \$20,325.94
Check Items \$5,341.64
Total: \$25,667.58

After lump it will be \$20,500/-. The ERV of this vehicle is \$28K

Kindly advise.

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

-----Original Message-----

From: Ng, Sharon [mailto:Sharon.Ng@sg.gaig.com]
Sent: Friday, 20 October, 2017 1:36 PM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SLF3201T OD claim (Pending authorization) - Our ref: CLMOMVP000000392

Hi Denise

The Revised estimate amount of \$20,326.14 is on Parts by Parts?
Check items \$5,691.64. Max liability to us is at most \$26,017.78.

How did the workshop derive lump sum of \$28,000.00? This is a 2016 vehicle, we are not inclined to settle on lump sum.

Regards
Sharon Ng
Great American

-----Original Message-----

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Thursday, October 19, 2017 10:54 AM
To: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SLF3201T OD claim

Dear Sharon,

Denise Tay (LKKAuto)

To: Ng, Sharon
Cc: SUR
Subject: RE: SLF3201T OD claim (Pending authorization) - Our ref: CLMOMVP000000392

Dear Sharon,

is based.

Refer to telephone conversation with Bryan, the part price on list price and repairer will carry out the repair on lump sum basis.

Please see breakdown below for easy reference.

Revised \$20,325.94
Check Items \$5,341.64
Total: \$25,667.58

After lump it will be \$20,500/-. *The ERV of this ~~car~~ is 28k.*
Kindly advise. *Vehicle.*

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Ng, Sharon [mailto:Sharon.Ng@sg.gaig.com]
Sent: Friday, 20 October, 2017 1:36 PM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SLF3201T OD claim (Pending authorization) - Our ref: CLMOMVP000000392

Hi Denise

The Revised estimate amount of \$20,326.14 is on Parts by Parts?
Check items \$5,691.64. Max liability to us is at most \$26,017.78.

How did the workshop derive lump sum of \$28,000.00? This is a 2016 vehicle, we are not inclined to settle on lump sum.

Regards
Sharon Ng
Great American

-----Original Message-----

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Thursday, October 19, 2017 10:54 AM
To: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SLF3201T OD claim

Dear Sharon,

67435192
Denise Tay (LKKAuto)

To: Ng, Sharon
Cc: SUR
Subject: RE: SLF3201T OD claim (Pending authorization) - Our ref: CLMOMVP000000392

Dear Sharon,

As per conversation, the amount is based on list price,

Revised \$20,325.94
Check Items \$5,341.64
Total: \$25,667.58

After lump it will be \$20,500/-.

Kindly advise on the authorization.

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

-----Original Message-----

From: Ng, Sharon [mailto:Sharon.Ng@sg.gaig.com]
Sent: Friday, 20 October, 2017 1:36 PM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SLF3201T OD claim (Pending authorization) - Our ref: CLMOMVP000000392

Hi Denise

The Revised estimate amount of \$20,326.14 is on Parts by Parts?
Check items \$5,691.64. Max liability to us is at most \$26,017.78.

How did the workshop derive lump sum of \$28,000.00? This is a 2016 vehicle, we are not inclined to settle on lump sum.

Regards
Sharon Ng
Great American

-----Original Message-----

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Thursday, October 19, 2017 10:54 AM
To: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SLF3201T OD claim

Dear Sharon,

According to the repairer there will be further supplementary and willing to undertake the repair cost at lump sum not more than \$28,000/- within the economical repair.

Kindly let us have your authorization.

Denise Tay (LKKAuto)

To: Ng, Sharon
Cc: SUR
Subject: RE: SLF3201T OD claim (Pending authorization) - Our ref: CLMOMVP000000392

Dear Sharon,

As spoken, the lump sum figure of \$28,000/- is due to further supplementary.

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

-----Original Message-----

From: Ng, Sharon [mailto:Sharon.Ng@sg.gaig.com]
Sent: Friday, 20 October, 2017 1:36 PM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SLF3201T OD claim (Pending authorization) - Our ref: CLMOMVP000000392

Hi Denise

The Revised estimate amount of \$20,326.14 is on Parts by Parts?
Check items \$5,691.64. Max liability to us is at most \$26,017.78.

How did the workshop derive lump sum of \$28,000.00? This is a 2016 vehicle, we are not inclined to settle on lump sum.

Regards
Sharon Ng
Great American

-----Original Message-----

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Thursday, October 19, 2017 10:54 AM
To: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SLF3201T OD claim

Dear Sharon,

According to the repairer there will be further supplementary and willing to undertake the repair cost at lump sum not more than \$28,000/- within the economical repair.

Kindly let us have your authorization.

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

* 68047845 *

Denise Tay (LKKAuto)

To: Admin-D (LKKAuto)
Subject: RE: SLF3201T OD claim
Attachments: CSGAI17019379T1tb.pdf

Dear Sharon,

According to the repairer there will be further supplementary and willing to undertake the repair cost at not more than lump sum \$28,000/- within the economical repair.

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 10 October, 2017 1:49 PM
To: 'Ng, Sharon' <Sharon.Ng@sg.gaig.com>; sur@lkkauto.com
Cc: assignments@lkkauto.com
Subject: RE: SLF3210T OD claim

Dear Sharon,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,
Catherine Chong | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Ng, Sharon [mailto:Sharon.Ng@sg.gaig.com]
Sent: Tuesday, 10 October, 2017 1:37 PM
To: sur@lkkauto.com
Cc: assignments@lkkauto.com
Subject: FW: SLF3210T OD claim
Importance: High

Hi Catherine

Please conduct OD survey and revert.

GIA report and estimates please obtain from workshop.

Excess : TBA

Regards
Sharon
Great American

-----Original Message-----

From: Edwin SgGarage [mailto:edwin@sugarage.com]
Sent: Tuesday, October 10, 2017 11:05 AM
To: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Subject: SLF3210T OD claim

Hi Sharon

Denise Tay (LKKAUTO)

To: 'Insurance SgGarage'
Cc: Admin-D (LKKAUTO); SUR; assignments
Subject: RE: ESTIMATE FOR SLF3201T HONDA VEZEL
Attachments: PAGE 1.tif; PAGE 2.tif; PAGE 3.tif

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLF3201T (Excess \$400/-)**. *the just signed*
~~the subject vehicle basis the first approved checklist~~ (with max cap at SGD28k) Reimbursement to be based on itemised invoice against checklist and photos of repaired vehicle. *based on*

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection. *Amended*

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Insurance SgGarage [mailto:insurance@sggarage.com]
Sent: Tuesday, 24 October, 2017 4:36 PM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Cc: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: Re: ESTIMATE FOR SLF3201T HONDA VEZEL

Dear Denise,

Pls explain how do you derive the figure of \$16,2500 with my submitted estimate of \$36,000.

Secondly, in the email you stated lump sum but on the phone you mentioned part by part after change out. Pls verify.

Edwin
97856612

> On 24 Oct 2017, at 4:01 PM, Denise Tay (LKKAUTO) <denisetay@lkkauto.com> wrote:

- >
- > Dear Sir,
- >
- > Refer to our conversation,
- >
- > Basing on the estimate calculation, the current mandate approval is at Lump sum \$16,250.00, check item to be confirm upon dismantling.
- >
- > Parts will apply the trade discount at 20% + labour = subtotal and Lump sum at 20%.
- >
- > As instructed by our client, please proceed to repair the insured vehicle SLF 3201T (Excess \$TBA/-).
- >
- > If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.
- >
- > All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.
- >
- > *Our client reserve their right not to pay if there is no valid approval obtained before repair.

Denise Tay (LKKAUTO)

From: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Sent: Tuesday, 24 October, 2017 2:02 PM
To: Denise Tay (LKKAUTO)
Cc: SUR; Ngian, Kelvyna
Subject: RE: SLF3201T OD claim (Pending authorization) - Our ref: CLMOMVP000000392

Importance: High

Dear Denise

Please approve on this basis:-

Repair costs \$20,325.94 plus verify check items \$5,341.64. I will be out of office this afternoon.

For urgent matter, you may liaise with my colleague Kelvyna.

Thanks & Regards
Sharon

-----Original Message-----

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Monday, October 23, 2017 5:48 PM
To: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SLF3201T OD claim (Pending authorization) - Our ref: CLMOMVP000000392

Dear Sharon,

Refer to telephone conversation with Bryan, the part price is based on list price and repairer will carry out the repair on lump sum basis.

Please see breakdown below for easy reference.

Revised \$20,325.94
Check items \$5,341.64
Total: \$25,667.58

After lump it will be \$20,500/-. The ERV of this vehicle is \$28K

Kindly advise.

Best Regards,

Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

-----Original Message-----

From: Ng, Sharon [mailto:Sharon.Ng@sg.gaig.com]
Sent: Friday, 20 October, 2017 1:36 PM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SLF3201T OD claim (Pending authorization) - Our ref: CLMOMVP000000392



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: -
Our Ref: CS/GAI17019379/T1tb

Date: 13/10/2017

GAI The Motor Claims Department
EQ INSURANCE COMPANY LTD

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SLF 3201T.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12/10/2017 at the premises of M/s Edwin Garage and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 38,440.20</u>
Revised Estimate Amount	: <u>S\$ 20,325.94</u>
Check" Items Amount	: <u>S\$ 5,341.64</u>
Market Value	: <u>S\$ 85,000.00</u>
LTA Reimbursement Value	: <u>S\$ 54,945.00</u>
Nett Value	: <u>S\$ 30,055.00</u>

Description of Damage:

The vehicle sustained at the front o/s portion
The chassis affected due to collision.



Comments/ Present Status:

Damage consistent
Repair cost Economical

Yours faithfully

Taufikh
Motor Surveyor



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: -
Our Ref: CS/GAI17019379/T1tb

Date: 13/10/2017

The Motor Claims Department
GREAT AMERICAN INSURANCE COMPANY

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SLF 3201T

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12/10/2017 at the premises of M/s Edwin Garage and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 38,440.20</u>
Revised Estimate Amount	: <u>S\$ 20,326.14</u>
Check" Items Amount	: <u>S\$ 5,691.64</u>
Market Value	: <u>S\$ 85,000.00</u>
LTA Reimbursement Value	: <u>S\$ 54,945.00</u>
Nett Value	: <u>S\$ 30,055.00</u>

Description of Damage:

The vehicle sustained at the front o/s portion
The chassis affected due to collision.



Comments/ Present Status:

Damage consistent
Repair cost Economical

Yours faithfully

Taufikh
Motor Surveyor



Parts

892.3	
187.3	Labour
187.7	
69.1	2200
659.8	1800
386.1	220
63.3	300
56.4	120
5.2	120
328.3	600
283.3	180
58.3	5540
69.3	
47.5	
190.6	
318.9	
491.3	
151.6	
1556.2	
491.3	
1387.5	
322.7	
206.3	
155.5	
57.3	
51.6	
868.1	
223.7	
283.5	
1585.6	
190.4	
273.2	
1467.4	
141.7	
156.1	
257.9	
125.2	
1740.8	2236.8
196.8	1750.5
666.4	860.2
157.3	643.2
188.7	158.9
420.8	738.1
256.3	149.5 sub total
462.1	329.5 38440.2
1840.3	963.5
802.3	396.4

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 1437H

Vehicle Details

Vehicle No.: SLF3201T

Vehicle to be Exported: No

Intended De-registration Date: 13 Oct 2017

Vehicle Make: HONDA

Vehicle Model: VEZEL 1.5X CVT

Primary Colour: White

Manufacturing Year: 2016

Engine No.: L15B4038034

Chassis No.: RU11118029

Maximum Power Output: 96.0 kW (128 bhp)

Open Market Value: \$20,640.00

Original Registration Date: 11 Aug 2016

First Registration Date: 11 Aug 2016

Transfer Count: 0

Actual ARF Paid: \$10,896.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 10 Aug 2026

PARF Rebate Amount: \$8,172.00

Intended COE Rebate Details

COE Expiry Date: 10 Aug 2026

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$53,000.00

COE Rebate Amount: \$46,773.00

Total Rebate Amount: \$54,945.00

The information contained herein is correct as at 13 Oct 2017

85K

25K
54945
30 055

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/10/2017 11:10
Date Of Accident	10/10/2017 06:45
Exact Location Of Accident	JUNCTION OF AMK STREET 44 AND AMK AVE 10
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF3201T
Insured/Policyholder	
Name Of Registered Owner	YEO KAH KIAT
NRIC No	S8851437H
Email Address	YEO_KAHKIAT88@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-98353321
Alternative Phone No	OFFICE-98353321

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MOMVP000002581-00-000
Cover Note Number	

Driver

Name of Driver	YEO KAH KIAT
NRIC No	S8851437H
Date Of Birth	19/12/1988
Occupation	INDOOR
Date Of Driving Pass	26/06/2009
Driving Experience	8 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98353321
Fax Number	(LOCAL) +65-98353321
Contact Number	OFFICE-98353321
E-Mail Address	YEO_KAHKIAT88@HOTMAIL.COM

Address	BLK 455A ANG MO KIO STREET 44 #32-01
Postcode	561455
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFW894U
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	KOH TECK GEE (XU DEYI)
NRIC/Passport Number	S7508518D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to renew policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

On 10/10/2017, at about 06:45am, I was driving along junction of AMF Street 44 and AMF Ave 10. I want to turn right to Ave 10 and check that there is no incoming cars before I moved. Suddenly, the vehicle SFW894U came from Ave 10 and speed up to the right lane and we banged into each other. That's all.

Declaration

We declare the foregoing particulars are true in every respect.

[Handwritten signature]

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Simla

MOTOR PTE LTD
VIN'S ★

Witnessed by Reporting Centre Personnel

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



892.3
 187.3
~~187.3~~ 187.7
 69.1
 659.8
~~386.14~~ 386.10
 126.6
 112.8
 5.2
 328.3
 283.3
 58.3
 69.3
 177.5
 190.6
 637.8
 491.3
 151.6
 3112.4
 982.6
 1387.5
 322.7
 206.3 51.6
 155.5 272.1 346.9
 57.3 1075 1467.4
 868.1 223.7 172.7 1800
 141.7 283.5 93.1 1500
 156.1 1585.6 750 100
 257.9 190.4 1316.7 100
 125.2 273.2 291.4 100
 1740.8 149.5 371.8 100
 196.8 643.2 1228.8 ~~3700~~
 1840.3 4696.2 6090.4

353.1 ~~3756.96~~ ~~4572.32~~ after 20% tread dis count

2236.8

1750.5

860.2

158.9

738.1

659

23322.34 23323.70
 18657.87

after 20%

tread dis count 18658.16

3067.44 ~~3106.75~~ Total labour & parts + Towing \$80
 Total parts 24853.9 ~~24853.92~~ after 20% lump sum
 45 \$24,700



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 3201T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Cost Price (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS				
1	FRONT BONNET ✓		892.30	Bt	892.30
1	FRONT BONNET INSULATOR ✓		187.38	de	187.38
1	FRONT BONNET LOCK ✓		187.70	Bt	187.70
1	FRONT BONNET LOCK CATCH		-	xnn	-
1	FRONT BONNET LOCK GARNISH		-	xnn	-
2	FRONT BONNET HINGES ✓		69.10	Bt	69.10
1	FRONT BUMPER ✓		659.80	de	659.80
1	FRONT BUMPER REINFORCEMENT ✓		386.10	Bt	386.10
2	FRONT BUMPER BRACKET ✓		63.30	nec	126.60 63.30
2	FRONT BUMPER SIDE RETAINER ✓		56.40	nec	112.80 56.40
1	FRONT BUMPER CLIP ✓		5.20	nec	5.20
1	FRONT BUMPER UPPER GRILL ✓		328.30	de	328.30
2	FRONT BUMPER UPPER GRILL CHROME ✓		283.50	dis	283.50
1	FRONT BUMPER UPPER GRILL LOGO ✓		58.30	nec	58.30
1	FRONT BUMPER MIDDLE GRILLE ✓		69.30	de	69.30
1	FRONT BUMPER LOWER MESH ✓		47.50	de	47.50
1	FRONT BUMPER LOWER SKIRT ✓		190.60	de	190.60
2	FRONT BUMPER FOG LAMP ✓		318.90	dis	637.80 318.90
1	FRONT SUPPORT PANEL ✓		491.30	bt	491.30
1	FRONT SUPPORT PANEL GARNISH ✓		151.60	de	151.60
2	FRONT HEADLAMP ✓	3112.40	1,556.20	cva	1,556.20
2	FRONT HEADLAMP PANEL ✓	982.60	491.30	Bt	491.30
1	RADIATOR ASSY ✓	Bt	1,387.50	Bt	1,387.50
1	RADIATOR FAN ASSY X	X nn	322.70		322.70
1	RADIATOR FAN COWLING ✓		206.30	cva	206.30
1	RADIATOR FAN BLADE ✓		155.50	Jim	155.50
1	RADIATOR TOP HOSE ✓		57.30	twi	57.30
1	RADIATOR BOTTOM HOSE ?	* CHECK	51.60	xnn	-
1	AIR CON CONDENSER ✓		868.10	Bt	868.10
1	AIR CON SUCTION PIPE ?	* CHECK	223.70	xnn	-
1	AIRCON DISCHARGE PIPE ?	* CHECK	283.50	Bt	-
1	AIR CON COMPRESSOR ?	* CHECK	1,585.60	Bt	-
1	AIR CON BELT ?	* CHECK	190.40	tn	-
1	BELT TENSIONER ?	* CHECK	273.20	dis	-

Report Ref No. CS/GAI17019379/T1tb



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Cost Price (\$)	Our Adjusted (\$)
1	ALTERNATOR	* CHECK	1,467.40	Bt	-
1	AIR DUCT TOP ✓		141.70	de	141.70
2	AIR FLAP COVER SIDE	X n/a	-	-	-
1	WIPER TANK ✓		156.10	de	156.10
1	WIPER TANK MOTOR ✓		257.90	dis	257.90
1	RADIATOR SPARE TANK ✓		125.20	de	125.20
1	FRONT LOWER MEMBER ✓		1,740.80	Bt	1,740.80
1	FRONT LOWER MEMBER GARNISH ✓		196.80	de	196.80
2	FRONT CHASSIS FRAME ✓	n/a X	666.40	F	-
2	WIPER ARM 14X24 ✓		X 157.30	-	-
2	WIPER BLADE 14X24 ✓		X 188.70	-	-
2	WIPER MOTOR		X 420.80	-	-
1	WIPER LINK		X 256.30	-	-
1	INTAKE MANIFOLD COVER		X 462.10	-	-
1	STEERING AIRBAG ✓		1,840.30	act	1,840.30
1	STEERING RING		X 802.30	-	-
1	STEERING WHEEL		X 802.30	-	-
1	STEERING COLUMN		X 1,729.30	-	-
1	STEERING CLOCK SPRING ✓		353.10	act	353.10
1	DASHBOARD AIR BAG ✓		2,236.80	act	2,236.80
1	DASHBOARD ✓		1,750.50	de	1,750.50
2	DASHBOARD SPEAKER GARNISH		n/a X -	-	-
1	ROOF TOP AIR BAG		act 860.20	-	860.20
1	ROOF LINING PIECE		-	de	8750
1	FRONT DOOR PILLAR AIR BAG	* CHECK	643.20	act	-
1	FRONT DOOR PILLAR GARNISH ✓		158.90	de	158.90
1	FRONT DRIVER SEAT AIR BAG ✓		738.10	act	738.10
1	FRONT DRIVER SEAT X		n/a X -	-	-
1	AIR CON TEMPERATURE sensor	* CHECK	149.50	dis	-
3	AIRBAG SENSOR ✓	act	329.50	act	329.50
1	ABS UNIT	* CHECK	n/a X 963.50	-	-
1	RELAY BOX	* CHECK	n/a X 396.40	-	-
2	FRONT FENDER 14X24 ✓		1075 537.50	Bt 1075	537.50 268.50
2	FRONT WHEEL ARCH GARNISH ✓	N/S * CHECK	272.10	* mis	272.10 136.55
	LESS 20% DISCOUNT		-	-	-4,156.49
			32,900.48	-	16,625.94

Report Ref No. CS/GAI17019379/T11b

2012.43



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Cost Price (\$)	Our Adjusted (\$)
	LABOUR				
	LABOUR CHARGES.		2,200.00	-	1,800.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		1,800.00	-	1,500.00
	TO APPLY RUST PROOFING ON AFFECTED AREAS.		220.00	-	100.00
	TO CHECK WIRING.		300.00	-	100.00
	TO REMOVE AND REFIT RADIATOR AND TOP COOLANT.		120.00	-	-
	TO REMOVE AND REFIT AIRCON CONDENSER AND TOP UP GAS.		120.00	-	100.00
	CAR-O-LINER.	* CHECK	600.00	-	-
	TO REMOVE AND REFIT GARNISH, UPHOLSTERY AND ETC TO FACILITATE REPAIR.		180.00	-	100.00
			5,540.00	-	3,700.00
	GRAND TOTAL		38,440.48	-	20,325.94

RECOMMENDED COST OF LUMP SUM REPAIRS					-
---	--	--	--	--	---

Report Ref No. CS/GAI17019379/T1tb

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

EDWIN GARAGE AUTOMOTIVE PTE LTD (201700483D)
5032 Ang Mo Kio Industrial Park 2 #01-293 Singapore 569535
Mobile: 9785 6612 Email: edwin@garage.com

APPROVED ESTIMATE FOR SLE3701T HONDA VEZEL

List Price		Labour	Amount	
892.30	✓	Labour Charges	\$1,800.00	✓
187.30	✓	To spray painting on affected areas	\$1,500.00	✓
187.70	✓	To apply rust proofing on affected areas	\$100.00	✓
69.10	✓	To check wiring	\$100.00	✓
659.80	✓	To remove and refit aircon condenser and top up gas	\$100.00	✓
386.10	✓	To remove and refit garnish, upholstery and etc to facilitate repair	\$100.00	✓
126.60	✓	Car-o-liner	\$250.00	✓
112.80	✓			
5.20	✓			
328.30	✓			
283.30	✓			
58.30	✓			
69.30	✓			
177.50	✓			
190.60	✓			
637.80	✓			
491.30	✓			
151.60	✓			
3112.40	✓			
982.60	✓			
1387.50	✓			
322.70	✓			
206.30	✓			
155.50	✓			
57.30	✓			
868.10	✓			
141.70	✓			
156.10	✓			
257.90	✓			
125.20	✓			
1740.80	✓			
196.80	✓			
1840.30	✓			
353.10	✓			
2736.80	✓			
1750.50	✓			
860.20	✓			
158.90	✓			
738.10	✓			
659.00	✓			
23322.70			\$3,950.00	

27272.70

ADDITIONAL ITEM FOR RESURVEY

272.10	✓
1075.00	✓
51.60	✓
223.70	✓
283.50	✓
346.90	✓
1585.60	✓
190.40	✓
273.20	✓
1467.40	✓
149.50	✓
643.20	✓
172.70	✓
93.10	✓
750.00	✓
1316.70	✓
750.00	✓
291.40	✓
371.80	✓
1228.80	✓

11536.60

38809.30

EDWIN GARAGE AUTOMOTIVE
3032 Ang Mo Kio Industrial Park
Mobile: 9783 6612 Email: edwin@edwincar.com.sg

APPROVED ESTIMATE FOR

DATE	11-Oct-17		
SNO	QTY	Part	List Price
1	1	Front bonnet BT	892.30
2	1	Front bonnet insulator BT de	187.30
3	1	Front bonnet lock BT de	187.70
4	2	Front bonnet hinges BT	69.10
5	1	Front bumper de	659.80
6	1	Front bumper reinforcement BT	386.10
7	2	Front bumper bracket nec	126.60
8	2	Front bumper side retainer nec	112.80
9	1	Front bumper clip nec	5.20
10	1	Front Bumper Upper Grill de	328.30
11	2	Front Bumper Upper Grill Chrome dis	283.30
12	1	Front Bumper Upper Grill Logo de	58.30
13	1	Front Bumper Middle Grill de	69.30
14	1	Front bumper lower Mesh de	177.50
15	1	Front bumper lower Skirt de	190.60
16	2	Front bumper fog lamp dis	637.80
17	1	Front support panel BT	491.30
18	1	Front support panel garnish de	151.60
19	2	Front headlamp C/A	3112.40
20	2	Front headlamp panel BT	982.60
21	1	Radiator assy BT	1387.50
22	1	Radiator fan motor C/A	322.70
23	1	Radiator fan cowling C/A	206.30
24	1	Radiator fan blade de	155.50
25	1	Radiator top hose BT	5.20
26	1	Air con condenser BT	868.10
27	1	Air duct Top de	141.70
28	1	wiper tank de	156.10
29	1	Wiper tank motor dis	257.90
30	1	Radiator spare tank de	125.20
31	1	Front lower member BT	1740.80
32	1	Front lower member garnish de	196.80
33	1	Steering airbag act	1840.30
34	1	Steering Clock Spring act	353.10
35	1	Dashboard air bag act	2236.80
36	1	Dashboard de	1750.50
37	1	Roof top air bag act	860.20
38	1	Front door pillar garnish de	158.90
39	1	Front driver seat air bag act	738.10
40	2	AirBag sensor act	659.00
SUBTOTAL			23322.70
APPROVED ESTIMATE			
			ADDITIONAL IT
1	1	Front wheel arch garnish mis	272.10
2	1	Front fender BT de	1075.00
3	1	Radiator Bottom Hose de	51.60
4	1	Air con suction pipe BT	223.70
5	1	Aircon discharge pipe BT	283.50
6	1	Aircon Liquid Pipe (CA) BT	346.90
7	1	Air con compressor BT	1585.60
8	1	Air con belt in BT	190.40
9	1	Belt Tensioner de	273.20
10	1	Alternator BT	1467.40
11	1	Air con temperature sensor de	149.50
12	1	Front door pillar air bag act	643.20
13	1	Engine Mounting (CA) BT	172.70
14	1	Radiator Neck (CA) de	93.10
15	1	Roof Lining Piece (Torn) de	750.00
16	1	Airbag SRS ECU (Activated) (CA) act	1315.70
17	1	Front chassis frame Repair	750.00
18	1	Water Pump (CA) BT	291.40
19	1	ATF Cooler (CA) BT	371.80
20	1	Starter (CA) chs	1228.80
RESURVEY ESTIMATE			
(Approved)			
FINAL TOTAL			

648/2265

ESTIMATE FOR SLF3201T HONDA VEZEL

DATE	11-Oct-17						
SNO	QTY	Part	Amount	Labour	Amount		
1	1	Front bonnet	252.30	Labour Charges	\$2,200.00	1800	
2	1	Front bonnet insulator	127.30	To spray painting on affected areas	\$1,800.00	1500	
3	1	Front bonnet lock	127.30	To apply rust proofing on affected areas	\$220.00	100	
4	1	Front bonnet lock catch	X	To check wiring	\$300.00	100	
5	1	Front bonnet lock garnish	X	To remove and refit radiator and top coolant	\$120.00	✓	
6	2	Front bonnet hinges	69.10	To remove and refit aircon condenser and top up gas	\$120.00	100	
7	1	Front bumper	259.80	Car-o-liner	\$600.00	2500	photo.
8	1	Front bumper reinforcement	326.10	To remove and refit garnish, upholstery and etc to facilitate repair	\$180.00	100	
9	2	Front bumper bracket	63.30				
10	2	Front bumper side retainer	50.40				
11	1	Front bumper clip	5.20				
12	1	Front Bumper Upper Grill	328.80				
13	2	Front Bumper Upper Grill Chrome	222.50				
14	1	Front Bumper Upper Grill Logo	55.20				
15	1	Front Bumper Middle Grill	69.30				
16	1	Front bumper lower Mesh	172.50				
17	1	Front bumper lower Skirt	190.60				
18	2	Front bumper fog lamp	218.90				
19	1	Front support panel	121.00				
20	1	Front support panel garnish	101.00				
21	2	Front headlamp	155.10				
22	2	Front headlamp panel	50.10				
23	1	Radiator assy	137.40				
24	1	Radiator fan motor	203.70				
25	1	Radiator fan cowl	206.80				
26	1	Radiator fan blade	108.80				
27	1	Radiator top hose	101.30				
28	1	Radiator bottom hose	101.30				
29	1	Air con condenser	188.00				
30	1	Air con suction pipe	120.00				
31	1	Air con discharge pipe	120.00				
32	1	Air con compressor	180.00				
33	1	Air con belt	100.00				
34	1	Belt Tensioner	273.00				
35	1	Alternator	146.40				
36	1	Air duct Top	141.70				
37	2	Air Flap Cover Side	156.10				
38	1	wiper tank	257.90				
39	1	Wiper tank motor	135.00				
40	1	Radiator spare tank	174.80				
41	1	Front lower member	196.80				
42	1	Front lower member garnish	66.90				
43	2	Front chassis frame	157.30				
44	2	Wiper arm LH - x RH - ut	188.70				
45	2	Wiper blade LH - x RH - ut	120.80				
46	2	Wiper motor	256.30				
47	1	Wiper Link	162.00				
48	1	Intake manifold cover	184.00				
49	1	Steering airbag	202.50				
50	1	Steering ring	170.30				
51	1	Steering wheel	253.10				
52	1	Steering column	226.80				
53	1	Steering Clock Spring	130.80				
54	1	Dashboard air bag	260.20				
55	1	Dashboard	66.20				
56	2	Dashboard Speaker Garnish	155.90				
57	1	Roof top air bag	76.10				
58	1	Roof Lining Piece					
59	1	Front door pillar air bag					
60	1	Front door pillar garnish					
61	1	Front driver seat air bag					
62	1	Front driver seat cover					

ESTIMATE FOR SLF3201T HONDA VEZEL			
SNQ	QTY	Part	Amount
1	1	Radiator Bottom Hose	Dented 51.6
2	1	Alternator	Bent 1467.4
3	1	Engine Mounting	Bent 172.7
4	1	Radiator Neck	Dented 93.1
5	1	Roof Lining Piece (Torn)	Dented 750
6	1	Airbag SRS ECU (Activated)	activated 1316.7
7	1	Water Pump	Bent 291.4
8	1	ATF Cooler	Bent 371.8
9	1	Starter	distorted 1228.8
10	1	Aircon Liquid Pipe	Bent 346.9
		Total	6090.4
		Less 20%	1218.08
			4872.32

EDWIN GARAGE AUTOMOTIVE PTE LTD (201700483D)
5032 Ang Mo Kio Industrial Park 2 601-385 Singapore 569533
Mobile 9785 6613 Email edwin@edwin.com

DATE 11-Oct-17

NO	QTY	Part	Unit Price	Labour	Amount	
1	1	Front bonnet	852.30	✓		
2	1	Front bonnet insulator	187.70	✓	\$1,800.00	✓
3	1	Front bonnet lock	187.70	✓	\$1,500.00	✓
4	2	Front bonnet hinges	69.10	✓	\$100.00	✓
5	1	Front bumper	659.80	✓	\$100.00	✓
6	1	Front bumper reinforcement	345.10	✓	\$100.00	✓
7	2	Front bumper bracket	126.60	✓	\$100.00	✓
8	2	Front bumper side retainer	112.80	✓	\$250.00	✓
9	1	Front bumper clip	5.20	✓		
10	1	Front Bumper Upper Grill	328.30	✓		
11	2	Front Bumper Upper Grill Chrome	283.30	✓		
12	1	Front Bumper Upper Grill Logo	58.30	✓		
13	1	Front Bumper Middle Grill	69.30	✓		
14	1	Front bumper lower Mesh	177.50	✓		
15	1	Front bumper lower Skirt	190.60	✓		
16	2	Front bumper fog lamp	637.80	✓		
17	1	Front support panel	491.30	✓		
18	1	Front support panel garnish	151.60	✓		
19	2	Front headlamp	3112.40	✓		
20	2	Front headlamp panel	987.60	✓		
21	1	Radiator assy	1387.50	✓		
22	1	Radiator fan motor	312.70	✓		
23	1	Radiator fan cowling	206.30	✓		
24	1	Radiator fan blade	155.50	✓		
25	1	Radiator top hose	57.30	✓		
26	1	Air con condenser	868.10	✓		
27	1	Air duct Top	141.70	✓		
28	1	wiper tank	156.10	✓		
29	1	Wiper tank motor	257.90	✓		
30	1	Radiator spare tank	125.20	✓		
31	1	Front lower member	1740.80	✓		
32	1	Front lower member garnish	195.80	✓		
33	1	Steering airbag	1840.30	✓		
34	1	Steering Clock Spring	353.10	✓		
35	1	Dashboard air bag	2236.80	✓		
36	1	Dashboard	1750.50	✓		
37	1	Roof top air bag	860.20	✓		
38	1	Front door pillar garnish	158.90	✓		
39	1	Front driver seat air bag	738.10	✓		
40	12	AirBag sensor	659.00	✓		
SUBTOTAL			23322.70		\$3,950.00	
APPROVED ESTIMATE					27272.70	
ADDITIONAL ITEM FOR RESURVEY						
1	1	Front wheel arch garnish	272.10	✓		
2	1	Front fender	1075.00	✓		(A)
3	1	Radiator Bottom Hose	51.40	✓		
4	1	Air con suction pipe	223.70	✓		
5	1	Aircon discharge pipe	283.50	✓		
6	1	Aircon Liquid Pipe	346.90	✓		(A)
7	1	Air con compressor	1585.60	✓		
8	1	Air con belt	190.40	✓		
9	1	Belt Tensioner	273.20	✓		
10	1	Alternator	1467.40	✓		(A)
11	1	Air con temperature sensor	149.50	✓		
12	1	Front door pillar air bag	643.20	✓		
13	1	Engine Mounting	172.70	✓		
14	1	Radiator Neck	93.10	✓		
15	1	Roof Lining Piece (Torn)	750.00	✓		
16	1	Airbag SAS ECU (Activated)	1315.70	✓		(A)
17	1	Front chassis frame Repair	750.00	✓		
18	1	Water Pump	291.40	✓		
19	1	ATF Cooler	371.80	✓		
20	1	Starter	1228.80	✓		
RESURVEY ESTIMATE						
(Approved)					11536.60	
FINAL TOTAL					38809.30	

63	1	Air con temperature sensor	1A9-SD	dis		
64	3	AirBag sensor	209-SD			
65	1	ABS unit	962-SD			
66	1	Relay Box	2A6-SD			
67	2	Front fender	537-SD	LH-Rx, RH-Lf	258-SD	10-15
68	2	Front wheel arch garnish	270-SD	LH-?, RH-de	136-SD	21-10

MIS

Taufik 97495749

office : 62563561

Ex d : To be advise

Revert

* To check repair limit
sur @ 1kkauto.com.

* Resurvey before paint
14 days.

20%

ESTIMATE FOR SLF3201T HONDA VEZEL

DATE	11-Oct-17						
SNO	QTY	Part	Amount	Labour	Amount		
1	1	Front bonnet ✓	892.3	Labour Charges	\$2,200.00	1800	
2	1	Front bonnet insulator ✓	187.3	To spray painting on affected areas	\$1,800.00	1500	
3	1	Front bonnet lock ✓	187.7	To apply rust proofing on affected areas	\$220.00	100	
4	1	Front bonnet lock catch ✓		To check wiring	\$300.00	100	
5	1	Front bonnet lock garnish ✓		To remove and refit radiator and top coolant	\$120.00		
6	2	Front bonnet hinges ✓	69.1	To remove and refit aircon condenser and top up gas	\$120.00	100	
7	1	Front bumper	659.8	Car-o-liner	\$600.00	250	
8	1	Front bumper reinforcement ✓	386.1	To remove and refit garnish, upholstery and etc to facilitate repair	\$180.00	100	
9	2	Front bumper bracket ✓	63.3	56 60			
10	2	Front bumper side retainer ✓	56.4	11 80			
11	1	Front bumper clip ✓	5.2				
12	1	Front Bumper Upper Grill ✓	328.3				
13	2	Front Bumper Upper Grill Chrome ✓	283.3				
14	1	Front Bumper Upper Grill Logo ✓	58.3				
15	1	Front Bumper Middle Grill ✓	69.3				
16	1	Front bumper lower Mesh ✓	47.5	14 80			
17	1	Front bumper lower Skirt ✓	190.6	63 80			
18	2	Front bumper fog lamp ✓	318.9	49 130			
19	1	Front support panel ✓	491.3				
20	1	Front support panel garnish ✓	151.6				
21	2	Front headlamp ✓	1556.2	312 40			
22	2	Front headlamp panel ✓	491.3	98 60			
23	1	Radiator assy ✓	1387.5	✓			
24	1	Radiator fan motor ✓	322.7				
25	1	Radiator fan cowling ✓	206.3				
26	1	Radiator fan blade ✓	155.5				
27	1	Radiator top hose ✓	57.3				
28	1	Radiator bottom hose ✓	51.6	X			
29	1	Air con condenser ✓	868.1				
30	1	Air con suction pipe ✓	223.7	?			
31	1	Aircon discharge pipe ✓	283.5	?			
32	1	Air con compressor ✓	1585.6	?			
33	1	Air con belt ✓	190.4	?			
34	1	Belt Tensioner ✓	273.2	?			
35	1	Alternator ✓	1467.4	✓			
36	1	Air duct Top ✓	141.7				
37	2	Air Flap Cover Side ✓		X			
38	1	wiper tank ✓	156.1				
39	1	Wiper tank motor ✓	257.9				
40	1	Radiator spare tank ✓	125.2				
41	1	Front lower member ✓	1740.8				
42	1	Front lower member garnish ✓	196.8				
43	2	Front chassis frame ✓	666.4	X X			
44	2	Wiper arm ✓	157.3	X X			
45	2	Wiper blade ✓	188.7	X X			
46	2	Wiper motor ✓	420.8	X X			
47	1	Wiper Link ✓	256.3	X			
48	1	Intake manifold cover ✓	462.1	X X			
49	1	Steering airbag ✓	1840.3				
50	1	Steering ring ✓	802.3	X X			
51	1	Steering wheel ✓	802.3	X			
52	1	Steering column ✓	1729.3	X			
53	1	Steering Clock Spring ✓	353.1	✓			
54	1	Dashboard air bag ✓	2236.8	✓			
55	1	Dashboard ✓	1750.5	✓			
56	2	Dashboard Speaker Garnish ✓		X X			
57	1	Roof top air bag ✓	860.2				
58	1	Roof Lining Piece ✓	750				
59	1	Front door pillar air bag ✓	643.2	?			
60	1	Front door pillar garnish ✓	158.9	✓			
61	1	Front driver seat air bag ✓	738.1	✓			
62	1	Front driver seat ✓		X			

63	1	Air con temperature sensor ✓	149.5	?			
64	3	AirBag sensor ✓	329.5	?	659		
65	1	ABS unit ✓	963.5	?			
66	1	Relay Box ✓	396.4	?			
67	2	Front fender ✓	537.5		LH RX ✓ ; RH-BH ✓ 1095	268.5	
68	2	Front wheel arch garnish ✓✓	272.1		LH-? ✓ ; RH-R ✓	136.55	

268.75
136.05

DATE		27 Oct 2017			
SNO	QTY	Part	List Price	Labour	Amount
ADDITIONAL ITEMS PENDING DELIVERY					
1	1	ABS unit	963.50	X	wis
2	1	Front wheel arch garnish	136.55		
4	1	Radiator bottom hose	51.60	/	
5	1	Air con suction pipe	223.70	/	
6	1	Aircon discharge pipe	283.50	/	10
7	1	Air con compressor	1585.60	/	
8	1	Air con belt	190.40	/	
9	1	Belt Tensioner	273.20	/	
		Alternator	1467.40	/	292
		Air con temperature sensor	149.50	/	
		Front door pillar air bag	643.20	/	
		Relay Box	396.40	X	
		Engine Mounting	172.70	/	✓
		Radiator Neck	93.10	/	
		Water Pump	175.40	X	
		Lining Piece (Torn)	??	/	
		ECU (Activated)	??		
		Chassis frame (Dented)	750.00		
				/	
				/	
		Mounting LHS		X	
		Mounting RHS		X	
		(Solid)		/	
		Charge		/	
				/	
				X	

EDWIN GARAGE AUTOMOTIVE PTE LTD (201700485H)
5032 Ang Mo Kio Industrial Park 2 #01-295 Singapore 569535
Mobile: 9785 6612 Email: edwin@s4garage.com

ESTIMATE FOR SLF3201T HONDA VEZEL

DATE 11-Oct-17					
SNO	QTY Part	Amount	Labour	Amount	
1	1 Front bonnet <i>bt</i>				
2	1 Front bonnet insulator <i>de</i>	892.3	Labour Charges	\$1,800.00	
3	1 Front bonnet lock <i>bt</i>	187.3	To spray painting on affected areas	\$1,500.00	
4	2 Front bonnet hinges <i>bt</i>	187.7	To apply rust proofing on affected areas	\$100.00	
5	1 Front bumper <i>de</i>	138.2	To check wiring	\$100.00	
6	1 Front bumper reinforcement <i>bt</i>	659.8	To remove and refit radiator and top coolant		
7	2 Front bumper bracket <i>bt</i>	386.1	To remove and refit aircon condenser and top up gas	\$100.00	
8	2 Front bumper side retainer <i>bt</i>	63.3	Car-o-liner	\$250.00	
9	1 Front bumper clip <i>bt</i>	56.4	To remove and refit garnish, upholstery and etc to facilitate	\$100.00	
10	1 Front Bumper Upper Grill <i>de</i>	5.2	To remove engine block & Weld + Gasket Set <i>CA</i>	\$1,000.00	Slight Cracked
11	2 Front Bumper Upper Grill Chrome <i>de</i>	328.3	Front driver seat leather <i>bt</i>	\$300.00	Slightly torn as airbag burst, to change leat
12	1 Front Bumper Upper Grill Logo <i>de</i>	233.3	Top Roof lining rewrap <i>de</i>	\$1,000.00	Slightly torn as airbag burst, to change linin
13	1 Front Bumper Middle Grill <i>de</i>	58.3			
14	1 Front bumper lower Mesh <i>de</i>	69.3			
15	1 Front bumper lower Skirt <i>de</i>	47.5			
16	2 Front bumper fog lamp <i>de</i>	190.6			
17	1 Front support panel <i>bt</i>	637.8			
18	1 Front support panel garnish <i>de</i>	491.3			
19	2 Front headlamp <i>CA</i>	151.6			
20	2 Front headlamp panel <i>bt</i>	3112.4			
21	1 Radiator assy <i>bt</i>	982.6			
22	1 Radiator fan motor <i>CA</i>	1387.5			
23	1 Radiator fan cowling <i>CA</i>	322.7			
24	1 Radiator fan blade <i>bt</i>	206.3			
25	1 Radiator top hose <i>bt</i>	155.5			
26	1 Radiator bottom hose <i>bt</i>	57.3			
27	1 Air con condenser <i>bt</i>	51.6			
28	1 Air con suction pipe <i>bt</i>	868.1			
29	1 Aircon discharge pipe <i>bt</i>	223.7			
30	1 Air con compressor <i>bt</i>	283.5			
31	1 Air con belt <i>bt</i>	1585.6			
32	1 Belt Tensioner <i>bt</i>	190.4			
33	1 Alternator <i>bt</i>	273.2			
		1467.4			

EDWIN GARAGE AUTOMOTIVE PTE LTD (201700485D)
5032 Ang Mo Kio Industrial Park 2 #01-295 Singapore 569535
Mobile: 9785 6612 Email: edwin@sfggarage.com

DATE 27 Oct 2017

SNO	QTY	Part	List Price	Labour	Amount
-----	-----	------	------------	--------	--------

ADDITIONAL ITEM PENDING RESURVEY

1	1	ABS unit	963.50	X	
2	1	Front wheel arch garnish	136.55		
4	1	Radiator bottom hose	51.60	/	
5	1	Air con suction pipe	223.70	/	
6	1	Aircon discharge pipe	283.50	/	
7	1	Air con compressor	1585.60	/	
8	1	Air con belt	190.40	/	
9	1	Belt Tensioner	273.20	/	
10	1	Alternator	1467.40	/	
11	1	Air con temperature sensor	149.50	/	
12	1	Front door pillar air bag	643.20	/	
13	1	Relay Box	396.40	X	
14	1	Engine Mounting	172.70	/	
15	1	Radiator Neck	93.10	/	
16	1	Horn	175.40	X	
17	1	Roof Lining Piece (Torn)	??	/	
18	1	Airbag ECU (Activated)	??	/	
19	1	Front chassis frame (Dented)	750.00		
20	1	Water Pump		/	
21	1	Cooler		/	
22	1	Engine Mounting LHS		X	
23	1	Engine Mounting RHS		X	
24	1	AC Pipe (liquid)		/	
25	1	AC Pipe Discharge		/	
26	1	AC Pipe Suction		/	
27	1	Starter		X	

wis

10

3/11/2017
Raj

28 2 Seat Belt SRS

3/11/2017

EDWIN GARAGE AUTOMOTIVE PTE LTD (2017004831)
 5032 Aljunied Industrial Park 2 #01-293 Singapore 569535
 Mobile: 97856612 Email: edwin@edwincars.com

ESTIMATE FOR SLF3201T HONDA VEZEL

DATE		11-Oct-17				
SNO	QTY	Part	Amount	LKK	Labour	Amount
1	1	Front bonnet	892.3		Labour Charges	\$1,800.00
2	1	Front bonnet insulator	187.3		To spray painting on affected areas	\$1,500.00
3	1	Front bonnet lock	187.7		To apply rust proofing on affected areas	\$100.00
4	2	Front bonnet hinges	138.2		To check wiring	\$100.00
5	1	Front bumper	659.8		To remove and refit radiator and top coolant	
6	1	Front bumper reinforcement	386.1		To remove and refit aircon condenser and top up gas	\$100.00
7	2	Front bumper bracket	63.3		Car-o-liner	\$250.00
8	2	Front bumper side retainer	56.4		To remove and refit garnish, upholstery and etc to facilitate repair	\$100.00
9	1	Front bumper clip	5.2		To remove engine block & Weld + Gasket Set	\$1,000.00 Slight Cracked
10	1	Front Bumper Upper Grill	328.3		Front driver seat leather	\$300.00 Slightly torn a
11	2	Front Bumper Upper Grill Chrome	283.3		Top Roof lining rewrap	\$1,000.00 Slightly torn a
12	1	Front Bumper Upper Grill Logo	58.3			
13	1	Front Bumper Middle Grill	69.3			
14	1	Front bumper lower Mesh	47.5			\$6,250.00
15	1	Front bumper lower Skirt	190.6			
16	2	Front bumper fog lamp	637.8			
17	1	Front support panel	491.3			
18	1	Front support panel garnish	151.6			
19	2	Front headlamp	3112.4			
20	2	Front headlamp panel	982.6			
21	1	Radiator assy	1387.5			
22	1	Radiator fan motor	322.7			
23	1	Radiator fan cowling	206.3			
24	1	Radiator fan blade	155.5			
25	1	Radiator top hose	57.3			
26	1	Radiator bottom hose	51.6			
27	1	Air con condenser	868.1			
28	1	Air con suction pipe	223.7			
29	1	Aircon discharge pipe	283.5			
30	1	Air con compressor	1585.6			
31	1	Air con belt	190.4			
32	1	Belt Tensioner	273.2			
33	1	Alternator	1467.4			
34	1	Air duct Top	141.7			
35	1	wiper tank	156.1	5571.35		
36	1	Wiper tank motor	257.9			
37	1	Radiator spare tank	125.2			
38	1	Front lower member	1740.8			

39	1	Front lower member garnish	196.8			
40	1	Steering airbag	1840.3			
41	1	Steering Clock Spring	353.1			
42	1	Dashboard air bag	2236.8			
43	1	Dashboard	1750.5			
44	1	Roof top air bag	860.2			
45	1	Front door pillar garnish	158.9			
46	1	Front driver seat air bag	738.1			
47	1	Air con temperature sensor	149.5			
48	3	AirBag sensor	329.5			
49	1	ABS unit	963.5			
50	1	Relay Box	396.4			
51	2	Front fender	1075	537.5		
52	2	Front wheel arch garnish	272.1	136.05		
53	1	Engine Mounting	172.7			
54	1	Radiator Neck	93.1			
55	1	Horn	175.4			\$6,250.00
PROPOSED TOTAL ESTIMATE			29744.5	24877.35		
			\$35,994.50			

		Pending items				
43	2	Front chassis frame		666.4		3208.7
44	2	Wiper arm		157.3		78.65
45	2	Wiper blade		188.7		94.35
46	2	Wiper motor		420.8		
47	1	Wiper Link		256.3		
48	1	Intake manifold cover		462.1		
50	1	Steering ring		802.3		
51	1	Steering wheel		802.3		
52	1	Steering column		1729.3		
59	1	Front door pillar air bag	643.2			173

List parts

8780.05

\$25,050.35

Check

7024.04

\$20,040.28

total part

\$27,064.32

part + labour

\$33,314.32

\$26,651.46 after lump

TO: Great America Insurance 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190			Invoice Number : 2018010501
SNO	Item	Sub Total	
1	LumpSum Cost of Repair for SLF3201T	24700	
2	Tow Fee - 2 way for reporting	80	
3	Car Rental Limit	1000	
4	Own Excess	0	
Total		25780	

B & O VEHICLE RENTAL

Blk 5033, Ang Mo Kio Industrial Park 2 #01-279 (off Ang Mo Kio Ave. 3)

Singapore 569536 Tel: 6482 5577 (3 Lines) Fax: 6482 5000

Reg. No: 53060835M

TOWING SERVICE: 9182 8211 (After 10.30 pm)

SLF 3201 T

车辆出租合同 VEHICLE RENTAL AGREEMENT

Date: 28/10/17
Owner: B & O VEHICLE RENTAL ("the owner")

Hirer: Yeo Kah Kiat

NRIC / Co. Reg. No: S 8857437H

Tel: _____ Fax: _____ H/P: 98353321

Address: Blk 455A Ang Mo Kio Ave 4 #32-01 S1 504357

Owner and Hirer have agreed to enter into this Vehicle Rental Agreement for the motor vehicle described below and upon the terms and conditions contained on both sides of this document. Hirer acknowledges having read and understood all the terms and conditions and signifies acceptance upon signing.

Vehicle Reg. No: SG L 8725		Agreement No.: 17348	
Driver's Particulars		Odometer: _____	
Name: Yeo Kah Kiat		Date & Time Out: 28/10/17 1259	
Address: _____		Date & Time In: 9/11/2017 800H	
I/C No: 8851437H	Dr/Licence No: 8857437H	Hour @\$ _____	
Date of Issue: 26/6/09	Occupation: Civil Servant	12 Days @\$ 85/-	
Date of Birth: 19/11/1988	Tools: 6w fit Spare Tyre: 6w fit	Wks @\$ _____	
		Mths @\$ _____	

Third Party Claim

In respect of each third party insurance claim arising from the date of hire to date of return of the vehicle (both dates inclusive). Hirer unconditionally agrees to pay Owner SS 3000/- comprising excess payable and compensation to Owner for impact of claim on future motor insurance premiums.

Own Vehicle Damage

Hirer is responsible for the first S 3000/- excess for collision/damage to first party, (i.e.) B & O VEHICLE RENTAL (including windscreen) plus loss of earnings while damaged vehicle is under repair.

Authorised Driver

Hirer shall pay additional excess of S\$1500 if the Authorised Driver is below the age of 25 or is above 65 years old or has less than 2 years driving experience.

Driver Not Cover By Insurance

General Exception: Insurance policy does not cover against any driver aged below 22 and/or above 70 years old and/or with driving experience of 1 year and below.

Deposit (Refundable): _____

Sub-Total: _____

Balance To Pay: 1000

PETROL/DIESEL AT YOUR OWN EXPENSE
FOR LOCAL USE ONLY

B & O VEHICLE RENTAL

Authorised Signature

Hirer's Signature

VIN'S AUTO PTE LTD

160 SIN MING DRIVE, SIN MING AUTOCITY, #03-03, SINGAPORE 575722. TEL: 6453 2121 (4 LINES) FAX: 6459 9795

OFFICIAL RECEIPT 0625

Date, 10-10-2017

Received from KEO KAH KAT

the sum of Eighty dollars only.

being payment of Towing fee for SLF 3201T
Honda Vezel (Two Trip.)

\$80

VIN'S AUTO PTE LTD

Authorised Signature

② Cash/Chicque No.: _____

MOTOR DISCHARGE VOUCHER

POLICY NO :

CLAIM NO : CLMDWVP000000392


Agree to accept from

the sum of DOLLARS

_____ (S\$) ONLY in full settlement of my/our
windscreen damage claim upon the said Company of the above said policy for loss, damage and
expenses caused by the accident which occurred on 10-10-2017 to the insured vehicle and
I/we hereby declare that the repairs to insured vehicle have been satisfactorily executed, I/we
herewith discharge the said Company without reserve from any liability to pay further claims arising
from the above mentioned accident.

VEHICLE NO : SLF32017

Insured Signature



(Company stamp if applicable)

APPROVED ESTIMATE

DATE	11-Oct-17		
SNO	QTY	Part	List Price
1	1	Front bonnet	892.30
2	1	Front bonnet insulator	187.30
3	1	Front bonnet lock	187.70
4	2	Front bonnet hinges	69.10
5	1	Front bumper	659.80
6	1	Front bumper reinforcement	386.10
7	2	Front bumper bracket	126.60
8	2	Front bumper side retainer	112.80
9	1	Front bumper clip	5.20
10	1	Front Bumper Upper Grill	328.30
11	2	Front Bumper Upper Grill Chrome	283.30
12	1	Front Bumper Upper Grill Logo	58.30
13	1	Front Bumper Middle Grill	69.30
14	1	Front bumper lower Mesh	177.50
15	1	Front bumper lower Skirt	190.60
16	2	Front bumper fog lamp	637.80
17	1	Front support panel	491.30
18	1	Front support panel garnish	151.60
19	2	Front headlamp	3112.40
20	2	Front headlamp panel	982.60
21	1	Radiator Assy	1387.50
22	1	Radiator fan motor	372.70
23	1	Radiator fan cowl	206.30
24	1	Radiator fan blade	155.50
25	1	Radiator top hose	57.50
26	1	Air con condenser	868.10
27	1	Air duct Top	141.70
28	1	wiper tank	156.10
29	1	Wiper tank motor	257.90
30	1	Radiator spare tank	125.20
31	1	Front lower member	1740.80
32	1	Front lower member garnish	196.80
33	1	Steering airbag	1840.80
34	1	Steering Clock Spring	353.10
35	1	Dashboard air bag	2236.80
36	1	Dashboard	1750.50
37	1	Roof top air bag	860.20
38	1	Front door pillar garnish	158.90
39	1	Front driver seat air bag	738.10
40	2	AirBag sensor	659.00
SUBTOTAL			23322.70
APPROVED ESTIMATE			
			ADDITIONAL
1	1	Front wheel arch garnish	272.10
2	1	Front fender	1075.00
3	1	Radiator Bottom Hose	51.60
4	1	Air con suction pipe	223.70
5	1	Aircon discharge pipe	283.50
6	1	Aircon Liquid Pipe	346.90
7	1	Air con compressor	1585.60
8	1	Air con belt	190.40
9	1	Belt Tensioner	273.20
10	1	Alternator	1467.40
11	1	Air con temperature sensor	149.50
12	1	Front door pillar air bag	643.20
13	1	Engine Mounting	172.70
14	1	Radiator Neck	93.10
15	1	Roof Lining Piece (Torn)	750.00
16	1	Airbag SRS ECU (Activated)	1316.70
17	1	Front chassis frame Repair	750.00
18	1	Water Pump	291.40
19	1	ATF Cooler	371.80
20	1	Starter	1228.80
RESURVEY ESTIMATE			
(Approved)			
FINAL TOTAL			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts Et Automobiles

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI17019379/T1tbe2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 12-01-2018



Code : GAI

1. Policy Particulars - OWN DAMAGE

Insured Veh.		Veh. Inspected	SLF 3201T
Policy No.	MOMVP000002581-00-000	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	SHARON NG	Assign Date	10/10/2017

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL 1.5X	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11118029	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	6 mm
L/H Front Tyre	215/60 R16	DUNLOP	6 mm
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/10/2017	Inspection Date	12/10/2017
Survey held at	EDWIN GARAGE 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-295 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569535		

5a. Remarks

A)THE MARKET VALUE IS S\$85,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	14 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 3201T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET	BENT	892.30	892.30
1	FRONT BONNET INSULATOR	DEFORMED	187.38	187.30
1	FRONT BONNET LOCK	BENT	187.70	187.70
1	FRONT BONNET LOCK CATCH (NPA)	NOT NECESSARY	-	-
1	FRONT BONNET LOCK GARNISH (NPA)	NOT NECESSARY	-	-
2	FRONT BONNET HINGES	BENT	69.10	69.10
1	FRONT BUMPER	DEFORMED	659.80	659.80
1	FRONT BUMPER REINFORCEMENT	BENT	386.10	386.10
2	FRONT BUMPER BRACKET	NECESSARY	126.60	126.60
2	FRONT BUMPER SIDE RETAINER	NECESSARY	112.80	112.80
1	FRONT BUMPER CLIP	NECESSARY	5.20	5.20
1	FRONT BUMPER UPPER GRILL	DEFORMED	328.30	328.30
2	FRONT BUMPER UPPER GRILL CHROME	DISTORTED	283.30	283.30
1	FRONT BUMPER UPPER GRILL LOGO	NECESSARY	58.30	58.30
1	FRONT BUMPER MIDDLE GRILLE	DEFORMED	69.30	69.30
1	FRONT BUMPER LOWER MESH	DEFORMED	177.50	177.50
1	FRONT BUMPER LOWER SKIRT	DEFORMED	190.60	190.60
2	FRONT BUMPER FOG LAMP	DISTORTED	637.80	637.80
1	FRONT SUPPORT PANEL	BENT	491.30	491.30
1	FRONT SUPPORT PANEL GARNISH	DEFORMED	151.60	151.60
2	FRONT HEADLAMP	CRACKED	3,112.40	3,112.40
2	FRONT HEADLAMP PANEL	BENT	982.60	982.60
1	RADIATOR ASSY	BENT	1,387.50	1,387.50
1	RADIATOR FAN ASSY	NOT NECESSARY	322.70	322.70
1	RADIATOR FAN COWLING	CRACKED	206.30	206.30
1	RADIATOR FAN BLADE	JAMMED	155.50	155.50
1	RADIATOR TOP HOSE	TWISTED	57.30	57.30
1	RADIATOR BOTTOM HOSE	DEFORMED	51.60	51.60
1	AIR CON CONDENSER	BENT	868.10	868.10
1	AIR CON SUCTION PIPE	BENT	223.70	223.70
1	AIRCON DISCHARGE PIPE	BENT	283.50	283.50

Report Ref No. CS/GAI17019379/T1tbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate by Workshop (\$)	Oil Adjusted (\$)
1	AIR CON COMPRESSOR	BENT	1,585.60	1,585.60
1	AIR CON BELT	TORN	190.40	190.40
1	BELT TENSIONER	DISTORTED	273.20	273.20
1	ALTERNATOR	BENT	1,467.40	1,467.40
1	AIR DUCT TOP	DEFORMED	141.70	141.70
2	AIR FLAP COVER SIDE (NPA)	NOT NECESSARY	-	-
1	WIPER TANK	DEFORMED	156.10	156.10
1	WIPER TANK MOTOR	DEFORMED	257.90	257.90
1	RADIATOR SPARE TANK	DEFORMED	125.20	125.20
1	FRONT LOWER MEMBER	BENT	1,740.80	1,740.80
1	FRONT LOWER MEMBER GARNISH	DEFORMED	196.80	196.80
2	FRONT CHASSIS FRAME	TO REPAIR SEE LABOUR	750.00	-
2	WIPER ARM	NOT NECESSARY	157.30	-
2	WIPER BLADE	NOT NECESSARY	188.70	-
2	WIPER MOTOR	NOT NECESSARY	420.80	-
1	WIPER LINK	NOT NECESSARY	256.30	-
1	INTAKE MANIFOLD COVER	NOT NECESSARY	462.10	-
1	STEERING AIRBAG	ACTIVATED	1,840.30	1,840.30
1	STEERING RING	NOT NECESSARY	802.30	-
1	STEERING WHEEL	NOT NECESSARY	802.30	-
1	STEERING COLUMN	NOT NECESSARY	1,729.30	-
1	STEERING CLOCK SPRING	ACTIVATED	353.10	353.10
1	DASHBOARD AIR BAG	ACTIVATED	2,236.80	2,236.80
1	DASHBOARD	DEFORMED	1,750.50	1,750.50
2	DASHBOARD SPEAKER GARNISH (NPA)	NOT NECESSARY	-	-
1	ROOF TOP AIR BAG	ACTIVATED	860.20	860.20
1	ROOF LINING PIECE	DEFORMED	750.00	750.00
1	FRONT DOOR PILLAR AIR BAG	ACTIVATED	643.20	643.20
1	FRONT DOOR PILLAR GARNISH	DEFORMED	158.90	158.90
1	FRONT DRIVER SEAT AIR BAG	ACTIVATED	738.10	738.10
1	FRONT DRIVER SEAT (NPA)	NOT NECESSARY	-	-
1	AIR CON TEMPERATURE SENSOR	DISTORTED	149.50	149.50

Report Ref No. CS/GAI17019379/T1tbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Old Adjusted (\$)
3	AIRBAG SENSOR	ACTIVATED	659.00	659.00
1	ABS UNIT	NOT NECESSARY	963.50	-
1	RELAY BOX	NOT NECESSARY	396.40	-
2	FRONT WHEEL ARCH GARNISH	MISSING	272.10	272.10
2	FRONT FENDER	BENT	1,075.00	1,075.00
1	AIRCON LIQUID PIPE (ADDITIONAL)	BENT	346.90	346.90
1	ENGINE MOUNTING (ADDITIONAL)	BENT	172.70	172.70
1	RADIATOR NECK (ADDITIONAL)	DEFORMED	93.10	93.10
1	AIR BAG SRS ECU (ADDITIONAL)	ACTIVATED	1,316.70	1,316.70
1	WATER PUMP (ADDITIONAL)	BENT	291.40	291.40
1	ATF COOLER (ADDITIONAL)	BENT	371.80	371.80
1	STARTER (ADDITIONAL)	DISTORTED	1,228.80	1,228.80
	LESS 20% DISCOUNT		-	-6,821.86
			41,038.38	27,287.44
	LABOUR			
	TO REMOVE AND REFIT GARNISH, UPHOLSTERY AND ETC TO FACILITATE REPAIR.		180.00	100.00
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF FRONT CHASSIS FRAME.		2,200.00	1,800.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		1,800.00	1,500.00
	TO APPLY RUST PROOFING ON AFFECTED AREAS.		220.00	100.00
	TO CHECK WIRING.		300.00	100.00
	TO REMOVE AND REFIT RADIATOR AND TOP COOLANT.		120.00	-
	TO REMOVE AND REFIT AIRCON CONDENSER AND TOP UP GAS.		120.00	100.00
	CAR-O-LINER.	NOT NECESSARY	600.00	-
	TOWING.		80.00	80.00
			-	-
			-	-
			5,620.00	3,780.00
GRAND TOTAL			46,658.38	31,067.44

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			24,700.00
---	--	--	------------------

Report Ref No. CS/GAI17019379/T1tbe2



Report Ref No. CS/GAI17019379/T1tbe2

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.