

ASS. REC. BY:

REF:

CS/FCI17019435/626⁷²

Special Instruction:

Survivor:

CWS

GQ

ASSIGNMENT (Office)

From (Person):

Sithara

of

FCI

Estimated Cost:

Date/Time: 10/10/17 @ 2.24pm

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJH 9596C

Insured:

SHD 8502 A

at Workshop m/s

Trans EuroKars

Tel:

63958685 / 96185991 / 91277928

of

5 UB1 close

Policy No:

Claim No:

D17009487MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 4/10/17

CA / REV / REP. / REV 24 HRS

lwp

17/10/17 @ 9am owner writing

Date/Time: 10/10/17 @ 2.54pm

Person Contacted:

Ronald

H.O.D. Endorsement

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SJH 9596C - CC3 / AIG 17019190 / K1ka3 - D.O.A: 4/10/17
	SHD 8502 A - CC3 / AIG 17019190 / K1ka3 - D.O.A: 4/10/17
10/10/17 @ 1.54pm	revised to Sithara by email.
08/10/18 @ 5.15pm	checked with Catherine Chua, according to Ronald, the vehicle was not sent in for repair due to awaiting liability issued.
09/10/18	Submit radi. report.

(08/11/13)

AS S. REC. BY:

REF:

Fci

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Trans Eurokars

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STU9596C Yr Regn: 18 Nov 2015Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 6 C.C. 2488Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 21416 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: IM6GJ1032G 0220914Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/55 R17R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 17-10-17Survey held at W/S 9AMDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

RECEIVED 09 OCT 2018.

Date/Time, File Pass to?



: Preli. Report

1) 04/10/2018

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS _____ \$

Photos _____

Others _____

TOTAL

Add Fee:



Site Insp (\$ _____)



Interview (\$ _____)



Tech. Invs (\$ _____)



Weekend (\$ _____)

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

160

50

16

226



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17019435/Gqb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-10-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 8502A	Veh. Inspected	SJH 9596C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17009487MFSH	Excess (\$)	0.00	
Assign From	CWS (SITHARA)	Assign Date	10/10/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	04/10/2017	Inspection Date		
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17009487MFSH
Our Ref: CS/FCI17019435/Gqb

Date: 19 October 2017

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJH 9596C

Please be informed that we had conducted the inspection of the abovementioned vehicle on 17/10/2017 at the premises of M/s TRANS EUROKARS, and have the following to report:-


Workshop Estimate Amount	: S\$ 8,554.78
Revised Estimate Amount	: S\$ 6,379.05
"Check" Items Amount	: S\$ -
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:
The vehicle sustained damages
at the n/s body.

Pending for parts prices.

Yours faithfully

Guo Qiang
Automotive Assessor



MOTOR SURVEY ASSIGNMENT

Date	06-10-2017	Our Ref No. D17009487MFSH
Accident Date	04-10-2017	Claim Type. Third Party
Insured Vehicle	SHD8502A	Third Party Vehicle. SJH9596C
Survey Location	5 UBI CLOSE	
Contact Person.	ERIC PAU	
Contact No.	63958685/ 96185991	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS EUROKARS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/228850)



PRI Documents



Close



PRI Header Details

Claim No	D17009487MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & TRANS EU
Workshop Name	TRANS EUOKARS PTE LTD (Contact Person : ERIC PAU)	Survey Location & Contact Details	5 UBI CLOSE Mobile: 96185991 , Phone: 63958685 , Fax: 0 EmailId: ERIC.PAU@EUOKARS.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHD8502A	TP Vehicle No	SJH9596C
PRI Recieved Date	09-10-2017 03:17:32 PM	Surveyor Appointed Date	10-10-2017 02:23:23 PM	Surveyor Accept Date	10-10-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	10-10-2017	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 19 October, 2017 1:54 PM
To: 'Claim Workflow System'; assignments
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17009487MFSH/1
Attachments: CSFCI17019435Gqb.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SJH 9596C.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 10 October, 2017 4:40 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17009487MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Tuesday, 10 October, 2017 2:23 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SITHARA@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17009487MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	2555C
Vehicle Details	
Vehicle No.	SJH9596C
Vehicle to be Exported	No
Intended De-registration Date	17 Oct 2017
Vehicle Make	MAZDA
Vehicle Model	MAZDA6 4-DOOR SEDAN 2.5L SP.6EAT SR LED
Primary Colour	Blue
Manufacturing Year	2015
Engine No.	PY20664965
Chassis No.	JM6GJ1032G0220914
Maximum Power Output	141.0 kW (189 bhp)
Open Market Value	\$23,481.00
Original Registration Date	18 Nov 2015
First Registration Date	18 Nov 2015
Transfer Count	0
Actual ARF Paid	\$24,874.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	17 Nov 2025
PARF Rebate Amount	\$18,655.00
Intended COE Rebate Details	
COE Expiry Date	17 Nov 2025
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$62,140.00
COE Rebate Amount	\$50,229.00
Total Rebate Amount	\$68,884.00

The information contained herein is correct as at 17 Oct 2017

OK



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
QUOTATION



FIRST CAPITAL INSURANCE LTD		NAME : Mr Chang Fu Gui	WIP : 36366
36 ROBINSON ROAD		ADDRESS : 25 Akyab Rd	EXCESS :
#16-01 CITY HOUSE		#20-05	DATE: 7-Oct-17
SINGAPORE 068877		Singapore 309979	
ATTN. :	MOTOR CLAIMS	TEL : 93664116	
FAX :			
VEH NO :	SJH9596C	DATE IN :	CONTACT PERSON : RONALD 6395 7875
CHASSIS NO :	JM6GJ1032G0220914	MILEAGE :	TYPE OF CLAIM : THIRD PARTY CLAIM
MODEL :	MAZDA6 2.5L SDN	DATE REG.: 18-Nov-15	POLICY NO. :

NATURE OF WORKS

<u>Parts Description</u>				
NO	QTY	REVISED	PRICES	
1	LHS REAR DOOR <i>✓ Blue</i>	1	MGHY1-73-02XB	\$ 1,249.60
2	HINGE LOWER(LHS), REAR DOOR <i>X</i>	1	MKD53-73-240	\$ 42.60
3	HINGE UPPER(LHS), REAR DOOR <i>X</i>	1	MKD53-73-210	\$ 46.00
4	CHROME(LHS), REAR DOOR <i>X</i>	1	MGHK1-50-670E	\$ 80.60
5	STRIPE SIDE(LHS), REAR DOOR <i>✓</i>	1	MGHP9-50-8W2 00	\$ 14.00
6	STRIPE UPPER(LHS), REAR DOOR <i>✓</i>	1	MGHK1-50-8W4 00	\$ 22.70
7	FASTENER, REAR DOOR <i>✓</i>	1	MGHP9-73-762	\$ 11.70
8	FASTENER, REAR DOOR <i>✓</i>	1	MGD7A-50-EA1	\$ 3.00
9	PIN-CATCH, REAR DOOR <i>✓</i>	1	MBN8F-72-917	\$ 10.40
10	CLIP, REAR DOOR <i>✓</i>	1	MGS1D-58-315A	\$ 2.20
11	GROMMET, REAR DOOR <i>✓</i>	2	MBF67-51-261	\$ 4.40
12	GROMMET, REAR DOOR <i>✓</i>	1	M9991-00-503	\$ 3.60
13	GROMMET, REAR DOOR <i>✓</i>	7	MGJ6A-58-975	\$ 19.60
14	CLIP, DOOR GARNISH <i>✓</i>	5	MKD53-50-M38	\$ 58.50
15	GROMMET, DOOR SPEAKER <i>✓</i>	4	MGJ6A-58-975	\$ 11.20
16	GUARD(LHS), STONE <i>✓</i>	1	MGHP9-50-4R2A	\$ 16.50
17	WHEEL,DISC (LHR) <i>✓ Cut</i>	1	M9965-07-7570	\$ 1,277.10
18	CAP,CENTER (LHR) <i>X NN</i>	1	MKD51-37-190	\$ 20.50
TOTAL PARTS				\$ 2,894.20
LESS 10%				\$ 289.42
TOTAL PARTS COST				\$ 2,604.78

Labour Description

1	TO REPLACE LHS REAR DOOR. TO REPAIR LHS REAR FENDER AND ALL AREAS AFFECTED BY THE ACCIDENT.	1260	\$ 1,890.00
2	TO RESPRAY LHS REAR DOOR AND LHS REAR FENDER.	1200	\$ 1,800.00

3	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	150	\$	250.00
4	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.	315	\$	630.00
5	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.	80	NETT	\$ 120.00
6	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	✓	NETT	\$ 560.00
7	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$	250.00
8	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$	350.00
9	MZ-BR-SUNDRI	SUNDRIES.	50	NETT	\$ 100.00 net

TOTAL LABOUR	\$ -	\$ 5,950.00
TOTAL PARTS	\$ -	\$ 2,604.78
TOTAL	\$ -	\$ 8,554.78
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

5 Days.

before paint photos.

Guo Qiang - 8288 0282.

17/10/17.

[Handwritten Signature]
19/10/17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17019435/Gqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 8502A	Veh. Inspected	SJH 9596C	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17009487MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	10/10/2017	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 6	c.c	2488	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JM6GJ1032G0220914	Colour	BLUE	
Odometer	21416	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	YOKOHAMA	6 mm	
L/H Front Tyre	225/55 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	225/55 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	225/55 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/10/2017	Inspection Date	17/10/2017	
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605			
5a. Remarks				
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)DAMAGES CONSISTENT TO ACCIDENT REPORT. C)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. D)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 9596C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	LHS REAR DOOR	BUCKLED	1,249.60	1,249.60
1	HINGE LOWER (LHS),REAR DOOR	NOT NECESSARY	42.60	-
1	HINGE UPPER (LHS),REAR DOOR	NOT NECESSARY	46.00	-
1	CHROME (LHS),REAR DOOR	NOT NECESSARY	80.60	-
1	STRIPE SIDE (LHS),REAR DOOR	NECESSARY	14.00	14.00
1	STRIPE UPPER (LHS),REAR DOOR	NECESSARY	22.70	22.70
1	FASTENER REAR DOOR	NECESSARY	11.70	11.70
1	FASTENER REAR DOOR	NECESSARY	3.00	3.00
1	PIN-CATCH,REAR DOOR	NECESSARY	10.40	10.40
1	CLIP,REAR DOOR	NECESSARY	2.20	2.20
2	GROMMET,REAR DOOR	NECESSARY	4.40	4.40
1	GROMMET,REAR DOOR	NECESSARY	3.60	3.60
7	GROMMET,REAR DOOR	NECESSARY	19.60	19.60
5	CLIP,DOOR GARNISH	NECESSARY	58.50	58.50
4	GROMMET,DOOR SPEAKER	NECESSARY	11.20	11.20
1	GUARD (LHS),STONE	NECESSARY	16.50	16.50
1	WHEEL,DISC (LHR)	CUT	1,277.10	1,277.10
1	CAP,CENTER (LHR)	NOT NECESSARY	20.50	-
	LESS 10% DISCOUNT		-289.42	-270.45
			2,604.78	2,434.05
SPECIAL NETT ITEMS				
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
			100.00	50.00
LABOUR				
	TO REPLACE LHS REAR DOOR.TO REPAIR LHS REAR FENDER AND ALL AREAS AFFECTED BY THE ACCIDENT.		1,890.00	1,260.00
	TO RESPRAY LHS REAR DOOR AND LHS REAR FENDER.		1,800.00	1,200.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.		250.00	150.00
	TO TRANSFER THE DOOR MECHANISM.		630.00	315.00
	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.		120.00	80.00

Report Ref No. CS/FCI17019435/Gqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.		560.00	560.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	180.00
			5,850.00	3,895.00
GRAND TOTAL			8,554.78	6,379.05
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)				6,379.05

Report Ref No. CS/FCI17019435/Gqbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.