

11/03/2017

ASS. REC. BY:

REF:

CS/MSH17019454/Rigby

Special Instruction:

SUN/10/

Rasul

ASSIGNMENT (Office)

From (Person):

Soslin Jim

of

MSIG

Date/Time: 11/10/17 @ 1028 am

Estimated Cost:

Bill to:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCA 75T

Insured:

at Workshop m/s

Wearnes Automotive

Tel:

917 68543

of

249 Alexandra Rd, 159935

Policy No:

A2864577MCY

Claim No:

532172

Sum Insured:

Excess:

\$ 900.00

Make of Veh:

(Client's Record)

D.O.A. 03/10/2017

CA / ☒ REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11/10/17 @ 11:07 am

Person Contacted:

Richmond

Vehicle ☒ OUT

Date/Time

Action/Instruction

☒ Estimate

SCA 75T - CS/UCL11007205/Ubn

D.O.A. 15052011

Signature: Rabe

REF:

01510

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
☒ TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: SCA 75 T
at Workshop m/s WEARNES
of 249, ALEXANDRA RD
Insured: msia/00
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: 900
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 285K
IDAQ Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 10 days Res.: Yes or No
Lum Sum: 1-B-1 % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SCA 75 T Yr Regn: 2014 / NOV
Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Land Rover Range Rover 3.0 c.c. 2993
Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: 062793 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: SALWALKE 3FA505103
Gen. Cond: Good / ☒ Fair / Poor / Burnt
Steering: ☒ In order / Jammed / Leaked / Burnt or
Brake: ☒ In order / Jammed / Leaked / Burnt or
Modi: Nil / ☒ SRim / STD A/Rim or
Tyre Size: F: 265/50R20
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / ☒ YOKO or _____

Front		Rear	
R/Bal.	<u>6</u> mm	R/Bal.	<u>6</u> mm
L/Bal.	<u>6</u> mm	L/Bal.	<u>6</u> mm
D.O.A.	<u>03/10/17</u>	D.O.I.	<u>11/10/17</u>

Survey held at WEARNES

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
12/10/17	REV in merimen.
13/10/17	Mandate approved by Huey Nt.
13/10/17	@ 4.30 pm email to Richmond, CA, EX: 900
28/12/17	confirmed final fig \$32007 with Richmond. (Red: 15597.42, 33%).

RECEIVED 2 DEC 2017

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 10

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee: 450

Transportation: _____

☐ S + RS SI

☐ Photos

☐ Others

TOTAL

Report Format: OD

Lump Sum / ☒ B1: (\$ 32007)

450

10

460



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17019494/R1gb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 11-10-2017



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SCA 75T
Policy No.	Coverage (\$)	0.00
Claim No. 532172	Excess (\$)	900.00
Assign From MERIMEN (JOSLIN LIM)	Assign Date	11/10/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	03/10/2017	Inspection Date	11/10/2017
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		

5a. Remarks

- A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Oct 2017		11 Oct 2017 10:08 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	BENG SOON MACHINERY SERVICES (S)PTE LTD , Co. Reg. No.: 199300151D		
Vehicle Reg. No.:	SCA75T	Date of Loss:	03/10/2017 21:00 - :59
Claim Type:	OD / 532172	Policy/Cover Note No.:	A28641577MCY (Comprehensive) Coverage: 28/11/2016 - 27/11/2017
		Excess:	S\$900.00
Repairer:	Wearnes Automotive Pte Ltd (Alexandra Road) 249 Alexandra Road, 159935 Alexandra - Tel: 63789370		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/10/2017]		
Driver/Custodian:	TAN CHEE BENG (62 / Male), NRIC: S1014656I, Tel: +6590111280		
Adj Asg. Remarks:	Please revert. (car-in)		

[View All](#)[Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Ai Phing (LKKAuto)

From: Ai Phing (LKKAuto)
Sent: Thursday, 28 December, 2017 4:54 PM
To: 'Richmond Ho'
Subject: RE: MSIG-OD Claim For SCA75T (DOA 03-10-2017)

Dear Richmond,

Confirmed final fig \$32,007.00 before Excess \$900 and GST.

***Please note as spoken with Rasul, FENDER-FRONT LH \$1,475.50 to remove.**

10 days of repair.

Please send DV and invoice direct to MSIG.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Richmond Ho [<mailto:richmond.ho@wearnes.com>]
Sent: Friday, 22 December, 2017 4:07 PM
To: Ai Phing (LKKAuto) <aiphing@lkkauto.com>
Subject: RE: MSIG-OD Claim For SCA75T (DOA 03-10-2017)
Importance: High

Hi Ai Phing,

Please refer to above attachment for the final bill.

Richmond Ho
Senior Service Consultant
Body & Paint – Insurance Claim



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
D (65) 6430 4890 M (65) 9176 8543
www.wearnesauto.com richmond.ho@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

Ai Phing (LKKAuto)

From: Ai Phing (LKKAuto)
Sent: Friday, 13 October, 2017 4:32 PM
To: Richmond Ho
Cc: SUR
Subject: RE: MSIG-OD Claim For SCA75T (DOA 03-10-2017)

Dear Richmond,

As instructed by our client, please proceed to repair the insured vehicle **SCA 75T (Excess \$900)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Ai Phing (LKKAuto)
Sent: Friday, 13 October, 2017 11:56 AM
To: Richmond Ho <richmond.ho@wearnes.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD Claim For SCA75T

Dear Richmond,

We are still pending MSIG approval.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	09 Oct 2017 09:47	Clim Veh Model Changed	(205353) LAND ROVER RANGE ROVER SPORT 3.0 TSS 7S SR (A).	[I] Joslin Lim
2	09 Oct 2017 09:47	Clim Created	Reg No: SCA75T, Policy No: A28641577MCY, Acct Date: 2017/10/03, Claim Type: SC, Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ), Ins.Status => Notification, Created from SAS:MSMM17132539	[I] Joslin Lim
3	10 Oct 2017 16:31	Notification Status Changed	Ins.Status => Incoming Claim	[I] Joslin Lim
4	10 Oct 2017 16:31	Clim Registration Modified	Setl.Type:3->0, Rep:1137->200084, Claim Type:SC->OD.	[I] Joslin Lim
5	10 Oct 2017 16:41	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):Please revert.	[I] Joslin Lim
6	10 Oct 2017 16:41	Adj Next Rpt Changed	Next Rpt:Im, Advice.Due Date:2017/10/11	[I] Joslin Lim
7	10 Oct 2017 16:41	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Joslin Lim
8	11 Oct 2017 09:33	Assignment 1st Accessed		[A] Ho Pei Fang
9	11 Oct 2017 10:07	Adj Assignment Cancelled	Est > \$40K	[I] Joslin Lim
10	11 Oct 2017 10:07	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Joslin Lim
11	11 Oct 2017 10:08	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please revert. (car-in)	[I] Joslin Lim
12	11 Oct 2017 10:08	Adj Next Rpt Changed	Next Rpt:Im, Advice.Due Date:2017/10/12	[I] Joslin Lim
13	11 Oct 2017 10:08	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Joslin Lim
14	11 Oct 2017 10:59	Assignment 1st Accessed		[A] Nivitha Govindasamy
15	11 Oct 2017 14:14	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] CATHERINE CHONG KAI LING
16	12 Oct 2017 14:59	Adj Rpt Initiated		[A] LOW AI PHING
17	12 Oct 2017 15:15	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/11/10	[A] LOW AI PHING
18	12 Oct 2017 15:15	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/11/10	[A] LOW AI PHING
19	12 Oct 2017 15:26	Adj Mandate Request	Cur.Reg:34009.80:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL.	[A] LOW AI PHING
20	13 Oct 2017 16:18	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/11/10, Mandate Remarks: Approved mandate \$34009.80 (including check items \$2889.30) before excess \$900	[I] Eng Huey Ni
21	13 Oct 2017 16:18	Adj Mandate Set	Approved:34009.80:Approved mandate \$34009.80 (including check items \$2889.30) before excess \$900	[I] Eng Huey Ni
22	27 Dec 2017 12:08	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/11/10	[A] LOW AI PHING
23	27 Dec 2017 12:09	Adj Mandate Request	Cur.Reg:32007.00:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL, PLEASE ASSIST SUPPLEMENTARY APPROVAL.	[A] LOW AI PHING
24	28 Dec 2017 16:45	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/11/10, Mandate Remarks: Approved mandate \$32,007.00 (including supplementary items \$773.20) before excess \$900	[I] Eng Huey Ni
25	28 Dec 2017 16:45	Adj Mandate Set	Approved:32007.00:Approved mandate \$32,007.00 (including supplementary items \$773.20) before excess \$900	[I] Eng Huey Ni

ACTIVITY

[11/10/2017 09:37] Ho Pei Fang:
As per Daniel's instructions, to outsource case as est more than 40k

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1609030	12/10/2017 14:59	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SCA75T		10.70

Claim Audit

AUDIT TRAIL				By
No.	On	Audit	Remarks	
1	09 Oct 2017 09:47	Cim Veh Model Changed	(205353) LAND ROVER RANGE ROVER SPORT 3.0 TSS 75 SR (A). Reg No: SCA75T. Policy No: A28641577MCY. Acct Date: 2017/10/03. Claim Type: SC. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Ins.Status => Notification. Created from SAS:MSMM17132539	[1] Joslin Lim
2	09 Oct 2017 09:47	Cim Created	Ins.Status => Incoming Claim	[1] Joslin Lim
3	10 Oct 2017 16:31	Notification Status Changed	Setl.Type:3->0. Rep:1137->200084. Claim Type:SC->OD.	[1] Joslin Lim
4	10 Oct 2017 16:31	Cim Registration Modified	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):Please revert.	[1] Joslin Lim
5	10 Oct 2017 16:41	Adj Co Assigned	Next Rpt:Im. Advice.Due Date:2017/10/11	[1] Joslin Lim
6	10 Oct 2017 16:41	Adj Next Rpt Changed	Approved:25000.00.Reinsp:Adj decides.	[1] Joslin Lim
7	10 Oct 2017 16:41	Adj Mandate Set		[A] Ho Pei Fang
8	11 Oct 2017 09:33	Assignment 1st Accessed	Est > \$40K	[1] Joslin Lim
9	11 Oct 2017 10:07	Adj Assignment Cancelled	Deleting Est Details For Cancelling Adjuster Assignment	[1] Joslin Lim
10	11 Oct 2017 10:07	Adj Est Details Deleted	LKK Auto Consultants Pte Ltd (HQ):Please revert. (car-in)	[1] Joslin Lim
11	11 Oct 2017 10:08	Adj Co Assigned	Next Rpt:Im. Advice.Due Date:2017/10/12	[1] Joslin Lim
12	11 Oct 2017 10:08	Adj Next Rpt Changed	Approved:25000.00.Reinsp:Adj decides.	[1] Joslin Lim
13	11 Oct 2017 10:08	Adj Mandate Set		[A] Nivitha Govindasamy
14	11 Oct 2017 10:59	Assignment 1st Accessed		[A] CATHERINE CHONG KAI LING
15	11 Oct 2017 14:14	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] LOW AI PHING
16	12 Oct 2017 14:59	Adj Rpt Initiated		[A] LOW AI PHING
17	12 Oct 2017 15:15	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/11/10	[A] LOW AI PHING
18	12 Oct 2017 15:15	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/11/10	[A] LOW AI PHING
19	12 Oct 2017 15:26	Adj Mandate Request	Cur.Req:34009.80:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.	[1] Eng Huey Ni
20	13 Oct 2017 16:18	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/11/10. Mandate Remarks: Approved mandate \$34009.80 (including check items \$2889.30) before excess \$900	[1] Eng Huey Ni
21	13 Oct 2017 16:18	Adj Mandate Set	Approved:34009.80:Approved mandate \$34009.80 (including check items \$2889.30) before excess \$900	

ACTIVITY

[11/10/2017 09:37] Ho Pei Fang:
As per Daniel's instructions, to outsource case as est more than 40k

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1609030	12/10/2017 14:59	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SCA75T		10.70

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joslin Lim

Date: 27 Dec 2017

Preliminary Advice

Vehicle No	: SCA75T	Accident Date	: 03/10/2017
Make	: LAND ROVER RANGE ROVER SPORT	Policy No.	: A28641577MCY
Assignment Date	: 11/10/2017	Excess	: S\$900.00
Date of Inspection	: 11/10/2017	Est. Duration of Repair	: 10.00
Inspection At	: WEARNES AUTOMOTIVE PTE LTD (ALEXANDRA ROAD) 249 ALEXANDRA ROAD SINGAPORE 159935		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	47,604.42	(with Supplementary \$773.20)
Revised Amount	:S\$	32,007.00	(with Supplementary \$773.20)
Check Items (Estimated)	:S\$	-	
Total	:S\$	32,007.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	285,000.00
COE / PARF Rebate	:S\$	154,423.00
Salvage Value	:S\$	
Margin for Repair	:S\$	130,577.00

Remarks

(X) The vehicle is economical for repair.

Please assist supplementary approval.

() The above survey was conducted on a 'without prejudice' basis.

Adjuster Immediate Advice

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joslin Lim

Date: 12 Oct 2017

Preliminary Advice

Vehicle No	: SCA75T	Accident Date	: 03/10/2017
Make	: LAND ROVER RANGE ROVER SPORT	Policy No.	: A28641577MCY
Assignment Date	: 11/10/2017	Excess	: S\$900.00
Date of Inspection	: 11/10/2017	Est. Duration of Repair	: 10.00
Inspection At	: WEARNES AUTOMOTIVE PTE LTD (ALEXANDRA ROAD) 249 ALEXANDRA ROAD SINGAPORE 159935		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	46,777.10
Revised Amount	:S\$	31,120.50
Check Items (Estimated)	:S\$	2,889.30
Total	:S\$	34,009.80
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	285,000.00
COE / PARF Rebate	:S\$	154,423.00
Salvage Value	:S\$	
Margin for Repair	:S\$	130,577.00

Remarks

- (X) The vehicle is economical for repair.
We have not authorise repair.
- () The above survey was conducted on a 'without prejudice' basis.

A A A

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0151D
Vehicle Details	
Vehicle No.:	SCA75T
Vehicle to be Exported:	No
Intended De-registration Date:	12 Oct 2017
Vehicle Make:	LAND ROVER
Vehicle Model:	RANGE ROVER SPORT 3.0D TSS
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	0877648306DT
Chassis No.:	SALWA2KE3FA505103
Maximum Power Output:	215.0 kW (288 bhp)
Open Market Value:	\$92,529.00
Original Registration Date:	<u>28 Nov 2014</u>
First Registration Date:	28 Nov 2014
0	

Transfer Count:	
Actual ARF Paid:	\$138,553.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Nov 2024
PARF Rebate Amount:	\$103,914.00
Intended COE Rebate Details	
COE Expiry Date:	27 Nov 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$70,890.00
COE Rebate Amount:	\$50,509.00
Total Rebate Amount:	\$154,423.00

The information contained herein is correct as at 12 Oct 2017

OK

285,000

154,423

130,577

Land Transport Authority (<https://www.lta.gov.sg>)

Please read through the Privacy Statement, Terms of Use, and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)

[Rate this e-Service \(https://www.lta.gov.sg/feedback/PublicSurvey.aspx?SurveyDetlNum=5201400011\)](https://www.lta.gov.sg/feedback/PublicSurvey.aspx?SurveyDetlNum=5201400011)

Last updated on 08 Oct 2017 at 01:03 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 06/10/2017 13:03
Date Of Accident 03/10/2017 21:00
Exact Location Of Accident 75 WOLSKEL ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SCA75T
Insured/Policyholder
Name Of Registered Owner BENG SOON MACHINERY SERVICES (S)PTE LTD
Co Reg No 199300151D
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-90111280
Alternative Phone No OFFICE-90111280

Vehicle Particulars

Manufacturer LAND ROVER
Model RANGE ROVER SPORT-3.0 TSS 7S SR (A)
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? YES
If No, Please state action to be taken
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number A28641577
Cover Note Number

Driver

Name of Driver TAN CHEE BENG
NRIC No S1014656I
Date Of Birth 18/12/1954
Occupation INDOOR
Date Of Driving Pass 18/06/1973
Driving Experience 44 YEARS AND 3 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-90111280
Fax Number
Contact Number
Email Address NOEMAIL

Address 75 WOLSKEL ROAD
Postcode 357980
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number
Vehicle Make/Model/Colour
Details Of Properties PILLAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)
Details of Witness
Name
Phone Number
Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstance of the Accident

While entering house, gate open halfway, did not notice
& hit onto gate.

IMPORTANT NOTE

Under **General Condition – Conduct of Claim** of the Motor Policy, you have to decide within 21 days of occurrence or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

Declaration

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre Personnel

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Complete and submit this Form to Allied World's Authorised Reporting Centre ("ARC") for filing.
2. Please report correctly the details of the accident to speed up the claims process.
3. This Form must be completed by the Policyholder and/or the Authorised Driver.
4. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
5. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
6. Any false reporting may be referred to the Traffic Police Department for investigation.

ACCIDENT STATEMENT

Date and Time of Accident

Date: 03/10/2017 Time: 1100.

Exact Location of Accident

75 NOLSKEL ROAD.

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SCA75T

INSURED / POLICYHOLDER (OWN VEHICLE)

Name of Registered Owner (See Insurance Cert.)

BENG SOON MACHINERY SERVICES P/L

Personal Identification - NRIC (Singaporean/PR)

M9300151D.

- FIN/Passport Number

- Not Applicable

VEHICLE PARTICULARS (OWN VEHICLE)

Vehicle Make / Model

Manufacturer: LAMPREVE Model:

Type of Vehicle*

☐ Saloon ☒ MPV ☐ CRV ☐ Van ☐ Lorry
☐ Bus ☐ Micycle ☐ Others, _____

Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle?

SCIALZ
☒ Yes ☐ No (If No, Pls select: ☐ Third Party ☐ Reporting)
☒ Private ☐ Commercial ☐ Motorcycle

INSURANCE COMPANY (OWN VEHICLE)

Name of Insurance Company *

MSIG

Type of Policy

☒ Comprehensive ☐ Third Party Fire & Theft ☐ TP Only

Fleet Policy

☐ Yes ☒ No

Policy Number

A 28641577 MCY

Motor CI

DRIVER

☐ Same as Insured above

Name of Driver

TAN CHEE BANH

Personal Identification - NRIC (Singaporean/PR)

S10146507.

- FIN/Passport Number

Date of Birth

18 dd/2 mm/84/yy

Driving Date Pass

16 dd/06 mm/1973/yy

Year of Driving Experience

Year(s)

Month(s)

Occupation

☒ Indoor ☐ Outdoor

Gender

☒ Male ☐ Female

Contact Number / Mobile Phone / Fax No.

90111280.

Address of Driver 75 WOLFE ROAD Postcode 357980

Email Address NDP@MAIL

Was driver an employee of the Insured's Company? ☐ Yes ☒ No

If No, Relationship of the Driver with the Insured QUINTE

Vehicle Registration Number of Driver's Own ☐ Yes ☐ No

Vehicle Registration Number of Driver's Own Vehicle (if applicable)

Insurance Company of Driver's Own Vehicle (if applicable)

GENERAL INFORMATION OF THE ACCIDENT

Type of Collision (Eg. Chain collision, Head-On collision, Side Swipe, Front to Rear) HIT ONTO PILLAR

Weather Conditions ☒ Clear ☐ Raining ☐ Others

Road Surface ☒ Dry ☐ Wet ☐ Others

OTHER INFORMATION

Was any foreign vehicle involved in this accident? ☐ Yes ☒ No

Was any body injured in the accident? ☐ Yes ☒ No

Was any other vehicle or property damaged? ☐ Yes ☒ No

Was there any video captured by Car Camera? ☐ Yes ☒ No

Number of Passengers (Including Driver) 01

DETAILS OF POLICE ACTION

Was the Accident reported to the Police? ☐ Yes ☒ No (If Yes, please state which Police Station.)

Police Station Name

Police Station Address

Police Station Contact

Was notice of intended Prosecution given? ☐ Yes ☒ No (If Yes, against whom?)

DETAILS OF OTHER VEHICLE / PROPERTY 1

Vehicle Registration Number

Vehicle Make/ Model/ Colour

Details of Properties

Name of Driver

Personal Identification - NRIC (Singaporean/PR)

- FIN/Passport Number

Contact Number

Address

Name of Insurance Company

Nature of Damage

No. of Passenger (Including Driver)

(Note - Please use page 6 if you need to add more vehicles.)



MSIG

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

MOTORMAX PLUS-COMMERCIAL Comprehensive

Form M.X.4
Company Ownership

Certificate No. A 28641577 MCY

Excess : SGD900

Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
SCA75T

2. Name of Policyholder
Beng Soon Machinery Services (S) Pte Ltd

3. Effective Date of the Commencement of Insurance for the purposes of the Act
28/11/2016

4. Date of Expiry of Insurance
27/11/2017

5. Persons or Classes of Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT ANY WORKSHOP OF YOUR CHOICE OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers

HUA LIAN AGENCIES PTE LTD
2 JURONG EAST ST 21
#03-150 IMM BUILDING
SINGAPORE 609601
TEL: +65 6561 2722 FAX: +65 6562 6766


for Chief Executive Officer

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S10146561



Name: TAN CHEE BENG
陈志明
Race: CHINESE
Date of birth: 18-12-1954 Sex: M
Country of birth: SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S10146561



Name: TAN CHEE BENG
Birth Date: 18 Dec 1954
Issue Date: 09 Apr 2003

362720H

NRIC No. S10146561



REPUBLIC AUTO PTE LTD
301 ALEXANDRA ROAD
Date of MERCEDES-BENZ CENTER
05-03-2004
SINGAPORE 159968
TEL: 6844 4448 FAX: 6866 1717

Address:
75 WOLSKEL ROAD
SINGAPORE 357080

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	PASS DATE
Class 2B Motorcycles not exceeding 200 cc	25 Feb 1977
Class 2A Motorcycles between 201 cc and 400 cc	25 Feb 1977
Class 2 Motorcycles exceeding 400 cc	25 Feb 1977
Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	16 Jun 1973
Class 4 Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 2500 kilograms	28 Feb 1977
Class 5 Motor Vehicles which are not constructed themselves to carry any load and the weight of which unladen exceeds 7250 kilograms	21 Sep 1977

Licence No: S10146561

NP 428A

SERVICE ESTIMATE

67612 - C00001 SL: SERVICE SALES - PC

Sirs BENG SOON MACHINERY SVC(S) PTE LTD

Attn: Sir/ Madam

142 Tagore Lane

Singapore 787561

Closed by : Richmond Ho

Svc Consultant :

Remarks : BENG SOON MACHINERY

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 10/10/2017

WIP No. . : 22904

Veh.In/Out: 06/10/2017

*Tel.No. . : Home: 82181820-ALVIN

Reg.No. . : SCA75T

Reg.date . : 28/11/2014

Mileage .. : 0

Chassis No: SALWA2KE3FA505103

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE FRONT BONNET,FRT LH FENDER,FRT LH HEADLAMP,FRT BUMPER,FRT BRACKET,FRT TOP PANEL,FRT LH COOLER,ETC	0	9600.00	0		9,600.00 S	8400
-----	--	---	---------	---	--	------------	------

800	TO PUTTY SPRAY PAINT ON FRT BONNET,FRT LH FENDER,FRT BUMPER,ETC	0	5000.00	0		5,000.00 S	3000
-----	---	---	---------	---	--	------------	------

802	TO VACCUM & TOP UP A/C GAS	0	600.00	0		600.00 S	/
280	TO FOCUS HEADLAMP	0	162.00	0		162.00 S	/
280	TO CHECK WIRING INCLUDE	0	486.00	0		486.00 S	/

RESETTING OF ALL ELECTRICAL MODULES

R16	TOWING CHARGES	0	250.00	0		250.00 S	250
	BUMPER COVER FRT RRS	1.0 EA	2469.50			2,469.50 S	Torn
	BUMPER MOULDING TOW	1.0 EA	513.10			513.10 S	Sch
	BRACKET - BUMPER MOU	1.0 EA	265.40			265.40 S	neu
	INSERT - BUMPER LH	1.0 EA	216.00			216.00 S	neu

SERVICE ESTIMATE

67612 - C00001 SL: SERVICE SALES - PC

Sirs BENG SOON MACHINERY SVC(S) PTE LTD

Attn: Sir/ Madam

142 Tagore Lane

Singapore 787561

Closed by : Richmond Ho

Svc Consultant :

Remarks : BENG SOON MACHINERY

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 10/10/2017

WIP No. . : 22904

Veh.In/Out: 06/10/2017

*Tel.No. . : Home: 82181820-ALVIN

Reg.No. . : SCA75T

Reg.date. : 28/11/2014

Mileage . : 0

Chassis No: SALWA2KE3FA505103

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

KIT - AIR DEFLECTOR	1.0 EA	157.20			157.20	S (Ar)	/
COVER - FRONT FOG LA	1.0 EA	256.30			256.30	S (M)	/
GRILLE - BUMPER LH	1.0 EA	151.20			151.20	S (M)	/
CAP - POWERWASH JET	1.0 EA	55.60			55.60	S (M)	/
LLR034394/BUMPER BEA	1.0 EA	958.70			958.70	S (T.X) SH	/
RADIATOR GRILLE CTR	1.0 EA	1138.10			1,138.10	S (Sch)	/
BRACKET - BUMPER MOU	1.0 EA	38.90			38.90	S (M)	/
BRACKET - BUMPER MOU	1.0 EA	41.00			41.00	S (M)	/
BUMPER BEAM BRACKET	1.0 EA	75.30			75.30	S (T.X) SH	/
DEFLECTOR - AIR	1.0 EA	98.90			98.90	S (M)	/
FRAME PANEL RRS3	1.0 EA	1046.00	909.30		1,046.00	S (Ar)	/
AIR COOLING DEFLECTO	1.0 EA	217.60			217.60	S (M)	/
AIR COOLING DEFLECTO	1.0 EA	204.40			204.40	S (M)	/
AIR DEFLECTOR UPPER	1.0 EA	116.30			116.30	S (T.X) SH	/
SHUTTER - RADIATOR C	1.0 EA	537.10			537.10	S (T.X) SH	/
AIR DEFLECTOR LH RRS	1.0 EA	50.50			50.50	S (M)	/
AIR DEFLECTOR LOWER	1.0 EA	169.90			169.90	S (M)	/

SERVICE ESTIMATE

67612 - C00001 SL: SERVICE SALES - PC
 Sirs BENG SOON MACHINERY SVC(S) PTE LTD
 Attn: Sir/ Madam
 142 Tagore Lane

Singapore 787561

Closed by : Richmond Ho
 Svc Consultant :
 Remarks : BENG SOON MACHINERY

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 3
 Inv.date. : 10/10/2017
 WIP No. . : 22904
 Veh.In/Out: 06/10/2017
 *Tel.No. . : Home: 82181820-ALVIN
 Reg.No. . : SCA75T
 Reg.date. : 28/11/2014
 Mileage . : 0
 Chassis No: SALWA2KE3FA505103

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

AIR DEFLECTOR RRS3 R	1.0 EA	363.80				363.80 S	? X su
WHEELARCH OUTER FRT	1.0 EA	370.50				370.50 S	not done
INTERCOOLER	1.0 EA	693.70				693.70 S	BT
PARKING AID 90 Degre	4.0 EA	401.30				1,605.20 S	ru
LLR057279/HEADLAMP A	1.0 EA	3297.60				3,297.60 S	pro
LLR033407/FOG LAMP L	1.0 EA	485.20				485.20 S	mis
LLR044230/HOOD	1.0 EA	3790.20				3,790.20 S	BT
BADGE 'RANGE' FRT RR	1.0 EA	183.20				183.20 S	acc
BADGE 'ROVER' FRT RR	1.0 EA	183.20				183.20 S	acc
ADHESIVE SEALER FL2	1.0 EA	425.40				425.40 S	acc
BODY PANEL SEALANT X	1.0 EA	875.00				875.00 S	X AN
BULB HEADLAMP HID EV	1.0 EA	387.40				387.40 S	X su
FENDER - FRONT LH	1.0 EA	1475.50				1,475.50 S	R
LLR044230/HOOD	1.0 EA	3790.20				3,790.20 S	X repeated
BADGE 'RANGE' FRT RR	1.0 EA	183.20				183.20 S	X repeated
BADGE 'ROVER' FRT RR	1.0 EA	183.20				183.20 S	X repeated
HOSE - COMPRESSED AI	1.0 EA	348.70				348.70 S	cut

SERVICE ESTIMATE

67612 - C00001 SL: SERVICE SALES - PC
Sirs BENG SOON MACHINERY SVC(S) PTE LTD
Attn: Sir/ Madam
142 Tagore Lane

Singapore 787561

Closed by : Richmond Ho
Svc Consultant :
Remarks : BENG SOON MACHINERY

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 4
Inv.date. : 10/10/2017
WIP No. . : 22904
Veh.In/Out: 06/10/2017
*Tel.No. . : Home: 82181820-ALVIN
Reg.No. . : SCA75T
Reg.date. : 28/11/2014
Mileage . : 0
Chassis No: SALWA2KE3FA505103

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount G
-------	-------------	----------	-------	-------	-----	----------

HOSE - COMPRESSED AI

1.0 EA 200.70

200.70 S *200.70*

Auto Consultants hence notify the Repairer of the following:

- Resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved and is subject to final approval from the insurance company

Acknowledged by Repairer
Signature: _____
Date: _____

Rasul
Hp 90010068

10 days

11/10/17 @ 1250

EXCESS : 900

Reverse Resurvey by paint

13/10/17

Gross Total. 43,716.90

Net..... 43,716.90

GST @ 7.0% 3,060.18

Total..... 46,777.10

Paid..... 0.00

Please Pay.. 46,777.10

47604.42

Labour Total	16,098.00		
Parts Total	27,618.90		
Package Total	0.00		

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

O - A00003 ST.: MSG INSURANCE (SINGAPORE) PTE. LTD.
 MSG INSURANCE (SINGAPORE) PTE. LTD. GST Reg.No:M28920628X
 4 SHENTON WAY #21-01 Inv.No. . : B&P 0 Page 1
 SGX CENTRE 2 Inv.date. : 22/12/2017
 SINGAPORE 068807 WIP No. . : 22904
 Veh.In/Out: 06/10/2017 15/11/2017

Closed by : Richmond Ho
 Svc Consultant : ACC
 Remarks : BENG SOON MACHINERY

*Tel.No. . : 68277888
 Reg.No. . : SCA75T
 Reg.date . : 28/11/2014
 Mileage .. : 50,971
 Chassis No: SALWA2KE3FA505103

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	INSERT - BUMPER RH	1.0 EA	216.00			216.00	S
	HOSE HEADLAMP LONG R	1.0 EA	88.40			88.40	S
	HOSE HEADLAMP SHORT	1.0 EA	71.60			71.60	S
	WRTNG - BUMPER	1.0 EA	354.60			354.60	S
	BRACKET - HEADLAMP M	1.0 EA	42.60			42.60	S

		Gross Total.	773.20
Labour Total	0.00	Net.....	773.20
Parts Total	773.20	GST @ 7.0%	54.12
Package Total	0.00	Total.....	827.32
		Paid.....	0.00
		Please Pay..	827.32

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

6449010

SERVICE ESTIMATE

0 - A00003 SL: MSIG INSURANCE (SINGAPORE) PTE. LTD
 MSIG INSURANCE (SINGAPORE) PTE. LTD.
 4 SHENTON WAY #21-01
 SGX CENTRE 2
 SINGAPORE 068807

GST Reg.No: M28920628X
 0 Page 1
 Inv.No. : B&P
 Inv.date : 05/12/2017
 WIP No. : 22904
 Veh.In/Out: 06/10/2017 15/11/2017
 *Tel.No. : 68277888
 Reg.No. : SCA75T
 Reg.date : 28/11/2014
 Mileage : 50,971
 Chassis No: SALWA2KE3FA505103

Closed by : Richmond Ho
 Svc Consultant : ACC
 Remarks : BENG SOON MACHINERY

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount G
802	TO REPLACE FRONT BONNET, FRT LH FENDER, FRT LH HEADLAMP, FRT BUMPER, FRT BRACKET, FRT TOP PANEL, FRT LH COOLER, ETC	0	8400.00	0		8,400.00 S
800	TO PUTTY SPRAY PAINT ON FRT BONNET, FRT LH FENDER, FRT BUMPER, ETC	0	3000.00	0		3,000.00 S
802	TO VACUUM & TOP UP A/C GAS	0	600.00	0		600.00 S
280	TO FOCUS HEADLAMP	0	162.00	0		162.00 S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	486.00	0		486.00 S
R16	TOWING CHARGES	0	250.00	0		250.00 S
FXC	Excess cost	0	900.00	0		-900.00 S
	BUMPER COVER FRT RRS ①	1.0 EA	2469.50			2,469.50 S
	BUMPER MOULDING TOW ②	1.0 EA	513.10			513.10 S
	BRACKET - BUMPER MOUN ③	1.0 EA	265.40			265.40 S

SERVICE ESTIMATE

Q - A00003 SL: MSIG INSURANCE (SINGAPORE) PTE. LTD
 MSIG INSURANCE (SINGAPORE) PTE. LTD. GST Reg.No:M28920628X
 4 SHENTON WAY #21-01 Inv.No. . : B&P 0 Page 2
 SGX CENTRE 2 Inv.date. : 05/12/2017
 SINGAPORE 068807 WIP No. . : 22904
 Veh.In/Out: 06/10/2017 15/11/2017

Closed by : Richmond Ho
 Svc Consultant : ACC
 Remarks : BENG SOON MACHINERY

*Tel.No. . : 68277888
 Reg.No. . : SCA75T
 Reg.date. : 28/11/2014
 Mileage . : 50,971
 Chassis No: SALWA2KE3FA505103

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	INSERT - BUMPER LH (4)	1.0 EA	216.00			216.00	S
	KIT - AIR DEFLECTOR (5)	1.0 EA	157.20			157.20	S
	COVER - FRONT FOG LA (C)	1.0 EA	256.30			256.30	S
	GRILLE - BUMPER LH (7)	1.0 EA	151.20			151.20	S
	CAP - POWERWASH JET (8)	1.0 EA	55.60			55.60	S
	RADIATOR GRILLE CTR (10)	1.0 EA	1138.10			1,138.10	S
	BRACKET - BUMPER MOD (11)	1.0 EA	38.90			38.90	S
	DEFLECTOR AIR (12)	1.0 EA	41.00			41.00	S
	AIR COOLING DEFLECTOR (14)	1.0 EA	98.90			98.90	S
	AIR COOLING DEFLECTOR (16)	1.0 EA	217.60			217.60	S
	AIR COOLING DEFLECTOR (17)	1.0 EA	204.40			204.40	S
	AIR DEFLECTOR LH RRS (20)	1.0 EA	50.50			50.50	S
	AIR DEFLECTOR LOWER (21)	1.0 EA	169.90			169.90	S
	WHEELARCH OUTER FRT (23)	1.0 EA	370.50			370.50	S
	INTERCOOLER (24)	1.0 EA	693.70			693.70	S
	PARKING AID 90 Degree (25)	4.0 EA	401.30			1,605.20	S
	LLR057279/HEADLAMP A (26)	1.0 EA	3297.60			3,297.60	S



S.L: MSIG INSURANCE (SINGAPORE) PTE. LTD

GST Reg.No:M28920628X

Inv.No. : B&P
 Inv.date: 05/12/2017
 WIP No. : 22904
 Veh. In/Out : 05/10/2017 15/11/2017
 *Tel.No. : 8827 7889
 Reg.No. : SCA75T
 Reg.date : 28/11/2014
 Mileage : 50,971
 Chassis No: SAIWA2KE3FA505103

Remarks : BENG SOON MACHINERY

Gross Total.	33,482.50
Less.....	900.00
Net.....	32,582.50
GST @ 7.0%	2,280.78
Total.....	34,863.28
Paid.....	0.00
Please Pay..	34,863.28

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Oct 2017		11 Oct 2017 10:08 Edit Adj Rpt	S\$32,007.00 Edit Estimates	S\$32,007.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

Vehicle Reg. No.:

Claim Type:

Repairer:

Handling Insurer:

Adjuster:

Driver/Custodian:

Adj Asg. Remarks:

BENG SOON MACHINERY SERVICES (S)PTE LTD, Co. Reg. No.: 199300151D

SCA75T

OD / 532172

Wearnes Automotive Pte Ltd (Alexandra Road) 249 Alexandra Road, 159935 Alexandra - Tel: 63789370

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 10/11/2017]

TAN CHEE BENG (62 / Male), NRIC: S1014656I, Tel: +6590111280

Please revert. (car-in)

[Created by insurer]

Date of Loss: 03/10/2017 21:00 - :59

Policy/Cover Note No.: A28641577MCY (Comprehensive)
Coverage: 28/11/2016 - 27/11/2017

Excess: S\$900.00

View All

Compose Case Mail

ASSOCIATED MAIL RECEIVED

- MSIG_SG (28/12/2017): Alert - Adj Mandate Approved (S\$32007.00) - SCA75T - Claim Handler: Joslin Lim
- MSIG_SG (13/10/2017): Alert - Adj Mandate Approved (S\$34009.80) - SCA75T - Claim Handler: Joslin Lim

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SCA75T (532172)

OD

Oct 3 2017 9:00PM

[BENG SOON MACHINERY SERVICES (S)PTE LTD]
Wearnes Automotive Pte Ltd

View View in Browser v

Upload Documents
Upload Photos
Compose New Letter

Assessment Reports			1 per page v	☒
			Thumbnail	Print
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)	1	
1	06/10/17 13:18	Accident Statement	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	1	
1	12/10/17 15:15	Adjuster Immediate Advice	Load HTM	
2	27/12/17 12:08	Adjuster Immediate Advice	Load HTM	

Photos/Images			3 per page v	☒
			Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	1	
1	12/10/17 14:55	General View	Load JPG	☒
2	12/10/17 14:55	General View	Load JPG	☒
3	12/10/17 14:55	General View	Load JPG	☒
4	12/10/17 14:55	General View	Load JPG	☒
5	12/10/17 14:55	General View	Load JPG	☒
6	12/10/17 14:55	General View	Load JPG	☒
7	12/10/17 14:55	General View	Load JPG	☒
8	12/10/17 14:55	General View	Load JPG	☒
9	12/10/17 14:55	General View	Load JPG	☒
10	12/10/17 14:55	General View	Load JPG	☒
11	12/10/17 14:55	General View	Load JPG	☒
12	12/10/17 14:55	General View	Load JPG	☒
13	12/10/17 14:55	General View	Load JPG	☒
14	12/10/17 14:55	General View	Load JPG	☒
15	12/10/17 14:55	General View	Load JPG	☒
16	12/10/17 14:55	General View	Load JPG	☒
17	12/10/17 14:55	General View	Load JPG	☒
18	12/10/17 14:55	General View	Load JPG	☒
19	12/10/17 14:55	General View	Load JPG	☒
20	12/10/17 14:55	General View	Load JPG	☒
21	12/10/17 14:55	General View	Load JPG	☒
22	12/10/17 14:55	General View	Load JPG	☒
23	12/10/17 14:55	General View	Load JPG	☒
24	12/10/17 14:55	General View	Load JPG	☒
25	12/10/17 14:55	General View	Load JPG	☒
26	12/10/17 14:55	General View	Load JPG	☒
27	12/10/17 14:55	General View	Load JPG	☒
28	12/10/17 14:55	General View	Load JPG	☒
29	12/10/17 14:55	General View	Load JPG	☒
30	12/10/17 14:55	General View	Load JPG	☒
31	12/10/17 14:55	General View	Load JPG	☒

32	12/10/17 14:55	General View	1	Load JPG	☒
33	12/10/17 14:55	General View	1	Load JPG	☒
34	12/10/17 14:55	General View	1	Load JPG	☒
35	12/10/17 14:55	General View	1	Load JPG	☒
36	12/10/17 14:55	General View	1	Load JPG	☒
37	12/10/17 14:55	General View	1	Load JPG	☒
38	12/10/17 14:55	General View	1	Load JPG	☒
39	12/10/17 14:55	General View	1	Load JPG	☒
40	12/10/17 14:55	General View	1	Load JPG	☒
41	12/10/17 14:55	General View	1	Load JPG	☒
42	12/10/17 14:55	General View	1	Load JPG	☒
43	12/10/17 14:55	General View	1	Load JPG	☒
44	12/10/17 14:55	General View	1	Load JPG	☒
45	12/10/17 14:55	General View	1	Load JPG	☒
46	12/10/17 14:55	General View	1	Load JPG	☒
47	12/10/17 14:55	General View	1	Load JPG	☒
48	12/10/17 14:55	General View	1	Load JPG	☒
49	12/10/17 14:55	General View	1	Load JPG	☒
50	12/10/17 14:55	General View	1	Load JPG	☒
51	12/10/17 14:55	General View	1	Load JPG	☒
52	12/10/17 14:55	General View	1	Load JPG	☒
53	12/10/17 14:55	General View	1	Load JPG	☒
54	12/10/17 14:55	General View	1	Load JPG	☒
55	12/10/17 14:55	General View	1	Load JPG	☒
56	12/10/17 14:55	General View	1	Load JPG	☒
57	12/10/17 14:55	General View	1	Load JPG	☒
58	27/12/17 11:24	RE-SURVEY PHOTO	1	Load JPG	☒
59	27/12/17 11:24	RE-SURVEY PHOTO	1	Load JPG	☒
60	27/12/17 11:24	RE-SURVEY PHOTO	1	Load JPG	☒
61	27/12/17 11:24	RE-SURVEY PHOTO	1	Load JPG	☒
62	27/12/17 11:24	RE-SURVEY PHOTO	1	Load JPG	☒
				1 per page	☒
Documentation				Thumbnail	Print
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)			
1	10/10/17 16:32	Email from Wearnes + Estimate + Accident Report + CI + IC + DL + Accident Form	1	Load PDF	
				Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			
1	12/10/17 15:24	ESTIMATE	1	Load PDF	
2	27/12/17 11:23	SUPPLEMENTARY	1	Load PDF	
3	27/12/17 11:59	ESTIMATE MARKING	1	Load PDF	

Linked Accident Report Documents

			View	View in Browser
			1 per page	☒
Assessment Reports			Thumbnail	Print
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)		
1	06/10/17 13:18	Accident Statement	1	Load HTM
			3 per page	☒
Photos/Images			Thumbnail	Print
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)		
1	06/10/17 13:16	Accident Photo	1	Load JPG
2	06/10/17 13:16	Accident Photo	1	Load JPG

3	06/10/17 13:16	Accident Photo	1	Load JPG	☒
4	06/10/17 13:16	Accident Photo	1	Load JPG	☒
5	06/10/17 13:16	Accident Photo	1	Load JPG	☒
6	06/10/17 13:16	Accident Photo	1	Load JPG	☒
7	06/10/17 13:16	Accident Photo	1	Load JPG	☒
				1 per page	☒
Documentation				Thumbnail	Print
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)	1	Load TIF	
1	06/10/17 13:15	Sketch Plan			

Documents Checklist

		Reset	Save	Print
DOCUMENTS CHECKLIST				
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17019494/R1GBE2

Date: 05/01/2018

REFERENCE

Insured/Claimant: BENG SOON MACHINERY SERVICES (S)PTE LTD Policy No: A28641577MCY
Date of Loss: 03/10/2017 Nature of Claim: OD Claim No: 532172

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCA75T**
 Make & Model: **LAND ROVER RANGE ROVER SPORT, 3.0 TSS 7S SR (A)** Engine No: 0877648306DT
 Reg. Date: 28/11/2014 (Man. Year: 2014) Chassis No: SALWA2KE3FA505103
 Colour: Blue Odometer: 62793 km
 Engine Capacity: 2993 cc
 Market Value/New Car Price: S\$285,000.00
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No
 Footbrake (Serviceable): Yes
 Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 265/50 R20 Rear Tyre Size: 265/50 R20
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,392.10	19,109.00	9,283.10	32.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,098.00	12,898.00	3,200.00	19.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	44,490.10	32,007.00	12,483.10	28.06
- Excess (S\$)	900.00	900.00	0.00	0.00
(S\$)	43,590.10	31,107.00	12,483.10	28.64
+ GST 7.00/7.00% (S\$)	3,051.31	2,177.49	873.82	28.64
Nett Amount (S\$)	46,641.41	33,284.49	13,356.92	28.64

INSPECTION

Date of Assignment: 11/10/2017
 Date Inspected: 11/10/2017 Inspected At:

Wearnes Automotive Pte Ltd (Alexandra Road)
 249 Alexandra Road
 Singapore 159935

Estimated Period of Repair: 10.0 days

Adjuster: MOHD RASUL**Manager:** LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Jan 2018)
 Parts: M1-SUV LAND ROVER RANGE ROVER SPORT 3.0 TSS 7S SR (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SCA75T)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT RRS	Torn	2,469.50 FS	*2,469.50 FS
2	1		*BUMPER MOULDING TOW	Scratched	513.10 FS	*513.10 FS
3	1		*BRACKET-BUMPER MOU	Necessary	265.40 FS	*265.40 FS
4	1		*INSERT-BUMPER LH	Necessary	216.00 FS	*216.00 FS
5	1		*KIT-AIR DEFLECTOR	Cracked	157.20 FS	*157.20 FS
6	1		*COVER-FRONT FOG LA	Missing	256.30 FS	*256.30 FS
7	1		*GRILLE-BUMPER LH	Missing	151.20 FS	*151.20 FS
8	1		*CAP-POWERWASH JET	Missing	55.60 FS	*55.60 FS
9	1		*LLR034394/BUMPER BEA	Serviceable	958.70 FS	*- FS
10	1		*RADIATOR GRILLE CTR	Scratched	1,138.10 FS	*1,138.10 FS
11	1		*BRACKET-BUMPER MOU	Necessary	38.90 FS	*38.90 FS
12	1		*BRACKET-BUMPER MOU	Necessary	41.00 FS	*41.00 FS
13	1		*BUMPER BEAM BRACKET	Serviceable	75.30 FS	*- FS
14	1		*DEFLECTOR - AIR	Missing	98.90 FS	*98.90 FS
15	1		*FRAME PANEL RRS3	Cracked	1,046.00 FS	*909.30 FS
16	1		*AIR COOLING DEFLECTO	Missing	217.60 FS	*217.60 FS
17	1		*AIR COOLING DEFLECTO	Missing	204.40 FS	*204.40 FS
18	1		*AIR DEFLECTOR UPPER	Serviceable	116.30 FS	*- FS
19	1		*SHUTTER-RADIATOR C	Serviceable	537.10 FS	*- FS
20	1		*AIR DEFLECTOR LH RRS	Missing	50.50 FS	*50.50 FS
21	1		*AIR DEFLECTOR LOWER	Missing	169.90 FS	*169.90 FS
22	1		*AIR DEFLECTOR RRS3 R	Serviceable	363.80 FS	*- FS
23	1		*WHEELARCH OUTER FRT	Torn	370.50 FS	*370.50 FS
24	1		*INTERCOOLER	Bent	693.70 FS	*693.70 FS
25	4		*PARKING AID 90 DEGRE	Not Working	1,605.20 FS	*1,605.20 FS
26	1		*LLR057279/HEADLAMP A	Broken	3,297.60 FS	*3,297.60 FS
27	1		*LLR033407/FOG LAMP L	Missing	485.20 FS	*485.20 FS
28	1		*LLR044230/HOOD	Bent	3,790.20 FS	*3,790.20 FS
29	1		*BADGE RANGE FRT RR	Necessary	183.20 FS	*183.20 FS
30	1		*BADGE ROVER FRT RR	Necessary	183.20 FS	*183.20 FS
31	1		*ADHESIVE SEALER FL2	Necessary	425.40 FS	*425.40 FS
32	1		*BODY PANEL SEALANT X	Not Necessary	875.00 FS	*- FS
33	1		*BULB HEADLAMP HID EV	Serviceable	387.40 FS	*- FS
34	1		*FENDER-FRONT LH	Repair	1,475.50 FS	*- FS
35	1		*LLR044230/HOOD	Repeated	3,790.20 FS	*- FS
36	1		*BADGE RANGE FRT RR	Repeated	183.20 FS	*- FS
37	1		*BADGE RANGE FRT RR	Repeated	183.20 FS	*- FS
38	1		*HOSE-COMPRESSED AI	Cut	348.70 FS	*348.70 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*HOSE-COMPRESSED AI	Serviceable	200.70 FS	*- FS
40	1		*INSERT-BUMPER RH	Necessary	216.00 FS	*216.00 FS
41	1		*HOSE HEADLAMP LONG R	Cut	88.40 FS	*88.40 FS
42	1		*HOSE HEADLAMP SHORT	Cut	71.60 FS	*71.60 FS
43	1		*WIRING - BUMPER	Cut	354.60 FS	*354.60 FS
44	1		*BRACKET-HEADLAMP M	Necessary	42.60 FS	*42.60 FS
F=Franchise part. S=SpcNett.					Total Parts (S\$)	28,392.10 19,109.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRONT BONNET, FRT LH FENDER, FRT LH HEADLAMP, FRT BUMPER, FRT BRACKET, FRT TOP PANEL, FRT LH COOLER, ETC	New	9,600.00	8,400.00
2	TO PUTTY SPRAY PAINT ON FRT BONNET, FRT LH FENDER, FRT BUMPER, ETC	New	5,000.00	3,000.00
3	TO VACUUM & TOP UP A/C GAS	New	600.00	600.00
4	TO FOCUS HEADLAMP	New	162.00	162.00
5	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	486.00	486.00
6	TOWING CHARGES	New	250.00	250.00
Gross Labour Cost (S\$)			16,098.00	12,898.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >