

S. REC. BY:

REF:

CS/ms617019509/Rib

Special Instruction:

Salvage:

RASH

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSU

Date/Time:

11-10-2017 920am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJZ 4927U

Insured:

SLE 75R

at Workshop m/s

Performance

Tel:

6319 0174

of

303 Alexandra Road

Policy No:

28950489MCT

Claim No:

532517

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10-10-2017

CA / REV / REP. / REV 24 HRS 'wp

23-10-2017

H.O.D. Endorsement:

Date/Time:

11-10-2017 243 pm

Person Contacted:

Caroline

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	Onna
	SJZ 4927U - x	
	SLE 75R - x	
	Sent peti through menimen	
	Confirm \$9,866.60, 5 days	
	Red. \$ 6044 b5, 387.	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17019509/R1rb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 11-10-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 75R	Veh. Inspected	SJZ 4927U
Policy No.	28950489MCY	Coverage (\$)	0.00
Claim No.	532517	Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	11/10/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	10/10/2017	Inspection Date
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Ret	Adj Submitted	Ins Auth ed	Status
Main	10 Oct 2017		11 Oct 2017 09:20 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	BENG SOON MACHINERY SERVICES (S) PTE LTD , Co. Reg. No.: 199300151D			[Created by insurer]
Main Claimant:	KANG KOK HUA , ID: S1614881D			
Vehicle Reg. No.:	SJZ4927U	Date of Loss:	10/10/2017 00:00 - :59	
Claim Type:	TP / 532517	Policy/Cover Note No.:	28950489MCY (Comprehensive) Coverage: 28/06/2017 - 27/06/2018	
Vehicle Reg. No. (Insured):	SLE75R	Policy No. (Claimant):		
		Excess:		
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/10/2017]			

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

est: ✓
Veh: X
2.43pm
caroline.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 26 Oct 2017

Preliminary Advice

Insured Vehicle No	: SLE75R		
TP Vehicle No	: SJZ4927U	Accident Date	: 10/10/2017
Make	: BMW 523i	Assignment Date	: 11/10/2017
Date of Inspection	: 23/10/2017	Est. Duration of Repair	: 5.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,441.10
Revised Amount	:S\$	8,538.23
Check Items (Estimated)	:S\$	4,338.40
Total	:S\$	12,876.63

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/10/2017 17:12
Date Of Accident	10/10/2017 09:20
Exact Location Of Accident	SLE-MANDAI SECTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJZ4927U
Insured/Policyholder	
Name Of Registered Owner	KANG KOK HUA
NRIC No	S1614881D
Email Address	KANGPRUDEE2.2013@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90052203
Alternative Phone No	OFFICE-90052203

Vehicle Particulars

Manufacturer	BMW
Model	523
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B27010134SMP
Cover Note Number	

Driver

Name of Driver	KANG KOK HUA
NRIC No	S1614881D
Date Of Birth	09/02/1963
Occupation	INDOOR
Date Of Driving Pass	23/04/1980
Driving Experience	37 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90052203
Fax Number	
Contact Number	OFFICE-90052203
Email Address	KANGPRUDEE2.2013@GMAIL.COM

Address	BLK 805 WOODLANDS ST 81#05-13
Postcode	730805
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAIN STOPPED ABOUT 1 HOUR BEFORE
Road Surface	SLIGHTLY WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLE75R
Vehicle Make/Model/Colour	MERCEDES S CLASS GREY
Details Of Properties	
Name of Driver	TAN WEI LEONG
NRIC/Passport Number	S9034091C
Contact Number	98281280
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	FRONT REAR
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	UNKNOWN
Vehicle Make/Model/Colour	

Sketch Plan Pg. 2

Describe Circumstances of the Accident

I WAS TRAVELLING ALONG LANE 2 SELETIME EXPRESSWAY (MANOH SECTION)
WHEN ACCIDENT OCCURRED AT 0919 HRS ON 10TH OCT 2017.

MY SPEED OF TRAVEL WAS ABOUT 90KM/H BUT WAS FORCED TO BRAKE ABRUPTLY DUE TO RAPID SLOWDOWN OF VEHICLES AHEAD OF ME DUE TO VEHICLE BREAKDOWN ON SAME LANE ABOUT 500 METRES AHEAD.

I WAS ABLE TO BREAK ON TIME WITHOUT COLLIDING INTO VEHICLE IN FRONT OF ME. THE CAR (SLE7SR) IMMEDIATELY BEHIND WAS ALSO ABLE TO (BASED ON MY JUDGEMENT) BUT A THIRD CAR BEHIND SLE7SR WAS UNABLE TO STOP VEHICLE ON TIME. THIS IN TURN CAUSED A MULTIPLE CAR COLLISION AS SLE7SR SURGED FORWARD AND HIT MY REAR BUMPER.

WEATHER WAS CLEAR ALTHOUGH IT RAINED ABOUT ONE HOUR BEFORE THE ACCIDENT. ROAD WAS SLIGHTLY WET.

NO ONE WAS INJURED IN THE ACCIDENT. A TOTAL OF 4 CARS WERE INVOLVED IN THIS CHAIN COLLISION, INCLUDING MINE.

Declaration

We declare the foregoing particulars are true in every respect.

10th Oct 2017
1557 hrs

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Center Personnel 10/10/2014 1640hrs

23/10/2017
- A. mening



BMW Dealer
Performance Motors Limited
A member of the Sime Darby Group
Co. Reg. No. 1974015594 GST Reg. No. M2-0020081-X

309, Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770	380, Kampong Arang Road East Coast Centre Singapore 438180 Tel. 63190888 (AfterSales) Fax. 63449773	315, Alexandra Road Sime Darby Business Centre Singapore 159944 Tel. 63190528 (AfterSales) 63190533/539 (Motorrad) Fax. 64796601 (AfterSales) 64796624 (Motorrad)
---	---	---

GST REG. NO : M2 - 0020081 - X
E S T I M A T E

10 OCT 2017
@ 9.30 pm

Estimate No. : b1 44420	Page No. : 1 of 2
Date Estimated : 10/10/2017	
Prepared By : Chua Kee Sin	

- ESTIMATE REPAIR FOR - Kang Kok Hua 805 Woodlands Street 81 #05-13 Singapore 730805	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJZ4927U	C547026	30/11/2010	523iA	0

DESCRIPTION	VALUE
Replace rear boot lid, rear bumper and remove attachment etc include knock on accident dent	2125 / 3,400.00
Spray painting on rear boot lid, rear bumper and tail end panel	2577 / 2,819.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 / 177.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	230 / 271.00
To replace rear PDC sensor wire harness including reset and checks for proper function.	150 / 226 / 266.00
To supply rear emboss number plate.	cat / 83.00
To carry out body cavity preservation. (Per panel).	100 / 118.00
Sundries. <i>Handwritten</i>	80 / 150.00
Total Labour 1:	7,284.00

DESCRIPTION	QTY	PRIC	VALUE
BLIND RIVET	6	1.25	7.50
LH BOOTLID HINGE	1	110.85	110.85
RH BOOTLID HINGE	1	110.85	110.85
BOOTLID	1	1,563.30	1,563.30
SET MOUNTS PDC SENSOR REAR (PDC)	1	62.50	62.50
RR BUMPER GUIDE BOTTOM CENTRE	1	57.50	57.50
RR BUMPER CTR GUIDE	1	65.75	65.75
RR BUMPER LH MOUNT	1	141.65	141.65
RR BUMPER RH MOUNT	1	141.65	141.65
RR BUMPER CARRIER	1	696.80	696.80

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



403, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63199100 (Sales & Admin)
63199111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190828 (AfterSales)
63190833/330 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 44420
Date Estimated : 10/10/2017
Prepared By : Chua Kee Sin

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJZ4927U	C547026	30/11/2010	523iA	0

DESCRIPTION	QTY	PRIC	VALUE
RR BUMPER PANEL PRIMED (PDC)	1	1,431.40	DE 1,431.40
RR BUMPER TOW HOOK COVER PRIMED	1	23.25	Suc 23.25
LH PROTECTION FOIL	1	15.15	Xfu 15.15
RH PROTECTION FOIL	1	15.15	15.15
PROTECTION FOIL L=55MM	2	4.65	9.30
RR BUMPER ADAPTER	1	46.80	CR 46.80
EMBLEM GROMMET	2	0.80	na 1.60
BMW EMBLEM	1	67.80	na 67.80
STRIKER BOOT LID	1	52.25	X 52.25
SPRING DAMPER TRUNK LID	1	84.75	X 84.75
SPINDLE DRIVE RH	1	522.65	X 522.65
TRUNK LID LOCK TOP	1	425.35	X 425.35
TRUNK LID POWER LOCK DRIVE	1	572.30	X 572.30
TRIGGER CONTACT	1	128.75	X 128.75
PLUG	6	1.05	na 10.50 6.30
LOADING SILL COVER	1	110.00	X 110.00
LH GUTTER STRIP	1	16.40	X 16.40
LH GUTTER STRIP	1	16.40	X 16.40
BOOTLID SEALING	1	112.45	X 112.45
REAR LH REFLECTOR	1	34.35	X 34.35
REAR RH REFLECTOR	1	34.35	X 34.35
DECOUPLING RING PDC TORQUE CONVERTE	4	4.95	X 19.80
BUMPER PDC SENSOR (A17 HAVANNA)	4	363.05	X 1,452.20

Total Parts : 8,157.10

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Page No. _____ Date No. _____
Date/Time 23/10/17 09:45 Exam 05
Surveyor's Name Raul Sign _____
Surveyor's Tel 90010068 Authorized Yes / No
Authorized Date _____ Time _____

SURVEY PHOTO BY SURVEYOR Yes / No PHL Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 5 days

LIK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature		
Labour 1	:	7,284.00
Parts	:	8,157.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,080.88
Grand Total	:	16,521.98

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-R



SUPPLEMENTARY

Estimate No. : b1 44420
Date Estimated : 10/10/2017
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Kang Kok Hua
805 Woodlands Street 81
#05-13

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 730805

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SJZ4927U	C547026	30/11/2010	523iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT *	1.00	2.00		2.00 <i>na</i>
# MODEL LETTERING 523i *	61.05	1.00		61.05 <i>na</i>
# COVERING REAR RIGHT *	69.10	1.00		69.10 <i>cut</i>
# REAR RH LIGHT IN TRUNK LID *	338.00	1.00		338.00 <i>(na)</i>

Total Labour :	0.00
Total Parts :	470.15
Total Labour & Parts :	470.15

15911.25

Celine Fong (LKKAUTO)

From: PBSP <pml-pbsp@sime-darby.com.sg>
Sent: Friday, 1 December 2017 4:10 PM
To: Rasul (LKKAUTO); SUR
Subject: FINAL REPORT / SJZ4927U
Attachments: Final Report SJZ4927U.pdf; Final Report SJZ4927U_2.pdf

Dear Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 5,455.00
Total Parts : 4,411.60
Total Labour & Parts : 9,866.60

Repair days: 5

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 44420
Date Estimated : 10/10/2017
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Kang Kok Hua
805 Woodlands Street 81
#05-13

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 730805

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SJZ4927U	C547026	30/11/2010	523iA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments, boot lid, rear RH covering, rear RH light in trunk lid include making good the tail end panel and knocking out dents caused by the accident	2125.00		2,125.00	
To spray paint boot lid, rear bumper and tail end panel	2537.00		2,537.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
To remove and install boot compartment carpet and garnish to facilitate repairs.	230.00		230.00	
* To remove and install PDC assembly to facilitate repairs include conducting checks for proper function	150.00		150.00	
To supply rear emboss number plate.	83.00		83.00	
To carry out body cavity preservation. (Per panel).	100.00		100.00	
Sundries.	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BOOTLID	1,563.30	1.00		1,563.30
# EXPANDING NUT *	1.00	2.00		2.00
RR BUMPER GUIDE BOTTOM CENTRE	57.50	1.00		57.50
RR BUMPER CTR GUIDE	65.75	1.00		65.75
RR BUMPER CARRIER	696.80	1.00		696.80
RR BUMPER PANEL PRIMED (PDC)	1,431.40	1.00		1,431.40
RR BUMPER ADAPTER	46.80	1.00		46.80
EMBLEM GROMMET	0.80	2.00		1.60
# MODEL LETTERING 523i *	61.05	1.00		61.05
BMW EMBLEM	67.80	1.00		67.80
PLUG	1.05	10.00		10.50
# COVERING REAR RIGHT *	69.10	1.00		69.10

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020061-X



FINAL REPORT

# REAR RH LIGHT IN TRUNK LID *	338.00	1.00	338.00
--------------------------------	--------	------	--------

SUPPLEMENTARY ITEMS

Total Labour :	5,455.00
Total Parts :	4,411.60
Total Labour & Parts :	9,866.60
Deduction for Excess :	0.00
Total Repair Costs less Excess:	9,866.60 ✓
GST @7%:	690.66
Grand Total :	10,557.26

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	10 Oct 2017		11 Oct 2017 09:20 Edit Adj Rpt	S\$9,866.60 Edit Estimates	S\$9,866.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	BENG SOON MACHINERY SERVICES (S) PTE LTD. Co. Reg. No.: 199300151D								
Main Claimant:	KANG KOK HUA , ID: S1614881D								
Vehicle Reg. No.:	SJZ4927U	Date of Loss:	10/10/2017 00:00 - :59 [82 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 532517	Policy/Cover Note No.:	28950489MCY (Comprehensive) Coverage: 28/06/2017 - 27/06/2018						
Vehicle Reg. No. (Insured):	SLE75R	Policy No. (Claimant):							
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 10/11/2017]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJZ4927U (532517)
[SLE75R]
TP
KANG KOK HUA
Oct 10 2017 12:00AM
[BENG SOON MACHINERY SERVICES (S) PTE LTD]
Performance Motors Limited

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	26/10/17 17:52	Adjuster Immediate Advice					1 Load HTM			
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	23/04/18 16:45	General View					1 Load JPG		☒	
2	23/04/18 16:45	General View					1 Load JPG		☒	
3	23/04/18 16:45	General View					1 Load JPG		☒	
4	23/04/18 16:45	General View					1 Load JPG		☒	
5	23/04/18 16:45	General View					1 Load JPG		☒	
6	23/04/18 16:45	General View					1 Load JPG		☒	
7	23/04/18 16:45	General View					1 Load JPG		☒	
8	23/04/18 16:45	General View					1 Load JPG		☒	
9	23/04/18 16:45	General View					1 Load JPG		☒	
10	23/04/18 16:45	General View					1 Load JPG		☒	
11	23/04/18 16:45	General View					1 Load JPG		☒	
12	23/04/18 16:45	General View					1 Load JPG		☒	
13	23/04/18 16:45	General View					1 Load JPG		☒	
14	23/04/18 16:45	General View					1 Load JPG		☒	
15	23/04/18 16:45	General View					1 Load JPG		☒	
16	23/04/18 16:45	General View					1 Load JPG		☒	
17	23/04/18 16:45	General View					1 Load JPG		☒	
18	23/04/18 16:45	General View					1 Load JPG		☒	
19	23/04/18 16:45	General View					1 Load JPG		☒	
20	23/04/18 16:45	General View					1 Load JPG		☒	
21	23/04/18 16:45	General View					1 Load JPG		☒	
22	23/04/18 16:45	General View					1 Load JPG		☒	
23	23/04/18 16:45	General View					1 Load JPG		☒	
24	23/04/18 16:45	General View					1 Load JPG		☒	
25	23/04/18 16:45	General View					1 Load JPG		☒	
26	23/04/18 16:45	General View					1 Load JPG		☒	
27	23/04/18 16:45	General View					1 Load JPG		☒	
28	23/04/18 16:45	General View					1 Load JPG		☒	
29	23/04/18 16:45	General View					1 Load JPG		☒	
30	23/04/18 16:45	General View					1 Load JPG		☒	
31	23/04/18 16:45	General View					1 Load JPG		☒	
32	23/04/18 16:45	General View					1 Load JPG		☒	
33	23/04/18 16:45	General View					1 Load JPG		☒	
34	23/04/18 16:45	General View					1 Load JPG		☒	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
35	23/04/18 16:45	General View	 Load JPG	☒
36	23/04/18 16:45	General View	 Load JPG	☒
37	23/04/18 16:45	General View	 Load JPG	☒
38	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
39	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
40	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
41	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
42	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
43	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
44	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
45	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
46	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
47	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
48	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
49	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
50	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
51	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
52	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
53	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
54	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
55	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
56	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
57	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
58	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
59	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
60	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
61	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
62	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
63	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
64	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
65	23/04/18 16:46	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/10/17 09:23	SJZ4927U GIA RPT	 Load PDF	
2	11/10/17 09:24	ESTIMATE	 Load PDF	
3	11/10/17 10:38	Survey AGREE ON SJE, Appoint LKK as Surveyor	 Load PDF	
4	11/10/17 10:39	Request Pre-Repair Inspection	 Load PDF	
5	11/10/17 11:15	SLK607A GIA RPT	 Load PDF	
6	11/10/17 11:15	SLE75R GIA RPT	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/04/18 14:23	SUPPLEMENTARY PART	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17019509/R1RBQ2

Date: 25/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28950489MCY

Claimant Vehicle No: SJZ4927U

Insured Vehicle No: SLE75R

Date of Loss: 10/10/2017

Nature of Claim: TP

Claim No: 532517

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJZ4927U

Make & Model: BMW 523i, 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A)

Engine No: N52B25A36A0669A101

Reg. Date: 30/11/2010 (Man. Year: 2010)

Chassis No: WBAFP32000C547026

Colour: Bronze

Odometer: 144808 km

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17

Rear Tyre Size: 225/55 R17

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,864.45	4,574.60	4,289.85	48.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,051.00	5,292.00	1,759.00	24.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,915.45	9,866.60	6,048.85	38.01
+ GST 7.00/7.00% (S\$)	1,114.08	690.66	423.42	38.01
Nett Amount (S\$)	17,029.53	10,557.26	6,472.27	38.01

INSPECTION

Date of Assignment: 11/10/2017

Date Inspected: 23/10/2017 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Apr 2018)
Parts:	143	BMW 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ4927U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR EMBOSS NUMBER PLATE	Cut	83.00 FS	*83.00 FS
2	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
3	6		*BLIND RIVET	Serviceable	7.50 FS	*- FS
4	1		*LH BOOTLID HINGE	Serviceable	110.85 FS	*- FS
5	1		*RH BOOTLID HINGE	Serviceable	110.85 FS	*- FS
6	1		*BOOTLID	Bent	1,563.30 FS	*1,563.30 FS
7	1		*SET MOUNTS PDC SENSOR REAR (PDC)	Serviceable	62.50 FS	*- FS
8	1		*RR BUMPER GUIDE BOTTOM CENTRE	Cracked	57.50 FS	*57.50 FS
9	1		*RR BUMPER CTR GUIDE	Cracked	65.75 FS	*65.75 FS
10	1		*RR BUMPER LH MOUNT	Serviceable	141.65 FS	*- FS
11	1		*RR BUMPER RH MOUNT	Serviceable	141.65 FS	*- FS
12	1		*RR BUMPER CARRIER	Bent	696.80 FS	*696.80 FS
13	1		*RR BUMPER PANEL PRIMED (PDC)	Deformed	1,431.40 FS	*1,431.40 FS
14	1		*RR BUMPER TOW HOOK COVER PRIMED	Serviceable	23.25 FS	*- FS
15	1		*LH PROTECTION FOIL	Serviceable	15.15 FS	*- FS
16	1		*RH PROTECTION FOIL	Serviceable	15.15 FS	*- FS
17	2		*PROTECTION FOIL L=55MM	Serviceable	9.30 FS	*- FS
18	1		*RR BUMPER ADAPTER	Cracked	46.80 FS	*46.80 FS
19	2		*EMBLEM GROMMET	Necessary	1.60 FS	*1.60 FS
20	1		*BMW EMBLEM	Necessary	67.80 FS	*67.80 FS
21	1		*STRIKER BOOT LID	Serviceable	52.25 FS	*- FS
22	1		*SPRING DAMPER TRUNK LID	Serviceable	84.75 FS	*- FS
23	1		*SPINDLE DRIVE RH	Serviceable	522.65 FS	*- FS
24	1		*TRUNK LID LOCK TOP	Serviceable	425.35 FS	*- FS
25	1		*TRUNK LID POWER LOCK DRIVE	Serviceable	572.30 FS	*- FS
26	1		*TRIGGER CONTACT	Serviceable	128.75 FS	*- FS
27	6		*PLUG	Necessary	10.50 FS	*10.50 FS
28	1		*LOADING SILL COVER	Serviceable	110.00 FS	*- FS
29	1		*LH GUTTER STRIP	Serviceable	16.40 FS	*- FS
30	1		*LH GUTTER STRIP	Serviceable	16.40 FS	*- FS
31	1		*BOOTLID SEALING	Serviceable	112.45 FS	*- FS
32	1		*REAR LH REFLECTOR	Serviceable	34.35 FS	*- FS
33	1		*REAR RH REFLECTOR	Serviceable	34.35 FS	*- FS
34	4		*DECOUPLING RING PDC TORQUE CONVERTE	Serviceable	19.80 FS	*- FS
35	4		*BUMPER PDC SENSOR (A17 HAVANNA)	Serviceable	1,452.20 FS	*- FS
36	2		*EXPANDING NUT	Necessary	2.00 FS	*2.00 FS
37	1		*MODEL LETTERING 523I	Necessary	61.05 FS	*61.05 FS
38	1		*COVERING REAR RIGHT	Cut	69.10 FS	*69.10 FS
39	1		*REAR RH LIGHT IN TRUNK LID	Cracked	338.00 FS	*338.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					8,864.45	4,574.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BOOT LID ,REAR BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT	New	3,400.00	2,125.00
2	SPRAY PAINTING ON REAR BOOT LID ,REAR BUMPER AND TAIL END PANEL	New	2,819.00	2,537.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	230.00
5	TO REPLACE REAR PDC SENSOR WIRE HARNESS INCLUDING RESET AND CHECKS FOR PROPER FUNCTION	New	266.00	150.00
6	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
Gross Labour Cost (S\$)			7,051.00	5,292.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >