

ASS. REC. BY: Adrian King

REF:

CC3 / ALG17019577 / Arb2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 2100346442-04

Claims No. 686221313156

Sum Insured: _____ Excess: 2000

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 130K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6.88 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKES767G Yr Regn: 2012, March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi S5 Cabriolet. c.c 2985

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 30361 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU2228F2CNO06039

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/35R19.

R: 255/35R19.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 11/10/17.

Survey held at Premium.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	DDA16.
	SKES 5167G - CC3 / ALG1402117 / Arb2k3
	DR: 250914
	Sent preli through Maximen
	Authorise approve; Inform Jeffery through email.
	Confirm \$7939.92, 6 days
	Red: \$3332.80, 30%.

RECEIVED 10 MAR 2018

Date/Time, File Pass to?

☐ : Preli. Report

1) typant

☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: 00

Lump Sum / I.B.I: (\$ 7939.92)

200

10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG17019577/Arb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 11-10-2017



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SKE 5767G
Policy No. 2100346442	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	11/10/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 06/10/2017	Inspection Date 11/10/2017
Survey held at PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1. SINGAPORE 408699	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 12 Oct 2017

Preliminary Advice

Vehicle No	: SKE5767G	Accident Date	: 06/10/2017
Make	: AUDI S5	Policy No.	: 2100346442-04
Assignment Date	: 11/10/2017	Excess	: S\$0.00
Date of Inspection	: 11/10/2017	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (HQ) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,272.00
Revised Amount	:S\$	9,045.00
Check Items (Estimated)	:S\$	536.00
Total	:S\$	9,581.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	130,000.00
COE / PARF Rebate	:S\$	91,501.00
Salvage Value	:S\$	
Margin for Repair	:S\$	38,499.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Print Received Message

This mail is associated with :

***SKE5767G (6862213131SG)**

OD

Oct 6 2017 7:55PM

[LIM ENG CHOO]

Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte, Ltd. (AIG_SG), sent on 16/10/2017 14:27 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9045.00) - SKE5767G - Claim Handler: Chan, Kian Meng

Approved:9045.00:Re-inspection to be done for damage check and supplementary items / labour.

View Received Message

This mail is associated with :

***SKE5767G (6862213131SG)**

OD

Oct 6 2017 7:55PM

[LIM ENG CHOO]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on **13/10/2017 17:37 PM.**

To LKK_HQ

Subject SKE5767G / OD / 06/10/2017 / Coverage & Excess update

Dear LKK Auto Consultants Pte Ltd

Please note that policy is in force and excess amount is \$2000.00

Thank you

Chan, Kian Meng

DOCUMENTS SUMMARY

There are no documents.

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Monday, October 16, 2017 3:59 PM
To: 'Claims Department'
Cc: SUR
Subject: RE: OD CLAIM FOR SKE 5767 G (Vehicle IN)
Attachments: SKE 5767G EST.pdf

Dear Sir,

As instructed by our client , please proceed to repair the insured vehicle **SKE 5767G (excess \$2,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Department [mailto:claims@premiumauto.com.sg]
Sent: Sunday, October 15, 2017 4:19 PM
To: Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; 'Claims Department' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIM FOR SKE 5767 G (Vehicle IN)

Dear Janice,

Any update on this case?

Many thanks!

Best regards,
Claims Advisor
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5909J
Vehicle Details	
Vehicle No.:	SKE5767G
Vehicle to be Exported:	No
Intended De-registration Date:	12 Oct 2017
Vehicle Make:	AUDI
Vehicle Model:	S5 CABRIOLET 3.0 TFSI QU (FACELIFT)
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	CGW035167
Chassis No.:	WAUZZZ8F2CN006039
Maximum Power Output:	245.0 kW (328 bhp)
Open Market Value:	\$80,649.00
Original Registration Date:	14 Mar 2012
First Registration Date:	14 Mar 2012
Transfer Count:	1
Actual ARF Paid:	\$80,649.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Mar 2022
PARF Rebate Amount:	\$56,454.00
Intended COE Rebate Details	
COE Expiry Date:	13 Mar 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$79,304.00
COE Rebate Amount:	\$35,047.00
Total Rebate Amount:	\$91,501.00

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S6905909J



Name

LIM ENG CHOO

林英珠

Race

CHINESE

Date of Birth

20-01-1969

Sex

F

Country of Birth

SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S6905909J

Name

LIM ENG CHOO

Birth Date: 20 Jan 1969

Issue Date: 10 Apr 2004



1550139

NRIC No. S6905909J



Blood Group

A+

Date of issue

28-12-1993

8 RIDGEWOOD CLOSE #01-12
SINGAPORE 276698

NRIC No: S6905909J

Date: 26/12/2012

No: 7141192

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms

19 Jan 1993

NP 428A





CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LIM ENG CHOO
Period of Insurance : 14 Sep 2017 To 13 Sep 2018
Engine No. : CGW035167
Chassis No. : WAUZZZ8F2CN006039

Vehicle No. : SKE5767G
Policy No. : 2100346442-04
Endorsement No. :
Issued Date : 13 Sep 2017

ABOUT THE COVER

Make/Model : AUDI S5 CABRIOLET 3.0 TFSI QU
Engine Capacity/Tonnage : 2,995.00 CC **Sum Insured** : Market Value
Driver Restriction : Age/DE Condition **Off Peak Car** : No **First Year of Registration** : 2012
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

- a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

Any driver who is below 26 years old is not covered under this Policy.
 You have to pay an additional sum of \$5,000 as "Elderly, Young and/or Inexperienced Driver Excess" ("EYIDR") if You are or Your Authorised Driver (named or unnamed) is above the age of 65 or under the age of 26 and/or has less than 2 years' driving experience.

Age Condition : Not Applicable

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$2000 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LIM ENG CHOO - \$2000 (Own Damage) LIM ENG MOY - \$2000 (Own Damage) Ang Thiam Teng, Alcer - \$2000 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63682323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125200

PREMIUM LEASING - AP
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SSPBRV

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0993/2017/JT
Date	:	10-Oct-17

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms. Lim Eng Choo
Address	:	8 Ridgewood Close #01-12 Singapore 276698
Telephone	:	HP +65 9631 7179
Type of Claim	:	Own Damage Claims
Policy No.	:	2100346442-04
Vehicle No	:	SKE 5767 G
Model Code	:	Audi S5 3.0 TFSI qu
Model / Year	:	Mar-12
Engine No	:	CGW 035167
Chassis No	:	WAUZZZ8F2CN006039
Mileage	:	-
Date In	:	10-Oct-17
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	6-Oct-17
Place of Accident	:	Newton Circus

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKE 5767 G.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer and front parking aid.	S/N \$ 480.00 ✓ /	
2	To dismantle and renew front bumper, LHS front fender and LHS headlight. Re-organize front crash management components. Reinstall all parts removed	\$ 2,100.00 1250 ✓	
3	To respray front bumper and LHS front fender.	\$ 1,500.00 1100 ✓	
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓ /	
TOTAL LABOUR CHARGES		: \$ 4,272.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKE 5767 G.

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	FRONT BUMPER <i>Deland</i>	\$ 2,429.00	✓ 1943.20
2	FRONT AIR GRILLE - LHS <i>Missing</i>	\$ 291.00	✓ 232.80
3	FRONT BUMPER GUIDE - LHS <i>new</i>	\$ 36.00	?
4	FRONT FENDER <i>Dented</i>	\$ 900.00	✓ 720.00
5	FRONT FENDER INNER BRACKET - LHS <i>new</i>	\$ 49.00	?
6	FRONT FENDER OUTER BRACKET - LHS <i>new</i>	\$ 49.00	?
7	FRONT FENDER BRACE - LHS <i>cut</i>	\$ 102.00	? 81.60
8	"V6T" EMBLEM <i>new</i>	\$ 105.00	✓ 84.00
9	FRONT INNER WHEEL HOUSE LINER - LHS <i>new</i>	\$ 208.00	+
10	FRONT WHEEL HOUSE LINER ATTACHMENT - LHS <i>new</i>	\$ 38.00	+
11	HEADLIGHT - LHS <i>cut</i>	\$ 2,298.00	✓ 1838.40
12	HEADLIGHT BRACKET - LHS <i>new</i>	\$ 89.00	+
13	HEADLIGHT MOUNTING - LHS <i>new</i>	\$ 106.00	+
14	SUNDRIES <i>new</i>	\$ 300.00	? 17.92
TOTAL SPARE PARTS		\$ 7,000.00	
TOTAL LABOUR CHARGES		\$ 4,272.00	
GRAND TOTAL		\$ 11,272.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian
Surveyed Date : 11/10/17.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Janice Lee (LKKAUTO)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Monday, December 04, 2017 8:47 AM
To: Janice Lee (LKKAUTO); Adrian Ling (LKKAUTO); SUR; Carrine Leong; Nora Khai
Subject: FINAL REVISION SLE5767G - OD AIG - SURVEYED 11 OCT 17
Attachments: PA09932017 - SKE 5767 G - S5 3.0 TFSI qu - Front (AIG).xls; 20171019_154522.jpg; 20171020_091809.jpg; 20171020_091820.jpg; 20171020_091831.jpg

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$7939.92 @ 6 days of repairs.

Photos attached.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0993/2017/JT
Date : 10-Oct-17

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
We took 6 days - ok - jb -4 Dec

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Lim Eng Choo
Address : 8 Ridgewood Close
#01-12
Singapore 276698
Telephone : HP +65 9631 7179
Type of Claim : Own Damage Claims
Policy No. : 2100346442-04
Vehicle No : **SKE 5767 G**
Model Code : Audi S5 3.0 TFSI qu
Model / Year : Mar-12
Engine No : CGW 035167
Chassis No : WAUZZZ8F2CN006039
Mileage : -
Date In : 10-Oct-17
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 06-Oct-17
Place of Accident : Newton Circus

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKE 5767 G.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer and front parking aid.	S/N \$ 480.00	\$ 480.00
2	To dismantle and renew front bumper, LHS front fender and LHS headlight. Re-organize front crash management components. Reinstall all parts removed.	\$ 2,100.00	\$ 1,250.00
3	To respray front bumper and LHS front fender.	\$ 1,500.00	\$ 1,100.00
4	To carry out diagnostic checks.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 4,272.00	\$ 3,022.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKE 5767 G.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,429.00	\$ 1,943.20
2	FRONT AIR GRILLE - LHS	\$ 291.00	\$ 232.80
3	FRONT BUMPER GUIDE - LHS	\$ 36.00	
4	FRONT FENDER	\$ 900.00	\$ 720.00
5	FRONT FENDER INNER BRACKET - LHS	\$ 49.00	
6	FRONT FENDER OUTER BRACKET - LHS	\$ 49.00	
7	FRONT FENDER BRACE - LHS	\$ 102.00	\$ 81.60
8	"V6T" EMBLEM	\$ 105.00	\$ 84.00
9	FRONT INNER WHEEL HOUSE LINER - LHS	\$ 208.00	
10	FRONT WHEEL HOUSE LINER ATTACHMENT - LHS	\$ 38.00	
11	HEADLIGHT - LHS	\$ 2,298.00	\$ 1,838.40
12	HEADLIGHT BRACKET - LHS	\$ 89.00	
13	HEADLIGHT MOUNTING - LHS	\$ 106.00	
14	SUNDRIES	\$ 300.00	\$ 17.92
TOTAL SPARE PARTS		\$ 7,000.00	\$ 4,917.92
TOTAL LABOUR CHARGES		\$ 4,272.00	\$ 3,022.00
GRAND TOTAL		\$ 11,272.00	\$ 7,939.92

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKE 5767 G

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0993/2017/MAS

13 March 2018

from
Telephone +65-
Telefax +65-
Email
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SKE 5767 G, Audi S5 Cab 3.0 TFSI Qu

With reference to the above-mentioned vehicle, no **SKE 5767 G**, claimant, **Ms. Lim Eng Choo**, please find the related document per attached.

1. A copy of the Original invoice no. 85012237 – S\$6,355.71
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai

Claims Dept

Encls

AIG – SKE 5767 G

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Oct 2017 12:10		11 Oct 2017 17:59 Edit Adj Rpt	\$57,939.92 Edit Estimates	\$57,939.92 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	LIM ENG CHOO, ID: S69059093, Tel: +6596317179, Email: CYNDYLEE@HOTMAIL.COM								
Vehicle Reg. No.:	SKE5767G	Date of Loss:	06/10/2017 19:00 - :59						
Claim Type:	OD / 6862213131SG	Policy/Cover Note No.:	2100346442-04 (Comprehensive)						
		Excess:	S\$2,000.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Kian Meng] kianmeng.chan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 23/10/2017]								
Driver/Custodian:	LIM ENG CHOO (48 / Female), NRIC: S69059093, Tel: +6596317179								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
● AIG_SG (16/10/2017): Alert - Adj Mandate Approved (S\$9045.00) - SKE5767G - Claim Handler: Chan, Kian ... ● AIG_SG (13/10/2017): SKE5767G / OD / 06/10/2017 / Coverage & Excess update									
☐ ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKE5767G (6862213131SG)

OD

Oct 6 2017 7:55PM

[LIM ENG CHOO]

Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		Use Viewer	
Assessment Reports														1 per page		☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print			
1	12/10/17 12:18	Adjuster Immediate Advice												Load HTM				
Photos/Images														3 per page		☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print			
1	12/10/17 12:03	General View												Load JPG	☒			
2	12/10/17 12:03	General View												Load JPG	☒			
3	12/10/17 12:03	General View												Load JPG	☒			
4	12/10/17 12:03	General View												Load JPG	☒			
5	12/10/17 12:03	General View												Load JPG	☒			
6	12/10/17 12:03	General View												Load JPG	☒			
7	12/10/17 12:03	General View												Load JPG	☒			
8	12/10/17 12:03	General View												Load JPG	☒			
9	12/10/17 12:03	General View												Load JPG	☒			
10	12/10/17 12:03	General View												Load JPG	☒			
11	12/10/17 12:03	General View												Load JPG	☒			
12	19/03/18 14:45	Reinspection Photo												Load JPG	☒			
13	19/03/18 14:45	Reinspection Photo												Load JPG	☒			
14	19/03/18 14:45	Reinspection Photo												Load JPG	☒			
15	19/03/18 14:45	Reinspection Photo												Load JPG	☒			
Documentation														1 per page		☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print			
1	12/10/17 12:02	Certificate of Insurance												Load PDF				
2	12/10/17 12:02	DL & NRIC												Load PDF				
3	12/10/17 12:02	WORKSHOP ESTIMATE												Load PDF				
4	12/10/17 12:02	Singapore Accident Statement												Load PDF				
5	21/03/18 10:06	WORKSHOP INVOICE												Load PDF				
6	21/03/18 10:06	DISCHARGE VOUCHER												Load PDF				

Linked Accident Report Documents

				View Use Viewer	
Assessment Reports				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	09/10/17 19:06	Accident Statement		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	09/10/17 19:03	Accident Photo		Load JPG	☒
2	09/10/17 19:03	Accident Photo		Load JPG	☒
3	09/10/17 19:03	Accident Photo		Load JPG	☒
4	09/10/17 19:03	Accident Photo		Load JPG	☒
5	09/10/17 19:03	Accident Photo		Load JPG	☒
6	09/10/17 19:03	Accident Photo		Load JPG	☒
7	09/10/17 19:03	Accident Photo		Load JPG	☒

8	09/10/17 19:03	Accident Photo		Load JPG	☒
9	09/10/17 19:03	Accident Photo		Load JPG	☒
Documentation					
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		1 per page	☒
1	09/10/17 19:00	Sketch Plan		Load JPG	☒
2	09/10/17 19:00	Sketch Plan #2		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG17019577/ARBN2

Date: 21/03/2018

REFERENCE

Insured/Claimant: LIM ENG CHOO Policy No: 2100346442-04
Date of Loss: 06/10/2017 Nature of Claim: OD Claim No: 6862213131SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKE5767G
Make & Model: AUDI S5, 3.0 TFSI QUATTRO (A) Engine No: CGW035167
Reg. Date: 14/03/2012 (Man. Year: 2012) Chassis No: WAUZZZ8F2CN006039
Colour: White Odometer: 30361 km
Engine Capacity: 2995 cc
Market Value/New Car Price: S\$130,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/35R19 Rear Tyre Size: 255/35R19
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,000.00	4,917.92	2,082.08	29.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,272.00	3,022.00	1,250.00	29.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,272.00	7,939.92	3,332.08	29.56
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	9,272.00	5,939.92	3,332.08	35.94
+ GST 7.00/7.00% (S\$)	649.04	415.79	233.25	35.94
Nett Amount (S\$)	9,921.04	6,355.71	3,565.33	35.94

INSPECTION

Date of Assignment: 11/10/2017
Date Inspected: 11/10/2017 Inspected At: Premium Automobiles Pte Ltd (HQ)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	2,429.00 FS	*1,943.20 FS
2	1	*FRONT AIR GRILLE-LHS	Missing	291.00 FS	*232.80 FS
3	1	*FRONT BUMPER GUIDE-LHS	Not Necessary	36.00 FS	*- FS
4	1	*FRONT FENDER	Dented	900.00 FS	*720.00 FS
5	1	*FRONT FENDER INNER BRACKET-LHS	Not Necessary	49.00 FS	*- FS
6	1	*FRONT FENDER OUTER BRACKET-LHS	Not Necessary	49.00 FS	*- FS
7	1	*FRONT FENDER BRACE-LHS	Bent	102.00 FS	*81.60 FS
8	1	*V6T EMBLEM	Necessary	105.00 FS	*84.00 FS
9	1	*FRONT INNER WHEEL HOUSE LINER-LHS	Not Necessary	208.00 FS	*- FS
10	1	*FRONT WHEEL HOUSE LINER ATTACHMENT-LHS	Not Necessary	38.00 FS	*- FS
11	1	*HEADLIGHT-LHS	Cut	2,298.00 FS	*1,838.40 FS
12	1	*HEADLIGHT BRACKET-LHS	Not Necessary	89.00 FS	*- FS
13	1	*HEADLIGHT MOUNTING-LHS	Not Necessary	106.00 FS	*- FS
14	1	*SUNDRIES	Necessary	300.00 FS	*17.92 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 7,000.00 4,917.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND LHS HEADLIGHT.RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	1,500.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			4,272.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >