

ASS. REC. BY: Adrian Ling

REF:

003 / ALG17019635 / A602

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 7109485170Claims No. 79124609715Sum Insured: _____ Excess: 600 16/10/17

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 138k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 08 8/8 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 53C 3122C Yr Regn: 2016 / Sept.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Audi A4 C.C. 1395Colour: white A/C: Insured / Std / NI / NASp. Reading: 17040 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU222F4XHA025468Gen. Cond: Good / Fair / Poor / BurntSteering: in order / Jammed / Leaked / Burnt or _____Brake: in order / Jammed / Leaked / Burnt or _____Modi: Nil / S/Rim / STD A/Rim or _____Tyre Size: F: 245/40 R18R: 245/40 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 12/10/17Survey held at PremiumDes. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	OD A19.
	53C 3122C - 003 / ALG17019635 / K2H2
12/10/17 @ 5.36pm	revert to Victor via Wechat.
16/10/17 @ 2.39pm	Victor informed via Wechat.
16/10/17 @ 5.13pm	informed Jeffrey via email.
20/12/17 @ 5.15pm	confirmed with Mr Boo final fig \$22474.04, 8 days by email. (Red & 21706.76, 49%)
24/12/17 @ 11.02am	re-confirmed with Carline final fig \$22489.04 by email. (Red & 21691.76, 49%)

Date/Time, File Pass to? ☐ : Preli. Report

1) 19/11/17 ☐ : Final Report

Date/Time, File Return to? _____

2) _____

Report Format: MER-OD

Lump Sum / I.B.I: (\$) 22474.04

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Invs (\$) ☐ : Weekend (\$)

Survey Fee: 200

Transportation: _____

\$ + RS. \$ _____

Photos: 10

Others: _____

TOTAL: 210




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG17019635/Aqb		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 12-10-2017		
Code : AIG				
1. Policy Particulars : OWN DAMAGE				
Insured Veh.		Veh. Inspected	SJC 3122C	
Policy No.	2100485170	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	12/10/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/10/2017	Inspection Date	12/10/2017	
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1. SINGAPORE 408699			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

Survey Department Check List (Case Handler)

Reference No. CC3/MG17019635/Aq6
Policy Type: OD / TP / TP RES / TL / EVA

SJC 3122C

Case Handler

Typist

Admin (Cather): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Adnan): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp. Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			
✓			
✓			
✓			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

✓			
---	--	--	--

Check By:

[Signature] 20/12/17
Case Handler Date

*C: Critical *N: Non-Critical

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 29 December, 2017 11:03 AM
To: 'Carrine Leong'
Cc: 'Boo seng yak'; SUR
Subject: RE: FINAL REVISION - SJC3122C - OD AIG - SURVEYED 12 OCT 17

Dear Carrine,

Re-confirm final fig \$22,489.04 before excess \$600.00 & GST and 8 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Wishes you a Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong [mailto:carrine.leong@premiumauto.com.sg]
Sent: Thursday, 28 December, 2017 10:29 AM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: 'Boo seng yak' <boojohnny@gmail.com>
Subject: RE: FINAL REVISION - SJC3122C - OD AIG - SURVEYED 12 OCT 17

Dear Adrian & Shiau Chan,

Revised estimate is attached.

Please re-confirm finalise COR at \$22489.04 instead of \$22474.04 (white colour number plate should be \$40.00 instead of \$25.00)

Thanks & Best Regard

Carrine Leong

Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 **d.** +65 6768 9925 **f.** +65 6841 1183

e. carrine.leong@premiumauto.com.sg **w.** www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 **p.** +65 6836 2223

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 20 December, 2017 5:15 PM
To: Boo seng yak; SUR; Carrine Leong; Nora Khai; Chang Chee Sing
Subject: RE: FINAL REVISION - SJC3122C - OD AIG - SURVEYED 12 OCT 17

Dear Mr Boo,

Confirm final fig \$22,474.04 before excess \$600.00 & GST and 8 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [<mailto:boojohnny@gmail.com>]
Sent: Friday, 8 December, 2017 12:52 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Nora Khai <nora.khai@premiumauto.com.sg>; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SJC3122C - OD AIG - SURVEYED 12 OCT 17

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$22,474.04 @ 8 days of repairs.

Photographs can be obtain from Ubi - Jeffrey Tan

Your early closure is well appreciated.

Best regards - jb

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 16 October, 2017 5:13 PM
To: 'Claims Department'; SUR
Subject: RE: SJC 3122 C Own Damage Claim (Vehicle IN)

Dear Jeffrey,

As instructed by our client AIG , please proceed to repair the insured vehicle **SJC 3122C (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Department [mailto:claims@premiumauto.com.sg]
Sent: Friday, 13 October, 2017 8:09 AM
To: SUR <sur@lkkauto.com>
Cc: 'Claims Department' <claims@premiumauto.com.sg>
Subject: RE: SJC 3122 C Own Damage Claim (Vehicle IN)

Dear all,

Any update on the approval for this?

Vehicle is in the workshop pending approval before repairs.

Many thanks!

Best regards,

Claims Advisor

Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	11 Oct 2017 13:28	Clim Veh Model Changed		[] Merimen Administrator
2	11 Oct 2017 13:28	Clim Created	Reg No: SJC3122C. Policy No: 2100485170-01. Acct Date: 2017/10/11. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA117135114	[I] Merimen Administrator
3	12 Oct 2017 14:32	Clim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] DENISE TAY KWEE CHENG
4	12 Oct 2017 14:32	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] DENISE TAY KWEE CHENG
5	12 Oct 2017 14:32	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] DENISE TAY KWEE CHENG
6	12 Oct 2017 14:32	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/10/24	[A] DENISE TAY KWEE CHENG
7	12 Oct 2017 14:32	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] DENISE TAY KWEE CHENG
8	12 Oct 2017 14:32	Clim Registration Modified	Rep:1137->200611.	[A] DENISE TAY KWEE CHENG
9	12 Oct 2017 14:32	Clim Veh Model Changed	(204567) AUDI A4 1.4 T (A).	[A] DENISE TAY KWEE CHENG
10	12 Oct 2017 14:32	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] DENISE TAY KWEE CHENG
11	12 Oct 2017 16:58	Adj Rpt Initiated		[A] SHIAU CHAN
12	12 Oct 2017 16:58	Clim Details Notified		[A] SHIAU CHAN
13	12 Oct 2017 17:35	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/10/24	[A] SHIAU CHAN
14	12 Oct 2017 17:36	Adj Mandate Request	Cur.Req:30973.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
15	13 Oct 2017 17:43	Clim Registration Modified	Init.Est.:->5,000 - 6,000. Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Chan, Kian Meng
16	13 Oct 2017 17:43	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
17	16 Oct 2017 14:39	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/10/24. Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
18	16 Oct 2017 14:39	Adj Mandate Set	Approved:23997.00:Re-inspection to be done for damage check and supplementary items / labour. Reinsp:Yes.	[I] Koh, Victor-CK

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1609310	12/10/2017 16:58	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SJC3122C		10.70

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 12 Oct 2017

Preliminary Advice

Vehicle No	: SJC3122C	Accident Date	: 11/10/2017
Make	: AUDI A4	Policy No.	: 2100485170-01
Assignment Date	: 12/10/2017	Excess	: S\$0.00
Date of Inspection	: 12/10/2017	Est. Duration of Repair	: 9.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (HQ) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	44,181.00
Revised Amount	:S\$	23,997.00
Check Items (Estimated)	:S\$	6,976.00
Total	:S\$	30,973.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	138,000.00
COE / PARF Rebate	:S\$	69,750.00
Salvage Value	:S\$	
Margin for Repair	:S\$	68,250.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 1975J

Vehicle Details

Vehicle No.: SJC3122C

Vehicle to be Exported: No

Intended De-registration Date: 12 Oct 2017

Vehicle Make: AUDI

Vehicle Model: A4 1.4 TFSI S TRONIC

Primary Colour: White

Manufacturing Year: 2016

Engine No.: CVN017647

Chassis No.: WAUZZZF4XHA025468

Maximum Power Output: 110.0 kW (147 bhp)

Open Market Value: \$32,161.00

Original Registration Date: 30 Sep 2016

First Registration Date: 30 Sep 2016

Transfer Count:

Actual ARF Paid: \$27,026.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Sep 2026

PARF Rebate Amount: \$20,269.00

Intended COE Rebate Details

COE Expiry Date: 29 Sep 2026

COE Category: E - Open Category

COE Period(Years): 10


QP Paid: \$55,201.00

COE Rebate Amount: \$49,481.00

Total Rebate Amount: \$69,750.00

The information contained herein is correct as at 12 Oct 2017

OK

 Land Transport Authority (<https://www.lta.gov.sg>)

Please read through the Privacy Statement, Terms of Use, and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) |

[Rate this e-Service \(https://www.lta.gov.sg/feedback/PublicSurv.aspx?SurveyDetlNum=S201400011\)](https://www.lta.gov.sg/feedback/PublicSurv.aspx?SurveyDetlNum=S201400011)

Last updated on 08 Oct 2017 at 01:03 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/10/2017 13:13
Date Of Accident	11/10/2017 07:20
Exact Location Of Accident	EXIT TO BOON LAY WAY FROM YUAN CHING RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJC3122C
Insured/Policyholder	
Name Of Registered Owner	TIN MIN
NRIC No	S6861975J
Email Address	MINNMINN2003@YAHOO.COM
Mobile Phone No	(LOCAL) +65-97320559
Alternative Phone No	HOME-63393945

Vehicle Particulars

Manufacturer	AUDI
Model	A4 SEDAN 1.4 TFSI S
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100485170-01
Cover Note Number	

Driver

Name of Driver	TIN MIN
NRIC No	S6861975J
Date Of Birth	26/06/1968
Occupation	INDOOR
Date Of Driving Pass	20/04/1995
Driving Experience	22 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97320559
Fax Number	
Contact Number	HOME-63393945
Email Address	MINNMINN2003@YAHOO.COM

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 11/10/17

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: ~~Woo Heng Guan~~ Tony Fung

NRIC/FIN No.: 92040174




Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo





CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Tin Min
Period of Insurance : 30 Sep 2017 To 29 Sep 2018
Engine No. : CVN017647
Chassis No. : WAUZZZF4XHA025468

Vehicle No. : SJC3122C
Policy No. : 2100485170-01
Endorsement No. :
Issued Date : 13 Sep 2017

ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2016
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Tin Min - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125219

PREMIUM LEASING - KATL

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Monile

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSCZSS

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S6861975J



Name

TIN MIN

Race

BURMESE

Date of birth

26-06-1968


Sex

M

S6861975J

Country of birth

MYANMAR



4010479

NRIC No. S6861975J



Date of issue

05-03-2007

56 LAKESIDE DRIVE, CASPIAN #07-26
SINGAPORE 648318

NRIC No: S6861975J

Date: 18/03/2013

No: 7335329

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

VALID DATE

Class 3 Motor cars =< 3000 kg with =< 7 passengers,
exclusive of the driver; and motor tractors
/vehicles =< 2500 kg

20 Apr 1996

NP 428A



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1011/2017/JT
Date : 12-Oct-17

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tin Min
Address : 56 Lakeside Drive
#07-26
Singapore 648318
Telephone : HP +65 9732 0559
Type of Claim : Own Damage Claims
Policy No. : 2100485170-01
Vehicle No : **SJC 3122 C**
Model Code : Audi A4 Sedan 1.4 TFSI
Model / Year : Sep-16
Engine No : CVN 017647
Chassis No : WAUZZZF4XHA025468
Mileage : -
Date In : 11-Oct-17
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 11-Oct-17
Place of Accident : Exit to Boon Lay way from Yuan Ching Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJC 3122 C.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 //	
2	To remove and transfer aircond condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum and to pressurize cooling system.	S/N \$ 1,000.00 //	
3	To dismantle front bumper, LHS front fender and bonnet. Renew front lock carrier and align to position. Renew front bumper, LHS front fender, bonnet and both headlights. Re-organize front crash management components. Reinstall all parts removed.	\$ 4,800.00 3000.	
4	To remove both front door panel trims, Remove and reinstall both wing mirror assy and renew window slot chrome. Reinstall all parts removed.	S/N \$ 600.00 //	
5	Torespray front bumper, both front fender, bonnet, bonnet hinges, front front doors and LHS A-pillar.	\$ 5,000.00 3600.	
6	To carry out diagnostic checks.	S/N \$ 192.00 //	
TOTAL LABOUR CHARGES		: \$ 11,952.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJC 3122 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	\$ 1,703.00	✓ 1362.40
2	FRONT BUMPER GRILLE - CENTRE <i>Dgd</i>	\$ 163.00	? 130 ✓
3	FRONT BUMPER CLOSING ELEMENT <i>not in</i>	\$ 171.00	x
4	AIR GUIDE COVER - LHS <i>not in</i>	\$ 67.00	x
5	RADIATOR GRILLE <i>cracked</i>	\$ 941.00	✓ 742.40
6	AIR GUIDE GRILLE - LHS/RHS <i>not in</i>	\$ 224.00	x
7	FRONT REINFORCEMENT BEAM <i>Bent</i>	\$ 674.00	✓ 539.20
8	REINFORCEMENT BEAM HOLDER - LHS/RHS <i>RH Dgd</i>	\$ 356.00	? 142.40 ✓
9	FRONT BUMPER GUIDE - LHS/RHS <i>not in</i>	\$ 60.00	x 47.28 ✓
10	FRONT BUMPER TOP COVER <i>cracked</i>	\$ 104.00	✓ 82.80
11	CAUTION STICKER <i>not in</i>	\$ 12.00	- 9.04
12	A/C STICKER <i>not in</i>	\$ 6.00	✓ 4.64
13	RELEASE LEVER <i>not in</i>	\$ 12.00	x
14	FOAM FILLER PIECE <i>Rebound</i>	\$ 101.00	✓ 80.30
15	LOCK CARRIER BRACKET <i>Dgd</i>	\$ 112.00	? 89.20 ✓
16	FRONT BUMPER SUPPORT <i>Dgd</i>	\$ 46.00	? 18 ✓
17	FRONT FENDER - LHS <i>Dented</i>	\$ 643.00	✓ 514.40
18	FRONT FENDER CLOSING ELEMENT - LHS <i>not in</i>	\$ 42.00	x 32.44
19	FRONT FENDER INNER BRACKET - LHS <i>not in</i>	\$ 29.00	? x
20	FRONT FENDER OUTER BRACKET - LHS <i>not in</i>	\$ 42.00	? x
SUB-TOTAL SPARE PARTS		\$ 5,508.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJC 3122 C.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT FENDER BRACE - LHS <i>Best.</i>	\$ 100.00	? 79.44 ✓
22	FRONT FENDER CORNER COVER - LHS/RHS <i>LH RH</i>	\$ 38.00	19. 14.64
23	FRONT FENDER TOP COVER - LHS/RHS <i>LH RH</i>	\$ 48.00	24. 15.58
24	FRONT FENDER COVER - LHS <i>rh</i>	\$ 52.00	- 40.96
25	LED HEADLIGHT - LHS/RHS <i>LH covered</i>	\$ 15,722.00	7861 6798.80
26	HEADLIGHT POWER CONTROL MODULE - LHS <i>Not New</i>	\$ 685.00	? X
27	HEADLIGHT CONTROL UNIT - LHS <i>Not New</i>	\$ 634.00	? X
28	HEADLIGHT COMPENSATING PIECE <i>Not New</i>	2 \$ 74.00	? X
29	HEADLIGHT WASHER - LHS <i>Not New</i>	\$ 180.00	? X
30	HEADLIGHT WASHER BRACKET - LHS <i>Not New</i>		? X
31	HEADLIGHT WASHER HOSE <i>Not New</i>	\$ 75.00	*
32	BONNET <i>Detached</i>	\$ 2,001.00	- 1600.80
33	BONNET ATTACHMENT PARTS <i>Not New</i>	\$ 103.00	? X
34	BONNET HINGE - LHS/RHS <i>Not New</i>	\$ 514.00	*
35	BONNET SEAL - LHS/RHS <i>rh</i>	\$ 46.00	- 36.32
36	BONNET CENTRE <i>rh</i>	\$ 23.00	✓ 18.16
37	BONNET STRIKER <i>2 Not New</i>	\$ 86.00	+
38	BONNET LID LOCK <i>Not New</i>	\$ 360.00	+
39	BOWDEN CABLE <i>Not New</i>	\$ 49.00	+
40	LOCK CARRIER <i>covered</i>	\$ 878.00	✓ 703.40
SUB-TOTAL SPARE PARTS		\$ 21,668.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJC 3122 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	LOCK CARRIER SUPPORT <i>Not New</i>	2 \$	64.00 ? X
42	LOCK CARRIER AIR GUIDE - LHS/RHS <i>24 del</i>	\$	44.00 ? 17.44 ✓
43	LOCK CARRIER LOWER AIR GUIDE - LHS/RHS <i>24 del</i>	\$	20.00 ? 7.36 ✓
44	A/C CONDENSER <i>del</i>	\$	525.00 ? 419.60 ✓
45	RADIATOR <i>New</i>	\$	572.00 ? X
46	RADIATOR BUSH <i>New</i>	4 \$	38.00 ? X
47	ADDITIONAL RADIATOR <i>del</i>	\$	444.00 X 354.80 ✓
48	COOLANT <i>New</i>	4 \$	132.00 - 105.28
49	FAN RING COVER <i>New</i>	\$	222.00 ? X
50	RADIATOR FAN WITH CTRL UNIT <i>del New</i>	\$	1,949.00 ? X
51	WINDOW CHROME SLOT SHIELD - LHS/RHS <i>del New</i>	\$	518.00 ? X
52	FRONT NUMBER <i>New</i>	S/N \$ 40	25.00 -
53	SUNDRIES <i>All</i>	\$	500.00 ? 42.16 ✓
TOTAL SPARE PARTS		\$	32,229.00 32244
GRAND TOTAL SPARE PARTS		\$	11,952.00
TOTAL LABOUR		\$	44,181.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

44196.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Lij*
Surveyed Date : *12/10/17*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 09 Days.*

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1011/2017/JT
Date : 12-Oct-17

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tin Min
Address : 56 Lakeside Drive
#07-26
Singapore 648318
Telephone : HP +65 9732 0559
Type of Claim : Own Damage Claims
Policy No. : 2100485170-01
Vehicle No : **SJC 3122 C**
Model Code : Audi A4 Sedan 1.4 TFSI
Model / Year : Sep-16
Engine No : CVN 017647
Chassis No : WAUZZZF4XHA025468
Mileage : -
Date In : 11-Oct-17
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 11-Oct-17
Place of Accident : Exit to Boon Lay way from Yuan Ching Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJC 3122 C.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$ 360.00
2	To remove and transfer aircond condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum and to pressurize cooling system.	S/N	\$ 1,000.00	\$ 1,000.00
3	To dismantle front bumper, LHS front fender and bonnet. Renew front lock carrier and align to position. Renew front bumper, LHS front fender, bonnet and both headlights. Re-organize front crash management components. Reinstall all parts removed.		\$ 4,800.00	\$ 3,000.00
4	To remove both front door panel trims, Remove and reinstall both wing mirror assy and renew window slot chrome. Reinstall all parts removed.	S/N	\$ 600.00	\$ 600.00
5	Torespray front bumper, both front fender, bonnet, bonnet hinges, front front doors and LHS A-pillar.		\$ 5,000.00	\$ 3,600.00
6	To carry out diagnostic checks.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 11,952.00	\$ 8,752.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJC 3122 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,703.00	\$ 1,362.40
2	FRONT BUMPER GRILLE - CENTRE	\$ 163.00	\$ 130.00
3	FRONT BUMPER CLOSING ELEMENT	\$ 171.00	
4	AIR GUIDE COVER - LHS	\$ 67.00	
5	RADIATOR GRILLE	\$ 941.00	\$ 752.40
6	AIR GUIDE GRILLE - LHS/RHS	\$ 224.00	
7	FRONT REINFORCEMENT BEAM	\$ 674.00	\$ 539.20
8	REINFORCEMENT BEAM HOLDER - LHS/RHS	\$ 356.00	\$ 142.40
9	FRONT BUMPER GUIDE - LHS/RHS	\$ 60.00	\$ 47.28
10	FRONT BUMPER TOP COVER	\$ 104.00	\$ 82.80
11	CAUTION STICKER	\$ 12.00	\$ 9.04
12	A/C STICKER	\$ 6.00	\$ 4.64
13	RELEASE LEVER	\$ 12.00	
14	FOAM FILLER PIECE	\$ 101.00	\$ 80.80
15	LOCK CARRIER BRACKET	\$ 112.00	\$ 89.20
16	FRONT BUMPER SUPPORT	\$ 46.00	\$ 18.00
17	FRONT FENDER - LHS	\$ 643.00	\$ 514.40
18	FRONT FENDER CLOSING ELEMENT - LHS	\$ 42.00	\$ 33.44
19	FRONT FENDER INNER BRACKET - LHS	\$ 29.00	
20	FRONT FENDER OUTER BRACKET - LHS	\$ 42.00	
SUB-TOTAL SPARE PARTS		\$ 5,508.00	\$ 3,806.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJC 3122 C.

S/N	Parts Description	Damage Parts & Prices		
		S/NETT	REMARKS	
		<i>cf</i>	\$	3,806.00
21	FRONT FENDER BRACE - LHS	\$ 100.00	\$	79.44
22	FRONT FENDER CORNER COVER - LHS/RHS	\$ 38.00	\$	14.64
23	FRONT FENDER TOP COVER - LHS/RHS	\$ 48.00	\$	18.88
24	FRONT FENDER COVER - LHS	\$ 52.00	\$	40.96
25	LED HEADLIGHT - LHS/RHS	\$ 15,722.00	\$	6,288.80
26	HEADLIGHT POWER CONTROL MODULE - LHS	\$ 685.00		
27	HEADLIGHT CONTROL UNIT - LHS	\$ 634.00		
28	HEADLIGHT COMPENSATING PIECE	2 \$ 74.00		
29	HEADLIGHT WASHER - LHS	\$ 180.00		
30	HEADLIGHT WASHER BRACKET - LHS			
31	HEADLIGHT WASHER HOSE	\$ 75.00		
32	BONNET	\$ 2,001.00	\$	1,600.80
33	BONNET ATTACHEMENT PARTS	\$ 103.00		
34	BONNET HINGE - LHS/RHS	\$ 514.00		
35	BONNET SEAL - LHS/RHS	\$ 46.00	\$	36.32
36	BONNET CENTRE	\$ 23.00	\$	18.16
37	BONNET STRIKER	\$ 86.00		
38	BONNET LID LOCK	\$ 360.00	\$	144.00
39	BOWDEN CABLE	\$ 49.00		
40	LOCK CARRIER	\$ 878.00	\$	702.40
SUB-TOTAL SPARE PARTS		\$ 21,668.00	\$	12,750.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJC 3122 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
		<i>cf</i>	\$ 12,750.40
41	LOCK CARRIER SUPPORT	2 \$ 64.00	
42	LOCK CARRIER AIR GUIDE - LHS/RHS	\$ 44.00	\$ 17.44
43	LOCK CARRIER LOWER AIR GUIDE - LHS/RHS	\$ 20.00	\$ 7.36
44	A/C CONDENSER	\$ 525.00	\$ 419.60
45	RADIATOR	\$ 572.00	
46	RADIATOR BUSH	4 \$ 38.00	
47	ADDITIONAL RADIATOR	\$ 444.00	\$ 354.80
48	COOLANT	4 \$ 132.00	\$ 105.28
49	FAN RING COVER	\$ 222.00	
50	RADIATOR FAN WITH CTRL UNIT	\$ 1,949.00	
51	WINDOW CHROME SLOT SHIELD - LHS/RHS	\$ 518.00	
52	FRONT NUMBER (WHITE BASE)	S/N \$ 25.00	\$ 40.00
53	SUNDRIES	\$ 500.00	\$ 42.16
	TOTAL SPARE PARTS	\$ 32,229.00	\$ 13,737.04
	GRAND TOTAL SPARE PARTS	\$ 11,952.00	\$ 8,752.00
	TOTAL LABOUR	\$ 44,181.00	\$ 22,489.04

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SJC 3122 C

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1011/2017/MAS

16 Jan 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SJC 3122 C, Audi A4 SEDAN 1.4 TFSI S-Tro

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SJC 3122 C**, claimant, **Mr. Tin Min**, please find the related document per attached.

1. A copy of the Original invoice no. 85012008 – S\$23,421.27
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SJC 3122 C



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Telephone 6386 2323

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 11:22

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012008 Date : 09/01/2016 Order : SJC3122C Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SJC3122C (V 31177)	Regn Date: 30/09/2016	Mileage: 17040	WIP No.: 41417
Model: A4 SEDAN 1.4 TFSI S tronic	Chassis: WAUZZZF4XH0025468	Engine: CVN 017647	Dept: U
VSB No.:			
You have been assisted by :- UB-Carrine (33)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	360.00	1.00	360.00
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE.	40.00	1.00	40.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER AIRCOND CONDENSER, RADIO/TRAFFIC CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT TO CARRY OUT VACUUM AND PRESSURIZE COOLING SYSTEM.	1000.00	1.00	1,000.00
S	BODYWORK	M: TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	3000.00	1.00	3,000.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Telephone 6388 2323

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 2 11:22

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012008 Date : 09/01/2018 Order : SJC3122C Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SJC3122C (V 31177)	Regn Date: 30/09/2016	Mileage: 17040	WIP No.: 41417
Model: A4 SEDAN 1.4 TFSI S tronic	Chassis: WAUZZZF4XH0025468	Engine: CVN 017647	Dept: U
VSB No.:			
You have been assisted by :- UB-Carrine (33)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE BOTH FRONT DOOR PANEL TRIMS, REMOVE AND REINSTALL BOTH WING MIRROR ASSY AND WINDOW SLOT CHROME. REINSTALL ALL PARTS REMOVED.	600.00	1.00	600.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER, BOTH FRONT FENDER, BONNET BOTH FRONT DOORS AND LHS A-PILLAR.	3600.00	1.00	3,600.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECKS.	192.00	1.00	192.00
X	AG A13A0JM1	COOLANT ADDITIVE	4.00	32.90	105.28
X	ABW0053651 3FZ	GRILLE	1.00	940.50	752.40
X	ABW0021105A	FENDER	1.00	643.00	514.40
X	ABW0023029A	HOOD	1.00	2001.00	1,600.80
X	ABW0007065C GRU	COVER	1.00	1703.00	1,362.40
X	ABW0007081	COVER	1.00	103.50	82.80
X	ABW0145804A	RADIATOR	1.00	443.50	354.80
X	ABW0016421H	CONDENSER	1.00	524.50	419.60
X	ABW0005594	CARRIER	1.00	878.00	702.40

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Telephone 6388 2323

Customer Service
Service Appointment
24-hour Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2323
9828 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 3 11:22

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012008 Date : 09/01/2018 Order : SJC3122C Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SJC3122C (V 31177) Regn Date: 30/09/2016 Mileage: 17040 WIP No.: 41417

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF4XH0025468 Engine: CVN 017647 Dept: U

VSF No.:

You have been assisted by :- UB-Carrine (33)

		Details	Qty	Unit Price	Amount
X	A8W0807550A	FOAM INSER	1.00	101.00	80.80
X	A8W0807113	BRACKET	1.00	674.00	539.20
X	A8K0973703	HOUSING	1.00	13.70	10.96
X	A3D0260749C	WASHER	1.00	3.70	2.96
X	A4E0260749A	WASHER	1.00	3.10	2.48
X	A8W0941773A	HEADLIGHT	1.00	7861.00	6,288.80
X	A8W0807333	SUPPORT	1.00	22.50	18.00
X	A8W0807284	GUIDE	1.00	30.10	24.08
X	A8W0821135C	SUPPORT	1.00	99.30	79.44
X	A8W0807283	GUIDE	1.00	29.00	23.20
X	A8W0807133	BRACKET	1.00	178.00	142.40
X	A8W0121673A	AIR DUCT	1.00	9.20	7.36
X	A8W0823509C	LATCH	1.00	180.00	144.00
X	A8W0823745	COVER	1.00	18.30	14.64
X	A8W0821091	PLATE	1.00	41.80	33.44
X	A8W0820501B	COVER	1.00	23.60	18.88
X	A8W0823125	PROTECTION	1.00	22.70	18.16
X	A8W0823126	PROTECTION	1.00	22.70	18.16
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408609
Telephone 6388 2323

Customer Service
Service Appointment
24-hour Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2323
9828 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 4 11:22

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012008 Date : 09/01/2018 Order : SJC3122C Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SJC3122C (V 31177)	Regn Date: 30/09/2016	Mileage: 17040	WIP No.: 41417
Model: A4 SEDAN 1.4 TFSI S tronic	Chassis: WAUZZZF4XH0025468	Engine: CVN 017647	Dept: U
VSB No.:			
You have been assisted by :- UB-Carrine (33)			

		Details	Qty	Unit Price	Amount
X	ABW0807683 9B9	GRILLE	1.00	162.50	130.00
X	ABW0821169C	COVER	1.00	51.20	40.96
X	ABW0010515A	STICKER	1.00	5.00	4.64
X	ABK0010520A	PLATE	1.00	11.30	9.04
X	ABW0121283AR	AIR DUCT	1.00	21.00	17.44
X	ABW0807771	BRACKET	1.00	111.50	89.20
X	AN 0161857	POP-RIVET	8.00	2.00	17.92
X	AN 91093901	RIVET	4.00	0.60	1.92
X	AN 0385012	RIVET	4.00	1.40	4.48
X	AN 0385053	RIVET	6.00	0.30	1.44
X	ABW0823124	PROTECTION	1.00	22.70	18.16

Parts 13,697.04
Labour 0.00
Sublet 8,792.00
Menus 0.00
Lubricant 0.00

Sub-Total 21,889.04

7% GST 1,532.23

Grand Total 23,421.27



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SJC 3122 C

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1011/2017/PH
26 Oct 2017

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1

total pages

RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER


Make & Model : Audi A4 SEDAN 1.4 TFSI
Vehicle Chassis No. : WAUZZZF4XHA025468
Vehicle Regn No. : SJC 3122 C
Vehicle Mileage : 17040 KM
Vehicle Owner : Mr Tin Min
Certificate No : 2100485170 - 01
Policy Excess : S\$ 642.00 (inclusive of 7% GST)
Accident Date : 11 October 2017
Place : Exit to Boon Lay way from Yuan Ching Road
Repair Cost : \$ 23,421.27
WIP No. : 41417
Repairer’s Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer’s charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :



Time :

Date :

28/10/2017

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S6861975J



Name

TIN MIN

Race

BURMESE

Date of birth

26-06-1968

Sex

M

S6861975J

Country of birth

MYANMAR



4010479

NRIC No. S6861975J



Date of issue

05-03-2007

56 LAKESIDE DRIVE, CASPIAN #07-26
SINGAPORE 648318

NRIC No: S6861975J

Date: 18/03/2013

No: 7335329

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor cars =< 3000 kg with =< 7 passengers,
exclusive of the driver; and motor tractors
/vehicles =< 2500 kg

PASS DATE

20 Apr 1995

NP 428A





CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Tin Min
Period of Insurance : 30 Sep 2017 To 29 Sep 2018
Engine No. : CVN017647
Chassis No. : WAUZZZF4XHA025468

Vehicle No. : SJC3122C
Policy No. : 2100485170-01
Endorsement No. :
Issued Date : 13 Sep 2017

ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2016
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.
You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Tin Min - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).


1000380378/AC1

0504125219

PREMIUM LEASING - KATL

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.


AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSC25S

78 Shenton Way #07-16 AIG Building S079120 | T: +65 6419 3000 | F: +65 6415 3723 | www.aig.com.sg

AIG Asia Pacific Insurance Pte. Ltd.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Oct 2017 16:58		12 Oct 2017 14:32 Edit Adj Rpt	S\$22,489.04 Edit Estimates	S\$22,489.04 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------



































CLAIM SUBFOLDER DETAILS		[Created by Insurer]	
Insured:	TIN MIN, ID: S6861975J, Tel: +6597320559, Email: MINNMINN2003@YAHOO.COM		
Vehicle Reg. No.:	SJC3122C	Date of Loss:	11/10/2017 07:00 - :59
Claim Type:	OD / 7912460971SG	Policy/Cover Note No.:	2100485170 (Comprehensive) Coverage: 30/09/2017 - 29/09/2018
		Excess:	S\$600.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Kian Meng] kianmeng.chan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 24/10/2017]		
Driver/Custodian:	TIN MIN (49 / Male), NRIC: S6861975J, Tel: +6597320559		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
<ul style="list-style-type: none"> AIG_SG (16/10/2017): Alert - Adj Mandate Approved (S\$23997.00) - SJC3122C - Claim Handler: Chan, Kian... AIG_SG (13/10/2017): SJC3122C / OD / 11/10/2017 / Coverage & Excess update 		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*SJC3122C (7912460971SG)
 OD
 Oct 11 2017 7:00AM
 [TIN MIN]
 Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Assessment Reports															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	12/10/17 17:35		Adjuster Immediate Advice												 Load HTM					
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
2	12/10/17 16:56		Chassis Number												 Load JPG			<input checked="" type="checkbox"/>		
3	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
4	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
5	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
6	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
7	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
8	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
9	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
10	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
11	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
12	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
13	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
14	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
15	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
16	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
17	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
18	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
19	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
20	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
21	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
22	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
23	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
24	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
25	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
26	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
27	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
28	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
29	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
30	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
31	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
32	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		
33	12/10/17 16:56		General View												 Load JPG			<input checked="" type="checkbox"/>		

34	12/10/17 16:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	12/10/17 16:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
36	12/10/17 16:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	12/10/17 16:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	12/10/17 16:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	12/10/17 16:56	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	20/12/17 09:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
41	20/12/17 09:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
42	20/12/17 09:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
43	20/12/17 09:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
44	20/12/17 09:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
45	20/12/17 09:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
46	20/12/17 09:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
47	20/12/17 09:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
48	20/12/17 09:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
49	20/12/17 09:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
50	20/12/17 09:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
51	20/12/17 09:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
52	20/12/17 09:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
53	20/12/17 09:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
54	20/12/17 09:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
55	20/12/17 09:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
56	20/12/17 09:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
57	20/12/17 09:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
58	20/12/17 09:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
59	20/12/17 09:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
60	20/12/17 09:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
61	20/12/17 09:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
62	20/12/17 09:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/10/17 16:55	Singapore Accident Statement	1 Load PDF	
2	12/10/17 16:55	Certificate of Insurance	1 Load PDF	
3	12/10/17 16:55	Drivers Driving License	1 Load PDF	
4	12/10/17 16:55	WORKSHOP ESTIMATE	1 Load PDF	
5	19/01/18 12:54	Discharge Voucher	1 Load PDF	
6	19/01/18 12:54	Workshop Invoice	1 Load PDF	

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	11/10/17 13:28	Accident Statement	1 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	11/10/17 13:26	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>
2	11/10/17 13:26	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>
3	11/10/17 13:26	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>
4	11/10/17 13:26	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>

5	11/10/17 13:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	11/10/17 13:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	11/10/17 13:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	11/10/17 13:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	11/10/17 13:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	11/10/17 13:21	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	11/10/17 13:21	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 500px; margin: 5px 0;"></div> <p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG17019635/AQBE2

Date: 19/01/2018

REFERENCE

Insured/Claimant: TIN MIN Policy No: 2100485170
Date of Loss: 11/10/2017 Nature of Claim: OD Claim No: 7912460971SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJC3122C**
Make & Model: AUDI A4, 1.4 T (A) Engine No: CVN017647
Reg. Date: 30/09/2016 (Man. Year: 2016) Chassis No: WAUZZZF4XHA025468
Colour: White Odometer: 17040 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$138,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,244.00	13,737.04	18,506.96	57.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,952.00	8,752.00	3,200.00	26.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	44,196.00	22,489.04	21,706.96	49.12
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	43,596.00	21,889.04	21,706.96	49.79
+ GST 7.00/7.00% (\$\$)	3,051.72	1,532.23	1,519.49	49.79
Nett Amount (\$\$)	46,647.72	23,421.27	23,226.45	49.79

INSPECTION

Date of Assignment: 12/10/2017

Date Inspected: 12/10/2017 Inspected At:

Premium Automobiles Pte Ltd (HQ)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,703.00 FS	*1,362.40 FS
2	1		*FRONT BUMPER GRILLE - CENTRE	Damaged	163.00 FS	*130.00 FS
3	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	171.00 FS	*- FS
4	1		*AIR GUIDE COVER - LHS	Not Necessary	67.00 FS	*- FS
5	1		*RADIATOR GRILLE	Cracked	941.00 FS	*752.40 FS
6	1		*AIR GUIDE GRILLE - LHS/RHS	Not Necessary	224.00 FS	*- FS
7	1		*FRONT REINFORCEMENT BEAM	Bent	674.00 FS	*539.20 FS
8	1		*REINFORCEMENT BEAM HOLDER - LHS/RHS	N/S Damaged	356.00 FS	*142.40 FS
9	1		*FRONT BUMPER GUIDE - LHS/RHS	Necessary	60.00 FS	*47.28 FS
10	1		*FRONT BUMPER TOP COVER	Cracked	104.00 FS	*82.80 FS
11	1		*CAUTION STICKER	Necessary	12.00 FS	*9.04 FS
12	1		*A/C STICKER	Necessary	6.00 FS	*4.64 FS
13	1		*RELEASE LEVER	Not Necessary	12.00 FS	*- FS
14	1		*FOAM FILLER PIECE	Deformed	101.00 FS	*80.80 FS
15	1		*LOCK CARRIER BRACKET	Damaged	112.00 FS	*89.20 FS
16	1		*FRONT BUMPER SUPPORT	Damaged	46.00 FS	*18.00 FS
17	1		*FRONT FENDER - LHS	Dented	643.00 FS	*514.40 FS
18	1		*FRONT FENDER CLOSING ELEMENT - LHS	Necessary	42.00 FS	*33.44 FS
19	1		*FRONT FENDER INNER BRACKET - LHS	Not Necessary	29.00 FS	*- FS
20	1		*FRONT FENDER OUTER BRACKET - LHS	Not Necessary	42.00 FS	*- FS
21	1		*FRONT FENDER BRACE - LHS	Bent	100.00 FS	*79.44 FS
22	1		*FRONT FENDER CORNER COVER - LHS/RHS	N/S Necessary	38.00 FS	*14.64 FS
23	1		*FRONT FENDER TOP COVER - LHS/RHS	N/S Necessary	48.00 FS	*18.88 FS
24	1		*FRONT FENDER COVER - LHS	Necessary	52.00 FS	*40.96 FS
25	1		*LED HEADLIGHT - LHS/RHS	N/S Cracked	15,722.00 FS	*6,288.80 FS
26	1		*HEADLIGHT POWER CONTROL MODULE - LHS	Not Necessary	685.00 FS	*- FS
27	1		*HEADLIGHT CONTROL UNIT - LHS	Not Necessary	634.00 FS	*- FS
28	2		*HEADLIGHT COMPENSATING PIECE	Not Necessary	74.00 FS	*- FS
29	1		*HEADLIGHT WASHER - LHS	Not Necessary	180.00 FS	*- FS
30	1		*HEADLIGHT WASHER BRACKET - LHS (NPA)	Not Necessary	0.00 FS	*- FS
31	1		*HEADLIGHT WASHER HOSE	Not Necessary	75.00 FS	*- FS
32	1		*BONNET	Dented	2,001.00 FS	*1,600.80 FS
33	1		*BONNET ATTACHEMENT PARTS	Not Necessary	103.00 FS	*- FS
34	1		*BONNET HINGE - LHS/RHS	Not Necessary	514.00 FS	*- FS
35	1		*BONNET SEAL - LHS/RHS	Necessary	46.00 FS	*36.32 FS
36	1		*BONNET CENTRE	Necessary	23.00 FS	*18.16 FS
37	1		*BONNET STRIKER	Not Necessary	86.00 FS	*- FS
38	1		*BONNET LID LOCK	Damaged	360.00 FS	*144.00 FS
39	1		*BOWDEN CABLE	Not Necessary	49.00 FS	*- FS
40	1		*LOCK CARRIER	Cracked	878.00 FS	*702.40 FS
41	2		*LOCK CARRIER SUPPORT	Not Necessary	64.00 FS	*- FS
42	1		*LOCK CARRIER AIR GUIDE - LHS/RHS	N/S Deformed	44.00 FS	*17.44 FS
43	1		*LOCK CARRIER LOWER AIR GUIDE - LHS/RHS	N/S Deformed	20.00 FS	*7.36 FS
44	1		*A/C CONDENSER	Dented	525.00 FS	*419.60 FS
45	1		*RADIATOR	Not Necessary	572.00 FS	*- FS
46	4		*RADIATOR BUSH	Not Necessary	38.00 FS	*- FS
47	1		*ADDITIONAL RADIATOR	Necessary	444.00 FS	*354.80 FS
48	4		*COOLANT	Necessary	132.00 FS	*105.28 FS
49	1		*FAN RING COVER	Not Necessary	222.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*RADIATOR FAN WITH CTRL UNIT	Not Necessary	1,949.00 FS	*- FS
51	1		*WINDOW CHROME SLOT SHIELD - LHS/RHS	Not Necessary	518.00 FS	*- FS
52	1		*FRONT NUMBER	Necessary	40.00 FS	*40.00 FS
53	1		*SUNDRIES	Necessary	500.00 FS	*42.16 FS
Total Parts (\$\$)					32,244.00	13,737.04

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER AIRCOND CONDENSER,RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM AND TO PRESSURISE COOLING SYSTEM	New	1,000.00	1,000.00
3	TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND BOTH HEADLIGHTS. RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,800.00	3,000.00
4	TO REMOVE BOTH FRONT DOOR PANEL TRIMS, REMOVE AND REINSTALL BOTH WING MIRROR ASSY AND RENEW WINDOW SLOT CHROME. REINSTALL ALL PARTS REMOVED	New	600.00	600.00
5	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDER, BONNET, BONNET HINGES, FRONT DOORS AND LHS A-PILLAR	New	5,000.00	3,600.00
6	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (\$\$)			11,952.00	8,752.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >