

ASS. REC. BY:

REF: CS/FCI17019682/Gtbn2

Special Instructions:

ASSIGNMENT

7A

ASSIGNMENT (Office)

cws

From (Person):

Joanne Yong

of

FCI

Date/Time:

12/10/17 @ 5:55pm

Estimated Cost:

Bill to:

OD / TP-WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL 601K

Insured:

SHA 58374

at Workshop no/s

S Three Automotive

Tel:

62841575/97662745

of Blk 8 Sin Ming Ind Est. #01-64/66

Policy No:

Claim No:

D17009658 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

11/10/17

CA / REV / REP. / REV 24 HRS

'wp'

R.O.D. Endorsement

Date/Time:

13/10/17 @ 9:16am

Person Contacted:

Ms. Joey

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLL 601K - X
	SHA 58374 - CC3/AIG/16020641/H1ub3g2-D.O.A - 27/10/2016

Singapore

XHL


REF: Fci

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s S Tree
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt.: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLL601K Yr Regn: 10 Feb 2017
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda vezel cc 1496
 Colour: Brown A/C: Insured / Std / NI / NA
 Sp. Reading: 94026 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RU3/220551
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/60R16
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front Rear
 R/Bal. 8 mm R/Bal. 8 mm
 L/Bal. 8 mm L/Bal. 8 mm
 D.O.A. _____ D.O.I. 23-10-17
 Survey held at W/S 5:30pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
Finalized @ 2800 with Joey. (Red: 7997.80 : 74%)

RECEIVED 07 DEC 20

Date/Time, File Pass to?

1) 11/2 Typset

Date/Time, File Return to?

2)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS: \$

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Report Format: TP

Lump Sum / I.B.I: (\$ 2800)

170
50
40
260



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17019682/Gtb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 13-10-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 5837U	Veh. Inspected	SLL 601K
Policy No.		Coverage (\$)	0.00
Claim No.	D17009658MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	13/10/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	11/10/2017	Inspection Date	
Survey held at	S THREE AUTOMOTIVE & RECOVERY PTE LTD BLK 8 SIN MING IND EST #01-64/66 SINGAPORE 575643		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	12-10-2017	Our Ref No. D17009658MFSH
Accident Date	11-10-2017	Claim Type. Third Party
Insured Vehicle	SHA5837U	Third Party Vehicle. SLL601K
Survey Location	BLK 8 SIN MING INDUSTRIAL ESTATE #01-64/66	
Contact Person.	MS JOEY	
Contact No.	62841575/ 97662745	Fax No. 64875315
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	S THREE AUTOMOTIVE RECOVERY PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/229057)



PRI Documents



Close



PRI Header Details

Claim No	D17009658MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & S THREE / LTD
Workshop Name	S THREE AUTOMOTIVE RECOVERY PTE LTD (Contact Person : MS JOEY)	Survey Location & Contact Details	BLK 8 SIN MING INDUSTRIAL ESTATE #01-64/66 Mobile: 97662745 , Phone: 62841575 , Fax: 6487531! EmailId: ADMIN@STHREEAUTOMOTIVE.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA5837U	TP Vehicle No	SLL601K
PRI Recieved Date	12-10-2017 04:26:16 PM	Surveyor Appointed Date	12-10-2017 05:54:40 PM	Surveyor Accept Date	13-10-2017 10

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	13-10-2017	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	4597K
Vehicle Details	
Vehicle No.	SLL601K
Vehicle to be Exported	No
Intended De-registration Date	24 Oct 2017
Vehicle Make	HONDA
Vehicle Model	VEZEL HYBRID 1.5X AUTO
Primary Colour	Brown
Manufacturing Year	2016
Engine No.	LEB5920563
Chassis No.	RU31220551
Maximum Power Output	112.0 kW (150 bhp)
Open Market Value	\$23,486.00
Original Registration Date	10 Feb 2017
First Registration Date	10 Feb 2017
Transfer Count	1
Actual ARF Paid	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	09 Feb 2027
PARF Rebate Amount	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date	09 Feb 2027
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$57,903.00
COE Rebate Amount	\$53,824.00
Total Rebate Amount	\$57,574.00

The information contained herein is correct as at 24 Oct 2017

OK

S THREE AUTOMOTIVE RECOVERY PTE LTD
 Blk 8 Sin Ming Industrial Estate
 #01-64/66 Singapore 575643
 Tel : 6284 1542 / 6284 1575
 Fax : 6487 5315
 sthreeautomotive@gmail.com

TO
 ATTN: MOTOR CLAIM DEPT.

T/P VEH. NO.: SHA5837U

ESTIMATE REPORT 1st QUOTATION

OWNER'S PARTICULAR

NAME: LCRF PTE LTD
 ADDRESS:

JOB NO: _____

CONTACT: _____

LICENSE NO.: SLL601K TRANS
 MAKE / MODEL: HONDA VEZEL
 OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE
 JOB-CODE: TP S/A: MICHELLE

CHASSIS NO:
 ENGINE NO:

ACCIDENT DATE: 11-Oct-17

CLAIM DETAIL

MATERIALS

- 1 FRONT DOOR LH / BT
- 2 FRONT DOOR RUBBER BEADING X
- 3 FRONT DOOR GLASS OUTER MOULDING LH X
- 4 FRONT DOOR FRAME STICKER LH X
- 5 FRONT DOOR TRIM BOARD LH X
- 6 FRONT FENDER LH X Repair
- 7 FRONT FENDER EMBLEM HYBRID X
- 8 FRONT FENDER PROTECTOR LH X
- 9 FRONT SHOCK ABSORBER LH X
- 10 FRONT KNUCKLE ARM LH X
- 11 FRONT KUNCLE ARM BEARING LH X
- 12 FRONT LOWER ARM LH X
- 13 REAR DOOR LH X Repair
- 14 REAR DOOR LOCK LH X
- 15 REAR DOOR GLASS OUTER MOULDING LH X
- 16 REAR DOOR FRAME STICKER LH X
- 17 REAR FENDER PROTECTOR LH X
- 18 REAR DOOR INNER BOARD LH X
- 19 REAR DOOR RUBBER BEADING LH X
- 20 REAR DOOR LOWER BLACK STICKER X
- 21 ROCKER PANEL GARNISH LH X
- 22 REAR FENDER PROTECTOR LH X Repeat

QTY	QUO-PRICE	DISC. %	DISC-PRICE	SUR DIS	REV. PRICE
1.00	1080.50	20.00	864.40	Y	/
1.00	250.00	20.00	200.00	Y	X
1.00	302.00	20.00	241.60	Y	X
1.00	60.00	20.00	48.00	Y	/
1.00	650.00	20.00	520.00	Y	X
1.00	420.00	20.00	336.00	Y	X
1.00	86.60	20.00	86.60	Y	/
1.00	160.00	20.00	128.00	Y	/
1.00	500.00	20.00	400.00	Y	X
1.00	390.50	20.00	312.40	Y	X
1.00	150.00	20.00	120.00	Y	/
1.00	351.50	20.00	281.20	Y	X
1.00	930.00	20.00	744.00	Y	X
1.00	310.00	20.00	248.00	Y	X
1.00	302.00	20.00	241.60	Y	X
1.00	60.00	20.00	48.00	Y	X
1.00	160.00	20.00	128.00	Y	/
1.00	650.00	20.00	520.00	Y	X
1.00	120.00	20.00	96.00	Y	X
1.00	60.00	20.00	48.00	Y	/
1.00	210.00	20.00	168.00	Y	/
1.00	160.00	20.00	128.00	Y	X

TOTAL (PARTS):

7363.10 ~~5907.80~~ 5890.48

SPECIAL NETT ITEM

- 1 FRONT DOOR INSULATOR PAD LH / NEC
- 2 FRONT SPORT RIM LH / GPR

1.00	120.00	0.00	120.00	Y	/
1.00	680.00	0.00	680.00	Y	200.

3	FRONT TYRE LH	X	NN	1.00	380.00	0.00	380.00	Y	X
4	FRONT DOOR TRIM BOARD CLIPS 1SET	/	NEC	1.00	50.00	0.00	50.00	Y	/
5	REAR DOOR TRIM BOARD CLIPS 1SET	X	NN	1.00	50.00	0.00	50.00	Y	X
6	REAR BUMPER CLIPS 1SET	X	NN	1.00	50.00	0.00	50.00	Y	X
7	REAR DOOR INSULATOR PAD LH	X	NN	1.00	120.00	0.00	120.00	Y	X
8	EMBLEM GARNISH STICKER	X	NN	1.00	60.00	0.00	60.00	Y	X

TOTAL (PARTS):

1510.00 1510.00

LABOUR

1	STRAIGHTEN & PANEL BEAT ON ACCIDENT AREA	1.00	1000.00	0.00	1000.00	Y	600
2	SPRAY PAINT ON ACCIDENT AREA	1.00	1400.00	0.00	1400.00	Y	1000
3	R&R FRONT DOOR COMPARTMENT	1.00	120.00	0.00	120.00	Y	60
4	R&R REAR DOOR COMPARTMENT	1.00	120.00	0.00	120.00	Y	X
5	R&R SUSPENSION SYSTEM	1.00	380.00	0.00	380.00	Y	50
6	CHECK WIRING SYSTEM	1.00	120.00	0.00	120.00	Y	X
7	CONDUCT FULL WHEEL ALIGNMENT	1.00	120.00	0.00	120.00	Y	60
8	RESPRAY TUFF KOTE ON AFFECTED AREA	1.00	120.00	0.00	120.00	Y	60

TOTAL (LABOUR):

3380.00 3380.00

TOTAL PARTS & LABOUR

12253.10 10797.80

EXCESS : : \$

NO. OF DAY : 5

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : \$

DATE OF SURVEY : 23/10/17

SURVEY BY : Gao Q. ap.

CONTACT NO :

FAX NO :

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

10780.48

L&R Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17019682/Gtbn2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 07-12-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 5837U	Veh. Inspected	SLL 601K
Policy No.	D-15072701MFSH	Coverage (\$)	0.00
Claim No.	D17009658MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	13/10/2017

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	RU31220551	Colour	BROWN
Odometer	54026	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	8 mm
L/H Front Tyre	215/60 R16	DUNLOP	8 mm
R/H Rear Tyre	215/60 R16	DUNLOP	8 mm
L/H Rear Tyre	215/60 R16	DUNLOP	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	11/10/2017	Inspection Date	23/10/2017
Survey held at	S THREE AUTOMOTIVE & RECOVERY PTE LTD BLK 8 SIN MING IND EST #01-64/66 SINGAPORE 575643		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 601K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT DOOR LH	BENT	1,080.50	1,080.50
1	FRONT DOOR RUBBER BEADING	NOT NECESSARY	250.00	-
1	FRONT DOOR GLASS OUTER MOULDING LH	NOT NECESSARY	302.00	-
1	FRONT DOOR FRAME STICKER LH	NECESSARY	60.00	60.00
1	FRONT DOOR TRIM BOARD LH	NOT NECESSARY	650.00	-
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	420.00	-
1	FRONT FENDER EMBLEM HYBRID	NECESSARY	86.60	86.60
1	FRONT FENDER PROTECTOR LH	SCRATCHED	160.00	160.00
1	FRONT SHOCK ABSORBER LH	NOT NECESSARY	500.00	-
1	FRONT KNUCKLE ARM LH	NOT NECESSARY	390.50	-
1	FRONT KNUCKLE ARM BEARING LH	NECESSARY	150.00	150.00
1	FRONT LOWER ARM LH	NOT NECESSARY	351.50	-
1	REAR DOOR LH	TO REPAIR SEE LABOUR	930.00	-
1	REAR DOOR LOCK LH	NOT NECESSARY	310.00	-
1	REAR DOOR GLASS OUTER MOULDING LH	NOT NECESSARY	302.00	-
1	REAR DOOR FRAME STICKER LH	NOT NECESSARY	60.00	-
1	REAR FENDER PROTECTOR LH	SCRATCHED	160.00	160.00
1	REAR DOOR INNER BOARD LH	NOT NECESSARY	650.00	-
1	REAR DOOR RUBBER BEADING LH	NOT NECESSARY	120.00	-
1	REAR DOOR LOWER BLACK STICKER	NECESSARY	60.00	60.00
1	ROCKER PANEL GARNISH LH	CRACKED	210.00	210.00
1	REAR FENDER PROTECTOR LH	REPEATED	160.00	-
	LESS 20% DISCOUNT		-1,472.62	-393.42
			5,890.48	1,573.68
<u>SPECIAL NETT ITEMS</u>				
1	FRONT DOOR INSULATOR PAD LH (SN)	NECESSARY	120.00	120.00
1	FRONT SPORT RIM LH (SN)	SCRATCHED	680.00	200.00
1	FRONT TYRE LH (SN)	NOT NECESSARY	380.00	-
1	SET FRONT DOOR TRIM BOARD CLIPS (SN)	NECESSARY	50.00	50.00

Report Ref No. CS/FCI17019682/Gtbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR DOOR TRIM BOARD CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	50.00	-
1	REAR DOOR INSULATOR PAD LH (SN)	NOT NECESSARY	120.00	-
1	EMBLEM GARNISH STICKER (SN)	NOT NECESSARY	60.00	-
			1,510.00	370.00
	LABOUR			
	STRAIGHTEN & PANEL BEAT ON ACCIDENT AREA.INCLUSIVE OF THE REPAIR OF FRONT FENDER LH AND REAR DOOR LH.		1,000.00	600.00
	SPRAY PAINT ON ACCIDENT AREA.		1,400.00	1,000.00
	R&R FRONT DOOR COMPARTMENT.		120.00	60.00
	R&R REAR DOOR COMPARTMENT.	NOT NECESSARY	120.00	-
	R&R SUSPENSION SYSTEM.		380.00	50.00
	CHECK WIRING SYSTEM.	NOT NECESSARY	120.00	-
	CONDUCT FULL WHEEL ALIGNMENT.		120.00	60.00
	RESPRAY TUFF KOTE ON AFFECTED AREA.		120.00	60.00
			3,380.00	1,830.00
	GRAND TOTAL		10,780.48	3,773.68
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,800.00

Report Ref No. CS/FC117019682/Gtbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.