

ASS. REC. BY:

REF:

CS/^{AS71}AXA17019698/Airb64z

Special Instruction:

Surveyor: Rasul ASSIGNMENT (Office)

From (Person): Smart claim Winnie Ho of AXA Date/Time: 12.10.2017

Estimated Cost: _____ Bill to: _____

TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKB 2827C Insured: _____

at Workshop m/s MOVU Tel: 6272 3892

of 91k 1008 Bukit Merah Lane 3 #01-04

Policy No: _____ Claim No: S7M00208

Sum Insured: _____ Excess: \$ 600.00

Make of Veh: _____ D.O.A. 06.10.2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 19.10.2017 @ after 12pm H.O.D. Endorsement: _____

Date/Time: 13.10.2017 10:21am Person Contacted: Avin Vehicle IN / ~~OUT~~

Date/Time	Action/Instruction (✓) Estimate
	SKB 2827C - x ✓
20/10/17	sent pref. through smart claim.
	Rasul confirm \$10865.00 @ 7 days
	Red: 2215, 171.

Surveyor: *Ramu*

REF: AXA

50640

ASSIGNMENT

From: _____ Date: 19/10/17

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKB 2827C

at Workshop m/s MOVA

of Blk 1008 Bukit Merah Lane 3

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$600.00

(Client's Record)

Make of Veh: _____

Veh No: SKB 2827C Yr Regn: 2011 / May

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____

Make: P.M.W 523 I C.C. 2497

Colour: WHTE A/C: Insured / Std / NI / NA

Sp. Reading: 123381 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAPP 32090C865615

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____


Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 245/40R19
R: _____

(Policy Condition) after 12pm

Remark: **The veh had commenced its repair at the time of inspection.**



Bal. or Market Value: 74K

IDAC Accident Rpt: _____ Consistent? : **Yes** or No

GIA / PR Seen: _____ Consistent? : **Yes** or No

Est. Repairs: _____ days Res.: **Yes** or No

Lum Sum: _____ % 3 Val.: **Yes** or No

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>06/10/17</u>	D.O.I. <u>12/10/17</u>

Survey held at MOVA CBM7

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
RECEIVED 31 JUL 2018	
	<i>[Signature]</i> 30/7/2018

Date/Time, File Pass to? : Preli. Report

1) Report : Final Report

Date/Time, File Return to? _____

2) _____

Report Format : OD

Lump Sum / I.B.I. (\$) 10865.00

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee: 250

Transportation: _____

_____ S + RS. \$ _____

Photos _____

Others _____

TOTAL 250

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/AXA17019698/R1rb

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 13-10-2017



Code : AXA2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SKB 2827C
Policy No.		Coverage (\$)	0.00
Claim No.	S7M00208	Excess (\$)	600.00
Assign From	SMART CLAIM (WINNIE HO)	Assign Date	12/10/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	06/10/2017	Inspection Date	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

◀ Service Request Details

Claim
S7M002O8

Reference
None 

Loss Date
October 6, 2017

Request Date
October 12, 2017

Due Date
October 20, 2017

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss
Own Damage

Services
Accelerated survey and authorize

Actions

Next Step
Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #
SKB2827C

Make
BMW

Service Address

Blk 1008, , , 159722

Primary Contact

KENG LOON VINCENT WONG
96834551
VINCEWKL@GMAIL.COM

Claim Handler

Winnie HO
6568804833
winnie.ho@axa.com.sg

Additional Instructions

1) SURVEY @ MOVA 2) ESTIMATE - \$12,970 3) XS-\$600

[Messages](#)

[Invoices](#)

[History](#)

[Documents](#)

[Assessment](#)

[Metrics](#)

[Notes](#)

[New Message](#)

« Preliminary Revised for SKB 2827C

Type

🗨 Question

Message

Repairer's Estimate (Gross) : S\$ 12,970.00. Revised Estimate Amount : S\$ 5,815.00 "Check" Items (Estimated) : S\$ 5,875.00 . Total Repair cost : S\$ 11,690.00 . Pre-Accident Value : S\$ 74,000.00 . COE/PARF value : S\$ 50,518.00 . Nett Value : S\$ 23,482.00 . Survey date and time: 19/10/2017 at 12.00pm. We have authorize repair. Days of repair: 7 days. Janice

Reply

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	5064D
Vehicle Details	
Vehicle No.	SKB2827C
Vehicle to be Exported	No
Intended De-registration Date	20 Oct 2017
Vehicle Make	B.M.W.
Vehicle Model	523I A
Primary Colour	White
Manufacturing Year	2011
Engine No.	07977723N52B25AF
Chassis No.	WBAFP32090C865615
Maximum Power Output	150.0 kW (201 bhp)
Open Market Value	\$47,598.00
Original Registration Date	13 May 2011
First Registration Date	13 May 2011
Transfer Count	0
Actual ARF Paid	\$47,598.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	12 May 2021
PARF Rebate Amount	\$30,938.00
Intended COE Rebate Details	
COE Expiry Date	12 May 2021
COE Category	B - Car (1601cc & above)
COE Period(Years)	10
QP Paid	\$55,001.00
COE Rebate Amount	\$19,580.00
Total Rebate Amount	\$50,518.00

The information contained herein is correct as at 20 Oct 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/10/2017 11:06
Date Of Accident	06/10/2017 19:00
Exact Location Of Accident	BUKIT TIMAH RAOD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKB2827C
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	WONG KENG LOON VINCENT
NRIC No	S7515064D
Email Address	VINCEWKL@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96834551
Alternative Phone No	OTHERS-96834551

Vehicle Particulars

Manufacturer	BMW
Model	523I A

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA035160/1
Cover Note Number	

Driver

Name of Driver	WONG KENG LOON VINCENT
NRIC No	S7515064D
Date Of Birth	13/05/1975
Occupation	INDOOR
Date Of Driving Pass	13/08/1996
Driving Experience	21 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96834551
Fax Number	
Contact Number	OTHERS-96834551
EEmail Address	VINCEWKL@GMAIL.COM

Address	900 DUNEARN ROAD #04-24
Postcode	589473
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLE8736P
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages) and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


 Policyholder's Signature / Date & Time
 7/10/2017
 1130hrs

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan





S7M00208
CR129681

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving 1 2011 BMW 523 I (SKB2827C)

Date of Loss 6 October 2017

Time of Loss 19.00

Loss Description SKB2827C (INSD) C/W SLE8736P (TP)

Comment

Workshop Details

Total Rebate Amount

Nett Loss Amount \$0.00

Assigned Workshop MOVA AUTOMOTIVE PTE LTD

Vendor

Target Date of Completion *

Days of work completion *



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

Add

EDIT	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC QUINT%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
<input type="checkbox"/>	1			A/C CONDENSER - CHECK				0		0	Reviewing	<input type="checkbox"/> 1 X SW
<input type="checkbox"/>	1			ENGINE OIL COOLER AIR DUCT LH				50		50	Reviewing	<input type="checkbox"/> ? X SW
<input type="checkbox"/>	1			ENGINE OIL COOLER AIR DUCT RH				50		50	Reviewing	<input type="checkbox"/> 1 X SW
<input type="checkbox"/>	1			FRONT AIR DUCT ASSY				280		280	Reviewing	<input type="checkbox"/> CORA
<input type="checkbox"/>	1			FRONT BONNET				1680		1680	Reviewing	<input type="checkbox"/> PA
<input type="checkbox"/>	1			FRONT BONNET HINGE LH				95		95	Reviewing	<input type="checkbox"/> X SW
<input type="checkbox"/>	1			FRONT BONNET HINGE RH				95		95	Reviewing	<input type="checkbox"/> X SW

EDIT	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC COUNT%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
<input type="checkbox"/>	10			FRONT BONNET INSULATOR CLIPS				2.5		25	Reviewing	<input type="checkbox"/> <i>Ne</i>
<input type="checkbox"/>	1			FRONT BUMPER				1450		1450	Reviewing	<input type="checkbox"/> <i>DE</i>
<input type="checkbox"/>	1			FRONT BUMPER LOGO				60		60	Reviewing	<input type="checkbox"/> <i>ne</i>
<input type="checkbox"/>	1			FRONT BUMPER LOWER BEAM				195		195	Reviewing	<input type="checkbox"/> <i>i x pm</i>
<input type="checkbox"/>	1			FRONT BUMPER LOWER GRILLE CENTRE				90		90	Reviewing	<input type="checkbox"/> <i>i x pm</i>
<input type="checkbox"/>	1			FRONT BUMPER LOWER GRILLE LH				65		65	Reviewing	<input type="checkbox"/> <i>i x pm</i>
<input type="checkbox"/>	1			FRONT BUMPER LOWER GRILLE RH				65		65	Reviewing	<input type="checkbox"/> <i>DE</i>
<input type="checkbox"/>	1			FRONT BUMPER LOWER GRILLE TRIM LH				30		30	Reviewing	<input type="checkbox"/> <i>3x su</i>
<input type="checkbox"/>	1			FRONT BUMPER LOWER GRILLE TRIM RH				30		30	Reviewing	<input type="checkbox"/> <i>su</i>
<input type="checkbox"/>	1			FRONT BUMPER REINFORCEMENT				490		490	Reviewing	<input type="checkbox"/> <i>7.9d</i>

EDIT	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC QUANT%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
<input type="checkbox"/>	2 *			FRONT BUMPER RIVET				2.5		5 /	Reviewing	<input type="checkbox"/> <i>see</i>
<input type="checkbox"/>	1 *			FRONT BUMPER SPONGE				50		50 /	Reviewing	<input type="checkbox"/> <i>i am</i>
<input type="checkbox"/>	2 *			FRONT CENTER SENSOR				180		360 /	Reviewing	<input type="checkbox"/> <i>i am</i>
<input type="checkbox"/>	1			FRONT FOG LAMP LH				265		265	Reviewing	<input type="checkbox"/> <i>Xsun</i>
<input type="checkbox"/>	1			FRONT FOG LAMP RH				265		265	Reviewing	<input type="checkbox"/> <i>Xsun</i>
<input type="checkbox"/>	1			FRONT GRILLE INNER BRACKET				25		25	Reviewing	<input type="checkbox"/> <i>i am</i>
<input type="checkbox"/>	1			FRONT GRILLE LH				130		130 /	Reviewing	<input type="checkbox"/> <i>DE</i>
<input type="checkbox"/>	1			FRONT GRILLE RH				130		130 /	Reviewing	<input type="checkbox"/> <i>CEA</i>
<input type="checkbox"/>	1			FRONT HEADLAMP LH				1800		1800 /	Reviewing	<input type="checkbox"/> <i>? CEA</i>
<input type="checkbox"/>	1 *			FRONT HEADLAMP LOWER SUPPORT LH				150		150 /	Reviewing	<input type="checkbox"/> <i>? CEA</i>
<input type="checkbox"/>	1			FRONT HEADLAMP LOWER SUPPORT RH				150		150 /	Reviewing	<input type="checkbox"/> <i>? CEA</i>

EDIT	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISCOUNT%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
<input type="checkbox"/>	1			FRONT HEADLAMP RH				1800		1800	Reviewing	<input type="checkbox"/> <i>CS</i>
<input type="checkbox"/>	1			FRONT HEADLAMP WASHER BRACKET LH				10		10	Reviewing	<input type="checkbox"/> <i>? X SW</i>
<input type="checkbox"/>	1			FRONT HEADLAMP WASHER BRACKET RH				10		10	Reviewing	<input type="checkbox"/> <i>? X SW</i>
<input type="checkbox"/>	1			FRONT HEADLAMP WASHER JET LH				195		195	Reviewing	<input type="checkbox"/> <i>? X SW</i>
<input type="checkbox"/>	1			FRONT HEADLAMP WASHER JET RH				195		195	Reviewing	<input type="checkbox"/> <i>? X SW</i>
<input type="checkbox"/>	1			FRONT LOWER AIR DUCT				55		55	Reviewing	<input type="checkbox"/> <i>? CS</i>
<input type="checkbox"/>	1			FRONT PANEL				145		145	Reviewing	<input type="checkbox"/> <i>BT</i>
<input type="checkbox"/>	1			FRONT PANEL BEAM				150		150	Reviewing	<input type="checkbox"/> <i>? X SW</i>
<input type="checkbox"/>	1			FRONT PANEL RUBBER SEAL				40		40	Reviewing	<input type="checkbox"/> <i>NEW</i>
<input type="checkbox"/>	1			FRONT REINFORCEMENT BAR LH				35		35	Reviewing	<input type="checkbox"/> <i>? X SW</i>

EDIT	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC COUNT%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
<input type="checkbox"/>	1			FRONT REINFORCEMENT BAR RH				35		35	Reviewing	<input type="checkbox"/> <i>zhu</i>
<input type="checkbox"/>	1			RADIATOR - CHECK				0		0	Reviewing	<input type="checkbox"/> <i>zhu</i>
<input type="checkbox"/>	1			RADIATOR LOWER COVER - CHECK				0		0	Reviewing	<input type="checkbox"/> <i>zhu</i>
<input type="checkbox"/>	1			RADIATOR TOP COVER				65		65	Reviewing	<input type="checkbox"/> <i>zhu</i>

Labour

Add

EDIT	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	REPAIR/REPLACE (LABOUR)	ACTION (LABOUR)	COMMENT	REMOVE
<input type="checkbox"/>	TO REPAIR FRONT FENDER LH & RH, TO REMOVE AND REPLACE ALL ACCIDENT DAMAGED PARTS AND REALIGN ALL AFFECTED AREA		850	700		Reviewing		<input type="checkbox"/>
<input type="checkbox"/>	TO SPRAY PAINT ON ACCIDENT AFFECTED AREA			900	800	Reviewing		<input type="checkbox"/>
<input type="checkbox"/>	TO RESET AND REPROGRAM FRONT HEADLAMP		280	180		Reviewing		<input type="checkbox"/>
<input type="checkbox"/>	TO REMOVE AND REFIX FRONT SENSORS AND CHECK WIRING		80	60		Reviewing		<input type="checkbox"/>



<< Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount \$12,970.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$10,815.00	\$10,815.00
Labour	\$1,210.00	\$1,210.00
Paint	\$900.00	\$900.00
Miscellaneous	\$45.00	\$45.00

Total: 13080

RASUL
 Hp 90010068
 7 days
 P/P
 19/10/17 @ 1200
 Excess : 600
 Authorised
 Resurvey b4 paint

[Signature]
 21/10/17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



<< Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

EDIT

NAME

ACTION

AMOUNT

COMMENT

REMOVE



FRONT
NUMBER
PLATE

Reviewing

45 35



Bf ✓



<< Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		2	AIR DUCT BRACKET	Reviewing	25 /	SUPPLEMENTARY	REC
<input type="checkbox"/>		3	FRONT BUMPER REINFORCEMENT BRACKET (QTY: 2)	Reviewing	50 /	SUPPLEMENTARY	REC
<input type="checkbox"/>		1	FRONT NUMBER PLATE	Reviewing	48 35		



SERVICE REQUESTS

MESSAGES

CLAIMS

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio **Parts & Labour** Miscellaneous Summary

Parts

Adj	EDIT	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISCOUNT	PART PRICE(NET)	ACTION (PARTS)	REMOVE
<input type="checkbox"/>	<input type="checkbox"/>	1			A/C CONDENSER - CHECK				0		0	Reviewing	<input type="checkbox"/> ?
<input type="checkbox"/>	<input type="checkbox"/>	1			ENGINE OIL COOLER AIR DUCT LH				50		50	Reviewing	<input type="checkbox"/> ?
<input type="checkbox"/>	<input type="checkbox"/>	1			ENGINE OIL COOLER AIR DUCT RH				50		50	Reviewing	<input type="checkbox"/> ?
<input type="checkbox"/>	<input type="checkbox"/>	1			FRONT AIR DUCT ASSY				280		280	Reviewing	<input type="checkbox"/> COA ✓
<input type="checkbox"/>	<input type="checkbox"/>	1			FRONT BONNET				1680		1680	Reviewing	<input type="checkbox"/> PA ✓
<input type="checkbox"/>	<input type="checkbox"/>	1			FRONT BONNET HINGE LH				95		95	Reviewing	<input type="checkbox"/> ✗
<input type="checkbox"/>	<input type="checkbox"/>	1			FRONT BONNET HINGE RH				95		95	Reviewing	<input type="checkbox"/> ✗

10/12/2017

Claim Portal

EDIT	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC CUNTK	PART PRICE(NET)	ACTION (PARTS)	REMOVE
<input type="checkbox"/>	/	10		FRONT BONNET INSULATOR CLIPS				2.5		25	Reviewing	<i>na</i>
<input type="checkbox"/>	/	1		FRONT BUMPER				1450		1450	Reviewing	<i>DE</i>
<input type="checkbox"/>	/	1		FRONT BUMPER LOGO				60		60	Reviewing	<i>na</i>
<input type="checkbox"/>	/	1		FRONT BUMPER LOWER BEAM				195		195	Reviewing	<i>?</i>
<input type="checkbox"/>	/	1		FRONT BUMPER LOWER GRILLE CENTRE				90		90	Reviewing	<i>?</i>
<input type="checkbox"/>	/	1		FRONT BUMPER LOWER GRILLE LH				65		65	Reviewing	<i>?</i>
<input type="checkbox"/>	/	1		FRONT BUMPER LOWER GRILLE RH				65		65	Reviewing	<i>DE</i>
<input type="checkbox"/>	/	1		FRONT BUMPER LOWER GRILLE TRIM LH				30		30	Reviewing	<i>DE</i>
<input type="checkbox"/>	/	1		FRONT BUMPER LOWER GRILLE TRIM RH				30		30	Reviewing	<i>sc</i>
<input type="checkbox"/>	/	1		FRONT BUMPER REINFORCEMENT				490		490	Reviewing	<i>?</i>

10/12/2017

Claim Portal

EDIT	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC COUNT%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
<input type="checkbox"/>	/	2		FRONT BUMPER RIVET				2.5		5	Reviewing	<i>see /</i>
<input type="checkbox"/>	/	1		FRONT BUMPER SPONGE				50		50	Reviewing	?
<input type="checkbox"/>	/	2		FRONT CENTER SENSOR				180		360	Reviewing	?
<input type="checkbox"/>	/	1		FRONT FOG LAMP LH				245		245	Reviewing	X
<input type="checkbox"/>	/	1		FRONT FOG LAMP RH				245		245	Reviewing	X
<input type="checkbox"/>	/	1		FRONT GRILLE INNER BRACKET				25		25	Reviewing	?
<input type="checkbox"/>	/	1		FRONT GRILLE LH				130		130	Reviewing	<i>DE</i>
<input type="checkbox"/>	/	1		FRONT GRILLE RH				130		130	Reviewing	<i>CEA</i>
<input type="checkbox"/>	/	1		FRONT HEADLAMP LH				1800		1800	Reviewing	?
<input type="checkbox"/>	/	1		FRONT HEADLAMP LOWER SUPPORT LH				150		150	Reviewing	?
<input type="checkbox"/>	/	1		FRONT HEADLAMP LOWER SUPPORT RH				150		150	Reviewing	?

10/12/2017

Claim Portal

EDIT	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC COUNT%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
<input type="checkbox"/>	1			FRONT HEADLAMP RH				1800		1800	Reviewing	?
<input type="checkbox"/>	1			FRONT HEADLAMP WASHER BRACKET LH				10		10	Reviewing	?
<input type="checkbox"/>	1			FRONT HEADLAMP WASHER BRACKET RH				10		10	Reviewing	?
<input type="checkbox"/>	1			FRONT HEADLAMP WASHER JET LH				195		195	Reviewing	?
<input type="checkbox"/>	1			FRONT HEADLAMP WASHER JET RH				195		195	Reviewing	?
<input type="checkbox"/>	1			FRONT LOWER AIR DUCT				55		55	Reviewing	?
<input type="checkbox"/>	1			FRONT PANEL				145		145	Reviewing	Bf ✓
<input type="checkbox"/>	1			FRONT PANEL BEAM				150		150	Reviewing	7X
<input type="checkbox"/>	1			FRONT PANEL RUBBER SEAL				40		40	Reviewing	New ✓
<input type="checkbox"/>	1			FRONT REINFORCEMENT BAR LH				35		35	Reviewing	?

10/12/2017

Claim Portal

EDIT	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC CUNTK	PART PRICE(NET)	ACTION (PARTS)	REMOVE
<input type="checkbox"/>	1			FRONT REINFORCEMENT BAR RH				35		35	Reviewing	?
<input type="checkbox"/>	1			RADIATOR - CHECK				0		0	Reviewing	?
<input type="checkbox"/>	1			RADIATOR LOWER COVER CHECK				0		0	Reviewing	?
<input type="checkbox"/>	1			RADIATOR TOP COVER				65		65	Reviewing	?

Labour

Add

EDIT	PART NAME	LABOUR RFR	LABOUR REPAIR	PART	REPAIR/REPLACE (LABOUR)	ACTION (LABOUR)	COMMENT	REMOVE
<input type="checkbox"/>	TO REPAIR FRONT FENDER LH & RH. TO REMOVE AND REPLACE ALL ACCIDENT DAMAGED PARTS AND REALIGN ALL AFFECTED AREA		850		700	Reviewing		
<input type="checkbox"/>	TO SPRAY PAINT ON ACCIDENT AFFECTED AREA				900 800	Reviewing		
<input type="checkbox"/>	TO RESET AND REPROGRAM FRONT HEADLAMP		280		180	Reviewing		
<input type="checkbox"/>	TO REMOVE AND REFIX FRONT SENSORS AND CHECK WIRING		80		60	Reviewing		

JAE 日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
 TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
 48A SUNGEI KADUT AVE SINGAPORE 729672
 TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
 GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
 Dept Direct: 6417 9791 / 6745 9809



Dept Direct: 6306 9610

Dept Direct: 6306 0611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
 Forch (Made in Germany)
 Spark plug: Nippon Denso, NGK (Made In Japan)

MOVA AUTOMOTIVE PTE LTD
 BLK 1001 ,#01-51 BUKIT MERAH LANE

SINGAPORE 159419
 TEL : 62723892/97185821 YONG FAX : 62708314/62643151
 ATTN : JIA YU 91917073

TAX INVOICE : AR201710-11011
 DATE : 20/10/2017
 CUSTOMER ID : MOV001
 VEH REG. NO. : SKB2827C
 TERMS : 30 days
 PO NO. :
 PAGE NO. : Page 1 of 2
 CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	51489119216	BONNET INSULATOR CLIP	U2 L1-A1-SD-B5	10	2.50	25.00
2.	51647200793	H/LAMP LWR BRACKET LH	U2 L1-C12-C	1	150.00	150.00
3.	51137203649	FRT GRILLE LH	U2 L1-B18	1	130.00	130.00
4.	51137203650	FRT GRILLE RH	U2 L1-B18	1	130.00	130.00
5.	51147057794	BMW LOGO	U2 L1-A10-D4	1	60.00	60.00
6.	66209270495	PARKING SENSOR	U2 L1-B23-H	2	180.00	360.00
7.	51117200700	FRT BUMPER GRILLE (CLOSED) RH	U2 L1-D2-G	1	65.00	65.00
8.	51117231860	FINISHER ROD RH	U2 L1-D2-R	1	30.00	30.00
9.	51111908077	BUMPER CLIP	U2 L1-A10-F5	2	2.50	5.00
10.	51117200707	FRT BUMPER FOAM	U2 L1-C20	1	50.00	50.00
11.	51117200705	FRT BUMPER BEAM	U2 L1-C21	1	490.00	490.00
12.	51767206521	BONNET SEAL	U2 L1-B28-C	1	40.00	40.00
13.	51647200689	FRT SUPPORT TOP PANEL (FRT)	U2 L1-C21	1	145.00	145.00
14.	51647187095	FRT SUPPORT LH	U2 L1-D3-B	1	35.00	35.00
15.	51647187096	FRT SUPPORT RH	U2 L1-D3-C	1	35.00	35.00

CONTINUE NEXT PAGE
 ORIGINAL

JAE 日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
 TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
 48A SUNGEI KADUT AVE SINGAPORE 729672
 TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

MOVA AUTOMOTIVE PTE LTD
 BLK 1001, #01-51 BUKIT MERAH LANE

SINGAPORE 159419
 TEL : 62723892/97185821 YONG FAX : 62708314/62643151
 ATTN : JIA YU 91917073

WINDSCREEN GLASS
 Dept Direct: 6417 9791 / 6745 9929

Dept Direct: 6305 9610

Dept Direct: 6417 9794

Arrange By

Driver

Dept Direct: 6305 9611

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 971

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made In Korea),
 Forch (Made in Germany)
 Spark plug: Nippon Denso, NGK (Made In Japan)

TAX INVOICE : AR201710-11011
 DATE : 20/10/2017
 CUSTOMER ID : MOV001
 VEH REG. NO. : SKB2827C
 TERMS : 30 days
 PO NO. :
 PAGE NO. : Page 2 of 2
 CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
------------	-------------	--------	-----	---------	--------

SUB-TOTAL : 1,750.00
 ADD GST 7.00 % 122.50

TOTAL AMOUNT SGD : 1,872.50

E. & O.E

[E] 20/10/2017 9:47:45AM

[P] 20/10/2017 10:05:55AM

Goods Sold are not refundable for Cash.
 Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

Goods Received in Good Order

JAE Auto Pte. Ltd.

Sales Executive : XIAN



This is computer generated document.
 No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司
JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9701 / 6745 9639

Arrange By

Driver *JCF*



Wiper blade: NWB (Nippon Wiper blade), Stilper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

MOVA AUTOMOTIVE PTE LTD
BLK 1001 ,#01-51 BUKIT MERAH LANE

SINGAPORE 159419
TEL : 62723892/97185821 YONG FAX : 62708314/62643151
ATTN : JIAYU 91917073

TAX INVOICE : AR201710-11006
DATE : 20/10/2017
CUSTOMER ID : MOV001
VEH REG. NO. : SKB2827C
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 41617207194	BONNET	CC CC2-G-020	1	1680.00	1,680.00
2. 51117285961	FRT BUMPER	CC CC3-A-020	1	1450.00	1,450.00
3. 51747200787	AIR DUCT	CC CC2-L-08C	1	280.00	280.00

SUB-TOTAL : 3,410.00
ADD GST 7.00 % 238.70

E. & OE TOTAL AMOUNT SGD : 3,648.70

[P] 20/10/2017 10:10:26AM

[E] 20/10/2017 9:46:18AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pta. Ltd.

Sales Executive : XIAN



This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9309

Arrange By _____ Driver LEE



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made In Korea),
Forch (Made In Germany)
Spark plug: Nippon Denso, NGK (Made In Japan)

MOVA AUTOMOTIVE PTE LTD
BLK 1001, #01-51 BUKIT MERAH LANE

SINGAPORE 159419
TEL : 62723892/97185821 YONG FAX : 62708314/62643151
ATTN : JIA YU

TAX INVOICE : AR201710-11412
DATE : 20/10/2017
CUSTOMER ID : MOV001
VEH REG. NO. : SKB2827C
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 13717577469	AIR CHANNEL UNION	KH KH1-N1-03A	1	25.00	25.00
2. 51747200797	AIR DUCT BRAKE LH	KH KH1-K1-03C	1	50.00	50.00

SUB-TOTAL : 75.00
ADD GST 7.00 % 5.25

E & OE TOTAL AMOUNT SGD: 80.25

[P] 20/10/2017 2:55:13PM

[E] 20/10/2017 2:43:05PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : XIAN



This is computer generated document.

No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司
JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9639

Arrange By _____ Driver _____



Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

MOVA AUTOMOTIVE PTE LTD
BLK 1001, #01-51 BUKIT MERAH LANE

SINGAPORE 159419
TEL : 62723892/97185821 YONG FAX : 62708314/62643151
ATTN : JIA YU

TAX INVOICE : AR201710-11069
DATE : 20/10/2017
CUSTOMER ID : MOV001
VEH REG. NO. : SKB2827C
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 5/647200794	H/LAMP LWR BRACKET RH	U2	1	150.00	150.00

SUPPLIER

SUB-TOTAL : 150.00
ADD GST 7.00 % 10.50

E. & O.E TOTAL AMOUNT SGD : 160.50

[P] 20/10/2017 10:21:06AM

[E] 20/10/2017 10:20:41AM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.
Sales Executive : XIAN



Goods Received in Good Order,

Signature / Co Stamp / Date

This is computer generated document.
No signature is required.

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg


GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939

W Audi Dept Direct: 6305 9610

Mitsubishi LUXURY Dept Direct: 6417 9794

Dept Direct: 6417 9795

Arrange By _____ Driver 
TOYOTA GENUINE PARTS Dept Direct: 6305 9611
LEXUS Dept Direct: 6417 9792

HONDA SUBARU NISSAN Dept Direct: 6417 9796 Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Sillper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made In Japan)

MOVA AUTOMOTIVE PTE LTD
BLK 1001 ,#01-51 BUKIT MERAH LANE

SINGAPORE 159419
TEL : 62723892/97185821 YONG FAX : 62708314/62643151
ATTN : JIA YU

TAX INVOICE : AR201710-11317
DATE : 20/10/2017
CUSTOMER ID : MOV001
VEH REG. NO. : SKB2827C
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 51117263325	FRT BUMPER BRACKET L/R	U2 L1-S1-C3	2	25.00	50.00

SUB-TOTAL : 50.00
ADD GST 7.00 % 3.50

E. & O.E TOTAL AMOUNT SGD : 53.50

[P] 20/10/2017 2:56:02PM

[E] 20/10/2017 1:35:58PM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

Goods Received in Good Order

JAE Auto Pte. Ltd.
Sales Executive : XIAN



This is computer generated document.
No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司
JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
 TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
 48A SUNGEI KADUT AVE SINGAPORE 729672
 TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
 GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
 Dept Direct: 6417 9791 / 6745 9699

Dept Direct: 6305 9610

Dept Direct: 6417 9795

Arrange By _____ Driver ALSO

TOYOTA GENUINE PARTS
 Dept Direct: 6305 9611
 LEXUS
 Dept Direct: 6417 9792
 DAIHATSU

HONDA
 Dept Direct: 6417 9796
 SUZUKI
 Dept Direct: 6417 9793
 NISSAN
 Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
 Forch (Made in Germany)
 Spark plug: Nippon Denso, NGK (Made in Japan)

MOVA AUTOMOTIVE PTE LTD
 BLK 1001, #01-51 BUKIT MERAH LANE

SINGAPORE 159419
 TEL: 62723892/97185821 YONG FAX: 62708314/62643151
 ATTN: JIAYU

TAX INVOICE : AR201710-11741
 DATE : 21/10/2017
 CUSTOMER ID : MOV001
 VEH REG. NO. : SKB2827C
 TERMS : 30 days
 PO NO. :
 PAGE NO. : Page 1 of 1
 CURR : SGD

SQ STOCKID	DESCRIPTION	SH-T SRLCC	QTY	U/D PRICE	AMOUNT
1. 51748049708	AIR DUCT FRT BOTTOM	KH KH1-G-01A	1	55.00	55.00

SUB-TOTAL : 55.00
 ADD GST 7.00 % 3.8

TOTAL AMOUNT SGD : 58.8

E. & OE [E] 21/10/2017 9:53:32AM

[F] 21/10/2017 9:57:41AM
 Goods Sold are not refundable for Cash
 Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.
 Sales Executive: XIAN

This is computer generated document.
 No signature is required.



ORIGINAL

Goods Received in Good Order

[Signature]
 Signature / Co Stamp / Date