

ASS. REC. BY:

REF: CS/MSG/17019732/Rlgbm

Special Instructions:

SURVEYOR

Rasul

ASSIGNMENT (Office)

MINIMEN

From (Person)

Jasmine Lok

of

MSG

Date/Time

13/10/17 @ 3:03pm

Estimated Cost

Bill to

OD: (P) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SLB 8325 H

Insured:

SJR 6114C

at Workshop m/s

Ding Auto

Tel:

64521208 / 9239 4128

of BIK 10, # 01-20, Sin Ming Ind Est Sec. C, 575645

Policy No. 80428177 QMX

Claim No.

532827

Sum Insured

Excess

Make of Veh.

D.O.A. 11/10/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

'up'

249 Jalan Boon Lay

H.O.D. Endorsement

Date/Time 13/10/17 @ 3:22pm

Person Contacted

Jin Feng

Vehicle (IN) OUT

Date/Time Action/Instruction (✓) Estimate

SLB 8325 H - X

SJR 6114C - X

08/11/17

REF:

4577k

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SLB 8325H**

at Workshop m/s **Pink Auto**

of

Insured:

msih / TP

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6 days

Res: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLB 8325H

Yr Regn:

2016 / APR

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

TOYOTA COROLLA ALTIS 1.6 CC 1898

Colour:

GREY

A/C:

Insured / Std / NI / NA

Sp. Reading

107153

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR053RKH 1045 40298

Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

205 / 55 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

TRIANGLE

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.I.

14/10/17

D.O.I.

13/10/17

Survey held at

SWH AUTO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/10/17

Rev preli in maximen.

4s \$ 2050

(Red: 5579.85, 73%).

RECEIVED 05 DEC 2017

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: **6**

Resurvey No. of Trip:

Survey Fee:

200

Transportation:

☐ S + RS, ☐ SI

☐ Photos

☐ Others:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Report Format: **TP**

Lump Sum / I.B.I: (\$ **2050**)

TOTAL

>10



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17019732/R1gb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 13-10-2017		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJR 6114C	Veh. Inspected	SLB 8325H	
Policy No.	80428177QMX	Coverage (\$)	0.00	
Claim No.	532827	Excess (\$)	0.00	
Assign From	MERIMEN (JASMINE LOK)	Assign Date	13/10/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/10/2017	Inspection Date		
Survey held at	249 JALAN BOON LAY			
Repairer	DING AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Oct 2017 Sendback Est	11 Oct 2017 18:20 S\$7,130.70	13 Oct 2017 15:03 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	LEE YING (NOT DRIVING), ID: 0		
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Vehicle Reg. No.:	SLB8325H	Date of Loss:	11/10/2017 11:00 - :59
Claim Type:	TP / 532827	Policy/Cover Note No.:	80428177QMX Coverage: 30/05/2017 - 24/02/2018
Vehicle Reg. No. (Insured):	SJR6114C	Policy No. (Claimant):	999995174
		Excess:	
Repairer:	Ding Auto Pte Ltd (HQ) Blk 10, #01-20, Sin Ming Industrial Estate Sector C, 575645 Sin Ming - Tel: 64521208		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwel - 6594 2550]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/10/2017]		
Driver/Custodian (Insured):	TAY PHUAH HAI (), Tel: +6596667615		
Adj Asg. Remarks:	ON WP		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS ☐

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Margaret Loh

From: JingFeng <jingfeng@dingauto.sg>
Sent: Thursday, 12 October, 2017 12:27 PM
To: Jasmine Lok Kheng Kwei
Cc: Margaret Loh; kenneth.ding@dingauto.sg; 'Vivian'; Yvonne Wong
Subject: Re: ACCIDENT INVOLVING SLB8325H AND SJR6114C - ARRANGE SURVEYOR & UPDATE LIABILITY
Attachments: SAS2291165(1).PDF

Dear All

Please check the attach GIA REPORT and arrange surveyor ASAP

Vehicle Location At 249 Jalan Boon Lay SINGAPORE 619523

and I have upload GIA Report And IC to Merimen

ThanKs

If you require any further information, feel free to contact me JIng Feng @97335832

Best Regards

YOU JING FENG

97335832

On 12/10/2017 10:48, Jasmine Lok Kheng Kwei wrote:

>
> Hi Jingfeng,
>
> Please refer to the email below
>
> Please be informed that our insured has not reported and we are unable
> to comment on the liability clearance.
>
> Thank you.
>
> Have a nice day ahead.
>
> Jasmine Lok
> Executive, Claims Services (Motor)
> Direct line +65 6594 2550 | Direct fax +65 6225 7402 |
> jasmine_lok@sg.msiga-asia.com
>
>
> MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong
> Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65
> 6225 6371 | Co. Reg. No. 200412212G | <http://www.msiga.com.sg/> |
> Follow us on
>
>
>

>
> -----Original Message-----
> From: Woon Choo Kwok
> Sent: Thursday, 12 October, 2017 9:50 AM
> To: Jasmine Lok Kheng Kwei <jasmine_lok@sg.msig-asia.com>; Margaret
> Loh <margaret_loh@sg.msig-asia.com>
> Cc: Christopher Chionh <christopher_chionh@sg.msig-asia.com>; Foo Ai
> Ngoh <aingoh_foo@sg.msig-asia.com>; Jason Sim
> <Jason_Sim@sg.msig-asia.com>
> Subject: FW: ACCIDENT INVOLVING SLB8325H AND SJR6114C - ARRANGE
> SURVEYOR & UPDATE LIABILITY

>
> Dear JLKK & ML,

>
> FYA

>
> Best Regards

>
> Kwok Woon Choo
> Senior Administrative Officer, Claims Services Direct line +65 6643
> 1330 | Direct fax +65 6225 7402 | woonchoo_kwok@sg.msig-asia.com

>
> MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong
> Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co.
> Reg. No. 200412212G | msig.com.sg

> -----Original Message-----
> From: Koh Lay Hoon
> Sent: Thursday, October 12, 2017 9:03 AM
> To: Woon Choo Kwok <WoonChoo_Kwok@sg.msig-asia.com>
> Subject: FW: ACCIDENT INVOLVING SLB8325H AND SJR6114C - ARRANGE
> SURVEYOR & UPDATE LIABILITY

> -----Original Message-----
> From: JingFeng [mailto:jingfeng@dingauto.sg]
> Sent: Wednesday, October 11, 2017 6:25 PM
> To: Claims <claims@sg.msig-asia.com>
> Cc: kenneth.ding@dingauto.sg; ACCOUNTS@DINGAUTO.SG;
> ACCIDENTREPAIR@stengg.com; 'Vivian' <vivian.tan@dingauto.sg>; Yvonne
> Wong <yvonne.wong@dingauto.sg>
> Subject: ACCIDENT INVOLVING SLB8325H AND SJR6114C - ARRANGE SURVEYOR
> & UPDATE LIABILITY

>
> Dear All

>
> Please arrange for survey SLB8325H ASAP

>
> and please update this case liability

> Location at 249 JALAN BOON LAY

>

> Beside STA INSPECTION CENTRA

>

> BEST REGARDS

>

> DING AUTO PTE LTD

>

> YOU JING FENG

>

> 9733583

>

>

>

> ---

> This email has been checked for viruses by Avast antivirus software.

> <https://www.avast.com/antivirus>

>

> _____

>

> CONFIDENTIALITY NOTICE

> This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

>

--

BEST REGARDS

DING AUTO PTE LTD

YOU JING FENG

HP : 97335832

TEL Office : 92394128

FAX :62652690

ADDRESS:249 JALAN BOON LAY SINGAPORE 619523
(BESIDE STA Vehicle Inspection)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 16 Oct 2017

Preliminary Advice

Insured Vehicle No : SJR6114C

TP Vehicle No : SLB8325H

Make : TOYOTA COROLLA ALTIS

Date of Inspection : 13/10/2017

Inspection At : DING AUTO PTE LTD (HQ)

BLK 10, #01-20, SIN MING INDUSTRIAL ESTATE SECTOR C
SINGAPORE 575645

Accident Date : 11/10/2017

Assignment Date : 13/10/2017

Est. Duration of Repair : 6.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,130.70
Revised Amount	:S\$	2,370.25
Check Items (Estimated)	:S\$	265.65
Total	:S\$	2,635.90

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/10/2017 15:03
Date Of Accident	11/10/2017 11:50
Exact Location Of Accident	FARRER ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB8325H
Insured/Policyholder	
Name Of Registered Owner	LORF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-31584255

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS CLASSIC 1.6 CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	999995174
Cover Note Number	

Driver

Name of Driver	MOHAMAD SHALAN BIN JURI
NRIC No	S1628945J
Date Of Birth	24/02/1964
Occupation	OUTDOOR
Date Of Driving Pass	27/05/1984
Driving Experience	33 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? YES

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJR6114C

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver TAY PHUAH HAI

NRIC/Passport Number

Contact Number 96667615

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name MOHAMAD SHALAN BIN JURI

Approximate Age

Injuries Sustain
Injured person in which vehicle? SLB8325H
Were seat belts worn?
Was injured conveyed to hospital by ambulance? NO
Address
Postcode:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims;
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms) which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

11 Oct 2017

Witnessed by Reporting Centre Personnel

A - SLB 83254
B - SJR 6114 C

Father Rd

Father Rd

Sketch Plan

Describe Circumstances of the Accident

On 11 Oct 2017 @ 11:50 am while approaching junction of Farrer Road & Empress (towards PIE), I stopped at the junction bus traffic light turn red.

After stopping at the junction, I heard a screaming followed with a loud bang.

My car was hit by another ^{car} from behind. with reg. no SJR 6114 C, Volvo XC60.

My car suffered a rear left bumper damaged.

I feel unwell after the incident and will consult doctor later.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



Signature of Driver



11. Oct 2017

Ding Auto Pte Ltd (Co.Reg.No.201311788Z)Blk 10, #01-20, Sin Ming Industrial Estate Sector C
Singapore 575645

Tel: 64521208 Fax: 64520614 Email: anna.chua@dingauto.sg; admin@dingauto.sg; ding@dingauto.sg

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)**TAY PHUAH HAI**

0

Singapore

Claimant Insurer: AIG Asia Pacific Insurance Pte. Ltd.**PARTICULARS OF CLAIM**

Claim Type:	Third Party	Ref. No:	
Policy No:		Date of Loss:	11/10/2017
Vehicle Reg. No.:	SLB8325H	Driveable?	NO
Party At Fault:	UNKNOWN		
Driver (TP):	MOHAMAD SHALAN BIN JURI		
Make/Model:	TOYOTA COROLLA ALTIS, 1.6 Classic (A)	Vehicle Reg. Date:	25/04/2016
Vehicle Colour:	Silver		
Engine No:	1ZRY219471	Chassis No:	MR053REH104540298
Odometer:	107753 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO GIA REPORT		
Remarks:	VEHICLE LYING AT 249 JALAN BOON LAY		
Present Location:	DING AUTO PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	3,840.70
Miscellaneous Items	0.00
Labour	3,290.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	7,130.70
+ GST 7.00% (\$\$)	499.15
Nett Amount (\$\$)	7,629.85

This claim is handled by: JING FENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Oct 2017)
 Parts: 143 TOYOTA COROLLA ALTIS 1.6 Classic (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ding Auto Pte Ltd/SLB8325H/11/10/2017 18:20
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	0.00	0.00	*200.00 F
2	1		*REAR BUMPER SIDE RETAINER LONG LHS	0.00	0.00	*25.00 F
3	1		*REAR BUMPER SIDE RETAINER LONG RHS	0.00	0.00	*25.00 F
4	1		*REAR BUMPER SIDE RETAINER SHORT RHS	0.00	0.00	*20.00 F
5	1		*REAR BUMPER SIDE RETAINER SHORT LHS	0.00	0.00	*20.00 F
6	1		*REAR BUMPER CLIP	0	0.00	*35.00 FS
7	1		*REAR BUMPER SIDE REFLECTOR LHS	0.00	0.00	*36.00 F
8	1		*REAR BUMPER SIDE REFLECTOR RHS	0.00	0.00	*36.00 F
9	1		*REVERSER SENSOR	0.00	0.00	*160.00 F
10	1		*REAR BOOT	0.00	0.00	*350.00 FR
11	1		*REAR BOOT EMBLEM-LOGO	0.00	0.00	*25.00 F
12	1		*REAR BOOT EMBLEM-COROLLA	0.00	0.00	*25.00 F
13	1		*REAR BOOT EMBLEM-ALTIS	0.00	0.00	*25.00 F
14	1		*REAR BOOT NUMBER PLATE LAMP LHS	0.00	0.00	*40.00 F
15	1		*REAR BOOT NUMBER PLATE LAMP RHS	0.00	0.00	*40.00 F
16	1		*REAR BOOT CHROME	0.00	0.00	*150.00 F
17	1		*REAR BOOT LOCK	0.00	0.00	*185.00 F
18	1		*REAR BOOT LOCK CATCH	0.00	0.00	*25.00 F
19	1		*REAR END PANEL	0.00	0.00	*180.00 F
20	1		*REAR END PANEL TOP GARNISH	0.00	0.00	*125.00 F
21	1		*REAR END PANEL TOP GARNISH CLIP	0	0.00	*35.00 FS
22	1		*SPARE TYRE PANEL	0.00	0.00	*180.00 F
23	1		*SPARE TYRE PANEL BOARD	0.00	0.00	*145.00 F
24	1		*REAR END WEATNERSTRIP	0.00	0.00	*65.00 F
25	1		*REAR END PANEL BRACKET LHS	0.00	0.00	*35.00 F
26	1		*REAR END PANEL BRACKET RHS	0.00	0.00	*35.00 F
27	1		*TAIL LAMP OUTER LHS	0.00	0.00	*150.00 F
28	1		*TAIL LAMP OUTER RHS	0.00	0.00	*150.00 F
29	1		*TAIL LAMP INNER RHS	0.00	0.00	*140.00 F
30	1		*TAIL LAMP INNER LHS	0.00	0.00	*140.00 F
31	1		*REAR BOOT INNER LINING CLIP	0	0.00	*35.00 FS
32	1		*REAR FENDER LHS	0.00	0.00	*450.00 F
33	1		*REAR FENDER INNER SHIELD LHS CLIP	0	0.00	*35.00 FS
34	1		*REAR FENDER INNER SHIELD LHS	0.00	0.00	*36.00 F

F=Franchise part, S=SpocNett.

Sub Total (\$\$) 3,358.00
 + Margin on L,N Items 15.00% (\$\$) 482.70
 Total Parts (\$\$) 3,840.70

Ding Auto Pte Ltd/SLB8325H/11/10/2017 18:20. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

S/N-140

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS	New	1,400.00 ⁷⁰⁰
2	R&R BOOTLID COMPONENTS	New	80.00 ⁴⁰
3	R&R REAR WINDSCREEN	New	150.00 ^{Xm}
4	R&R SPARETYRE BOARD/CARPET/TRIM	New	100.00 ⁶⁰
5	R&R REAR REVERSE SENSOR	New	50.00 ✓
6	SPRAY REAR BUMPER	New	250.00 ²⁰⁰
7	SPRAY REAR END PANEL	New	250.00 ²⁰⁰
8	SPRAY REAR BOOT	New	250.00 ²⁰⁰
9	SPRAY REAR FENDER LHS	New	250.00 ^{Xnn}
10	SPRAY REAR FENDER RHS	New	80.00 ⁴⁰
11	CHECK WIRING	New	80.00 ⁴⁰
12	RUSH PROOFING	New	100.00 ^{Xnn}
13	SPRAY REVERSE SENSOR	New	
Gross Labour Cost (\$\$)			3,290.00

Ding Auto Pte Ltd/SLB8325H/11/10/2017 18:20. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Ram

Hp 90010068

6 days

4s

13/10/17 @ 1800

Resy after repair

13/10/17

732.60

140.00

1730.00

2602.60

208

2082.08

4/5-2050

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6 days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17019732/R1GBN2

Date: 06/12/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	80428177QMX
Claimant Vehicle No :	SLB8325H	Insured Vehicle No :	SJR6114C
Date of Loss:	11/10/2017	Nature of Claim:	TP
		Claim No:	532827

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB8325H	Engine No:	1ZRY219471
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 Classic (A)	Chassis No:	MR053REH104540298
Reg. Date:	25/04/2016 (Man. Year: 2015)	Odometer:	107753 km
Colour:	Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,840.70	905.90	2,934.80	76.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,290.00	1,730.00	1,560.00	47.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,130.70	2,635.90	4,494.80	63.03
Approved Total (Overridden) (S\$)		2,050.00		
(S\$)	7,130.70	2,050.00	5,080.70	71.25
+ GST 7.00/7.00% (S\$)	499.15	143.50	355.65	71.25
Nett Amount (S\$)	7,629.85	2,193.50	5,436.35	71.25

INSPECTION

Date of Assignment:	13/10/2017 Present Location:	-
Date Inspected:	13/10/2017 Inspected At:	249 Jalan Boon Lay Repairer: Ding Auto Pte Ltd Blk 10 #01-20 Sin Ming Ind Est Sec C Singapore 575645

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Dec 2017)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 Classic (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB8325H)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	200.00 F	*200.00 F
2	1		*REAR BUMPER SIDE RETAINER LONG LHS	Cracked	25.00 F	*25.00 F
3	1		*REAR BUMPER SIDE RETAINER LONG RHS	Serviceable	25.00 F	*- F
4	1		*REAR BUMPER SIDE RETAINER SHORT RHS	Serviceable	20.00 F	*- F
5	1		*REAR BUMPER SIDE RETAINER SHORT LHS	Cracked	20.00 F	*20.00 F
6	1		*REAR BUMPER CLIP	Necessary	35.00 FS	*35.00 FS
7	1		*REAR BUMPER SIDE REFLECTOR LHS	Cracked	36.00 F	*36.00 F
8	1		*REAR BUMPER SIDE REFLECTOR RHS	Not Necessary	36.00 F	*- F
9	1		*REVERSER SENSOR	Necessary	160.00 F	*160.00 F
10	1		*REAR BOOT	Repair	350.00 F	*- F
11	1		*REAR BOOT EMBLEM-LOGO	Necessary	25.00 F	*25.00 F
12	1		*REAR BOOT EMBLEM-COROLLA	Necessary	25.00 F	*25.00 F
13	1		*REAR BOOT EMBLEM-ALTIS	Necessary	25.00 F	*25.00 F
14	1		*REAR BOOT NUMBER PLATE LAMP LHS	Serviceable	40.00 F	*- F
15	1		*REAR BOOT NUMBER PLATE LAMP RHS	Not Necessary	40.00 F	*- F
16	1		*REAR BOOT CHROME	Serviceable	150.00 F	*- F
17	1		*REAR BOOT LOCK	Serviceable	185.00 F	*- F
18	1		*REAR BOOT LOCK CATCH	Serviceable	25.00 F	*- F
19	1		*REAR END PANEL	Repair	180.00 F	*- F
20	1		*REAR END PANEL TOP GARNISH	Serviceable	125.00 F	*- F
21	1		*REAR END PANEL TOP GARNISH CLIP	Necessary	35.00 FS	*35.00 FS
22	1		*SPARE TYRE PANEL	Repair	180.00 F	*- F
23	1		*SPARE TYRE PANEL BOARD	Serviceable	145.00 F	*- F
24	1		*REAR END WEATNERSTRIP	Serviceable	65.00 F	*- F
25	1		*REAR END PANEL BRACKET LHS	Serviceable	35.00 F	*- F
26	1		*REAR END PANEL BRACKET RHS	Serviceable	35.00 F	*- F
27	1		*TAIL LAMP OUTER LHS	Cracked	150.00 F	*150.00 F
28	1		*TAIL LAMP OUTER RHS	Serviceable	150.00 F	*- F
29	1		*TAIL LAMP INNER RHS	Not Necessary	140.00 F	*- F
30	1		*TAIL LAMP INNER LHS	Serviceable	140.00 F	*- F
31	1		*REAR BOOT INNER LINING CLIP	Necessary	35.00 FS	*35.00 FS
32	1		*REAR FENDER LHS	Repair	450.00 F	*- F
33	1		*REAR FENDER INNER SHIELD LHS CLIP	Necessary	35.00 FS	*35.00 FS
34	1		*REAR FENDER INNER SHIELD LHS	Not Necessary	36.00 F	*- F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	3,358.00	806.00
+ Margin on L,N Items 15.00/15.00% (\$\$)	482.70	99.90
Total Parts (\$\$)	3,840.70	905.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS	New	1,400.00	700.00
2	R&R BOOTLID COMPONENTS	New	80.00	40.00
3	R&R REAR WINDSCREEN	New	150.00	-
4	R&R SPARETYRE BOARD/CARPET/TRIM	New	100.00	60.00
5	R&R REAR REVERSE SENSOR	New	50.00	50.00
6	SPRAY REAR BUMPER	New	250.00	200.00
7	SPRAY REAR END PANEL	New	250.00	200.00
8	SPRAY REAR BOOT	New	250.00	200.00
9	SPRAY REAR FENDER LHS	New	250.00	200.00
10	SPRAY REAR FENDER RHS	New	250.00	-
11	CHECK WIRING	New	80.00	40.00
12	RUSH PROOFING	New	80.00	40.00
13	SPRAY REVERSE SENSOR	New	100.00	-
Gross Labour Cost (\$\$)			3,290.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >