

APS REC BY

REF CS/LPC/7019740/TTB32

Serial Inspection

Merimen

Taufik

ASSIGNMENT (Office)

Final Person

Gerald Poh

of

LPC

Date/Time

16/10/17 @ 6.43pm

Assigned For

By

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No

SKA 1960L

Insured

at Workshop n/o

Mova Automotive

Tel 62723892

at No.22 jln Kilang #03-01, Main Building, 159419

Policy No Z1VP05015446

Claim No 17/17/17/VP05/020153

Sum Insured

Excess \$500.00

Make of Veh

D.O.A 10/10/2017

(Client's Record)

CA (REV) / REP. / REV 24 HRS

17.10.2017 @ 11.30am

H.O.D. Endorsement

Date/Time 16/10/17

Person Contacted

Annie

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKA 1960 L - cc 31 LPC/7019586/RTHB3-D.O.A: 10/10/17

19/10 Report via merimen

19/10 - 2:29pm email by Gerald authorise repair

19/10 @ 2:33pm inform suanne authorise repair excess \$500

Surveyor: Tanfer

REF: LPC

ASSIGNMENT

From: _____ Date: 17/10/17

Estimated Cost: _____

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKA 1960 L

at Workshop m/s Mova Automotive

of Blk 1008, Blk Merah Lane 3 #01-04, 159722

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: \$500.00

(Client's Record)

Make of Veh: _____

(Policy Condition) 11:30 am owner waiting

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 465K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKA 1960 L Yr Regn: 2011, Jan

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Land Rover Freelander c.c. 3192

Colour grey A/C: Insured / Std / NI / NA

Sp. Reading 38035 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SALFAR2 AAXBM230040

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/55R19

R: 4 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Survey held at Mova Bkt Merah

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

49867.15, 5 days - email to Sir Yu.
(Red: 4672.50:32%)

RECEIVED 30 JAN 2018

Date/Time, File Pass to?

1) 30/1 Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee: 276

Transportation: 50

50 S + RS, SI

Photos 53

Others 53

TOTAL

42910

Report Format: 00

Lump Sum / (LB): (\$ 9867.15)

4x15=60
60+170=230
230x276=46
46+230=276



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CS/LPC17019790/T1tb	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 16-10-2017	
		Code : LPC2	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SKA 1960L
Policy No.	Z1VP05015446	Coverage (\$)	0.00
Claim No.	17/17/17/VP05/020153	Excess (\$)	500.00
Assign From	MERIMEN (GERALD POH)	Assign Date	16/10/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	10/10/2017	Inspection Date	16/10/2017
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Oct 2017 Sendback Est	13 Oct 2017 16:23 S\$14,539.65	16 Oct 2017 06:43 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	BOYLE NG CHAI TEE, ID: S1687489B, Tel: +6597607900, Email: BOYLE.NG@BORNEOMOTORS.COM.SG		
Vehicle Reg. No.:	SKA1960L	Date of Loss:	10/10/2017 09:00 - :59
Claim Type:	OD / 17/17/17/VP05/020153	Policy/Cover Note No.:	Z17VP05015446 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) No. 22 Jalan Kilang, #03-01, Mova Building, 159419 Bukit Merah - Tel: 62723892/64763333		
Handling Insurer:	Lompac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/10/2017]		
Driver/Custodian:	BOYLE NG CHAI TEE (52 / Male), NRIC: S1687489B, Tel: +6597607900		
Adj Asg. Remarks:	SURVEY & REVERT.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Taufikh (LKK Auto)

From: Jia Yu [jiayu@movs.com.sg]
Sent: Wednesday, 20 December 2017 2:48 PM
To: 'Taufikh (LKK Auto)'
Subject: RE: SKA1960L FINALIZATION

Hi Taufikh,

Okay. Confirmed at \$9867.15.
Thank You.

Best Regards,
Jia Yu
MOVA Automotive Pte Ltd

From: Taufikh (LKK Auto) [<mailto:taufikh@lkkauto.com>]
Sent: Tuesday, 19 December 2017 5:12 PM
To: 'Jia Yu'
Cc: 'Denise Tay (LKKAuto)'
Subject: RE: SKA1960L FINALIZATION

Hi Jia Yu,

Labour to repair door revised to \$300. Therefore COR \$9867.15 , 5 days.

Regards
Taufikh
Lkk Auto

From: Jia Yu [<mailto:jiayu@movs.com.sg>]
Sent: Monday, 27 November 2017 3:32 PM
To: 'Taufikh (LKK Auto)'
Cc: sur@lkkauto.com
Subject: SKA1960L FINALIZATION

Hi Taufikh,

Above attached with before paint, check items and after repair photos for SKA1960L.
Would like to request additional \$400 labour for repair of rear door LH as the part is currently unavailable worldwide.
Please advice whether we can finalise the cost of repair at \$9967.15 ?
Thank You.

Best Regards,
Jia Yu
MOVA Automotive Pte Ltd

Denise Tay (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 19 October, 2017 2:29 PM
To: Admin-D (LKKAUTO)
Cc: MT_Claim_SG
Subject: FW: OD CLAIM - SKA1960L

Dear Catherine,

Your letter of 19 October 2017 refers.

You may proceed to authorize repair as per your adjustment.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: GERALD POH WEE BIN
Sent: Friday, 13 October, 2017 1:33 PM
To: 'Catherine Chong (LKK Auto)'
Cc: 'mt_claim@lonpac.com'
Subject: OD CLAIM - SKA1960L

Our Ref : 17/17/17/VP05/020153

Dear Catherine,

Kindly proceed to survey the vehicle first as the estimates are being uploaded into Merimen by the workshop.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gerald Poh

Date: 19 Oct 2017

Preliminary Advice

Vehicle No	: SKA1960L	Accident Date	: 10/10/2017
Make	: LAND ROVER FREELANDER 2	Policy No.	: Z17VP05015446
Assignment Date	: 16/10/2017	Excess	: S\$500.00
Date of Inspection	: 17/10/2017	Est. Duration of Repair	: 5.00
Inspection At	: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH) NO. 22 JALAN KILANG, #03-01, MOVA BUILDING SINGAPORE 159419		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages N/S portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,539.65
Revised Amount	:S\$	12,982.65
Check Items (Estimated)	:S\$	1,127.00
Total	:S\$	14,109.65

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	65,000.00
COE / PARF Rebate	:S\$	46,012.00
Salvage Value	:S\$	
Margin for Repair	:S\$	18,988.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/10/2017 09:01
Date Of Accident	10/10/2017 09:20
Exact Location Of Accident	SENJA RD JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA1960L
Insured/Policyholder	
Name Of Registered Owner	BOYLE NG CHAI TEE
NRIC No	S1687489B
Email Address	BOYLE.NG@BORNEOMOTORS.COM.SG
Mobile Phone No	(LOCAL) +65-97607900
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	LAND ROVER
Model	FREELANDER 2 LF 3.2L (A) ABS A/B G/D SR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle? YES	
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z17VP05015446
Cover Note Number	
Driver	
Name of Driver	BOYLE NG CHAI TEE
NRIC No	S1687489B
Date Of Birth	30/01/1965
Occupation	INDOOR
Date Of Driving Pass	13/02/1985
Driving Experience	32 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97607900
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	BOYLE.NG@BORNEOMOTORS.COM.SG

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKR8737E
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver WONG YUH YEH
 NRIC/Passport Number S8011456G
 Contact Number 98513614
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness


Name
 Phone Number
 Email Address

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date &
Time 9.15 am

Sketch Plan 11/10/2017


Driver's Signature (if driver is not the policyholder) / Date
& Time



Witnessed by Reporting Centre
Personnel

A - SKA1960L

B - SKR 8731E



Sketch Plan Pg. 2

Describe Circumstances of the Accident		LICENSE PLATE NUMBER: SKA 1960 L
ACCIDENT DATE: 10/10/2017	CONTACT NUMBER: 97607900	
ACCIDENT TIME: 9.20 am	EMAIL: boyle.ng@borneomotors.com.sg	
LOCATION: Senja Rd Junction		
On morning of 10th Oct 2017 at about 9.20 am, I was travelling along Senja Road on the right lane when at the traffic light, a car driven by Mr Wong Yuh Yeh, IC S 80114566, car registration number SKR 8737E knocked into my left side doors. upon assessing the road condition as to how I was being (knocked) while travelling on a straight road, I realized I was on a right turn lane while the other driver car was on my left lane trying to make a right turn. The road sign arrow shows that the left lane has a straight and right turn arrow. I had my wife and daughter in my car but no injury. The other driver has his wife with him, also no injury.		
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION.		
Please state:		
☒ Claim Own Policy ☐ Claim Third Party ☐ Claim OD/TP at other workshop ☐ Reporting Only		

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &

Time
11/10/2017
9.15 am

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	7489B
Vehicle Details	
Vehicle No.	SKA1960L
Vehicle to be Exported	No
Intended De-registration Date	19 Oct 2017
Vehicle Make	LAND ROVER
Vehicle Model	FREELANDER 2 LF 3.2L (A) ABS A/B G/D SR
Primary Colour	Grey
Manufacturing Year	2010
Engine No.	B6324S18111015321
Chassis No.	5ALFA2AAXBH230040
Maximum Power Output	171.0 kW (229 bhp)
Open Market Value	\$41,164.00
Original Registration Date	27 Jan 2011
First Registration Date	27 Jan 2011
Transfer Count	1
Actual ARF Paid	\$41,164.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	26 Jan 2021
PARF Rebate Amount	\$26,756.00
Intended COE Rebate Details	
COE Expiry Date	26 Jan 2021
COE Category	B - Car (1601cc & above)
COE Period(Years)	10
QP Paid	\$58,910.00
COE Rebate Amount	\$19,256.00
Total Rebate Amount	\$46,012.00

The information contained herein is correct as at 19 Oct 2017

OK



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0068864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



INSURER:

Lonpac Insurance Bhd (HQ)

PARTICULARS OF CLAIM

Claim Type: OD (OWN DAMAGE)
Policy No: Z17VP05015446
Vehicle Reg. No.: SKA1960L
Driver Age/Info: 52 / MALE
TP Injury Involved? NO
Insured/Claimant: BOYLE NG CHAI TEE
Driver: BOYLE NG CHAI TEE

Ref. No:
Date of Loss: 10/10/2017
Driveable?
Party At Fault: UNKNOWN
Third Party Involved? YES
Contact No: +6597607900

Make/Model: LAND ROVER FREELANDER 2, 3.2 I6 HSE (A)
Vehicle Colour: GREY
Engine No: B6324S18111015321
Odometer: 0 KM

Vehicle Reg. Date: 27/01/2011
Chassis No: SALFA2AAXBH230040

Paint Type:
Total Loss? NO
Est. Duration of Repair (day) 5

Present Location: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)

*Taughtin 97495749
Revent. Ex 9500
17/10/17 @ 12pm
5 days*

Resurvey before paint.

sur @ khairat.com

	Amount
	13,099.65
	0.00
	1,440.00
	0.00
	0.00

COST OF CLAIMS

Parts
Miscellaneous Items
Labour
Paintwork Labour
Towing

Gross Total (\$\$)	14,539.65
+ GST 7.00% (\$\$)	1,017.78
Nett Amount (\$\$)	15,557.43

This claim is handled by: JIAYU

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Oct 2017)

Parts: M1-SUV LAND ROVER FREELANDER 2 3.2 i6 HSE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Mova Automotive Pte Ltd/SKA1960L/13/10/2017 16:23

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT DOOR LH	0.00	0.00	bt 3,550.00 F
2	1		*FRONT DOOR PROTECTOR LH	0.00	0.00	mis 380.00 F
3	12		*FRONT DOOR PROTECTOR CLIPS	0.00	0.00	ne 96.00 F
4	1		*FRONT DOOR WEATHERSTRIP LH	0.00	0.00	ne 215.00 F
5	1		*REAR DOOR LH	0.00	0.00	bt x 3,350.00 FRx
6	1		*REAR DOOR PROTECTOR LH	0.00	0.00	mis 260.00 F
7	10		*REAR DOOR PROTECTOR CLIPS	0.00	0.00	ne 80.00 F
8	1		*REAR DOOR WEATHERSTRIP LH	0.00	0.00	ne 220.00 F
9	1		*REAR DOOR EDGE RUBBER LH	0.00	0.00	ne 110.00 F
10	1		*REAR DOOR WINDOW REGULATOR LH	0.00	0.00	nm R 600.00 F
11	1		*SIDE SKIRT LH	0.00	0.00	? 380.00 F at
12	1		*REAR WHEEL RIM LH	0.00	0.00	at 2,150.00 F

F=Franchise part.

Sub Total (S\$)	7441	11,391.00
+ Margin on L,N Items 15.00% (S\$)	1110.15	1,708.65
Total Parts (S\$)	8557.15	13,099.65

Mova Automotive Pte Ltd/SKA1960L/13/10/2017 16:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REPAIR ROCKER PANEL LH. TO REMOVE AND REPLACE ALL ACCIDENT DAMAGED PARTS AND REALIGN ALL AFFECTED	New	300 450.00
2	TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS	New	500. 700.00
3	TO REMOVE AND REFIX DOOR MECHANISM, CHECK AND TEST POWER WINDOW AND CENTRE LOCKING SYSTEM	New	100. 160.00
4	TO CONDUCT WHEEL ALIGNMENT	New	✓ 80.00
5	TO REMOVE AND REFIX WHEEL RIM AND CONDUCT BALANCING	New	30 50.00
Gross Labour Cost (\$\$)			1,440.00

Mova Automotive Pte Ltd/SKA1960L/13/10/2017 16:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



Main Office : No. 22, Jalan Klang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/08/08/116, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088884-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



INSURER:

Lonpac Insurance Bhd (HQ)

PARTICULARS OF CLAIM

Claim Type: OD (OWN DAMAGE)
Policy No: Z17VP05015446
Vehicle Reg. No.: SKA1960L
Driver Age/Info: 52 / MALE
TP Injury Involved? NO
Insured/Claimant: BOYLE NG CHAI TEE
Driver: BOYLE NG CHAI TEE

Ref. No:
Date of Loss: 10/10/2017
Driveable?
Party At Fault: UNKNOWN
Third Party Involved? YES
Contact No: +6597607900

Make/Model: LAND ROVER FREELANDER 2, 3.2 I6 HSE (A)
Vehicle Colour: GREY
Engine No: B6324S18111015321
Odometer: 0 KM

Vehicle Reg. Date: 27/01/2011

Chassis No: SALFA2AAXBH230040

Paint Type:
Total Loss? NO
Est. Duration of Repair (day) 5

Taughtin 97495749
Reverts Ex 8500
17/10/17 @ 12pm
5 days

Present Location: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)

Reservy before paint.
sur @ khairi.com

COST OF CLAIMS

	Amount
Parts	13,099.65
Miscellaneous Items	0.00
Labour	1,440.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (\$\$) 14,539.65
+ GST 7.00% (\$\$) 1,017.78
Nett Amount (\$\$) 15,557.43

This claim is handled by: JIAYU

Generated using Merlimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Oct 2017)
 Parts: M1-SUV LAND ROVER FREELANDER 2 3.2 16 HSE (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)

Print Code: Mova Automotive Pte Ltd/KA1960L/13/10/2017 16:23

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT DOOR LH	0.00	0.00	ht 3,550.00 F
2	1		*FRONT DOOR PROTECTOR LH	0.00	0.00	mis 380.00 F
3	12		*FRONT DOOR PROTECTOR CLIPS	0.00	0.00	nc 96.00 F
4	1		*FRONT DOOR WEATHERSTRIP LH	0.00	0.00	nc 215.00 F
5	1		*REAR DOOR LH	0.00	0.00	ht 3,950.00 F
6	1		*REAR DOOR PROTECTOR LH	0.00	0.00	mis 280.00 F
7	10		*REAR DOOR PROTECTOR CLIPS	0.00	0.00	nc 80.00 F
8	1		*REAR DOOR WEATHERSTRIP LH	0.00	0.00	nc 220.00 F
9	1		*REAR DOOR EDGE RUBBER LH	0.00	0.00	nc 110.00 F
10	1		*REAR DOOR WINDOW REGULATOR LH	0.00	0.00	? 600.00 F
11	1		*SIDE SKIRT LH	0.00	0.00	? 380.00 F
12	1		*REAR WHEEL RIM LH	0.00	0.00	at 2,150.00 F

P=Franchise part.

Sub Total (\$\$) 11,391.00
 + Margin on L,N Items 15.00% (\$\$) 1,708.65
 Total Parts (\$\$) 13,099.65

Mova Automotive Pte Ltd/KA1960L/13/10/2017 16:23. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REPAIR ROCKER PANEL LH. TO REMOVE AND REPLACE ALL ACCIDENT DAMAGED PARTS AND REALIGN ALL AFFECTED	New	300 450.00
2	TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS	New	500. 700.00
3	TO REMOVE AND REFIX DOOR MECHANISM, CHECK AND TEST POWER WINDOW AND CENTRE LOCKING SYSTEM	New	100. 160.00
4	TO CONDUCT WHEEL ALIGNMENT	New	✓ 80.00
5	TO REMOVE AND REFIX WHEEL RIM AND CONDUCT BALANCING	New	30 50.00
Gross Labour Cost (\$\$)			1,440.00

Mova Automotive Pte Ltd/SKA1960L/13/10/2017 16:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

1310

PARTS : \$7441.00 + 15%
= \$8557.15

8557.15

1310

LABOUR: \$1410.00

\$9867.15
✱

Total: \$9967.15 ✱

11/25/2017

Estimate Report

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
			300
		New	(A) 400.00
		Gross Labour Cost (\$)	400.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



UNICO MOTOR (PTE) LIMITED 友和汽車(私人)有限公司
HEAD OFFICE: Blk 9 Selegie Road, #01-23 Selegie House Singapore 180009
BRANCH OFFICE: Blk 22 Sin Ming Road, #01-242 Singapore 570022
EMAIL: sales@unicomotor.com.sg | kee@unicomotor.com.sg
WEBSITE: www.unicomotor.com.sg

GST REG NO: M2-0017235-3
CO. REG NO: 197302096R
(HO) Tel: (65) 6336 1828 (4 lines) Fax: (65) 6337 2043
(BR) Tel: (65) 6453 5221 (3 lines) Fax: (65) 6453 2878

TAX INVOICE

MOVA AUTOMOTIVE PTE LTD
BLK 1008 BUKIT MERAH LANE 3 #01-04
SINGAPORE 159722

INVOICE NO.: 17CII10117
DATE: 10/11/2017
A/C NO.: LMOVA

Customer
Copy

REMARKS:

ITEM PART NOS. DESCRIPTION

17CDO110031 - Mr Goh Jia Yu (SKA1960L/LandRover FREELANDER 2 LF 3.2L-SALFA2AAXBH230040) Deliver To #01-51

ITEM	PART NOS.	DESCRIPTION	QTY	UNIT	PRICE	TOTAL
1	KRF100003	DOOR MLDG CLIPS,RR	10	PC	8.00	80.00
2	LR006361	DOOR EDGE STRIP LH,RR	1	PC	110.00	110.00
3	LR012844	DOOR MLDG CLIPS,FRT	12	PCS	8.00	96.00
4	LR014202	R/BOARD DEFLECTOR LH(10176)	1	PC	380.00	380.00
5	LR022067	SPORTS RIM(19")	1	PC	2,150.00	2,150.00
6	LR023161	DOOR LH,FRT	1	PC	3,550.00	3,550.00
7	LR026446	DOOR STRIP LH,RR(25324)	1	PC	220.00	220.00
8	LR030289	DOOR STRIP LH,FRT(Lower/211A74)	1	PC	215.00	215.00
9	LR044655	DOOR MLDG LH,FRT(Lower/25557)	1	PC	380.00	380.00
10	LR044657	DOOR MLDG LH,RR(Lower/20855)	1	PC	260.00	260.00

AUTHORISED SIGNATURE:

ALL CHEQUES TO BE MADE PAYABLE TO UNICO MOTOR (PTE) LTD.

CREDIT TERM: C.O.D



All enquiries are welcome.

SUBTOTAL : SGD 7,441.00
GST 7.0% : SGD 520.87
TOTAL : SGD 7,961.87

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Oct 2017 Sendback Est	13 Oct 2017 16:23 S\$14,539.65	16 Oct 2017 06:43 Edit Adj Rpt	S\$9,867.15 Edit Estimates	S\$9,867.15 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	BOYLE NG CHAI TEE, ID: S1687489B, Tel: +6597607900, Email: BOYLE.NG@BORNEOMOTORS.COM.SG		
Vehicle Reg. No.:	SKA1960L	Date of Loss:	10/10/2017 09:00 - :59
Claim Type:	OD / 17/17/17/VP05/020153	Policy/Cover Note No.:	Z17VP05015446 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) No. 22 Jalan Kilang, #07-01, Mova Building, 159419 Bukit Merah - Tel: 62723892/64763333		
Handling Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 26/10/2017]		
Driver/Custodian:	BOYLE NG CHAI TEE (52 / Male), NRIC: S1687489B, Tel: +6597607900		
Adj Asg. Remarks:	SURVEY & REVERT.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- LONPAC_HQ (23/10/2017): Alert - Adj Mandate Approved (S\$14109.65) - SKA1960L - Claim Handler: Gerald Poh

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKA1960L (17/17/17/VP05/020153)

OD

Oct 10 2017 9:00AM

[BOYLE NG CHAI TEE]

Mova Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports

No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	1 per page ▼	Thumbnail	Print
1	13/10/17 16:23	Repairer Estimates		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/10/17 13:50	Adjuster Immediate Advice		Load HTM	

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page ▼	Thumbnail	Print
1	19/10/17 13:34	General View		Load JPG	
2	19/10/17 13:34	General View		Load JPG	
3	19/10/17 13:34	General View		Load JPG	
4	19/10/17 13:34	General View		Load JPG	
5	19/10/17 13:34	General View		Load JPG	
6	19/10/17 13:34	General View		Load JPG	
7	19/10/17 13:34	General View		Load JPG	
8	19/10/17 13:34	General View		Load JPG	
9	19/10/17 13:34	General View		Load JPG	
10	19/10/17 13:34	General View		Load JPG	
11	19/10/17 13:34	General View		Load JPG	
12	19/10/17 13:34	General View		Load JPG	
13	19/10/17 13:34	General View		Load JPG	
14	19/10/17 13:34	General View		Load JPG	
15	19/10/17 13:34	General View		Load JPG	
16	19/10/17 13:34	General View		Load JPG	
17	19/10/17 13:34	General View		Load JPG	
18	19/10/17 13:34	General View		Load JPG	
19	19/10/17 13:34	General View		Load JPG	
20	19/10/17 13:34	General View		Load JPG	
21	19/10/17 13:34	General View		Load JPG	
22	19/10/17 13:34	General View		Load JPG	
23	19/10/17 13:34	General View		Load JPG	
24	19/10/17 13:34	General View		Load JPG	
25	19/10/17 13:34	General View		Load JPG	
26	19/10/17 13:34	General View		Load JPG	
27	19/10/17 13:34	General View		Load JPG	
28	19/10/17 13:34	General View		Load JPG	
29	19/10/17 13:34	General View		Load JPG	
30	19/10/17 13:34	General View		Load JPG	

31	19/10/17 13:34	General View	1	Load JPG	✓
32	19/10/17 13:34	General View	1	Load JPG	✓
33	30/01/18 10:53	Reinspection Photo	1	Load JPG	✓
34	30/01/18 10:53	Reinspection Photo	1	Load JPG	✓
35	30/01/18 10:53	Reinspection Photo	1	Load JPG	✓
36	30/01/18 10:53	Reinspection Photo	1	Load JPG	✓
37	30/01/18 10:53	Reinspection Photo	1	Load JPG	✓
38	30/01/18 10:53	Reinspection Photo	1	Load JPG	✓
39	30/01/18 10:53	Reinspection Photo	1	Load JPG	✓
40	30/01/18 10:53	Reinspection Photo	1	Load JPG	✓
41	30/01/18 10:53	Reinspection Photo	1	Load JPG	✓
42	30/01/18 10:53	Reinspection Photo	1	Load JPG	✓
43	30/01/18 10:53	Reinspection Photo	1	Load JPG	✓
44	30/01/18 10:53	Reinspection Photo	1	Load JPG	✓
45	30/01/18 10:53	Reinspection Photo	1	Load JPG	✓
46	30/01/18 10:53	Reinspection Photo	1	Load JPG	✓
47	30/01/18 10:53	Reinspection Photo	1	Load JPG	✓
48	30/01/18 10:53	Reinspection Photo	1	Load JPG	✓
49	30/01/18 10:53	Reinspection Photo	1	Load JPG	✓
50	30/01/18 10:53	Reinspection Photo	1	Load JPG	✓
51	30/01/18 10:53	Reinspection Photo	1	Load JPG	✓
52	30/01/18 10:53	Reinspection Photo	1	Load JPG	✓
53	30/01/18 10:53	Reinspection Photo	1	Load JPG	✓
Documentation				1 per page ▼	✓
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)		Thumbnail	Print
1	13/10/17 16:22	Certificate of Insurance	1	Load PDF	
2	13/10/17 16:22	Drivers Driving License	1	Load PDF	
3	13/10/17 16:22	Drivers NRIC	1	Load PDF	
4	13/10/17 16:22	E-filed GIA report	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/10/17 13:56	ESTIMATE	1	Load PDF	
2	30/01/18 10:50	SUPPLEMENTARY	1	Load PDF	
3	05/02/18 11:19	PARTS INVOICE	1	Load PDF	

Linked Accident Report Documents

				View	View in Browser ▼
Assessment Reports				1 per page ▼	✓
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)		Thumbnail	Print
1	11/10/17 09:37	Accident Statement	1	Load HTM	
Photos/Images				3 per page ▼	✓
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)		Thumbnail	Print
1	11/10/17 09:34	Accident Photo	1	Load JPG	✓
2	11/10/17 09:34	Accident Photo	1	Load JPG	✓
3	11/10/17 09:34	Accident Photo	1	Load JPG	✓
4	11/10/17 09:34	Accident Photo	1	Load JPG	✓
5	11/10/17 09:34	Accident Photo	1	Load JPG	✓
6	11/10/17 09:34	Accident Photo	1	Load JPG	✓
7	11/10/17 09:34	Accident Photo	1	Load JPG	✓

8	11/10/17 09:34	Accident Photo	1	Load JPG	✓
9	11/10/17 09:34	Accident Photo	1	Load JPG	✓
10	11/10/17 09:34	Accident Photo	1	Load JPG	✓
11	11/10/17 09:34	Accident Photo	1	Load JPG	✓
Documentation			1 per page		✓
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)		Thumbnail	Print
1	11/10/17 09:34	Sketch Plan	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC17019790/T1TBS2

Date: 07/02/2018

REFERENCE

Insured/Claimant: BOYLE NG CHAI TEE Policy No: Z17VP05015446
Date of Loss: 10/10/2017 Nature of Claim: OD Claim No: 17/17/17/VP05/020153

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKA1960L**
Make & Model: LAND ROVER FREELANDER 2, 3.2 i6 HSE (A) Engine No: B6324S18111015321
Reg. Date: 27/01/2011 (Man. Year: 2010) Chassis No: SALFA2AAXBH230040
Colour: Grey Odometer: 38035 km
Engine Capacity: 3192 cc
Market Value/New Car Price: S\$65,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55R19 Rear Tyre Size: 235/55R19
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,099.65	8,557.15	4,542.50	34.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,440.00	1,310.00	130.00	9.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,539.65	9,867.15	4,672.50	32.14
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	14,539.65	9,367.15	5,172.50	35.58
+ GST 7.00/7.00% (S\$)	1,017.78	655.70	362.08	35.58
Nett Amount (S\$)	15,557.43	10,022.85	5,534.58	35.58

INSPECTION

Date of Assignment: 16/10/2017 Present Location: Mova Automotive Pte Ltd (Bukit Merah)
Mova Automotive Pte Ltd (Bukit Merah)
Date Inspected: 17/10/2017 Inspected At: No. 22 Jalan Kilang, #03-01, Mova Building
Singapore 159419
Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Feb 2018)

Parts: M1-SUV LAND ROVER FREELANDER 2 3.2 i6 HSE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKA1960L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH (WCP)	Bent	3,550.00 F	*3,550.00 F
2	1		*FRONT DOOR PROTECTOR LH (WCP)	Missing	380.00 F	*380.00 F
3	12		*FRONT DOOR PROTECTOR CLIPS (WCP)	Necessary	96.00 F	*96.00 F
4	1		*FRONT DOOR WEATHERSTRIP LH (WCP)	Necessary	215.00 F	*215.00 F
5	1		*REAR DOOR LH (WCP)	Repair	3,350.00 F	*- F
6	1		*REAR DOOR PROTECTOR LH (WCP)	Missing	260.00 F	*260.00 F
7	10		*REAR DOOR PROTECTOR CLIPS (WCP)	Necessary	80.00 F	*80.00 F
8	1		*REAR DOOR WEATHERSTRIP LH (WCP)	Necessary	220.00 F	*220.00 F
9	1		*REAR DOOR EDGE RUBBER LH (WCP)	Necessary	110.00 F	*110.00 F
10	1		*REAR DOOR WINDOW REGULATOR LH (WCP)	Not Necessary	600.00 F	*- F
11	1		*SIDE SKIRT LH (WCP)	Cut	380.00 F	*380.00 F
12	1		*REAR WHEEL RIM LH (WCP)	Cut	2,150.00 F	*2,150.00 F

F=Franchise part.

Sub Total (S\$)	11,391.00	7,441.00
+ Margin on L,N Items 15.00/15.00% (S\$)	1,708.65	1,116.15
Total Parts (S\$)	13,099.65	8,557.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR ROCKER PANEL LH. TO REMOVE AND REPLACE ALL ACCIDENT DAMAGED PARTS AND REALIGN ALL AFFECTED	New	450.00	300.00
2	TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS	New	700.00	500.00
3	TO REMOVE AND REFIX DOOR MECHANISM, CHECK AND TEST POWER WINDOW AND CENTRE LOCKING SYSTEM	New	160.00	100.00
4	TO CONDUCT WHEEL ALIGNMENT	New	80.00	80.00
5	TO REMOVE AND REFIX WHEEL RIM AND CONDUCT BALANCING	New	50.00	30.00
6	TO REPAIR REAR DOOR LH	New	-	300.00
Gross Labour Cost (\$\$)			1,440.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >